
Title List of Documents Made Publicly Available

August 1-31, 1982

Office of Administration
U.S. Nuclear Regulatory Commission



RETURN TO GPO 2005, CLERK

Available from

NRC/GPO Sales Program

Superintendent of Documents
Government Printing Office
Washington, D. C. 20402

A year's subscription consists of 12 issues for
this publication.

Single copies of this publication
are available from National Technical
Information Service, Springfield, VA 22161

Microfiche of single copies are
available from NRC/GPO Sales Program
Washington, D. C. 20555

Title List of Documents Made Publicly Available

August 1-31, 1982

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number.....	ix
Alphabetic Arrangement of Docket Items by Facility Name.....	xvii
Docketed Items	
Low Level Radwaste Disposal Sites — Docket 27.....	1
Domestic Licensing of Source Material — Docket 40.....	2
Domestic Licensing of Production and Utilization Facilities — Docket 50 ...	11
Domestic Licensing of Special Nuclear Material — Docket 70.....	417
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71	424
Licensing of Independent Spent Fuel Storage — Docket 72	428
Nondocketed Items	
10 CFR — Commission Meeting Records	429
ACRS — Advisory Committee on Reactor Safeguards.....	429
COMMISSION — NRC Commissioners.....	430
CONTRACT — NRC Contracts and Modifications	430
FOIA — Freedom of Information Act Requests and Releases.....	434
GEN TECH IS — Generic Technical Issues	439
I&E — Inspection and Enforcement.....	439
MISC — Public Document Room Miscellaneous.....	440
NUREG — NUREG Reports and Related Correspondence.....	440
ORG — Correspondence with Other Organizations.....	443
PR — Proposed Rule.....	444
PRM — Petition for Rulemaking	446
PROJ — Projects - Predocket Licensing	446
PT 21 — Noncompliance Reports and Related Correspondence.....	446
QA999 — Quality Assurance Inspections.....	447
REGGD — Regulatory Guides.....	450
RES — Research and Technical Assistance Reports	451
REVIEW GROUP — NRC Research Review Groups.....	452
SECY — Position Papers Before the Commission.....	454
STATE PROG — State Programs.....	454
TOPREP — Vendor Reports and Related Correspondence.....	455
WASTE MGT — Nuclear Waste Management.....	457
XPORTLIC — Export and Import Licenses.....	460
Personal Author Index	463
Corporate Source Index	495
Report Number Index.....	531
Cross Reference of Enclosures to Principal Documents	533
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nondocketed Categories	B-1

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

- (1) P. Operating license stage documents & correspondence
- (2) 8203090028 (3) Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research Ctr by 820408. Proprietary repts will be provided to NRC by 820510.
- (4) MILLS, L.M. (5) Tennessee Valley Authority. (6) 82/03/04. (7) VASSALLO, D.B. Operating Reactors Branch 2. (8) 1p. 1216:254. 24XFiche: 50-259, 82/03/04, 8203090028.
- (9) (10) (11) (12)

1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number (year, month, day, and sequence number of item).
3. Description of information contained in the document.
4. Personal author(s). An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source.
6. Date of document described.
7. Recipient of document and NRC or corporate affiliation.
8. Pages in this document.
9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
10. This three-digit portion of this entry is the number of the frame on which this document starts.
11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
 ACRS — Advisory Committee on Reactor Safeguards
 COMMISSION — NRC Commissioners
 CONTRACT — NRC Contracts and Modifications
 DISCLOSURE — Financial Disclosure Information
 FOIA — Freedom of Information Act Requests and Releases
 GENTECH IS — Generic Technical Issues

15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service
Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W.
Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Radwaste Disposal Sites — Docket 27			40-8452	Bear Creek Uranium Co., Casper, WY	8
27-039	Sheffield, IL, U.S. Ecology, Inc.	1	40-8502	Wyoming Mineral Corp., Lakewood, CO	9
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.	1	40-8546	National Aeronautics & Space Administration, Hampton, VA	9
27-048	Richland, WA, U.S. Ecology, Inc.	1	40-8584	Minerals Exploration Co., Los Angeles, CA	9
Domestic Licensing of Source Material — Docket 40			40-8585	Wyoming Mineral Corp., Lakewood, CO	9
40-0086	W. R. Grace & Co., Pompton Plains, NJ	2	40-8602	Silver King Mines, Inc., Casper, WY	9
40-0299	Union Carbide Corp., Grand Junction, CO	5	40-8674	Plateau Resources, Ltd., Grand Junction, CO	9
40-0460	Washington Public Power Supply System, Richland, WA	5	40-8681	Energy Fuels Nuclear, Inc., Denver, CO	9
40-0501	Aluminium Co. of America	5	40-8684	Western Nuclear, Inc., Lakewood, CO	9
40-0672	Nuclear Metals, Inc., Concord, MA	6	40-8697	Rocky Mountain Energy Co., Denver, CO	9
40-1162	Western Nuclear Corp., Jeffrey City, WY	6	40-8714	Cleveland-Cliffs Iron Co., Cleveland, OH	9
40-2061	Kerr-McGee Chemical Corp., Oklahoma City, OK	6	40-8724	Chemetron Corp., Chicago, IL	9
40-2259	Pathfinder Mines Corp., Riverton, WY	7	40-8743	Conoco, Inc., Denver, CO	9
40-3453	Atlas Mineral, Inc., Denver, CO	7	40-8745	Ogle Petroleum, Inc., Casper, WY	10
40-4492	Federal-American Partners, Riverton, WY	7	40-8768	Kerr-McGee Nuclear Corp., Oklahoma City, OK	10
40-6622	Pathfinder Mines Corp., Shirley Basin, WY	7	40-8781	Teton Exploration Drilling Co., Inc. Casper, WY	10
40-6940	Kawecki Berylo Industries, Inc., Boyertown, PA	7	40-8783	Uranerz USA, Inc., Casper, WY	10
40-7138	Yankee Atomic Electric Co., Westborough, MA	7	40-8786	Uranium Resources, Inc., Richardson, TX	10
40-7604	Vistron Corp., Lima, OH	7	40-8791	Custom Machine, Inc., Cleveland, OH	10
40-8027	Kerr-McGee Nuclear Corp., Oklahoma City, OK	7	40-8793	Conoco, Inc., Denver, CO	10
40-8064	Exxon Minerals Co. USA, Houston, TX	8	40-8794	Molycorp, Inc., Los Angeles, CA	10
40-8084	Rio Algom Corp., Moab, UT	8	40-8801	Radiation Management Corp., Northbrook, IL	10
40-8102	Exxon Co. USA, Houston, TX	8	40-8823	EM Chemicals, Hawthorne, NY	11
40-8135	Minnesota Mining & Manufacturing, St. Paul, MN	8	Domestic Licensing of Production and Utilization Facilities — Docket 50		
40-8211	Chamberlain Manufacturing Corp., Waterloo, IA	8	50-2	Univ. of Michigan Research Reactor	11
40-8348	Minerals Exploration Co., Los Angeles, CA	8	50-3	Indian Point Station, Unit 1	11
			50-5	Pennsylvania State Univ. Research Reactor	12

Docket	Name	Page	Docket	Name	Page
50-10	Dresden Nuclear Power Station, Unit 1	12	50-157	Cornell Univ. Research Reactor	25
50-13	Babcock & Wilcox Co. Critical Facility	13	50-160	Georgia Institute of Technology Research Reactor	25
50-16	Enrico Fermi Atomic Power Plant, Unit 1	14	50-163	General Atomic Company	25
50-20	Massachusetts Institute of Technology Research Reactor	14	50-166	Univ. of Maryland Research Reactor	25
50-27	Washington State Univ. Research Reactor	14	50-170	National Naval Medical Center	25
50-29	Yankee-Rowe Nuclear Power Station	14	50-171	Peach Bottom Atomic Power Station, Unit 1	26
50-54	Union Carbide Research Reactor	17	50-182	Purdue Univ. Research Reactor	26
50-57	State Univ. of New York Research Reactor	17	50-184	National Bureau of Standards Reactor	26
50-59	Texas A&M Univ. Research Reactor	17	50-186	Univ. of Missouri Research Reactor	26
50-70	General Electric Test Reactor	17	50-187	Space Radiation Research Reactor	26
50-73	General Electric Nuclear Test Reactor	17	50-188	Kansas State Univ. Research Reactor	27
50-77	Catholic Univ. of America Research Reactor	17	50-193	Rhode Island & Providence Plantations ABC	27
50-83	Univ. of Florida Training Reactor	17	50-199	Manhattan College Research Reactor	27
50-87	Westinghouse Critical Experiment	17	50-201	West Valley Reprocessing Plant	27
50-89	General Atomic Co.	18	50-206	San Onofre Nuclear Station, Unit 1	27
50-97	Cornell Univ. Zero Power Reactor	18	50-208	Columbia Univ. Research Reactor	31
50-99	Babcock & Wilcox Test Reactor	18	50-213	Haddam Neck Plant	31
50-112	Univ. of Oklahoma Research Reactor	18	50-219	Oyster Creek Nuclear Power Plant	33
50-113	Univ. of Arizona Research Reactor	18	50-220	Nine Mile Point Nuclear Station, Unit 1	36
50-116	Iowa State Univ. Research Reactor	18	50-223	Univ. of Lowell Research Reactor	38
50-123	Univ. of Missouri Research Reactor	18	50-225	RPI Critical Experiment	38
50-128	Texas A&M Univ. Research Reactor	18	50-228	Aerotest Radiography & Research Reactor	38
50-133	Humboldt Bay Power Plant, Unit 3	18	50-237	Dresden Nuclear Power Station, Unit 2	39
50-134	Worcester Polytechnic Institute Research Reactor	19	50-241	Mississippi State Univ. Research Reactor	42
50-139	Univ. of Washington Research Reactor	19	50-243	Oregon State Univ. Research Reactor	42
50-142	UCLA Training Reactor	20	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	42
50-146	Saxton Nuclear Experimental Facility	21	50-245	Millstone Nuclear Power Station, Unit 1	45
50-147	Rockwell International Corp. Critical Facility	21	50-246	Advanced Critical Reactor Experiment	47
50-148	Univ. of Kansas Research Reactor	21	50-247	Indian Point Station, Unit 2	47
50-150	Ohio State Univ. Research Reactor	21	50-249	Dresden Nuclear Power Station, Unit 3	51
50-155	Big Rock Point Nuclear Plant	21	50-250	Turkey Point Plant, Unit 3	54
50-156	Univ. of Wisconsin Research Reactor	25	50-251	Turkey Point Plant, Unit 4	56
			50-252	Univ. of New Mexico Research Reactor	59

Docket	Name	Page	Docket	Name	Page
50-254	Quad-Cities Station, Unit 1	59	50-296	Browns Ferry Nuclear Power Station, Unit 3	132
50-255	Palisades Nuclear Plant	62	50-297	North Carolina State Univ. PULSTAR Reactor	136
50-259	Browns Ferry Nuclear Power Station, Unit 1	65	50-298	Cooper Nuclear Station	136
50-260	Browns Ferry Nuclear Power Station, Unit 2	70	50-301	Point Beach Nuclear Plant, Unit 2	138
50-261	H.B. Robinson Plant, Unit 2	74	50-302	Crystal River Nuclear Plant, Unit 3	141
50-262	Brigham Young Univ. Research Reactor	77	50-304	Zion Nuclear Power Station, Unit 2	143
50-263	Monticello Nuclear Generating Plant	77	50-305	Kewaunee Nuclear Power Plant	145
50-264	Dow Chemical Co.	79	50-306	Prairie Island Nuclear Station, Unit 2	147
50-265	Quad-Cities Station, Unit 2	79	50-309	Maine Yankee Atomic Power Plant	150
50-266	Point Beach Nuclear Plant, Unit 1	82	50-311	Salem Nuclear Generating Station, Unit 2	153
50-267	Fort St. Vrain Nuclear Generating Station	85	50-312	Rancho Seco Nuclear Generating Station	156
50-268	Midwest Fuel Recovery Plant	87	50-313	Arkansas Nuclear One, Unit 1	159
50-269	Oconee Nuclear Station, Unit 1	87	50-315	Donald C. Cook Nuclear Power Plant, Unit 1	163
50-270	Oconee Nuclear Station, Unit 2	90	50-316	Donald C. Cook Nuclear Power Plant, Unit 2	166
50-271	Vermont Yankee Nuclear Power Station	93	50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	168
50-272	Salem Nuclear Generating Station, Unit 1	94	50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	173
50-274	U.S. Geological Survey Research Reactor	97	50-320	Three Mile Island Nuclear Station, Unit 2	176
50-275	Diablo Canyon Nuclear Power Plant, Unit 1	97	50-321	Edwin I. Hatch Nuclear Plant, Unit 1	179
50-276	Georgia Tech Research Reactor	101	50-322	Shoreham Nuclear Power Station	182
50-277	Peach Bottom Atomic Power Station, Unit 2	101	50-323	Diablo Canyon Nuclear Power Plant, Unit 2	187
50-278	Peach Bottom Atomic Power Station, Unit 3	103	50-324	Brunswick Steam Electric Plant, Unit 2	189
50-280	Surry Power Station, Unit 1	104	50-325	Brunswick Steam Electric Plant, Unit 1	192
50-281	Surry Power Station, Unit 2	108	50-326	Univ. of California at Irvine Research Reactor	196
50-282	Prairie Island Nuclear Station, Unit 1	110	50-327	Sequoyah Nuclear Plant, Unit 1	196
50-284	Idaho State Univ. Research Reactor	113	50-328	Sequoyah Nuclear Plant, Unit 2	200
50-285	Fort Calhoun Station, Unit 1	113	50-329	Midland Plant, Unit 1	203
50-286	Indian Point Station, Unit 3	116	50-330	Midland Plant, Unit 2	207
50-287	Oconee Nuclear Station, Unit 3	119	50-331	Duane Arnold Energy Center	210
50-288	Reed College Research Reactor	122	50-332	Barnwell Reprocessing Plant	213
50-289	Three Mile Island Nuclear Station, Unit 1	122	50-333	James A. Fitzpatrick Nuclear Power Plant	213
50-293	Pilgrim Nuclear Power Station, Unit 1	127	50-334	Beaver Valley Power Station, Unit 1	215
50-294	Michigan State Univ. Research Reactor	129	50-335	St. Lucie Plant, Unit 1	220
50-295	Zion Nuclear Power Station, Unit 1	129	50-336	Millstone Nuclear Power Station, Unit 2	222

Docket	Name	Page	Docket	Name	Page
50-338	North Anna Power Station, Unit 1	225	50-401	Shearon Harris Nuclear Power Plant, Unit 2	309
50-339	North Anna Power Station, Unit 2	228	50-402	Shearon Harris Nuclear Power Plant, Unit 3	311
50-341	Enrico Fermi Atomic Power Plant, Unit 2	231	50-403	Shearon Harris Nuclear Power Plant, Unit 4	311
50-344	Trojan Nuclear Plant	233	50-404	North Anna Power Station, Unit 3	311
50-346	Davis-Besse Nuclear Power Station, Unit 1	235	50-406	Tuskegee Institute Research Reactor	311
50-348	Joseph M. Farley Nuclear Plant, Unit 1	239	50-407	Univ. of Utah Research Reactor	311
50-352	Limerick Generating Station, Unit 1	242	50-409	La Crosse Bolling Water Reactor	312
50-353	Limerick Generating Station, Unit 2	247	50-410	Nine Mile Point Nuclear Station, Unit 2	315
50-354	Hope Creek Nuclear Station, Unit 1	250	50-412	Beaver Valley Power Station, Unit 2	316
50-355	Hope Creek Nuclear Station, Unit 2	251	50-413	Catawba Nuclear Station, Unit 1	316
50-356	Univ. of Illinois LOPRA Research Reactor	252	50-414	Catawba Nuclear Station, Unit 2	320
50-358	William H. Zimmer Nuclear Station, Unit 1	252	50-416	Grand Gulf Nuclear Station, Unit 1	323
50-361	San Onofre Nuclear Station, Unit 2	255	50-417	Grand Gulf Nuclear Station, Unit 2	328
50-362	San Onofre Nuclear Station, Unit 3	260	50-423	Millstone Nuclear Power Station, Unit 3	330
50-363	Forked River Nuclear Station, Unit 1	262	50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	331
50-364	Joseph M. Farley Nuclear Plant, Unit 2	262	50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	332
50-366	Edwin I. Hatch Nuclear Plant, Unit 2	264	STN-50-437	Floating Nuclear Plant	332
50-367	Bailly Generating Station	267	50-438	Bellefonte Nuclear Plant, Unit 1	333
50-368	Arkansas Nuclear One, Unit 2	267	50-439	Bellefonte Nuclear Plant, Unit 2	337
50-369	William B. McGuire Nuclear Station, Unit 1	270	50-440	Perry Nuclear Power Plant, Unit 1	340
50-370	William B. McGuire Nuclear Station, Unit 2	274	50-441	Perry Nuclear Power Plant, Unit 2	344
50-373	LaSalle County Station, Unit 1	276	50-443	Seabrook Nuclear Station, Unit 1	347
50-374	LaSalle County Station, Unit 2	281	50-444	Seabrook Nuclear Station, Unit 2	349
50-375	Nuclear Examination Reactor	283	50-445	Comanche Peak Steam Electric Station, Unit 1	351
50-382	Waterford Generating Station, Unit 3	283	50-446	Comanche Peak Steam Electric Station, Unit 2	354
50-387	Susquehanna Steam Electric Station, Unit 1	287	STN-50-447	GESSAR-238	356
50-388	Susquehanna Steam Electric Station, Unit 2	291	STN-50-454	Byron Station, Unit 1	356
50-389	St. Lucie Plant, Unit 2	293	STN-50-455	Byron Station, Unit 2	360
50-390	Watts Bar Nuclear Plant, Unit 1	296	STN-50-456	Braidwood Station, Unit 1	364
50-391	Watts Bar Nuclear Plant, Unit 2	299	STN-50-457	Braidwood Station, Unit 2	365
50-395	Virgil C. Summer Nuclear Station, Unit 1	302	50-458	River Bend Station, Unit 1	367
50-397	WPPSS Nuclear Project, Unit 2	305	50-459	River Bend Station, Unit 2	369
50-400	Shearon Harris Nuclear Power Plant, Unit 1	307	50-460	WPPSS Nuclear Project, Unit 1	369

Docket	Name	Page	Docket	Name	Page
50-461	Clinton Power Station, Unit 1	371	STN-50-528	Palo Verde Nuclear Station, Unit 1	396
50-462	Clinton Power Station, Unit 2	372	STN-50-529	Palo Verde Nuclear Station, Unit 2	399
50-466	Allens Creek Nuclear Station, Unit 1	373	STN-50-530	Palo Verde Nuclear Station, Unit 3	401
STN-50-470	CESSAR System 80	374	STN-50-531	GESSAR-251	403
STN-50-480	RESAR-41	374	STN-50-532	BRAUNSAR	403
STN-50-481	B-SAR-241	374	STN-50-535	GASSAR-6	403
STN-50-482	Wolf Creek Generating Station	374	50-537	Clinch River Breeder Reactor	403
STN-50-483	Callaway Plant, Unit 1	375	50-538	Memphis State Univ. Research Reactor	410
STN-50-485	Sterling Power Nuclear Project, Unit 1	377	STN-50-545	RESAR-3S	410
STN-50-486	Callaway Plant, Unit 2	378	STN-50-546	Marble Hill Nuclear Station, Unit 1	410
STN-50-488	Perkins Nuclear Station, Unit 1	378	STN-50-547	Marble Hill Nuclear Station, Unit 2	411
STN-50-489	Perkins Nuclear Station, Unit 2	378	50-549	Greene County Nuclear Power Plant	412
STN-50-490	Perkins Nuclear Station, Unit 3	379	STN-50-550	GESSAR-238-BOP, Interface	412
STN-50-491	Cherokee Nuclear Station, Unit 1	379	STN-50-553	Phipps Bend Nuclear Station, Unit 1	412
STN-50-492	Cherokee Nuclear Station, Unit 2	380	STN-50-554	Phipps Bend Nuclear Station, Unit 2	413
STN-50-493	Cherokee Nuclear Station, Unit 3	380	STN-50-556	Black Fox Station, Unit 1	413
STN-50-495	SWESSAR-P1	381	STN-50-557	Black Fox Station, Unit 2	414
STN-50-498	South Texas Project, Unit 1	381	STN-50-560	BOPSSAR	414
STN-50-499	South Texas Project, Unit 2	383	STN-50-561	B-SAR-205	414
50-500	Davis-Besse Nuclear Power Station, Unit 2	385	50-564	Nuclear Fuels Recovery & Recycle Center	414
50-501	Davis-Besse Nuclear Power Station, Unit 3	385	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	414
STN-50-502	Haven Nuclear Plant, Unit 1	385	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	415
STN-50-508	WPPSS Nuclear Project, Unit 3	386	STN-50-572	RESAR-414 Westinghouse Electric Corp.	416
STN-50-509	WPPSS Nuclear Project, Unit 5	388	STN-50-584	Gibbsar, Gibbs & Hill	416
50-513	WPPSS Nuclear Project, Unit 4	389	STN-50-591	Essar, Ebasco Services	416
50-514	Pebble Springs Nuclear Plant, Unit 1	390	STN-50-597	New Haven, Unit 2	416
50-515	Pebble Springs Nuclear Plant, Unit 2	390	STN-50-599	Carroll Facility I	416
STN-50-518	Hartsville Nuclear Plant, Unit 1	391	STN-50-600	Carroll Facility II	417
STN-50-519	Hartsville Nuclear Plant, Unit 2	392	Domestic Licensing of Special Nuclear Material — Docket 70		
STN-50-520	Hartsville Nuclear Plant, Unit 3	392	70-0025	Rockwell International Corp., Canoga Park, CA	417
STN-50-521	Hartsville Nuclear Plant, Unit 4	393	70-0027	Babcock & Wilcox Co., Lynchburg, VA	417
50-522	Skagit Nuclear Power Project, Unit 1	394	70-0033	Texas Instruments, Inc., Attleboro, MA	418
50-523	Skagit Nuclear Power Project, Unit 2	395			

Docket	Name	Page	Docket	Name	Page
70-0036	Combustion Engineering, Inc., Windsor, CT	418	70-1173	Mercyhurst College, Erie, PA	422
70-0113	Pennsylvania State Univ., University Park, PA	418	70-1193	Kerr-McGee Nuclear Corp., Oklahoma City, OK	422
70-0135	Babcock & Wilcox Co., Apollo, PA	418	70-1201	Babcock & Wilcox Co., Lynchburg, VA	422
70-0143	Nuclear Fuel Services, Inc., Erwin, TN	418	70-1230	Slippery Rock State College, Slippery Rock, PA	422
70-0184	Westinghouse Electric Corp., Horseheads, NY	419	70-1257	Exxon Nuclear Co., Inc., Richland, WA	422
70-0190	Catholic Univ. of America, Washington, DC	419	70-1308	General Electric Co., San Jose, CA	423
70-0261	Schlumberger Technology Corp., Ridgefield, CT	419	70-1314	National Aeronautics & Space Administration, Hampton, VA	423
70-0273	National Carbon Co., Fostoria, OH	419	70-1810	Westinghouse Electric Corp., Pittsburgh, PA	423
70-0303	Carnegie-Mellon Univ., Pittsburgh, PA	419	70-2174	Southeast Missouri Hospital, Cape Girardeau, MO	423
70-0356	Nuclear Research Corp., Dover, NJ	419	70-2623	Duke Power Co., Charlotte, NC	423
70-0359	Pittsburgh, Univ. of, Pittsburgh, PA	420	70-2625	Newton Memorial Hospital, Newton, NJ	423
70-0364	Babcock & Wilcox Co., Apollo, PA	420	70-2884	Long Island Lighting Co., Hicksville, NY	423
70-0371	UNC Naval Products, Inc., Uncasville, CT	420	70-2909	Westinghouse Electric Corp., Prattville, AL	423
70-0398	Commerce, Dept. of, Washington, DC	420	70-2936	Mississippi Power & Light Co., Jackson, MS	423
70-0511	St. Peter's College, Jersey City, NJ	420	70-2937	Pennsylvania Power & Light, Allentown, PA	423
70-0600	Seattle Univ., Seattle, WA	420	70-2955	Edlow International Co., Washington, DC	423
70-0624	Gulf Research & Development Co., Pittsburgh, PA	420	Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71		
70-0625	Howard Univ., Washington, DC	420	71-0062	Industrial Nuclear Co.	424
70-0629	Washington & Jefferson College, Washington, PA	420	71-0370	Amersham Corp.	424
70-0687	Union Carbide Corp., Tuxedo, NY	420	71-0478	X-Scan Inspection Co.	424
70-0734	General Atomic Co., San Diego, CA	420	71-0480	Mercury Metals, Inc.	424
70-0754	General Electric Co., Pleasanton, CA	421	71-5097	Model: 44, Energy, Dept. of	424
70-0820	United Nuclear Corp., Wood River Junction, RI	421	71-5149	Model: 814A, Babcock & Wilcox Co.	424
70-0824	Babcock & Wilcox Co., Lynchburg, VA	421	71-5768	Model: BB-250-2, Combustion Engineering Co., Inc.	424
70-0925	Kerr-McGee Nuclear Corp., Oklahoma City, OK	421	71-5796	Model: 181375, 181361, Advanced Medical Systems, Inc.	424
70-0938	Massachusetts Institute of Technology, Cambridge, MA	421	71-5805	Model: Vandenberg, Chem-Nuclear Systems, Inc.	424
70-0968	Gannon College, Erie, PA	421	71-5874	Model: WAPD-40, Energy, Dept. of	424
70-1068	Florida, Univ. of, Gainesville, FL	421	71-5908	Model: DOT-6M Type B, Babcock & Wilcox Co.	424
70-1113	General Electric Co., Wilmington, NC	421			
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	422			

Docket	Name	Page	Docket	Name	Page
71-5926	Model: GE-100, General Electric Co.	424	71-9094	Model: CNS 14-195-H, Chem-Nuclear Systems, Inc.	427
71-5939	Model: GE-1500, General Electric Co.	424	71-9096	Model: CNS 21-300, Chem-Nuclear Systems, Inc.	427
71-5957	Model: BMI-1, Battelle Columbus Laboratory	424	71-9098	Model: UCC-20WC-2 & 2A, Union Carbide Corp.	427
71-6088	Model: D-38, Oak Ridge National Lab	424	71-9111	Model: CNS 6-80-2, Chem-Nuclear Systems, Inc.	427
71-6115	Model: R1010-0032, Energy, Dept. of	425	71-9128	Model: C-8, Gamma Industries	427
71-6574	Model: HN-200, Hittman Nuclear & Development Corp.	425	71-9132	Model: T-3, Energy, Dept. of	427
71-6601	Model: CNS 8-120, Chem-Nuclear Systems, Inc.	425	71-9135	Model: Century S & SA, Century Univ. S & SA, Gamma Industries	427
71-6678	Model: LP-50, Energy, Dept. of	425	71-9139	Model: 589, General Electric Co.	427
71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	425	71-9145	Model: NUPAC 50-1.5L, -2.5L, -3.OL & -4.OL, No Users	427
71-6717	Model: 6717-B, Gamma Industries	426	71-9151	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	428
71-9006	Model: 500-SU, Automation Industries, Inc.	426	71-9158	Model: GPU 80, General Public Utilities	428
71-9032	Model: 650, Technical Operations, Inc.	426	71-9159	Model: NUPAC Series A, Nuclear Packing, Inc.	428
71-9033	Model: 660 & 660E, Technical Operations, Inc.	426	71-9161	Model: R, Gulf Nuclear, Inc.	428
71-9036	Model: C-1, Source Production & Equipment Co.	426	71-9162	Model: GNM-20, Gulf Nuclear, Inc.	428
71-9053	Model: 683, Technical Operations, Inc.	426	71-9163	Model: GNG-20, Gulf Nuclear, Inc.	428
71-9056	Model: Spec 2-T, Source Production & Equipment Co.	426	71-9166	Model: 864 Type B, Technical Operations, Inc.	428
71-9074	Model: AP-100, ANEFCO, Inc.	426	71-9186	Model: S-6213, Energy, Dept. of	428
71-9079	Model: HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	426			
71-9080	Model: 9080, Hittman Nuclear & Development Corp.	427			
71-9086	Model: HN-100, Series 1, Hittman Nuclear & Development Corp.	427			
71-9089	Model: HN-100S, Hittman Nuclear & Development Corp.	427			
			Licensing of Independent Spent Fuel Storage — Docket 72		
			72-0001	Morris Operations, General Electric Co.	428

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites — Docket 27					
Barnwell, SC, Chem-Nuclear Systems, Inc.	27-047	1	Minnesota Mining & Manufacturing, St. Paul, MN	40-8135	8
Richland, WA, U.S. Ecology, Inc.	27-048	1	Molycorp, Inc., Los Angeles, CA	40-8794	10
Sheffield, IL, U.S. Ecology, Inc.	27-039	1	National Aeronautics & Space Administration, Hampton, VA	40-8546	9
Domestic Licensing of Source Material — Docket 40					
Aluminium Co. of America	40-0501	5	Nuclear Metals, Inc., Concord, MA	40-0672	6
Atlas Mineral, Inc., Denver, CO	40-3453	7	Ogle Petroleum, Inc., Casper, WY	40-8745	10
Bear Creek Uranium Co., Casper, WY	40-8452	8	Pathfinder Mines Corp., Riverton, WY	40-2259	7
Chamberlain Manufacturing Corp., Waterloo, IA	40-8211	8	Pathfinder Mines Corp., Shirley Basin, WY	40-6622	7
Chemetron Corp., Chicago, IL	40-8724	9	Plateau Resources, Ltd., Grand Junction, CO	40-8674	9
Cleveland-Cliffs Iron Co., Cleveland, OH	40-8714	9	Radiation Management Corp., Northbrook, IL	40-8801	10
Conoco, Inc., Denver, CO	40-8743	9	Rio Algom Corp., Moab, UT	40-8084	8
Conoco, Inc., Denver, CO	40-8793	10	Rocky Mountain Energy Co., Denver, CO	40-8697	9
Custom Machine, Inc., Cleveland, OH	40-8791	10	Silver King Mines, Inc., Casper, WY	40-8602	9
EM Chemicals, Hawthorne, NY	40-8823	11	Teton Exploration Drilling Co., Inc., Casper, WY	40-8781	10
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	9	Union Carbide Corp., Grand Junction, CO	40-0299	5
Exxon Co. USA, Houston, TX	40-8102	8	Uranerz USA, Inc., Casper, WY	40-8783	10
Exxon Minerals Co. USA, Houston, TX	40-8064	8	Uranium Resources, Inc., Richardson, TX	40-8786	10
Federal-American Partners, Riverton, WY	40-4492	7	Vistron Corp., Lima, OH	40-7604	7
Kawecki Berylo Industries, Inc., Boyertown, PA	40-6940	7	W. R. Grace & Co., Pompton Plains, NJ	40-0086	2
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	6	Washington Public Power Supply System, Richland, WA	40-0460	5
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8027	7	Western Nuclear Corp., Jeffrey City, WY	40-1162	6
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8768	10	Western Nuclear, Inc., Lakewood, CO	40-8684	9
Minerals Exploration Co., Los Angeles, CA	40-8348	8	Wyoming Mineral Corp., Lakewood, CO	40-8502	9
Minerals Exploration Co., Los Angeles, CA	40-8584	9	Wyoming Mineral Corp., Lakewood, CO	40-8585	9
			Yankee Atomic Electric Co., Westborough, MA	40-7138	7

Name	Docket	Page	Name	Docket	Page
Domestic Licensing of Production and Utilization Facilities — Docket 50			Callaway Plant, Unit 1	STN-50-483	375
Advanced Critical Reactor Experiment	50-246	47	Callaway Plant, Unit 2	STN-50-486	378
Aerotest Radiography & Research Reactor	50-228	38	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	168
Allens Creek Nuclear Station, Unit 1	50-466	373	Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	173
Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	331	Carroll Facility I	STN-50-599	416
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	332	Carroll Facility II	STN-50-600	417
Arkansas Nuclear One, Unit 1	50-313	159	Catawba Nuclear Station, Unit 1	50-413	316
Arkansas Nuclear One, Unit 2	50-368	267	Catawba Nuclear Station, Unit 2	50-414	320
B-SAR-205	STN-50-561	414	Catholic Univ. of America Research Reactor	50-77	17
B-SAR-241	STN-50-481	374	CESSAR System 80	STN-50-470	374
Babcock & Wilcox Co. Critical Facility	50-13	13	Cherokee Nuclear Station, Unit 1	STN-50-491	379
Babcock & Wilcox Test Reactor	50-99	18	Cherokee Nuclear Station, Unit 2	STN-50-492	380
Bailly Generating Station	50-367	267	Cherokee Nuclear Station, Unit 3	STN-50-493	380
Barnwell Reprocessing Plant	50-332	213	Clinch River Breeder Reactor	50-537	403
Beaver Valley Power Station, Unit 1	50-334	215	Clinton Power Station, Unit 1	50-461	371
Beaver Valley Power Station, Unit 2	50-412	316	Clinton Power Station, Unit 2	50-462	372
Bellefonte Nuclear Plant, Unit 1	50-438	333	Columbia Univ. Research Reactor	50-208	31
Bellefonte Nuclear Plant, Unit 2	50-439	337	Comanche Peak Steam Electric Station, Unit 1	50-445	351
Big Rock Point Nuclear Plant	50-155	21	Comanche Peak Steam Electric Station, Unit 2	50-446	354
Black Fox Station, Unit 1	STN-50-556	413	Cooper Nuclear Station	50-298	136
Black Fox Station, Unit 2	STN-50-557	414	Cornell Univ. Research Reactor	50-157	25
BOPSSAR	STN-50-560	414	Cornell Univ. Zero Power Reactor	50-97	18
Braidwood Station, Unit 1	STN-50-456	364	Crystal River Nuclear Plant, Unit 3	50-302	141
Braidwood Station, Unit 2	STN-50-457	365	Davis-Besse Nuclear Power Station, Unit 1	50-346	235
BRAUN SAR	STN-50-532	403	Davis-Besse Nuclear Power Station, Unit 2	50-500	385
Brigham Young Univ. Research Reactor	50-262	77	Davis-Besse Nuclear Power Station, Unit 3	50-501	385
Browns Ferry Nuclear Power Station, Unit 1	50-259	65	Diablo Canyon Nuclear Power Plant, Unit 1	50-275	97
Browns Ferry Nuclear Power Station, Unit 2	50-260	70	Diablo Canyon Nuclear Power Plant, Unit 2	50-323	187
Browns Ferry Nuclear Power Station, Unit 3	50-296	132	Donald C. Cook Nuclear Power Plant, Unit 1	50-315	163
Brunswick Steam Electric Plant, Unit 1	50-325	192	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	166
Brunswick Steam Electric Plant, Unit 2	50-324	189	Dow Chemical Co.	50-264	79
Byron Station, Unit 1	STN-50-454	356	Dresden Nuclear Power Station, Unit 1	50-10	12
Byron Station, Unit 2	STN-50-455	360	Dresden Nuclear Power Station, Unit 2	50-237	39

Name	Docket	Page	Name	Docket	Page
Dresden Nuclear Power Station, Unit 3	50-249	51	Hope Creek Nuclear Station, Unit 2	50-355	251
Duane Arnold Energy Center	50-331	210	Humboldt Bay Power Plant, Unit 3	50-133	18
Edwin I. Hatch Nuclear Plant, Unit 1	50-321	179	Idaho State Univ. Research Reactor	50-284	113
Edwin I. Hatch Nuclear Plant, Unit 2	50-366	264	Indian Point Station, Unit 1	50-3	11
Enrico Fermi Atomic Power Plant, Unit 1	50-16	14	Indian Point Station, Unit 2	50-247	47
Enrico Fermi Atomic Power Plant, Unit 2	50-341	231	Indian Point Station, Unit 3	50-286	116
Essar, Ebasco Services	STN-50-591	416	Iowa State Univ. Research Reactor	50-116	18
Floating Nuclear Plant	STN-50-437	332	James A. Fitzpatrick Nuclear Power Plant	50-333	213
Forked River Nuclear Station, Unit 1	50-363	262	Joseph M. Farley Nuclear Plant, Unit 1	50-348	239
Fort Calhoun Station, Unit 1	50-285	113	Joseph M. Farley Nuclear Plant, Unit 2	50-364	262
Fort St. Vrain Nuclear Generating Station	50-267	85	Kansas State Univ. Research Reactor	50-188	27
GASSAR-6	STN-50-535	403	Kewaunee Nuclear Power Plant	50-305	145
General Atomic Co.	50-89	18	La Crosse Boiling Water Reactor	50-409	312
General Atomic Company	50-163	25	LaSalle County Station, Unit 1	50-373	276
General Electric Nuclear Test Reactor	50-73	17	LaSalle County Station, Unit 2	50-374	281
General Electric Test Reactor	50-70	17	Limerick Generating Station, Unit 1	50-352	242
Georgia Institute of Technology Research Reactor	50-160	25	Limerick Generating Station, Unit 2	50-353	247
Georgia Tech Research Reactor	50-276	101	Maine Yankee Atomic Power Plant	50-309	150
GESSAR-238	STN-50-447	356	Manhattan College Research Reactor	50-199	27
GESSAR-238-BOP, Interface	STN-50-550	412	Marble Hill Nuclear Station, Unit 1	STN-50-546	410
GESSAR-251	STN-50-531	403	Marble Hill Nuclear Station, Unit 2	STN-50-547	411
Gibbsar, Gibbs & Hill	STN-50-584	416	Massachusetts Institute of Technology Research Reactor	50-20	14
Grand Gulf Nuclear Station, Unit 1	50-416	323	Memphis State Univ. Research Reactor	50-538	410
Grand Gulf Nuclear Station, Unit 2	50-417	328	Michigan State Univ. Research Reactor	50-294	129
Greene County Nuclear Power Plant	50-549	412	Midland Plant, Unit 1	50-329	203
H.B. Robinson Plant, Unit 2	50-261	74	Midland Plant, Unit 2	50-330	207
Haddam Neck Plant	50-213	31	Midwest Fuel Recovery Plant	50-268	87
Hartsville Nuclear Plant, Unit 1	STN-50-518	391	Millstone Nuclear Power Station, Unit 1	50-245	45
Hartsville Nuclear Plant, Unit 2	STN-50-519	392	Millstone Nuclear Power Station, Unit 2	50-336	222
Hartsville Nuclear Plant, Unit 3	STN-50-520	392	Millstone Nuclear Power Station, Unit 3	50-423	330
Hartsville Nuclear Plant, Unit 4	STN-50-521	393	Mississippi State Univ. Research Reactor	50-241	42
Haven Nuclear Plant, Unit 1	STN-50-502	385	Monticello Nuclear Generating Plant	50-263	77
Hope Creek Nuclear Station, Unit 1	50-354	250	National Bureau of Standards Reactor	50-184	26

Name	Docket	Page	Name	Docket	Page
National Naval Medical Center	50-170	23	Pilgrim Nuclear Power Station, Unit 1	50-293	127
New Haven, Unit 2	STN-50-597	416	Point Beach Nuclear Plant, Unit 1	50-266	82
Nine Mile Point Nuclear Station, Unit 1	50-220	36	Point Beach Nuclear Plant, Unit 2	50-301	138
Nine Mile Point Nuclear Station, Unit 2	50-410	315	Prairie Island Nuclear Station, Unit 1	50-282	110
North Anna Power Station, Unit 1	50-338	225	Prairie Island Nuclear Station, Unit 2	50-306	147
North Anna Power Station, Unit 2	50-339	228	Purdue Univ. Research Reactor	50-182	26
North Anna Power Station, Unit 3	50-404	311	Quad-Cities Station, Unit 1	50-254	59
North Carolina State Univ. PULSTAR Reactor	50-297	136	Quad-Cities Station, Unit 2	50-265	79
Nuclear Examination Reactor	50-375	283	Rancho Seco Nuclear Generating Station	50-312	156
Nuclear Fuels Recovery & Recycle Center	50-564	414	Reed College Research Reactor	50-288	122
Oconee Nuclear Station, Unit 1	50-269	87	RESAR-3S	STN-50-545	410
Oconee Nuclear Station, Unit 2	50-270	90	RESAR-41	STN-50-480	374
Oconee Nuclear Station, Unit 3	50-287	119	RESAR-414 Westinghouse Electric Corp.	STN-50-572	416
Ohio State Univ. Research Reactor	50-150	21	Rhode Island & Providence Plantations AEC	50-193	27
Oregon State Univ. Research Reactor	50-243	42	River Bend Station, Unit 1	50-458	367
Oyster Creek Nuclear Power Plant	50-219	33	River Bend Station, Unit 2	50-459	369
Palisades Nuclear Plant	50-255	62	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	42
Palo Verde Nuclear Station, Unit 1	STN-50-528	396	Rockwell International Corp. Critical Facility	50-147	21
Palo Verde Nuclear Station, Unit 2	STN-50-529	399	RPI Critical Experiment	50-225	38
Palo Verde Nuclear Station, Unit 3	STN-50-530	401	Salem Nuclear Generating Station, Unit 1	50-272	94
Peach Bottom Atomic Power Station, Unit 1	50-171	26	Salem Nuclear Generating Station, Unit 2	50-311	153
Peach Bottom Atomic Power Station, Unit 2	50-277	101	San Onofre Nuclear Station, Unit 1	50-206	27
Peach Bottom Atomic Power Station, Unit 3	50-278	103	San Onofre Nuclear Station, Unit 2	50-361	255
Pebble Springs Nuclear Plant, Unit 1	50-514	390	San Onofre Nuclear Station, Unit 3	50-362	260
Pebble Springs Nuclear Plant, Unit 2	50-515	390	Saxton Nuclear Experimental Facility	50-146	21
Pennsylvania State Univ. Research Reactor	50-5	12	Seabrook Nuclear Station, Unit 1	50-443	347
Perkins Nuclear Station, Unit 1	STN-50-488	378	Seabrook Nuclear Station, Unit 2	50-444	349
Perkins Nuclear Station, Unit 2	STN-50-489	378	Sequoyah Nuclear Plant, Unit 1	50-327	196
Perkins Nuclear Station, Unit 3	STN-50-490	379	Sequoyah Nuclear Plant, Unit 2	50-328	200
Perry Nuclear Power Plant, Unit 1	50-440	340	Shearon Harris Nuclear Power Plant, Unit 1	50-400	307
Perry Nuclear Power Plant, Unit 2	50-441	344	Shearon Harris Nuclear Power Plant, Unit 2	50-401	309
Phipps Bend Nuclear Station, Unit 1	STN-50-553	412	Shearon Harris Nuclear Power Plant, Unit 3	50-402	311
Phipps Bend Nuclear Station, Unit 2	STN-50-554	413	Shearon Harris Nuclear Power Plant, Unit 4	50-403	311

Name	Docket	Page	Name	Docket	Page
Shoreham Nuclear Power Station	50-322	182	Univ. of Michigan Research Reactor	50-2	11
Skagit Nuclear Power Project, Unit 1	50-522	394	Univ. of Missouri Research Reactor	50-186	26
Skagit Nuclear Power Project, Unit 2	50-523	395	Univ. of Missouri Research Reactor	50-123	18
South Texas Project, Unit 1	STN-50-498	381	Univ. of New Mexico Research Reactor	50-252	59
South Texas Project, Unit 2	STN-50-499	383	Univ. of Oklahoma Research Reactor	50-112	18
Space Radiation Research Reactor	50-187	26	Univ. of Utah Research Reactor	50-407	311
St. Lucie Plant, Unit 1	50-335	220	Univ. of Washington Research Reactor	50-139	19
St. Lucie Plant, Unit 2	50-389	293	Univ. of Wisconsin Research Reactor	50-156	25
State Univ. of New York Research Reactor	50-57	17	Vermont Yankee Nuclear Power Station	50-271	93
Sterling Power Nuclear Project, Unit 1	STN-50-485	377	Virgil C. Summer Nuclear Station, Unit 1	50-395	302
Surry Power Station, Unit 1	50-280	104	Washington State Univ. Research Reactor	50-27	14
Surry Power Station, Unit 2	50-281	108	Waterford Generating Station, Unit 3	50-382	283
Susquehanna Steam Electric Station, Unit 1	50-387	287	Watts Bar Nuclear Plant, Unit 1	50-390	296
Susquehanna Steam Electric Station, Unit 2	50-388	291	Watts Bar Nuclear Plant, Unit 2	50-391	299
SWESSAR-P1	STN-50-495	381	West Valley Reprocessing Plant	50-201	27
Texas A&M Univ. Research Reactor	50-59	17	Westinghouse Critical Experiment	50-87	17
Texas A&M Univ. Research Reactor	50-128	18	William B. McGuire Station, Unit 1	50-369	270
Three Mile Island Nuclear Station, Unit 1	50-289	122	William B. McGuire Station, Unit 2	50-370	274
Three Mile Island Nuclear Station, Unit 2	50-320	176	William H. Zimmer Nuclear Station, Unit 1	50-358	252
Trojan Nuclear Plant	50-344	233	Wolf Creek Generating Station	STN-50-482	374
Turkey Point Plant, Unit 3	50-250	54	Worcester Polytechnic Institute Research Reactor	50-134	19
Turkey Point Plant, Unit 4	50-251	56	WPPSS Nuclear Project, Unit 1	50-460	369
Tuskegee Institute Research Reactor	50-406	311	WPPSS Nuclear Project, Unit 2	50-397	305
U.S. Geological Survey Research Reactor	50-274	97	WPPSS Nuclear Project, Unit 3	STN-50-508	386
UCLA Training Reactor	50-142	20	WPPSS Nuclear Project, Unit 4	50-513	389
Union Carbide Research Reactor	50-54	17	WPPSS Nuclear Project, Unit 5	STN-50-509	388
Univ. of Arizona Research Reactor	50-113	18	Yankee-Rowe Nuclear Power Station	50-29	14
Univ. of California at Irvine Research Reactor	50-326	196	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	414
Univ. of Florida Training Reactor	50-83	17	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	415
Univ. of Illinois LOPRA Research Reactor	50-356	252	Zion Nuclear Power Station, Unit 1	50-295	129
Univ. of Kansas Research Reactor	50-148	21	Zion Nuclear Power Station, Unit 2	50-304	143
Univ. of Lowell Research Reactor	50-223	38			
Univ. of Maryland Research Reactor	50-166	25			

Name	Docket	Page	Name	Docket	Page
Domestic Licensing of Special Nuclear Material — Docket 70			Pennsylvania State Univ., University Park, PA	70-0113	418
Babcock & Wilcox Co., Apollo, PA	70-0135	418	Pittsburgh, Univ. of, Pittsburgh, PA	70-0359	420
Babcock & Wilcox Co., Apollo, PA	70-0364	420	Rockwell International Corp., Canoga Park, CA	70-0025	417
Babcock & Wilcox Co., Lynchburg, VA	70-1201	422	Schlumberger Technology Corp., Ridgefield, CT	70-0261	419
Babcock & Wilcox Co., Lynchburg, VA	70-0824	421	Seattle Univ., Seattle, WA	70-0600	420
Babcock & Wilcox Co., Lynchburg, VA	70-0027	417	Slippery Rock State College, Slippery Rock, PA	70-1230	422
Carnegie-Mellon Univ., Pittsburgh, PA	70-0303	419	Southeast Missouri Hospital, Cape Girardeau, MO	70-2174	423
Catholic Univ. of America, Washington, DC	70-0190	419	St. Peter's College, Jersey City, NJ	70-0511	420
Combustion Engineering, Inc., Windsor, CT	70-0036	418	Texas Instruments, Inc., Attleboro, MA	70-0033	418
Commerce, Dept. of, Washington, DC	70-0398	420	UNC Naval Products, Inc., Uncasville, CT	70-0371	420
Duke Power Co., Charlotte, NC	70-2623	423	Union Carbide Corp., Tuxedo, NY	70-0687	420
Edlow International Co., Washington, DC	70-2955	423	United Nuclear Corp., Wood River Junction, RI	70-0820	421
Exxon Nuclear Co., Inc., Richland, WA	70-1257	422	Washington & Jefferson College, Washington, PA	70-0629	420
Florida, Univ. of, Gainesville, FL	70-1068	421	Westinghouse Electric Corp., Horseheads, NY	70-0184	419
Gannon College, Erie, PA	70-0968	421	Westinghouse Electric Corp., Pittsburgh, PA	70-1151	422
General Atomic Co., San Diego, CA	70-0734	420	Westinghouse Electric Corp., Pittsburgh, PA	70-1810	423
General Electric Co., Pleasanton, CA	70-0754	421	Westinghouse Electric Corp., Prattville, AL	70-2909	423
General Electric Co., San Jose, CA	70-1308	423	Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71		
General Electric Co., Wilmington, NC	70-1113	421	Amersham Corp.	71-0370	424
Gulf Research & Development Co., Pittsburgh, PA	70-0624	420	Industrial Nuclear Co.	71-0062	424
Howard Univ., Washington, DC	70-0625	420	Mercury Metals, Inc.	71-0480	424
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-1193	422	Model: 181375, 181361, Advanced Medical Systems, Inc.	71-5796	424
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-0923	421	Model: 44, Energy, Dept. of	71-5097	424
Long Island Lighting Co., Hicksville, NY	70-2884	423	Model: 500-SU, Automation Industries, Inc.	71-9006	426
Massachusetts Institute of Technology, Cambridge, MA	70-0938	421	Model: 589, General Electric Co.	71-9139	427
Mercyhurst College, Erie, PA	70-1173	422	Model: 650, Technical Operations, Inc.	71-9032	426
Mississippi Power & Light Co., Jackson, MS	70-2936	423	Model: 660 & 660E, Technical Operations, Inc.	71-9033	426
National Aeronautics & Space Administration, Hampton, VA	70-1314	423	Model: 6717-B, Gamma Industries	71-6717	426
National Carbon Co., Fostoria, OH	70-0273	419	Model: 683, Technical Operations, Inc.	71-9053	426
Newton Memorial Hospital, Newton, NJ	70-2625	423	Model: 814A, Babcock & Wilcox Co.	71-5149	424
Nuclear Fuel Services, Inc., Erwin, TN	70-0143	418	Model: 864 Type B, Technical Operations, Inc.	71-9166	428
Nuclear Research Corp., Dover, NJ	70-0356	419	Model: 9080, Hittman Nuclear & Development Corp.	71-9080	427
Pennsylvania Power & Light, Allentown, PA	70-2937	423			

Name	Docket	Page	Name	Docket	Page
Model: AP-100, ANEPSCO, Inc.	71-9074	426	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	71-9151	428
Model: BB-250-2, Combustion Engineering Co., Inc.	71-5768	424	Model: HN-100S, Hittman Nuclear & Development Corp.	71-9089	427
Model: BM1-1, Battelle Columbus Laboratory	71-5957	424	Model: HN-200, Hittman Nuclear & Development Corp.	71-6574	425
Model: C-1, Source Production & Equipment Co.	71-9036	426	Model: LP-50, Energy, Dept. of	71-6678	425
Model: C-8, Gamma Industries	71-9128	427	Model: NFS-4, Nuclear Fuel Services, Inc.	71-6698	425
Model: Century S & SA, Century Univ. S & SA, Gamma Industries	71-9135	427	Model: NUPAC 50-1.5L, -2.5L, -3.0L & -4.0L, No Users	71-9145	427
Model: CNS 14-195-H, Chem-Nuclear Systems, Inc.	71-9094	427	Model: NUPAC Series A, Nuclear Packing, Inc.	71-9159	428
Model: CNS 21-300, Chem-Nuclear Systems, Inc.	71-9096	427	Model: R, Gulf Nuclear, Inc.	71-9161	428
Model: CNS 8-120, Chem-Nuclear Systems, Inc.	71-6601	425	Model: R1010-0032, Energy, Dept. of	71-6115	425
Model: CNS 6-80-2, Chem-Nuclear Systems, Inc.	71-9111	427	Model: S-6213, Energy, Dept. of	71-9186	428
Model: D-38, Oak Ridge National Lab	71-6088	424	Model: Spec 2-T, Source Production & Equipment Co.	71-9056	426
Model: DOT-6M Type B, Babcock & Wilcox Co.	71-5908	424	Model: T-3, Energy, Dept. of	71-9132	427
Model: GE-100, General Electric Co.	71-5926	424	Model: UCC-20WC-2 & 2A, Union Carbide Corp.	71-9098	427
Model: GE-1500, General Electric Co.	71-5939	424	Model: Vandenberg, Chem-Nuclear Systems, Inc.	71-5805	424
Model: GNG-20, Gulf Nuclear, Inc.	71-9163	428	Model: WAPD-40, Energy, Dept. of	71-5874	424
Model: GNM-20, Gulf Nuclear, Inc.	71-9162	428	X-Scan Inspection Co.	71-0478	424
Model: GPU 80, General Public Utilities	71-9158	428	Licensing of Independent Spent Fuel Storage — Docket 72		
Model: HN-100, Series 1, Hittman Nuclear & Development Corp.	71-9086	427	Morris Operations, General Electric Co.	72-0001	428
Model: HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	71-9079	426			

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL. U.S. ECOLOGY, INC.

B208030125 Forwards sampling & analysis data received from Phase 1 study info distributed to committee members prior to B20610 meeting.
 GAYNOR, R. K. US Ecology, Inc. (Formerly Nuclear Engineering)
 82/06/07. US Ecology, Inc. (Formerly Nuclear Engineering) 1p.
 14200:285.

--B208030127 Sampling & analysis data for Mar 1982
 * US Ecology, Inc. (Formerly Nuclear Engineering) 82/06/07. 3pp.
 14200:284.

B208170227 Forwards "Trench 1B Monitoring Record, Jan-Mar 1982"
 HIPBHER, W. M. US Ecology, Inc. (Formerly Nuclear Engineering).
 82/06/11. EBB10, T. H. Region 3, Office of Director 1p. 14369:028

--B208170234 "Trench 1B Monitoring Record, Jan-Mar 1982"
 * US Ecology, Inc. (Formerly Nuclear Engineering) 82/06/11 1p
 14369:029.

B208030119 Forwards summary of B20610 technical update meeting to evaluate Phase 1 of tritium investigation.
 GAYNOR, R. K. US Ecology, Inc. (Formerly Nuclear Engineering).
 82/07/07. US Ecology, Inc. (Formerly Nuclear Engineering) 8pp.
 14197:393.

B208130242 Forwards summary of B20610 technical update meeting re site tritium migration investigation. Sampling & analysis data & map of locations of well to be dug in Phase 2 encl.
 GAYNOR, R. K. US Ecology, Inc. (Formerly Nuclear Engineering).
 82/07/07. NRC - No Detailed Affiliation Given 8pp. 14333:157.

B208130158 Forwards quarterly monitoring data of piezometers & wells in vicinity of Trench 1B & Trench 1B sumps for Apr-June 1982
 HIPBHER, W. M. US Ecology, Inc. (Formerly Nuclear Engineering).
 82/07/12. EBB10, T. H. Region 3, Office of Director. 1p. 14339:030.

--B208130161 Quarterly monitoring data of piezometers & wells in vicinity of Trench 1B & Trench 1B sumps for Apr-June 1982.
 * US Ecology, Inc. (Formerly Nuclear Engineering). 82/07/12. 1p.
 14339:031.

B208040302 Summary of B20610 meeting w/IL Dept of Nuclear Safety, IL Atty General Ofc, IL State Geological Survey & US Ecology to discuss results of Phase 1 tritium migration studies & finalize plans for Phase II studies.
 STEFKEN, D. L. Low Level Waste Licensing Branch. 82/07/15.
 HAWKINS, E. F. Low Level Waste Licensing Branch. 28pp. 14223:280.

B208020224 Statement re status of settlement negotiations per ASLB B20714 order. Certificate of Svc encl.
 WETTERHAHN, M. J. US Ecology, Inc. (Formerly Nuclear Engineering).
 WETTERHAHN, M. J. Conner & Wetterhahn. 82/07/29. 3pp. 14152:028.

B208030258 Order granting NRC B20728 motion to file status rept on negotiations 10 days after repts filed by other parties. Motion consistent w/Commission regulations.
 GOODHOPE, A. C. Atomic Safety and Licensing Board Panel. 82/08/02.
 Office of the Executive Legal Director. 2pp. 14158:127.

B208030802 Notice of CF Eason change of address. Certificate of Svc encl.
 EASON, C. F. US Ecology, Inc. (Formerly Nuclear Engineering).
 82/08/02. 3pp. 14214:161.

B208060107 Statement of progress in settlement negotiations. Certificate of Svc encl.
 CHAGNOFF, B. A. Illinois, State of. 82/08/02. 8pp. 14238:186.

B208170335 Statement concerning progress in ongoing settlement negotiations w/US Ecology & State of IL. Portions of 15 points addressed in NRC/US Ecology site stabilization & closure conditions met. Certificate of Svc encl.
 LEBBY, R. P. Hearings Division 82/08/13. 6pp. 14367:008

DOCKET 27-047 BARNWELL, SC. CHEM-NUCLEAR SYSTEMS, INC

B208110125 Responds to questions raised at B20715 meeting re tender offer for common stock of Chem-Nuclear Sys. Inc.
 GERSHOWITZ, H. Waste Management, Inc. 82/07/19. DAVIS, J. Q. Office of Nuclear Material Safety & Safeguards, Director 3pp. 14328:354.

B208170385 Advice of developments re tender offer made for common stock of Chem-Nuclear Sys. Inc. Waste Mgt. Inc. will acquire up to 55% of common stock for cash w/balance of stock exchanged for Waste Mgt. Inc. stock in merger.
 REIS, H. F. Lowenstein, Neuman, Reis, Axelrad & Toll. 82/07/27.
 DAVIS, J. Q. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 14372:322.

B208170381 Forwards B20729 ltr originally delivered by messenger re Chem-Nuclear Sys. Inc. & Waste Mgt. Inc. merger.
 REIS, H. F. Lowenstein, Neuman, Reis, Axelrad & Toll. 82/07/29.
 DAVIS, J. Q. Office of Nuclear Material Safety & Safeguards, Director 1p. 14372:014.

--B208170383 Forwards pertinent provisions of agreement of merger between Chem-Nuclear Sys. Inc. & Waste Mgt. Inc. Request for NRC consent to transfer of control will be filed soon.
 REIS, H. F. Lowenstein, Neuman, Reis, Axelrad & Toll. 82/07/29.
 DAVIS, J. Q. Office of Nuclear Material Safety & Safeguards, Director. 10pp. 14372:015.

DOCKET 27-048 RICHLAND, WA. U.S. ECOLOGY, INC.

B208030365 Forwards Waste Packaging Insp Rept 15000046/B2-09 on B20622. Noncompliance noted.
 BOOK, H. E. Division of Radiological Safety & Safeguards Program 82/07/29. GRELLA, A. Division of Fuel Facilities, Materials & Safeguards. 1p. 14158:113.

--B208030369 Waste Packaging Insp Rept 15000046/B2-09 on B20622. Noncompliance noted. 55-gallon drum of low specific activity, NBS, radioactive matl had 1 to 1 1/2-inch diameter hole in lid of drum.
 WAITE, J. A. THOMAS, R. D., BOOK, H. E. Division of Radiological Safety & Safeguards Program. 82/07/29. US Ecology, Inc. (Formerly Nuclear Engineering). 3pp. 14158:114.

B208050536 PND-V-82-032 on B20728, shipment containing 54 wooden boxes of low level waste received w/nine boxes not labelled as LBA matl & one box leaking. Burial permit for TVA suspended, effective B20728.
 THOMAS, R. D. Region 5, Office of Director. 82/07/30 1p.
 14213:301.

B208100145 PND-V-82-033 on B20805, shipment containing 42 drums of low specific activity low level waste received from Nuclear Mats of Concord, MA w/lid off one drum. Licensee banned from site. Shipment placed in trench for disposal.
 THOMAS, R. D. Region 5, Office of Director. 82/08/05. 1p.
 14298:052.

B208100192 Forwards Waste Packaging Insp Rept 15000046/B2-10 on B20707. Noncompliance noted.
 BOOK, H. E. Region 5, Office of Director. 82/08/06. GRELLA, A. Fuel Facilities & Materials Branch. 1p. 14297:218.

DOCKETED ITEMS

--B208100196 Waste Packaging Insp Rept 15000046/B2-10 on B20707
Noncompliance noted incorrect placarding & failure to brace
shipment.
WAITE, J. A., THOMAS, R. D., BODK, H. E. Region 5, Office of Director
82/08/06 US Ecology, Inc. (Formerly Nuclear Engineering) 13pp
14297 219

B209240407 Forwards IE Waste Packaging Insp Rept 15000046/B2-11 on
B20728
BCDA, H. E. Division of Radiological Safety & Safeguards Program
82/08/17 ORELLA, A. Fuel Facilities & Materials Branch 1p.
14522 316

--B208240410 IE Waste Packaging Insp Rept 15000046/B2-11 on B20728
Noncompliance noted. shipment received from TVA Browns Ferry
Nuclear Plant was inspected & nine boxes identified w/o
radioactive low-specific activity markings
STEWART, N. J., THOMAS, R. D., BODK, H. E. Region 5, Office of Director
82/08/17 US Ecology, Inc. (Formerly Nuclear Engineering) 2pp.
14522 317

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-C086 W. R. GRACE & CO., POMPTON PLAINS, NJ

B208250061 Responds to FOIA request for documents re NRC activities
concerning Sheffield Brook & matl re radiation in Wayne, NJ.
Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records. 82/06/17. AMST, D.
Record, The Hackensack, NJ 10pp 14560 003

--B201140133 Summary of 811124 & 25 discussions w/HR Grace Chemical Co
re radiological survey plan for Pompton Plains site.
CROW, W. T. Uranium Fuel Licensing Branch 81/11/30 Uranium
Fuel Licensing Branch. 2pp 14561 216

--B208250066 Issues License R-132, authorizing receipt, possession & title
to unlimited raw source matl. Related info encl.
JOHNSON, L. Atomic Energy Commission. 54/04/01. STONE, R. L. Rare
Earths, Inc. 3pp 14560 013

--B208250067 Forwards renewed Source Matl License STA-422.
HARMON, D. F. Atomic Energy Commission. 68/02/26 GARINO, P. J. W.
R. Grace & Co. 1p 14560 330

--B208250072 Issues License R-132, authorizing receipt, possession & title
to unlimited raw source matl from producers & distributors
licensed by AEC & through importation, for processing only.
Related info encl.
JOHNSON, L. Atomic Energy Commission. 56/07/25 STONE, R. L. Rare
Earths, Inc. 7pp 14560 048

--B208250073 Renewed Source Matl License STA-422 for W. R. Grace & Co.
Davison Chemical Div. authorizing unlimited use of thorium
for ore processing
* Atomic Energy Commission 68/02/26 2pp 14560 331

--B208250077 Forwards guidance in response to 569629 ltr re proposed
receipt of 100 lb thorium bomb reduction residues.
JOHNSON, L. Atomic Energy Commission. 56/07/25 HANDLE, R. M. W.
R. Grace & Co. 1p 14560 055

--B208250080 Issues Revision 1 to License R-132, authorizing use of
100 lb thorium bomb reduction residues for experimental
processing at Curtis Bay, MD.
JOHNSON, L. Atomic Energy Commission. 56/08/15. HANDLE, R. M. Rare
Earths, Inc. 1p. 14560 056

1209250082 Forwards Revision 1 to Source Matl License R-132, authorizing
procurement of 100 lb thorium bomb reduction residues.
JOHNSON, L. Atomic Energy Commission. 56/08/20 HANDLE, R. M. Rare
Earths, Inc. 1p 14560 057

--B208250084 Insp Findings & Licensee Act dtd 681204 of License STA-422.
Noncompliance noted: records of surveys or disposals not
properly maintained.
* Atomic Energy Commission. 68/12/04. 1p. 14560 341

--B208250086 Forwards Form AEC-591, listing items of compliance noted
during 681204 Insp W/o Form. Related info encl.
KIRKMAN, R. W. Atomic Energy Commission. 68/12/06 BWEITZER, H. W.
R. Grace & Co. 18pp. 14560 342

--B208250089 Requests transfer of License R-132 to Davison Chemical Co.
Div of W. R. Grace & Co. Baltimore, MD.
STONE, R. L. Rare Earths, Inc. 56/12/21. JOHNSON, L. Atomic Energy
Commission. 2pp. 14560 060

--B208250091 Summarizes 681220 telcon w/P Garino re spill of natural
thorium in unrefined ore near Wayne, NJ. No hazard associated
w/spill. Matl exempt from AEC regulation. No further action
planned. Related info encl.
CLEVELAND, R. S. Atomic Energy Commission. 69/01/06. ROEDER, J. R.
Atomic Energy Commission. 2pp. 14561 008

--B208250093 Confirms RL Stone 561221 ltr re liquidation of Rare Earths,
Inc. Request for transfer of License R-132 to Davison
Chemical Co. reinstated.
BARRETT, D. P. W. R. Grace & Co. 57/01/14. JOHNSON, L. Atomic
Energy Commission. 1p. 14560 062

--B208250094 Notifies of discontinuation of monazite processing on
710407. Storage license requested.
GARINO, P. J. W. R. Grace & Co. 71/04/06. Atomic Energy
Commission. 1p 14561 010

--B208250102 Discusses 710408 telcon w/R Stone re discontinued production
of licensed matl at facility. No further action recommended.
STEARNS, C. F. Atomic Energy Commission. 71/04/21. NELSON, R. P.
Atomic Energy Commission. 1p 14561 011

--B208250105 Forwards application for renewal of Source Matl License
R-196
BARRETT, D. P. W. R. Grace & Co. 58/03/10. JOHNSON, L. Atomic
Energy Commission. 1p. 14560 066

--B208250106 Issues Amend 1 to Source Matl License STA-422 to authorize
thorium storage only.
LAVFIELD, L. Atomic Energy Commission. 71/04/23 GARINO, P. J. W.
R. Grace & Co. 1p. 14561 012

--B208250110 Notifies of expiration of Source Matl License STA-422 on
730228
HALARO, J. C. Atomic Energy Commission. 72/12/27. W. R. Grace &
Co. 4pp. 14561 013

--B208250112 Forwards application for renewal of storage License
STA-422. Related info encl.
MOBLEY, B. L. W. R. Grace & Co. 73/12/14. ROUSE, L. Atomic Energy
Commission, Directorate of Licensing. 6pp. 14561 017

--B208250114 Application for renewal of Source Matl License R-196.
* W. R. Grace & Co. 58/04/11. 1p 14560 067

--B208250117 Discusses 731206 telcons w/J Mettger & Mobley re Source
Matl License STA-422. No problem w/leaving burial matl on
property.
SMITH, R. Atomic Energy Commission. 73/12/06. Atomic Energy
Commission. 3pp. 14561 026

--B208250118 Issues Source Matl License R-196, authorizing possession of
unlimited quantities of thorium-containing matl for
processing at Pompton Plains, NJ & Curtis Bay, MD facilities.
DELANEY, J. C. Atomic Energy Commission. 58/03/13. BARRETT, D. P.
W. R. Grace & Co. 1p. 14560 068

--B208250119 Forwards application to renew Source Matl License R-196.
BARRETT, D. P. W. R. Grace & Co. 59/03/19. DELANEY, J. C. Atomic
Energy Commission. 1p. 14560 069

--B208250120 Forwards fee for renewal of Source Matl License STA-422,
authorizing matl storage, per 731226 telcon.
MOBLEY, B. L. W. R. Grace & Co. 74/01/03. WEISS, D. Atomic Energy
Commission. 1p. 14561 029

--B208250122 Application for renewal of Source Matl License STA-422,
authorizing continued use of storage facilities.
MOBLEY, B. L. W. R. Grace & Co. 73/12/14. 2pp. 14561 030

--B208250123 Issues Source Matl License R-196, authorizing possession of
thorium-containing matl for processing at Pompton Plains, NJ
& Curtis Bay, MD plants.
DELANEY, J. C. Atomic Energy Commission. 53/03/27. BARRETT, D. P.
W. R. Grace & Co. 1p. 14560 071

--B208250124 Requests application fee for renewal of License STA-422 in
response to 731214 ltr. Related info encl.
MILLER, W. D. Atomic Energy Commission. 74/01/03. SHAW, F. W. R.
Grace & Co. 2pp. 14561 032

--B208250125 Requests advice re importation of 5 lb normal U dioxide from
Canada.
PRICE, A. L. W. R. Grace & Co. 59/04/29. DELANEY, J. C. Atomic
Energy Commission. 1p. 14560 072

08250134 Discusses telcon w/ O Epstein re close-out survey of facility. Further decontamination required prior to release for unrestricted use. Related info encl.
BUCHANAN, Atomic Energy Commission 74/08/06 SINGER, B. Atomic Energy Commission 13pp. 14561:136.

08250136 Forwards compliance insp rept of Licenses R-196, R-132 & R-3623. Noncompliance noted excess radiation levels in restricted areas, failure to perform radiation surveys & improper storage of licensed matl w/o encl.
KIRKMAN, R. W. Atomic Energy Commission. 60/01/26 Atomic Energy Commission 3pp. 14560:089.

08250139 Requests renewal of License R-196 to receive & process thorium-containing matl at facility.
TONQUE, T. O. W. R. Grace & Co. 60/02/11. DELANEY, J. C. Atomic Energy Commission 1p. 14560:092.

08250140 Ack receipt of 600211 application to renew License R-196.
DELANEY, J. C. Atomic Energy Commission 60/02/15 TONQUE, T. O. W. R. Grace & Co. 1p. 14560:093.

08250142 Ack receipt of 600211 application to renew License R-196.
DELANEY, J. C. Atomic Energy Commission. 60/02/17. TONQUE, T. O. W. R. Grace & Co. 1p. 14560:094.

08250146 Discusses 591125 insp. No noncompliance noted re License R-3623. Noncompliance noted re License R-196: failure to conduct radiation surveys & improper radwaste disposal.
JOHNSON, L. Atomic Energy Commission. 60/03/14. BARRETT, D. P. W. R. Grace & Co. App. 14560:095.

08250151 Discusses 600408 telcon w/ DC Hubbard of Davison Chemical Co confirming AEC 600413 visit to investigate 600314 notice of violation.
PAGE, R. O. Atomic Energy Commission. 60/04/08. Atomic Energy Commission 1p. 14560:099.

08250153 Summary of 600413 meeting w/ DLR & Davison Chemical Co to discuss compliance status of Pompton Plains, NJ facility.
NELTY, C. O. Atomic Energy Commission. 60/05/24 Atomic Energy Commission 2pp. 14560:100.

08250155 Forwards final rept re decontamination of facility. Release of facility for unrestricted use & termination of storage license requested w/o encl.
MOBLEY, B. L. W. R. Grace & Co. 74/09/16. SINGER, B. Atomic Energy Commission. 1p. 14561:148.

08250158 Ack receipt of 600411 ltr informing of corrective actions taken in response to violations noted in AEC 600314 ltr. Application to release source matl to unrestricted areas not received.
JOHNSON, L. Atomic Energy Commission. 60/06/06. BARRETT, D. P. W. R. Grace & Co. 1p. 14560:102.

08250159 Forwards RO Insp Rept 40-0086/74-01.
NELSON, P. R. Atomic Energy Commission. 74/10/22. THORNBURG, H. D. Atomic Energy Commission. 1p. 14561:149.

08250166 RO Insp Rept 40-0086/74-01 on 740731-0920 re close-out survey of facility. Final survey results showed agreement w/ license results.
EPSTEIN, E., MCCLINTOCK, R. Atomic Energy Commission. 74/10/08. 22pp. 14561:150.

08250167 Forwards "Health Physics Manual" & "Procedures for Measurement of Radioactivity."
TONQUE, T. O. W. R. Grace & Co. 60/06/29. JOHNSON, L. Atomic Energy Commission. 1p. 14560:104.

08250174 Submits addl info for release of facility per 741029 telcon. Burial area graded, dressed w/ fill dirt & seeded. Drainage measurements failed to disclose any radioactivity.
MOBLEY, B. L. W. R. Grace & Co. 74/10/30. SINGER, B. Atomic Energy Commission. 1p. 14561:172.

08250182 Discusses close-out survey of facilities for release to unrestricted use. New owner should be licensed to possess buried thorium or matl should be transferred to authorized disposal site.
RDY, W. Atomic Energy Commission. 74/11/07. NELSON, P. R. Atomic Energy Commission. 2pp. 14561:174.

--8208250187 Transcript re point of noncompliance noted during 1964 insp of facility concerning radwaste burial. Reburial completed in accord w/ exact requirement following citing.
GARINO, P. J. Affiliation Unknown. 74/12/16. Atomic Energy Commission. 1p. 14561:176.

--8208250188 Advises re deferred reinspection scheduling of licensee pending receipt of info that enforcement action has been completed.
WARNER, D. E. Atomic Energy Commission. 61/03/15. ROGER, L. R. Atomic Energy Commission 1p. 14560:174.

--8208250193 Transcript re reburial of radwaste at facility during 1964-65.
BAUM, J. Affiliation Unknown. 74/12/16. Atomic Energy Commission. 1p. 14561:177.

--8208250199 Recommends release of unrestricted property, based on licensee statements of compliance. Land records should indicate that matl has been buried on property.
LIEBERMAN, J. Office of the General Counsel. 75/01/09. BUCHANAN, C. NRC - No Detailed Affiliation Given 1p. 14561:178.

--8208250200 Compliance insp rept on 610629. No noncompliance noted. Major areas inspected: previous items of noncompliance re maint of records, inventories, receipts & transfers of refined source matl.
KLEVIN, P. B., KIRKMAN, R. Atomic Energy Commission. 61/06/29. 9pp. 14560:176.

--8208250201 Advises that property meets decontamination criteria for release of facilities for unrestricted use, based on 740909 survey rept & 0916, 1030 & 1217 ltrs.
SINGER, B. Office of Nuclear Material Safety & Safeguards, Director. 75/01/22. MOBLEY, B. L. W. R. Grace & Co. 1p. 14561:179.

--8208250204 Responds to request for release of property formerly under License STA-422 for unrestricted use. Property meets decontamination criteria & can be released for unrestricted use. Radwaste should be buried per 10CFR20.304 (1974).
SINGER, B. Office of Nuclear Material Safety & Safeguards, Director. 75/01/22. MOBLEY, B. L. W. R. Grace & Co. 1p. 14561:180.

--8208250206 Advises that next inspector should assure that new facility owner is licensed. Related info encl.
MCCLINTOCK, R. O. NRC - No Detailed Affiliation Given. 75/02/19. NRC - No Detailed Affiliation Given. 12pp. 14561:181.

--8208250222 Advises that preliminary evaluation of Pompton Plains site indicates surface radiation up to 1 m/h. Site does not meet criteria for release for unrestricted use.
JOYNER, J. H. Division of Engineering & Technical Inspection. 81/07/30. HIGGINSBOTHAM, L. Radiological Safety Branch. 6pp. 14561:196.

--8208250226 Forwards Region 1 file for License STA-422, including requested insp repts. w/o encl.
JOYNER, J. H. Technical Inspection Branch. 81/08/25. CROW, W. T. Uranium Fuel Licensing Branch. 1p. 14561:202.

--8208250231 Requests review of Pompton Plains, NJ site to determine legal responsibility for remedial action.
HIGGINSBOTHAM, L. Radiological Safety Branch. 81/09/18. CUNNINGHAM, Q. Office of the Executive Legal Director. 1p. 14561:203.

--8208250236 Advises that request for legal interpretation of responsibility for remedial action at Pompton Plains, NJ site has been initiated in response to 810730 memo.
HIGGINSBOTHAM, L. Radiological Safety Branch. 81/09/18. NRC - No Detailed Affiliation Given. 1p. 14561:204.

--8208250237 Requests authorization to burn 100 lb of burlap bags containing monazite sand.
GARINO, P. J. W. R. Grace & Co. 61/07/03. JOHNSON, L. Atomic Energy Commission. 1p. 14560:198.

--8208250242 Forwards Region 1 request for survey of Pompton Plains, NJ site. Tentative completion date requested.
HIGGINSBOTHAM, L. Radiological Safety Branch. 81/09/18. PAGE, R. O. Uranium Fuel Licensing Branch. 2pp. 14561:205.

CARLINO, P. J. W. R. Grace & Co. 61/07/08 JOHNSON, L. Atomic Energy Commission 2pp 14560 199

--8208250249 Advises that radiological survey of Pompton Plains site will be initiated, in response to 810918 request
PAGE, R. O. Uranium Fuel Licensing Branch 81/10/08
HICGINSBOTHAM, L. Radiological Safety Branch 1p 14561 208

--8208250251 Advises that no items of noncompliance noted during 810629 insp
ALEVIN, P. B. Atomic Energy Commission 61/07/19 HANDLE, R. W. R. Grace & Co. 2pp 14560 201

--8208250259 Requests preliminary site visit & development of radiological survey plan for Pompton Plains, NJ site.
WILDE, R. H. Uranium Fuel Licensing Branch FIN A-9093 81/10/08
CRESHAM, J. R. Office of Nuclear Material Safety & Safeguards, Director 2pp 14561 209

--8208250261 Requests full rept on 810629 insp of facility.
CUNNINGHAM, R. E. Atomic Energy Commission 61/07/28 DUBINSKI, L. Atomic Energy Commission 1p 14560 205

--8208250266 Forwards summary licensing history of facility & file for License STA-422, per request
KINNEMAN, J. D. Materials Radiological Protection Section 81/10/27
FOMMER, R. Office of the Executive Legal Director. 4pp 14561 211

--8208250267 Submits application for new source matl license for unlimited amount of matl for use in rare earth operations in Pompton Plains, NJ
TOAQUE, T. O. W. R. Grace & Co. 61/08/02 JOHNSON, L. Atomic Energy Commission 2pp 14560 206

--8208250273 Forwards excerpt from "clear" compliance insp rept of facility
KIRKMAN, R. W. Atomic Energy Commission 61/08/07 LOWENSTEIN, R. Atomic Energy Commission 3pp 14560 208

--8208250275 Confirms 811125 discussion re preliminary visit to site during wk of 811207 Final comprehensive survey plan & tentative schedule will be provided.
CROW, W. T. Uranium Fuel Licensing Branch 81/11/27 HARDWICKE, J. W. R. Grace & Co. 1p 14561 215

--8208250278 Requests complete rept of 810629 insp of facility to assist in license application processing
DUBINSKI, L. Atomic Energy Commission 61/08/08 KIRKMAN, R. W. Atomic Energy Commission 1p 14560 211

--8208250283 Ack receipt of 810719 "clear" notice of insp on 810629. Further enforcement action unnecessary
CUNNINGHAM, R. E. Atomic Energy Commission. 61/08/10
NUSSBAUMER, D. Atomic Energy Commission. 1p 14560 212

--8208250285 Forwards licensing history of WR Grace & Co. Pompton Plains, NJ facility
CAMPBELL, M. Region 1, Philadelphia, Office of the Director (81/03/01). 81/11/30. SLY, D. Director's Office, Office of Inspection and Enforcement 4pp 14561 218

--8208250288 Forwards "clear" followup insp rept for facility
KIRKMAN, R. W. Atomic Energy Commission. 61/08/17. LOWENSTEIN, R. Atomic Energy Commission. 1p 14560 213

8208250291 Forwards GA Program Insp Rept 99990001/81-21, in response to 811125 request
MAYES, R. Region 1, Philadelphia, Office of the Director (81/03/01). 81/11/30. STELL, D. V. Regional Operations & Generic Requirements 4pp 14561 222

--8208250293 Forwards historical background & summary of WR Grace insp rept
CAMPBELL, M. Region 1, Philadelphia, Office of the Director (81/03/01). 81/12/01. SLY, D. Region 1, Philadelphia, Office of the Director (81/03/01) 2pp 14561 250

--8208250299 Confirms results of 811214 meeting re WR Grace site in Pompton Plains, NJ Characterization of potential radiological visit to public from crest holds priority.
THORNBURG, M. D. Division of Safeguards & Radiological Safety Inspection. 81/12/16 MAUSKARDT, D. Office of Nuclear Material Safety & Safeguards, Director. 1p 14561 256

--8208250310 Forwards GA Program Insp Rept 99990001/81-21 More details surveys will be performed in 1982.
MARTIN, T. F. Technical Inspection Branch 81/12/30 FELDMAN, J. Environmental Protection Agency 1p 14561 239

--8208250313 Submits analysis, findings & conclusions from radiological safety evaluation of facility Licensee complies w/AEC regulations.
HARMON, D. F. NUSSBAUMER, D. A. Atomic Energy Commission 61/10/08 Atomic Energy Commission 3pp 14560 227

--8208250315 Discusses 820218 telcon w/J Kinneinan re preliminary site visit on 820226 to formulate plans for radiological survey Project assigned to R Pace
CROW, W. T. NRC - No Detailed Affiliation Given. 02/02/19
PAGE, R. O. NRC - No Detailed Affiliation Given 2pp 14561 261

--8208250317 Forwards Source Matl License STA-422 Special request required for utilizing respirators in determination of airborne radioactivity exposure Related info encl
NUSSBAUMER, D. A. Atomic Energy Commission 61/11/22 HANDLE, R. W. R. Grace & Co. 2pp 14560 230

--8208250321 Source Matl License BUA-442 for WR Grace & Co. Davison Chemical Div. authorizing use of unlimited thorium for processing.
NUSSBAUMER, D. Atomic Energy Commission 61/11/22. 1p 14560 232

--8208250325 Notifies of insp on 640701 re status of compliance w/ 10CFR30.40 & 20 Related info encl
KIRKMAN, R. W. Atomic Energy Commission 64/06/24 HANDLE, R. W. R. Grace & Co. 2pp 14560 235

--8208250327 Summary of 811214 meeting w/DOE to discuss WR Grace & Co. facility in Pompton Plains, NJ DOE agreed to inform NRC re decision on remedial action List of attendees encl.
CAMPBELL, M. A. Region 1, Office of Director. 02/03/24.
KINNEMAN, J. D. Region 1, Office of Director 3pp 14561 266

--8208250329 "Proposed Radiological Survey Plan, WR Grace Property Pompton Plains, NJ."
* NRC - No Detailed Affiliation Given 02/03/15 1pp 14561 269

--8208250330 Responds to 640717 notice of noncompliance Corrective actions: surface contamination surveys conducted & thorium sludge burial method modified. Decontamination procedures encl
HANDLE, R. M. W. R. Grace & Co. 64/07/24 KIRKMAN, R. W. Atomic Energy Commission. 3pp 14560 237

--8208250332 Summary of 820226 meeting w/Dak Ridge Associated Univs. WR Grace & Co. & Electro-Nuclear, Inc to provide first hand info re site geography & briefing concerning radiological survey. Public notification recommended.
CAMPBELL, M. Region 1, Office of Director 82/04/01 KINNEMAN, J. Region 1, Office of Director. 2pp 14561 277

--8208250334 Application for renewal of Source Matl License STA-422, for use of unlimited quantities of thorium for ore processing.
SHEITZER, H. J. W. R. Grace & Co. 67/11/03. 3pp 14560 262

--8208250337 Responds to 670310 inquiry re license Source Matl License STA-422 issued on 641012, authorizing possession of unlimited quantity of thorium.
KIRKMAN, R. W. Atomic Energy Commission. 67/03/20 Marcus & Levy. 1p 14560 255

--8208250338 Notice of violation from insp on 640701 Noncompliance not surveys to determine concentrations of removable surface contamination in restricted & unrestricted areas conducted.
EPSTEIN, E. Atomic Energy Commission. 64/07/17. 1p 14560 240

--8208250343 Notifies of expiration of License STA-422 on 641031. Application for license renewal should be filed if program continues.
NUSSBAUMER, D. Atomic Energy Commission. 64/09/02. W. R. Grace & Co. 1p 14560 243

250347 Application for renewal of Source Matl License STA-422, authorizing possession of unlimited quantities of thorium for processing
W. R. Grace & Co. 64/09/21. 1p. 14560:244

250348 Summary of 820416 meeting w/Mayor of Wayne Township, NJ re contamination at WR Grace facility
KINNEMAN, J. D. Region 1, Office of Director. 82/04/28.
JOYNER, J. H. Region 1, Office of Director. 1p. 14561:319.

250352 Forwards application for renewal of Source Matl License STA-422
KINNEMAN, J. D. W. R. Grace & Co. 64/09/18. Atomic Energy Commission. 1p. 14560:245

250359 Forwards renewed Source Matl License STA-422.
NUSSBAUMER, D. Atomic Energy Commission. 64/10/12. STONE, R. L. W. R. Grace & Co. 1p. 14560:247

250364 Concurs that present exemption inappropriate in response to 10923 ltr re amend to 10CFR20, Section 20.203(f)
GARINO, P. J. W. R. Grace & Co. 66/10/07. NUSSBAUMER, D. Atomic Energy Commission. 1p. 14560:250.

250365 Amends Source Matl License STA-422 per 661007 application. License exempt from requirements of 10CFR20, Section 20.203 (f)(2), provided all entrances to plant are conspicuously posted
HARMON, D. F. Atomic Energy Commission. 66/11/04. GARINO, P. J. W. R. Grace & Co. 1p. 14560:251.

250366 Notices of 661107 Insp of facilities re compliance with 10CFR30, 32, 33, 34, 35, 40 & 70
KINNEMAN, R. W. Atomic Energy Commission. 66/11/13. GARINO, P. J. W. R. Grace & Co. 1p. 14560:252.

250368 Submits evaluation of compliance insp. Licensee has corrected deficiencies. No apparent health & safety irregularities found
FRANK, W. B. Atomic Energy Commission. 66/11/30. Atomic Energy Commission. 1p. 14560:254.

250369 Advises that Source Matl License STA-422 expires on 11/03/1 Application for license renewal should be filed if program continues.
NUSSBAUMER, D. Atomic Energy Commission. 67/08/28. GARINO, P. J. W. R. Grace & Co. 1p. 14560:256

250370 Application for renewal of Source Matl License STA-422, authorizing use of unlimited quantity of thorium for ore processing.
WEITZER, H. J. W. R. Grace & Co. 67/09/19. 1p. 14560:257.

250371 Requests filling of new application for Source Matl License STA-422 w/o ref to previous application 30-days prior to license expiration.
HARMON, D. F. Atomic Energy Commission. 67/10/06. SWEITZER, H. J. W. R. Grace & Co. 1p. 14560:259.

250372 Requests that encl process description re breakup of monazite sands be treated as company confidential matl & withheld from PDR.
WEITZER, H. J. W. R. Grace & Co. 67/11/03. HARMON, D. F. Atomic Energy Commission. 2pp. 14560:260.

250373 Forwards process description for breaking monazite sands into rare earth & thorium compounds & "Health Physics Manual." Includes procedures for measurement of radioactivity.
GARINO, P. J. W. R. Grace & Co. 68/02/13. HARMON, D. F. Atomic Energy Commission. 4pp. 14560:266.

250378 "Health Physics Manual."
GARINO, P. J. W. R. Grace & Co. 67/10/10. 36pp. 14560:270.

250381 Advises of corrective measures taken in response to insp on 11123. Surveys to determine external radiation levels in & around plant set up on monthly basis to include all areas where source matl used or stored.
MONQUE, T. O. W. R. Grace & Co. 60/04/11. JOHNSON, L. Atomic Energy Commission. 2pp. 14561:333.

TONQUE, T. O. W. R. Grace & Co. 60/06/20. JOHNSON, L. Atomic Energy Commission. 9pp. 14561:335

--8208250389 Forwards statements of PJ Garino & JJ Baum supporting release of facilities in Wayne, NJ.
MOBLEY, B. L. W. R. Grace & Co. 74/12/17. BINGER, B. Atomic Energy Commission. 2pp. 14561:349

--8208250392 Summary of 780905 meeting w/DOE in Germantown, MD re WR Grace site in Curtis Bay, MD. Company will submit complete radiological survey of disposal area by 781001. Related info encl.
KINNEMAN, J. D. Office of Nuclear Material Safety & Safeguards, Director. 78/09/22. Office of Nuclear Material Safety & Safeguards, Director. 13pp. 14561:353

8208130227 Provides results of 820630 soil sample analysis of three low level hot spots near railroad siding north of old Pompton Plains, NJ railroad station. Th-121 concentrations indicate no immediate hazard.
KINNEMAN, J. D. Division of Engineering & Technical Programs. 82/08/09. FITZPATRICK, F. Pequannock, Township of, NJ. 1p. 14333:142

--8208130236 Requests results of soil sample analysis of three low level hot spots near railroad siding north of old Pompton Plains, NJ railroad station
FITZPATRICK, F. Pequannock, Township of, NJ. 82/07/12. CAMPBELL, M. Region 1, Office of Director. 1p. 14333:143

8208180003 Informs that rept re Oak Ridge Associated Univs surveys will be completed by late Aug or early Sept. Final rept will not be available until Dec 1982. Aerial radiological survey indicates no hazard to nursing home.
KINNEMAN, J. D. Region 1, Office of Director. 82/08/11. HAVERMANN, B. Willowbrook Nursing Home Wayne, NJ. 1p. 14378:289.

8208200070 Forwards "Radiological Surveys of Sheffield Brook." preliminary rept.
MOBLEY, B. W. R. Grace & Co. 82/08/16. JOYNER, J. H. Division of Engineering & Technical Programs. 2pp. 14392:262.

--8208200081 "Radiological Surveys of Sheffield Brook." preliminary rept.
FRANK, P. W., BERGER, COLE, L. W. Oak Ridge Associated Univ. 82/07/31. 57pp. 14392:264.

DOCKET 40-0299 UNION CARBIDE CORP., GRAND JUNCTION, CO

8208050045 Discusses 820621 telcon w/H Pettengill of NRC re status of Land Quality Div schedule for review of Union Carbide tailings reclamation plan. Review completed & forwarded to NRC.
FRANCIS, E. Wyoming, State of. 82/06/23. Wyoming, State of. 3pp. 14244:031.

8208040044 Forwards summary on reclamation performance bonding for Oak Hills mining operation. Bonds require recalculation
WONG, T. Union Carbide Corp. 82/07/12. FLEMING, T. NRC - No Detailed Affiliation Given. 3pp. 14232:361.

8208040292 Grants 820707 request for extension until 820815 to answer 820614 requests, in form of revisions to tailing & heap leach reclamation plan.
ACKERMAN, W. C. Wyoming, State of. 82/07/13. WONG, T. Union Carbide Corp. 5pp. 14232:273.

DOCKET 40-0460 WASHINGTON PUBLIC POWER SUPPLY SYSTEM, RICHLAND, WA

8208200090 Forwards corporate organizational changes effective 820810. Changes will be reflected in future revisions to FEAR & operational GA program description.
BOUCHEY, G. D. Washington Public Power Supply System. 82/08/16. NOVAK, T. H. Assistant Director for Licensing. 4pp. 14393:241. 24x Fiche: 80-397, 82/08/16. 8208200090

DOCKET 40-0301 ALUMINIUM CO. OF AMERICA

8208230206 Forwards IE Insp Rept 40-0501/82-01 on 820629 No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 82/08/06. GEIGER, R. Aluminum Co. of America. 2pp. 14513:209.

--8208230214 IE Insp Rept 40-0501/82-01 on B20629 No noncompliance noted. Major areas inspected formerly licensed site engaged in production of magnesium thorium casting alloys, including interviews w/site owners.
JOHANSEN, J. H. KINNEHAN, J. D. Region I. Office of Director.
82/07/28. 6pp. 14513:211

--8208230222 Source Matl License C-5023 for Aluminum Co of America authorizing use of 1,600 lb source matl for experimental use for production of magnesium thorium casting alloys.
DELANEY, J. C. Atomic Energy Commission, Directorate of Licensing
60/01/11. ZAKES, R. H. Aluminum Co of America. 3pp. 14513:214

8208230229 Forwards IE Insp Rept 40-0501/82-01 on B20629 No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 82/08/06
GRUBER, C. Gruber Supply Corp. 2pp. 14513:334.

8208230236 Forwards IE Insp Rept 40-0501/82-01 on B20629 No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 82/08/06
MURLEY, J. CPC International Inc. 2pp. 14508:341.

DOCKET 40-0472 NUCLEAR METALS, INC., CONCORD, MA

8208060240 Requests addl info re rept on Last Quarter 1981 skin dose to employer, per B20301 ltr. Info requested within 14 days Rept withheld (ref 10CFR2.790)
MARTIN, T. T. Division of Engineering & Technical Programs. 82/07/21
VUMBACO, F. Nuclear Metals, Inc. 2pp. 14241:318

8208310421 Advises that B20818 request for extension to respond to IE Insp rept forwarded in NRC B20721 ltr granted Response to be submitted by B20927.
KINNEHAN, J. D. Division of Engineering & Technical Programs
82/08/26. TRIFFIN, W. B. Nuclear Metals, Inc. 1p. 14693:289.

--8208310423 Requests 30-day extension to respond to B20721 ltr re rept on 1981 last quarter skin dose to employee, contained in IE Insp rept.
VUMBACO, F. J. Nuclear Metals, Inc. 82/07/29. MARTIN, T. T. Region I, Office of Director. 1p. 14693:290

DOCKET 40-1162 WESTERN NUCLEAR CORP., JEFFREY CITY, MO

8207220663 Forwards annual technical evaluation, "Insp & Surveillance of Embankment Retention Sys." required per License Condition 16.
BOGDEN, O. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.)
82/06/30. PETTENGILL, H. J. Uranium Recovery Licensing Branch. 2pp. 14024:022.

--8207220673 "Insp & Surveillance of Embankment Retention Sys." annual technical evaluation required per License Condition 16, for period Jul 1981-May 1982, w/16 oversize drawings. Aperture cards are available in PDR.
* Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 82/06/29. 38pp. 14024:024.

8208090025 Forwards "Split Rock Mill Water Quality Rept." Jan-Mar 1982. Rept includes groundwater, drinking water & surface water results.
BOGDEN, O. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.)
82/06/30. PETTENGILL, H. J. Uranium Recovery Licensing Branch. 2pp. 14301:172.

--8208090026 "Split Rock Mill Water Quality Rept." Jan-Mar 1982. Three oversize maps encl. Aperture cards are available in PDR.
* Western Nuclear, Inc. (subs. of Phelps Dodge Corp.) 82/06/30. 33pp. 14301:174.

8208170393 Responds to request for addl info re B20319 & 0520 submittals of environ monitoring data. In future repts, concentrations of radionuclides in water will be reported in units of uCi/ml.
BOGDEN, O. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.)
82/07/16. PETTENGILL, H. J. Uranium Recovery Licensing Branch. 2pp. 14372:326.

8208240481 Informs that Wells 17, 18, 19 & 23 located on floodplain to north/northwest of permit boundary presently inaccessible for sampling period. Addendum to third quarter 1982 groundwater monitoring rept will be submitted.
BOGDEN, O. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.)
82/07/16. PETTENGILL, H. J. Uranium Recovery Licensing Branch. 1p. 14344:163.

8208040070 Advises that all important items addressed in land use survey for Split Rock Mill.
GARCIA, P. J., PETTENGILL, H. J. Uranium Recovery Licensing Branch
82/07/20. Uranium Recovery Licensing Branch. 1p. 14228:284

DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP., OKLAHOMA CITY, OK

8208040630 Revision 0 to "Health Physics Manual for Decommissioning & Stabilization of Kerr-McGee Chemical Corp. West Chicago Rare Earths Facility."
LEVINE, A. J., OSGOOD, N. L. Kerr-McGee Corp. 81/09/22. 360pp. 14226:001.

8208020462 Comments re DES on decommissioning Rare Earths Facility. Proposal has no impact on prime or important farmlands. Consideration must be given to impact on adjoining residential & recreational tracts.
ECKES, J. J. Agriculture, Dept. of. 82/06/21. PAGE, R. Q. Uranium Fuel Licensing Branch. 1p. 14180:078.

8208230183 Forwards comments on DES for decommissioning Rare Earths Facility NRC should be prepared to monitor site for more than 3 yrs.
EARLEY, D. F. Affiliation Unknown. 82/06/21. Uranium Recovery Licensing Branch. 6pp. 14517:339

8208020447 Clarifies A Rapkin B20629 ltr confirming B20629 telcon re DES (NUREG-0904). Comments on DES should be submitted before B20706. All timely comments to be addressed before FES issuance. Comments received by end of Jul considered timely.
CROOK, W. T. Uranium Recovery Licensing Branch. 82/07/02. RAPKIN, A. Illinois, State of. 1p. 14181:044.

8208060004 Comments on DES for decommissioning of Rare Earths Facility, West Chicago, IL. Document only partially addresses waste problems & health hazards in West Chicago, IL area.
CAHILL, P. Environmental Protection Agency. 82/07/06. PAGE, R. Q. Uranium Fuel Licensing Branch. 4pp. 14272:360

8208130332 Requests copies of Argonne EIA studies re characterization of geohydrology & subsurface chemistry & site surface.
RAPKIN, A. Illinois, State of. 82/07/15. NIXON, W. A. Uranium Recovery Licensing Branch. 1p. 14340:244.

8208130327 Forwards comments re DES for decommissioning of Kerr-McGee Rare Earths, Inc. facility in West Chicago, IL.
QUESTAFBON, P. F. Illinois, State of. 82/07/27. PAGE, R. Q. Uranium Recovery Licensing Branch. 2pp. 14340:230.

8208240058 Forwards comments on DES (NUREG-0904) re decommissioning of Rare Earths Facility.
SHELLEY, W. J. Kerr-McGee Corp. 82/07/27. PAGE, R. Q. Licensing Policy & Programs Branch. 36pp. 14548:111.

8208130391 Comments on DES re decommissioning Rare Earths Facility, West Chicago, IL. DES does not clarify recommended action.
RAPKIN, A., FARNER, T. C. Illinois, State of. 82/07/29. PAGE, R. Q. Uranium Fuel Licensing Branch. 34pp. 14354:270

8208190029 Summary of B20728 meeting w/Kerr-McGee re views on NEPA issues raised in EPA B20706 ltr on decommissioning of Kerr-McGee Rare Earths facility. No decisions or conclusions reached.
NIXON, W. A. Uranium Fuel Licensing Branch. 82/07/30. Uranium Fuel Licensing Branch. 1p. 14506:360.

8207180028 FOIA request for all drafts or preliminary versions of NUREG-0904 re DES concerning decommissioning of facility.
RAPKIN, A. Illinois, State of. 82/08/05. Office of Administration. 2pp. 14567:354.

8208090165 Order CLE-82-21 directing NMSB director or designee to act as presiding officer to adjudicate City of West Chicago contentions challenging Kerr-McGee request for Amend 5 to license for Rare Earths Facility.
HOYLE, J. C. Office of the Secretary of the Commission. 82/08/06. Kerr-McGee Corp. 3pp. 14271:355.

8208230212 Forwards questions & statements received at B20621 public meeting re Kerr-McGee Rare Earths Facility in West Chicago, IL.
* NRC - No Detailed Affiliation Given. 82/08/09. NRC - No Detailed Affiliation Given. 10pp. 14551:294.

8208260001 Responds to FOIA request for draft or preliminary versions of NUREG-0904, DES concerning decommissioning of facility. Selected records in PDR. Preliminary drafts withheld (ref FOIA Exemption 5).
FELTON, J. M. Division of Rules and Records. 82/08/16. RAPKIN, A. Illinois, State of. 2pp. 14567:355.

type of hearing granted. Findings of no public interest & lack of state upon which findings based.
ELLMAN, H. J. Harold J. Spelman & Associates. SPELMAN, H. J. West
Chicago, IL 82/08/23 HOYLE NRC - No Detailed Affiliation Given.
p. 14599 163

ET 40-2259 PATHFINDER MINES CORP., RIVERTON, WY

040079 Comments on licensee environ monitoring data & dose
evaluations for First Quarter 1982 submitted per License
Condition 34. Licensee in compliance w/40CFR190. Three minor
errors in reporting corrected.
LLENBERGER, D., PETTENGILL, H. J. Uranium Recovery Licensing Branch.
07/20. Uranium Recovery Licensing Branch. 6pp. 14228 294.

ET 40-3453 ATLAS MINERAL, INC., DENVER, CO

060189 Forwards IE Insp Rept 40-3453/82-01 on 820525-27 & notice
violation
OWN, O. D. Division of Vendor & Technical Programs. 82/06/23.
AVER, R. R. Atlas Minerals. 2pp. 13706 142.

07060191 Notice of violation from Insp on 820525-27.
Division of Vendor & Technical Programs. 82/06/23 2pp.
13706 144.

07060192 IE Insp Rept 40-3453/82-01 on 820525-27. Noncompliance noted:
Failure to prevent recurrence of 40-h control measure &
failure to select proper respiratory protection.
CAIN, C. L., SHOPENN, N. M., EVERETT, R. J. Region 4, Office of
Director. 82/06/16 11pp. 13706 146

060348 Discusses Atlas Minerals 820519 response to request for info
40CFR190 data. Background air monitoring site should be
located.

RCIA, P. J., PETTENGILL, H. J. Uranium Recovery Licensing Branch.
07/28. Uranium Recovery Licensing Branch. 2pp. 14281 281.

110009 Advises that licensee 820519 response to item 1 of NRC
0803 request for info re present location of background
r monitoring station unacceptable. Proposed site for
location of station requested by 820501.

TTENGILL, H. J. Uranium Recovery Licensing Branch. 82/07/28.
UBAUGH, R. E. Atlas Minerals. 1p. 14330 292.

110193 Ack receipt of 820720 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept.
OWN, O. D. Division of Vendor & Technical Programs 82/08/05.
UBAUGH, R. E. Atlas Minerals. 1p. 14323 266.

08120196 Responds to NRC 820623 ltr re violations noted in IE Insp
rept. Corrective actions: taller of environ air samplers
performed on 820228 & Kurz Intl. Inc notified that extended
turn-around time is unacceptable.
UBAUGH, R. E. Atlas Minerals. 82/07/20. BROWN, O. D. Division of
Vendor & Technical Programs. 3pp. 14323 267.

ET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY

04040306 Forwards water quality data requested in 820625 telcon.
TTB, K. Federal American Partners. 82/06/28. GILLEN, D. Division
Fuel Cycle & Material Safety. 11pp. 14223 269.

06040295 Ack receipt of 820610 ltr re Tailings Pond 1 & proposal for
n-pit tailings disposal. DES will be issued re proposed use
of tailings ponds as evaporation ponds & sagebrush pit for
surface disposal.
NDRUS, N. J. Federal American Partners. 82/07/19. ACKERMAN, W. C.
oming, State of. App. 14223 308.

ET 40-6622 PATHFINDER MINES CORP., SHIRLEY BASIN, WY

0270556 Forwards one oversize topographic map requested by License
Condition 41 of License SUA-442. Amend 7. Aperature card is
available in PDR.
HITH, J. C. Pathfinder Mines Corp. 82/07/20. Uranium Recovery
Licensing Branch. 1p. 14683 221.

8208040168 Application for amend of License SMB-920, correcting Form
NRC-2, Item 2 re name change of corporation.
COYLE, F. T. Cabot Corp. 82/06/18. CROW, W. T. Uranium Fuel Licensing
Branch. 43pp. 14236 316.

DOCKET 40-7138 YANKEE ATOMIC ELECTRIC CO., WESTBOROUGH, MA

8208270010 Responds to FOIA request for documents detailing collective
dose exposures in 1981 for operating nuclear power plants &
analyzing said info. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A.
Critical Mass Energy Project. 8pp. 14679 208. 24X
Fiche: 80-000, 82/07/13, 8208270010.

--8208270629 Forwards whole body range rept for CY81, per 10CFR20.407.
MOODY, D. E. Yankee Atomic Electric Co. 82/03/12. HALLER, N. M.
Office of Management and Program Analysis. 1p. 14680 050. 24X
Fiche: 80-000, 82/07/13, 8208270010.

--8208270638 Whole body range rept for CY81.
TRIJD, J., ANTIU, H. A. Yankee Atomic Electric Co. 82/03/08. 1p.
14680 051. 24X Fiche: 80-000, 82/07/13, 8208270010.

DOCKET 40-7604 VISTRON CORP., LIMA, OH

8208270552 Forwards IE Insp Rept 40-7604/82-01 on 820712-16 & 26.
No noncompliance noted.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational
Support. 82/08/11. SHOWER, R. C. Vistron Corp. 2pp. 14566 047.

--8208270557 IE Insp Rept 40-7604/82-01 on 820712-16 & 26. No
noncompliance noted. Major areas inspected: site radiological
status for license termination, shipping papers to confirm
offsite disposal of U-238 & effluent piping diagrams.
NICHOLSON, N. A., BUCHMACHER, M. C. Division of Emergency Preparedness
& Operational Support. 82/08/04. App. 14566 049.

DOCKET 40-8027 KERR-MCQUEE NUCLEAR CORP., OKLAHOMA CITY, OK

8208040423 Requests copy of License SUB-1010 listed in 820617 FR &
environ appraisal of subv license.
CORVON, L. Pechiney Ugine Kuhlmann Development, Inc. 82/07/15.
Division of Fuel Cycle & Material Safety. 1p. 14220 171.

8208040407 Requests suspension of Condition 3b of Amend 17 to License
SUB-1010 re molybdenum limit. Strict adherence to spec would
limit fertilizer application of nitrogen. Nitrogen
concentration due to unusually heavy rains.
SHELLEY, W. J. Kerr-McQuee Corp. 82/07/21. PAGE, R. O. Uranium Fuel
Licensing Branch. 2pp. 14224 333.

8208040669 Requests EIA for Bequoyah U hexafluoride facility as
described in 820617 FR.
CLAPPER, T. H. Oklahoma, State of. 82/07/21. Division of Fuel
Cycle & Material Safety. 1p. 14224 362.

8208090291 Inform of issuance of Amend 18 to License SUB-1010,
exempting first 3 million gallons of treated raffinate
distributed as fertilizer from molybdenum content
requirements of Amend 17, Condition 3. b.
PAGE, R. O. Uranium Fuel Licensing Branch. 82/07/28. SHELLEY, W. J.
Kerr-McQuee Nuclear Corp. 1p. 14307 100.

--8208090295 Safety evaluation supporting limited exemption for
molybdenum content of treated raffinate.
NIXON, W. A., CROW, W. T. Uranium Fuel Licensing Branch. 82/07/28.
3pp. 14307 101.

8208240465 Informs that Div of Accounting & Finance will refund portion
of amend fee for Amend 17 to License SUB-1010.
MILLER, W. O. License Fee Management Branch. 82/08/11. SHELLEY, W. J.
Kerr-McQuee Nuclear Corp. 1p. 14544 169.

8208270002 Requests withdrawal of 820522 & 0414 applications to
dispose of solidified raffinate sludge in below grade pit.
Applications should be resubmitted when decision re sludge
process reached.
PAGE, R. O. Uranium Fuel Licensing Branch. 82/08/17. SHELLEY, W. J.
Kerr-McQuee Nuclear Corp. 1p. 14683 220.

DOCKET 40-8064 EXXON MINERALS CO. USA, HOUSTON, TX

8208060005 Documents 820702 telcon Summary breakdown of tailings basin reclamation vol & costs, mill decommissioning cost & solution mine restoration costs encl. Engineering studies focusing on cut-fill vol continuing.
SHANNON, J.B. Exxon Corp. 82/07/09. FLEMMING, T.E. NRC - No Detailed Affiliation Given. 3pp. 14244.361.

8208160429 Forwards IE Insp Rept 40-8102/82-01 on 820628-0702 & notice of violation for License SUA-1064.
BROWN, O.D. Division of Vendor & Technical Programs. 82/07/28.
SHANNON, J.B. Exxon Corp. 2pp. 14348.184.

--8208160441 Notice of violation from insp on 820630 Noncompliance noted: three monitor wells exceeded criteria for sulfates by greater than 20% from 820103-0323
* Division of Vendor & Technical Programs. 82/07/28. 1p. 14348.186

--8208160449 IE Insp Rept 40-8102/82-01 on 820628-0702 No noncompliance noted. Major areas inspected: U milling operations & radiation safety program, including organization & administration. Internal review & audit.
WHITTEN, J.E., SPITZBERG, D.B., EVERETT, R.J. Division of Vendor & Technical Programs. 82/07/22. 7pp. 14348.187

8208260911 Provides contract costs incurred & manhours expended in reviewing 810728 application for renewal of License SUA-1064.
KALMAN, K., FLORY, C., LINEHAN, J. Uranium Recovery Licensing Branch. 82/08/05. MILLER, W.D. License Fee Management Branch. 3pp. 14395.044.

DOCKET 40-8084 RIO ALGOM CORP., MOAB, UT

8208040286 Explains process for recovering U-308 from product emanating from Allied Chemical Metropolis Plant. Approval requested.
LAWTON, M.D. Rio Algom Ltd. 82/07/16. PETTENQILL, H. Uranium Recovery Licensing Branch. 15pp. 14225.179

DOCKET 40-8102 EXXON CO. USA, HOUSTON, TX

8208230432 Informs of 10CFR170.31 Category 2A fee requirement for 820429 request for approval of Highland U Operations embankment surveillance program.
WEISB, D. License Fee Management Branch. 82/05/14. SHANNON, J.B. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 2pp. 14528.123.

--8208230435 Forwards Highland U Operations tailings retention sys embankment surveillance program, incorporating applicable portions of Reg Guide 3.11 & self-imposed weekly insp, pursuant to License Condition 27.
SHANNON, J.B. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 82/04/29. PETTENQILL, H.J. Uranium Recovery Licensing Branch. 1p. 14528.125.

--8208240076 "Highland U Operations Tailings Retention Sys Operational Surveillance Program."
WEISB, D. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 82/04/29. 6pp. 14528.126.

8208230437 Forwards general emergency plan documenting actions to be initiated by personnel in event of radiological incidents, fires, tailings dam failure & transportation accidents w/ yellowcake spillage, pursuant to License Condition 28.
SHANNON, J.B. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 82/05/26. PETTENQILL, H.J. Uranium Recovery Licensing Branch. 6pp. 14529.076

--8208230440 Highland U Operations emergency action plan.
* Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). 82/05/26. 6pp. 14529.078.

8208030159 Reviews license amend request for onsite burial of waste mats & equipment contaminated w/ natural U. Supports request.
SMITH, R.D. High Level Waste Licensing Management Branch. 82/07/08. SCARANO, R.A. Uranium Recovery Licensing Branch. 2pp. 14200.303.

8208060005 Documents 820702 telcon Summary breakdown of tailings basin reclamation vol & costs, mill decommissioning cost & solution mine restoration costs encl. Engineering studies focusing on cut-fill vol continuing.
SHANNON, J.B. Exxon Corp. 82/07/09. FLEMMING, T.E. NRC - No Detailed Affiliation Given. 3pp. 14244.361.

8208170002 Amends Source Mat'l License SUA-1129, revising License Condition 27 to require implementation of embankment surveillance program.
SCARANO, R.A. Uranium Recovery Licensing Branch. 82/07/27. 1p. 14372.003

--8208170241 Discusses proposed amend to Source Mat'l License SUA 1129 revising License Condition 27 to require implementation of embankment surveillance program.
JONES, B.Z., PETTENQILL, H.J. Uranium Recovery Licensing Branch. 82/07/27. Uranium Recovery Licensing Branch. 2pp. 14372.004

8208160429 Forwards IE Insp Rept 40-8102/82-01 on 820628-0702 & notice of violation for License SUA-1064.
BROWN, O.D. Division of Vendor & Technical Programs. 82/07/28.
SHANNON, J.B. Exxon Corp. 2pp. 14348.184

--8208160449 IE Insp Rept 40-8102/82-01 on 820628-0702. No noncompliance noted. Major areas inspected: U milling operations & radiation safety program, including organization & administration. Internal review & audit.
WHITTEN, J.E., SPITZBERG, D.B., EVERETT, R.J. Division of Vendor & Technical Programs. 82/07/22. 7pp. 14348.187

DOCKET 40-8135 MINNESOTA MINING & MANUFACTURING, ST. PAUL, MN

8208040673 Forwards application to renew License STB-1129.
WISBINK, R.G. 3M Co., Minnesota Mining & Mfg. Co. 82/07/14. Division of Fuel Cycle & Material Safety. 1p. 14225.238

--8208040677 Application for renewal of License STB-1129, authorizing use of 5.682 kg thorium.
WISBINK, R.G. 3M Co., Minnesota Mining & Mfg. Co. 82/07/14. 2pp. 14225.239.

DOCKET 40-8211 CHAMBERLAIN MANUFACTURING CORP., WATERLOO, IA

8208040291 Responds to NRC 820630 ltr re License SUD-1148. No radioactive mats ever used, so no mats or wastes to be disposed of & no need for closeout survey.
WILCOX, G.L. Chamberlain Manufacturing Corp. 82/07/06. RAQUIL II. Procedures & Certification Branch. 3pp. 14224.357.

DOCKET 40-8348 MINERALS EXPLORATION CO., LOS ANGELES, CA

8208110082 Advises that License SUA-1223 amended by revising license Condition 4 to extend expiration date from 820731 to 830201. Extension necessary for NRC to make final decision on adequacy of groundwater restoration.
SCARANO, R.A. Uranium Recovery Licensing Branch. 82/07/27. Union Oil Co. of California. 1p. 14329.356.

DOCKET 40-8452 BEAR CREEK URANIUM CO., CASPER, WY

8208230116 Memorializes 820706 telcon License SUA-1310 820630 renewal application is for mill activities only. Heap leach tests referenced in Amends 2 & 8 no longer being conducted.
HERSLOFF, L.W. Rocky Mountain Energy Co. 82/07/07. WEISB, D. Uranium Recovery Licensing Branch. 1p. 14517.354.

8208110053 Forwards dam raise specs for Geotechnical Engineering w/ tailings dam const control & expansion of tailings disposal area. Specs should be incorporated into Nov 1981 tailings mgt plan at App B.
HEDLOCK, R.L. Bear Creek Uranium Co. 82/07/08. SCARANO, R.A. Uranium Recovery Licensing Branch. 6pp. 14329.209.

--8208110054 Revision 2 to "Tech Spec for Geotechnical Engineering w/ Tailings Dam Const Control."
* Rocky Mountain Energy Co. 82/06/30. 9pp. 14329.215

--8208110057 Revision C to "Tech Spec for Expanding Capacity of Bear Creek Tailings Disposal Area." One oversize drawing encl. Aperture card is available in PDR.
* Rocky Mountain Energy Co. 82/06/30. 17pp. 14329.224.

8208260989 Notifies that preliminary review of 820630 renewal application acceptable. Addl info will be requested during renewal review process. Current license valid under 10CFR40.43(b).
PETTENQILL, H.J. Uranium Recovery Licensing Branch. 82/07/30. BAUMANN, W. Bear Creek Uranium Co. 1p. 14569.145.

DOCKET 40-8502 WYOMING MINERAL CORP., LAKEWOOD, CO

8208170372 Confirms 820715 telcon re excessive levels of chloride & alkalinity in Coal Zone Well 98M-1. Pumping initiated in closest well completed in upper Irigaray sandstone until chloride level decreases.
CONROY, B. W. Wyoming Mineral Corp. 82/07/20 CHANCELLOR, R. Wyoming, State of 2pp. 14371:115

8208170389 Provides corrective actions re 820630 leak in evaporation pond RA Leak & loose patch repaired & pumping stopped.
CONROY, B. W. Wyoming Mineral Corp. 82/07/20. SCARANO, R. A. Uranium Recovery Licensing Branch. CHANCELLOR, R. Wyoming, State of. 2pp. 14372:324

8208300353 Amends Source Mat'l License SUA-1341 authorizing replacement of Monitor Well RB-63 w/ Monitor Well RB-79 in monitor well network at Irigaray Mine & requiring continuation of monthly monitoring of all excursion monitor wells.
SCARANO, R. Uranium Recovery Licensing Branch. 82/08/19. Wyoming Mineral Corp. 2pp. 14697:193.

DOCKET 40-8546 NATIONAL AERONAUTICS & SPACE ADMIN., HAMPTON, VA

8208030232 IE Insp Findings & Licensee Ack dtd 820713 of License SUB-1297 Insp findings, no violations observed.
FRANKLIN, L. C. Region 2, Office of Director. 82/07/13. 1p. 14198:287.

DOCKET 40-8584 MINERALS EXPLORATION CO., LOS ANGELES, CA

8208030121 Forwards support documentation concerning design const. testing & insp of tailings impoundment Cell C for Suestwater U Mill, in response to 820517 request.
PETTINGILL, H. J. Uranium Recovery Licensing Branch. 82/05/28. FERRITER, R. Colorado, State of 2pp. 14198:354.

--8208030122 Requests that Div of Waste Mgt provide assistance to Mine Safety & Health Administration re info on Suestwater U Mill Tailings insp on 820519.
LEAR, D. Hydrologic & Geotechnical Engineering Branch. 82/05/13. SCARANO, R. A. Uranium Recovery Licensing Branch. 1p. 14198:356.

8208120032 Ack receipt of 820701 ltr informing NRC of steps taken to correct violations noted in IE Insp of License SUA-1350.
BROWN, G. D. Region 4, Office of Director. 82/08/03. DYKERS, L. G. Minerals Exploration Co. (subs. of Union Oil Co. of California). 1p. 14324:233.

--8208120034 Responds to NRC 820611 ltr re violations noted in IE Insp of License SUA-1350. Corrective actions: repairs to product packaging equipment completed, including installation of butterfly shutoff valve.
SNYDER, H. L. Minerals Exploration Co. (subs. of Union Oil Co. of California). 82/07/01. SEYFRIT, K. V. Region 4, Office of Director. 3pp. 14324:234.

DOCKET 40-8585 WYOMING MINERAL CORP., LAKEWOOD, CO

8208260543 Submits results of review of semiannual effluent monitoring rept. Release rates below those previously estimated in Section 5 of EIA.
QUONOLIO, O. N. Uranium Recovery Licensing Branch. 82/07/27. Uranium Recovery Licensing Branch. 2pp. 14572:333.

DOCKET 40-8602 SILVER KING MINES, INC., CASPER, WY

8208260536 Comments on 820422 "Review of Preoperational Radiological Environ Monitoring Rept for Jul-Dec 1981 for Morton Ranch." Air particulate concentrations considered typical of background values.
PANTELL, S. E. Uranium Recovery Licensing Branch. 82/08/11. Uranium Recovery Licensing Branch. 1p. 14572:336.

DOCKET 40-8674 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO

8208040438 Advises of issuance of Amend 4 to License SUA-1326, revising License Condition 26 re reclamation & decommissioning plan described in 810629 submittal.
SCARANO, R. A. Uranium Recovery Licensing Branch. 82/05/18. GUPTA, U. K. Plateau Resources, Ltd. 2pp. 14220:188.

8207200518 Forwards radiological safety training manual.
GERDEMAN, F. H. Plateau Resources, Ltd. 82/06/30. QUONOLIO, O. N. Uranium Recovery Licensing Branch. 2pp. 13996:223.

--8207200520 Radiological safety training manual.
* Plateau Resources, Ltd. 82/03/31. 52pp. 13996:223

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC., DENVER, CO

8207140402 Requests Region 4 assistance re const insp. scheduled by License Condition 26(a), of White Mesa Cell 3 tailings impoundment & Cell 4 site.
SCARANO, R. A. Uranium Recovery Licensing Branch. 82/06/22. COLLINS, J. T. Region 4, Office of Director. 2pp. 13858:006

8208300350 Ack receipt of 820521 ltr requesting amend to Source Mat'l License SUA-1358 reducing thickness of tailings reclamation cover at White Mesa Mill. Add'l info required by 820830.
MARTIN, D. E. Uranium Recovery Licensing Branch. 82/08/12. BAKER, C. Energy Fuels Nuclear, Inc. 2pp. 14697:131.

DOCKET 40-8684 WESTERN NUCLEAR, INC., LAKEWOOD, CO

8208030011 Discusses prelicensing guidance re vendor proposed pumping test program for planned R&D in situ solution mining operation. License application not yet received.
POHLE, J. A. Uranium Recovery Licensing Branch. 82/07/08. Uranium Recovery Licensing Branch. 4pp. 14208:342.

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO., DENVER, CO

8208050031 Forwards addendum to "Reno Creek Pattern 2 Restoration Rept."
NEUMANN, M. R. Rocky Mountain Energy Co. 82/07/16. SCARANO, R. A. Uranium Recovery Licensing Branch. 2pp. 14243:130.

--8208050035 Addendum to "Reno Creek Pattern 2 Restoration Rept."
* Rocky Mountain Energy Co. 82/07/16. 18pp. 14243:132.

DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH

8208240022 Discusses aquifer restoration of A & B fields at Collins Draw Site to achieve baseline groundwater quality. Restoration is inadequate to meet min requirements of quality & use.
GOLE, K. M. Cleveland-Cliffs Iron Co. 82/07/19. Cleveland-Cliffs Iron Co. 3pp. 14548:163.

8208300005 Forwards quarterly rept for Apr-June 1982.
WODEK, D. J. Cleveland-Cliffs Iron Co. 82/07/21. SCARANO, R. A. Uranium Recovery Licensing Branch. 1p. 14695:049.

--8208300007 Quarterly rept for Apr-June 1982. One oversize figure and Aperture card is available in PDR.
* Cleveland-Cliffs Iron Co. 82/07/21. 23pp. 14695:050.

DOCKET 40-8724 CHEMETRON CORP., CHICAGO, IL

8208130400 Application for amend to License SUB-1357, extending expiration date to 830731.
PHILLIPS, B. J. Allegheny International. 82/07/14. PAGE, R. G. Uranium Fuel Licensing Branch. 1p. 14350:360.

8208190037 Advises of issuance of Amend 6 to License SUB-1357, extending expiration date to 830731.
PAGE, R. G. Uranium Fuel Licensing Branch. 82/07/30. PHILLIPS, B. J. Chemtron Corp. 1p. 14307:027.

--8208190040 Safety evaluation supporting Amend 6 to License SUB-1357.
KOSLA, B. M. Uranium Fuel Licensing Branch. 82/07/30. 1p. 14307:028.

DOCKET 40-8743 CONOCO, INC., DENVER, CO

8207140406 Forwards public, State agency & Federal agency comments on DES re operation of Sand Rock Mill Project in Campbell County, WY. Written comment responses required by 820720. W/o encl.
FLEMING, T. E. Uranium Recovery Licensing Branch. 82/07/02. NELSON, J. D. Colorado State Univ. 3pp. 13858:201.

8208090029 Forwards addl geohydrology data in response to NRC B11103
1tr & B21014 meeting. Five oversize figures encl. Aperture
cards are available in PDR.
BOLLIG, D. W. CONOCO, Inc. (Continental Oil Co.) 82/07/13
FLEMING, T. NRC - No Detailed Affiliation Given 11pp 14301 124

--8208090031 "Spots for Bentonite Slurry Cutoff Trench Proposed for
Evaporation Pond " One oversize figure encl. Aperture card
is available in PDR.
* CONOCO, Inc. (Continental Oil Co.) 82/07/13 32pp 14301 137

8208110054 Forwards for signature. Mod 1 to Test Order 10 of NRC
Contract NRC-02-B1-039, requiring work re CONOCO Sand Rock
U Mill project.
HAQAN, T. F. Technical Assistance Contracts Branch FIN 8-7301
82/07/14 Williams-Robinette & Associates, Inc 4pp 14329:348

DOCKET 40-B745 OGLE PETROLEUM, INC., CASPER, WY

8208040607 Forwards "Ore-Sand Aquifer Test in Ogle Petroleum, Inc. Bison
Basin Mining Unit 2," per License Condition 51.
LAWSON, B. A. Ogle Petroleum, Inc. 82/05/23 SCARANO, R. A. Uranium
Recovery Licensing Branch 2pp. 14220:001.

--8208040614 "Ore-Sand Aquifer Test in Ogle Petroleum, Inc. Bison
Mining Unit 2 " Two oversize maps encl. Aperture cards are
available in PDR.
PLAYTON, B. J., HOFFMAN, G. L. Hydro-Engineering, 82/06/30. 168pp.
14220:003.

8208040392 Submits annual land use survey conducted on 820709, per
License Condition 70 No changes in land use observed.
LAWSON, B. Ogle Petroleum, Inc. 82/07/15. SCARANO, R. A. Uranium
Recovery Licensing Branch 2pp 14224:311.

82080310514 Informs that rept on annual land use survey submitted
820715 complete & acceptable.
BRYCK, C. J. Uranium Recovery Licensing Branch. 82/08/19. Uranium
Recovery Licensing Branch. 1p. 14697 274

DOCKET 40-B768 KERR-MCQUEE NUCLEAR CORP., OKLAHOMA CITY, OK

8208040634 Forwards application for amend to License SUA-1387, changing
wording of License Conditions 43, 47, 49 & 50 re well & pond
sampling.
SHELLEY, W. J. Kerr-McQuee Nuclear Corp. 82/05/28. SCARANO, R. A.
Uranium Recovery Licensing Branch 1p. 14224:013.

--8208040640 Application for amend to License SUA-1387, changing wording
of License Conditions 43, 47, 49 & 50 re well & pond sampling.
* Kerr-McQuee Nuclear Corp. 82/05/28. 3pp. 14224:014

DOCKET 40-B781 TETON EXPLORATION DRILLING CO., INC., CASPER, WY

8208040443 Informs that NRC is issuing DES on environ considerations re
Leavenberger Project. Notice transmitted to FR for
publication.
ROSB, F. W. Uranium Recovery Licensing Branch 82/06/30. APPEL, R.
Teton Exploration Drilling Co., Inc. 1p 14220 197.

8208040318 Advises that EPA scheduled 820709 FR publication of notice
of availability of EIS, "Operation of Teton Solution Mining
Project, License, Converse County, WY." (NUREG-0925).
WILSON, K. L. Environmental Protection Agency 82/07/07 SCARANO, R.
NRC - No Detailed Affiliation Given. 1p. 14223:321

8208040429 Ack receipt of info re issuance of source & byproduct mat'l
license for Teton Exploration Drilling Co in Converse
County, WY. No comments provided.
DAVIS, V. M. Agriculture, Dept. of. 82/07/15 SCARANO, R. A. Uranium
Recovery Licensing Branch. 1p 14220:172

8208040349 Advises that Forest Bvc has no substantive comments on Teton
Exploration Drilling, Inc - Teton Project DES, since project
not on & does not affect Nat'l Forest Bvs lands.
SCHESSLER, T. E. Agriculture, Dept. of, Forest Service. 82/07/19
SCARANO, R. A. Uranium Recovery Licensing Branch. 1p. 14223 334.

8208240482 Comments on DES re issuance of source & byproduct mat'l
license for Teton Exploration Drilling, Inc on 820722
Clearance for project recommended.
BASTRON, A. F. Wyoming, State of. 82/08/06. Uranium Recovery
Licensing Branch. 1p. 14544:162.

DOCKET 40-B783 URANERZ USA, INC., CASPER, WY

82080310521 Documents review of Uranerz Ruth In Situ Leach Project third
quarterly rept submitted 820707 Rept complete & acceptable
BRYCK, C. J. Uranium Recovery Licensing Branch. 82/08/19. Uranium
Recovery Licensing Branch 2pp. 14697 269.

DOCKET 40-B786 URANIUM RESOURCES, INC., RICHARDSON, TX

8208030123 Issues Amend 3 to License SUA-1400 modifying License
Conditions 33 & 40 re requirement for submittal showing
airborne monitoring locations.
SCARANO, R. A. Uranium Recovery Licensing Branch. 82/06/16.
PELIZZA, M. S. Uranium Resources, Inc. 2pp. 14198 357

--8208030124 Informs that Amend 3 has been issued to License SUA-1400
modifying License Conditions 33 & 40 re requirement for
submittal showing airborne monitoring locations.
WEBSTER, K. B. Uranium Recovery Licensing Branch. 82/06/16
Uranium Recovery Licensing Branch 2pp. 14198 359.

8208040359 Advises of issuance of Amend 4 to License SUA-1400, deleting
License Condition 22 which required mechanical integrity
tests of injection wells & revising License Condition 39.
SCARANO, R. A. Uranium Recovery Licensing Branch. 82/07/22.
PELIZZA, M. S. Uranium Resources, Inc. 2pp 14221:358.

--8208040362 Safety evaluation supporting Amend 4 to License SUA-1400,
deleting License Condition 22 & revising Condition 39.
WEBSTER, K. B., LINEHAN, J. J. Uranium Recovery Licensing Branch
82/07/22 2pp. 14221:360

8208110080 Discusses problems of inaccurate fluid balance data
presented in license 820521 quarterly rept Plans for
rectifying problems requested by 820820.
LINEHAN, J. J. Uranium Recovery Licensing Branch. 82/07/23.
PELIZZA, M. S. Uranium Resources, Inc. 2pp. 14329:354.

DOCKET 40-B791 CUSTOM MACHINE, INC., CLEVELAND, OH

8208100107 Forwards IE Insp Findings & Licensee Ack dtd 820729 of
License SUB-1397
SLAWINSKI, W. J. Region 3, Office of Director 82/08/05 HQD06DN, O.
Custom Machine. 1p 14298 188.

--8208100113 IE Insp Findings & Licensee Ack dtd 820729 of License
SUB-1397. Insp findings no noncompliance noted.
SLAWINSKI, W. J. Region 3, Office of Director 82/07/29. 1p.
14298 189

DOCKET 40-B793 CONOCO, INC., DENVER, CO

8208040542 Summary of 820505 meeting w/CONOCO in Silver Spring, MD to
discuss status of overdue requested submittals & results of
review of aquifer pump test.
YOUNG, Y. A., LINEHAN, J. J. Uranium Recovery Licensing Branch
82/06/04 Uranium Recovery Licensing Branch. 6pp. 14220:351.

8208240467 Requests withdrawal of Ruby Ranch R&D In Situ U Leach
Project license application. Vendor in process of phasing out
mineral operations & will not continue w/development of
project
HEGGLAND, R. W. CONOCO, Inc. (Continental Oil Co.) 82/07/20.
LINEHAN, J. J. Uranium Recovery Licensing Branch. 1p. 14544:173.

DOCKET 40-B794 MOLYCORP., INC., LOS ANGELES, CA

8208120241 Forwards results of test well sample analysis performed by
EPA Eastern Environ Radiation Facility. Concentrations of
Ra-228 & Th-232 do not appear to exceed NRC limits Results
to be further reviewed during upcoming Insp.
JOYNER, J. H. Division of Engineering & Technical Programs 82/08/05
SINGER, B. Procedures & Certification Branch 4pp. 14326:271.

DOCKET 40-B801 RADIATION MANAGEMENT CORP., NORTHBROOK, IL

8208230016 Requests formal notification if Commission intends to take
further action on findings of radiological survey at West
Lake Landfill.
CORCORAN, M. J. Bridgeton, MD. 82/06/21. CROW, W. T. Uranium Recovery
Licensing Branch. 1p. 14518:003.

B208130347 Forwards application for source mat'l license & license fee.
FEIHAN, S. D. EM Chemicals. B2/07/12. Office of Nuclear Material
Safety & Safeguards, Director. 1p. 14340:251.

--B208130351 Application for license to import, store & ship 50 kg
thorium fluoride, sealed in 100 g & 500 g metal containers.
FEIHAN, S. D. EM Chemicals. B2/07/12. 1p. 14340:252.

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV. OF MICHIGAN RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

B208310057 Releases public version of licensee response to NRC request
for info re reactor emergency plan.
FELTON, J. M. Division of Rules and Records. B2/08/11. Document
Management Branch. 1p. 14697:244. 24X Fiche: 50-002, B2/08/11.
B208310057.

--B208310058 Submits public version of licensee response to NRC request
for info re reactor emergency plan Plan dtd B01126 meets
review guidelines of NUREG-0849.
BURN, R. R. Michigan, Univ. of. B2/07/29. BATES, E. F. Division of
Emergency Preparedness. 1p. 14697:245. 24X Fiche: 50-002,
B2/08/11, B208310057.

G. Inspection reports, IE Bulletins & correspondence

B204210395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. B2/07/19.
Michigan, Univ. of. 112pp. 14357:354. 24X Fiche: 50-000, B2/07/19.
B204210395.

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

B208030686 Releases public version of revised emergency plan
implementing procedures.
FELTON, J. M. Division of Rules and Records. B2/07/20. Document
Management Branch. 1p. 14301:074. 24X Fiche: 50-003, B2/07/20.
B208030686.

--B208030728 Forwards public version of revisions to Emergency Plan
Implementing Procedures IP-1023, "Operational Support Ctr" &
IP-1024, "Monthly Check of Indian Point Emergency Radios,
Telephones & Outdoor Evacuation Alarm."
O'TOOLE, J. D. Consolidated Edison Co. of New York. B2/07/09.
HAYNES, R. C. Region 1, Office of Director. 3pp. 14301:075. 24X
Fiche: 50-003, B2/07/20, B208030686.

--B208030730 Public version of Emergency Plan Implementing Procedures
IP-1023, "Operational Support Ctr" & IP-1024, "Monthly Check
of Indian Point Emergency Radios, Telephones & Outdoor
Evacuation Alarm."
FINCH, G. L. Consolidated Edison Co. of New York. B2/06/18. 23pp.
14301:078. 24X Fiche: 50-003, B2/07/20, B208030686.

B208020073 Advises that amended Page 3-14 from physical security plan,
per B20121 ltr, is withdrawn. Approved page in effect on
B20526 remains in effect in response to NRC B20518 ltr.
O'TOOLE, J. D. Consolidated Edison Co. of New York. B2/07/27.
VARQA, B. A. Operating Reactors Branch 1. 1p. 14144:112. 24X
Fiche: 50-003, B2/07/27, B208020073.

B208270584 Releases public version of revised emergency plan
implementing procedures.
FELTON, J. M. Division of Rules and Records. B2/08/12. Document
Management Branch. 1p. 14683:227. 24X Fiche: 50-003, B2/08/12.
B208270584.

--B208270590 Forwards public version of revised emergency plan
implementing procedures, including Procedures IP-1016 re
obtaining meteorological data & IP-1037 re obtaining offsite
Rueter-Stokes monitor data.
O'TOOLE, J. D., LIEBLER, O. H. Consolidated Edison Co. of New York.
B2/07/01. Office of Nuclear Reactor Regulation, Director. 1p.
14683:228. 24X Fiche: 50-003, B2/08/12, B208270584.

--B208270593 Public version of revised emergency plan implementing
procedures, including Procedures IP-1016 re obtaining
meteorological data & IP-1037 re obtaining offsite Rueter-
Stokes monitor data.
* Consolidated Edison Co. of New York. B2/07/01. 51pp
14683:229. 24X Fiche: 50-003, B2/08/12, B208270584.

H. General correspondence

B208020290 Ack receipt of NRC ltr in response to Westchester County,
NY request for 120-day regulatory clock against facilities.
County appreciates NRC efforts to meet concerns by
requesting interim findings from FEMA.
DELBELLO, A. B. Westchester County, NY. B2/07/13. PALLADINO, N.
Commissioners. 1p. 14151:301. 24X Fiche: 50-003, B2/07/13,
B208020290.

I. Financial information

B208030217 Forwards projection of util ability to pay \$20 million
retrospective premium adjustment for Aug 1982-Jul 1983.
O'TOOLE, J. D. Consolidated Edison Co. of New York. B2/07/29.
SALTZMAN, J. Antitrust & Economic Analysis Branch (Utility Finance).
2pp. 14159:338. 24X Fiche: 50-003, B2/07/29, B208030217.

P. Operating license stage documents & correspondence

B207080064 Generic ltr to all licensees of operating plants, applicants
for OL & holders of CP re Commission approved charter for
CROR. Svc list encl.
DIRCKS, W. J. Office of the Executive Director for Operations.
B2/07/02. Consolidated Edison Co. of New York. 93pp. 14194:001.
24X Fiche: 50-000, B2/07/02, B207080064.

B208110050 Requests info re NY City water supply sys to aid R Code11
testimony for hearing on risk re water contamination by
release of radioactivity in event of severe accident, per
B20709 discussion.
HANAUER, S. H. Division of Safety Technology. B2/07/22. CONWAY, J.
New York, State of. 4pp. 14330:218. 24X Fiche: 50-003, B2/07/22,
B208110050.

B208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP &
applicants re submittal of documents to NRC. Summarizes 10CFR
Chapter I requirements & provides alternatives to
requirements. Svc list encl.
EISENHUT, D. Q. Division of Licensing. B2/08/09. Consolidated
Edison Co. of New York. 1p. 14336:332. 24X Fiche: 50-000, B2/08/09,
B208090194.

G. Inspection reports, IE Bulletins & correspondence

B204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MSIV)
Leakage." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. B2/07/16.
Consolidated Edison Co. of New York. 87pp. 14356:274. 24X
Fiche: 50-000, B2/07/16, B204210393.

B204210395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. B2/07/19.
Michigan, Univ. of. 112pp. 14357:354. 24X Fiche: 50-000, B2/07/19,
B204210395.

B204210396 IE Info Notice B2-25, "Failures of Hiller Actuators Upon
Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. B2/07/20.
Consolidated Edison Co. of New York. 112pp. 14380:252. 24X
Fiche: 50-000, B2/07/20, B204210396.

B204210397 IE Info Notice B2-24, "Water Leaking From U Hexafluoride
Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards.
B2/07/20. Consolidated Edison Co. of New York. 71pp. 14357:276.
24X Fiche: 50-000, B2/07/20, B204210397.

B204210398 IE Info Notice B2-26, "RCIC & HPCI Turbine Exhaust Check
Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. B2/07/22.
Consolidated Edison Co. of New York. 112pp. 14194:321. 24X
Fiche: 50-000, B2/07/22, B204210398.

B204210401 IE Info Notice B2-28, "Hydrogen Explosion While Grinding in
Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. B2/07/23.
Consolidated Edison Co. of New York. 122pp. 14380:115. 24X
Fiche: 50-000, B2/07/23, B204210401.

B204210402 IE Info Notice B2-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co of New York 127pp 14194 120 24X
Fiche 50-000.82/07/23.8204210402

B204210403 IE Info Notice B2-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26
Consolidated Edison Co of New York 121pp 14337 013 24X
Fiche 50-000.82/07/26.8204210403

B204210405 IE Info Notice B2-31. "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28
Consolidated Edison Co of New York 122pp 14337 146 24X
Fiche 50-000.82/07/28.8204210405

B204210407 IE Info Notice B2-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/05
Consolidated Edison Co of New York 117pp 14388 201 24X
Fiche 50-000.82/08/05.8204210407

R Periodic operating reports & related correspondence

B206270010 Responds to FOIA request for documents detailing collective dose exposures in 1961 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records 82/07/13 UOELL, R. A
Critical Mass Energy Project 8pp 14679 208 24X
Fiche 50-000.82/07/13.8206270010

--B208270012 Forwards "Number of Personnel & Man Rem By Work & Job Function for CY81." per 10CFR20.407
O'TOOLE, J. D. Consolidated Edison Co of New York 82/03/01
HAYNES, R. C. Region 1, Office of Director. 1p. 14679 361. 24X
Fiche 50-000.82/07/13.8208270010

--B208270016 "Number of Personnel & Man Rem By Work & Job Function for CY81"
Consolidated Edison Co of New York 82/03/01 1p. 14679 362
24X Fiche 50-000.82/07/13.8208270010

--B208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81"
NRC - No Detailed Affiliation Given 82/07/13 48pp
14679 216 24X Fiche 50-000.82/07/13.8208270010

--B208270632 Forwards "Personnel Whole Body Exposures For CY81." per 10CFR20.407
BRONX, J. C. Power Authority of the State of New York 82/02/26
Office of Management and Program Analysis 1p. 14679 345 24X
Fiche 50-000.82/07/13.8208270010

--B208270637 "Personnel Whole Body Exposures for CY81"
Consolidated Edison Co of New York 82/02/26 1p. 14679 346
24X Fiche 50-000.82/07/13.8208270010

DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

B208190112 Notifies of B20820 meeting to discuss subcritical experiments w/new core fuel elements containing U oxide pellets enriched to 7% U-235
LEVINE, B. H. Pennsylvania State Univ 82/08/12. BERNARD, H
Standardization & Special Projects Branch 1p. 14383 145 24X
Fiche 50-005.82/08/12.8208190112

Q Inspection reports, IE Bulletins & correspondence

B204210395 IE Info Notice B1-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/19
Michigan, Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19, 8204210395

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

B208040353 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records 82/07/13 Document
Management Branch 1p 14223 161. 24X Fiche 50-010.82/07/13, 8208040353

--B208040359 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-C8. "Rad/Chem Director" Receipt form, procedure history & safety evaluation encl
SCOTT, D. J. Commonwealth Edison Co 82/07/02 DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 3pp. 14223 162 24X
Fiche 50-010.82/07/13.8208040353

--B208040361 Public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-C8. "Rad/Chem Director" Revised index of station group director duties encl
Commonwealth Edison Co 82/06/30 3pp 14223 165 24X
Fiche 50-010.82/07/13.8208040361

B208040473 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 82/07/22 Document
Management Branch 1p 14220 294 24X Fiche 50-010.82/07/22, 8208040473

--B208040479 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-C7. "Security Director" & Revision 0 to EPIP 500-9. "Operational Check of Notification Phone List" Receipt form encl
SCOTT, D. J. Commonwealth Edison Co 82/07/10 DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 5pp 14220 295 24X
Fiche 50-010.82/07/22.8208040473

--B208040483 Public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-C7. "Security Director" & Revision 0 to EPIP 500-9. "Operational Check of Notification Phone List"
Commonwealth Edison Co. 82/07/07 6pp 14220 300 24X
Fiche 50-010.82/07/22.8208040473

B208270134 Forwards IE Insp Repts 50-010/82-11.50-237/82-15 & 50-249/82-16 on B20624.29.30 & 0709 & notice of significant test deficiency
HIND, J. A. Division of Emergency Preparedness & Operational Support. 82/08/03 REED, C. Commonwealth Edison Co. 3pp 14563 338 24X
Fiche 50-010.82/08/03.8208270134

--B208270142 IE Insp Repts 50-010/82-11.50-237/82-15 & 50-249/82-16 on B20624.29.30 & 0709 Significant test deficiency noted.
Failure of seven prompt public notification sys sirens
JANUSKA, A. O., SMITH, M. J., PATTERSON, J. P. Division of Emergency Preparedness & Operational Support 82/07/23 12pp 14563 341.
24X Fiche 50-010.82/08/03.8208270134

B208250559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"
FELTON, J. M. Division of Rules and Records 82/08/12. Document
Management Branch 1p 14559 354 24X Fiche 50-000.82/08/12, 8208250559

--B208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"
HODGE, R. D. Commonwealth Edison Co 82/07/19 DENTON, H. R. NRC -
No Detailed Affiliation Given 1p 14559 355. 24X
Fiche 50-000.82/08/12.8208250559

--B208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"
Commonwealth Edison Co 82/06/30. 7pp 14559 356. 24X
Fiche 50-000.82/08/12.8208250559

P Operating license stage documents & correspondence

B207080064 Generic ltr to all licensees of operating plants, applicants for GL & holders of CP re Commission approved charter for CROR Svc list encl.
DIRKS, W. J. Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York. 93pp 14194.001.
24X Fiche 50-000.82/07/02.8207080064

B208030254 Comments on BEP in response to B20714 request Few deviations identified between design criteria used for Phase 1/II plants vs current criteria.
DELGORE, L. O. Commonwealth Edison Co. 82/07/29 CRUTCHFIELD, D. Operating Reactors Branch 3pp 14158 227. 24X
Fiche 50-010.82/07/29.8208030254

B208110188 Forwards revised pages to CE-1-A. "Com Ed QA Program For Nuclear Generating Stations." Revision 21. Revised pages correct typographical & other minor errors.
SWARTZ, E. D. Commonwealth Edison Co. 82/08/06 HAAS, W. P. Quality Assurance Branch 1p. 14314 079. 24X Fiche 50-000.82/08/06, 8208110188

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl
EISENHUT, D. O. Division of Licensing. 82/08/09 Consolidated Edison Co. of New York 1p. 14396.332 24X Fiche 50-000.82/08/09, 8208090194

0 Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16 Consolidated Edison Co. of New York 87pp. 14396.274 24X Fiche 50-000.82/07/16.8204210393.

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19, Michigan, Univ. of 112pp. 14398.001 24X Fiche: 50-000.82/07/19, 8204210395

8208050393 Forwards IE Insp Repts 50-010/82-06.50-237/82-10 & 50-249/82-11 on 820507-0604 & notice of violation.
SPESSARD, R. L. Division of Project & Resident Programs. 82/07/19. REED, C. Commonwealth Edison Co. 2pp. 14209.191 24X Fiche 50-010.82/07/19.8208050393.

--8208050398 Notice of violation from insp on 820507-0604.
* Division of Project & Resident Programs. 82/07/19. 2pp 14209.193 24X Fiche: 50-010.82/07/19.8208050393.

--8208050403 IE Insp Repts 50-010/82-06.50-237/82-10 & 50-249/82-11 on 820507-0604. Noncompliance noted. Failure to follow hose color code.
TONQUE, T. M., JORDAN, M. J., WALKER, R. D. Division of Project & Resident Programs. 82/07/11. 9pp. 14209.195 24X Fiche: 50-010.82/07/19.8208050393

8204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp. 14380.252. 24X Fiche: 50-000.82/07/20.8204210396.

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L. J. Division of Fuel Facilities, Materials & Safeguards. 82/07/20. Consolidated Edison Co. of New York. 71pp. 14397.276 24X Fiche: 50-000.82/07/20.8204210397

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22. Consolidated Edison Co. of New York 112pp. 14194.321. 24X Fiche: 50-000.82/07/22.8204210398.

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 122pp. 14380.115 24X Fiche: 50-000.82/07/23.8204210401.

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 127pp 14194.120. 24X Fiche 50-000.82/07/23.8204210402.

8208100289 Forwards IE Insp Repts 50-010/82-09.50-237/82-13 & 50-249/82-14 on 820616-17 & 21-25. No noncompliance noted.
MILLER, J. R. Division of Engineering & Technical Programs. 82/07/23 REED, C. Commonwealth Edison Co. 2pp 14294.191. 24X Fiche: 50-010.82/07/23.8208100289.

--8208100299 IE Insp Repts 50-010/82-09.50-237/82-13 & 50-249/82-14 on 820616-17 & 21-25. No noncompliance noted. Major areas inspected: action on previous findings, open items & hydrogen gas addition into reactor feedwater sys.
PAUL, R. A., GREGOR, L. R. Division of Engineering & Technical Programs. 82/07/22 7pp. 14294.193. 24X Fiche: 50-010.82/07/23.8208100289.

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28. Consolidated Edison Co. of New York 122pp. 14397.146 24X Fiche 50-000.82/07/28.8204210405

8208270134 Forwards IE Insp Repts 50-010/82-11.50-237/82-15 & 50-249/82-16 on 820624.29.30 & 0709 & notice of significant test deficiency.
HIND, J. A. Division of Emergency Preparedness & Operational Support. 82/08/03 REED, C. Commonwealth Edison Co. 3pp. 14563.338. 24X Fiche 50-010.82/08/03.8208270134

--8208270142 IE Insp Repts 50-010/82-11.50-237/82-15 & 50-249/82-16 on 820624.29.30 & 0709 Significant test deficiency noted. Failure of seven prompt public notification sys sirens.
JANUSKA, A. O., GRANT, W. B., NICHOLSON, N. A. Division of Emergency Preparedness & Operational Support. 82/07/23 12pp 14563.341. 24X Fiche: 50-010.82/08/03.8208270134.

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/05. Consolidated Edison Co. of New York 117pp. 14388.201. 24X Fiche: 50-000.82/08/05.8204210407.

8208200241 Advises of error in NRC 820719 ltr transmitting IE Insp Repts 50-010/82-06.50-237/82-10 & 50-249/82-11 Page 2 should be replaced w/encl page
SPESSARD, R. L. Division of Project & Resident Programs. 82/08/13. REED, C. Commonwealth Edison Co. 2pp. 14399.031. 24X Fiche: 50-010.82/08/13.8208200241.

8208310218 Forwards suppl to util 820526 response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Bys Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)." SWARTZ, E. D. Commonwealth Edison Co. 82/08/23. KEPPLER, J. O. Region 3, Office of Director 9pp. 14693.130 24X Fiche 50-010.82/08/23.8208310218

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A. Critical Mass Energy Project. 8pp. 14679.208. 24X Fiche: 50-000.82/07/13.8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp. 14679.216. 24X Fiche: 50-000.82/07/13.8208270010.

--8208270559 Forwards "Recorded Annual Whole Body External Exposure for CY81," per 10CFR20.407(b) w/o Quads Cities, Zion, LaSalle, Byron & Braidwood repts.
RAUSCH, T. J. Commonwealth Edison Co. 82/03/31. Office of Management and Program Analysis. 1p. 14680.075. 24X Fiche: 50-000.82/07/13.8208270010.

--8208270567 "Recorded Annual Whole Body External Exposure for CY81."
* Commonwealth Edison Co. 82/03/31. 1p. 14680.076. 24X Fiche: 50-000.82/07/13.8208270010.

8208170242 Forwards monthly operating repts for Jul 1982.
SCOTT, D. J. Commonwealth Edison Co. 82/08/01. Director's Office. Office of Inspection and Enforcement. 1p. 14369.228. 24X Fiche: 50-010.82/08/01.8208170242

--8208170245 Monthly operating repts for Jul 1982.
SCHROEDER, B. A. Commonwealth Edison Co. 82/08/01. 18pp. 14369.229. 24X Fiche: 50-010.82/08/01.8208170242.

DOCKET 50-13 BABCOCK & WILCOX CO. CRITICAL FACILITY

0 Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of. 112pp. 14398.001. 24X Fiche: 50-000.82/07/19.8204210395.

DOCKET 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1

R Periodic operating reports & related correspondence

8208240143 Forwards annual rept for decommissioned License DPR-9 for yr ending 820630
GRIFFING, E. P. Detroit Edison Co 82/07/29 STOLZ, J. Operating Reactors Branch 4 1p 14319 338 24X Fiche 50-016, 82/07/29, 8208240143

--8208240147 Annual rept for decommissioned License DPR-9 for yr ending 820630
HARRISON, W. O., GRIFFING, E. P., ALEXANDERSON, E. Detroit Edison Co EF-128 82/08/09 10pp 14319 339 24X Fiche 50-016, 82/07/29, 8208240143

DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR

F Security, medical, emergency & fire protection plans

8208230039 Forwards IE Insp Rept 50-020/82-01 on 820614-15 No noncompliance noted
STAROSTECKI, R. Division of Project & Resident Programs 82/08/06
CLARK, L. Massachusetts Institute of Technology 2pp 14317 242 24X Fiche 50-020, 82/08/06, 8208230039

--8208230041 IE Insp Rept 50-020/82-01 on 820614-15 No noncompliance noted Major areas inspected: licensee action on previous insp findings, facility operation, organization, audits & MIT reactor safeguards committee activities
KINNEY, W. W., ROTH, J., GREENMAN, E. Q. Division of Project & Resident Programs 82/08/05 7pp 14317 244 24X Fiche 50-020, 82/08/06, 8208230039

8208250127 Requests 30-day extension for implementation of Amends 19 & 21 to License R-37, per NRC 820611 ltr Amend 19 identifies physical security plan & Amend 21 authorizes change in storage of fresh fuel
CLARK, L. Massachusetts Institute of Technology 82/08/20
MILLER, J. R. Standardization & Special Projects Branch 1p 14340 273 24X Fiche 50-020, 82/08/20, 8208250127

P Operating license stage documents & correspondence

8208250127 Requests 30-day extension for implementation of Amends 19 & 21 to License R-37, per NRC 820611 ltr Amend 19 identifies physical security plan & Amend 21 authorizes change in storage of fresh fuel
CLARK, L. Massachusetts Institute of Technology 82/08/20
MILLER, J. R. Standardization & Special Projects Branch 1p 14340 273 24X Fiche 50-020, 82/08/20, 8208250127

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/19
Michigan Univ. of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395

8208230039 Forwards IE Insp Rept 50-020/82-01 on 820614-15 No noncompliance noted
STAROSTECKI, R. Division of Project & Resident Programs 82/08/06
CLARK, L. Massachusetts Institute of Technology 2pp 14317 242 24X Fiche 50-020, 82/08/06, 8208230039

--8208230041 IE Insp Rept 50-020/82-01 on 820614-15 No noncompliance noted Major areas inspected: licensee action on previous insp findings, facility operation, organization, audits & MIT reactor safeguards committee activities
KINNEY, W. W., ROTH, J., GREENMAN, E. Q. Division of Project & Resident Programs 82/08/05 7pp 14317 244 24X Fiche 50-020, 82/08/06, 8208230039

9 Reportable occurrences, LERs & related correspondence

8208260293 RO on 820809, slight increase found in levels of fission products in reactor primary sys Cause under investigation. Criterion for operation w/potential faulty core element per RO 50-20/79-4 will be observed
CLARK, L. Massachusetts Institute of Technology 82/08/17
HAYNES, R. C. Region 1, Office of Director 3pp 14334 283 24X Fiche 50-020, 82/08/17, 8208260293

DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8208030143 Forwards IE Safeguards Insp Rept 50-027/82-01 on 820719-20 No noncompliance noted
NORDERHAUG, L. Division of Radiological Safety & Safeguards Program 82/07/28 WILSON, W. E. Washington Univ 4pp 14160 013 24X Fiche 50-027, 82/07/28, 8208030143

--8208030151 IE Safeguards Insp Rept 50-027/82-01 on 820719-20 No noncompliance noted Major areas inspected: security plan, SNM protection, security organization & access controls Details withheld (ref IOCFR2 790)
MCQUEEN, A. D., SCHWAN, C. A., SCHUSTER, M. D. Division of Radiological Safety & Safeguards Program 82/07/28 1p 14160 017 24X Fiche 50-027, 82/07/28, 8208030143

P Operating license stage documents & correspondence

8208260399 Forwards Amend 10 to License R-76, SER (NUREG-0911), EIA & notice of issuance & availability Amend renews DL for 20 yrs, adds Tech Spec limit on max reactivity & incorporates new requirements on pool water quality
BERNARD, H. Standardization & Special Projects Branch 82/08/11
WILSON, W. E. Washington State Univ 2pp 14371 331 24X Fiche 50-027, 82/08/11, 8208260399

--8208260404 Amend 10 to License R-76, renewing DL for 20 yrs, adding Tech Spec limit on max reactivity & incorporating new requirements on pool water quality
BERNARD, H. Standardization & Special Projects Branch 82/08/11 4pp 14371 333 24X Fiche 50-027, 82/08/11, 8208260399

--8208260407 EIA supporting Amend 10 to License R-76
* NRC - No Detailed Affiliation Given 82/08/11 2pp 14372 016 24X Fiche 50-027, 82/08/11, 8208260399

--8208260412 Notice of issuance & availability of Amend 10 to License R-76
BERNARD, H. Standardization & Special Projects Branch 82/08/11 2pp 14372 022 24X Fiche 50-027, 82/08/11, 8208260399

Q Inspection reports, IE Bulletins & correspondence

8208030143 Forwards IE Safeguards Insp Rept 50-027/82-01 on 820719-20 No noncompliance noted
NORDERHAUG, L. Division of Radiological Safety & Safeguards Program 82/07/28 WILSON, W. E. Washington Univ 4pp 14160 013 24X Fiche 50-027, 82/07/28, 8208030143

--8208030151 IE Safeguards Insp Rept 50-027/82-01 on 820719-20 No noncompliance noted Major areas inspected: security plan, SNM protection, security organization & access controls Details withheld (ref IOCFR2 790)
MCQUEEN, A. D., SCHWAN, C. A., SCHUSTER, M. D. Division of Radiological Safety & Safeguards Program 82/07/28 1p 14160 017 24X Fiche 50-027, 82/07/28, 8208030143

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

8208040298 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 82/07/20 Document Management Branch 1p 14231 060 24X Fiche 50-029, 82/07/20, 8208040298

--8208040304 Forwards public version of revised emergency plan implementing procedures, including Procedures CP-3301 re unusual event, CP-3302 re alert & CP-3303 re site area emergency Receipt form encl
MARKT, D. Yankee Atomic Electric Co 82/07/13 Office of Nuclear Reactor Regulation, Director 1p 14231 061 24X Fiche 50-029, 82/07/20, 8208040298

--8208040309 Public version of revised emergency plan implementing procedures, including Procedures CP-3301 re unusual event, CP-3302 re alert & CP-3303 re site area emergency Revised table of contents encl
* Yankee Atomic Electric Co 82/07/09 50pp 14231 062 24X Fiche 50-029, 82/07/20, 8208040298

B208110119 Forwards exemption from requirement of 10CFR50.48 & App R re installation of fixed fire suppression sys in control room in response to util B20513 ltr.
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/05. KAY, J. A. Yankee Atomic Electric Co. 2pp. 14314:319. 24X
Fiche: 50-029, 82/08/05, B208110119

--B208110122 Exemption from requirement of 10CFR50.48 & App R re installation of fixed fire suppression sys in control room
EISENHUT, D. O. Division of Licensing. 82/08/05. Yankee Atomic Electric Co. App 14314:321. 24X Fiche: 50-029, 82/08/05, B208110119.

B208310039 Releases public version of revised emergency plan implementing procedures table of contents
FELTON, J. M. Division of Rules and Records. 82/08/11. Document Management Branch. 1p. 14697:202. 24X Fiche: 50-029, 82/08/11, B208310039.

--B208310033 Forwards public version of Revision 12 to emergency plan implementing procedures table of contents Receipt form encl
MARKT, D. Yankee Atomic Electric Co. 82/07/30. Office of Nuclear Reactor Regulation, Director. 2pp. 14697:203. 24X
Fiche: 50-029, 82/08/11, B208310039.

--B208310035 Public version of Revision 12 to emergency plan implementing procedures table of contents
* Yankee Atomic Electric Co. 82/07/28. 1p. 14697:205. 24X
Fiche: 50-029, 82/08/11, B208310039

P. Operating license stage documents & correspondence

B207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR. Svc list encl.
DIRCKB, W. J. Office of the Executive Director for Operations. 82/07/02. Consolidated Edison Co of New York. 93pp. 14194:001. 24X Fiche: 50-000, 82/07/02, B207080064

B208020185 Forwards response to B20617 & 29 requests for addl info re degraded grid voltage. Marked-up preliminary Tech Specs encl.
KAY, J. A. Yankee Atomic Electric Co. 82/07/09. CRUTCHFIELD, D. Operating Reactors Branch 5. 8pp. 14141:025. 24X
Fiche: 50-029, 82/07/09, B208020185

B208040534 Notification of B20727-29 meetings w/util in Rowe & Framingham, MA to perform onsite insp of soil conditions & to review licensee documentation on SEP Topics II-4, D, II-4, E & II-4 F.
CARUSO, R. Operating Reactors Branch 5. 82/07/21. CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 14221:205. 24X
Fiche: 50-029, 82/07/21, B208040534

B208060184 Responds to NRC B20512 request for addl info re spent fuel pool mods. Personnel exposure dose rates, analysis methods & spent fuel pool surveillance results discussed.
KAY, J. A. Yankee Atomic Electric Co. 82/07/28. CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 14239:101. 24X
Fiche: 50-029, 82/07/28, B208060184.

B208030165 Forwards Franklin Research Ctr request for addl info needed to complete review of util submittal on TMI Item II.K.3.17 re rept on outages of ECCB.
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/07/29. KAY, J. A. Yankee Atomic Electric Co. 2pp. 14160:109. 24X
Fiche: 50-029, 82/07/29, B208030165.

--B208030167 "ECCB Repts (F-47) TMI Action Plan Requirements." request for addl info.
VOBBURY, F. Franklin Institute/Franklin Research Center. NRC-03-81-130. TER-C8506-303. 82/06/22. CHOW, E. NRC - No Detailed Affiliation Given. 5pp. 14160:111. 24X
Fiche: 50-029, 82/07/29, B208030165.

B208030193 Forwards Franklin Research Ctr environ qualification review of Fisher & Porter Model 13D-2495-JBNB level transmitters. Justification for adequacy of transmitters for interim or short-term operation requested within 30 days.
CRUTCHFIELD, D. Operating Reactors Branch 5. NRC-03-79-118. 82/07/29. KAY, J. A. Yankee Atomic Electric Co. 26pp. 14160:126. 24X Fiche: 50-029, 82/07/29, B208030193.

B208050533 Forwards latest revision to proposed radiological ETB, per B20413-14 meeting w/NRC. Revision reflects requirements necessary to meet intent of std radiological ETB for operating reactors.
KAY, J. A. Yankee Atomic Electric Co. 82/07/30. PANDEY, S. Franklin Institute/Franklin Research Center. 2pp. 14213:321. 24X
Fiche: 50-029, 82/07/30, B208050533.

--B208050537 Preliminary radiological ETB re channel function test requirement on liquid & gaseous effluent monitors & deletion of channel calibr & functional test requirements for PVS flow rate measuring device.
* Yankee Atomic Electric Co. 82/07/31. 95pp. 14213:323. 24X
Fiche: 50-029, 82/07/30, B208050533

B208170229 Forwards addl info re TMI Item II D 1. "Safety & Relief Valves."
KAY, J. A. Yankee Atomic Electric Co. 82/08/01. CRUTCHFIELD, D. Operating Reactors Branch 5. 24pp. 14369:004. 24X
Fiche: 50-029, 82/08/01, B208170229.

B208260310 Forwards criteria contained in NUREG-0737 w/guidelines developed by NRC to assess acceptability of licensee mod & procedures for TMI Item II B.3. "Post-Accident Sampling" Schedule for response requested within 20 days
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/04. KAY, J. A. Yankee Atomic Electric Co. 10pp. 14576:121. 24X
Fiche: 50-029, 82/08/04, B208260310

B208090206 Submits response to NRC B20714 ltr re SEP Phase II Urges NRC to avoid prematurely launching another SEP phase before value of Phase II has been determined
EDWARDS, D. W. Yankee Atomic Electric Co. 82/08/05. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 14272:069. 24X
Fiche: 50-029, 82/08/05, B208090206

B208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl.
EISENHUT, D. O. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14336:332. 24X Fiche: 50-000, 82/08/09, B208090194

B208250516 Informs that B20727 application, proposing Tech Spec changes to eliminate need for SER issuance & to reduce review for routine core refueling changes, requires Class III fee in lieu of Class II fee submitted. Addl fee requested.
DIOGS, R. H. License Fee Management Branch. 82/08/11. KAY, J. A. Yankee Atomic Electric Co. 1p. 14362:243. 24X
Fiche: 50-029, 82/08/11, B208250516.

B208260336 Notification of B20908-09 meetings w/util in Bethesda, MD to initiate integrated assessment of facility.
BOYLE, M. L. Systematic Evaluation Program Branch. 82/08/12. RUSSELL, W. T. Systematic Evaluation Program Branch. 2pp. 14578:210. 24X Fiche: 50-029, 82/08/12, B208260336.

B208170332 Forwards final safety evaluation of SEP Topic VIII-4 re electrical penetrations of reactor containment. Changes in protection for medium & low voltage electrical penetrations, plant Tech Specs & operating procedures recommended.
CARUSO, R. Operating Reactors Branch 5. 82/08/13. KAY, J. A. Yankee Atomic Electric Co. App. 14367:004. 24X Fiche: 50-029, 82/08/13, B208170332.

B208190199 Forwards safety evaluation of TMI Action Plan Item II.E.1.2. "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication." & technical evaluation rept Tech Specs should be revised to include monthly testing of pumps.
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/16. KAY, J. A. Yankee Atomic Electric Co. 5pp. 14500:177. 24X
Fiche: 50-029, 82/08/16, B208190199.

--B204220204 "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication." technical evaluation rept.
KAUCHER, J. E., FERTNER, K. Franklin Institute/Franklin Research Center. NRC-03-79-118. TER-C5237-289. 82/06/18. KENDALL, R. NRC - No Detailed Affiliation Given. 12pp. 14500:182. 24X
Fiche: 50-029, 82/08/16, B208190199.

B208200017 Clarifies position concerning misunderstanding re B20712 request for info on status of unresolved safety issues at facility.
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/17. KAY, J. A. Yankee Atomic Electric Co. 3pp. 14392:197. 24X
Fiche: 50-029, 82/08/17, B208200017.

B208270681 Forwards licensee responses to questions re TMI Action Plan Items II.F.1.4, II.F.1.5 & II.F.1.6 re containment monitors.
CARUSO, R. Operating Reactors Branch 5. 82/08/19. Operating Reactors Branch 5. 6pp. 14683:179. 24X Fiche: 50-029, 82/08/19, B208270681.

B208240292 Forwards evaluation of SEP Topic III-5.A, "Effects of Pipe Break on Structures, Sys & Components Inside Containment." Criteria acceptable.
CARUSO, R. Operating Reactors Branch 5. 82/08/20. KAY, J. A. Yankee Atomic Electric Co. 12pp. 14528:097. 24X Fiche: 50-029, 82/08/20, B208240292.

8208240304 Confirms 820813 telcon re EEP Topics VI-2 D, "Mass & Energy Release for Possible Pipe Break Inside Containment" & VI-3, "Containment Pressure & Heat Removal Capability." Temp profiles & pressure acceptable
CARUSO, R. Operating Reactors Branch 5 82/08/20 KAY, J. A. Yankee Atomic Electric Co 2pp 14328 076 24X Fiche 50-029, 82/08/20, 8208240304

Q Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp. 14356 274 24X Fiche 50-000, 82/07/16, 8204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl. 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/19, Michigan Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, 8204210395

8204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20, Consolidated Edison Co of New York 112pp. 14381 001 24X Fiche 50-000, 82/07/20, 8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks" Svc list encl
C088, L. I. Division of Fuel Facilities, Materials & Safeguards, 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000, 82/07/20, 8204210397

8208040534 Notification of 820727-29 meetings w/util in Rowe & Framingham, MA to perform onsite insp of soil conditions & to review licensee documentation on SEP Topics II-4, D, II-4, E & II-4 F
CARUSO, R. Operating Reactors Branch 5 82/07/21 CRUTCHFIELD, D. Operating Reactors Branch 5 3pp 14221 205 24X Fiche 50-029, 82/07/21, 8208040534

8204210398 IE Info Notice 82-26, "RCIC & WPCI Turbine Exhaust Check Valve Failures" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp. 14194 321 24X Fiche 50-000, 82/07/22, 8204210398

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24X Fiche 50-000, 82/07/23, 8204210401

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24X Fiche 50-000, 82/07/23, 8204210402

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp. 14357 013 24X Fiche 50-000, 82/07/26, 8204210403

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp. 14357 146 24X Fiche 50-000, 82/07/28, 8204210405

8208100137 Responds to IE Bulletin 82-02 re leakage in bolted closures of RCPB insp conducted revealed flange leak in main coolant pump 3. Gasket sealing surfaces cleaned & lapped.
MOODY, D. E. Yankee Atomic Electric Co 82/07/30 HAYNES, R. C. Region 1, Office of Director 2pp 14298 018 24X Fiche 50-029, 82/07/30, 8208100137

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/05, Consolidated Edison Co of New York 117pp. 14388 201 24X Fiche 50-000, 82/08/05, 8204210407

8208240276 Ack receipt of 820701 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-029/82-07.
HARTIN, T. T. Division of Engineering & Technical Programs 82/08/19, KAY, J. A. Yankee Atomic Electric Co. 1p. 14527 178 24X Fiche 50-029, 82/08/19, 8208240276

--8208240280 Responds to NRC 820604 ltr re violations noted in IE Insp Rept 50-029/82-07. Corrective actions: plant mgt will re-emphasize need for comprehensive corrective action planning & procedures will be revised.
MOODY, D. E. Yankee Atomic Electric Co 82/07/01, HAYNES, R. C. Region 1, Office of Director 3pp 14527 179 24X Fiche 50-029, 82/08/19, 8208240276

R Periodic operating reports & related correspondence

8208120232 Forwards monthly operating rept for June 1982
MOODY, D. E. Yankee Atomic Electric Co 82/07/09, Office of Resource Management, Director 2pp. 14326 277 24X Fiche 50-029, 82/07/09, 8208120232

--8208120234 Monthly operating rept for June 1982
DOYLE, A. E. Yankee Atomic Electric Co. 82/07/09. 4pp. 14326 279 24X Fiche 50-029, 82/07/09, 8208120232

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J. H. Division of Rules and Records 82/07/13 UDELL, R. A. Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81"
NRC - No Detailed Affiliation Given 82/07/13 48pp. 14679 216 24X Fiche 50-000, 82/07/13, 8208270010

--8208270347 Forwards "Yankee Rowe Personnel & Man Rem By Work & Duty Function Rept CY81"
MOODY, D. E. Yankee Atomic Electric Co. 82/03/04, HAYNES, R. C. Region 1, Office of Director 1p 14680 030 24X Fiche 50-000, 82/07/13, 8208270010

--8208270550 "Yankee Rowe Personnel & Man Rgm By Work & Duty Function Rept, CY81."
ANTIO, R. H., TRIGER, J. C. Yankee Atomic Electric Co. 82/02/16. 1p. 14680 031 24X Fiche 50-000, 82/07/13, 8208270010

--8208270629 Forwards whole body range rept for CY81, per 10CFR20.407.
MOODY, D. E. Yankee Atomic Electric Co 82/03/12, HALLER, N. H. Office of Management and Program Analysis 1p 14680 050 24X Fiche 50-000, 82/07/13, 8208270010

--8208270638 Whole body range rept for CY81.
TRIGER, J. C., ANTIO, R. H. Yankee Atomic Electric Co 82/03/08. 1p. 14680 031 24X Fiche 50-000, 82/07/13, 8208270010

5 Reportable occurrences, LERs & related correspondence

8208020292 Forwards LER 82-018/03L-0
ANTIO, R. H. A. Yankee Atomic Electric Co. 82/07/23 HAYNES, R. C. Region 1, Office of Director 1p. 14151 304 24X Fiche 50-029, 82/07/23, 8208020292

--8208020301 LER 82-018/03L-0 on 820624, low main coolant flow relay phase C in sys B failed to drop out when de-energized. Caused by abnormal friction between plunger & upper bushing Relays SC-1, 1876-072 replaced
FRENCH, L. A. Yankee Atomic Electric Co. 82/07/23, Region 1, Office of Director 1p. 14151 305 24X Fiche 50-029, 82/07/23, 8208020292

8208090050 Forwards LER 82-020/03L-0
ANTIO, R. H. A. Yankee Atomic Electric Co. 82/07/29, HAYNES, R. C. Region 1, Office of Director 1p. 14269 361 24X Fiche 50-029, 82/07/29, 8208090050

--8208090052 LER 82-020/03L-0 on 820629, during testing of nonreturn valve tripping sys, valve 3 failed to close on actuation of train A. Caused by failure of main dump solenoid valve Valve replaced w/improved model. Remaining valves will be replaced.
FRENCH, L. A. Yankee Atomic Electric Co. 82/07/29, Region 1, Office of Director 1p. 14269 362 24X Fiche 50-029, 82/07/29, 8208090050

8208090118 Forwards LER 82-019/03L-0
ANTIO, R. H. A. Yankee Atomic Electric Co. 82/07/29, HAYNES, R. C. Region 1, Office of Director 1p. 14269 353 24X Fiche 50-029, 82/07/29, 8208090118

8090122 LER 82-019/03L-0 on 820629, voltage surges on 115-kV lines during thunderstorm resulted in loss of 2 126 line & loss of flow scram. Caused by lightning strike on 115-kV line during storm line restored to svc.
AY, E. L. Yankee Atomic Electric Co. 82/07/29 Region 1, Office of Director. Ip. 14269.354. 24X Fiche: 50-029, 82/07/29, 8208090118

30032 Forwards LER 82-021/03L-0
IO, H. A. Yankee Atomic Electric Co. 82/08/11. HAYNES, R. C. Region 1, Office of Director. Ip. 14517.262. 24X Fiche: 50-029, 82/08/11, 8208230032

8230045 LER 82-021/03L-0 on 820712, fire detection sys zones for charging pump cubicles & charcoal filters failed. Caused by rain water which entered junction box through openings made to facilitate const activity. Openings sealed.
AY, E. L. Yankee Atomic Electric Co. 82/08/11. Region 1, Office of Director. Ip. 14517.263. 24X Fiche: 50-029, 82/08/11, 8208230032

30072 Forwards LER 82-022/03L-0.
IO, H. A. Yankee Atomic Electric Co. 82/08/12. HAYNES, R. C. Region 1, Office of Director. Ip. 14517.205. 24X Fiche: 50-029, 82/08/12, 8208230072

8230074 LER 82-022/03L-0 on 820713, BI MOV-1 motor operator contactor circuit control transformer primary winding grounded during normal operation. Caused by nearby const activity resulting in rain entering EMCC-2 & BI-MOV-1 operator contactor.
ICE, D. A. Yankee Atomic Electric Co. 82/08/12. Region 1, Office of Director. Ip. 14517.206. 24X Fiche: 50-029, 82/08/12, 8208230072

Y 50-54 UNION CARBIDE RESEARCH REACTOR

Inspection reports, IE Bulletins & correspondence

10395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of. 112pp. 14358.001. 24X Fiche: 50-000, 82/07/19, 8204210395

Y 50-57 STATE UNIV. OF NEW YORK RESEARCH REACTOR

Inspection reports, IE Bulletins & correspondence

10395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of. 112pp. 14358.001. 24X Fiche: 50-000, 82/07/19, 8204210395

Y 50-59 TEXAS A&M UNIV. RESEARCH REACTOR

Inspection reports, IE Bulletins & correspondence

10395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of. 112pp. 14358.001. 24X Fiche: 50-000, 82/07/19, 8204210395

Y 50-70 GENERAL ELECTRIC TEST REACTOR

Judiciary correspondence

90121 Initial decision removing NRR 771024 show cause order, proving restart & designating proper geologic & seismic sign bases.
FOREMAN, H. Atomic Safety and Licensing Board Panel. 82/08/16. 240pp. 14381.303. 24X Fiche: 50-070, 82/08/16, 8208190121.

40232 Notice of ASLAB constitution. CN Kohl, chairman & BF Eilperin, A. Wilber, members.
EMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 82/08/20. 14519.147. 24X Fiche: 50-070, 82/08/20, 8208240232.

P Operating license stage documents & correspondence

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl.
EIBENHUT, D. Q. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. Ip. 14356.332. 24X Fiche: 50-000, 82/08/09, 8208090194

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

0 Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of. 112pp. 14358.001. 24X Fiche: 50-000, 82/07/19, 8204210395

DOCKET 50-77 CATHOLIC UNIV. OF AMERICA RESEARCH REACTOR

0 Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of. 112pp. 14358.001. 24X Fiche: 50-000, 82/07/19, 8204210395

DOCKET 50-83 UNIV. OF FLORIDA TRAINING REACTOR

P Security, medical, emergency & fire protection plans

8208130294 Forwards IE Safeguards Insp Repts 50-083/82-01 & 70-1068/82-01 on 820629-0701. No noncompliance noted.
VERRELLI, D. Division of Project & Resident Programs. 82/07/19. JACOB, A. M. Florida, Univ. of, Gainesville. 2pp. 14336.317. 24X Fiche: 50-083, 82/07/19, 8208130294.

--8208130299 IE Safeguards Insp Repts 50-083/82-01 & 70-1068/82-01 on 820629-0701. No noncompliance noted. Major areas inspected: security plan & organization, access controls, records & repts & physical barriers. Details withheld (ref 10CFR2.790).
MOORE, D. E., MCQUIRE, D. R. Division of Engineering & Technical Programs. 82/07/19. Ip. 14336.319. 24X Fiche: 50-083, 82/07/19, 8208130294.

0 Inspection reports, IE Bulletins & correspondence

8208130294 Forwards IE Safeguards Insp Repts 50-083/82-01 & 70-1068/82-01 on 820629-0701. No noncompliance noted.
VERRELLI, D. Division of Project & Resident Programs. 82/07/19. JACOB, A. M. Florida, Univ. of, Gainesville. 2pp. 14336.317. 24X Fiche: 50-083, 82/07/19, 8208130294.

--8208130299 IE Safeguards Insp Repts 50-083/82-01 & 70-1068/82-01 on 820629-0701. No noncompliance noted. Major areas inspected: security plan & organization, access controls, records & repts & physical barriers. Details withheld (ref 10CFR2.790).
MOORE, D. E., MCQUIRE, D. R. Division of Engineering & Technical Programs. 82/07/19. Ip. 14336.319. 24X Fiche: 50-083, 82/07/19, 8208130294.

DOCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

0 Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of. 112pp. 14358.001. 24X Fiche: 50-000, 82/07/19, 8204210395.

DOCKET 50-89 GENERAL ATOMIC CO.

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/19
Michigan, Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19.
8204210395

DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/19
Michigan, Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19.
8204210395

DOCKET 50-99 BABCOCK & WILCOX TEST REACTOR

J. Insurance & indemnity information

8208090032 Unexecuted Amend 21 to Indemnity Agreement B-B.
SALTZMAN, J. Assistant Director for State & License Relations
82/07/26. 1p. 14301.101 24X Fiche:50-099.82/07/26.8208090032

8208060217 Forwards Amend 21 to Indemnity Agreement B-B. in response to NRC 820720 ltr.
OLSEN, A F Babcock & Wilcox Co. 82/08/03 Division of Licensing
2pp. 14241 083 24X Fiche 50-099.82/08/03.8208060217

Q. Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/19
Michigan, Univ of 112pp. 14358 001. 24X Fiche 50-000.82/07/19.
8204210395

W Decommissioning Stage Documents & Correspondence

8208120004 Forwards order terminating License R-47 in accordance w/810723 application & Amend 21 to Indemnity Agreement B
EISENHUT, D O Division of Licensing. 82/07/20 OLSEN, A F Babcock & Wilcox Co 2pp 14332 244. 24X Fiche 50-099.82/07/20.8208120004

--8208120095 Order authorizing termination of License R-47, effective 82/07/20.
EISENHUT, D O Division of Licensing 82/07/20 Babcock & Wilcox Co 2pp 14332 247 24X Fiche 50-099.82/07/20.8208120004

--8208120097 Safety evaluation supporting termination of License R-47.
* Office of Nuclear Reactor Regulation, Director 82/07/20. 3pp.
14332 249. 24X Fiche: 50-099.82/07/20.8208120004

DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR

P. Operating license stage documents & correspondence

8208060197 Requests amend to License R-33 Amend authorizes increase in number of fuel elements from current license limitation of 12 to 20 elements or less increase in fuel elements allows reactor to operate in flux trap configuration.
TERRELL, C W Oklahoma, Univ of. 82/07/31. MILLER, J R Standardization & Special Projects Branch 6pp. 14239:009. 24X Fiche. 50-112.82/07/31.8208060197

DOCKET 50-113 UNIV OF ARIZONA RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/19
Michigan, Univ of. 112pp. 14358 001 24X Fiche:50-000.82/07/19.
8204210395

DOCKET 50-116 IOWA STATE UNIV. RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/19.
Michigan, Univ. of 112pp 14358 001 24X Fiche 50-000.82/07/19.
8204210395

DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR

H General correspondence

8208050256 Requests that DL Warner replace TJ Planje on distribution list re License R-79 Ltr dtd 820602, referred to in NRC 820712 ltr. cannot be found
BOLON, A E Missouri, Univ. of. Rolla 82/07/20 BERNARD, H Standardization & Special Projects Branch 1p. 14209:337 24X Fiche 50-123.82/07/20.8208050256

--8208050260 Advises of death of TJ Planje in Jul 1980 DL Warner is now Dean of School of Mines & Metallurgy
STODOLILL, P Missouri, Univ. of. Rolla. 82/07/20. BERNARD, H. Standardization & Special Projects Branch. 1p. 14209:338 24X Fiche 50-123.82/07/20.8208050256

DOCKET 50-128 TEXAS A&M UNIV. RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/19.
Michigan, Univ of 112pp. 14358 001 24X Fiche 50-000.82/07/19.
8204210395

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

8208240290 Forwards IE Insp Rept 50-133/82-03 on 820720-23 No noncompliance noted
STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/08/03 CRANE, P A Pacific Gas & Electric Co. 4pp. 14544 128 24X Fiche 50-133.82/08/03.8208240290

--8208240295 IE Insp Rept 50-133/82-03 on 820720-23 No noncompliance noted Major areas inspected operations, organization & administration, procedures, procurement & fire prevention
WILLETT, D J, YOUNG, T Division of Resident, Reactor Project & Engineering Programs 82/08/03 3pp 14544 132 24X Fiche: 50-133.82/08/03.8208240290

H General correspondence

8208020456 Responds to 820608 ltr re decommissioning facility Plant shut down in 1962 ABLD 820216 order established schedule for licensee to decide whether to decommission plant or resume operation Safety issues to be resolved prior to reopening.
DENTON, H R. Office of Nuclear Reactor Regulation, Director 82/07/07. SIMMONS, Q T. Affiliation Unknown. 3pp 14180 167. 24X Fiche. 50-133.82/07/07.8208020456

--8208020458 Demands facility be decommissioned.
SIMMONS, Q T. Affiliation Unknown. 82/06/08 Office of Nuclear Reactor Regulation, Director 2pp 14180 170 24X Fiche: 50-133.82/07/07.8208020456

8208020134 Requests decommissioning of facility.
D'ABBRACCI, T. Affiliation Unknown. 82/07/25. DENTON, H. Office of Nuclear Reactor Regulation, Director 1p. 14141:334. 24X Fiche: 50-133.82/07/25.8208020134

8208300354 Responds to 820725 ltr to H Denton re need for decommissioning plant Since facility has been shut down since 760706, public health & safety are not compromised.
LAJNAB, Q C Assistant Director For Operating Reactors. 82/08/20. D'ABBRACCI, T. Affiliation Unknown. 1p 14697:153 24X Fiche: 50-133.82/08/20.8208300354

Insurance & indemnity information

0303523 Submits responses to questions re insurance coverage per
0524 ltr No add'l studies analyzing risk & consequences
accident in cold shutdown conducted
NEATIS, O A Pacific Gas & Electric Co 82/07/28. SALTZMAN, J
Assistant Director for State & Licensee Relations 5pp 14163-093.
X Fiche 50-133, 82/07/28, 8208030523

Operating license stage documents & correspondence

080064 Generic ltr to all licensees of operating plants, applicants
for DL & holders of CP re Commission approved charter for
RRC Svc list encl
RCKS, W J Office of the Executive Director for Operations,
82/07/02 Consolidated Edison Co of New York 93pp. 14194-001
X Fiche 50-000, 82/07/02, 8207080064
0909194 Generic Ltr 82-14 to all reactor licensees, holders of CP &
applicants re submittal of documents to NRC Summarizes 10CFR
Chapter I requirements & provides alternatives to
requirements Svc list encl.
EENHUT, D O Division of Licensing 82/08/09 Consolidated
Edison Co of New York. 1p 14356:332. 24X Fiche 50-000, 82/08/09,
808090194.

Inspection reports, IE Bulletins & correspondence

210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
Damage." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16.
Consolidated Edison Co of New York 87pp. 14356-274. 24X
Fiche 50-000, 82/07/16, 8204210393.

210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19
Michigan, Univ. of 112pp. 14358-001 24X Fiche 50-000, 82/07/19,
8204210395

210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon
Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20.
Consolidated Edison Co of New York. 112pp. 14381-001. 24X
Fiche 50-000, 82/07/20, 8204210396.

210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride
Vessels." Svc list encl.
JORDAN, E. L. Division of Fuel Facilities, Materials & Safeguards.
82/07/20 Consolidated Edison Co. of New York. 71pp 14357-276.
X Fiche 50-000, 82/07/20, 8204210397.

210398 IE Info Notice 82-26, "RCIC & IFCI Turbine Exhaust Check
Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22
Consolidated Edison Co. of New York 112pp. 14194-321 24X
Fiche 50-000, 82/07/22, 8204210398.

210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in
Proximity of Drained & Open RCS." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23
Consolidated Edison Co. of New York. 122pp. 14380-115. 24X
Fiche 50-000, 82/07/23, 8204210401.

210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube
Support Pin Failures at Westinghouse PWRs." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York. 127pp. 14194-120. 24X
Fiche 50-000, 82/07/23, 8204210402.

210403 IE Info Notice 82-30, "Loss of Thermal Bleeders in RCS Piping
at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26.
Consolidated Edison Co. of New York. 121pp. 14357-013. 24X
Fiche 50-000, 82/07/26, 8204210403.

210405 IE Info Notice 82-31, "Overexposure of Diver During Work in
Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28.
Consolidated Edison Co. of New York. 122pp. 14357-146. 24X
Fiche 50-000, 82/07/28, 8204210405.

240290 Forwards IE Insp Rept 50-133/82-03 on 820720-23. No
noncompliance noted.
ERNBERG, D. M. Division of Resident, Reactor Project & Engineering
Programs 82/08/03. CRANE, P. A Pacific Gas & Electric Co. 4pp.
14544-128 24X Fiche 50-133, 82/08/03, 8208240290.

--8208240295 IE Insp Rept 50-133/82-03 on 820720-23. No noncompliance
noted Major areas inspected operations, organization &
administration, procedures, procurement & fire prevention
WILLETT, D J., YOUNG, T. Division of Resident, Reactor Project &
Engineering Programs 82/08/03 5pp 14544-132. 24X
Fiche 50-133, 82/08/03, 8208240290

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From
Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/03.
Consolidated Edison Co of New York. 117pp 14388-201 24X
Fiche 50-000, 82/08/03, 8204210407

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective
dose exposures in 1981 for operating nuclear power plants &
analyzing said info Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records 82/07/13 UDELL, R. A.
Critical Mass Energy Project. 8pp. 14679-208 24X
Fiche 50-000, 82/07/13, 8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power
Facilities for CY81."
* NRC - No Detailed Affiliation Given 82/07/13. 48pp
14679-216 24X Fiche 50-000, 82/07/13, 8208270010

--8208270611 Forwards "Rept of Recorded Personnel Whole Body Exposures
for CY81." per 10CFR20.407(a)
CRANE, P. A. Pacific Gas & Electric Co. 82/03/26. BASSETT, H. B.
Office of Management and Program Analysis. 1p. 14680-056 24X
Fiche 50-000, 82/07/13, 8208270010.

--8208270616 "Rept of Recorded Personnel Whole Body Exposures for CY81."
Pacific Gas & Electric Co. 82/03/26 1p. 14680-057. 24X
Fiche 50-000, 82/07/13, 8208270010

8208120316 Forwards monthly operating rept for June 1982.
WEEKS, E. D. Pacific Gas & Electric Co. 82/07/19. Office of P
Resource Management, Director. 1p. 14324-263. 24X
Fiche 50-133, 82/07/19, 8208120316.

--8208120318 Monthly operating rept for June 1982
DERBS, P. B. Pacific Gas & Electric Co. 82/07/19. App. 14324-266
24X Fiche 50-133, 82/07/19, 8208120316.

B Reportable occurrences, LERs & related correspondence

8208020241 Forwards LER 82-007/03L-0
CRANE, P. A. Pacific Gas & Electric Co. 82/07/23 ENGELKEN, R. H.
Region 5, Office of Director. 1p. 14151-231. 24X
Fiche 50-133, 82/07/23, 8208020241.

--8208020247 LER 82-007/03L-0: on 820623, w/unit shutdown, screen wash
pump 1 was started but no discharge pressure observed. Cause
by stuck open position on discharge check valve. Pump
repaired & returned to svc.
OETTY, B. C. Pacific Gas & Electric Co. 82/07/23. Region 5,
Office of Director. 1p. 14151-232. 24X Fiche 50-133, 82/07/23,
8208020241

DOCKET 50-134 WORCESTER POLYTECH INST. RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19.
Michigan, Univ. of 112pp. 14358-001. 24X Fiche 50-000, 82/07/19,
8204210395.

DOCKET 50-139 UNIV. OF WASHINGTON RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8208030504 Forwards IE Safeguards Insp Rept 50-139/82-02 on 820722. No
noncompliance noted.
NORDEHAUG, L. R. Division of Radiological Safety & Safeguards
Program. 82/07/29. CARLSON, D. A. Washington, Univ. of. 4pp.
14162-301. 24X Fiche 50-139, 82/07/29, 8208030504.

--B20803045B IE Safeguards Insp Rept 50-139/82-02 on B20722 No noncompliance noted Major areas inspected security plan & procedures, protection of SNM, access control alarm sys communications & security organization Details withheld
SCHWAB, C. A., MCQUEEN, A. D., SCHUSTER, M. D. Division of Radiological Safety & Safeguards Program B2/07/29 1p 14162 305 24X
Fiche 50-139, B2/07/29, B208030504

G Inspection Reports, IE Bulletins & correspondence

B208030504 Forwards IE Safeguards Insp Rept 50-139/82-02 on B20722 No noncompliance noted
NGACERHAUG, L. R. Division of Radiological Safety & Safeguards Program B2/07/29 CARLSON, D. A. Washington, Univ. of. 4pp
14162 301 24X Fiche 50-139, B2/07/29, B208030504

--B20803049B IE Safeguards Insp Rept 50-139/82-02 on B20722 No noncompliance noted Major areas inspected security plan & procedures, protection of SNM, access control alarm sys communications & security organization Details withheld
SCHWAB, C. A., MCQUEEN, A. D., SCHUSTER, M. D. Division of Radiological Safety & Safeguards Program B2/07/29 1p 14162 305 24X
Fiche 50-139, B2/07/29, B208030504

DOCKET 50-142 UCLA TRAINING REACTOR

F Security, medical, emergency & fire protection plans

B208190160 Forwards five pages of Amend 5 to physical security plan Pages withheld (ref 10CFR2 790)
ASHBAUGH, C. E. California, Univ. of. Los Angeles B2/08/10
BERNARD, M. Standardization & Special Projects Branch 1p
14391 019 24X Fiche 50-142, B2/08/10, B208190160

G Adjudicatory correspondence

B208020289 Objects to City of Santa Monica proposed protective order & affidavit of nondisclosure & responds to Committee to Bridge the Gap B20712 mods to contention language.
CORMIER, W. H. California, Univ. of. Los Angeles B2/07/26
FRYE, J. H., PARIS, D. H., LUEBKE, E. A. Atomic Safety and Licensing Board Panel 2pp 14151 302 24X Fiche 50-142, B2/07/26, B208020289

B208090182 Advises that univ submitted emergency response plan to Commission on B20729 Plan nearly identical to Mar 1982 version Plan & transmittal ltr encl w/o encl
CORMIER, W. H. California, Univ. of. Los Angeles B2/08/02
FRYE, J. H., PARIS, D. H., LUEBKE, E. A. Atomic Safety and Licensing Board Panel 1p 14272 056 24X Fiche 50-142, B2/08/02, B208090182

B208110139 Advises of change in circumstances affecting scope of discovery on Contention XX UCLA recently completed transfer of reactor fuel, reducing U-235 inventory to less than 5 kg Transfer changes basis of 10CFR73 60 exemption request
CORMIER, W. H. California, Univ. of. Los Angeles B2/08/06
FRYE, J. H., PARIS, D. H., LUEBKE, E. A. Atomic Safety and Licensing Board Panel 1p 14314 207 24X Fiche 50-142, B2/08/06, B208110139

--B208110142 Advises of recent transfer of U-235, reducing inventory to less than 5 kg UCLA need not maintain self-protecting conditions for inc-core fuel to remain exempt from updated safeguards requirements of 10CFR73 60
WEIST, W. F. California, Univ. of. Los Angeles B2/08/06
BERNARD, M. Standardization & Special Projects Branch 1p
14314 308 24X Fiche 50-142, B2/08/06, B208110139

B208110178 Requests svc to listed persons of new emergency plan & B20430 amends future timely svc & compliance w/filing deadlines requested
HIRSCH, D. Committee to Bridge the Gap B2/08/06 CORMIER, W. H. California, Univ. of. Los Angeles 1p 14314 172 24X
Fiche 50-142, B2/08/06, B208110178

B208110179 Comments on Cormier B20802 ltr re applicant proposed amends to emergency plan ASLB should not schedule add'l discovery & motions for summary disposition until amends completed & plan reviewed by Committee to Bridge the Gap
HIRSCH, D. Committee to Bridge the Gap B2/08/06 FRYE, J. H., PARIS, D. H., LUEBKE, E. A. Atomic Safety and Licensing Board Panel 2pp 14314 170 24X Fiche 50-142, B2/08/06, B208110179

B208110195 Objections to portions of ASLB B20726 prehearing conference order denying Committee to Bridge the Gap request that NRC be directed to furnish info to assess potential conflict of interest Declaration of Svc encl
HIRSCH, D. Committee to Bridge the Gap B2/08/06 Atomic Safety and Licensing Board Panel 7pp 14313 033 24X
Fiche 50-142, B2/08/06, B208110195

B208110212 Response to NRC & UCLA concerns re B20712 language mods to Contention VIII reflecting proposed application amends Basis for contention does not refer to 1982 amended application Declaration of Svc encl
HIRSCH, D. Committee to Bridge the Gap B2/08/06 16pp 14313 045 24X Fiche 50-142, B2/08/06, B208110212

B208130152 Response to Committee to Bridge the Gap B20720 request for production of documents re security-related Contention XX. UCLA will provide outlined documents at B20812 document exam session Certificate of Svc encl
CORMIER, W. H. California, Univ. of. Los Angeles B2/08/09
Committee to Bridge the Gap 11pp 14338 318 24X
Fiche 50-142, B2/08/09, B208130152

B208130204 Response to first set on interrogatories for Contention XX Certificate of Svc encl
CORMIER, W. H. California, Univ. of. Los Angeles B2/08/09 Atomic Safety and Licensing Board Panel 14pp 14339 080 24X
Fiche 50-142, B2/08/09, B208130204

B208170266 Memorandum scheduling B20825 conference call to discuss hearing schedule for emergency plan contentions not subj of motions for summary disposition, per B20729 prehearing conference order. SER to be issued on B20816
FRYE, J. H. Atomic Safety and Licensing Board Panel B2/08/13 2pp 14367 137 24X Fiche 50-142, B2/08/13, B208170266

B208170325 Informs of ASLB decision to treat Committee to Bridge the Gap B20806 objections to B20726 prehearing conference order as motion for reconsideration Responses due by B20823
FRYE, J. H. Atomic Safety and Licensing Board Panel B2/08/13
WOODHEAD, C. P. Hearing Branch 1 CORMIER, W. H. California, Univ. of. Los Angeles 1p 14366 348 24X Fiche 50-142, B2/08/13, B208170325

B208170330 Advises of intent to file motion for summary disposition of all contentions except Contention XXI, pursuant to ASLB B20726 prehearing conference order Contention to be revised to reflect UCLA B20729 emergency plan
WOODHEAD, C. P. Hearing Branch 1 B2/08/16 FRYE, J. H., PARIS, D. H., LUEBKE, E. A. Atomic Safety and Licensing Board Panel 1p 14367 003 24X Fiche 50-142, B2/08/16, B208170330

B208180121 Memorandum & order approving Committee to Bridge the Gap B20712 mods to Contentions VIII, I 2 & V 3 Contentions based only on 1960 Hazards Analysis Restatement of contentions pursuant to ASLB B20816 order encl
LUEBKE, E. A., PARIS, D. H., FRYE, J. Atomic Safety and Licensing Board Panel B2/08/16 28pp 14377 127 24X Fiche 50-142, B2/08/16, B208180121

B208200301 Provides info per ASLB B20726 order re in camera hearing & motion for summary disposition Transcript of hearing should not be withheld from public disclosure. Committee to move for summary disposition of Contentions XIII & XVII
HIRSCH, D. Committee to Bridge the Gap B2/08/16 FRYE, J. H., PARIS, D. H., LUEBKE, E. A. Atomic Safety and Licensing Board Panel 1p 14394 149 24X Fiche 50-142, B2/08/16, B208200301

B208240249 Advises that univ intends to move for summary disposition of all contentions admitted to proceeding w/exception of Contentions XX & XXI Transcript of prehearing conference contains no security sensitive info
CORMIER, W. H. California, Univ. of. Los Angeles B2/08/16
FRYE, J. H., PARIS, D. H., LUEBKE, E. A. Atomic Safety and Licensing Board Panel 3pp 14520 095 24X Fiche 50-142, B2/08/16, B208240249

B208230052 Clarifies ASLB B20816 order ruling on mod to contentions. Withdrawn document identified as 1960 hazards analysis submitted as SAR in 1980 application
WOODHEAD, C. P. Hearing Branch 1 B2/08/19 FRYE, J. H., LUEBKE, E. A., PARIS, D. H. Atomic Safety and Licensing Board Panel 3pp 14517 232 24X Fiche 50-142, B2/08/19, B208230052

B208230078 Motion to amend Apr 1981 motion for summary disposition of Contention XX, to reflect recent reduction in inventory of SNM to less than 5 kg & change in application of 10CFR73, Certificate of Svc encl
WOODHEAD, C. P. Hearing Branch 1 B2/08/20 Atomic Safety and Licensing Board Panel 5pp 14517 146 24X Fiche 50-142, B2/08/20, B208230078

B208240337 Response to Committee to Bridge the Gap B20806 filing which ASLB is treating as motion for reconsideration of ASLB B20726 prehearing conference order Concurs w/ASLB decision to deny Gap request for add'l info Certificate of Svc encl
CORMIER, W. H. California, Univ. of. Los Angeles B2/08/20 Atomic Safety and Licensing Board Panel 5pp 14520 316 24X
Fiche 50-142, B2/08/20, B208240337

40356 Forwards latest amends to application, correcting two items emergency response plan.
MIER, W.H. California. Univ. of. Los Angeles 82/08/20
SCH.D. Committee to Bridge the Gap App 14521 053 24X
Fiche 50-142, 82/08/20, 8208240356

50216 Forwards IE Insp Rept 50-142/82-02 & H Bernard photographs exterior of Boelter Hall w/o encl
DHEDAD, C.P. Hearing Branch 1 82/08/23 HIRSCH, D. Committee to Bridge the Gap Ip. 14541 357 24X Fiche 50-142, 82/08/23, 8250216

50287 Response opposing Committee to Bridge the Gap 820806 filing ch ASLB treated as motion for reconsideration of ASLB 726 prehearing conference order Interrogatories unlikely lead to admissible evidence w/Certificate of Svc.
DHEDAD, C.P. Hearing Branch 1 82/08/23 Atomic Safety and Licensing Board Panel 32pp 14542 186 24X Fiche 50-142, 82/08/23, 8250287

70418 Forwards addl questions re fuel self-protection calculations included as Exhibit A to Univ response to Committee to Bridge the Gap Interrogatories on Contention XX, per 820819
J.H. Affiliation Unknown 82/08/23 CORNIER, W.H. California, Univ. of. Los Angeles 3pp. 14545 240. 24X Fiche 50-142, 82/08/23, 8270418

800293 Memorandum & order confirming 820825 telcon w/UCLA, Committee to Bridge the Gap, Santa Monica, CA & NRC re scope Santa Monica interest in contentions, status of Contentions XXI & XXIII & use of technical terminology
E.J.H. Atomic Safety and Licensing Board Panel. 82/08/26 3pp 99-235. 24X Fiche 50-142, 82/08/26, 8208300293

800301 Order directing Secretary to place 820630 prehearing Conference transcript, Pages 672-712 in PDH & LPDR.
E.J.H. Atomic Safety and Licensing Board Panel. 82/08/26 14673:218 24X Fiche 50-142, 82/08/26, 8208300301

Operating license stage documents & correspondence

810139 Advises of change in circumstances affecting scope of recovery on Contention XX. UCLA recently completed transfer reactor fuel, reducing U-235 inventory to less than 5 kg under changes basis of 10CFR73.60 exemption request.
MIER, W.H. California. Univ. of. Los Angeles 82/08/06
SCH.D. H. PARIS, D.H., LUEDKE, E.A. Atomic Safety and Licensing Board Panel. Ip. 14314 307 24X Fiche 50-142, 82/08/06, 8208110139

8110142 Advises of recent transfer of U-235, reducing inventory to less than 5 kg UCLA need not maintain self-protecting conditions for in-core fuel to remain exempt from updated safeguards requirements of 10CFR73.60
WEOST, W.F. California. Univ. of. Los Angeles. 82/08/06.
BERNARD, H. Standardization & Special Projects Branch Ip. 14314:308 24X Fiche 50-142, 82/08/06, 8208110139

Inspection reports, IE Bulletins & correspondence

810395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl
DAN, E.L. Division of Engineering & Quality Assurance. 82/07/19.
Michigan, Univ. of. 112pp. 14358:001. 24X Fiche 50-000, 82/07/19, 8210395

80100 Forwards IE Insp Rept 50-142/82-02 on 820628-30 & notice violation
BERNBERG, D.M. Division of Resident, Reactor Project & Engineering Programs. 82/07/22 WEOST, W.F. California. Univ. of. Los Angeles. 14345:160. 24X Fiche 50-142, 82/07/22, 8208160100.

8160102 Notice of violation from Insp on 820628-30
YOUNG, T. Division of Resident, Reactor Project & Engineering Programs. 82/07/22 Ip. 14345:162. 24X Fiche 50-142, 82/07/22, 8208160100.

8160105 IE Insp Rept 50-142/82-02 on 820628-30. Noncompliance noted: addendum to prestart checkoff for 820111 not submitted to Director of nuclear energy lab for routine review.
ORRILL, P., STEWART, P., YOUNG, T. Division of Resident, Reactor Project & Engineering Programs 82/07/20. App 14345:163. 24X Fiche 50-142, 82/07/22, 8208160100.

80172 Ack receipt of 820803 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-142/82-02
HOP, T.W. Division of Resident, Reactor Project & Engineering Programs. 82/08/16 WEOST, W.F. California. Univ. of. Los Angeles. 14519:327 24X Fiche 50-142, 82/08/16, 8208240172

--8208240174 Responds to NRC 820722 ltr re violations noted in IE Insp Rept 50-142/82-02 Corrective actions N Osterlander designated as NEL acting director Action will allow for approval prior to implementation of changes.
WEOST, W.F. California. Univ. of. Los Angeles 82/08/03 YOUNG, T. Division of Resident, Reactor Project & Engineering Programs 2pp 14558 171. 24X Fiche 50-142, 82/08/16, 8208240172

I Hearing transcripts on non-antitrust matters

8208300297 Transcript of ASLB 820630 prehearing conference in Los Angeles, CA Pp 672-712. Released per ASLB 820826 order
* Atomic Safety and Licensing Board Panel 82/06/30 42pp. 14599:238 24X Fiche 50-142, 82/06/30, 8208300297

DOCKET 50-146 SAXTON NUCLEAR EXPERIMENTAL FACILITY

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A
FELTON, J.M. Division of Rules and Records 82/07/13 UCELL, R.A. Critical Mass Energy Project. Pp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81"
* NRC - No Detailed Affiliation Given. 82/07/13 48pp 14679:216 24X Fiche 50-000, 82/07/13, 8208270010

DOCKET 50-147 ROCKWELL INTL CORP. CRITICAL FACILITY

Q Inspection reports, IE Bulletins & correspondence

8208240269 Ack receipt of 820809 ltr informing NRC of steps taken to correct violation noted in IE Insp rept
STERNBERG, D.M. Division of Resident, Reactor Project & Engineering Programs. 82/08/16. CRANDALL, W.E. Northrop Research & Technical Center. Ip. 14544:126 24X Fiche 50-147, 82/08/16, 8208240269.

--8208240273 Responds to NRC 820727 ltr re violation noted in IE Insp rept. Corrective actions: Future meetings scheduled so health physicist may attend & addl health physicists will be certified to comply w/Tech Specs
CRANDALL, W.E. Northrop Research & Technical Center 82/08/09.
STERNBERG, D.M. Division of Resident, Reactor Project & Engineering Programs Ip. 14544:127. 24X Fiche 50-147, 82/08/16, 8208240269.

DOCKET 50-148 UNIV. OF KANSAS RESEARCH REACTOR

R Periodic operating reports & related correspondence

8208020362 Submits annual operating rept for Jul 1981-June 1982.
MEBLER, R.B. Kansas. Univ. of. 82/07/23 Division of Licensing. 2pp 14150:130. 24X Fiche 50-148, 82/07/23, 8208020362.

DOCKET 50-150 OHIO STATE UNIV RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19.
Michigan, Univ. of 112pp. 14358:001. 24X Fiche 50-000, 82/07/19, 8204210395.

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

8208090197 Forwards response to NRC 820607 ltr re intrusion detection sys. Present sys deemed adequate. Response withheld (ref 10CFR73.21).
VANDEWALLE, D.J. Consumers Power Co. 82/07/29. CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 14272:014. 24X Fiche 50-155, 82/07/29, 8208090197

8208190430 Releases public version of revised site emergency plan & implementing procedures.
FELTON, J.M. Division of Rules and Records. 82/08/10. Document Management Branch. Ip. 14504:281 24X Fiche 50-155, 82/08/10, 8208190430.

- 8208190433 Forwards public version of revised Vol 9 to site emergency plan & revised Vol 9A to site emergency plan implementing procedures
VANDEWALLE, D. J. Consumers Power Co 82/07/30 CRUTCHFIELD, D. Operating Reactors Branch 5 1p 14504 284 24X
Fiche 50-155, 82/08/10, 8208190433
- 8208190434 Public version of revised Vol 9 to site emergency plan & Consumers Power Co 81/11/17 250pp 14504 285 24X
Fiche 50-155, 82/08/10, 8208190430
- 8208190435 Public version of Vol 9A to site emergency plan implementing procedures, including Procedures 1 re activation of emergency plan, 2 re facility actions during emergency & 3 re activation of technical support ctrs
HARTMAN, C. J. Consumers Power Co 81/11/24 300pp 14505 177 24X
Fiche 50-155, 82/08/10, 8208190430
- 8208170171 Requests submittal of current engineering drawings of facility layout & sys needed in support of two reactor safeguards programs aimed at reviewing effectiveness of NRC regulations & validating vital area designations
CRUTCHFIELD, D. Operating Reactors Branch 5 82/08/11
VANDEWALLE, D. Consumers Power Co 4pp 14364 318 24X
Fiche 50-155, 82/08/11, 8208170171
- Q Adjudicatory correspondence
- 8208030306 Reply opposing Christa-Maria 820714 motion requesting NRC 820625 testimony be sub'd of evidentiary hearings rather than first being pursued through deposition process Certificate of Svc encl
GALLO, J. Consumers Power Co GALLO, J. Isham, Lincoln & Beale 82/07/29 Atomic Safety and Licensing Board Panel 9pp 14157 147 24X
Fiche 50-155, 82/07/29, 8208030306
- 8208030388 Proposed findings of fact & conclusions of law on Christa-Maria Contentions 9(4), 9(5) & 9(7) Certificate of Svc encl.
SEMEL, H. Christa-Maria SEMEL, H. Antioch College of Law 82/07/29 7pp 14154 265 24X
Fiche 50-155, 82/07/29, 8208030388
- 8208040227 Forwards proposed opinion on administrative controls contention & certain emergency planning subcontentions & proposed findings of fact & conclusions of law on same issues
COPELAND, V. O. Isham, Lincoln & Beale, COPELAND, V. O. Consumers Power Co 82/07/30 BLOCH, P. B., PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel 1p 14188 140 24X
Fiche 50-155, 82/07/30, 8208040227
- 8208040232 Proposed opinion on administrative controls contention (O'Neill) 110(a) & emergency planning subcontentions (Christa-Maria 9(4), 9(5), 9(7) & part of 9(2))
GALLO, J., STEPTOE, P. P., COPELAND, V. O. Consumers Power Co 82/07/30 15pp 14188 141 24X
Fiche 50-155, 82/07/30, 8208040227
- 8208040243 Proposed findings of fact & conclusions of law on administrative controls contention, O'Neill 110(a) & emergency planning subcontentions, Christa-Maria 9(4), 9(5), 9(7) & part of 9(2)
GALLO, J., STEPTOE, P. P., COPELAND, V. O. Consumers Power Co 82/07/30 17pp 14188 136 24X
Fiche 50-155, 82/07/30, 8208040227
- 8208060090 Forwards proposed findings of fact & conclusions of law on O'Neill Contention II Q. (a) & Christa-Maria Contentions 9(4), 9(5) & 9(7)
ODDARD, R. J. Hearing Branch 3 82/07/30 BLOCH, P. B., SHON, F. J., PARIS, D. H. Atomic Safety and Licensing Board Panel 1p 14238 134 24X
Fiche 50-155, 82/07/30, 8208060090
- 8208060093 Proposed findings of fact & conclusions of law on O'Neill Contention II Q. (a) re adequacy of administrative controls proposed to prevent cost drop over spent fuel pool.
ODDARD, R. J. Hearing Branch 3 82/07/30 6pp 14238 135 24X
Fiche 50-155, 82/07/30, 8208060090
- 8208060096 Proposed findings of fact & conclusions of law on Christa-Maria Contentions 9(4), 9(5) & 9(7) re emergency evacuation
ODDARD, R. J. Hearing Branch 3 82/07/30 6pp 14238 141 24X
Fiche 50-155, 82/07/30, 8208060090
- 8208040025 Inform that licensee had promptly notified NRC, on 820519, before hearings, of possible structural inadequacy of seat-gantry crane to support 24-ton fuel transfer cast. Issue of cost drop properly lies within ASLB jurisdiction
ODDARD, R. J. Hearing Branch 3 82/08/03 BLOCH, P. B., SHON, F. J., PARIS, D. H. Atomic Safety and Licensing Board Panel 2pp 14189 155 24X
Fiche 50-155, 82/08/03, 8208040025
- 8208060111 Forwards util draft evaluation rept re INPO 1982 review, formalizing handwritten preliminary findings & recommendations made available to ASLB & parties on 820608
GALLO, J. Isham, Lincoln & Beale GALLO, J. Consumers Power Co 82/08/03 BLOCH, P. B., SHON, F. J., PARIS, D. H. Atomic Safety and Licensing Board Panel 38pp 14238 194 24X
Fiche 50-155, 82/08/03, 8208060111
- 8208090264 Summarizes pertinent provisions of ASLB 820804 telcon re spent fuel pool mod No schedule determined for further evidentiary hearings Unresolved issues involve structural concrete analysis & seismic stability of overhead crane
ODDARD, R. J. Hearing Branch 3 BACHMANN, R. J. Hearing Branch 1 82/08/06 BLOCH, P. B., PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel 2pp 14270 319 24X
Fiche 50-155, 82/08/06, 8208090264
- 8208110072 Memorandum & order denying J. O'Neill 820706 motion that ASLB adopt terms of agreement between CPC & NRC re 60-ton spent fuel transfer cast as license condition
BLOCH, P. B. Atomic Safety and Licensing Board Panel 82/08/06, O'Neill, J. 1p 14316 352 24X
Fiche 50-155, 82/08/06, 8208110072
- 8208110093 Initial decision re emergency planning contentions on emergency planning pamphlet Pamphlet shall be modified as listed & promptly distributed
BLOCH, P. B., PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel 82/08/06 19pp 14316 315 24X
Fiche 50-155, 82/08/06, 8208110093
- 8208110194 Response in opposition to intervenors Christa Maria, et al 820714 motion to reopen hearing record re Contention 11, C on potential for dropping spent fuel transfer cast. Intervenor had ample notice of design inadequacies.
GALLO, J. Consumers Power Co GALLO, J. Isham, Lincoln & Beale 82/08/06 Atomic Safety and Licensing Board Panel 6pp 14314 001 24X
Fiche 50-155, 82/08/06, 8208110194
- 8208110199 Affidavit of FA Turaki re potential deficiencies w/spent fuel transfer cast load-bearing pins & reactor bldg crane girder load-bearing bolts. Event rept based upon Whiting Corp analyses of unreliability of pins & bolts.
TURAKI, F. A. Consumers Power Co 82/08/04 3pp 14314 007 24X
Fiche 50-155, 82/08/06, 8208110194
- 8208110211 Affidavit of DE Demoor re Event Rept E-BRP-82-26 prepared by F. Turaki on safety concern w/spent fuel transfer cast. Based upon Whiting Corp testimony, situation did not require reporting Rept retracted. W/Certificate of Svc.
DEMOOR, D. E. Consumers Power Co 82/08/04 28pp 14314 010 24X
Fiche 50-155, 82/08/06, 8208110194
- 8208130005 Confirms 820810 telcon agreement w/Judge Bloch delaying date for filing findings of fact on TMI issues until 820913
BACHMANN, R. J. Regulations Division 82/08/11 BLOCH, P. B., SHON, F. J., PARIS, D. H. Atomic Safety and Licensing Board Panel 1p 14333 198 24X
Fiche 50-155, 82/08/11, 8208130005
- 8208130133 Order extending Commission time to review Director's Decision 80-82-05 until 820913.
CHILK, S. J. Office of the Secretary of the Commission 82/08/12, Commissioners 1p 14336 017 24X
Fiche 50-155, 82/08/12, 8208130133
- 8208130145 Memorandum & order denying Christa-Maria, et al 820719 motion requesting reopening of record re cost drop contention.
BLOCH, P. B. Atomic Safety and Licensing Board Panel 82/08/12, Christa-Maria 1p 14337 148 24X
Fiche 50-155, 82/08/12, 8208130145
- 8208170124 Proposed findings of fact re Christa-Maria Contention B & O'Neill Contention III-2 (Subparts 1, 2 & 3). Certificate of Svc encl.
SEMEL, H. Christa-Maria SEMEL, H. Antioch College of Law 82/08/13 14pp 14365 213 24X
Fiche 50-155, 82/08/13, 8208170124
- 8208170264 Forwards Chapter 5 & portions of App IV to probabilistic risk assessment re containment integrity, Licensee 820720 11r containing revisions to isolation failure calculations encl.
GALLO, J. Isham, Lincoln & Beale GALLO, J. Consumers Power Co 82/08/13 BLOCH, P. B., PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel 100pp 14367 139 24X
Fiche 50-155, 82/08/13, 8208170264
- 8208200189 Memorandum correcting error on Page 13 of 820806 initial decision
BLOCH, P. B. Atomic Safety and Licensing Board Panel 82/08/18 1p 14500 138 24X
Fiche 50-155, 82/08/18, 8208200189

40374 Forwards until reply to intervenor proposed findings on Christa-Maria Contentions 9(4), 9(5) & part of 9(2). ELAND, V. O. Isham, Lincoln & Beale. COPELAND, V. O. Consumers Power Co. 82/08/19. BLOCH, P., PARIS, D. H., SHON, F. J. Atomic Safety Licensing Board Panel. 1p. 14522 319. 24X Fiche: 50-155, 82/08/19, 8208240374

8240377 Reply to intervenor proposed findings on Christa-Maria Contentions 9(4), 9(5) & part of 9(2). GALLO, J. Isham, Lincoln & Beale. 82/08/19. 14pp. 14522 320. 24X Fiche: 50-155, 82/08/19, 8208240374

70508 Proposed findings of fact & conclusions of law re EIA Certificate of Bvc encl. SEMMEL, H. Antioch College of Law. 08/20. 11pp. 14564 095. 24X Fiche: 50-155, 82/08/20, 8208270508.

50224 Forwards proposed findings of fact & conclusions of law on O'Neill Contention VIII re NEPA issues & Christa-Maria Contention B & O'Neill Contention III E 2 re THM issues. HAHN, R. O. Hearing Branch 1. 82/08/23. BLOCH, P. B., SHON, F. J., 18, O. H. Atomic Safety and Licensing Board Panel. 1p. 14542 004. 24X Fiche: 50-155, 82/08/23, 8208250224.

8250232 Proposed findings of fact & conclusions of law on O'Neill Contention VIII re NEPA issues. ACHMANN, R. O. Hearing Branch 1. 82/08/23. 7pp. 14542 005. 24X Fiche: 50-155, 82/08/23, 8208250224

8250238 Proposed findings of fact & conclusions of law on Christa-Maria Contention B & O'Neill Contention III E 2 re THM issues. ACHMANN, R. O. Hearing Branch 1. 82/08/23. 10pp. 14542 012. 24X Fiche: 50-155, 82/08/23, 8208250224.

70328 Forwards proposed partial initial decision & proposed findings of fact & conclusions of law on Christa-Maria Contention B & O'Neill Contention III E-2. ELAND, V. O. Isham, Lincoln & Beale. COPELAND, V. O. Consumers Power Co. 82/08/23. BLOCH, P., PARIS, D. H., SHON, F. J. Atomic Safety Licensing Board Panel. 1p. 14567 019. 24X Fiche: 50-155, 82/08/23, 8208270328

8270333 Proposed partial initial decision on admitted issues re Christa-Maria Contention B & O'Neill Contention III E-2. license demonstrated makeup line-pool water level monitor motor-operated valves adequate. GALLO, J. Isham, Lincoln & Beale. 82/08/23. Atomic Safety and Licensing Board Panel. 1pp. 14567 020. 24X Fiche: 50-155, 82/08/23, 8208270328.

8270337 Proposed findings of fact & conclusions of law on admitted issues re Christa-Maria Contention B & O'Neill Contention III E-2. Consumers Power Co. * Isham, Lincoln & Beale. 82/08/23. 1pp. 14567 035. 24X Fiche: 50-155, 82/08/23, 8208270328.

70514 Forwards until proposed findings of fact & conclusions of law remaining NEPA issues. THORNTON, P. Isham, Lincoln & Beale. THORNTON, P. Consumers Power Co. 82/08/23. BLOCH, P., PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel. 1p. 14564 109. 24X Fiche: 50-155, 82/08/23, 82070514.

8270518 Proposed findings of fact & conclusions of law on remaining NEPA issues. Certificate of Bvc encl. GALLO, J. THORNTON, P. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale. 82/08/23. 18pp. 14564 110. 24X Fiche: 50-155, 82/08/23, 8208270514

70414 Advises that parties agree to 820927 data for simultaneous findings of fact & conclusions of law re O'Neill Contention II, C on cash drop issues. GALLO, J. Isham, Lincoln & Beale. GALLO, J. Consumers Power Co. 08/25. BLOCH, P. B., PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board Panel. 1p. 14565 237. 24X Fiche: 50-155, 82/08/25, 82070414.

Insurance & indemnity information

60224 Forwards Endorsement 92 to NELIA Policy NF-117. UNFELKER, R. Consumers Power Co. 82/08/02. SALTZMAN, J. (Trust & Economic analysis Branch (Utility Finance)). 2pp. 141 067. 24X Fiche: 50-155, 82/08/02, 8208060224.

70494 Forwards Endorsement 93 to NELIA Policy NF-117. UNFELKER, R. Consumers Power Co. 82/08/20. SALTZMAN, J. (Trust & Economic analysis Branch (Utility Finance)). 2pp. 141 078. 24X Fiche: 50-155, 82/08/20, 8208270494.

P Operating license stage documents & correspondence

8208260377 Approves 820208 request for route for transport of spent reactor fuel. Sanitized version of info to be incorporated into shipment plan & approved route encl. SHERR, T. B. Material Transfer Safeguards Licensing Branch. 82/02/24. BORDINE, T. C. Consumers Power Co. 1p. 14579 219. 24X Fiche: 50-155, 82/02/24, 8208260377.

8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR Bvc list encl. DIRCKS, W. J. Office of the Executive Director for Operations. 82/07/02. Consolidated Edison Co. of New York. 93pp. 14194 001. 24X Fiche: 50-000, 82/07/02, 8207080064

8208020081 Requests clarification of NRC 820702 ltr. establishing applicability of statement re access limitations during LOCA, expressed in 820521 & 0604 ltrs. Util concurs w/applicability of 820521 ltr re spent fuel pool. VANDEWALLE, D. J. Consumers Power Co. 82/07/28. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 14144 102. 24X Fiche: 50-155, 82/07/28, 8208020081.

8208050534 Advises that interpretation of Tech Spec Section 3.7(c) re leak testing of calor test connections is acceptable, until issue is resolved as part of SEP Topic VI-4, "Containment Isolation Bys." CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/02. VANDEWALLE, D. Consumers Power Co. 4pp. 14213 317. 24X Fiche: 50-155, 82/08/02, 8208050534.

8208060178 Forwards review of NRC & contractor evaluations of util response to SEP Topic VIII-2, "Onsite Emergency Power Bys & Diesel Generator." VINCENT, R. A. Consumers Power Co. 82/08/03. CRUTCHFIELD, D. Operating Reactors Branch 5. 7pp. 14239 046. 24X Fiche: 50-155, 82/08/03, 8208060178.

8208090081 Forwards evaluation of SEP Topic III-2 re wind & tornado loadings. Facility provides adequate tornado protection. VINCENT, R. A. Consumers Power Co. 82/08/03. CRUTCHFIELD, D. Operating Reactors Branch 5. 30pp. 14270 204. 24X Fiche: 50-155, 82/08/03, 8208090081.

8208090208 Forwards preliminary comments on SEP Topics VI-2 D, "Mass & Energy Release for Possible Pipe Break Inside Containment" & VI-3, "Containment Pressure & Heat Removal Capability," per NRC 820610 draft evaluation. VINCENT, R. A. Consumers Power Co. 82/08/05. CRUTCHFIELD, D. Operating Reactors Branch 5. 4pp. 14271 120. 24X Fiche: 50-155, 82/08/05, 8208090208.

8208090257 Discusses status of seismic analyses per SEP Topic III-6, "Seismic Design Considerations." Meeting to discuss unresolved questions proposed for wk of 820823. VINCENT, R. A. Consumers Power Co. 82/08/05. CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 14270 348. 24X Fiche: 50-155, 82/08/05, 8208090257.

8208100320 Forwards comments on NRC draft safety evaluation of SEP Topic VI-10. A re testing of reactor trip sys & EBF, including response time. Existing programs for instrument & control testing adequate. VINCENT, R. A. Consumers Power Co. 82/08/05. CRUTCHFIELD, D. Operating Reactors Branch 5. 16pp. 14297 111. 24X Fiche: 50-155, 82/08/05, 8208100320.

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Bvc list encl. EISENHUT, D. Q. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14356 332. 24X Fiche: 50-000, 82/08/09, 8208090194.

8208170259 Forwards "Responses to BNL Questions on Release & Consequence Analysis Reported in Big Rock Point Probabilistic Risk Assessment." Results of addl analyses re hydrogen generation & base mat penetration failure encl. VANDEWALLE, D. J. Consumers Power Co. 82/08/10. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 14367 045. 24X Fiche: 50-155, 82/08/10, 8208170259.

--8208170261 "Responses to BNL Questions on Release & Consequence Analysis Reported in Big Rock Point Probabilistic Risk Assessment." * Wood-Leaver & Associates, Inc. * Fauske & Associates, Inc. WLA-1-R-82-05. 82/07/29. 33pp. 14367 047. 24X Fiche: 50-155, 82/08/10, 8208170259.

--8208170003 "SEP Topic V-II, A, Electrical Instrumentation & Control Features for Isolation of High & Low Pressure Sys. Big Rock Point Nuclear Station"
MAYB, S.E., FARMER, F.O. EG&G, Inc E00-EA-5931. 82/07/31
SCHOLL, R.F. Division of Licensing 10pp. 14361 217. 24X
Fiche: 50-155, 82/08/12, 8208170001

8208170198 Forwards safety evaluation of util responses to SEP Topic III-4 D, "Site Proximity Missiles (Including Aircraft)"
Potential site proximity missiles do not pose significant hazard to safe operation of plant
CRUTCHFIELD, D. Operating Reactors Branch 5 82/08/12
VANDEWALLE, D.J. Consumers Power Co 10pp 14366 258. 24X
Fiche: 50-155, 82/08/12, 8208170198

8208170264 Forwards Chapter 5 & portions of App IV to probabilistic risk assessment re containment integrity Licensee 820720
ltr containing revisions to isolation failure calculations
encl
GALLO, J. Isham, Lincoln & Beale GALLO, J. Consumers Power Co 82/08/13 BLOCH, P.B., PARIS, O.W., SHON, F.J. Atomic Safety and Licensing Board Panel 100pp 14357 139 24X Fiche: 50-155, 82/08/13, 8208170264.

8208200278 Notification of 820831 meeting w/util in Bethesda, MD to discuss SEP seismic program
EMCH, R. Operating Reactors Branch 5 82/08/18 CRUTCHFIELD, D. Operating Reactors Branch 5 App. 14399 001 24X
Fiche: 50-155, 82/08/18, 8208200278

8208230006 Notification of 820824 meeting w/util in Bethesda, MD to discuss SEP seismic program for facility
EMCH, R. Operating Reactors Branch 5 82/08/19 CRUTCHFIELD, D. Operating Reactors Branch 5 App. 14317 229 24X
Fiche: 50-155, 82/08/19, 8208230006

8208230077 Summary of 820810 meeting w/util & MVS Corp in Gaithersburg, MD re spent fuel pool expansion Attendance list & agenda
encl
EMCH, R. Operating Reactors Branch 5 82/08/19 CRUTCHFIELD, D. Operating Reactors Branch 5 App. 14314 361. 24X
Fiche: 50-155, 82/08/19, 8208230077.

8208240324 Requests relief from 10CFR50 App J, Type C testing requirements for containment pressure instrument lines at penetrations H-87, H-90, H-96, H-98 & H-99 Updated SER App J review which incorporates request for exemption requested
BORDINE, T.C. Consumers Power Co. 82/08/19. CRUTCHFIELD, D. Operating Reactors Branch 5 App. 14520 288 24X
Fiche: 50-155, 82/08/19, 8208240324

8208240329 Requests extension until 830215 for response to NRC 820713 ltr re facility unresolved safety issues Extension is in agreement w/current schedule for issuance of integrated assessment rept
VANDEWALLE, D.J. Consumers Power Co 82/08/19 CRUTCHFIELD, D. Operating Reactors Branch 5 App. 14520 224. 24X
Fiche: 50-155, 82/08/19, 8208240329.

8208240442 Forwards EG&G final technical evaluation rept & NRC safety evaluation on SEP Topic VI-7 A.3, "ECCS Actuation Sys."
Plant satisfies review criteria. Review complete
CRUTCHFIELD, D. Operating Reactors Branch 5 82/08/20
VANDEWALLE, D.J. Consumers Power Co App. 14526 301. 24X
Fiche: 50-155, 82/08/20, 8208240442

--8208240446 "SEP Topic VI-7 A.3, ECCS Actuation Sys. Big Rock Point," final technical evaluation rept.
VANDERBECK, R. EG&G, Inc FIN A-6425 E00-EA-5961 82/07/31.
SCHOLL, R.F. Division of Licensing. 12pp. 14526 304. 24X
Fiche: 50-155, 82/08/20, 8208240442.

8208250107 Notification of 820826 meeting w/util & Whiting Corp in Harvey, IL to discuss methodology for seismic qualification of facility semi-gantry crane
EMCH, R. Operating Reactors Branch 5. 82/08/24 CRUTCHFIELD, D. Operating Reactors Branch 5. App. 14540 360. 24X
Fiche: 50-155, 82/08/24, 8208250107.

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19.
Michigan, Univ. of. 112pp. 14358 001 24X Fiche: 50-000, 82/07/19, 8204210395

8204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/20
Consolidated Edison Co. of New York 112pp 14381 001 24X
Fiche: 50-000, 82/07/20, 8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks" Svc list encl
COBB, L.I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Consolidated Edison Co. of New York. 71pp. 14357 276 24X Fiche: 50-000, 82/07/20, 8204210397.

8208050462 Forwards IE Insp Rept 50-155/82-11 on 820628-0701 No noncompliance noted.
MILLER, J.R. Division of Engineering & Technical Programs. 82/07/21.
DEWITT, R.B. Consumers Power Co App. 14216 325 24X
Fiche: 50-155, 82/07/21, 8208050462.

--8208050478 IE Insp Rept 50-155/82-11 on 820628-0701. No noncompliance noted
Major areas inspected radiation protection activities, effluent control instrumentation, testing of air cleaning sys, reactor coolant water quality & license audits.
LOVENDALE, P.C., OREGER, L.R. Region 3, Office of Director. 82/07/19. App. 14216 327. 24X Fiche: 50-155, 82/07/21, 8208050462.

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/22.
Consolidated Edison Co. of New York 112pp 14194 321 24X
Fiche: 50-000, 82/07/22, 8204210398

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS" Svc list encl
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York 122pp. 14380 115. 24X
Fiche: 50-000, 82/07/23, 8204210401.

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHWRs." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co. of New York 127pp 14194 120 24X
Fiche: 50-000, 82/07/23, 8204210402.

8204210403 IE Info Notice 82-30, "Loss of Thermal Bleeders in RCS Piping at Certain Westinghouse PHWR Power Plants." Svc list encl
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/26.
Consolidated Edison Co. of New York. 121pp. 14357 013. 24X
Fiche: 50-000, 82/07/26, 8204210403

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/28.
Consolidated Edison Co. of New York. 122pp. 14357 146. 24X
Fiche: 50-000, 82/07/28, 8204210405.

8208050366 Forwards revised Page 2 to 801223 response to IE Bulletin 80-24, "Prevention of Damage Due to Water Leakage Inside Containment (801017 Indian Point 2 Event)."
VANDEWALLE, D.J. Consumers Power Co. 82/07/28. KEPPLER, J.O. Region 3, Office of Director App. 14209 131. 24X Fiche: 50-155, 82/07/28, 8208050366.

8208100204 Ack receipt of 820601 & 0701 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/82-04 Ltrs unresponsive to NRC concerns. Meeting requested to discuss corrective actions.
NORELIUS, C.E. Division of Engineering & Technical Programs. 82/08/04. DEWITT, R.B. Consumers Power Co. App. 14294 264. 24X
Fiche: 50-155, 82/08/04, 8208100204

--8208100212 Response to NRC 820421 ltr re violations noted in IE Insp Rept 50-155/82-04. Corrective actions: training session on posting high radiation areas conducted & all visitors & contractors will be instructed in radiation protection.
VANDEWALLE, D.J. Consumers Power Co 82/08/01. KEPPLER, J.O. Region 3, Office of Director. App. 14294 266. 24X
Fiche: 50-155, 82/08/04, 8208100204

0100217 Responds to NRC 820615 telcon re violations noted in IE Insp
pt 50-155/82-04 Corrective actions: training program will
be implemented for all radiation workers Basic course will
start in Sept 1982
DEWALLE, D. J. Consumers Power Co 82/07/01 KEPLER, J. O.
Region 3, Office of Director 3pp 14294.272 24X
Fiche 50-155, 82/08/04, 8208100204.

0407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From
Die Water-Jet Impingement." Svc list encl
JAN, E. L. Division of Engineering & Quality Assurance 82/08/05
Consolidated Edison Co of New York. 117pp 14388.201 24X
Fiche 50-000, 82/08/05, 8204210407

0104 Forwards rationale for request for relief from internal
insp of reactor cleanup pump internal welds &
for circulation pump casing welds Relief request will be
submitted as addenda to until 820503 ltr
DEWALLE, D. J. Consumers Power Co 82/08/11 CRUTCHFIELD, D.
Operating Reactors Branch 9 18pp 14378.168 24X
Fiche 50-155, 82/08/11, 8208180104

Periodic operating reports & related correspondence

0010 Responds to FOIA request for documents detailing collective
exposures in 1981 for operating nuclear power plants &
releasing said info. Forwards documents listed in App A
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/13 UDELL, R. A.
Federal Mass Energy Project 8pp 14679.208 24X
Fiche 50-000, 82/07/13, 8208270010

0270029 Forwards "Big Rock Point Plant Annual Operating
Rept-Occupational Exposure for CY81."
JORDAN, E. L. Consumers Power Co 82/03/01. KEPLER, J. O. Region
3, Office of Director 1p. 14680.004 24X Fiche: 50-000, 82/07/13,
8208270010

0270035 "Big Rock Point Plant Annual Operating Rept-Occupational
Exposure for CY81."
Consumers Power Co 82/03/01. 9pp. 14680.005 24X
Fiche 50-000, 82/07/13, 8208270010.

0270078 "Annual Whole Body Dose At Licensed Nuclear Power
Facilities for CY81."
NRC - No Detailed Affiliation Given. 82/07/13. 48pp.
14679.216 24X Fiche: 50-000, 82/07/13, 8208270010.

0270531 Forwards "Annual Exposure Range Rept, 1981." per 10CFR20.407.
to License 21-08606-01 rept.
DEWALLE, D. J. Consumers Power Co 82/03/29. Office of
Management and Program Analysis. 1p. 14680.064 24X
Fiche: 50-000, 82/07/13, 8208270010.

0270537 "Annual Exposure Range Rept, 1981."
Consumers Power Co. 82/03/29 1p. 14680.065 24X
Fiche: 50-000, 82/07/13, 8208270010.

Portable occurrences, LERs & related correspondence

020268 Forwards LER 82-022/03L-0
DEWALLE, D. J. Consumers Power Co. 82/07/30. KEPLER, J. O. Region
3, Office of Director. 1p. 14270.316 24X Fiche: 50-155, 82/07/30,
82070268.

090273 LER 82-022/03L-0 on 820702, during post-implementation review
recent facility change, one pair of flanges in 8-inch fire
piping did not meet facing requirements. Caused by
engineer error to be corrected at outages.
Consumers Power Co. 82/07/30. Region 3, Office of Director.
14270.318 24X Fiche: 50-155, 82/07/30, 8208090268.

020278 Forwards LER 82-021/03L-0.
JORDAN, E. L. Consumers Power Co. 82/08/05. KEPLER, J. O. Region 3,
Office of Director. 1p. 14333.061 24X Fiche: 50-155, 82/08/05,
1130278.

1130279 LER 82-021/03L-0 on 820707, both open & closed position
direction lights remained on when backup core spray valve
82071 returned to normal closed position. Caused by
misaligned open position switch. Switch adjusted.
Consumers Power Co. 82/08/05. Region 3, Office of Director.
14333.062 24X Fiche: 50-155, 82/08/05, 8208130278.

020282 Forwards LER 82-023/03L-0.
JORDAN, E. L. Consumers Power Co. 82/08/19. KEPLER, J. O. Region 3,
Office of Director. 1p. 14599.281 24X Fiche: 50-155, 82/08/19,
8200282.

--8208300288 LER 82-023/03L-0 on 820801, backup core spray valve M07071
opening stroke found one-half of normal full stroke, but
adequate for core cooling requirements Cause unknown Slip
clutch in positioning mechanism adjusted
Consumers Power Co. 82/08/19. Region 3, Office of Director.
1p. 14599.282 24X Fiche: 50-155, 82/08/19, 8208300282.

DOCKET 50-156 UNIV. OF WISCONSIN RESEARCH REACTOR

R Periodic operating reports & related correspondence

8208030484 Forwards Annual Operations Rept for FY81-82
CASHWELL, R. J. Wisconsin, Univ. of Madison. 82/07/27 MILLER, J. H.
Standardization & Special Projects Branch 1p. 14154.068 24X
Fiche: 50-156, 82/07/27, 8208030484.

--8208030488 Annual Operating Rept for FY81-82.
CASHWELL, R. J. Wisconsin, Univ. of Madison. 82/07/27 14pp.
14154.069 24X Fiche: 50-156, 82/07/27, 8208030484.

DOCKET 50-197 CORNELL UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19.
Michigan, Univ. of. 112pp. 14358.001 24X Fiche: 50-000, 82/07/19,
8204210395.

DOCKET 50-160 GEORGIA INST. OF TECH RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19.
Michigan, Univ. of. 112pp. 14358.001 24X Fiche: 50-000, 82/07/19,
8204210395.

DOCKET 50-163 GENERAL ATOMIC COMPANY

G Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19.
Michigan, Univ. of. 112pp. 14358.001 24X Fiche: 50-000, 82/07/19,
8204210395.

DOCKET 50-166 UNIV. OF MARYLAND RESEARCH REACTOR

R Periodic operating reports & related correspondence

8208020138 Submits annual operating rept for Jul 1981-June 1982.
BELCHER, R. L. Maryland, Univ. of. 82/07/27. TEDESCO, R. L. NRC - Nn
Detailed Affiliation Given. 5pp. 14142.032 24X
Fiche: 50-166, 82/07/27, 8208020138

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

G Adjudicatory correspondence

8208060119 Supplementary response to first set of interrogatories.
Related correspondence.
ENTWISLE, E. D. Citizens for Nuclear Reactor Safety, Inc. 82/08/02.
Armed Forces Radiobiological Research Institute. 29pp. 14238.288.
24X Fiche: 50-170, 82/08/02, 8208060119.

8208060132 Motion for leave to suppl responses to listed Armed Forces
Radiobiology Research Inst interrogatories. Expert witness
unable to complete response due to illness. Certificate of
Svc encl. Related correspondence.
ENTWISLE, E. D., MACKLIN, L. Citizens for Nuclear Reactor Safety, Inc.
MACKLIN, L. Institute for Public Representation. 82/08/02. Atomic
Safety and Licensing Board Panel. 5pp. 14241.277 24X
Fiche: 50-170, 82/08/02, 8208060132.

8208170281 Informs that no response to Citizens for Nuclear Reactor Safety 820802 motion for leave to supply further interrogatory responses will be submitted Motion involves discovery matter between Citizens & licensee BACHMAN, R G Hearing Branch 1 82/08/16 HOYT, H. SCHINK, D R. HILL, E E Atomic Safety and Licensing Board Panel 1p 14367 080 24x Fiche 50-170, 82/08/16, 8208170281

8208240194 Response opposing Citizens for Nuclear Reactor Safety 820802 supplementary response to licensee first set of interrogatories Draft order & Certificate of Svc encl BRITTON, R L Armed Forces Radiobiological Research Institute 82/08/17 10pp 14521 251 24x Fiche 50-170, 82/08/17, 8208240194

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance. 82/07/19 Michigan, Univ of 112pp 14358 001 24x Fiche 50-000, 82/07/19, 8204210395

DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1

P Operating license stage documents & correspondence

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter 1 requirements & provides alternatives to requirements Svc list encl EISENHART, D Q Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24x Fiche 50-000, 82/08/09, 8208090194

Q Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leaks" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co of New York 87pp 14356 274 24x Fiche 50-000, 82/07/16, 8204210393

8204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24x Fiche 50-000, 82/07/20, 8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks" Svc list encl COBB, L I Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24x Fiche 50-000, 82/07/20, 8204210397

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co of New York 112pp 14194 321 24x Fiche 50-000, 82/07/22, 8204210398

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 122pp 14380 115 24x Fiche 50-000, 82/07/23, 8204210401

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHRs" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co of New York 127pp 14194 120 24x Fiche 50-000, 82/07/23, 8204210402

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PHR Power Plants" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co of New York 121pp 14357 013 24x Fiche 50-000, 82/07/26, 8204210403

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co of New York 122pp 14357 146 24x Fiche 50-000, 82/07/28, 8204210405

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/08/05 Consolidated Edison Co of New York 117pp 14388 201 24x Fiche 50-000, 82/08/05, 8204210407

DOCKET 50-182 PURDUE UNIV. RESEARCH REACTOR

P Operating license stage documents & correspondence

8208240401 Provides addl info for Change 1 to Tech Specs re reactivity limits as requested in 820524 Ltr STANSBERRY, E R Purdue Univ. 82/08/16 Standardization & Spc Projects Branch 1p 14322 293 24x Fiche 50-182, 82/08/16, 8208240401

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24x Fiche 50-000, 82/07/19, 8204210395

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24x Fiche 50-000, 82/07/19, 8204210395

DOCKET 50-186 UNIV. OF MISSOURI RESEARCH REACTOR

P Operating license stage documents & correspondence

8208310369 Forwards "Reactor Operations Annual Rept. Jul 1981-June 1982" MCKIBBEN, J C Missouri, Univ. of, Columbia 82/08/27 Division of Licensing 1p 14693 291 24x Fiche 50-186, 82/08/27, 8208310369

--8208310385 Std operating procedures * Missouri, Univ. of, Columbia 81/10/31 275pp 14694 010 24x Fiche 50-186, 82/08/27, 8208310385

R Periodic operating reports & related correspondence

8208310369 Forwards "Reactor Operations Annual Rept. Jul 1981-June 1982" MCKIBBEN, J C Missouri, Univ. of, Columbia 82/08/27 Division of Licensing 1p 14693 291 24x Fiche 50-186, 82/08/27, 8208310369

--8208310377 "Reactor Operations Annual Rept. Jul 1981-June 1982." MCKIBBEN, J C., ALGER, D M Missouri, Univ. of, Columbia 82/08/27 52pp 14693 292 24x Fiche 50-186, 82/08/27, 8208310369

--8208310385 Std operating procedures * Missouri, Univ. of, Columbia 81/10/31 275pp 14694 010 24x Fiche 50-186, 82/08/27, 8208310369

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl JORDAN, E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ. of 112pp 14358 001 24x Fiche 50-000, 82/07/19, 8204210395

8208160108 Forwards IE Insp Rept 50-187/82-01 on 820628-30 & notice violation STERNBERG, D M Division of Resident, Reactor Project & Engineering Programs 82/07/27 CRANDALL, W E Northrop Research & Technical Center 2pp 14345 171 24x Fiche 50-187, 82/07/27, 8208160108

--8208160111 Notice of violation from insp on 820628-30 YOUNG, T. Division of Resident, Reactor Project & Engineering Programs 82/07/27 4pp 14345 173 24x Fiche 50-187, 82/07/27, 8208160108

0115 IE Insp Rept 50-187/82-01 on 820628-30 Noncompliance noted.
nce of qualified health physicist at reactor safety
committee quarterly meeting
ETT.D.J., YOUNG, T. Division of Resident, Reactor Project &
neering Programs. 82/07/16. 6pp. 14345 177. 24X
e 30-187. 82/07/27. 8208160108

0-188 KANSAS STATE UNIV. RESEARCH REACTOR

ction reports. IE Bulletins & correspondence

95 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of
ent of Personnel Monitoring Devices for External
ion." Bvc list encl.
E.L. Division of Engineering & Quality Assurance. 82/07/19.
igen. Univ. of. 112pp. 14398. 001. 24X Fiche: 50-000, 82/07/19,
0395.

0-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

ction reports. IE Bulletins & correspondence

95 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of
ent of Personnel Monitoring Devices for External
ion." Bvc list encl.
E.L. Division of Engineering & Quality Assurance. 82/07/19.
igen. Univ. of. 112pp. 14398. 001. 24X Fiche: 50-000, 82/07/19,
0395.

0-199 MANHATTAN COLLEGE RESEARCH REACTOR

ction reports. IE Bulletins & correspondence

95 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of
ent of Personnel Monitoring Devices for External
ion." Bvc list encl.
E.L. Division of Engineering & Quality Assurance. 82/07/19.
igen. Univ. of. 112pp. 14398. 001. 24X Fiche: 50-000, 82/07/19,
0395.

0-201 WEBB VALLEY REPROCESSING PLANT

icatory correspondence

49 Order extending time within which Commission may act to
ALAB-677 until 820917.
B.J. Office of the Secretary of the Commission. 82/08/09.
sioners. 1p. 14314. 293. 24X Fiche: 50-201, 82/08/09,
0149.

37 Forwards NRC 820728 ltr acknowledging receipt of encl
Club 820714 ltr re approx 3 dozen drums found in
ondition near site, per Note 2 of ASLB 811231
ndum & order. Certificate of Bvc encl.
R. Regulations Division. 82/08/13. BRENNER, L., HARBOUR, J.,
P.A. Atomic Safety and Licensing Board Panel. 3pp.
342. 24X Fiche: 50-201, 82/08/13, 8208170337.

04 Forwards NRC 820823 response to Sierra Club request for
ideration of Change 32, for info & per ASLB 811231
ndum & order. Certificate of Bvc encl.
R. Regulations Division. 82/08/25. BRENNER, L. Atomic
and Licensing Board Panel. 30pp. 14596: 080. 24X
50-201, 82/08/25, 8208300104.

ting license stage documents & correspondence

01 Expresses concern re approx three dozen drums found near
n poor condition. Listed questions should be appended
rra Club 820326 petition re License Change 32 to
e CBF-1.
I.L. Sierra Club. 82/07/14. CUNNINGHAM, R. Division of Fuel
& Material Safety. 4pp. 14224: 323. 24X Fiche: 50-201,
14, 8208040401.

37 Forwards NRC 820728 ltr acknowledging receipt of encl
Club 820714 ltr re approx 3 dozen drums found in
ondition near site, per Note 2 of ASLB 811231
ndum & order. Certificate of Bvc encl.
R. Regulations Division. 82/08/13. BRENNER, L., HARBOUR, J.,
P.A. Atomic Safety and Licensing Board Panel. 3pp.
342. 24X Fiche: 50-201, 82/08/13, 8208170337.

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8208020376 Responds to 820721 telephone request for status of ingestion
ione planning by State of CA. State has retained consultants
to do planning. Plan will be submitted to FEMA in late Sept
1982.
KRIMM, R.W. Federal Emergency Management Agency. 82/07/28.
ORIHES, B. Division of Emergency Preparedness. 1p. 14150: 118. 24X
Fiche: 50-206, 82/07/28, 8208020376.

8208190180 Discusses status of ingestion pathway planning in CA. Final
evaluation re capability of involved jurisdictions to
implement ingestion pathway plans must await drills expected
in late Aug/early Sept 1982.
KRIMM, R.W. Federal Emergency Management Agency. 82/08/05.
ORIHES, B.K. Division of Emergency Preparedness. 4pp. 14386: 353.
24X Fiche: 50-206, 82/08/05, 8208190180.

8208170170 Requests current version of full-size engineering drawings
of facility layout & sys to review effectiveness of NRC
safeguards regulations & validate vital area designations.
Drawing list encl.
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/11. DIETCH, R.
Southern California Edison Co. 3pp. 14366: 236. 24X
Fiche: 50-206, 82/08/11, 8208170170.

8208270696 Responds to 820630 ltr re changes to facility physical
security plan. Revision 5. NRC concurs w/changes except
provisions in Section 1.3.1.4 re protected & vital areas.
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/17. BASKIN, K.P.
Southern California Edison Co. 3pp. 14683: 091. 24X
Fiche: 50-206, 82/08/17, 8208270696.

8208230023 Forwards Revision 6 to Mar 1981 physical security plan.
Revision withheld (ref 10CFR73.21).
BASKIN, K.P. Southern California Edison Co. 82/08/18. EISENHUT, D.Q.
Division of Licensing. 1p. 14517: 227. 24X Fiche: 50-206, 82/08/18,
8208230023

0 Adjudicatory correspondence

8208050482 Supplemental requests for exemption from listed fire
protection rule implementation schedule & request for
reconsideration of exemption decision to allow safe shutdown
measures implementation w/coordination of BEP.
PIGOTT, D.R. Southern California Edison Co. PIGOTT, D.R. Orrick,
Herrington & Sutcliffe. 82/08/03. Commissioners. 34pp.
14214: 167. 24X Fiche: 50-206, 82/08/03, 8208050482.

--8208050487 Affidavit of KP Baskin supporting supplemental request for
exemption & reconsideration re fire protection rule
implementation.
BASKIN, K.P. Southern California Edison Co. 82/08/02. 10pp.
14214: 200. 24X Fiche: 50-206, 82/08/03, 8208050482

8208170167 Ltr to CA residents who petitioned NRC to suspend or revoke
DL for facility. Order confirming licensee commitments on
seismic upgrading encl.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director.
82/08/11. Affiliation Unknown. 5pp. 14366: 241. 24X
Fiche: 50-206, 82/08/11, 8208170167.

P. Operating license stage documents & correspondence

8207140515 Advises that Class III fee owed for 820105 application for
approval of Tech Spec changes to increase allowable
phosphate discharge limit. Review involves consideration of
single environ issue.
MILLER, W.O. License Fee Management Branch. 82/07/01. DIETCH, R.
Southern California Edison Co. 1p. 13848: 359. 24X
Fiche: 50-206, 82/07/01, 8207140515.

8207080064 Generic ltr to all licensees of operating plants, applicants
for DL & holders of CP re Commission approved charter for
CROR, Bvc list encl.
DIRCKS, W.J. Office of the Executive Director for Operations.
82/07/02. Consolidated Edison Co. of New York. 93pp. 14194: 001.
24X Fiche: 50-000, 82/07/02, 8207080064.

8208020214 Forwards results of verification testing of electric
distribution sys voltages conducted per NRC 820224 ltr.
Results demonstrate adequacy of sys. Computational procedures
also verified.
BASKIN, K.P. Southern California Edison Co. 82/07/15.
CRUTCHFIELD, D. Operating Reactors Branch 5. 15pp. 14141: 044. 24X
Fiche: 50-206, 82/07/15, 8208020214.

8208050293 Remits licensing application fee for Amend 103 to DL consisting of Proposed Change 108 to Tech Specs. Application not fee exempt since review involves consideration of single environ issue
BASKIN, K. P. Southern California Edison Co. 82/07/27 MILLER, H. D. License Fee Management Branch 2pp 14209:348. 24X
Fiche: 50-206, 82/07/27, 8208050293

8208170186 Responds to 820706 request for info on status of unresolved safety issues. Util requires until 821015 to provide status due to extensive & time consuming research.
KRIEGER, R. W. Southern California Edison Co. 82/07/29
CRUTCHFIELD, D. Operating Reactors Branch 5 1p. 14364:323. 24X
Fiche: 50-206, 82/07/29, 8208170186

8208060157 Forwards "Control of Heavy Loads," technical evaluation rept
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/03 DIETCH, R. Southern California Edison Co. 2pp 14239:243. 24X
Fiche: 50-206, 82/08/03, 8208060157

--8208060161 "Control of Heavy Loads," technical evaluation rept.
VITO, D. J. Franklin Institute/Franklin Research Center.
TER-C3257-529 82/07/16 CLEMENSON, F. NRC - No Detailed Affiliation Given. 3pp 14239:243. 24X Fiche: 50-206, 82/08/03, 8208060157

8208060214 Informs that pump runout protection on low discharge pressure similar to protection installed on existing pump will be provided for new auxiliary feedwater sys pump.
BASKIN, K. P. Southern California Edison Co. 82/08/03
CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14241:085. 24X
Fiche: 50-206, 82/08/03, 8208060214

8208100148 Responds to 760421 request for exemptions from 10CFR 50, App J. All exemptions re airlock testing denied. Safety evaluation encl Proposed Tech Specs that include pertinent requirements of App J should be submitted within 60 days.
EISENHUT, D. Q. Division of Licensing. 82/08/03. DIETCH, R. Southern California Edison Co. 3pp. 14298:049. 24X Fiche: 50-206, 82/08/03, 8208100148

--8208100156 Safety evaluation denying util request for exemptions from 10CFR 50, App J re airlock testing requirements.
* Office of Nuclear Reactor Regulation, Director. 82/08/03. 2pp. 14298:048. 24X Fiche: 50-206, 82/08/03, 8208100148

8208100077 Advises that util decision between replacing valves & redesigning alternative for safety injection sys mode has not yet been made. Decision on redesign alternative expected by 820913. Procurement of replacement valves continues.
KRIEGER, R. W. Southern California Edison Co. 82/08/03
CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14296:156. 24X
Fiche: 50-206, 82/08/03, 8208100077

8208100088 Resubmits Amend 100 to License DPR-13, consisting of proposed Change 110 to Tech Specs reflecting reorganization of managerial responsibility to maintain organizational requirements of three unit station.
BASKIN, K. P. Southern California Edison Co. 82/08/03.
CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14297:237. 24X
Fiche: 50-206, 82/08/03, 8208100088

--8208100093 Proposed Change 110 to Tech Specs reflecting reorganization of managerial responsibility to maintain organizational requirements of three unit station.
* Southern California Edison Co. 82/08/03. 13pp. 14297:238. 24X Fiche: 50-206, 82/08/03, 8208100088

8208100223 Advises that because of further review, performance testing of power operated relief & safety valves per TMI Action Item II, D. 1 will not be completed until Sept.
KRIEGER, R. W. Southern California Edison Co. 82/08/06.
CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14294:340. 24X
Fiche: 50-206, 82/08/06, 8208100223

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Enc list encl.
EISENHUT, D. Q. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York 1p. 14396:332. 24X Fiche: 50-000, 82/08/09, 8208090194.

--8208120111 "Supplemental Analysis of Dispersion of 1975 Oroville & 1979 Imperial Valley Aftershock Data."
* Woodward-Clyde Consultants, Inc. 82/08/07. 30pp. 14319:120. 24X Fiche: 50-206, 82/08/07, 8208120108

8208200040 Advises that implementation schedule for NUREO-0737, Item 11, D. 3.4, "Control Room Habitability," will be delayed pending completion of SEP integrated assessment by Apr 1983.
BASKIN, K. P. Southern California Edison Co. 82/08/09
CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14392:291. 24X
Fiche: 50-206, 82/08/09, 8208200040.

8208170143 Forwards order confirming licensee commitments on seismic upgrading.
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/11. DIETCH, R. Southern California Edison Co. 2pp. 14366:127. 24X
Fiche: 50-206, 82/08/11, 8208170143.

--8208170146 Order confirming licensee commitments on seismic upgrading.
EISENHUT, D. Q. Division of Licensing. 82/08/11. Southern California Edison Co. 6pp. 14366:129. 24X Fiche: 50-206, 82/08/11, 8208170143.

8208170251 Forwards Amend 61 to License DPR-13, safety evaluation & notice of issuance & availability. Amend approves changes to App A Tech Specs, incorporating revised Section 6.11, "Radiation Protection Program."
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/11. DIETCH, R. Southern California Edison Co. 2pp. 14369:202. 24X
Fiche: 50-206, 82/08/11, 8208170251.

--8208170256 Amend 61 to License DPR-13, revising App A Tech Specs to incorporate revised Section 6.11, "Radiation Protection Program." Tech Spec changes encl.
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/11. 7pp. 14369:204. 24X Fiche: 50-206, 82/08/11, 8208170251

--8208170262 Safety evaluation supporting Amend 61 to License DPR-13.
* Office of Nuclear Reactor Regulation, Director. 82/08/11. 2pp. 14369:211. 24X Fiche: 50-206, 82/08/11, 8208170251

--8208170265 Notice of issuance & availability of Amend 61 to License DPR-13.
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/11. 2pp. 14369:213. 24X Fiche: 50-206, 82/08/11, 8208170251.

8208170345 Forwards HR Denton 820806 ltr & Div of Licensing order confirming licensee commitment to maintain shutdown condition until completion of seismic mods & until NRC approval for restart obtained, per 820615 & 24 submittals.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 82/08/11. NADER, R. Center for Progressive Law. 2pp. 14367:019. 24X Fiche: 50-206, 82/08/11, 8208170345.

--8208170348 Informs of issuance of encl Div of Licensing order confirming licensee commitment to maintain shutdown condition until completion of seismic mods & until NRC approval for restart obtained, per 820615 & 24 submittals.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 82/08/06. NADER, R. Center for Progressive Law. 3pp. 14367:021. 24X Fiche: 50-206, 82/08/11, 8208170345.

--8208170351 Order confirming licensee commitment to maintain shutdown condition until completion of seismic mods, per licensee 820615 & 24 submittals & until NRC approval for restart obtained.
EISENHUT, D. Q. Division of Licensing. 82/08/11. Southern California Edison Co. 6pp. 14367:024. 24X Fiche: 50-206, 82/08/11, 8208170345.

8208240257 Forwards application for Amend 108 to License DPR-13, proposing Tech Spec Change 113 to revise Table 4.1.2 re min equipment check & sampling frequency. Amend fee encl.
DIETCH, R. Southern California Edison Co. 82/08/11. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 14527:065. 24X
Fiche: 50-206, 82/08/11, 8208240257

--8208240259 Application for Amend 108 to License DPR-13, proposing Tech Spec Change 113 to revise Table 4.1.2 re min equipment check & sampling frequency. Description of proposed change & safety analysis encl.
DIETCH, R. Southern California Edison Co. COTTON, Q. D. San Diego Gas & Electric Co. 82/08/10. 8pp. 14527:066. 24X
Fiche: 50-206, 82/08/11, 8208240257.

--B208240264 Proposed Tech Spec Table 4 1 2 re min equipment check & sampling frequency Certificate of Evc encl
* Southern California Edison Co. 82/08/10 3pp. 14327 074. 24X
Fiche: 50-206, 82/08/11, B208240257

B208160101 Advises that response to NUREQ-0737, Action Item II B.3. "Post-Accident Sampling." will be provided by B21101
BASKIN, K. P. Southern California Edison Co. 82/08/12.
CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 14345 193. 24X
Fiche: 50-206, 82/08/12, B208160101

B208170005 Informs that SEP Topic VI-6 re containment leak testing, considered complete Topic covered in NRC B20803 safety evaluation re extent of compliance w/App J to 10CFR50 & exemption requests.
PAULSON, W. Operating Reactors Branch 5. 82/08/12. DIETCH, R. Southern California Edison Co. 2pp. 14361 212. 24X
Fiche: 50-206, 82/08/12, B208170005

B208270684 Forwards case study rept containing detailed description, findings, conclusions & recommendations re B00310 loss of salt water cooling event
MICHELSON, C. Director's Office. 82/08/12. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. MINOQUE, B. B. Office of Nuclear Regulatory Research, Director. 3pp. 14683 072. 24X
Fiche: 50-206, 82/08/12, B208270684

--B208270688 Forwards case study rept containing detailed description, findings, conclusions & recommendations re B00310 loss of salt water cooling event
MICHELSON, C. Director's Office. 82/08/12. WILKINSON, E. P. Institute of Nuclear Power Operations. 2pp. 14683 079. 24X
Fiche: 50-206, 82/08/12, B208270684

--B208270691 Forwards case study rept containing detailed description, findings, conclusions & recommendations re B00310 loss of salt water cooling event
MICHELSON, C. Director's Office. 82/08/12. ROBBIN, D. Nuclear Safety Analysis Center. 2pp. 14683 077. 24X
Fiche: 50-206, 82/08/12, B208270684

--B208270695 Forwards case study rept containing detailed description, findings, conclusions & recommendations re B00310 loss of salt water cooling event
MICHELSON, C. Director's Office. 82/08/12. RAY, H. B. Southern California Edison Co. 2pp. 14683 079. 24X
Fiche: 50-206, 82/08/12, B208270684

--B208270697 "San Onofre Unit 1 Loss of Salt Water Cooling Event on B00310."
ORNSTEIN, H. L. Director's Office. 82/07/31. 58pp. 14683 081. 24X
Fiche: 50-206, 82/08/12, B208270684

B208180113 Forwards "Seismic Safety Margins re 84th Percentile Instrumental Spectrum." Previous analyses will not be impacted by exceedances of up to 10% over specified ranges. Response spectra of 0.67 g Housner will be used.
BASKIN, K. P. Southern California Edison Co. 82/08/16.
CRUTCHFIELD, D. Operating Reactors Branch 5. 48pp. 14379 195. 24X
Fiche: 50-206, 82/08/16, B208180113

B208260390 Forwards "San Onofre Unit 1 Loss of Salt Water Cooling Event on B00310."
DIRCKE, W. J. Office of the Executive Director for Operations. 82/08/16. PALLADIO, N. GILINSKY, V. AHEARNE, J. Commissioners. 1p. 14569 149. 24X
Fiche: 50-206, 82/08/16, B208260390

--B208260403 "San Onofre Unit 1 Loss of Salt Water Cooling Event on B00310."
ORNSTEIN, H. L. Director's Office. 82/07/31. 58pp. 14569 150. 24X
Fiche: 50-206, 82/08/16, B208260390

B208190114 Forwards addl comments on draft review of operating experience submitted by NRC B20312 ltr. Comments suppl B20714 submittal & complete response.
BASKIN, K. P. Southern California Edison Co. 82/08/17.
CRUTCHFIELD, D. Operating Reactors Branch 5. 7pp. 14383 129. 24X
Fiche: 50-206, 82/08/17, B208190114

B208190145 Forwards "Electric Raceway Supports, Seismic Re-evaluation Criteria." providing description of seismic re-evaluation of cable tray & conduit support.
BASKIN, K. P. Southern California Edison Co. 82/08/17.
CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14381 099. 24X
Fiche: 50-206, 82/08/17, B208190145

--B208190147 "Electric Raceway Supports, Seismic Re-evaluation Criteria."
* Southern California Edison Co. 82/08/13. 21pp. 14381 100. 24X
Fiche: 50-206, 82/08/17, B208190145

B208190205 Forwards "Soil Backfill Conditions" in response to SEP Topic III-6. "Seismic Design Considerations." Structures evaluated are not affected by in-situ soil conditions Fuel storage bldg evaluation will be provided by B21001.
BASKIN, K. P. Southern California Edison Co. 82/08/17.
CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 14387 351. 24X
Fiche: 50-206, 82/08/17, B208190205

--B208190208 "Soil Backfill Conditions"
* Southern California Edison Co. 82/08/12. 200pp. 14387 353. 24X
Fiche: 50-206, 82/08/17, B208190205

B208200192 Confirms intentions re NRC B20726 re-evaluation guidelines for seismic criteria, per B20728-30 discussion. Seismic anchor displacements due to DBE & mechanical equipment internals will not be evaluated for seismic re-evaluation program.
BASKIN, K. P. Southern California Edison Co. 82/08/17.
CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14500 137. 24X
Fiche: 50-206, 82/08/17, B208200192

B208250169 Provides addl info to B20310 ltr re beta radiation assessment & environ qualification of electrical equipment. Exposed cables are only equipment inside containment which do not have metal ends.
BASKIN, K. P. Southern California Edison Co. 82/08/23.
CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14540 277. 24X
Fiche: 50-206, 82/08/23, B208250169

B208310251 Forwards Amend 62 to License DPR-13, safety evaluation & FR notice of issuance & availability Amend approves changes to App A Tech Specs incorporating mods to testing interval for safety injection sys hydraulic valve testing
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/25. DIETCH, R. Southern California Edison Co. 2pp. 14688 172. 24X
Fiche: 50-206, 82/08/25, B208310251

--B208310254 Amend 62 to License DPR-13, revising App A Tech Specs to incorporate mods to testing interval for safety injection sys hydraulic valve testing Revised Tech Specs encl
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/25. 4pp. 14688 174. 24X
Fiche: 50-206, 82/08/25, B208310251

--B208310257 Safety evaluation supporting Amend 62 to License DPR-13.
* Office of Nuclear Reactor Regulation, Director. 82/08/25. 2pp. 14688 178. 24X
Fiche: 50-206, 82/08/25, B208310251

--B208310262 Notice of issuance & availability of Amend 62 to License DPR-13
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/25. 2pp. 14688 180. 24X
Fiche: 50-206, 82/08/25, B208310251

B208300234 Responds to open items of SEP Topic III-6, "Seismic Design Considerations." Eight oversize drawings encl. Aperture cards are available in PDR.
BASKIN, K. P. Southern California Edison Co. 82/08/26.
CRUTCHFIELD, D. Operating Reactors Branch 5. 95pp. 14673 012. 24X
Fiche: 50-206, 82/08/26, B208300234

--B208300271 "FFTF Rept Drilled-In Expansion Bolts Under Static & Alternating Load"
LIN, M. S. Bachtel Corp. BR-5853-C-4. 75/01/16. 90pp. 14673 108. 24X
Fiche: 50-206, 82/08/26, B208300234

B208310013 Notification of B20908 meeting w/util in Bethesda, MD to discuss approach to resolve safety injection sys valve issue.
PAULSON, W. A. Operating Reactors Branch 5. 82/08/26. CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 14689 287. 24X
Fiche: 50-206, 82/08/26, B208310013

B208310233 Notification of B20909 meeting w/util in Bethesda, MD to discuss licensee structural analysis of steam generator wrapper support & address concerns re potential wear of steam generator tubes.
PAULSON, W. A. Operating Reactors Branch 5. 82/08/26. CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 14695 112. 24X
Fiche: 50-206, 82/08/26, B208310233

0 Inspection reports, IE Bulletins & correspondence

B204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Evc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16. Consolidated Edison Co. of New York. 87pp. 14336 274. 24X
Fiche: 50-000, 82/07/16, B204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19.
Michigan Univ. of. 112pp. 14358:001. 24X Fiche: 50-000, 82/07/19, 8204210395.

8204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20
Consolidated Edison Co. of New York. 112pp. 14381:001. 24X
Fiche: 50-000, 82/07/20, 8204210396.

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
CDBB, L. I. Division of Fuel Facilities, Materials & Safeguards.
82/07/20. Consolidated Edison Co. of New York. 71pp. 14397:276.
24X Fiche: 50-000, 82/07/20, 8204210397.

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22.
Consolidated Edison Co. of New York. 112pp. 14194:321. 24X
Fiche: 50-000, 82/07/22, 8204210398.

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York. 122pp. 14380:115. 24X
Fiche: 50-000, 82/07/23, 8204210401.

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York. 127pp. 14194:120. 24X
Fiche: 50-000, 82/07/23, 8204210402.

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26.
Consolidated Edison Co. of New York. 121pp. 14357:013. 24X
Fiche: 50-000, 82/07/26, 8204210403.

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28.
Consolidated Edison Co. of New York. 122pp. 14357:146. 24X
Fiche: 50-000, 82/07/28, 8204210405.

8208060214 Informs that pump rundown protection on low discharge pressure similar to protection installed on existing pump will be provided for new auxiliary feedwater sys pump.
BARKIN, K. P. Southern California Edison Co. 82/08/03
CRUTCHFIELD, D. D. Operating Reactors Branch 9. 1p. 14241:085. 24X
Fiche: 50-206, 82/08/03, 8208060214.

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/05.
Consolidated Edison Co. of New York. 117pp. 14388:201. 24X
Fiche: 50-000, 82/08/05, 8204210407.

8208230368 Advise of delay until 821001 to comply w/Action Item 5 in IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPs of PWR Plants."
HAYNES, J. O. Southern California Edison Co. 82/08/05. ENGELKEN, R. H.
Region 5, Office of Director. 1p. 14512:354. 24X
Fiche: 50-206, 82/08/05, 8208230368.

8208160113 EN-82-019A: on 820811, order imposing civil penalties in amount of \$40,000 will be issued for violations re positive access control to vital areas associated w/implementation of physical security plan.
ROSBAND, R.; LIEBERMAN, J. Director's Office, Office of Inspection and Enforcement. 82/08/11. 1p. 14345:170. 24X Fiche: 50-206, 82/08/11, 8208160113.

8208230042 Forwards notarized version of response to IE Bulletin 81-01 & 81-03 re flow blockage of cooling water to safety sys by Corbicula Sp & Mytilus Sp, respectively.
HAYNES, J. O. Southern California Edison Co. 82/08/12. ENGELKEN, R. H.
Region 5, Office of Director. 2pp. 14517:251. 24X
Fiche: 50-206, 82/08/12, 8208230042.

8208230076 Resubmits 820809 & 820804 responses to IE Bulletin 81-01 & 81-01 re mechanical snubbers, to include required affirmation
HAYNES, J. O. Southern California Edison Co. 82/08/12. ENGELKEN, R. H.
Region 5, Office of Director. 2pp. 14517:151. 24X
Fiche: 50-206, 82/08/12, 8208230076.

--8208230086 Submits addl info to 810227 & 0421 responses to IE Bulletin 81-01 re mechanical snubbers. Summary of installed mechanical snubbers on safety-related sys encl.
HAYNES, J. O. Southern California Edison Co. 82/08/12.
ENGELKEN, R. H. Region 5, Office of Director. 3pp. 14517:153. 24X
Fiche: 50-206, 82/08/12, 8208230076.

8208240197 Ack receipt of 820806 ltr informing NRC of steps taken to correct violations noted in IE Insp Rpt 50-206/82-19
800K, H. E. Division of Radiological Safety & Safeguards Program
82/08/18. PAPAY, L. T. Southern California Edison Co. 1p.
14519:297. 24X Fiche: 50-206, 82/08/18, 8208240197.

--8208240203 Responds to NRC 820707 ltr re violations noted in IE Insp Rpt 50-206/82-19. Corrective actions caution signs posted in high radiation area & Health Physics Procedure 50123 VII-7. 4 re posting implemented on 820624
PAPAY, L. T. Southern California Edison Co. 82/08/06.
ENGELKEN, R. H. Region 5, Office of Director. 3pp. 14519:298. 24X
Fiche: 50-206, 82/08/18, 8208240197.

8. Periodic operating reports & related correspondence

8208120147 Forwards monthly operating rept for June 1982
RAY, H. B. Southern California Edison Co. 82/07/06. Management
Information Branch. 1p. 14319:231. 24X Fiche: 50-206, 82/07/06, 8208120147.

--8208120152 Monthly operating rept for June 1982
RAIDY, T. Southern California Edison Co. 82/07/06. 5pp.
14319:232. 24X Fiche: 50-206, 82/07/06, 8208120147.

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A.
Critical Mass Energy Project. 8pp. 14679:208. 24X
Fiche: 50-000, 82/07/13, 8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp.
14679:216. 24X Fiche: 50-000, 82/07/13, 8208270010.

--8208270553 Rept of total man rem for 1981.
* Southern California Edison Co. 82/03/04. 1p. 14680:032. 24X
Fiche: 50-000, 82/07/13, 8208270010.

--8208270582 "Forwards "Number of Personnel & Man Rem Exposure By Work & Job Function for CY81." per 10CFR20.407.
RAY, H. B. Southern California Edison Co. 82/03/08. Office of
Management and Program Analysis. 1p. 14680:039. 24X
Fiche: 50-000, 82/07/13, 8208270010.

--8208270588 "Number of Personnel & Man Rem Exposure By Work & Job Function for CY81."
* Southern California Edison Co. 82/03/08. 2pp. 14680:040. 24X
Fiche: 50-000, 82/07/13, 8208270010.

8208170250 Forwards monthly operating rept for Jul 1982.
RAY, H. B. Southern California Edison Co. 82/08/11. Office of
Resource Management, Director. 1p. 14367:039. 24X
Fiche: 50-206, 82/08/11, 8208170250.

--8208170314 Monthly operating rept for Jul 1982.
SPEER, M. Southern California Edison Co. 82/08/13. 5pp.
14367:040. 24X Fiche: 50-206, 82/08/11, 8208170250.

9. Reportable occurrences, LERs & related correspondence

8208020324 Forwards updated LER 82-011/03X-1. Detailed event analysis submitted.
RAY, H. B. Southern California Edison Co. 82/07/21. ENGELKEN, R. H.
Region 5, Office of Director. 2pp. 14151:147. 24X
Fiche: 50-206, 82/07/21, 8208020324.

--B208020329 Updated LER B2-011/03X-1 from B11215 to 0218, surveillance tests not performed for containment, purge & exhaust isolation & power operated relief valve channels. Caused by insufficient communication between depts.
RAY, H. B. Southern California Edison Co. B2/07/21. Region 5.
Office of Director. Ip. 14151:149. 24X Fiche: 50-206, B2/07/21.
B208020324

B208120180 Forwards LER B2-017/01X-1 Detailed event analysis encl.
RAY, H. B. Southern California Edison Co. B2/08/02. ENOELKEN, R. H.
Region 5, Office of Director. 3pp. 14327:013. 24X
Fiche: 50-206, B2/08/02, B208120180

--B208120182 LER B2-017/01X-1 on B20614, south waste gas decay tank depressurized from 25 psig to approx 0 psig during 24-h surveillance period. Cause not stated. Helium leak test performed by outside contractor.
RAY, H. B. Southern California Edison Co. B2/08/02. Region 5.
Office of Director. Ip. 14327:016. 24X Fiche: 50-206, B2/08/02, B208120180

B208180076 RD B2-013 installation of radiation monitors in release line of reheater pit sump & oily sump not completed due to delays in performing hydrostatic testing of sump piping. Completion expected prior to end of outage
RAY, H. B. Southern California Edison Co. B2/08/06. ENOELKEN, R. H.
Region 5, Office of Director. 2pp. 14376:345. 24X
Fiche: 50-206, B2/08/06, B208180076

B208200231 Forwards LER B2-018/03L-0 Detailed event analysis submitted.
RAY, H. B. Southern California Edison Co. B2/08/06. ENOELKEN, R. H.
Region 5, Office of Director. 2pp. 14399:338. 24X
Fiche: 50-206, B2/08/06, B208200231.

--B208200242 LER B2-018/03L-0 on B20706, particulate filter samples taken from main stack in May & Jul 1982 discarded before analysis for Sr-89 & Sr-90 conducted. Caused by human error. Procedure revised.
RAY, H. B. Southern California Edison Co. B2/08/06. Region 5.
Office of Director. Ip. 14399:340. 24X Fiche: 50-206, B2/08/06, B208200231

B208300057 Forwards LER B2-019/03L-0 Detailed event analysis submitted.
RAY, H. B. Southern California Edison Co. B2/08/17. ENOELKEN, R. H.
Region 5, Office of Director. 2pp. 14679:149. 24X
Fiche: 50-206, B2/08/17, B208300057

--B208300058 LER B2-019/03L-0 on B20719, effective leakage from circulation loop outside containment found greater than Tech Spec limit. Caused by leak in south refueling water pump casing drain valve & spray orifice bypass valve.
RAY, H. B. Southern California Edison Co. B2/08/17. Region 5.
Office of Director. Ip. 14679:151. 24X Fiche: 50-206, B2/08/17, B208300057

B208300087 Forwards LER B2-020/03L-0 Detailed event analysis submitted.
RAY, H. B. Southern California Edison Co. B2/08/20. ENOELKEN, R. H.
Region 5, Office of Director. 2pp. 14596:145. 24X
Fiche: 50-206, B2/08/20, B208300087.

--B208300089 LER B2-020/03L-0 on B10702.16, B20209 & 0729, Tech Spec testing period limits not adhered to. Caused by operator misinterpretation of Tech Specs. Operator retraining will be completed by B20930 & surveillance instructions revised.
RAY, H. B. Southern California Edison Co. B2/08/20. Region 5.
Office of Director. Ip. 14596:147. 24X Fiche: 50-206, B2/08/20, B208300087.

DOCKET 50-208 COLUMBIA UNIV. RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

B204210395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Bvc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. B2/07/19.
Michigan, Univ. of. 112pp. 14358:001. 24X Fiche: 50-000, B2/07/19, B204210395.

DOCKET 50-213 HADDAM NECK PLANT

F. Security, medical, emergency & fire protection plans

B207210248 Forwards addl info supporting B10319 exemption request from App R requirements.
COUNBIL, W. Q. CAONETTA, J. P. Connecticut Yankee Atomic Power Co. B2/07/16. EISENHUT, D. O. Division of Licensing. 152pp. 13934:351. 24X Fiche: 50-213, B2/07/16, B207210248.

B208050163 Forwards "Fire Protection App R Review, Haddam Neck Plant, Supplemental Info."
COUNBIL, W. Q. CAONETTA, J. P. Connecticut Yankee Atomic Power Co. B2/07/16. EISENHUT, D. O. Division of Licensing. 10pp. 14211:247. 24X Fiche: 50-213, B2/07/16, B208050163.

--B208050167 "Fire Protection App R Review, Haddam Neck Plant, Supplemental Info."
COUNBIL, W. Q. CAONETTA, J. P. Connecticut Yankee Atomic Power Co. B2/07/31. 150pp. 14211:258. 24X Fiche: 50-213, B2/07/16, B208050163.

B208030013 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. B2/07/20. Document Management Branch. Ip. 14201:001. 24X Fiche: 50-000, B2/07/20, B208030013

--B208030019 Public version of revised emergency plan implementing procedures, including Procedures EPIP 4102 re alert, EPIP 4103 re site area emergency & EPIP 4104 re general emergency.
COUNBIL, W. Q. CAONETTA, J. P. Connecticut Yankee Atomic Power Co. * Northeast Nuclear Energy Co. (subs. of Northeast Utilities). B2/07/20. 718pp. 14201:005. 24X Fiche: 50-000, B2/07/20, B208030013

B208060267 Submits addl clarifications of B20301 App R review for facilities, in response to NRC B20625 & 0707 requests.
COUNBIL, W. Q. Connecticut Yankee Atomic Power Co. COUNBIL, W. Q. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). B2/07/30. CLARK, R. A. Operating Reactors Branch 3. CRUTCHFIELD, D. Operating Reactors Branch 5. 10pp. 14241:196. 24X Fiche: 50-000, B2/07/30, B208060267.

B208090312 Advises that fee sent w/B20120 application for exemption from safeguarding requirements of 10CFR73.21 will be refunded.
MILLER, W. O. License Fee Management Branch. B2/07/30. COUNBIL, W. Q. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). Ip. 14307:323. 24X Fiche: 50-000, B2/07/30, B208090312.

B208160434 Forwards revision to suitability, training & qualification plan. Revision withheld (ref 10CFR2.790).
ADDY, R. J. Connecticut Yankee Atomic Power Co. B2/08/04. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. Ip. 14349:198. 24X Fiche: 50-213, B2/08/04, B208160434

B208260447 Releases public version of revised emergency plan procedures.
FELTON, J. M. Division of Rules and Records. B2/08/09. Document Management Branch. Ip. 14579:048. 24X Fiche: 50-213, B2/08/09, B208260447.

--B208260451 Forwards public version of revised emergency plan procedures, including Procedures EPP 1.5-1 re emergency assessment, EPP 1.5-2 re notification & communication & 1.5-3 re notification of unusual event.
COUNBIL, W. Q. Connecticut Yankee Atomic Power Co. B2/07/29. EISENHUT, D. O. Division of Licensing. Ip. 14579:046. 24X Fiche: 50-213, B2/08/09, B208260447.

--B208260455 Public version of revised emergency plan procedures, including Procedures EPP 1.5-1 re emergency assessment, EPP 1.5-2 re notification & communication & 1.5-3 re notification of unusual event. Revised index encl.
COUNBIL, W. Q. Connecticut Yankee Atomic Power Co. B2/07/31. 200pp. 14579:047. 24X Fiche: 50-213, B2/08/09, B208260447.

H. General correspondence

B208250135 Notifies of recent changes in util organization reflected in QA program topical report Revision 4A Details encl.
COUNBIL, W. Q. CAONETTA, J. P. Northeast Utilities Service Co. B2/08/17. HAASB, W. P. Quality Assurance Branch. 7pp. 14541:302. 24X Fiche: 50-000, B2/08/17, B208250135.

P. Operating license stage documents & correspondence

B207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR. Bvc list encl.
DIRCKS, W. J. Office of the Executive Director for Operations. B2/07/02. Consolidated Edison Co. of New York. 93pp. 14194:001. 24X Fiche: 50-000, B2/07/02, B207080064.

B208020076 Advises that facilities fully meet position of NUREG-0737, Item III D.3.3, "Improved In-Plant Iodine Instrumentation Under Accident Conditions." No deviations requested.
COUNBIL, W. Q. Connecticut Yankee Atomic Power Co. COUNBIL, W. Q. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). B2/07/20. CRUTCHFIELD, D. Operating Reactors Branch 5. Ip. 14144:106. 24X Fiche: 50-000, B2/07/20, B208020076.

--B208020234 Proposed Tech Specs, changing definition of containment integrity & updating removal plan for remaining reactor vessel surveillance capsules.
* Connecticut Yankee Atomic Power Co. B2/06/30. 14pp.
14152 037 24X Fiche: 50-213, B2/07/23, B208020235

--B208020239 Proposed ETS, changing surveillance & reporting requirements of fish impingement.
* Connecticut Yankee Atomic Power Co. B2/06/30. 1p. 14152 051
24X Fiche: 50-213, B2/07/23, B208020235.

B208020244 Notifies of proposed programmatic change to QA program topical rept, Revision 4A Exception to Paragraph 1.4 of ANSI N45 2.9-1974 re definition of QA records will be added to App F of topical rept.
COUNCIL, W. Q. Northeast Utilities Service Co. COUNCIL, W. Q. Northeast Utilities. B2/07/26 HAASS, W. P. Quality Assurance Branch. 2pp. 14132 234. 24X Fiche: 50-000, B2/07/26, B208020244

B208060230 Notifies of delay in submittal of head vent procedures until B20901
COUNCIL, W. Q. CAONETTA, J. P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNCIL, W. Q. Connecticut Yankee Atomic Power Co. B2/07/30 CRUTCHFIELD, D. Operating Reactors Branch 5. CLARK, R. A. Operating Reactors Branch 3. 2pp. 14241:332. 24X Fiche: 50-000, B2/07/30, B208060230

B208060231 Submits comments on SEP Phase II, to assist NRC in development of proposed program for Phase III.
COUNCIL, W. Q. Connecticut Yankee Atomic Power Co. COUNCIL, W. Q. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). B2/07/30. CRUTCHFIELD, D. Operating Reactors Branch 5. 8pp. 14241:323. 24X Fiche: 50-000, B2/07/30, B208060231

B208060279 Provides further response to NRC B01222 request for info re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants." Schedule for completion of remaining work expected by B20927
COUNCIL, W. Q. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNCIL, W. Q. Connecticut Yankee Atomic Power Co. B2/07/30. EISENHUT, D. G. Division of Licensing. 6pp. 14241:088
24X Fiche: 50-000, B2/07/30, B208060279

B208310426 Responds to FOIA request for documents re NFB-4 shipping casks. Forwards Documents 2, 5, 8, 9, 11, 12, 13, 29, 31, 33 & 48 listed in App A Remaining documents available in PDR.
FELTON, J. M. Division of Rules and Records. B2/07/30 KRONZEK, A. L. FOI Services. 4pp. 14705:134. 24X Fiche: 50-000, B2/07/30, B208310426

--B208310481 Informs of intent to ship BNM in form of three irradiated fuel assemblies from Haddam Neck, CT to BHI in Columbus, OH on B00422, 28 & 0502
COUNCIL, W. Q. FEE, W. F. Connecticut Yankee Atomic Power Co. B0/04/15 ORIER, B. H. Region 1, Philadelphia, Office of the Director. 1p. 14705:256. 24X Fiche: 50-000, B2/07/30, B208310426.

--B208310483 Informs that first spent fuel assembly shipped from facility to BHI in NAC-1 cask exceeded decay heat limit. No adverse effects on health & safety observed, therefore no further action necessary.
COUNCIL, W. Q. Connecticut Yankee Atomic Power Co. B0/03/21. ORIER, B. H. Region 1, Philadelphia, Office of the Director. 2pp. 14705:274. 24X Fiche: 50-000, B2/07/30, B208310426.

B208050076 Forwards final evaluation of licensee response to SEP Topic III-4. A re tornado missiles Facility can be operated safely until issue of providing addl protection to 10 listed areas is resolved in integrated assessment.
CRUTCHFIELD, D. Operating Reactors Branch 5. B2/08/02. COUNCIL, W. Q. Connecticut Yankee Atomic Power Co. 17pp. 14213:210. 24X Fiche: 50-213, B2/08/02, B208050076.

B208110039 Discusses changes to Tech Specs re containment air recirculation sys filtration sys in EBF filter sys. No Tech Spec need yet be proposed for primary auxiliary bldg filters & fuel storage bldg filters. Multi-Plant Test C-04 closed.
CRUTCHFIELD, D. Operating Reactors Branch 5. B2/08/05. COUNCIL, W. Q. Connecticut Yankee Atomic Power Co. 2pp. 14317:172. 24X Fiche: 50-213, B2/08/05, B208110039.

B208160117 Requests assurance that final radiological effluent Specs will be submitted no later than B31001
CRUTCHFIELD, D. Operating Reactors Branch 5. B2/08/11. COUNCIL, W. Q. Connecticut Yankee Atomic Power Co. 2pp. 14345:103. 24X Fiche: 50-213, B2/08/11, B208160117

B208190297 Comments on draft technical & safety evaluations of Topic VII-1 A, "Isolation of Reactor Protection Sys From Nonsafety Sys, including Qualification of Isolation Devices."
COUNCIL, W. Q. Connecticut Yankee Atomic Power Co. B2/08/11. CRUTCHFIELD, D. Operating Reactors Branch 5. 6pp. 14500:07. Fiche: 50-213, B2/08/11, B208190297.

B208170158 Forwards "Control of Heavy Loads," draft technical evaluation rept. Safety evaluation will be issued following receipt of comments.
CRUTCHFIELD, D. Operating Reactors Branch 5. NRC-03-79-118 B2/08/12. COUNCIL, W. Q. Connecticut Yankee Atomic Power Co. 14364:345. 24X Fiche: 50-213, B2/08/12, B208170158.

--B208170163 "Control of Heavy Loads," draft technical evaluation. HOFKIN, T. BARGENT, I. H. Franklin Institute/Franklin Research Center. NRC-03-79-118. TER-C5297-445. B2/08/03. CLEMEN, NRC - No Detailed Affiliation Given. 27pp. 14364:347. 24X Fiche: 50-213, B2/08/12, B208170158

B208170169 Forwards final evaluation of sys portion of SEP Topic VI-7, B, "EBF Switchover From Injection to Recirculation Mode Automatic ECCB Realignment." Manual switchover procedure does not meet SEP review criteria.
CRUTCHFIELD, D. Operating Reactors Branch 5. B2/08/12. COUNCIL, W. Q. Connecticut Yankee Atomic Power Co. 7pp. 14364:333. 24X Fiche: 50-213, B2/08/12, B208170169

B208240251 Forwards technical evaluation rept & draft safety evaluation re SEP Topic III-1, "Quality Group Classification of Components & Sys." for review. Response requested within 30 days of ltr receipt.
CRUTCHFIELD, D. Operating Reactors Branch 5. B2/08/12. COUNCIL, W. Q. Connecticut Yankee Atomic Power Co. 6pp. 14523:001. 24X Fiche: 50-213, B2/08/12, B208240251.

--B207260247 "Quality Group Classification of Components & Sys (SEP, III-1) CT Yankee Atomic Power Co. Haddam Neck Plant," technical evaluation rept.
TIKOO, S. QONZALEZ, A. BERKOWITZ, L. Franklin Institute/Franklin Research Center. NRC-03-79-118. TER-C5237-435. B2/07/22. BOYLE, H. NRC - No Detailed Affiliation Given. 180pp. 14364:347. 24X Fiche: 50-213, B2/08/12, B208240251

B208240384 Forwards addl info re NUREG-0737, Item II, K. 3. 17, "E Outages," in response to NRC B20622 request.
COUNCIL, W. Q. OPEKA, J. F. Connecticut Yankee Atomic Power Co. COUNCIL, W. Q. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). B2/08/16. CRUTCHFIELD, D. Operating Reactors Branch 5. CLARK, R. A. Operating Reactors Branch 3. 23pp. 14524:043. Fiche: 50-000, B2/08/16, B208240384

B208240404 Forwards comments on SEP Topic VI-4, "Containment I Sys." Requests comments be incorporated into revised safety evaluation for SEP topic.
COUNCIL, W. Q. WERNER, R. P. Connecticut Yankee Atomic Power Co. B2/08/18. CRUTCHFIELD, D. Operating Reactors Branch 5. 20pp. 14522:295. 24X Fiche: 50-213, B2/08/18, B208240404.

B208250138 Forwards safety evaluation of util B20407 safety assessment rept for sys & radiological consequences of SEP Topic XV-17, "Steam Generator Tube Rupture." Assessment acceptable.
CRUTCHFIELD, D. Operating Reactors Branch 5. B2/08/19. COUNCIL, W. Q. Connecticut Yankee Atomic Power Co. 17pp. 14540:330. 24X Fiche: 50-213, B2/08/19, B208250138.

B208300094 Advises that leased temporary modular structures on site do not violate Tech Spec Section 5.2. No action required or requested.
COUNCIL, W. Q. Connecticut Yankee Atomic Power Co. B2/08/19. CRUTCHFIELD, D. Assistant Director for Operating Reactors. 14596:154. 24X Fiche: 50-213, B2/08/19, B208300094.

B208300075 Advises that BAR for SEP Topic III-5, A, "High Energy Break Inside Containment," will be submitted on or before B20917
COUNCIL, W. Q. CAONETTA, J. P. Connecticut Yankee Atomic Power Co. B2/08/23. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14598:306. 24X Fiche: 50-213, B2/08/23, B208300075.

B208300036 Forwards "Aerial Radiological Survey of Haddam Neck Plant & Surrounding Area." date of survey Oct 1981.
BOREB, R.J. Region 1, Office of Director. 82/08/25 COUNSIL, W.O.
Connecticut Yankee Atomic Power Co. 1p 14998:255 24X
Fiche: 50-213, 82/08/25, B208300036.

--B208300038 "Aerial Radiological Survey of Haddam Neck Plant & Surrounding Area." date of survey Oct 1981.
HOBBAUGH, J.L., MAQUIRE, T.C., TIPTON, W.J. EG&O, Inc. E00-1183:1829.
82/07/31. NRC - No Detailed Affiliation Given. 15pp.
Available at NTIS. \$6 00 14998:256 24X Fiche: 50-213, 82/08/25,
B208300036.

Q. Inspection reports, IE Bulletins & correspondence

B204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MSIV) Leakage." Bvc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/16.
Consolidated Edison Co. of New York. 87pp. 14356:274. 24X
Fiche: 50-000, 82/07/16, B204210393

B204210395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Bvc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/19.
Michigan, Univ. of 112pp. 14358:001. 24X Fiche: 50-000, 82/07/19,
B204210395.

B204210396 IE Info Notice B2-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Bvc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/20.
Consolidated Edison Co. of New York. 112pp. 14381:001 24X
Fiche: 50-000, 82/07/20, B204210396.

B204210397 IE Info Notice B2-24, "Water Leaking From U Hexafluoride Overpacks." Bvc list encl.
COBB, L.I. Division of Fuel Facilities, Materials & Safeguards.
82/07/20. Consolidated Edison Co. of New York. 71pp. 14357:276.
24X Fiche: 50-000, 82/07/20, B204210397.

B204210398 IE Info Notice B2-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Bvc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/22.
Consolidated Edison Co. of New York. 112pp. 14194:321. 24X
Fiche: 50-000, 82/07/22, B204210398.

B204210401 IE Info Notice B2-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Bvc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23
Consolidated Edison Co. of New York. 122pp. 14380:115. 24X
Fiche: 50-000, 82/07/23, B204210401.

B204210402 IE Info Notice B2-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Bvc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York. 127pp. 14194:120. 24X
Fiche: 50-000, 82/07/23, B204210402

B204210403 IE Info Notice B2-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Bvc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/26.
Consolidated Edison Co. of New York. 121pp. 14357:013. 24X
Fiche: 50-000, 82/07/26, B204210403.

B204210405 IE Info Notice B2-31, "Overexposure of Diver During Work in Fuel Storage Pool." Bvc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/28.
Consolidated Edison Co. of New York. 122pp. 14357:146. 24X
Fiche: 50-000, 82/07/28, B204210405

B208100142 Responds to IE Bulletin B2-02 re degradation of threaded fasteners in RCPB. Action Item 1, procedures for threaded fastener practices, will be implemented prior to Action Item 2 insp.
COUNSIL, W.O., CAONETTA, J.P. Connecticut Yankee Atomic Power Co.
COUNSIL, W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/07/28. HAYNES, R.C. Region 1, Office of Director.
2pp. 14298:050. 24X Fiche: 50-213, 82/07/28, B208100142.

B208160423 Responds to Action Items 3 & 5 of IE Bulletin B2-02 re degradation of threaded fasteners in RCPB. Occurrences of visible leakage from body to bonnet areas of valves noted. No fastener corrosion observed.
COUNSIL, W.O. Connecticut Yankee Atomic Power Co. COUNSIL, W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
82/07/30. HAYNES, R.C. Region 1, Office of Director. 4pp.
14348:173. 24X Fiche: 50-000, 82/07/30, B208160423.

B208310426 Responds to FOIA request for documents re NFB-4 shipping cases. Forwards Documents 2, 3, 8, 9, 11, 12, 13, 29, 31, 33 & 40 listed in App A. Remaining documents available in PDR.
FELTON, J.M. Division of Rules and Records. 82/07/30. KRONZEK, A.
FDI Services. 4pp. 14705:134 24X Fiche: 50-000, 82/07/30,
B208310426

--B208310469 Forwards IE Investigation Repts 50-213/80-20 & 50-219/80 on B01006-B10114 & notice of violation.
CARLSON, R.T. Enforcement & Investigation Staff. 81/12/23.
COUNSIL, W.O. Connecticut Yankee Atomic Power Co. 2pp. 14705:2
24X Fiche: 50-000, 82/07/30, B208310426.

--B208310472 Notice of violation from investigation on B01006-B10114.
CARLSON, R.T. Enforcement & Investigation Staff. 81/12/23. 1p.
14705:229. 24X Fiche: 50-000, 82/07/30, B208310426.

--B208310476 IE Investigation Repts 50-213/80-20 & 50-219/80-38 on B01006-B10114. Noncompliance noted on B00501, Model NFB-4. Serial NAC-IE cask, loaded w/faded bundle H07, delivered to carrier w/decay heat generation in excess of 2.5 kW.
SMITH, R.H., ROTH, J., CARLSON, R.T. Enforcement & Investigation Staff. 81/10/06. 14pp. 14705:230. 24X Fiche: 50-000, 82/07/30,
B208310426.

B204210407 IE Info Notice B2-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Bvc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/08/03.
Consolidated Edison Co. of New York. 117pp. 14388:201. 24X
Fiche: 50-000, 82/08/03, B204210407.

R. Periodic operating reports & related correspondence

B208120238 Forwards monthly operating rept for June 1982
GRAVES, R.H. Connecticut Yankee Atomic Power Co. 82/07/13. Off
of Management and Program Analysis. 1p. 14326:035 24X
Fiche: 50-213, 82/07/13, B208120238

--B208120239 Monthly operating rept for June 1982.
* Connecticut Yankee Atomic Power Co. 82/07/13. 12pp.
14326:036. 24X Fiche: 50-213, 82/07/13, B208120238.

B208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J.M. Division of Rules and Records. 82/07/13. UDELL, R.A.
Critical Mass Energy Project. 8pp. 14679:208 24X
Fiche: 50-000, 82/07/13, B208270010.

--B208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp.
14679:216. 24X Fiche: 50-000, 82/07/13, B208270010.

--B208270271 Forwards annual occupational exposures by work & job function for CY81.
GRAVES, R.H. Connecticut Yankee Atomic Power Co. 82/02/18.
Director's Office, Office of Inspection and Enforcement. 1p.
14679:304 24X Fiche: 50-000, 82/07/13, B208270010.

--B208270276 Annual occupational exposures by work & job function for CY81.
* Connecticut Yankee Atomic Power Co. 82/02/18. 1p. 14679:30
24X Fiche: 50-000, 82/07/13, B208270010.

--B208270551 Forwards "Personnel Exposure & Monitoring Rept - 10CFR2 Rept for 1981."
GRAVES, R.H. Connecticut Yankee Atomic Power Co. 82/03/31.
HALLER, N.H. Office of Management and Program Analysis. 1p.
14680:070. 24X Fiche: 50-000, 82/07/13, B208270010.

--B208270554 "Personnel Exposure & Monitoring Rept - 10CFR20.407 Rept 1981."
* Connecticut Yankee Atomic Power Co. 82/03/31. 4pp. 14680:0
24X Fiche: 50-000, 82/07/13, B208270010.

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

B208050390 Forwards IE Safeguards Insp Rept 50-219/B2-14 on B20817-2. No noncompliance noted. Rept details withheld (ref 10CFR73.21).
MARTIN, T.T. Division of Engineering & Technical Programs. 82/07/
FELDER, P.B. General Public Utilities - OPU Service Corp. 2pp.
14209:188. 24X Fiche: 50-219, 82/07/21, B208050390.

add. Details withheld (ref 10CFR73 21)
MADDEN, W., SMITH, O., GODY, A. T. Division of Engineering & Technical Programs. 82/07/19 1p 14209 190 24x Fiche: 50-219, 82/07/21, 8208050390

P Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR. Svc list encl
DIRCKB, W. J. Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York. 93pp. 14194 001 24x Fiche: 50-000, 82/07/02, 8207080064

8208240247 Confirms 820720-22 visits to util headquarters & plant site to discuss SEP integrated assessment program. Meetings involve review of licensee position on differences & discussion of factors re backfitting decisions.
CRUTCHFIELD, D. Operating Reactors Branch 5 82/07/12 FIEDLER, P. B. General Public Utilities - GPU Service Corp 2pp. 14520 092 24x Fiche: 50-219, 82/07/12, 8208240247

8208020384 Responds to util 811224 request for deferment of items previously committed to accomplish during 1982 Cycle 10 refueling/maint outage. Deferment of items 3, 4, 5, 8, 9 & 10 acceptable.
EISENHUT, D. O. Division of Licensing 82/07/30. CLARK, P. R. General Public Utilities - GPU Service Corp. 11pp 14148 210 24x Fiche: 50-219, 82/07/30, 8208020384

8208060201 Requests exemption from final interim requirements re hydrogen control. Installation of high point vents on isolation condensers should be deferred until Cycle 11 refueling outage after Aug 1982.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 82/08/02. Office of Nuclear Reactor Regulation, Director 2pp. 14238 361 24x Fiche: 50-219, 82/08/02, 8208060201

8208060297 Submits addl info re SEP Topics III-5, B, III-6, III-10, A, V-5, VI-7, A, 3, VI-7, C, 1, VI-10, A, VII-1, A, VII-2 & VII-4, per 820518-20 commitment. Info re Topics III-6, VI-4, VI-7, A, 3, VII-1, A & VII-2 will be provided later.
FIEDLER, P. B. General Public Utilities - GPU Service Corp 82/08/02 CRUTCHFIELD, D. Operating Reactors Branch 5 7pp. 14241 297 24x Fiche: 50-219, 82/08/02, 8208060297

8208190157 Forwards proprietary version of XN-NF-7B-12, "Bspray Cooling Heat Transfer Test Results, Phase-II Facility & Test Data ENC B-8 BWR Fuel." Encl withheld (ref 10CFR2 790). Affidavit encl
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 82/08/06 CRUTCHFIELD, D. Operating Reactors Branch 5 4pp 14381 015 24x Fiche: 50-219, 82/08/06, 8208190157

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D. O. Division of Licensing. 82/08/09 Consolidated Edison Co. of New York. 1p 14356 332 24x Fiche: 50-000, 82/08/09, 8208090194

8208190182 Advises of 820824 meeting w/util to discuss SEP integrated assessment program. Discussion will include review of licensee position on difference factors pertinent to backfitting decisions & to close out resolved differences.
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/13. FIEDLER, P. B. General Public Utilities - GPU Service Corp. 3pp. 14386 349 24x Fiche: 50-219, 82/08/13, 8208190182

8208240230 Comments on value of SEP. SEP should be terminated at end of Phase II, since major objectives & benefits will be reached, other NRC programs overlap SEP & resources needed for other programs.
FIEDLER, P. B. General Public Utilities - GPU Service Corp 82/08/16. CRUTCHFIELD, D. Operating Reactors Branch 5 3pp. 14519 149 24x Fiche: 50-219, 82/08/16, 8208240230

8208270103 Forwards application to amend License DPR-16, consisting of Change Request II, increasing capacity of spent fuel storage facilities to allow storage of 2,600 fuel assemblies Class III amend fee encl.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 82/08/20 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp. 14563 319 24x Fiche: 50-219, 82/08/20, 8208270103

Certificate of Svc encl
FIEDLER, P. B. General Public Utilities - GPU Service Corp 82/08/20. 3pp 14563 320 24x Fiche: 50-219, 82/08/20, 8208270103

8208270284 Forwards responses to list of deficiencies identified in NRC 820316 ltr re radiological effluent Tech Specs Schedule for submitting final radiological specs & offsite dose calculation manual will be provided later.
FIEDLER, P. B. Jersey Central Power & Light Co 82/08/20 CRUTCHFIELD, D. Operating Reactors Branch 5 16pp 14563 097 24x Fiche: 50-219, 82/08/20, 8208270284

8208310413 Submits response to questions raised by M Masnik re Tech Spec Change Request 94 re intake water canal level.
FIEDLER, P. B. General Public Utilities - GPU Service Corp 82/08/20. LOMBARD, D. J. Operating Reactors Branch 5 2pp. 14673 274 24x Fiche: 50-219, 82/08/20, 8208310413

8208310440 Forwards Revision O to "Tech Spec for Water Quality," in response to SEP Topic V-12 A, "Water Purity of BWR Primary Coolant."
NAGAI, Y. General Public Utilities - GPU Service Corp 82/08/24. FELL, R. Systematic Evaluation Program Branch 2pp 14690 170 24x Fiche: 50-219, 82/08/24, 8208310440

--8208310447 Revision O to "Tech Spec for Water Quality,"
WATERS, C. R. General Public Utilities - GPU Service Corp 82/07/01 26pp. 14690 172 24x Fiche: 50-219, 82/08/24, 8208310440

8208260174 Notification of 820902 meeting w/util in Bethesda, MD to discuss SEP integrated assessment program for facility.
LOMBARD, D. J. Operating Reactors Branch 5 82/08/25 CRUTCHFIELD, D. Operating Reactors Branch 5 3pp 14554 324 24x Fiche: 50-219, 82/08/25, 8208260174

Q Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16 Consolidated Edison Co of New York 87pp. 14356 274 24x Fiche: 50-000, 82/07/16, 8204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19 Michigan, Univ. of 112pp. 14358 001 24x Fiche: 50-000, 82/07/19, 8204210395

8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20. Consolidated Edison Co. of New York 112pp 14381 001 24x Fiche: 50-000, 82/07/20, 8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co. of New York. 71pp. 14357 276 24x Fiche: 50-000, 82/07/20, 8204210397

8208050390 Forwards IE Safeguards Insp Rept 50-219/82-14 on 820517-21. No noncompliance noted. Rept details withheld (ref 10CFR73, 21).
MARTIN, T. T. Division of Engineering & Technical Programs. 82/07/21. FIEDLER, P. B. General Public Utilities - GPU Service Corp. 3pp. 14209 188 24x Fiche: 50-219, 82/07/21, 8208050390

--8208050400 IE Safeguards Rept 50-219/82-14 on 820517-21. No noncompliance noted. Major areas inspected physical barriers, vital/protected areas, security sys power supply & lighting aids. Details withheld (ref 10CFR73 21).
MADDEN, W., SMITH, O., GODY, A. T. Division of Engineering & Technical Programs. 82/07/19 1p. 14209 190 24x Fiche: 50-219, 82/07/21, 8208050390

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/22. Consolidated Edison Co. of New York 112pp. 14194 321 24x Fiche: 50-000, 82/07/22, 8204210398

8208050275 Forwards IE Insp Rept 50-219/82-17 on 820602-0705 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs. 82/07/22. FIEDLER, P. B. General Public Utilities - GPU Service Corp. 2pp. 14210 122 24x Fiche: 50-219, 82/07/22, 8208050275

ange --8208050278 Notice of violation from insp on 820602-0705
STAROSTECKI, R Division of Project & Resident Programs 82/07/22
1p 14210 124 24X Fiche 50-219, 82/07/22, 8208050275

0103 --8208030285 IE Insp Rept 50-219/82-17 on 820602-0705 Noncompliance
noted unmonitored release of radioactive liquid to discharge
canal, contaminating new radwaste bldg svc air sys
THOMAS, J. TRIPP, L E Division of Project & Resident Programs
82/07/20 11pp 14210 125 24X Fiche 50-219, 82/07/22, 8208050275.

24X 8204210401 IE Info Notice 82-23. "Hydrogen Explosion While Grinding in
Vicinity of Drained & Open RCS " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23.
Consolidated Edison Co of New York 122pp 14380 115 24X
Fiche: 50-000, 82/07/23, 8204210401

8/20 8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube
Support Pin Failures at Westinghouse PHRs." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co of New York 127pp 14194 120 24X
Fiche: 50-000, 82/07/23, 8204210402.

24X 8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping
at Certain Westinghouse PHR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26
Consolidated Edison Co of New York. 121pp 14357 013 24X
Fiche: 50-000, 82/07/26, 8204210403

0440. 8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in
Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28
Consolidated Edison Co of New York 122pp 14357 146 24X
Fiche: 50-000, 82/07/28, 8204210405.

24X 8208100207 Ack receipt of 820709 ltr informing NRC of steps taken to
correct violations noted in IE Insp Rept 50-219/82-06
MARTIN, T. T. Division of Engineering & Technical Programs 82/07/30.
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 2pp.
14294 255 24X Fiche: 50-219, 82/07/30, 8208100207.

16 --8208100213 Responds to NRC 820520 ltr re violations noted in IE Insp
Rept 50-219/82-06. Corrective actions reporting guidelines
incorporated into local leak rate testing procedure
FIEDLER, P. B. General Public Utilities - GPU Service Corp.
82/07/09. MARTIN, T. T. Division of Engineering & Technical
Programs. 7pp 14294 257. 24X Fiche: 50-219, 82/07/30, 8208100207.

19 8208310426 Responds to FOIA request for documents re NFB-4 shipping
lists. Forwards Documents 2, 5, 8, 9, 11, 12, 13, 29, 31, 33 & 48
listed in App A Remaining documents available in PDR.
FELTON, J. M. Division of Rules and Records 82/07/30. KRONZEK, A. L.
FOI Services. 4pp. 14705 134. 24X Fiche: 50-000, 82/07/30.
8208310426.

20 --8208310469 Forwards IE Investigation Repts 50-213/80-20 & 50-219/80-38
on 801006-810114 & notice of violation.
CARLESON, R. T. Enforcement & Investigation Staff. 81/12/23
COUNSEL, W. O. Connecticut Yankee Atomic Power Co. 2pp. 14705 227.
24X Fiche: 50-000, 82/07/30, 8208310426

76 --8208310476 IE Investigation Repts 50-213/80-20 & 50-219/80-38 on
801006-810114 Noncompliance noted on 800501, Model NFB-4.
Serial NAC-1E cask, loaded w/failed bundle HQ7, delivered to
carrier w/decay heat generation in excess of 2.5 MW.
SMITH, R. H. ROTH, J. CARLESON, R. T. Enforcement & Investigation
Staff. 81/10/06. 14pp. 14705 230. 24X Fiche: 50-000, 82/07/30,
8208310426.

21 --8208310486 Discusses review of licensee mgt of NAC-1E spent fuel
shipping container on 800723-0801 (IE Insp Rept
50-219/80-26). No noncompliance noted. Shipping & receiving
survey records encl.
PLUMLEE, K. E. Facility Radiological Protection Section. 81/09/17.
SMITH, R. H. Region 1, Philadelphia, Office of the Director
(81/03/01). 34pp. 14705 276. 24X Fiche: 50-000, 82/07/30,
8208310426.

22 8208060247 Advises of intent to use ABME B & PV Code Section XI 1980
Edition through 1981 Winter Addenda IWA-5000 for inservice
insp program, per 10CFR50.55 a(g).
FIEDLER, P. B. General Public Utilities - GPU Service Corp. 82/08/02.
Office of Nuclear Reactor Regulation, Director. 2pp. 14241 310.
24X Fiche: 50-219, 82/08/02, 8208060247.

8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From
Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/05.
Consolidated Edison Co. of New York. 117pp. 14388 201. 24X
Fiche: 50-000, 82/08/05, 8204210407.

6208190305 Forwards inservice insp rept on 820302-0723 Rept
examined performed on support components of feedwater,
containment spray & core spray sys
FIEDLER, P. B. General Public Utilities - GPU Service Corp.
HAYNES, R. C. Region 1, Office of Director 1p. 14387 349
Fiche: 50-219, 82/08/12, 8208190305

--8208190309 Inservice insp rept on 820302-0723, describing a
performed on support components of feedwater, containment
spray & core spray sys
THOMAS, R. S. General Public Utilities - GPU Service Corp
3pp. 14387 349. 24X Fiche: 50-219, 82/08/12, 8208190309.

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing
dose exposures in 1981 for operating nuclear power plants
analyzing said info Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records 82/07/13 UD
Critical Mass Energy Project. 8pp 14679 208 24X
Fiche: 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Pow
Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13 48pp
14679 216 24X Fiche: 50-000, 82/07/13, 8208270010.

--8208270280 Forwards "Personnel Whole Body Exposures for CY
per 10CFR20.407
FIEDLER, P. B. General Public Utilities - GPU Service Corp
82/02/18 Office of Management and Program Analysis
14679 306. 24X Fiche: 50-000, 82/07/13, 8208270010.

--8208270288 "Personnel Whole Body Exposures for CY81."
* General Public Utilities - GPU Service Corp. 82/02/18
14679 307. 24X Fiche: 50-000, 82/07/13, 8208270010.

8208120037 Forwards inadvertently omitted page to monthly op
rept for Apr 1982.
FIEDLER, P. B. General Public Utilities - GPU Service Corp.
Management Information Branch. 2pp 14324 004. 24X
Fiche: 50-219, 82/07/14, 8208120037.

--8208120038 Inadvertently omitted unit shutdown & power red
to monthly operating rept for Apr 1982.
BARAN, R. General Public Utilities - GPU Service Corp
2pp. 14324 006 24X Fiche: 50-219, 82/07/14, 8208120037

B. Reportable occurrences, LERs & related correspondence

8208050453 Forwards LER 82-016/03L-0 Detailed event analysis
FIEDLER, P. B. General Public Utilities - GPU Service Corp.
HAYNES, R. C. Region 1, Office of Director. 5pp. 14216 3
Fiche: 50-219, 82/07/14, 8208050453.

--8208050460 LER 82-016/03L-0 on 820611, during transfer of a
svc air piping became cross contaminated w/water, resulti
in three leaks to environ. Caused by blocked vent lines o
tank. Affected sys isolated.
FITZGERALD, M. J. General Public Utilities - GPU Service
82/07/14. Region 1, Office of Director. 1p. 14216 3
Fiche: 50-219, 82/07/14, 8208050453

8208050126 Forwards LER 82-034/03L-0 Detailed event analysis
FIEDLER, P. B. General Public Utilities - GPU Service Corp.
HAYNES, R. C. Region 1, Office of Director. 3pp. 14213 1
Fiche: 50-219, 82/07/16, 8208050126.

--8208050131 LER 82-034/03L-0 on 820616, 300 gallons of conta
water leaked to environs due to broken fitting. Caused by
failure of threaded connection on 1-2 condensate transfe
pump discharge. Connection replaced.
HAGER, C. General Public Utilities - GPU Service Corp.
Region 1, Office of Director. 1p. 14213 118. 24X
Fiche: 50-219, 82/07/16, 8208050126.

8208050346 Forwards LER 82-035/03L-0 Detailed event analysis
FIEDLER, P. B. General Public Utilities - GPU Service Corp.
HAYNES, R. C. Region 1, Office of Director. 3pp. 14219 3
Fiche: 50-219, 82/07/19, 8208050346.

--8208050338 LER 82-035/03L-0 on 820613, off-gas isolation va
indicate closure. Caused by piece of foreign matl lodged
redundant solenoid valve. Solenoid valve removed & replac
SOBEL, C. P. General Public Utilities - GPU Service Corp.
Region 1, Office of Director. 1p. 14219 337. 24X
Fiche: 50-219, 82/07/19, 8208050346.

control
FIEDLER, P. B. General Public Utilities - OPU Service Corp. 82/07/20
HAYNES, R. C. Region 1, Office of Director 3pp. 14130 070. 24X
Fiche: 30-219, 82/07/20, 8208050443

8208050443 RO on 820611, new radwaste svc air sys was contaminated w/ radioactive water from resin transfer tank. Caused by failure of check valve to isolate at cross-connection of two sys. All plant floor & roof drain sys will be reviewed.
FIEDLER, P. B. General Public Utilities - OPU Service Corp. 82/07/20
HAYNES, R. C. Region 1, Office of Director 2pp. 14218:026 24X
Fiche: 30-219, 82/07/20, 8208050443

8208050084 Forwards LER 82-041/017-0 Detailed event analysis encl.
FIEDLER, P. B. General Public Utilities - OPU Service Corp. 82/07/23
HAYNES, R. C. Region 1, Office of Director 3pp. 14213 194. 24X
Fiche: 30-219, 82/07/23, 8208050084

--8208050091 LER 82-041/017-0 on 820707 & 08, stack gas sample pump B electrically tripped overload causing stack gas sampling to reduce to 0 std cubic ft per minute. Caused by high ambient temp near motor controller. Backup pump activated.
CHARTERINA, J. General Public Utilities - OPU Service Corp. 82/07/23
Region 1, Office of Director 1p. 14213 197. 24X
Fiche: 30-219, 82/07/23, 8208050084

8208050270 Forwards LER 82-040/017-0 Detailed event analysis encl.
FIEDLER, P. B. General Public Utilities - OPU Service Corp. 82/07/26
HAYNES, R. C. Region 1, Office of Director 3pp. 14210 112. 24X
Fiche: 30-219, 82/07/26, 8208050270.

--8208050274 LER 82-040/017-0 on 820707, signal input disconnected to safety valve vibration monitor rendering acoustic monitoring channel inoperable. Cause undetermined. Wire reconnected & alarm will be added to alarm circuit.
HARKLERDAD, R. General Public Utilities - OPU Service Corp. 82/07/26
Region 1, Office of Director 1p. 14210 115. 24X
Fiche: 30-219, 82/07/26, 8208050270.

8208060030 Forwards incident reporting sys repts re effects of fire protection sys actuation on safety-related equipment & seismic qualification of safety-related sys for transmission to NEA.
MICHELBON, C. Director's Office. 82/07/29 LAFLEUR, J. P. Office of International Programs, Director. 21pp. 14244:315. 24X
Fiche: 30-000, 82/07/29, 8208060030.

8208160034 Forwards LER 82-038/031-0 Detailed event analysis encl.
FIEDLER, P. B. General Public Utilities - OPU Service Corp. 82/08/02
HAYNES, R. C. Region 1, Office of Director 3pp. 14344:304. 24X
Fiche: 30-219, 82/08/02, 8208160034.

--8208160035 LER 82-038/031-0 on 820630, monthly surveillance of safety & relief valve backup monitoring sys (thermocouples) not performed per Tech Spec. Caused by personnel error & inadequate implementation of procedural controls.
FITZGERALD, M. J. General Public Utilities - OPU Service Corp. 82/08/02
Region 1, Office of Director 1p. 14344:307. 24X
Fiche: 30-219, 82/08/02, 8208160034

8208160174 Forwards LER 82-039/031-0 Detailed event analysis encl.
FIEDLER, P. B. General Public Utilities - OPU Service Corp. 82/08/02
HAYNES, R. C. Region 1, Office of Director 3pp. 14345 059. 24X
Fiche: 30-219, 82/08/02, 8208160174.

--8208160177 LER 82-039/031-0 on 820701, during surveillance testing, thermocouple for safety valve NR2BJ found inoperable. Caused undetermined. Adjacent acoustic monitor setpoint reduced. Thermocouple will be removed during next outage.
BOBEL, C. P. General Public Utilities - OPU Service Corp. 82/08/02
Region 1, Office of Director 1p. 14345 058. 24X
Fiche: 30-219, 82/08/02, 8208160174

8208130255 Forwards LER 82-037/017-0 Detailed event analysis encl.
FIEDLER, P. B. General Public Utilities - OPU Service Corp. 82/08/03
HAYNES, R. C. Region 1, Office of Director 3pp. 14333:007. 24X
Fiche: 30-219, 82/08/03, 8208130255.

--8208130258 LER 82-037/017-0 on 820719, procedural error identified which removed capability to automatically isolate isolation condenser as required by Tech Specs. Caused by procedural inadequacy. Procedure will be revised.
RIDDLE, E. I. General Public Utilities - OPU Service Corp. 82/08/03
Region 1, Office of Director 1p. 14333:010. 24X
Fiche: 30-219, 82/08/03, 8208130255

control
FIEDLER, P. B. General Public Utilities - OPU Service Corp. 82/07/20
HAYNES, R. C. Region 1, Office of Director 2pp. 14598:308
Fiche: 30-219, 82/08/11, 8208300055

8208190254 PND-1-82-056 on 820814, reactor shut down to clean HX & repair leaking electronic relief valve following inservice testing which indicated fouling of containment spray/emergency svc water HX
TRIPP, L. KEIMIG, R. Region 1, Office of Director 82/08/16
14388 170. 24X Fiche: 30-219, 82/08/16, 8208190254

8208260194 Forwards LER 82-042/031-0 Detailed event analysis encl.
FIEDLER, P. B. General Public Utilities - OPU Service Corp. 82/08/16
HAYNES, R. C. Region 1, Office of Director 4pp. 14554:312
Fiche: 30-219, 82/08/16, 8208260194.

--8208260199 LER 82-042/031-0 on 820716, during surveillance testing, relay 16K118 & 15K148 timers failed, preventing automatic actuation of containment spray sys II. Caused by instrument drift. Relays replaced & tested.
CUSTODIO, D. B. General Public Utilities - OPU Service Corp. 82/08/16
Region 1, Office of Director 1p. 14554:316
Fiche: 30-219, 82/08/16, 8208260194

DSCKET 30-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8208020200 Informs that submittal of analyses for compliance w/BR III Q of 10CFR50 App R will be delayed until 821001. Schedule for completion of fuse coordination study will also be submitted on 821001.
LEMPGES, T. E. Niagara Mohawk Power Corp. 82/07/22. VASSALLO, D. Operating Reactors Branch 2 1p. 14141:004. 24X
Fiche: 30-220, 82/07/22, 8208020200

8208100327 Forwards 1E Insp Rept 30-220/82-09 on 820615-18 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 82/07/23
LEMPGES, T. E. Niagara Mohawk Power Corp. 3pp. 14297:189. 24X
Fiche: 30-220, 82/07/23, 8208100327.

--8208100329 Notice of violation from insp on 820615-18.
* Division of Engineering & Technical Programs. 82/07/23.
14297:188. 24X Fiche: 30-220, 82/07/23, 8208100327.

--8208100333 1E Insp Rept 30-220/82-09 on 820615-18 Noncompliance. Failure to follow procedure re fire watch in screen & pump house where welding was being conducted.
RICHARDS, S. PADLINO, R. BECKMAN, D. Division of Engineering & Technical Programs. 82/07/23. 9pp. 14297:189. 24X
Fiche: 30-220, 82/07/23, 8208100327.

8208270496 Requests exemption from Section IV F of App E to 10CFR to waive requirement to conduct small-scale exercise during yr subsequent to 810913 full-scale exercise. Exemption requested due to work outage.
LEMPGES, T. E. Niagara Mohawk Power Corp. 82/08/20. VASSALLO, D. Operating Reactors Branch 2 2pp. 14565 059. 24X
Fiche: 30-220, 82/08/20, 8208270496.

8208270230 Forwards changes to security plan. Changes withheld (ref 10CFR2 7501).
SUNBER, J. J. Niagara Mohawk Power Corp. 82/08/23. VASSALLO, D. Operating Reactors Branch 2 1p. 14563:126. 24X
Fiche: 30-220, 82/08/23, 8208270230.

H. General correspondence

8208050053 Responds to 820705 concerns re design defects. Preliminary review of control board layout revealed potential for cord entangling critical controls. Program of design review will be implemented.
THOMPSON, H. L. Division of Human Factors Safety. 82/07/29
HIGGINS, R. Affiliation Unknown. 2pp. 14317:305. 24X
Fiche: 30-220, 82/07/29, 8208050053.

I Financial information

8208130293 Forwards Annual Financial Rept 1981 & add'l financial info.
RUSHMORE, J. W. Niagara Mohawk Power Corp. 82/08/09. BALTIMAN, Antitrust & Economic Analysis Branch (Utility Finance). 1p. 14336:271. 24X Fiche: 30-220, 82/08/09, 8208130293.

P Operating license stage documents & correspondence

8208240051 Submits action plan progress rept for Dec 1981-Mar 1982, including items discussed w/R Daer in Feb PERKINS, T. J., LEMPOES, T. E. Niagara Mohawk Power Corp. 82/05/14 HAYNES, R. C. Region 1, Office of Director 7pp. 14320.007 24X Fiche 50-220, 82/05/14, 8208240051

8208030688 Corrects Paragraph 2 of Amend 48 to License DPR-63, issued on 820609 POLK, P. J. Operating Reactors Branch 2 82/07/01 DISE, D. P. Niagara Mohawk Power Corp. 2pp. 14196.319 24X Fiche 50-220, 82/07/01, 8208030688

8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR Svc list encl DIRCKS, W. J. Office of the Executive Director for Operations. 82/07/02 Consolidated Edison Co. of New York 93pp. 14194.001. 24X Fiche 50-000, 82/07/02, 8207080064

8208050047 Approves final welding procedures & authorizes welding of replacement safe end, listed as license condition in Amend 49 to License DPR-63 VASSALLO, D. B. Operating Reactors Branch 2 82/07/20 DISE, D. P. Niagara Mohawk Power Corp. 2pp. 14244.034. 24X Fiche 50-220, 82/07/20, 8208050047

8208040574 Requests submittal of documents explaining util satisfaction of NUREC-0737, Item II B 3 criterion re post-accident sampling sys Guidelines encl VASSALLO, D. B. Operating Reactors Branch 2 82/07/26 DISE, D. P. Niagara Mohawk Power Corp. 10pp. 14223.346 24X Fiche 50-220, 82/07/26, 8208040574

8208040216 Concludes that commitments & exceptions to requirements of Reg Guide 1.5B, Revision 1 & Reg Guide 1.146 re qualification of insp & audit personnel acceptable. Review of 820301 response to Generic Ltr 81-01 complete VASSALLO, D. B. Operating Reactors Branch 2 82/07/28 DISE, D. P. Niagara Mohawk Power Corp. 2pp. 14232.278 24X Fiche 50-220, 82/07/28, 8208040216

8208130115 SOCIOECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS: NINE MILE PLANT AND FITZPATRICK CASE STUDY. Docket Nos. 50-220, 50-410 & 50-333 (Niagara Mohawk Power Corporation And Power Authority Of The State of New York) BRANCH, K. J., MEALE, R. Mountain West Research, Inc. * Social Impact Research, Inc. FIN 8-1268 NUREC/CR-2749 V06 82/07/31. Division of Health, Siting & Environment 287pp. Available at NTIS. \$8.00 14341.001 24X Fiche 50-000, 82/07/31, 8208130115

8208050470 Forwards addl info re control of heavy loads in response to 801222 request. Heavy loads handled w/reactor bldg crane main hoist & lifting devices Load lift points required by NUREC-0612 provided LEMPOES, T. E. Niagara Mohawk Power Corp. 82/08/01 EISENHUT, D. O. Division of Licensing 35pp. 14214.123. 24X Fiche 50-220, 82/08/01, 8208050470

8208090047 Informs that interim dose assessment sys will not be operational by 820731 due to electrical problems w/computer hardware. Problems should be corrected within 2 wks. LEMPOES, T. E. Niagara Mohawk Power Corp. 82/08/03 EISENHUT, D. O. Division of Licensing 1p. 14270.034. 24X Fiche 50-220, 82/08/03, 8208090047

8208130195 Confirms previous verbal communication w/NRC re replacement of all 28-inch recirculation sys piping Methodology being developed. Revised occupational dose estimate will be submitted w/next quarterly repair program status rept. LEMPOES, T. E. Niagara Mohawk Power Corp. 82/08/06 EISENHUT, D. O. Division of Licensing 11pp. 14339.147. 24X Fiche 50-220, 82/08/06, 8208130195

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter 1 requirements & provides alternatives to requirements. Svc list encl. EISENHUT, D. O. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14336.332 24X Fiche 50-000, 82/08/09, 8208090194

8208200042 Advises that equipment & procedures utilized for in-plant iodine measurements are in place & consistent w/NUREC-0737, Item II D.3.3 technical guidance. MANGAN, C. V. Niagara Mohawk Power Corp. 82/08/16 VASSALLO, D. B. Operating Reactors Branch 2. 1p. 14392.250. 24X Fiche 50-220, 82/08/16, 8208200042

8208200049 Submits addl info supplementing 820806 ltr re preliminary plans for replacing all 28-inch recirculation sys piping ALARA program will be utilized for mitigating worker radiation doses during piping replacement MANGAN, C. V. Niagara Mohawk Power Corp. 82/08/16 EISENHUT, D. O. Division of Licensing 7pp. 14392.187 24X Fiche 50-220, 82/08/16, 8208200049

8208250197 Informs that schedule for providing addl info re NUREC-0737, Item II B 3 on post-accident sampling will be provided by 821203, per 820726 request MANGAN, C. V. Niagara Mohawk Power Corp. 82/08/18 VASSALLO, D. B. Operating Reactors Branch 2. 1p. 14540.280 24X Fiche 50-220, 82/08/18, 8208250197

8208270399 Revises 820707 implementation schedule for operational dose assessment sys, due to delays in obtaining design info from equipment vendor Hardware & software operational by 830301. Inland pole & associated equipment operational by 830701 LEMPOES, T. E. Niagara Mohawk Power Corp. 82/08/20 EISENHUT, D. O. Division of Licensing 2pp. 14363.116 24X Fiche 50-220, 82/08/20, 8208270399

Q Inspection reports, IE Bulletins & correspondence

8208160032 Forwards waste handling procedures, fulfilling commitment to IE Bulletin 79-19. GERBER, C. A. Niagara Mohawk Power Corp. 81/04/17 DAER, R. Region 1, Philadelphia, Office of the Director (81/03/01) 2pp. 14343.010 24X Fiche 50-220, 81/04/17, 8208160032

--8208160037 Waste Handling Procedure N1-WHP-8, "Van Shipment Preparation Procedure" * Niagara Mohawk Power Corp. 81/04/06 11pp. 14345.012. 24X Fiche 50-220, 81/04/17, 8208160032

--8208160039 Waste Handling Procedure N1-WHP-9, "Solidification Procedure" * Niagara Mohawk Power Corp. 81/04/06 3pp. 14345.023 24X Fiche 50-220, 81/04/17, 8208160032

--8208160042 Waste Handling Procedure N1-WHP-11, "Process Control Procedure" * Niagara Mohawk Power Corp. 81/04/06 3pp. 14345.026 24X Fiche 50-220, 81/04/17, 8208160032

--8208160045 Waste Handling Procedure N1-WHP-12, "Solid Dry Waste Collection & Compaction" * Niagara Mohawk Power Corp. 81/04/02 9pp. 14345.029. 24X Fiche 50-220, 81/04/17, 8208160032

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage" Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16 Consolidated Edison Co. of New York. 87pp. 14356.274 24X Fiche 50-000, 82/07/16, 8204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19, Michigan Univ of 112pp. 14358.001. 24X Fiche 50-000, 82/07/19, 8204210395

8208020370 Forwards IE Insp Rept 50-220/82-10 on 820621-25 & notice of violation. Response to 820619 mislocation of cutting operation for safe-end replacement program requested. MARTIN, T. T. Division of Engineering & Technical Programs. 82/07/19, LEMPOES, T. E. Niagara Mohawk Power Corp. 2pp. 14150.100. 24X Fiche 50-220, 82/07/19, 8208020370

--8208020374 Notice of violation from insp on 820621-25 * Division of Engineering & Technical Programs. 82/07/19. 1p. 14150.102. 24X Fiche 50-220, 82/07/19, 8208020370

--8208020378 IE Insp Rept 50-220/82-10 on 820621-25. Noncompliance noted: failure to obtain Site Operations Review Committee approval for safe-end replacement program procedures. EAPEN, P. K., CAPTON, D. L. Division of Engineering & Technical Programs. 82/07/13. 6pp. 14150.103. 24X Fiche 50-220, 82/07/19, 8208020370

8204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure" Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20, Consolidated Edison Co. of New York. 112pp. 14381.001. 24X Fiche 50-000, 82/07/20, 8204210396

82/07/20 Consolidated Edison Co. of New York. 71pp 14357-276
24X Fiche: 50-000, 82/07/20, 8204210397.

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/22.
Consolidated Edison Co. of New York. 112pp. 14194-321 24X
Fiche: 50-000, 82/07/22, 8204210398

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23.
Consolidated Edison Co. of New York. 122pp. 14380-115. 24X
Fiche: 50-000, 82/07/23, 8204210401

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHRs." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23.
Consolidated Edison Co. of New York. 127pp. 14194-120 24X
Fiche: 50-000, 82/07/23, 8204210402

8208100327 Forwards IE Insp Rept 50-220/82-09 on 820615-18 & notice of violation
HARTMAN, T. T. Division of Engineering & Technical Programs 82/07/23.
LEMPQES, T. E. Niagara Mohawk Power Corp. 3pp. 14297-183 24X
Fiche: 50-220, 82/07/23, 8208100327.

--8208100329 Notice of violation from Insp on 820615-18
* Division of Engineering & Technical Programs 82/07/23 1p.
14297-188 24X Fiche: 50-220, 82/07/23, 8208100327

--8208100333 IE Insp Rept 50-220/82-09 on 820615-18 Noncompliance noted
Failure to follow procedure re fire watch in screen & pump house where welding was being conducted
RICHARDS, S., PAOLINO, R., BECKMAN, D. Division of Engineering & Technical Programs. 82/07/23 9pp. 14297-189. 24X
Fiche: 50-220, 82/07/23, 8208100327.

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PHR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26.
Consolidated Edison Co. of New York. 121pp. 14357-013 24X
Fiche: 50-000, 82/07/26, 8204210403.

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28.
Consolidated Edison Co. of New York. 122pp. 14357-146 24X
Fiche: 50-000, 82/07/28, 8204210405

8208050436 Forwards addl info re inservice insp program in response to NRC 820414 ltr.
LEMPQES, T. E. Niagara Mohawk Power Corp. 82/07/30. VASSALLO, D. B.
Operating Reactors Branch 2 18pp 14218-030. 24X
Fiche: 50-220, 82/07/30, 8208050436.

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/05
Consolidated Edison Co. of New York. 117pp. 14389-201. 24X
Fiche: 50-000, 82/08/05, 8204210407

R. Periodic operating reports & related correspondence

8208270010 Response to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A.
Critical Mass Energy Project. 8pp. 14679-208. 24X
Fiche: 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given 82/07/13. 48pp.
14679-216. 24X Fiche: 50-000, 82/07/13, 8208270010.

--8208270579 Forwards "Personnel Whole Body Exposures for CY81," per IOCFR20.407.
LEMPQES, T. E. Niagara Mohawk Power Corp. 82/05/06. Office of Resource Management, Director. 1p. 14680-079. 24X
Fiche: 50-000, 82/07/13, 8208270010.

--8208270583 "Personnel Whole Body Exposures for CY81."
* Niagara Mohawk Power Corp. 82/05/06. 23pp. 14680-080. 24X
Fiche: 50-000, 82/07/13, 8208270010.

82/08/09, 8208160448

--8208160455 Monthly operating rept for Jul 1982
ROMAN, T. W. Niagara Mohawk Power Corp. 82/08/04 4pp 14349-263
24X Fiche: 50-220, 82/08/09, 8208160448

S. Reportable occurrences, LERs & related correspondence

8208200104 Forwards LER 82-011/03L-0
LEMPQES, T. E. Niagara Mohawk Power Corp. 82/08/07. HAYNES, R. C.
Region 1, Office of Director. 1p 14393-047 24X
Fiche: 50-220, 82/08/09, 8208200104

--8208200112 LER 82-011/03L-0 on 820802, oil leak on fuel oil supply manifold discovered on diesel fire pump. Caused by defective brake joint. Leak repaired by manufacturer.
GALAZZO, S. Niagara Mohawk Power Corp. 82/08/05. Region 1, Office of Director. 1p 14393-048 24X Fiche: 50-220, 82/08/09, 8208200104

8208180064 PND-I-82-031A continuing nondestructive exams (ultrasonic & dye penetrant tests) of circumferential welds in 28-inch diameter reactor recirculation sys piping disclosed indications in 31 of 37 welds tested
KISTER, H., BRUNNER, E. Region 1, Office of Director. 82/08/12. 1p. 14379-276 24X Fiche: 50-220, 82/08/12, 8208180064

8208230299 Forwards updated LER 82-009/01X-1
LEMPQES, T. E. Niagara Mohawk Power Corp. 82/08/12. HAYNES, R. C.
Region 1, Office of Director. 1p 14509-341. 24X
Fiche: 50-220, 82/08/12, 8208230299.

--8208230304 Updated LER 82-009/01X-1 on 820323, water observed leaking from insulation on recirculation piping discharges 11 & 15 from reactor vessel. Caused by cracking in riser elbow welds. Recirculation piping replaced
GALAZZO, S. Niagara Mohawk Power Corp. 82/08/11. Region 1, Office of Director. 2pp 14509-342 24X Fiche: 50-220, 82/08/12, 8208230299.

DOCKET 50-223 UNIV. OF LOWELL RESEARCH REACTOR

Q. Inspection reports, IE Bulletins & correspondence

8208300236 Forwards IE Insp Rept 50-223/82-01 on 820616 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs. 82/08/11
BECHIAN, L. E. Lowell, Univ. of. 2pp. 14679-163 24X
Fiche: 50-223, 82/08/11, 8208300236

--8208300241 Notice of violation from Insp on 820616
STAROSTECKI, R. Division of Project & Resident Programs. 82/08/11.
2pp. 14679-167. 24X Fiche: 50-223, 82/08/11, 8208300236.

--8208300250 IE Insp Rept 50-223/82-01 on 820616 Noncompliance noted: failure to have procedures for opening, receipt & handling of Model GE-1500 shipping casks containing Co-60 matl.
KINNEY, W. W., ROTH, J., GREENMAN, E. G. Division of Project & Resident Programs. 82/08/10 7pp. 14679-169. 24X Fiche: 50-223, 82/08/11, 8208300236.

DOCKET 50-225 RPI CRITICAL EXPERIMENT

Q. Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19.
Michigan, Univ. of. 112pp. 14358-001. 24X Fiche: 50-000, 82/07/19, 8204210395.

DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR

R. Periodic operating reports & related correspondence

8208030889 Forwards annual summary of changes, tests & experiments performed at Aerotest Radiography & Research Reactor for period ending 820630.
HASKINS, J. J. Aerotest Operations. 82/07/21. STERNBERG, D. M.
Division of Resident, Reactor Project & Engineering Programs. 1p. 14160-200. 24X Fiche: 50-228, 82/07/21, 8208030889.

--8208030598 Annual summary of changes, tests & experiments performed at Aerotest Radiography & Research Reactor for period ending 820630
HASKINS, J. J., NEWACHECK, R. L. Aerotest Operations 82/07/21 4pp.
14160 201 24X Fiche 50-000.82/07/21.8208030598

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8208040353 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records 82/07/13 Document
Management Branch. 1p 14223 161 24X Fiche 50-010.82/07/13.
8208040353

--8208040358 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-CB. "Rad/Chem Director" Receipt Form, procedure history & safety evaluation encl.
SCOTT, D. J. Commonwealth Edison Co 82/07/02 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp 14223 162 24X
Fiche 50-010.82/07/13.8208040353

--8208040361 Public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-CB. "Rad/Chem Director" Revised index of station group director duties encl.
Commonwealth Edison Co 82/06/30 5pp 14223 165. 24X
Fiche 50-010.82/07/13.8208040353

8208040473 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records 82/07/22 Document
Management Branch. 1p 14220 294 24X Fiche 50-010.82/07/22.
8208040473.

--8208040479 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-C7. "Security Director" & Revision 0 to EPIP 500-9. "Operational Check of Notification Phone List." Receipt Form encl.
SCOTT, D. J. Commonwealth Edison Co 82/07/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 5pp. 14220 295. 24X
Fiche 50-010.82/07/22.8208040473

--8208040483 Public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-C7. "Security Director" & Revision 0 to EPIP 500-9. "Operational Check of Notification Phone List."
Commonwealth Edison Co 82/07/07. 6pp. 14220 300. 24X
Fiche 50-010.82/07/22.8208040473.

8208270134 Forwards IE Insp Repts 50-010/82-11.50-237/82-19 & 50-249/82-16 on 820624.29.30 & 0709 & notice of significant test deficiency
HIND, J. A. Division of Emergency Preparedness & Operational Support. 82/08/03 REED, C. Commonwealth Edison Co 3pp. 14563.338. 24X
Fiche 50-010.82/08/03.8208270134

--8208270142 IE Insp Repts 50-010/82-11.50-237/82-19 & 50-249/82-16 on 820624.29.30 & 0709 Significant test deficiency noted:
failure of seven prompt public notification sys sirens.
JANUSKA, A. G., SMITH, M. J., PATTERSON, J. P. Division of Emergency Preparedness & Operational Support. 82/07/23. 12pp 14563.341.
24X Fiche 50-010.82/08/03.8208270134.

8208250559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures."
FELTON, J. M. Division of Rules and Records. 82/08/12. Document
Management Branch. 1p. 14559 334 24X Fiche: 50-000.82/08/12.
8208250559

--8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures."
MOORE, R. D. Commonwealth Edison Co. 82/07/19. DENTON, H. R. NRC - No Detailed Affiliation Given. 1p 14559.335. 24X
Fiche: 50-000.82/08/12.8208250559

--8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures."
Commonwealth Edison Co. 82/06/30. 7pp. 14559.356. 24X
Fiche: 50-000.82/08/12.8208250559.

8208230107 Forwards revised cable discrepancy lists re fire protection safe shutdown analyses Lists indicate how each discrepancy noted in fire protection associated circuit analysis & mod repts will be resolved.
RAUSCH, T. J. Commonwealth Edison Co. 82/08/13. EIBENHUT, D. O. Division of Licensing. 2pp. 14513.001. 24X Fiche: 50-000.82/08/13.
8208230107.

--8208230113 "Fire Protection Cable Discrepancy List, Dresden Unit 2."
Commonwealth Edison Co. 82/08/03. 123pp 14513.003. 24X
Fiche 50-000.82/08/13.8208230107.

--8208230119 "Fire Protection Cable Discrepancy List, Dresden Unit 3."
Commonwealth Edison Co. 82/08/04. 150pp 14515.144. 24X
Fiche: 50-000.82/08/13.8208230107

--8208230122 "Fire Protection Cable Discrepancy List, Quad Cities Unit 1."
Commonwealth Edison Co. 82/08/06. 250pp. 14515 293 24X
Fiche 50-000.82/08/13.8208230107

--8208230130 "Fire Protection Cable Discrepancy List, Quad Cities Unit 2."
Commonwealth Edison Co. 82/08/02. 250pp. 14516 216 24X
Fiche 50-000.82/08/13.8208230107

0 Adjudicatory correspondence

8208190125 Final initial decision ordering NRR issue license amend authorizing installation of 33 high density storage racks in each spent fuel pool
WOLFE, J. F., REMICK, F. J., LITTLE, L. W. Atomic Safety and Licensing Board Panel. 82/08/17 29pp 14301 043 24X Fiche 50-237.
82/08/17.8208190125

8208240267 Response to ABLB 820728 order. Requests leave to withdraw application w/o prejudice. Need for transshipment in near-term reduced due to approval of installation of high density spent fuel racks Certificate of Bvc encl.
STEPHENS, P. Commonwealth Edison Co. STEPHENS, P. Isham, Lincoln & Deale. 82/08/18. Atomic Safety and Licensing Board Panel. 6pp.
14527.120. 24X Fiche 50-000.82/08/18.8208240267

8208240233 Notice of ABLAB constitution. AS Rosenthal, chairman & TB Moore & RL Gotchy, members.
SHENKNER, C. J. Atomic Safety and Licensing Appeal Panel. 82/08/20.
1p 14319 148. 24X Fiche: 50-237.82/08/20.8208240233.

8208240265 Response to ABLB 820728 order. NRC does not object to proceeding termination since licensee has moved to withdraw license application w/o prejudice. due to decision in Dresden high density storage rack case. W/Certificate of Bvc.
WRIGHT, N. A. Hearing Branch 2. 82/08/20. Atomic Safety and Licensing Board Panel. 3pp. 14527.126. 24X Fiche: 50-000.82/08/20.
8208240265.

P. Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR. Svc list encl.
DIRCKB, M. J. Office of the Executive Director for Operations. 82/07/02. Consolidated Edison Co. of New York. 93pp. 14194.001.
24X Fiche: 50-000.82/07/02.8207080064.

8208030057 Forwards request for addl info re TMI Item II. D. 1. "Performance Testing of BWR & PWR Safety/Relief Valves." Applicability of generic results reported in NEDE-2498B-P must be demonstrated for specific valves at facility.
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/27. DELCORQUE, L. Commonwealth Edison Co. 5pp. 14244.047. 24X Fiche: 50-237.82/07/27.
8208030057.

8208180266 Forwards revised version of model Tech Specs for reactor protection sys/power monitoring sys design.
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/28. DELCORQUE, L. Commonwealth Edison Co. 3pp. 14389.318. 24X Fiche: 50-000.82/07/28.
8208180266.

--8208180271 Revised model Tech Specs re electric power monitoring of reactor protection sys design.
Operating Reactors Branch 2. 82/07/28. 1p. 14389.321. 24X
Fiche: 50-000.82/07/28.8208180266

8208030254 Comments on SEP in response to 820714 request. Few deviations identified between design criteria used for Phase I/II plants vs current criteria
DELCORQUE, L. O. Commonwealth Edison Co. 82/07/29. CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 14158.227. 24X
Fiche: 50-010.82/07/29.8208030254

8208060268 Forwards comments on design codes, design criteria & loading combinations per BEP Topic III-7. B. Sargent & Lundy input to 820513 NCT Engineering rept encl.
RAUSCH, T. J. Commonwealth Edison Co. 82/08/02. O'CONNOR, P. W. Operating Reactors Branch 5. 13pp. 14241.160. 24X
Fiche: 50-237.82/08/02.8208060268.

B20B110041 Forwards response to request to cross-ref info re environ qualification of safety-related equipment & TMI action plan equipment
SWARTZ, E. D. Commonwealth Edison Co. 82/08/02. EISENHUT, D. O. Division of Licensing. 557pp. 14315 001. 24X Fiche: 50-000. 82/08/02. B20B110041

B20B130046 Requests approval to delay implementation of commitments in response to Generic Ltr 82-05 re NUREG-0737, Item 11 F. 1.8. "Containment Hydrogen Monitor." Completion postponed until 840101 to accommodate schedule requirements
SWARTZ, E. D. Commonwealth Edison Co. 82/08/05. EISENHUT, D. O. Division of Licensing. 2pp. 14335 333. 24X Fiche: 50-000. 82/08/05. B20B130046

B20B110188 Forwards revised pages to CE-1-A. "Com Ed GA Program for Nuclear Generating Stations." Revision 21 Revised pages correct typographical & other minor errors.
SWARTZ, E. D. Commonwealth Edison Co. 82/08/06. HAASS, W. P. Quality Assurance Branch. 1p. 14314 079. 24X Fiche: 50-000. 82/08/06. B20B110188

--B20B110204 Revised pages to CE-1-A, Revision 21. "Com Ed GA Program for Nuclear Generating Stations."
* Commonwealth Edison Co. 82/08/06. 11pp. 14314 080. 24X Fiche: 50-000. 82/08/06. B20B110188

B20B240464 Requests appropriate action be taken re acceptable vent sys for isolation condenser per hydrogen rule & NUREG-0737 guidance (TMI Item II B. 1) or exemptions from applicable provisions of 10CFR50.44 should be requested
VASSALLO, D. B. Operating Reactors Branch 2. 82/08/06. DELOERGE, L. Commonwealth Edison Co. 3pp. 14544 170. 24X Fiche: 50-237. 82/08/06. B20B240464

B20B090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter 1 requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D. O. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14356 332. 24X Fiche: 50-000. 82/08/09. B20B090194

B20B170135 Responds to NRC 820721 request to provide notification if util intends to deviate from NUREG-0737, Item III. D. 3.3. "Improved In-Plant Iodine Instrumentation Under Accident Conditions." Both facilities comply w/requirement.
SWARTZ, E. D. Commonwealth Edison Co. 82/08/12. EISENHUT, D. O. Division of Licensing. 2pp. 14365 211. 24X Fiche: 50-000. 82/08/12. B20B170135

B20B230352 Forwards aperture card print of listed electrical schematics of reactor protection sys. per NRC request info needed to perform probabilistic risk assessment. W/o encl.
RAUSCH, T. J. Commonwealth Edison Co. 82/08/13. O'CONNOR, P. Operating Reactors Branch 5. 1p. 14508 276. 24X Fiche: 50-237. 82/08/13. B20B230352

B20B230349 Forwards revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of previously submitted inservice insp & testing program for second 10 yrs. Revision necessary to enable insp of LPCI/CCBW HX tube welds
RAUSCH, T. J. Commonwealth Edison Co. 82/08/16. EISENHUT, D. O. Division of Licensing. 2pp. 14512 337. 24X Fiche: 50-237. 82/08/16. B20B230349

--B20B230359 Revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of inservice insp & testing program for second 10 years.
* Commonwealth Edison Co. 82/08/16. 3pp. 14512 339. 24X Fiche: 50-237. 82/08/16. B20B230349

B20B240398 Forwards NRC responses to util 820406 comments on evaluation of BEP Topics VI-2. D & VI-3 Revised Table 4 to 820610 evaluation encl. Evaluation final & will be used as basic input to integrated safety assessment
O'CONNOR, P. Operating Reactors Branch 5. 82/08/19. DELOERGE, L. Commonwealth Edison Co. 8pp. 14524 203. 24X Fiche: 50-237. 82/08/19. B20B240398

B20B270250 Application for amend to License DPR-29, proposing Tech Spec changes to implement 10CFR50.59 reload licensing w/DDYN transient analyses & extended exposure MAPLHGR limits. Significant changes discussed. Class III amend fee encl.
RAUSCH, T. J. Commonwealth Edison Co. 82/08/19. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 5pp. 14564 001. 24X Fiche: 50-000. 82/08/19. B20B270250

--B20B270273 Errata & Addenda Sheet 7, replacing Pages 4-11 & 4-14 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations."
* General Electric Co. NEDO-24246A ERR 07. 82/07/31. 5pp. 14564 026. 24X Fiche: 50-000. 82/08/19. B20B270250

B20B290147 Forwards safety evaluation addressing open items in 820117 draft safety evaluation of BEP Topic III-5 B. "Pipe Break Outside Containment." Facility adequately protected from pipe break effects, subj to listed resolution.
O'CONNOR, P. W. Operating Reactors Branch 5. 82/08/20. DELOERGE, L. Commonwealth Edison Co. 17pp. 14540 313. 24X Fiche: 50-237. 82/08/20. B20B290147

B20B270468 Forwards final safety evaluation of util 820617 assessment of BEP Topic II. 1 C re potential hazards due to nearby transportation, institutional, industrial & military facilities. Facility adequately protected
O'CONNOR, P. Operating Reactors Branch 5. 82/08/20. DELOERGE, L. Commonwealth Edison Co. 25pp. 14965 298. 24X Fiche: 50-237. 82/08/20. B20B270468

B20B310230 Application for amend to Licenses DPR-19 & DPR-25 re installation & use of high density fuel storage racks
RAUSCH, T. J. Commonwealth Edison Co. 82/08/26. EISENHUT, D. O. Division of Licensing. 2pp. 14695 115. 24X Fiche: 50-237. 82/08/26. B20B310230

G Inspection reports, IE Bulletins & correspondence

B20B050414 Forwards IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-299/81-31 & 50-304/81-29 on 810813-820503. No noncompliance noted.
KEPPLER, J. O. Region 3, Office of Director. 82/07/12. REED, C. Commonwealth Edison Co. 1p. 14217 166. 24X Fiche: 50-000. 82/07/12. B20B050414

--B20B050441 IE Insp Repts 50-237/81-37, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-299/81-31 & 50-304/81-29 on 810813-820503. No noncompliance noted. Major areas inspected allegations re Comm Ed operation of facilities & compliance w/10CFR21.
HAYES, D. W., PHILLIP, O. A., HINDS, J. M. Division of Project & Resident Programs. 82/07/09. 15pp. 14217 169. 24X Fiche: 50-000. 82/07/12. B20B050414

B204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16. Consolidated Edison Co. of New York. 87pp. 14356 274. 24X Fiche: 50-000. 82/07/16. B204210393

B204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of. 112pp. 14358 001. 24X Fiche: 50-000. 82/07/19. B204210395

B20B050393 Forwards IE Insp Repts 50-010/82-06, 50-237/82-10 & 50-249/82-11 on 820507-0604 & notice of violation
BPESSARD, R. L. Division of Project & Resident Programs. 82/07/19. REED, C. Commonwealth Edison Co. 2pp. 14209 191. 24X Fiche: 50-010. 82/07/19. B20B050393

--B20B050390 Notice of violation from insp on 820507-0604.
* Division of Project & Resident Programs. 82/07/19. 2pp. 14209 193. 24X Fiche: 50-010. 82/07/19. B20B050393

--B20B050403 IE Insp Repts 50-010/82-06, 50-237/82-10 & 50-249/82-11 on 820507-0604. Noncompliance noted. Failure to follow hose color code.
TONQUE, T. M., JORDAN, M. J., WALKER, R. D. Division of Project & Resident Programs. 82/07/11. 9pp. 14209 199. 24X Fiche: 50-010. 82/07/19. B20B050393

B204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp. 14381 001. 24X Fiche: 50-000. 82/07/20. B204210396

B204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20. Consolidated Edison Co. of New York. 71pp. 14357 276. 24X Fiche: 50-000. 82/07/20. B204210397

B204210398 IE Info Notice 82-26, "RCIC & LPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22. Consolidated Edison Co. of New York. 112pp. 14194 321. 24X Fiche: 50-000. 82/07/22. B204210398

B204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 122pp. 14380 115. 24X Fiche: 50-000. 82/07/23. B204210401

DOCKETED ITEMS

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co. of New York 127pp. 14194 120 24X
Fiche: 50-000, 82/07/23, 8204210402

8208100289 Forwards IE Insp Repts 50-010/82-09, 50-237/82-13 & 50-249/82-14 on 820616-17 & 21-25 No noncompliance noted
MILLER, J. R. Division of Engineering & Technical Programs 82/07/23
REED, C. Commonwealth Edison Co. 2pp 14294 191 24X
Fiche: 50-010, 82/07/23, 8208100289

--8208100299 IE Insp Repts 50-010/82-09, 50-237/82-13 & 50-249/82-14 on 820616-17 & 21-25 No noncompliance noted. Major areas inspected: action on previous findings, open items & hydrogen gas addition into reactor feedwater sys.
PAUL, R. A., GREGER, L. R. Division of Engineering & Technical Programs 82/07/22 7pp. 14294 193 24X Fiche: 50-010, 82/07/23, 8208100289

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26
Consolidated Edison Co. of New York 121pp. 14397 013 24X
Fiche: 50-000, 82/07/26, 8204210403

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28
Consolidated Edison Co. of New York 122pp 14397 146 24X
Fiche: 50-000, 82/07/28, 8204210405

8208270134 Forwards IE Insp Repts 50-010/82-11, 50-237/82-15 & 50-249/82-16 on 820624, 29, 30 & 0709 Significant test deficiency noted: failure of seven prompt notification sys sirens
HIND, J. A. Division of Emergency Preparedness & Operational Support 82/08/03 REED, C. Commonwealth Edison Co. 3pp 14563 330 24X
Fiche: 50-010, 82/08/03, 8208270134

--8208270142 IE Insp Repts 50-010/82-11, 50-237/82-15 & 50-249/82-16 on 820624, 29, 30 & 0709 Significant test deficiency noted: failure of seven prompt notification sys sirens
JANUSKA, A. G., GRANT, W. B., NICHOLSON, N. A. Division of Emergency Preparedness & Operational Support 82/07/23 12pp. 14563 341 24X Fiche: 50-010, 82/08/03, 8208270134

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/03
Consolidated Edison Co. of New York 117pp 14308 201 24X
Fiche: 50-000, 82/08/03, 8204210407

8208200241 Advises of error in NRC 820719 ltr transmitting IE Insp Repts 50-010/82-06, 50-237/82-10 & 50-249/82-11. Page 2 should be replaced w/encl page.
SPESBARD, R. L. Division of Project & Resident Programs 82/08/13
REED, C. Commonwealth Edison Co. 2pp 14399 031 24X
Fiche: 50-010, 82/08/13, 8208200241

8208230349 Forwards revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of previously submitted inservice insp & testing program for second 10 yrs. Revision necessary to enable insp of LPCI/CCSW HK tube welds
RAUSCH, T. J. Commonwealth Edison Co. 82/08/16 EISENHUT, D. O. Division of Licensing 2pp 14312 357 24X Fiche: 50-237, 82/08/16, 8208230349

--8208230359 Revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of inservice insp & testing program for second 10 years.
Commonwealth Edison Co. 82/08/16 3pp 14312 359 24X
Fiche: 50-237, 82/08/16, 8208230349

8208310212 Forwards final response to IE Bulletin 80-06, "EBF Reset Controls." Testing of listed mods performed after installation & specifically demonstrated equipment will not reposition from emergency position w/initial signal reset.
SHARTZ, E. D. Commonwealth Edison Co. 82/08/20 KEPLER, J. O. Region 3, Office of Director. 5pp. 14693 148 24X Fiche: 50-237, 82/08/20, 8208310212

8208310218 Forwards suppl to util 820526 response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)." SHARTZ, E. D. Commonwealth Edison Co. 82/08/23 KEPLER, J. O. Region 3, Office of Director. 9pp 14693 130 24X Fiche: 50-010, 82/08/23, 8208310218

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records 82/07/13 UDELL, R. A. Critical Mass Energy Project. 8pp 14679 208 24X
Fiche: 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given 82/07/13 48pp. 14679 216 24X Fiche: 50-000, 82/07/13, 8208270010

--8208270599 Forwards "Recorded Annual Whole Body External Exposure for CY81." per 10CFR20 407(b). W/o Quad Cities, Zion, LaSalle, Byron & Braidwood repts.
RAUSCH, T. J. Commonwealth Edison Co. 82/03/31 Office of Management and Program Analysis 1p. 14680 075 24X
Fiche: 50-000, 82/07/13, 8208270010

--8208270567 "Recorded Annual Whole Body External Exposure for CY81."
* Commonwealth Edison Co. 82/03/31 1p 14680 076 24X
Fiche: 50-000, 82/07/13, 8208270010

8208170242 Forwards monthly operating repts for Jul 1982.
SCOTT, D. J. Commonwealth Edison Co. 82/08/01 Director's Office, Office of Inspection and Enforcement 1p 14369 228 24X
Fiche: 50-010, 82/08/01, 8208170242

--8208170245 Monthly operating repts for Jul 1982
BCHROEDER, B. A. Commonwealth Edison Co. 82/08/01 18pp 14369 229 24X Fiche: 50-010, 82/08/01, 8208170242

S Reportable occurrences, LERs & related correspondence

8208130055 Forwards updated LER 82-014/03X-1.
SCOTT, D. J. Commonwealth Edison Co. 82/07/07. KEPLER, J. O. Region 3, Office of Director. 1p 14336 001 24X Fiche: 50-237, 82/07/07, 8208130055

--8208130063 Updated LER 82-014/03X-1 on 820502, radwaste sump pumps started & floor drain collector tank level rose. Caused by small corrosion-related crack in line 2/3-20340, 2.9-inch diameter pipe. Line taken out of svc for repairs.
ANANDAPPA, T. Commonwealth Edison Co. 82/07/07. Region 3, Office of Director. 2pp 14336 002 24X Fiche: 50-237, 82/07/07, 8208130055

8208130052 Forwards updated LER 81-055/03X-1
SCOTT, D. J. Commonwealth Edison Co. 82/07/08. KEPLER, J. O. Region 3, Office of Director. 1p. 14339 360 24X Fiche: 50-237, 82/07/08, 8208130052

--8208130057 Updated LER 81-055/03X-1 on 810830, small leak detected in floor drain discharge line. Caused by butt weld failure on line 2/3-2014 6-inch carbon steel pipe, weakened by corrosive solutions. Affected pipe section replaced.
ANANDAPPA, A. Commonwealth Edison Co. 82/07/08. Region 3, Office of Director. 2pp 14339 361 24X Fiche: 50-237, 82/07/08, 8208130052

8208020184 Forwards LER 82-030/01T-0
SCOTT, D. J. Commonwealth Edison Co. 82/07/20 KEPLER, J. O. Region 3, Office of Director. 1p. 14141 037 24X Fiche: 50-237, 82/07/20, 8208020184

--8208020186 LER 82-030/01T-0 on 820712, during HPCI motor operated valve operability test, steam supply isolation valve 2301-04 failed to close. Caused by valve packing leak. Valve repacked & motor replaced.
ANANDAPPA, A. Commonwealth Edison Co. 82/07/23. Region 3, Office of Director. 3pp. 14141 038 24X Fiche: 50-237, 82/07/20, 8208020184

8208090242 Forwards LER 82-026/03L-0 Detailed event analysis encl.
SCOTT, D. J. Commonwealth Edison Co. 82/07/20. KEPLER, J. O. Region 3, Office of Director. 2pp. 14271 088 24X Fiche: 50-237, 82/07/20, 8208090242

--8208090245 LER 82-026/03L-0 on 820701, M02-1501-5C failed to close & breaker tripped. Caused by stuck closed contact in reversing contactor causing short circuit & tripped breaker. Contactor replaced & valve successfully cycled.
COYLE, L. Commonwealth Edison Co. 82/07/20. Region 3, Office of Director. 1p. 14271 090 24X Fiche: 50-237, 82/07/20, 8208090242

B208030338 Forwards LER 82-024/03L-0.
SCOTT, D. J. Commonwealth Edison Co. 82/07/21. KEPLER, J. O. Region
3. Office of Director. 1p 14157 037 24X Fiche 50-237, 82/07/21.
B208030338

--B208030340 LER 82-024/03L-0 on B20629, drywell to torus differential
pressure dropped to 0.94 psid when HPCI steam supply
isolation valve MO 2-2301-4 was automatically closed. Caused
by packing leak on valve Valve repacked.
ANANDAPPA, A. Commonwealth Edison Co. 82/07/23 Region 3.
Office of Director. 2pp 14157 038. 24X Fiche 50-237, 82/07/21.
B208030338

B208090228 Forwards LER 82-025/03L-0 Detailed event analysis encl
SCOTT, D. J. Commonwealth Edison Co. 82/07/21. KEPLER, J. O. Region
3. Office of Director. 2pp 14271 100. 24X Fiche 50-237, 82/07/21.
B208090228.

--B208090230 LER 82-025/03L-0 on B20701, during testing, LPCI suction valve
MO-2-1501-50 failed to open electrically. Caused by dirty
auxiliary contact in breaker. Contact cleaned
COYLE, L. M. Commonwealth Edison Co. 82/07/22 Region 3. Office
of Director. 1p. 14271. 102. 24X Fiche 50-237, 82/07/21.
B208090228.

B208130269 Forwards LER 82-028/03L-0
SCOTT, D. J. Commonwealth Edison Co. 82/08/05 KEPLER, J. O. Region
3. Office of Director. 1p. 14333 072. 24X Fiche 50-237, 82/08/05.
B208130269.

--B208130272 LER 82-028/03L-0 on B20708, during normal operation
w/isolation condenser valve operability test in progress,
valve MO2-1301-10 failed to close. Caused by bent auxiliary
contact in motor control ctr. Contact repaired
COYLE, L. M. Commonwealth Edison Co. 82/08/05 Region 3. Office of
Director. 2pp. 14333 073 24X Fiche 50-237, 82/08/05. B208130269.

B208200053 Forwards LER 82-029/03L-0
SCOTT, D. J. Commonwealth Edison Co. 82/08/09. KEPLER, J. O. Region
3. Office of Director. 1p. 14392 184. 24X Fiche 50-237, 82/08/09.
B208200053.

--B208200063 LER 82-029/03L-0 on B20712, HPCI min flow valve 2-2301-14
failed to reclose after opening. Caused by control wire
caught under torque switch. Wire secured away from torque
switch & recycled to verify operability.
MORRIS, W. Commonwealth Edison Co. 82/08/02 Region 3. Office
of Director. 2pp. 14392 185. 24X Fiche 50-237, 82/08/09.
B208200053.

B208230026 Forwards LER 82-037/03L-0
SCOTT, D. J. Commonwealth Edison Co. 82/08/10. KEPLER, J. O. Region
3. Office of Director. 1p 14317 283 24X Fiche 50-237, 82/08/10.
B208230026.

--B208230030 LER 04-037/03L-0 on B20724, average power range monitor gain
adjustment factor for average power range monitors 4 & 6
exceeded 1.02 while in final hours of 12-h rampen soak
period. Caused by changes in flux distribution & lag time.
SCHROEDER, B. A. Commonwealth Edison Co. 82/08/10 Region 3.
Office of Director. 2pp. 14317 286 24X Fiche 50-237, 82/08/10.
B208230026.

B208230252 Forwards LER 82-036/03L-0
SCOTT, D. J. Commonwealth Edison Co. 82/08/10. KEPLER, J. O. Region
3. Office of Director. 1p. 14508 358. 24X Fiche 50-237, 82/08/10.
B208230252

--B208230259 LER 82-036/03L-0 on B20723, average power range monitor gain
adjustment factor for ARPMs 2 & 3 exceeded Tech Spec. Caused
by changes in flux distribution & lag time for instrument
mechanic to make gain adjustment.
SCHROEDER, B. A. Commonwealth Edison Co. 82/08/10 Region 3.
Office of Director. 2pp 14508 359. 24X Fiche 50-237, 82/08/10.
B208230252.

B208300128 Forwards LER 82-033/03L-0.
SCOTT, D. J. Commonwealth Edison Co. 82/08/20. KEPLER, J. O. Region
3. Office of Director. 1p. 14595 354. 24X Fiche 50-237, 82/08/20.
B208300128.

--B208300134 LER 82-033/03L-0 on B20722, reactor water cleanup valve
MO-2-1201-3 failed to close upon close signal. Apparently
caused by sticky limit switch contact that bypasses torque
switch in close direction & lack of valve stem lubrication.
GARNIER, P. Commonwealth Edison Co. 82/08/20 Region 3. Office
of Director. 2pp. 14595 355. 24X Fiche 50-237, 82/08/20.
B208300128.

B208310092 Forwards LER 82-035/03L-0
SCOTT, D. J. Commonwealth Edison Co. 82/08/25 KEPLER, J. O. Region
3. Office of Director. 1p 14689 300 24X Fiche 50-237, 82/08/23.
B208310092

--B208310094 LER 82-035/03L-0 on B20724, offgas flow indicated high during
normal startup. Caused by cracked fillet weld in 201
Feedwater heater emergency spill to normal heater drain line
connection. Weld cracked due to excessive line movement.
CHRISTEL, B. Commonwealth Edison Co. 82/08/23 Region 3. Office
of Director. 2pp 14689 301 24X Fiche 50-237, 82/08/23.
B208310092

B208310270 Forwards LER 82-034/03L-0
SCOTT, D. J. Commonwealth Edison Co. 82/08/23 KEPLER, J. O. Region
3. Office of Director. 1p 14688 144 24X Fiche 50-237, 82/08/23.
B208310270

--B208310279 LER 82-034/03L-0 on B20726, pinhole leak discovered in
1-inch diameter HPCI drain pot drain line 2-2323-1-LX to
main condenser. Cause unknown. Temporary patch installed &
area decontaminated. Deviation report encl
GARNIER, P. J. Commonwealth Edison Co. 82/08/23 Region 3.
Office of Director. 2pp 14688 145. 24X Fiche 50-237, 82/08/23.
B208310270.

DOCKET 50-241 MISSISSIPPI STATE UNIV. RESEARCH REACTOR

Q. Inspection reports, IE Bulletins & correspondence

B208160428 Forwards IE Insp Rept 50-241/82-01 on B20621-22 No
noncompliance noted.
VERRELL, J. D. M. Division of Project & Resident Programs 82/07/19.
CARLEY, C. T. Mississippi State Univ. 2pp 14349 250 24X
Fiche 50-241, 82/07/19. B208160428

--B208160437 IE Insp Rept 50-241/82-01 on B20621-22 No noncompliance
noted. Major areas inspected, survey for residual
contamination after disposal of contaminated reactor
components.
ALBRIGHT, R. H., BARR, K. P. Division of Engineering & Technical
Programs. 82/07/13 3pp 14349 260. 24X Fiche 50-241, 82/07/19.
B208160428.

DOCKET 50-243 OREGON STATE UNIV. RESEARCH REACTOR

Q. Inspection reports, IE Bulletins & correspondence

B204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation." Bvc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19.
Michigan, Univ. of. 112pp. 14358 001. 24X Fiche 50-000, 82/07/19.
B204210399

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

Q. NRC Draft/Final Environmental Statements, suppl & correspondence

B208110100 Requests review of existing FES, dtd Dec 1973 to determine
feasibility of license conversion. Comments re significant
changes to facility or environs should be submitted within
30 days of receipt of ltr
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/06. HAIER, J. E.
Rochester Gas & Electric Corp. 2pp. 14317 178 24X
Fiche 50-244, 82/08/06. B208110100.

F. Security, medical, emergency & fire protection plans

B208020193 Releases public version of revised emergency plan
implementing procedures.
FELTON, J. M. Division of Rules and Records. 82/07/13. Document
Management Branch. 1p. 14179 162. 24X Fiche 50-244, 82/07/13.
B208020193.

--B208020194 Forwards public version of revised emergency plan
implementing procedures, including Procedures SC-213 re
accountability of personnel, SC-233 re search & rescue
operation & SC-322 re manning of emergency survey ctr.
HAIER, J. E. Rochester Gas & Electric Corp. 82/06/30.
CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14179 163. 24X
Fiche 50-244, 82/07/13. B208020193

--B208020195 Public version of revised emergency plan implementing
procedures, including Procedures SC-213 re accountability of
personnel, SC-233 re search & rescue operation & SC-322 re
manning of emergency survey ctr.
BODINE, J. C. Rochester Gas & Electric Corp. 82/06/25. 16pp.
14179 164. 24X Fiche 50-244, 82/07/13. B208020193.

8208030363 Forwards response to NRC 820507 ltr re request for exemption from 72-h requirement for achieving cold shutdown following fire in auxiliary bldg RHR pit zone Cold shutdown can be achieved & maintained within 72-h of plant shutdown MAIER, J. E. Rochester Gas & Electric Corp. 82/07/28. CRUTCHFIELD, D. Operating Reactors Branch 5. 10pp. 14158. 103. 24X Fiche 50-244. 82/07/28. 8208030363

8208030250 Forwards Amend 53 to License DPR-18, safety evaluation & notice of issuance & availability Amend approves provisions updating fire protection sys operability & surveillance requirements CRUTCHFIELD, D. Operating Reactors Branch 5. 82/07/29. MAIER, J. E. Rochester Gas & Electric Corp. 2pp. 14158. 230. 24X Fiche 50-244. 82/07/29. 8208030250.

--8208030253 Amend 53 to License DPR-18, approving provisions which update fire protection sys operability & surveillance requirements. CRUTCHFIELD, D. Operating Reactors Branch 5. 82/07/29. 12pp. 14158. 232. 24X Fiche 50-244. 82/07/29. 8208030250.

--8208030259 Safety evaluation supporting Amend 53 to License DPR-18. * Office of Nuclear Reactor Regulation, Director. 82/07/29. 4pp. 14158. 244. 24X Fiche 50-244. 82/07/29. 8208030250.

--8208030260 Notice of issuance & availability of Amend 53 to License DPR-18. CRUTCHFIELD, D. Operating Reactors Branch 5. 82/07/29. 2pp. 14158. 240. 24X Fiche 50-244. 82/07/29. 8208030250.

8208060074 Releases public version of revised emergency plan implementing procedure. FELTON, J. M. Division of Rules and Records. 82/08/02. Document Management Branch. 1p. 14283. 091. 24X Fiche 50-244. 82/08/02. 8208060074.

--8208060079 Forwards public version of Revision 1 to Emergency Plan Implementing Procedure BC-452. "Sampling Snow, Grass, Soil & Vegetation." MAIER, J. E. Rochester Gas & Electric Corp. 82/07/21. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14283. 092. 24X Fiche 50-244. 82/08/02. 8208060074.

--8208060081 Public version of Revision 1 to Emergency Plan Implementing Procedure BC-452. "Sampling Snow, Grass, Soil & Vegetation." BODINE, J. C. Rochester Gas & Electric Corp. 82/07/16. 6pp. 14283. 093. 24X Fiche 50-244. 82/08/02. 8208060074.

O. Adjudicatory correspondence

8208020213 Response to ASLB 820708 order re status of hearing. Discussion of matters re discovery, prehearing conferences & hearings are premature & should be postponed pending issuance of documents. Certificate of Svc encl. VOIOT, H. H. Rochester Gas & Electric Corp. VOIOT, H. H. LeBoeuf, Lamb, Leiby & MacRae. 82/07/30. 3pp. 14141. 115. 24X Fiche 50-244. 82/07/30. 8208020213

8208020231 Response to ASLB 820708 order to submit status rept. Immediate prehearing conference or conversion hearing not needed due to uncertainty re completion of integrated safety assessment & conversion SER. W/Certificate of Svc. YOUNG, M. A. Hearing Branch 4. 82/07/30. 7pp. 14152. 337. 24X Fiche 50-244. 82/07/30. 8208020231.

O. Advisory Committee on Reactor Safeguards reports & correspondence

8208230274 Discusses ACRB 267th meeting on 820708-10 re SEP Phase II review. Stated objectives achieved & NRC actions on SEP assessment acceptable. SHEWMON, P. ACRB - Advisory Committee on Reactor Safeguards. 82/08/18. PALLADINO, N. J. Commissioners. 3pp. 14313. 202. 24X Fiche 50-244. 82/08/18. 8208230274.

P. Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR. Svc list encl. DIRCKS, W. J. Office of the Executive Director for Operations. 82/07/02. Consolidated Edison Co. of New York. 93pp. 14194. 001. 24X Fiche 50-000. 82/07/02. 8207080064.

8208030250 Forwards Amend 53 to License DPR-18, safety evaluation & notice of issuance & availability. Amend approves provisions updating fire protection sys operability & surveillance requirements. CRUTCHFIELD, D. Operating Reactors Branch 5. 82/07/29. MAIER, J. E. Rochester Gas & Electric Corp. 2pp. 14158. 230. 24X Fiche 50-244. 82/07/29. 8208030250.

--8208030253 Amend 53 to License DPR-18, approving provisions which update fire protection sys operability & surveillance requirements. CRUTCHFIELD, D. Operating Reactors Branch 5. 82/07/29. 12pp. 14158. 232. 24X Fiche 50-244. 82/07/29. 8208030250.

--8208030259 Safety evaluation supporting Amend 53 to License DPR-18. * Office of Nuclear Reactor Regulation, Director. 82/07/29. 4pp. 14158. 244. 24X Fiche 50-244. 82/07/29. 8208030250.

--8208030260 Notice of issuance & availability of Amend 53 to License DPR-18. CRUTCHFIELD, D. Operating Reactors Branch 5. 82/07/29. 2pp. 14158. 248. 24X Fiche 50-244. 82/07/29. 8208030250.

8208030319 Comments on SEP, Phase II. SEP-like program incorporating experience of SEP (minimal topics, acceptable alternative to SRP & integrated assessment) is of safety benefit. MAIER, J. E. Rochester Gas & Electric Corp. 82/07/30. CRUTCHFIELD, D. Operating Reactors Branch 5. 6pp. 14163. 244. 24X Fiche 50-244. 82/07/30. 8208030319.

8208090194 Generic ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl. EISENHUT, D. Q. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14356. 332. 24X Fiche 50-000. 82/08/09. 8208090194.

8208170164 Forwards application for amend to License DPR-18, proposing Tech Spec change to permit operation at both current & reduced primary sys temp & pressure. MAIER, J. E. Rochester Gas & Electric Corp. 82/08/09. DENTON, H. Office of Nuclear Reactor Regulation, Director. 1p. 14365. 012. 24X Fiche 50-244. 82/08/09. 8208170164.

--8208170173 Application for amend to License DPR-18, proposing Tech Spec change to permit operation at reduced primary sys pressure & temp. MAIER, J. E. Rochester Gas & Electric Corp. 82/08/09. 2pp. 14365. 013. 24X Fiche 50-244. 82/08/09. 8208170164.

--8208170181 Proposed Tech Specs 1.0 & 2.3 & Table 3.5-2 re definitions, limiting safety sys settings & protective instrumentation applicability & emergency cooling, respectively. Safety evaluation encl. * Rochester Gas & Electric Corp. 82/08/09. 17pp. 14365. 015. 24X Fiche 50-244. 82/08/09. 8208170164.

--8208170188 "Plant Transient Analysis for Operation of RE Ginna Unit 1 Nuclear Power Plant at Reduced Pressure & Temp." NUTT, W. T., COOKE, G. C., MORGAN, J. N. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-NF-82-45 R01. 82/07/22. 99pp. 14365. 032. 24X Fiche 50-244. 82/08/09. 8208170164.

--8208170206 "RE Ginna Nuclear Plant Cycle 12 BAR for Low Temp & Pressure." NIELSEN, L. A., COPELAND, R. A., KRAJICEK, J. E. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.). XN-NF-82-37. 82/07/20. 44pp. 14365. 130. 24X Fiche 50-244. 82/08/09. 8208170164.

8208170214 Forwards application for amend to License DPR-18, revising Tech Specs to incorporate radiological effluent Tech Specs. Change supersedes 790214 proposal. MAIER, J. E. Rochester Gas & Electric Corp. 82/08/12. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 14361. 234. 24X Fiche 50-244. 82/08/12. 8208170214.

--8208170216 Application for amend to License DPR-18, revising Tech Specs to incorporate radiological effluent Tech Specs. MAIER, J. E. Rochester Gas & Electric Corp. 82/08/12. 2pp. 14361. 235. 24X Fiche 50-244. 82/08/12. 8208170214.

--8208170220 Proposed Tech Specs incorporating radiological effluent Tech Specs. Safety evaluation encl. * Rochester Gas & Electric Corp. 82/08/12. 80pp. 14361. 237. 24X Fiche 50-244. 82/08/12. 8208170214.

8208240149 Requests that rept of relief & safety valve failures & challenges be included in next annual rept, per TMI Action Item 11.K.3.3, "Reporting Relief & Safety Valve Failures & Challenges." Commitment resolves item. CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/18. MAIER, J. E. Rochester Gas & Electric Corp. 2pp. 14319. 359. 24X Fiche 50-244. 82/08/18. 8208240149.

8208240331 Forwards "Control of Heavy Loads (C-10), Rochester Gas & Electric Corp. RE Dinna Nuclear Power Plant." draft technical evaluation rept per 820201 response to 801222 generic ltr After 4-wk review period, conference call will be arranged.
CRUTCHFIELD, D. Operating Reactors Branch 5 82/08/19 MAIER, J. E. Rochester Gas & Electric Corp 2pp 14528 044 24X
Fiche 50-244, 82/08/19, 8208240331

--8208240344 "Control of Heavy Loads (C-10), Rochester Gas & Electric Corp. RE Dinna Nuclear Power Plant." draft technical evaluation rept
HOFKIN, I. Franklin Institute/Franklin Research Center.
TER-C5Q57-444 DRFT 82/08/10. CLEMENSON, F. NRC - No Detailed Affiliation Given. 29pp. 14528 046 24X Fiche 50-244, 82/08/19, 8208240331

8208300249 Notifies that response to 820617 request for status info re unresolved safety issues will be provided by late Sept 1982 for inclusion in safety evaluation. No short-term safety implication associated w/response delay
MAIER, J. E. Rochester Gas & Electric Corp. 82/08/20 CRUTCHFIELD, D. Operating Reactors Branch 5 1p 14679 136 24X
Fiche 50-244, 82/08/20, 8208300249

8208310335 Forwards response to open items noted in draft SEP Integrated Plant Safety Assessment Rept. NUREG-0821. Every effort will be made to ensure task completion within schedule.
MAIER, J. E. Rochester Gas & Electric Corp 82/08/23 CRUTCHFIELD, D. Operating Reactors Branch 5 7pp 14694 323 24X
Fiche 50-244, 82/08/23, 8208310335.

8208310329 Forwards Page 4, 15-2 of Tech Specs re scheduling functional tests, inadvertently omitted from Amend 53 to License DPR-18, forwarded by NRC 820729 ltr.
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/26 MAIER, J. E. Rochester Gas & Electric Corp 3pp 14692 148 24X
Fiche 50-244, 82/08/26, 8208310329.

Q. Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16. Consolidated Edison Co. of New York. 87pp 14356 274 24X
Fiche 50-000, 82/07/16, 8204210393.

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of. 112pp. 14358 001 24X Fiche 50-000, 82/07/19, 8204210395.

8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp. 14381 001 24X
Fiche 50-000, 82/07/20, 8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Consolidated Edison Co. of New York 71pp. 14357 276 24X Fiche 50-000, 82/07/20, 8204210397

8204210398 IE Info Notice 82-26, "RC1C & HPC1 Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22. Consolidated Edison Co. of New York. 112pp. 14194 321 24X
Fiche 50-000, 82/07/22, 8204210398.

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 122pp. 14380 115 24X
Fiche 50-000, 82/07/23, 8204210401.

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHRs." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 127pp. 14194 120 24X
Fiche 50-000, 82/07/23, 8204210402

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PHR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26. Consolidated Edison Co. of New York. 121pp. 14357 013 24X
Fiche 50-000, 82/07/26, 8204210403

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28. Consolidated Edison Co. of New York. 122pp 14357 146 24X
Fiche 50-000, 82/07/28, 8204210405

8208020223 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-10
STAROSTECKI, R. Division of Project & Resident Programs. 82/07/29. MAIER, J. E. Rochester Gas & Electric Corp 1p 14151 219 24X
Fiche 50-244, 82/07/29, 8208020223

--8208020228 Responds to NRC 820616 ltr re violations noted in IE Insp Rept 50-244/82-10 Corrective actions. QC inspectors made aware of incident & instructed to discuss contents of all surveillance repts when submitting repts for review
MAIER, J. E. Rochester Gas & Electric Corp 82/07/16 BRUNNER, E. J. Division of Project & Resident Programs. 2pp. 14151 220 24X
Fiche 50-244, 82/07/29, 8208020223

8208120100 Forwards IE Insp Rept 50-244/82-13 on 820628-0701. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 82/07/29. MAIER, J. E. Rochester Gas & Electric Corp. 2pp. 14324 242 24X
Fiche 50-244, 82/07/29, 8208120100

--8208120104 IE Insp Rept 50-244/82-13 on 820628-0701. No noncompliance noted. Major areas inspected. Followup on IE Circular 80-21, verification of core load, post-refueling startup testing & control rod worth measurements & predictions.
PETRONI, C. D., BETTENHAUSEN, L. Division of Engineering & Technical Programs. 82/07/20 7pp. 14324 244 24X Fiche 50-244, 82/07/29, 8208120100

8208090048 Forwards response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PHR Plants." Rept identifies bolted closures experiencing leakage since plant startup. Rept will follow 1983 outage for remaining items.
MAIER, J. E. Rochester Gas & Electric Corp 82/07/30. HAYNES, R. C. Region 1, Office of Director. 2pp 14270 032 24X
Fiche 50-244, 82/07/30, 8208090048

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/05. Consolidated Edison Co. of New York 117pp 14388 201 24X
Fiche 50-000, 82/08/05, 8204210407

8208300044 Forwards IE Insp Rept 50-244/82-09 on 820503-06 & notice of violation.
MARTIN, T. T. Division of Engineering & Technical Programs. 82/08/13. MAIER, J. E. Rochester Gas & Electric Corp 2pp 14598 311 24X
Fiche 50-244, 82/08/13, 8208300044

--8208300045 Notice of violation from insp on 820503-06.
* Region 1, Office of Director. 82/08/13. 1p 14598 313 24X
Fiche 50-244, 82/08/13, 8208300044

--8208300047 IE Insp Rept 50-244/82-09 on 820503-06. Noncompliance noted. Failure to follow requirements of special work permit procedure.
MCBRIDE, M. H., GREENMAN, E. G. Division of Engineering & Technical Programs. 82/08/11. 10pp 14598 314 24X Fiche 50-244, 82/08/13, 8208300044.

8208300048 Forwards IE Insp Rept 50-244/82-14 on 820701-31 & notice of violation.
STAROSTECKI, R. Division of Project & Resident Programs. 82/08/16. MAIER, J. E. Rochester Gas & Electric Corp. 2pp 14598 324 24X
Fiche 50-244, 82/08/16, 8208300048.

--8208300050 Notice of violation from insp on 820701-31.
STAROSTECKI, R. Division of Project & Resident Programs. 82/08/16. 1p. 14598 326 24X Fiche 50-244, 82/08/16, 8208300048

--8208300052 IE Insp Rept 50-244/82-14 on 820701-31 Noncompliance noted. Failure to perform surveillance test within required frequency.
ZIMMERMAN, R. P. Region 1, Office of Director. KISTER, H. B. Division of Project & Resident Programs. 82/08/13. 8pp. 14598 327 24X Fiche 50-244, 82/08/16, 8208300048.

R. Periodic operating reports & related correspondence

8208120245 Forwards monthly operating rept for June 1982.
ENOH, B. A. Rochester Gas & Electric Corp. 82/07/09. Office of Management and Program Analysis. 1p. 14326 341 24X
Fiche 50-244, 82/07/09, 8208120245

--8208120247 Monthly operating rept for June 1982
MCNAMARA, A E. Rochester Gas & Electric Corp 82/07/09 6pp
14326 342. 24X Fiche 50-244.82/07/09.8208120245.

8208270010 Responds to FOIA request for documents detailing collective
dose exposures in 1901 for operating nuclear power plants &
analyzing said info. Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records. 02/07/13 UDELL, R. A.
Critical Mass Energy Project 8pp 14679 208 24X
Fiche 50-000.82/07/13.8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power
Facilities for CY81"
* NRC - No Detailed Affiliation Given 82/07/13 48pp
14679 216 24X Fiche 50-000.82/07/13.8208270010

--8208270946 Forwards "Btd Rept of Personnel Whole Body Exposure (REM)
By Exposure Groups for 1981." per 10CFR20 407
MAIER, J. E. Rochester Gas & Electric Corp. 82/03/31 Office of
Management and Program Analysis 1p 14680:06B 24X
Fiche 50-000.82/07/13.8208270010

--8208270549 "Btd Rept of Personnel Whole Body Exposure (REM) By
Exposure Groups for 1981"
MAIER, J. E. Rochester Gas & Electric Corp. 82/03/31 1p
14680:069 24X Fiche 50-000.82/07/13.8208270010.

G Reportable occurrences, LERs & related correspondence

8208020266 Forwards LER 82-014/03L-0
MAIER, J. E. Rochester Gas & Electric Corp. 82/07/22 HAYNES, R. C.
Region 1, Office of Director 1p 14152 310. 24X
Fiche 50-244.82/07/22.8208020266.

--8208020274 LER 82-014/03L-0 on 820624, discharge check valve 862B on
containment spray pump failed to close at required
differential pressure. Caused by wear on pin & swing arm
Parts will be replaced during next outage.
SPECTOR, S. M. Rochester Gas & Electric Corp. 82/07/22 Region
1, Office of Director. 1p 14152 311 24X Fiche 50-244.82/07/22,
8208020266.

8208020313 Forwards LER 82-015/03L-0
MAIER, J. E. Rochester Gas & Electric Corp. 82/07/24 HAYNES, R. C.
Region 1, Office of Director 1p 14151 128. 24X
Fiche 50-244.82/07/24.8208020313

--8208020321 LER 82-015/03L-0 on 820622, at steady-state 100% operation,
periodic test identified faulty sealing of containment gas
radiation monitor return line check valve. Caused by dirt
deposits from veins of monitor pump
SPECTOR, S. M. Rochester Gas & Electric Corp. 82/07/24 Region
1, Office of Director 1p 14151 129. 24X Fiche 50-244.82/07/24,
8208020313

8208060030 Forwards incident reporting sys repts re effects of fire
protection sys actuation on safety-related equipment &
seismic qualification of safety-related sys for transmission
to NEA
MICHELSON, C. Director's Office. 82/07/29. LAFLEUR, J. D. Office of
International Programs, Director. 21pp. 14244 315 24X
Fiche 50-000.82/07/29.8208060030

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8208090388 Forwards "Fire Protection App R Review, Millstone Unit 1,"
supplemental info. supporting 810319 request for exemption
from App R requirements
COUNCIL, W. G., CAONETTA, J. P. Northeast Nuclear Energy Co. (subs. of
Northeast Utilities). COUNCIL, W. G. Northeast Utilities. 82/07/16.
EISENHUT, D. O. Division of Licensing. 7pp. 14209:001. 24X
Fiche 50-245.82/07/16.8208090388

--8208090393 "Fire Protection App R Review, Millstone Unit 1,"
supplemental info.
* Northeast Utilities. 82/07/31 140pp. 14209:008. 24X
Fiche 50-245.82/07/16.8208090388

8208030013 Releases public version of revised emergency plan
implementing procedures
FELTON, J. M. Division of Rules and Records. 82/07/20. Document
Management Branch. 1p. 14201:001. 24X Fiche 50-000.82/07/20.
8208030013.

--8208030019 Public version of revised emergency plan implementing
procedures, including Procedures EPIP 4102 re alert, EPIP 4103
re site area emergency & EPIP 4104 re general emergency.
* Connecticut Yankee Atomic Power Co. * Northeast Nuclear Energy
Co. (subs. of Northeast Utilities). 82/07/20. 718pp 14201:005
24X Fiche 50-000.82/07/20.8208030013.

8208050082 Forwards IE Safeguards Insp Repts 50-245/82-11 &
50-336/82-11 on 820524-28 & notice of deviation Insp rept
details & notice of deviation withheld (ref 10CFR73 21).
MARTIN, T. T. Division of Engineering & Technical Programs. 82/07/21.
COUNCIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast
Utilities). 2pp. 14213 203. 24X Fiche 50-245.82/07/21.8208050082.

--8208050085 IE Safeguards Insp Repts 50-245/82-11 & 50-336/82-11 on
820524-28 Deviation noted failure to meet commitment. Details
withheld (ref 10CFR73 21)
COGAN, N. J., OODY, A. T. Region 1, Office of Director. 82/07/19.
1p 14213 205 24X Fiche 50-245.82/07/21.8208050082.

8208060267 Submits addl clarifications of 820301 App R review for
facilities in response to NRC 820625 & 0707 requests
COUNCIL, W. G. Connecticut Yankee Atomic Power Co. COUNCIL, W. G.
Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
82/07/30 CLARK, R. A. Operating Reactors Branch 3. CRUTCHFIELD, D.
Operating Reactors Branch 5. 10pp 14241 196 24X
Fiche 50-000.82/07/30.8208060267

8208090312 Advises that fee sent w/820120 application for exemption
from safeguarding requirements of 10CFR73 21 will be
refunded
MILLER, W. D. License Fee Management Branch. 82/07/30 COUNCIL, W. G.
Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 1p.
14307 323. 24X Fiche 50-000.82/07/30.8208090312.

8208160340 Forwards suitability, training & qualification plan. Plan
withheld (ref 10CFR2 790)
ADDY, R. J. Northeast Utilities Service Co. 82/08/04 BENTON, H. R.
NRC - No Detailed Affiliation Given. 1p. 14348 069. 24X
Fiche 50-245.82/08/04.8208160340

8208250494 Responds to 820603 ltr re Revision 9 to modified amended
security plan. Revised Page 12-2 should be changed to
incorporate commitment to maintain isolation tone
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/11. COUNCIL, W. G.
Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 1p.
14362 234 24X Fiche 50-245.82/08/11.8208250494.

8208310468 Releases public version of revised emergency plan
implementing procedures
FELTON, J. M. Division of Rules and Records. 82/08/11. Document
Management Branch. 1p 14697 343 24X Fiche 50-245.82/08/11.
8208310468

--8208310471 Forwards public version of revised emergency plan
implementing procedures, including Procedures EPIP 4105,
"Bomb Threat" & EPIP Form 4105-1, "Bomb Threat Search
Checklist Unit 1 Shift Supervisor/Designee."
COUNCIL, W. G. Northeast Nuclear Energy Co. (subs. of Northeast
Utilities). 82/07/30 EISENHUT, D. O. Division of Licensing. 1p.
14697:344. 24X Fiche 50-245.82/08/11.8208310468.

--8208310473 Public version of revised emergency plan implementing
procedures, including Procedures EPIP 4105, "Bomb Threat" &
EPIP Form 4105-1, "Bomb Threat Search Checklist Unit 1 Shift
Supervisor Designee."
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
82/07/20. 22pp 14697:345 24X Fiche 50-245.82/08/11.8208310468.

H General correspondence

8208250135 Notifies of recent changes in util organization reflected in
QA program topical rept Revision 4A. Details encl
COUNCIL, W. G., CAONETTA, J. P. Northeast Utilities Service Co.
82/08/17. HAASB, W. P. Quality Assurance Branch. 7pp. 14541:302.
24X Fiche 50-000.82/08/17.8208250135.

P. Operating license stage documents & correspondence

8208020076 Advises that facilities fully meet position of NUREG-0737,
Item III.D.3.3, "Improved In-Plant Iodine Instrumentation
Under Accident Conditions." No deviations requested
COUNCIL, W. G. Connecticut Yankee Atomic Power Co. COUNCIL, W. G.
Northeast Nuclear Energy Co. (subs. of Northeast Utilities).
82/07/20 CRUTCHFIELD, D. Operating Reactors Branch 5. 1p.
14144:106. 24X Fiche 50-000.82/07/20.8208020076.

DOCKETED ITEMS

8208020244 Notifies of proposed programmatic change to QA program topical rept. Revision 4A Exception to Paragraph 1.4 of ANSI N49.2 9-1974 re definition of QA records will be added to App F of topical rept.
COUNSIL, W. O. Northeast Utilities Service Co. COUNSIL, W. O. Northeast Utilities 82/07/26. MAASS, W. P. Quality Assurance Branch. 2pp. 14132:234. 24X Fiche: 50-000, 82/07/26, 8208020244

8208030179 Comments on NRC draft evaluation of SEP Topic IX-5 re ventilation sys. transmitted in NRC B20510 ltr. Util. considers NUREG-0737, Item 11.8.2 to be of no consequence & resolved.
COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/07/29. CRUTCHFIELD, D. Operating Reactors Branch 3. 2pp. 14212:069. 24X Fiche: 50-245, 82/07/29, 8208030179

8208040231 Submits comments on SEP Phase II, to assist NRC in development of proposed program for Phase III
COUNSIL, W. O. Connecticut Yankee Atomic Power Co. COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/07/30. CRUTCHFIELD, D. Operating Reactors Branch 3. 8pp. 14241:323. 24X Fiche: 50-000, 82/07/30, 8208040231.

8208040279 Provides further response to NRC B01222 request for info re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants." Schedule for completion of remaining work expected by 820827.
COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. O. Connecticut Yankee Atomic Power Co. 82/07/30. EISENHUT, D. Q. Division of Licensing. 6pp. 14241:088 24X Fiche: 50-000, 82/07/30, 8208040279.

8208100001 Confirms validity of assumption that design of control rod drive sys precludes operation of more than one control rod, excluding reactor trip, in response to draft evaluation of SEP Topic IV-2, W/six aperture cards Aperture cards in PDR.
COUNSIL, W. O. CAQUETTA, J. P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/08/02. CRUTCHFIELD, D. Operating Reactors Branch 3. 2pp. 14298:235. 24X Fiche: 50-245, 82/08/02, 8208100001.

8208050480 Forwards revised final evaluation of SEP Topic II-1, C re potential hazards due to nearby transportation.
Institutional, industrial & military facilities. Facility meets current licensing criteria.
SHEA, J. J. Operating Reactors Branch 3. 82/08/04. COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 7pp. 14237:281. 24X Fiche: 50-245, 82/08/04, 8208050480.

8208250545 Forwards draft technical evaluation rept "Control of Heavy Loads (C-10)," based on responses to Section 2.1 of B01222 generic ltr Comments requested within 30 days of receipt of ltr
CRUTCHFIELD, D. Operating Reactors Branch 3. 82/08/04. COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 14562:212. 24X Fiche: 50-245, 82/08/04, 8208250545.

--8208250548 "Control of Heavy Loads (C-10)," draft technical evaluation rept.
HOFKIN, T. Franklin Institute/Franklin Research Center. NRC-03-79-118 TER-C5257-481 DRAFT. 82/07/27. NRC -- No Detailed Affiliation Given 27pp. 14562:214. 24X Fiche: 50-245, 82/08/04, 8208250548.

8208160074 Forwards addl info re individuals experience, college ed & current operator licenses, per NUREG-0737, Item 1.1.1, "Shift Technical Advisor."
COUNSIL, W. O. CAQUETTA, J. P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. O. Northeast Utilities 82/08/06. EISENHUT, D. Q. Division of Licensing. 3pp. 14342:114. 24X Fiche: 50-245, 82/08/06, 8208160074.

8208190218 Forwards detailed technical description of evaluation & findings re combustible gas control. Evaluation demonstrates that primary means of combustion gas control is nitrogen inerted containment.
COUNSIL, W. O. CAQUETTA, J. P. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. O. Northeast Utilities Service Co. 82/08/06. DIRCKS, W. J. Office of the Executive Director for Operations. 350pp. 14499:073. 24X Fiche: 50-245, 82/08/06, 8208190218.

8208090194 Generic ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D. Q. Division of Licensing. 82/08/09. Consolidated Edition Co. of New York. 1p. 14356:332. 24X Fiche: 50-000, 82/08/09, 8208090194.

8208190279 Submits no comment re draft evaluation of SEP Topic II-07.8, "Design Codes, Design Criteria & Load Combinations." Coincident seismic & LOCA events inappropriate for inclusion in design basis of plant.
COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/08/11. CRUTCHFIELD, D. Operating Reactors Branch 3.

8208200072 Application to amend Licenses DPR-21 & DPR-65, incorporating revised radiological ETS in Safety Tech Specs.
COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W. O. Northeast Utilities. 82/08/12. CLARK, R. A. Operating Reactors Branch 3. CRUTCHFIELD, D. Operating Reactors Branch 3. 5pp. 14392:010. 24X Fiche: 50-245, 82/08/12, 8208200072

--8208200080 Proposed revisions to radiological ETB for incorporation into safety Tech Specs
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/08/31. 175pp. 14392:013. 24X Fiche: 50-245, 82/08/12, 8208200072

8208240384 Forwards addl info re NUREG-0737, Item 11 K 3 17, "ECCB Outages," in response to NRC B20622 request
COUNSIL, W. O. OPEKA, J. F. Connecticut Yankee Atomic Power Co. COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/08/16. CRUTCHFIELD, D. Operating Reactors Branch 3. CLARK, R. A. Operating Reactors Branch 3. 23pp. 14524:045. 24X Fiche: 50-000, 82/08/16, 8208240384

8208200238 Notification of 820914 meeting w/Northeast Nuclear Energy Co in Bethesda, MD to discuss licensee 820806 rept & supplemental info re post-LOCA oxygen formation by water decomposition due to radiolysis.
SHEA, J. J. Operating Reactors Branch 3. 82/08/19. CRUTCHFIELD, D. Operating Reactors Branch 3. 3pp. 14399:083. 24X Fiche: 50-245, 82/08/19, 8208200238.

8208310306 Forwards offsite dose calculation manual, providing parameters & methodology for offsite dose & effluent monitor setpoint calculator.
COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/08/20. CLARK, R. A. Operating Reactors Branch 3. 1p. 14688:057. 24X Fiche: 50-245, 82/08/20, 8208310306.

--8208310310 Offsite dose calculation manual, providing parameters & methodology for offsite dose & effluent monitor setpoint calculation
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/08/31. 86pp. 14688:058. 24X Fiche: 50-245, 82/08/20, 8208310306

Q. Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16. Consolidated Edison Co. of New York. 87pp. 14356:274. 24X Fiche: 50-000, 82/07/16, 8204210393.

8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp. 14381:001. 24X Fiche: 50-000, 82/07/20, 8204210396.

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20. Consolidated Edison Co. of New York. 71pp. 14357:276. 24X Fiche: 50-000, 82/07/20, 8204210397.

8208050082 Forwards IE Safeguards Insp Repts 50-245/82-11 & 50-336/82-11 on 820524-28 & notice of deviation insp rept details & notice of deviation withheld (ref 10CFR73.21).
MARTIN, T. T. Division of Engineering & Technical Programs. 82/07/21. COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 2pp. 14213:203. 24X Fiche: 50-245, 82/07/21, 8208050082.

--8208050085 IE Safeguards Insp Repts 50-245/82-11 & 50-336/82-11 on 820524-28. Deviation noted: failure to meet commitment Details withheld (ref 10CFR73.21).
COGAN, N. J. GODY, A. T. Region 1, Office of Director. 82/07/19. 1p. 14213:205. 24X Fiche: 50-245, 82/07/21, 8208050082.

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22. Consolidated Edison Co. of New York. 112pp. 14194:321. 24X Fiche: 50-000, 82/07/22, 8204210398

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 122pp. 14380:115. 24X Fiche: 50-000, 82/07/23, 8204210401.

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York. 127pp. 14194 120 24X
Fiche: 50-000. 82/07/23. 8204210402

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants " Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26.
Consolidated Edison Co. of New York. 121pp. 14357-013 24X
Fiche: 50-000. 82/07/26. 8204210403

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28.
Consolidated Edison Co. of New York. 122pp. 14357 146 24X
Fiche: 50-000. 82/07/28. 8204210405

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Gaffle Water-Jet Impingement " Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/05
Consolidated Edison Co. of New York. 117pp. 14388. 201. 24X
Fiche: 50-000. 82/08/05. 8204210407

8208300065 Forwards IE Insp Repts 50-245/82-10 & 50-336/82-14 on 820621-25 & notice of violation
MARTIN, T. T. Division of Engineering & Technical Programs. 82/08/13.
CONUNGIL, M. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 2pp. 14598. 341 24X Fiche: 50-245. 82/08/13. 8208300065.

--8208300067 Notice of violation from insp on 820621-25.
* Division of Engineering & Technical Programs. 82/08/13. 2pp
14598. 343. 24X Fiche: 50-245. 82/08/13. 8208300065.

--8208300068 IE Insp Repts 50-245/82-10 & 50-336/82-14 on 820621-25.
Noncompliance noted failure to maintain procedures & engineering drawings.
NAPUDA, O. BISSETT, P. MEYER, O. Division of Engineering & Technical Programs. 82/08/12. 20pp. 14598. 345. 24X
Fiche: 50-245. 82/08/13. 8208300065

R Periodic operating reports & related correspondence

8208120090 Forwards monthly operating rept for June 1982
MRDCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). MRDCZKA, E. J. Northeast Utilities. 82/07/12. Office of Resource Management, Director. 1p. 14327. 139. 24X
Fiche: 50-245. 82/07/12. 8208120090

--8208120091 Monthly operating rept for June 1982
HARRAN, O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/07/07. 6pp. 14327. 140. 24X Fiche: 50-245. 82/07/12. 8208120090.

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A. Critical Mass Energy Project. 8pp. 14679. 208. 24X
Fiche: 50-000. 82/07/13. 8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp.
14679. 216. 24X Fiche: 50-000. 82/07/13. 8208270010.

--8208270941 Forwards "Reporting of Recorded Personnel Whole Body Exposures for CY81." per 10CFR20.407.
MRDCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/03/31. Office of Management and Program Analysis. 1p. 14680. 066. 24X Fiche: 50-000. 82/07/13. 8208270010.

--8208270943 "Reporting of Recorded Personnel Whole Body Exposures for CY81."
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 82/03/31. 1p. 14680. 067. 24X Fiche: 50-000. 82/07/13. 8208270010.

5. Reportable occurrences, LERs & related correspondence

8208260488 LER 81-004/01T-0 on 810421, reactor manual scram & blowdown/ cooldown subsequent to main turbine & condenser failure resulted in reactor coolant pressure decrease. Cooldown rate exceeded due to necessity for manual reactor blowdown.
* Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 81/05/05. Region 1, Philadelphia, Office of the Director (81/03/01). 3pp. 14595. 047. 24X Fiche: 50-245. 81/05/05. 8208260488.

DOCKET 50-246 ADVANCED CRITICAL REACTOR EXPERIMENT

P Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl.
DIRCKS, W. J. Office of the Executive Director for Operations. 82/07/02. Consolidated Edison Co. of New York. 93pp. 14194. 001. 24X Fiche: 50-000. 82/07/02. 8207080064

Q. Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation " Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of 112pp. 14398. 001. 24X Fiche: 50-000. 82/07/19. 8204210395

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8208030085 Requests FEMA Findings on adequacy of offsite preparedness around facilities to determine whether to invoke provisions of NRC regulations requiring licensees to demonstrate removal of identified significant deficiencies.
CRINEB, B. K. Division of Emergency Preparedness. 82/06/16. KRITHM, R. M. Federal Emergency Management Agency. 4pp. 14200. 291. 24X Fiche: 50-247. 82/07/06. 8208030085.

8207300508 Responds to 820602 ltr concerning emergency response plans for facilities & requesting initiation of 120-day regulatory clock against facilities. FEMA will provide findings on adequacy of plant offsite preparedness.
DEVOUNO, R. C. Director's Office, Office of Inspection and Enforcement. 82/07/07. DEL BELLO, A. B. Westchester County, NY. 4pp. 14172. 063. 24X Fiche: 50-247. 82/07/07. 8207300508

--8206060006 Expresses concerns re facility emergency response plans & requests initiation of 120-day regulatory clock against facilities. Critiques on emergency drill encl.
DELBELLO, A. B. Westchester County, NY. 82/06/02. PALLADINO, N. Commissioners. 57pp. 14172. 066. 24X Fiche: 50-247. 82/07/07. 8207300508

8208030686 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 82/07/20. Document Management Branch. 1p. 14301. 074. 24X Fiche: 50-003. 82/07/20. 8208030686.

--8208030728 Forwards public version of revisions to Emergency Plan Implementing Procedures IP-1023, "Operational Support Ctr" & IP-1024, "Monthly Check of Indian Point Emergency Radios, Telephones & Outdoor Evacuation Alarm."
O'TOOLE, J. D. Consolidated Edison Co. of New York. 82/07/09. HAYNES, R. C. Region 1, Office of Director. 3pp. 14301. 075. 24X Fiche: 50-003. 82/07/20. 8208030686.

--8208030730 Public version of Emergency Plan Implementing Procedures IP-1023, "Operational Support Ctr" & IP-1024, "Monthly Check of Indian Point Emergency Radios, Telephones & Outdoor Evacuation Alarm."
FINCH, O. L. Consolidated Edison Co. of New York. 82/06/18. 23pp. 14301. 078. 24X Fiche: 50-003. 82/07/20. 8208030686.

8208020073 Advises that amended Page 3-14 from physical security plan, per 820121 ltr, is withdrawn. Approved page in effect on 820526 remains in effect. In response to NRC 820518 ltr.
O'TOOLE, J. D. Consolidated Edison Co. of New York. 82/07/27. VARGA, S. A. Operating Reactors Branch 1. 1p. 14144. 112. 24X Fiche: 50-003. 82/07/27. 8208020073.

8208050050 Forwards FEMA 820802 ltr & interim findings rept on adequacy of radiological emergency response preparedness of state & local govt's near plant.
HASSELL, D. F. Hearing Branch 1. 82/08/02. CARTER, L. J., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 36pp. 14213. 231. 24X Fiche: 50-247. 82/08/02. 8208050050.

8208100030 Notifies that NRC will determine whether reactor should be shut down if significant deficiencies identified in FEMA 820802 ltr are not corrected within 120 days. Written statement describing plans requested within 30 days.
HAYNES, R. C. Region 1, Office of Director. 82/08/03. O'TOOLE, J. D. Consolidated Edison Co. of New York. 2pp. 14296. 275. 24X Fiche: 50-247. 82/08/03. 8208100030

--8208100039 Interim findings on adequacy of radiological emergency response preparation of state & local govts at Indian Point Nuclear Power Station
PETROONE, F.P. Federal Emergency Management Agency 82/07/30
33pp. 14296:279. 24X Fiche: 50-247, 82/08/03, 8208100039.

8208230413 Forwards minutes of 820701 meeting w/BNL re NRC review of util compliance w/10CFR50. App R & summary of 820713 site visit re investigation of methods for reducing risk of core melt due to fires.
VARGA, S.A. Operating Reactors Branch 1 82/08/06 O'TOOLE, J.D.
Consolidated Edison Co. of New York. 24pp. 14529:001 24X
Fiche: 50-247, 82/08/06, 8208230413

8208260349 Forwards minutes of 820701 meeting re review of compliance w/fire protection requirements of 10CFR50 4B. Firm schedule of answers to specific issues requested within 20 days of receipt of ltr.
EISENHUT, D.O. Division of Licensing 82/08/10 O'TOOLE, J.D.
Consolidated Edison Co. of New York. 51pp 14575:220. 24X
Fiche: 50-247, 82/08/10, 8208260349

8208270584 Releases public version of revised emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 82/08/12. Document Management Branch. 1p. 14683:227 24X Fiche: 50-003, 82/08/12, 8208270584.

--8208270590 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-1016 re obtaining meteorological data & IP-1037 re obtaining offsite Rueter-Stokes monitor data
O'TOOLE, J.D., LIEBLER, O.H. Consolidated Edison Co. of New York 82/07/01. Office of Nuclear Reactor Regulation, Director. 1p. 14683:228 24X Fiche: 50-003, 82/08/12, 8208270584

--8208270593 Public version of revised emergency plan implementing procedures, including Procedures IP-1016 re obtaining meteorological data & IP-1037 re obtaining offsite Rueter-Stokes monitor data.
Consolidated Edison Co. of New York 82/07/01. 51pp. 14683:229 24X Fiche: 50-003, 82/08/12, 8208270584.

0. Adjudicatory correspondence

8208110236 Response to UCS/NY PIR0 820921 request for admissions. Affidavits & Certificate of Svc encl.
MCOURRAN, H.J. Hearing Branch 1. 82/06/11. Union of Concerned Scientists. 25pp. 14330:315 24X Fiche: 50-247, 82/06/11, 8208110236

8208270458 Expresses appreciation for opportunity to address ASLB.
DIAMANT, L. Affiliation Unknown. 82/07/07. CARTER, L. Atomic Safety and Licensing Board Panel. 1p. 14565:272. 24X
Fiche: 50-247, 82/07/07, 8208270458

8208030348 Response to final set of interrogatories & document requests re Commission Question 1. Certificate of Svc encl. Related correspondence.
POBNER, P. Parents Concerned About Indian Point. 82/07/23
Consolidated Edison Co. of New York 8pp. 14137:214. 24X
Fiche: 50-247, 82/07/23, 8208030348

8208030335 Attempts to clear confusion of ASLB 820714 & 16 telcons to Comm Ed. Conversation on 820714 was substantive. Discussions re merits of motions or issues should be entertained only w/all parties participating. W/Certificate of Svc.
SOHNKE, B.M. Consolidated Edison Co. of New York. 82/07/27.
CARTER, L.J. Atomic Safety and Licensing Board Panel. 7pp. 14136:331. 24X Fiche: 50-247, 82/07/27, 8208030335.

8208160223 Memorandum & Order CLI-82-15 denying PABNY request for directed certification of charges that ASLB exceeded or misapplied jurisdiction in admitting UCS & other intervenor contentions. Addl Commissioner views encl.
CHILK, B.J. Office of the Secretary of the Commission. 82/07/27. 30pp. 14346:290. 24X Fiche: 50-247, 82/07/27, 8208160223.

8208020275 Urges Order CLI-82-15 be rescinded. Interests of nearby residents must be considered.
HEBSINGER, R.L., FRIEDLANDER, M., GREITZER, C. New York, NY. 82/07/28.
PALLADINO, N.J., AHEARNE, J., QILINSKY, V. Commissioners. 1p. 14132:262. 24X Fiche: 50-247, 82/07/28, 8208020275

8208050050 Forwards FEHA 820802 ltr & interim findings re adequacy of radiological emergency response preparedness of state & local govts near plant
HASSELL, D.F. Hearing Branch 1. 82/08/02. CARTER, L.J., SHON, F.J., PARIS, O.H. Atomic Safety and Licensing Board Panel. 36pp. 14213:231. 24X Fiche: 50-247, 82/08/02, 8208050050

8208060100 Requests immediate suspension of plant OLS until determination made that adequate emergency plans exist that are capable of protecting public
WEISS, E.R., SHOLLY, S.C. Union of Concerned Scientists WEISS, E.R., Harmon & Weiss. 82/08/04 PALLADINO, N.J., QILINSKY, V., AHEARNE, Commissioners. 3pp. 14238:173 24X Fiche: 50-247, 82/08/04, 8208060100

8208100053 Forwards Region 1 820803 ltr to licensee re emergency preparedness.
HASSELL, D.F. Hearing Branch 1. 02/08/03. CARTER, L.J., SHON, F.J., PARIS, O.H. Atomic Safety and Licensing Board Panel. 5pp. 14296:234 24X Fiche: 50-247, 82/08/03, 8208100053.

8208110079 Memorandum & certification seeking further Commission guidance on witness testimony on consequences & probabilities & evidence on status & degree of conformance w/NRC/FEMA guidelines.
CARTER, L.J., PARIS, O.H., SHON, F.J. Atomic Safety and Licensing Board Panel. 82/08/09. 6pp. 14316:344. 24X Fiche: 50-247, 82/08/09, 8208110079.

8208110085 Errata to 820809 memorandum & certification, correcting typographical errors
CARTER, L.J. Atomic Safety and Licensing Board Panel. 02/08/09. 14316:343 24X Fiche: 50-247, 82/08/09, 8208110085

8208170274 Solicits support for encl Croton-Harmon Board of Ed 8207 resolution demanding NRC institute 120-day clock to develop acceptable evacuation plan.
OERAD, K.A. Affiliation Unknown. 82/08/10. PARIS, O.H. Atomic Safety and Licensing Board Panel. 2pp. 14369:226. 24X
Fiche: 50-247, 82/08/10, 8208170274

8208160440 Supports UCS/NY PIR0 motion for order to show cause requesting shutdown. Cancellation of testimony & tardiness of objections to 820423 order unsupported.
FLEISHER, Z.B. West Branch Conservation Association. 82/08/11. PALLADINO, N. Commissioners. 1p. 14348:255. 24X
Fiche: 50-247, 82/08/11, 8208160440

8208170120 Forwards Town of Cortlandt 820810 Resolutions 250-02 & 251-82 committing to cooperate in formulating evacuation plans & to demand documents re evacuation plans from utils.
BOYLE, H.L. Cortlandt, Town of, NY. 82/08/12. Docketing & Services Branch. 3pp. 14365:206. 24X Fiche: 50-247, 82/08/12, 8208170120.

8208170284 Opposes congressional investigation re conduct of ongoing adjudicatory proceeding. Investigation could irreparably impair legal validity of subsequent agency decisions. Memo detailing concerns encl.
DUFFY, J.F. Power Authority of the State of New York. 82/08/13. OTTINGER, R.L. House of Rep., Energy & Commerce. 7pp. 14369:193. 24X Fiche: 50-247, 82/08/13, 8208170284

8208170285 Response supporting ASLB 820809 memorandum & order on two questions to Commission re probabilities & consequences. Certificate of Svc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York. MORGAN, C. Power Authority of the State of New York. MORGAN, C. Morgan Associates. 82/08/13. Commissioners. 12pp. 14369:183. 24X
Fiche: 50-247, 82/08/13, 8208170285.

8208190119 Lists corrections to licensee 820813 response to ASLB 820809 memorandum & certification.
COLARULLI, P.F. Morgan Associates. COLARULLI, P.F. Consolidated Edison Co. of New York. COLARULLI, P.F. Power Authority of the State of New York. 82/08/17. STUCKY, B.W. Docketing & Services Branch. 1p. 14381:294. 24X Fiche: 50-247, 82/08/17, 8208190119.

--8208190123 Corrected copy of response to ASLB 820809 memorandum & certification. Commission should reaffirm 820727 decision w/o further opinion.
BRANDENBURG, B. Consolidated Edison Co. of New York. MORGAN, C. Power Authority of the State of New York. MORGAN, C. Morgan Associates. 82/08/17. 8pp. 14381:295. 24X Fiche: 50-247, 82/08/17, 8208190119.

DOCKETED ITEMS

8208200120 Forwards documents in response to Interrogatory 7 filed on 820719. W/o encl
MOORE, J. E. Hearing Branch 1 82/08/19 WEISS, E. R. Harmon & Weiss.
WEISS, E. R. Union of Concerned Scientists WEISS, E. R. Public
Interest Research Group. New York. 1p 14300 086 24X
Fiche: 50-247, 82/08/19, 8208200120

8208240367 Submits informal Commission response to ASLB 820809 memorandum & certification of questions re intent to issue 820727 memorandum & order. CLI-82-15. Formal response expected during wk of 820830
CHILK, B. J. Office of the Secretary of the Commission. 82/08/23.
CARTER, L. J., SHON, F. J., PARIS, O. H. Atomic Safety and Licensing Board Panel. 3pp. 14320 168 24X Fiche: 50-247, 82/08/23, 8208240367

H General correspondence

8208030080 Responds to Rockland County Legislature Resolution 320 prohibiting use of county employees funds for federally mandated radiological response plans for facilities. FEMA will provide findings on adequacy of offsite preparedness.
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 82/07/06 GRANT, J. T. Rockland County, NY 2pp. 14200 289. 24X Fiche: 50-247, 82/07/06, 8208030080.

--8208030085 Requests FEMA findings on adequacy of offsite preparedness around facilities to determine whether to invoke provisions of NRC regulations requiring licensee to demonstrate removal of identified significant deficiencies.
GRIMES, B. K. Division of Emergency Preparedness. 82/06/16
KRIMM, R. M. Federal Emergency Management Agency App. 14200 291. 24X Fiche: 50-247, 82/07/06, 8208030080.

8208020290 Ack receipt of NRC ltr in response to Westchester County, NY request for 120-day regulatory clock against facilities. County appreciates NRC efforts to meet concerns by requesting interim findings from FEMA
DELBELLO, A. B. Westchester County, NY 82/07/13. PALLADIO, N. Commissioners. 1p. 14131 301 24X Fiche: 50-003, 82/07/13, 8208020290

8208180044 Informs of concerns & objections to proposed NRC plans for evacuation of residents from areas surrounding facilities in event of accident
ELBON, O. Gray Panthers. 82/07/22. Commissioners. 2pp. 14376 300. 24X Fiche: 50-247, 82/07/22, 8208180044.

I Financial information

8208030217 Forwards projection of util ability to pay \$20 million retrospective premium adjustment for Aug 1982-Jul 1983
O'TOOLE, J. D. Consolidated Edison Co. of New York. 82/07/29.
BALTZMAN, J. Antitrust & Economic analysis Branch (Utility Finance). 2pp 14189 338. 24X Fiche: 50-003, 82/07/29, 8208030217.

P Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR. Svc list encl.
DIRCKS, W. J. Office of the Executive Director for Operations. 82/07/02. Consolidated Edison Co. of New York. 93pp. 14194 001. 24X Fiche: 50-000, 82/07/02, 8207080064.

8208200291 Forwards advance notification of shipment of nuclear waste from facilities to Barnwell, SC
O'TOOLE, J. D. Consolidated Edison Co. of New York. 82/07/14.
HAYNEB, R. C. Region 1, Office of Director. 3pp. 14398 323. 24X Fiche: 50-247, 82/07/14, 8208200291.

8208040311 Notification of 820727 meeting w/util in Bethesda, MD to discuss scheduling of open items.
THOMA, J. D. Operating Reactors Branch 1. 82/07/21 VARQA, B. A. Operating Reactors Branch 1. 2pp. 14220 335. 24X Fiche: 50-247, 82/07/21, 8208040311

8208110050 Requests info re NY City water supply sys to aid R Cadell testimony for hearing on risk re water contamination by release of radioactivity in event of severe accident, per 820709 discussion.
HANAUER, S. H. Division of Safety Technology. 82/07/22. CONWAY, J. New York, State of. App. 14330 218. 24X Fiche: 50-003, 82/07/22, 8208110050.

8208020426 Notification of 820727 meeting w/Bandia Natl Lab & Pickard Luse & Gerrick in Albuquerque, NM to obtain info re open technical issues raised during meeting in June 1982.
HANNON, J. Operating Reactors Branch 1. 82/07/26. VARQA, B. A. Operating Reactors Branch 1. 2pp 14181 023. 24X Fiche: 50-247, 82/07/26, 8208020426.

8208160012 Responds to NRC 820630 request for schedule for responding to encl info request final design details re implementation of NUREG-0737, Item II.B.3. "Post-Accident Sampling," will be provided for post-implementation review by 830301.
O'TOOLE, J. D. Consolidated Edison Co. of New York. 82/08/06.
VARQA, B. A. Operating Reactors Branch 1. 1p 14344 335 24X Fiche: 50-247, 82/08/06, 8208160012.

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl.
EISENHUT, D. O. Division of Licensing. 82/08/09 Consolidated Edison Co. of New York. 1p. 14356 332 24X Fiche: 50-000, 82/08/09, 8208090194

8208160407 Forwards replacement pages to 810622 ltr re control of heavy loads.
O'TOOLE, J. D. Consolidated Edison Co. of New York. 82/08/10
VARQA, B. A. Operating Reactors Branch 1. 8pp 14349 007 24X Fiche: 50-247, 82/08/10, 8208160407

8208230232 Forwards application for amend to License DPR-26 & proposed Tech Specs to incorporate various requirements re steam generator exams.
O'TOOLE, J. D. Commonwealth Edison Co. 82/08/18 VARQA, B. A. Operating Reactors Branch 1. 1p 14514 276 24X Fiche: 50-247, 82/08/18, 8208230232.

--8208230238 Application to amend License DPR-26, incorporating requirements re steam generator exams.
O'TOOLE, J. D. Commonwealth Edison Co. 82/08/18. 2pp. 14514 277. 24X Fiche: 50-247, 82/08/18, 8208230232

---8208230242 Proposed Tech Spec page revisions to incorporate various requirements re steam generator exams.
Commonwealth Edison Co. 82/08/31. 16pp. 14514 279. 24X Fiche: 50-247, 82/08/31, 8208230242.

Q. Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16 Consolidated Edison Co. of New York. 87pp. 14336 274. 24X Fiche: 50-000, 82/07/16, 8204210393.

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of. 112pp. 14338 001. 24X Fiche: 50-000, 82/07/19, 8204210395.

8204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp. 14381 001. 24X Fiche: 50-000, 82/07/20, 8204210396.

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20. Consolidated Edison Co. of New York. 71pp. 14357 276. 24X Fiche: 50-000, 82/07/20, 8204210397.

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22. Consolidated Edison Co. of New York. 112pp. 14194 321. 24X Fiche: 50-000, 82/07/22, 8204210398.

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 122pp. 14380 115. 24X Fiche: 50-000, 82/07/23, 8204210401.

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 127pp. 14194 120. 24X Fiche: 50-000, 82/07/23, 8204210402.

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. Consolidated Edison Co. of New York. 121pp. 14357 01 Fiche: 50-000, 82/07/26, 8204210403

DOCKETED ITEMS

B204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28.
Consolidated Edison Co. of New York 122pp. 14357 146 24X
Fiche: 50-000, 82/07/28, B204210405

B208130296 Forwards response to Action Item 3A of IE Bulletin 82-02.
"Degradation of Threaded Fasteners in ACPB of PWR Plants."
Response to remainder of Items 3A & 3B will be submitted by
B20830
O'TOOLE, J. D. Consolidated Edison Co. of New York 82/08/02
HAYNES, R. C. Region 1, Office of Director 4pp. 14337 088 24X
Fiche: 50-247, 82/08/02, B208130296

B204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Gaffie Water-Jet Impingement." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/05
Consolidated Edison Co. of New York 117pp. 14388 201 24X
Fiche: 50-000, 82/08/05, B204210407

B208120230 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-247/82-09.
STAROSTECKI, R. Division of Project & Resident Programs 82/08/05.
O'TOOLE, J. D. Consolidated Edison Co. of New York 1p 14326 283
24X Fiche: 50-247, 82/08/05, B208120230.

--B208120237 Forwards response to NRC 820616 ltr re violations noted in IE Insp Rept 30-247/82-09. Corrective actions temporary procedure change for heatup from cold shutdown issued per station administrative orders & Tech Specs
O'TOOLE, J. D. Consolidated Edison Co. of New York 82/07/16
STAROSTECKI, R. Division of Project & Resident Programs 4pp 14326 284 24X Fiche: 50-247, 82/08/05, B208120230.

B208180077 Forwards "Fourth Refueling Outage Inservice Insp Exam Summary for Oct 1980-May 1981." Summary includes areas sub- to exams, exam results & equipment used. Detailed data will be available onsite
O'TOOLE, J. D. Consolidated Edison Co. of New York 82/08/12
ORIER, B. H. Region 1, Office of Director 1p 14376 330 24X
Fiche: 50-247, 82/08/12, B208180077

--B208180084 "Fourth Refueling Outage Inservice Insp Exam Summary for Oct 1980-May 1981."
* Consolidated Edison Co. of New York 81/08/31 14pp. 14376 331 24X Fiche: 50-247, 82/08/12, B208180077.

B208230282 Forwards response to IE Bulletin 80-11. "Masonry Wall Design." Response covers final re-evaluation rept & justifications
O'TOOLE, J. D. Consolidated Edison Co. of New York 82/08/16
VARQA, S. A. Operating Reactors Branch 1. 4pp 14510 001 24X
Fiche: 50-247, 82/08/16, B208230282

--B208230285 "Final Re-Evaluation Rept in Response to IE Bulletin 80-11."
* Computech Engineering Services, Inc. R347 01 82/06/30 100pp. 14510 005 24X Fiche: 50-247, 82/08/16, B208230282

--B208230287 "Justification for Various Aspects of Re-Evaluation Criteria in Response to NRC B11222 Request for Addl Info re IE Bulletin 80-11."
* Computech Engineering Services, Inc. 82/08/31 48pp 14510 114 24X Fiche: 50-247, 82/08/16, B208230282

B208300041 Forwards IE Insp Rept 50-247/82-14 on B20701-31 & notice of violation
STAROSTECKI, R. Division of Project & Resident Programs 82/08/16
O'TOOLE, J. D. Consolidated Edison Co. of New York 2pp. 14598 277.
24X Fiche: 50-247, 82/08/16, B208300041.

--B208300042 Notice of violation from insp on B20701-31.
STAROSTECKI, R. Division of Project & Resident Programs 82/08/16
1p. 14598 279. 24X Fiche: 50-247, 82/08/16, B208300041.

--B208300046 IE Insp Rept 50-247/82-14 on B20701-31 Noncompliance noted: failure to chain & padlock recirculating bypass valve on Charging Pump 23
REBELOWSKI, T. KOLTAY, P., KISTER, H. Division of Project & Resident Programs 82/08/13. 17pp. 14598 280. 24X Fiche: 50-247, 82/08/16, B208300041.

R. Periodic operating reports & related correspondence

B208110049 "Core Melt Metals Interactions Evaluations." annual progress rept for Apr 1980-Mar 1981.
SWANSON, D. G., CATTON, I. Applied Science Associates, Inc.
NRC-03-80-104. AB41-81-001. 81/03/31 Division of Systems Integration (post B11003). 21pp. 14330 001. 24X
Fiche: 50-247, 81/03/31, B208110049.

B208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A.
FELTON, J. H. Division of Rules and Records 82/07/13. UDELL, R. A. Critical Mass Energy Project. 8pp. 14679 208 24X
Fiche: 50-000, 82/07/13, B208270010

--B208270012 Forwards "Number of Personnel & Man Rem By Work & Job Function for CY81." per 10CFR20 407
O'TOOLE, J. D. Consolidated Edison Co. of New York 82/03/01
HAYNES, R. C. Region 1, Office of Director 1p 14679 361 24X
Fiche: 50-000, 82/07/13, B208270010.

--B208270016 "Number of Personnel & Man Rem By Work & Job Function for CY81."
* Consolidated Edison Co. of New York. 82/03/01. 1p. 14679 362.
24X Fiche: 50-000, 82/07/13, B208270010.

--B208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given 82/07/13. 48pp.
14679 216 24X Fiche: 50-000, 82/07/13, B208270010

--B208270632 Forwards "Personnel Whole Body Exposures For CY81." per 10CFR20 407
BRONS, J. C. Power Authority of the State of New York. 82/02/26.
Office of Management and Program Analysis. 1p. 14679 345 24X
Fiche: 50-000, 82/07/13, B208270010

--B208270637 "Personnel Whole Body Exposures for CY81."
* Consolidated Edison Co. of New York. 82/02/26 1p. 14679 346
24X Fiche: 50-000, 82/07/13, B208270010

B208240248 Forwards monthly operating rept for Jul 1982
O'TOOLE, J. D. Consolidated Edison Co. of New York 82/08/16
MCDONALD, W. O. Distribution Services Branch. 1p. 14544 137. 24X
Fiche: 50-247, 82/08/16, B208240248

--B208240252 Monthly operating rept for Jul 1982
EICH, E. F. Consolidated Edison Co. of New York 82/08/05. 5pp.
14544 138 24X Fiche: 50-247, 82/08/16, B208240248

B. Reportable occurrences, LERs & related correspondence

B208050217 Forwards LER 82-026/03L-0
O'TOOLE, J. D. Consolidated Edison Co. of New York. 82/07/16.
HAYNES, R. C. Region 1, Office of Director 1p 14209 261 24X
Fiche: 50-247, 82/07/16, B208050217

--B208050220 LER 82-026/03L-0 on B20618, during normal operation essential svc water sys being supplied by svc water pumps 21, 22 & 23 declared inoperable caused by low pump head values. Pumps repaired, replaced & tested.
FITZPATRICK, B. Tennessee Valley Authority. 02/07/18 Region 1, Office of Director. 1p. 14209 262 24X Fiche: 50-247, 82/07/16, B208050217.

B208020229 Forwards LER 82-027/03L-0
O'TOOLE, J. D. Consolidated Edison Co. of New York. 82/07/21.
HAYNES, R. C. Region 1, Office of Director. 1p. 14152 236. 24X
Fiche: 50-247, 82/07/21, B208020229.

--B208020232 LER 82-027/03L-0 on B20621, during normal operation, boron injection tank level indicator read low caused by solidification of boric acid in instrument pulse line. Line cleared & instrument returned to normal operation.
FITZPATRICK, B. Consolidated Edison Co. of New York. 82/07/21.
Region 1, Office of Director 2pp. 14152 237. 24X
Fiche: 50-247, 82/07/21, B208020229.

B208050191 Releases sanitized version of overexposure rept 10CFR20. 405.
* Administration Branch. 82/07/23. Document Management Branch.
1p. 14242 061. 24X Fiche: 50-247, 82/07/23, B208050191.

--B208050249 Sanitized version of overexposure rept re B20601 event in which limit for whole body exposure per 10CFR20. 101(b)(1) exceeded for one employee of contractor performing activities. Ltr supplies B20602 & B20609 repts.
O'TOOLE, J. D. Consolidated Edison Co. of New York. 82/07/01.
HAYNES, R. C. Region 1, Office of Director. 7pp. 14242 062. 24X
Fiche: 50-247, 82/07/23, B208050191.

B208060327 Forwards incident reporting sys repts re spill of contaminated water & contamination of personnel in auxiliary bldg & failure of control rod guide tube support pins for transmutal to NEA
MICHELS, G. C. Director's Office. 82/07/29. LAFLEUR, J. D. Office of International Programs. Director. 17pp. 14281 234. 24X
Fiche: 50-000, 82/07/29, B208060327.

DOCKETED ITEMS

5

8208160004 Forwards LER 82-029/03L-0
O'TOOLE, J. Consolidated Edison Co. of New York 82/07/30
HAYNES, R. C. Region 1, Office of Director 1p 14344 313. 24X
Fiche: 50-247, 82/07/30, 8208160004

--8208160005 LER 82-029/03L-0 on 820702, containment isolation valve in primary make-up water sys would not fully close when tested. Valve will be secured in closed position until repaired. Cause & corrective actions will be reported after repair.
FITZPATRICK, B. Consolidated Edison Co. of New York 82/07/30.
Region 1, Office of Director 2pp 14344 314. 24X
Fiche: 50-247, 82/07/30, 8208160004

8208230341 Forwards LER 82-030/03L-0.
O'TOOLE, J. D. Consolidated Edison Co. of New York 82/08/09.
HAYNES, R. C. Region 1, Office of Director 1p 14608 271. 24X
Fiche: 50-247, 82/08/09, 8208230341

--8208230347 LER 82-030/03L-0 on 820710, during normal operation, bypass valve 267A in chemical & vol control sys found leaking. Caused by damaged diaphragm. New valve bonnet assembly & diaphragm installed.
FITZPATRICK, B. Consolidated Edison Co. of New York 82/08/09
Region 1, Office of Director 1p 14508 272. 24X
Fiche: 50-247, 82/08/09, 8208230341

8208260132 RO 82-32 on 820817, steam generator 22 blowdown outer isolation valve CV1215A closed. Caused by failure of 1313A solenoid valve. Jumper installed in instrument air sys to establish blowdown. Also reportable per Part 21.
JACKSON, C. W. Consolidated Edison Co. of New York 82/08/18.
HAYNES, R. C. Region 1, Office of Director 2pp 14556 331. 24X
Fiche: 50-247, 82/08/18, 8208260132

8208310178 Forwards LER 82-028/03L-0.
O'TOOLE, J. D. Consolidated Edison Co. of New York 82/08/19.
HAYNES, R. C. Region 1, Office of Director 1p 14689 003. 24X
Fiche: 50-247, 82/08/19, 8208310178

--8208310186 LER 82-028/03L-0 on 820720, operator observed low air flow condition to R11/R12 containment gas & particulate monitors. Caused by moisture on electrical leads. Source of moisture corrected & motor leads dried & reconnected.
FITZPATRICK, B. Consolidated Edison Co. of New York 82/08/19.
Region 1, Office of Director 1p 14689 004. 24X
Fiche: 50-247, 82/08/19, 8208310178

T. Hearing transcripts on non-antitrust matters

8208040357 Transcript of Commission 820722 public meeting/affirmation session in Washington, DC re BECY-82-270A on alternative Commission decision in Indian Point special proceeding.
* Commissioners. 82/07/22. 10pp. 14223 170. 24X
Fiche: 50-247, 82/07/22, 8208040357

U Congressional/Executive Correspondence

8208100350 Responds to 820608 ltr to Chairman Palladino requesting that facilities be shut down pending NRC review of results of hearings. Protective measures imposed by NRC cited. Results of current hearings to be reported to Commissioners Sept 1982.
DIRCKS, W. J. Office of the Executive Director for Operations. 82/07/09. QILMAN, B. A. House of Rep. 5pp. 14308 347. 24X
Fiche: 50-247, 82/07/09, 8208100350.

--8206060022 Urges shutdown of facilities until adequate emergency plan can be formulated & ASLB findings studied. Constituent concern re plant safety & inadequate evacuation plan cited.
QILMAN, B. A. House of Rep. 82/06/08. PALLADINO, N. Commissioners. 4pp. 14308 351. 24X Fiche: 50-247, 82/07/09, 8208100350.

DOCKET 50-249 DREDDEN NUCLEAR POWER STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8208040353 Releases public version of revised emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records. 82/07/13. Document Management Branch. 1p. 14223 161. 24X Fiche: 50-010, 82/07/13, 8208040353

--8208040358 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-CB, "Rad/Chem Director." Receipt form, procedure history & safety evaluation encl.
SCOTT, D. J. Commonwealth Edison Co. 82/07/02. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 14223 162. 24X
Fiche: 50-010, 82/07/13, 8208040353.

--8208040361 Public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-CB, "Rad/Chem Director." Revised index of station group director duties encl.
* Commonwealth Edison Co. 82/06/30. 5pp. 14223 165. 24X
Fiche: 50-010, 82/07/13, 8208040353

8208040473 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 82/07/22. Document Management Branch. 1p. 14220 294. 24X Fiche: 50-010, 82/07/22, 8208040473

--8208040479 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-C7, "Security Director" & Revision 0 to EPIP 500-9, "Operational Check of Notification Phone List." Receipt form encl.
SCOTT, D. J. Commonwealth Edison Co. 82/07/10. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 5pp. 14220 295. 24X
Fiche: 50-010, 82/07/22, 8208040473.

--8208040483 Public version of Revision 2 to Emergency Plan Implementing Procedure EPIP 100-C7, "Security Director" & Revision 0 to EPIP 500-9, "Operational Check of Notification Phone List."
* Commonwealth Edison Co. 82/07/07. 6pp. 14220 300. 24X
Fiche: 50-010, 82/07/22, 8208040473.

8208270134 Forwards 1E Insp Repts 50-010/82-11, 50-237/82-15 & 50-249/82-16 on 820624, 29, 30 & 0709 & notice of significant test deficiency.
HIND, J. A. Division of Emergency Preparedness & Operational Support. 82/08/03. REED, C. Commonwealth Edison Co. 3pp. 14563 338. 24X
Fiche: 50-010, 82/08/03, 8208270134.

--8208270142 1E Insp Repts 50-010/82-11, 50-237/82-15 & 50-249/82-16 on 820624, 29, 30 & 0709 Significant test deficiency noted: Failure of seven prompt public notification sys sirens.
JANUSKA, A. D., AXELSON, W. L. Division of Emergency Preparedness & Operational Support. 82/07/23. 12pp. 14563 341. 24X
Fiche: 50-010, 82/08/03, 8208270134.

8208250559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures."
FELTON, J. M. Division of Rules and Records. 82/08/12. Document Management Branch. 1p. 14559 354. 24X Fiche: 50-000, 82/08/12, 8208250559.

--8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures."
MOORE, R. D. Commonwealth Edison Co. 82/07/19. DENTON, H. R. NRC - No Detailed Affiliation Given. 1p. 14559 355. 24X
Fiche: 50-000, 82/08/12, 8208250559.

--8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures."
* Commonwealth Edison Co. 82/06/30. 7pp. 14559 356. 24X
Fiche: 50-000, 82/08/12, 8208250559.

8208230107 Forwards revised cable discrepancy lists re fire protection safe shutdown analyses. Lists indicate how each discrepancy noted in fire protection associated circuit analysis & mod repts will be resolved.
RAUSCH, T. J. Commonwealth Edison Co. 82/08/13. EIBENHUT, D. Q. Division of Licensing. 2pp. 14513 001. 24X Fiche: 50-000, 82/08/13, 8208230107.

--8208230119 "Fire Protection Cable Discrepancy List, Dresden Unit 3."
* Commonwealth Edison Co. 82/08/04. 150pp. 14513 144. 24X
Fiche: 50-000, 82/08/13, 8208230107.

O. Adjudicatory correspondence

8208190125 Final initial decision ordering NRR issue license amend authorizing installation of 33 high density storage racks in each spent fuel pool.
WOLFE, J. F., REMICK, F. J., LITTLE, L. W. Atomic Safety and Licensing Board Panel. 82/08/17. 29pp. 14381 043. 24X Fiche: 50-237, 82/08/17, 8208190125.

8208240267 Response to ASLB 820728 order. Requests leave to witi application w/o prejudice Need for transshipment in term reduced due to approval of installation of hi- density spent fuel racks. Certificate of Svc encl.
STEPTOE, P. Commonwealth Edison Co. STEPTOE, P. 1 Beale. 82/08/18. Atomic Safety and Licensing B. 14527 120. 24X Fiche: 50-000, 82/08/18, 8208240267.

DOCKETED ITEMS

B208240233 Notice of ASL&B constitution AS Rosenthal, chairman & TS Moore & RL Gotchy, members
SHOENAKER, C J Atomic Safety and Licensing Appeal Panel B2/08/20.
Ip 14519.148 24X Fiche 50-237.82/08/20. B208240233

B208240265 Response to ASLB B20728 order NRC does not object to proceeding termination since licensee has moved to withdraw license application w/o prejudice. Due to decision in Dresden high density storage rack case w/Certificate of Evc WRIGHT, N A Hearing Branch 2 B2/08/20 Atomic Safety and Licensing Board Panel 3pp 14527.126 24X Fiche 50-000.82/08/20. B208240265

P Operating license stage documents & correspondence

B207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR Evc list encl.
DIRKIN, W J Office of the Executive Director for Operations B2/07/02. Consolidated Edison Co. of New York 93pp 14194.001 24X Fiche 50-000.82/07/02. B207080064

B208050115 Forwards "Dresden Unit 3 Reactor Containment Bldg Integrated Leak Rate Test," conducted during B20423-25, per requirement of 10CFR50. App J, Section V.B.3
SCOTT, D. J. Commonwealth Edison Co B2/07/09 DENTON, H R Office of Nuclear Reactor Regulation, Director Ip 14213.125 24X Fiche 50-249.82/07/09. B208050115

--B208050118 "Dresden Unit 3 Reactor Containment Bldg Integrated Leak Rate Test," conducted during B20423-25
* Commonwealth Edison Co B2/04/25 53pp. 14213.126 24X Fiche 50-249.82/07/09. B208050118

B208050057 Forwards request for addl info re THF Item II D 1. "Performance Testing of BWR & PWR Safety/Relief Valves"
Applicability of generic results reported in NEDE-24988-P must be demonstrated for specific valves at facility
VASSALLO, D B Operating Reactors Branch 2 B2/07/27 DELGEORGE, L Commonwealth Edison Co 3pp 14244.047. 24X Fiche 50-237.82/07/27. B208050057

B208180266 Forwards revised version of model Tech Specs for reactor protection sys/power monitoring sys design
VASSALLO, D B Operating Reactors Branch 2 B2/07/28 DELGEORGE, L Commonwealth Edison Co 3pp 14389.318 24X Fiche 50-000.82/07/28. B208180266

--B208180271 Revised model Tech Specs re electric power monitoring of reactor protection sys design.
* Operating Reactors Branch 2 B2/07/28 Ip 14389.321 24X Fiche 50-000.82/07/28. B208180266

B208110041 Forwards response to request to cross-ref info re environ qualification of safety-related equipment & THF action plan equipment.
SWARTZ, E D Commonwealth Edison Co. B2/08/02 EISENHUT, D O Division of Licensing 557pp 14315.001. 24X Fiche 50-000.82/08/02. B208110041

B208130046 Requests approval to delay implementation of commitments in response to Generic Ltr B2-05 re NUREG-0737, Item II.F.1.6, "Containment Hydrogen Monitor." Completion postponed until B40101 to accommodate schedule requirements
SWARTZ, E D Commonwealth Edison Co B2/08/05 EISENHUT, D O Division of Licensing 2pp. 14335.353 24X Fiche 50-000.82/08/05. B208130046

B208110188 Forwards revised pages to CE-I-A. "Comm Ed QA Program for Nuclear Generating Stations." Revision 21 Revised pages correct typographical & other minor errors
SWARTZ, E D Commonwealth Edison Co B2/08/06 HAAS, W P. Quality Assurance Branch Ip 14314.079 24X Fiche 50-000.82/08/06. B208110188

--B208110204 Revised pages to CE-I-A. Revision 21. "Comm Ed QA Program for Nuclear Generating Stations"
* Commonwealth Edison Co B2/06/06 11pp 14314.080 24X Fiche 50-000.82/08/06. B208110188

B208240464 Requests appropriate action be taken re acceptable vent sys for isolation condenser per hydrogen rule & NUREG-0737 guidance (THF Item II B 1) or exemptions from applicable provisions of 10CFR50.44 should be requested
VASSALLO, D B Operating Reactors Branch 2 B2/08/06 DELGEORGE, L Commonwealth Edison Co 3pp. 14344.170. 24X Fiche 50-237.82/08/06. B208240464

B208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Evc list encl.
EISENHUT, D O Division of Licensing. B2/08/09. Consolidated Edison Co. of New York Ip 14336.332 24X Fiche 50-000.82/08/09. B208090194

B208170085 Forwards "Dresden Unit 3 Cycle 8 Startup Testing Summary"
RAUSCH, T J Commonwealth Edison Co B2/08/10 VASSALLO, D B Operating Reactors Branch 2 Ip 14358.139 24X Fiche 50-249.82/08/10. B208170085

--B208170088 "Dresden Unit 3 Cycle 8 Startup Testing Summary"
* Commonwealth Edison Co. B2/08/10 10pp. 14358.136 24X Fiche 50-249.82/08/10. B208170085

B208170135 Responds to NRC B20721 request to provide notification if unit intends to deviate from NUREG-0737, Item III.D.3.3, "Improved In-Plant Iodine Instrumentation Under Accident Conditions." Both facilities comply w/requirement.
SWARTZ, E D Commonwealth Edison Co. B2/08/12 EISENHUT, D O. Division of Licensing 2pp 14365.211 24X Fiche 50-000.82/08/12. B208170135

B208230349 Forwards revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of previously submitted inservice insp & testing program for second 10 yrs Revision necessary to enable insp of LPCI/CCSW HX tube welds
RAUSCH, T J Commonwealth Edison Co B2/08/16 EISENHUT, D O Division of Licensing 2pp 14512.357 24X Fiche 50-237.82/08/16. B208230349

--B208230359 Revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of inservice insp & testing program for second 10 years.
* Commonwealth Edison Co B2/08/16 3pp 14512.359 24X Fiche 50-237.82/08/16. B208230349

B208270250 Application for amend to License DPR-29, proposing Tech Spec changes to implement 10CFR50.59 reload licensing w/ODYN transient analyses & extended exposure MAPLING limits
Significant changes discussed Class III amend fee encl
RAUSCH, T J. Commonwealth Edison Co. B2/08/19. DENTON, H R Office of Nuclear Reactor Regulation, Director. 3pp. 14564.001. 24X Fiche 50-000.82/08/19. B208270250

--B208270273 Errata & Addenda Sheet 7, replacing Pages 4-11 & 4-14 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations."
* General Electric Co. NE00-24246A ERR 07 B2/07/31. 5pp. 14564.026. 24X Fiche 50-000.82/08/19. B208270250.

B208270296 Informs that analysis to determine appropriate equipment qualification temp profiles will be submitted in Sept 1982, not Jul 1982, as previously indicated
RAUSCH, T J Commonwealth Edison Co B2/08/23. VASSALLO, D B. Division of Licensing Ip. 14564.177. 24X Fiche 50-000.82/08/23. B208270296.

B208310230 Application for amend to Licenses DPR-19 & DPR-29 re installation & use of high density fuel storage racks
RAUSCH, T J. Commonwealth Edison Co B2/08/26 EISENHUT, D O Division of Licensing 2pp 14695.115. 24X Fiche 50-237.82/08/26. B208310230

Q Inspection reports, IE Bulletins & correspondence

B208050414 Forwards IE Insp Repts 50-237/81-39, 50-249/81-32, 50-263/81-23, 50-295/81-31 & 50-304/81-29 on B10813-B20503. No noncompliance noted
KEPPLER, J O Region J. Office of Director B2/07/12 REED, C Commonwealth Edison Co. Ip 14217.166 24X Fiche 50-000.82/07/12. B208050414.

--B208050441 IE Insp Repts 50-237/81-39, 50-249/81-32, 50-263/81-23, 50-295/81-31 & 50-304/81-29 on B10813-B20503
No noncompliance noted Major areas inspected: allegations re Comm Ed operation of facilities & compliance w/10CFR21.
HAYES, D W., PHILLIP, G A., HINDS, J M. Division of Project & Resident Programs B2/07/09. 154pp. 14217.169. 24X Fiche 50-000.82/07/12. B208050414

B204210393 IE Info Notice B2-23. "Main Steam Isolation Valve (MSIV) Leakage." Evc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. B2/07/16. Consolidated Edison Co. of New York 87pp. 14256.274. 24X Fiche 50-000.82/07/16. B204210393.

Michigan, Univ of 112pp 14388 001 24X Fiche 50-000.82/07/29.8204210395

82050393 Forwards IE Insp Repts 50-010/82-06,50-237/82-10 & 50-249/82-11 on 820507-0604 & notice of violation
PESSEBARD, R L Division of Project & Resident Programs 82/07/19
REED, C Commonwealth Edison Co 2pp 14209.191. 24X
Fiche 50-010.82/07/19.8208050393

208050398 Notice of violation from insp on 820507-0604
* Division of Project & Resident Programs 82/07/19 2pp.
14209.193 24X Fiche 50-010.82/07/19.8208050393

208050403 IE Insp Repts 50-010/82-06,50-237/82-10 & 50-249/82-11 on 820507-0604 Noncompliance noted: failure to follow hose color code.
TONQUE, T. M., JORDAN, M J., WALKER, R D Division of Project & Resident Programs 82/07/11 9pp 14209.195 24X
Fiche 50-010.82/07/19.8208050393

820410396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20.
Consolidated Edison Co of New York. 112pp 14381.001 24X
Fiche 50-000.82/07/20.8204210396

820410397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl
OBB, L I. Division of Fuel Facilities, Materials & Safeguards 82/07/20.
Consolidated Edison Co of New York 71pp 14357.276
24X Fiche 50-000.82/07/20.8204210397.

820410398 IE Info Notice 82-26, "RCIC & IPCI Turbine Exhaust Check Valve Failures " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/22.
Consolidated Edison Co of New York 112pp 14194.321. 24X
Fiche 50-000.82/07/22.8204210398

820410401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co of New York. 122pp 14380.115 24X
Fiche 50-000.82/07/23.8204210401

820410402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHRs " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co of New York 127pp 14194.120. 24X
Fiche 50-000.82/07/23.8204210402

8208100289 Forwards IE Insp Repts 50-010/82-09,50-237/82-13 & 50-249/82-14 on 820616-17 & 21-25. No noncompliance noted.
MILLER, J. R. Division of Engineering & Technical Programs. 82/07/23.
REED, C Commonwealth Edison Co 2pp 14294.191 24X
Fiche 50-010.82/07/23.8208100289

8208100299 IE Insp Repts 50-010/82-09,50-237/82-13 & 50-249/82-14 on 820616-17 & 21-25. No noncompliance noted. Major areas inspected action on previous findings, open items & hydrogen gas addition into reactor feedwater sys
PAUL, R. A., GREGER, L. R. Division of Engineering & Technical Programs. 82/07/22 7pp. 14294.193 24X Fiche 50-010.82/07/23.8208100289.

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PHR Power Plants." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26.
Consolidated Edison Co of New York. 121pp 14357.013. 24X
Fiche 50-000.82/07/26.8204210403

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28.
Consolidated Edison Co of New York. 122pp. 14357.146 24X
Fiche 50-000.82/07/28.8204210405

8208100252 Forwards IE Insp Rept 50-249/82-08 on 820420-0521 & notice of violation
NDRELIUS, C. E. Division of Engineering & Technical Programs 82/07/29 REED, C Commonwealth Edison Co. 2pp. 14297.001. 24X
Fiche 50-249.82/07/29.8208100252

8208100257 Notice of violation from insp on 820420-0521.
NDRELIUS, C. E. Division of Engineering & Technical Programs 82/07/29. 2pp. 14297.003. 24X Fiche 50-249.82/07/29.8208100252.

JACKW. I. N. MAURA, F. ROBINSON, D. Region 3. Office of Director. 82/06/28 8pp 14297.005. 24X Fiche 50-249.82/07/29.8208100252.

8208270134 Forwards IE Insp Repts 50-010/82-11,50-237/82-15 & 50-249/82-16 on 820624.29.30 & 0709 & notice of significant test deficiency.
HIND, J. A. Division of Emergency Preparedness & Operational Support. 82/08/03. REED, C Commonwealth Edison Co 3pp. 14563.338 24X
Fiche 50-010.82/08/03.8208270134

--8208270142 IE Insp Repts 50-010/82-11,50-237/82-15 & 50-249/82-16 on 820624.29.30 & 0709 Significant test deficiency noted.
failure of seven prompt public notification sys sirens.
JANUSKA, A O., GRANT, W B., NICHOLSON, N. A. Division of Emergency Preparedness & Operational Support. 82/07/23 12pp. 14963.341.
24X Fiche 50-010.82/08/03.8208270134

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement " Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/05.
Consolidated Edison Co of New York 117pp 14388.201 24X
Fiche 50-000.82/08/05.8204210407

8208200241 Advises of error in NRC 820719 ltr transmitting IE Insp Repts 50-010/82-06,50-237/82-10 & 50-249/82-11 Page 2 should be replaced w/encl page
PESSEBARD, R. L. Division of Project & Resident Programs 82/08/13
REED, C Commonwealth Edison Co 2pp 14399.031 24X
Fiche 50-010.82/08/13.8208200241

8208230349 Forwards revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of previously submitted inservice insp & testing program for second 10 yrs Revision necessary to enable insp of LPCI/CCSW HX tube welds
RAUSCH, T. J. Commonwealth Edison Co 82/08/16 EISENHUT, D. G. Division of Licensing. 2pp. 14512.357. 24X Fiche: 50-237.82/08/16.8208230349

--8208230359 Revised Pages 24 of 44 for Unit 2 & 24 of 43 for Unit 3 of inservice insp & testing program for second 10 years
* Commonwealth Edison Co 82/08/16. 3pp. 14512.359 24X
Fiche. 50-237.82/08/16.8208230349.

8208310212 Forwards final response to IE Bulletin 80-06, "ESF Reset Controls " Testing of listed mods performed after installation & specifically demonstrated equipment will not reposition from emergency position w/initial signal reset.
SWARTZ, E. D. Commonwealth Edison Co 82/08/20. KEPLER, J. O. Region 3. Office of Director 5pp. 14693.148. 24X Fiche: 50-237.82/08/20.8208310212.

8208310218 Forwards suppl to util 820926 response to IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Bys Components by Corbicular Sp (Asiatic Clam) & Mytilus Sp (Mussel)."
SWARTZ, E. D. Commonwealth Edison Co 82/08/23 KEPLER, J. O. Region 3. Office of Director 7pp 14693.130 24X Fiche: 50-010.82/08/23.8208310218.

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records 82/07/13. UBELL, R. A. Critical Mass Energy Project. 8pp 14679.208. 24X
Fiche 50-000.82/07/13.8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given 82/07/13. 48pp.
14679.216 24X Fiche: 50-000.82/07/13.8208270010.

--8208270559 Forwards "Recorded Annual Whole Body External Exposure for CY81," per 10CFR20.407(b). W/o Quad Cities, Zion, LaSalle, Byron & Braidwood repts
RAUSCH, T. J. Commonwealth Edison Co. 82/03/31. Office of Management and Program Analysis. 1p. 14680.075. 24X
Fiche 50-000.82/07/13.8208270010

--8208270567 "Recorded Annual Whole Body External Exposure for CY81."
* Commonwealth Edison Co. 82/03/31. 1p. 14680.076. 24X
Fiche 50-000.82/07/13.8208270010.

8208170242 Forwards monthly operating repts for Jul 1982.
SCOTT, D. J. Commonwealth Edison Co. 82/08/01. Director's Office, Office of Inspection and Enforcement. 1p. 14369.228 24X
Fiche: 50-010.82/08/01.8208170242.

--8208170245 Monthly operating repts for Jul 1982

SCHROEDER, B. A. Commonwealth Edison Co. 82/08/01. 18pp.
14369.229. 24X Fiche: 50-010, 82/08/01, 8208170242.

9 Reportable occurrences, LERs & related correspondence

8208310222 Forwards LER 82-018/03X-1.

SCOTT, D. J. Commonwealth Edison Co. 82/07/12. KEPLER, J. O. Region
3, Office of Director. 1p. 14695.125. 24X Fiche: 50-249, 82/07/12.
8208310222.

--8208310228 LER 82-018/03X-1 on 820414, during refueling outage, quarterly
valve timing per Procedure DOB 1600-1, nitrogen inerting stop
valve J-1601-55 closure time exceeded Tech Specs. Caused by
hardening of internal seals. Valve actuator replaced.
WHALEN, R. Commonwealth Edison Co. 82/07/30. Region 3, Office
of Director. 2pp. 14695.126. 24X Fiche: 50-249, 82/07/12.
8208310222.

8208020246 Forwards LER 82-029/01T-0

SCOTT, D. J. Commonwealth Edison Co. 82/07/22. KEPLER, J. O. Region
3, Office of Director. 1p. 14150.053. 24X Fiche: 50-249, 82/07/22.
8208020246.

--8208020254 LER 82-029/01T-0 on 820712, while testing scram discharge vol
level scram switches for proper tripping upon water loading.
B2C & B0D Magnetrol switches did not trip. Cause not
determined. Visual insp revealed no abnormalities.
WHALEN, R. Commonwealth Edison Co. 82/07/22. Region 3, Office
of Director. 4pp. 14150.054. 24X Fiche: 50-249, 82/07/22.
8208020246.

8208230273 Forwards updated LER 82-025/03X-1

SCOTT, D. J. Commonwealth Edison Co. 82/07/27. KEPLER, J. O. Region
3, Office of Director. 1p. 14513.205. 24X Fiche: 50-249, 82/07/27.
8208230273.

--8208230279 Updated LER 82-025/03X-1 on 820605, while performing plant
insp, water discovered dripping from insulation in vicinity
of isolation valve. Caused by cracked fillet weld on 1-inch
drain line off M03-3206A isolation valve. Weld reworked.
CHRISTEL, B. Commonwealth Edison Co. 82/07/16. Region 3, Office
of Director. 3pp. 14513.206. 24X Fiche: 50-249, 82/07/27.
8208230273.

8208060030 Forwards incident reporting sys repts re effects of fire
protection sys actuation on safety-related equipment &
seismic qualification of safety-related sys for transmission
to NEA.

MICHELSON, C. Director's Office. 82/07/29. LAFLEUR, J. D. Office of
International Programs, Director. 21pp. 14244.315. 24X
Fiche: 50-000, 82/07/29, 8208060030.

8208130322 Forwards LER 82-028/03L-0

SCOTT, D. J. Commonwealth Edison Co. 82/08/05. KEPLER, J. O. Region
3, Office of Director. 1p. 14336.326. 24X Fiche: 50-249, 82/08/05.
8208130322.

--8208130324 LER 82-028/03L-0 on 820708, LPC1 & core spray pressure switch
1554 F tripped above Tech Spec limit. Caused by linkage
sticking due to poor past work practices. Linkage freed &
switch tested. Work practices improved.
COYLE, L. Commonwealth Edison Co. 82/08/05. Region 3, Office of
Director. 2pp. 14336.327. 24X Fiche: 50-249, 82/08/05, 8208130322.

8208230029 Forwards LER 82-032/03L-0.

SCOTT, D. J. Commonwealth Edison Co. 82/08/06. KEPLER, J. O. Region
3, Office of Director. 1p. 14517.264. 24X Fiche: 50-249, 82/08/06.
8208230029.

--8208230033 LER 82-032/03L-0 on 820718, during attempt to open J-1601-23
valve, valve cycled from open to close w/o operator action.
Caused by leakage of air from weep hole of Versa valve, due
to hardening of O-ring seal. Versa valve replaced.
TANQ, WEE, D. Commonwealth Edison Co. 82/08/06. Region 3, Office
of Director. 2pp. 14517.265. 24X Fiche: 50-249, 82/08/06.
8208230029.

8208230292 Forwards LER 82-031/03L-0.

SCOTT, D. J. Commonwealth Edison Co. 82/08/06. KEPLER, J. O. Region
3, Office of Director. 1p. 14509.338. 24X Fiche: 50-249, 82/08/06.
8208230292.

--8208230297 LER 82-031/03L-0 on 820718, several spurious trips of main
steam line high flow isolation switch occurred. Caused by
disconnection of mechanical linkage between torque tube
mechanism & electrical switch. Linkage replaced.
PEDIRO, B. Commonwealth Edison Co. 82/08/06. Region 3, Office
of Director. 1p. 14509.339. 24X Fiche: 50-249, 82/08/06.
8208230292.

8208230390 Forwards LER 82-030/03L-0

SCOTT, D. J. Commonwealth Edison Co. 82/08/06. KEPLER, J. O. Region
3, Office of Director. 1p. 14513.007. 24X Fiche: 50-249, 82/08/06.
8208230390.

--8208230401 LER 82-030/03L-0 on 820716, transient in-core probe ball
valve JA failed to reclose after opening. Cause will be
resolved during next outage. Valve will be replaced &
supplemental LER submitted when cause determined.
MORQAN, W. Commonwealth Edison Co. 82/08/06. Region 3, Office
of Director. 2pp. 14513.008. 24X Fiche: 50-249, 82/08/06.
8208230390.

8208310048 Forwards LER 82-033/03L-0

SCOTT, D. J. Commonwealth Edison Co. 82/08/17. KEPLER, J. O. Region
3, Office of Director. 1p. 14694.355. 24X Fiche: 50-249, 82/08/17.
8208310048.

--8208310052 LER 82-033/03L-0 on 820727, sporadic Group 1 isolation
signals occurred on one channel & relay 595-101B dropped in
& out. Caused by faulty main steamline temp switch 261-188.
Contacts jumped until next shutdown. Insp planned.
SCHROEDER, B. Commonwealth Edison Co. 82/08/17. Region 3,
Office of Director. 2pp. 14694.356. 24X Fiche: 50-249, 82/08/17.
8208310048.

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

8208030404 Forwards IE Safeguards Insp Repts 50-250/82-27 &

50-251/82-27 on 820712-16. No noncompliance noted.
GANCE, H. C. Division of Project & Resident Programs. 82/07/29.
UHRIG, R. E. Florida Power & Light Co. 2pp. 14154.008. 24X
Fiche: 50-250, 82/07/29, 8208030404.

--8208030417 IE Safeguards Insp Repts 50-250/82-27 & 50-251/82-27 on
820712-16. No noncompliance noted. Major areas inspected:
security plan & implementing procedures, security
organization & personnel. Details withheld (ref IOCFR73 21).
STANSBERRY, W. W. MCQUIRE, D. R. Division of Engineering & Technical
Programs. 82/07/29. 1p. 14154.010. 24X Fiche: 50-250, 82/07/29.
8208030404.

8208090061 Forwards Revision 5 to security plan & discussion on Section
B.4.(d) referenced in SA Verge 820317 ltr. Encls withheld
(ref IOCFR73 21).
UHRIG, R. E. Florida Power & Light Co. 82/07/30. EISENHUT, D. O.
Division of Licensing. 1p. 14270.397. 24X Fiche: 50-250, 82/07/30.
8208090061.

8208110240 Releases public version of emergency plan implementing

procedure.
FELTON, J. H. Division of Rules and Records. 82/08/05. Document
Management Branch. 1p. 14331.030. 24X Fiche: 50-250, 82/08/05.
8208110240.

--8208110242 Forwards public version of Emergency Plan Implementing
Procedure 20126, "Offsite Dose Calculations," per 820727
telcon.
UHRIG, R. E. Florida Power & Light Co. 82/07/28. O'REILLY, J. P.
Region 2, Office of Director. 1p. 14331.032. 24X
Fiche: 50-250, 82/08/05, 8208110240.

--8208110244 Public version of Emergency Plan Implementing Procedure
20126, "Offsite Dose Calculations."
HAYB, J. C., WILLIAMS, J. H. Florida Power & Light Co. 82/03/17.
28pp. 14331.033. 24X Fiche: 50-250, 82/08/05, 8208110240.

8208230007 Forwards corrected discussion of Section B.4(d) of physical
security plan referenced in 8 Verge 820517 ltr. Discussion
withheld (ref IOCFR73 21).
UHRIG, R. E. Florida Power & Light Co. 82/08/16. EISENHUT, D. O.
Division of Licensing. 1p. 14517.273. 24X Fiche: 50-250, 82/08/16.
8208230007.

H General correspondence

8207300503 Responds to 820618 ltr re steam generator tube degradation
at plant. Encl safety evaluation & Amend 80 provides basis
for approval to operate Unit 4 until Oct 1982. Special
actions based on Qinna event under consideration w/o encl.
DIRCKB, W. J. Office of the Executive Director for Operations.
82/07/09. FABCELL, D. B. House of Rep. 7pp. 14172.001. 24X
Fiche: 50-250, 82/07/09, 8207300503.

DOCKETED ITEMS

55

--8206200036 Expresses constituent concern re steam generator tube degradation problem at plant Basis of NRC decision allowing Unit 4 to operate until Oct 1982 & hearing of event at Ginna on plant requested
FASCELL, D B House of Rep 82/06/18 PALLADINO, N
Commissioners 2pp. 14172:007 24X Fiche 50-250.82/07/09.
8207300503

p Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRGR. Svc list encl
DIRCKS, W J Office of the Executive Director for Operations
82/07/02 Consolidated Edison Co of New York 93pp. 14194:001
24X Fiche 50-000.82/07/02.8207080064

8208030050 Consents to provide FERC w/access to documentation provided by util & required by FERC & PSC of FL to retain, as backup to util record retention sys Util could establish symbiotic relationship to alleviate recordkeeping burden
MAASS, W P Quality Assurance Branch 82/07/13 UHRIO, R E Florida Power & Light Co. 2pp. 14208:030. 24X Fiche 50-000.82/07/13.
8208030050

8208110213 Forwards evaluation of proposed Tech Specs re organizational changes, per 820216 ltr Proposal to eliminate Figure 6-2-1 & composition of FL Power & Light Nuclear Review Board unacceptable.
VARQA, S A Operating Reactors Branch 1. 82/07/20. UHRIO, R E. Florida Power & Light Co. 4pp. 14328:360 24X
Fiche 50-250.82/07/20.8208110213

8208100130 Informs that info requested in 820630 ltr re NUREG-0737, Item II.B.3. "Post-Accident Sampling Sys." will be transmitted on or before 821115
UHRIO, R E Florida Power & Light Co. 82/08/02. VARQA, S A. Operating Reactors Branch 1. 14298:179. 24X
Fiche 50-250.82/08/02.8208100130.

8208100075 Advises that radiological effluent Tech Spec & offsite dose calculation manual will be submitted by 820910.
UHRIO, R E Florida Power & Light Co 82/08/05 EISENHUT, D O
Division of Licensing. 1p. 14296:174 24X Fiche:50-250.82/08/05.
8208100075

8208130039 Application for amend to Licenses DPR-31 & DPR-41, revising Tech Spec Tables 3.5-2 re emergency buses, 3.5-4 re undervoltage relay setpoints & 4.1-1 re 4.16-kV & 480-volt load ctr test requirements.
UHRIO, R E. Florida Power & Light Co. 82/08/06. EISENHUT, D O.
Division of Licensing 2pp 14335:075 24X Fiche. 50-250.82/08/06.
8208130039.

--8208130042 Tech Spec Tables 3.5-2 re emergency buses, 3.5-4 re undervoltage relay setpoints & 4.1-1 re 4.16-kV & 480-volt load ctr test requirements.
* Florida Power & Light Co. 82/08/06. 5pp. 14335:077 24X
Fiche: 50-250.82/08/06.8208130039

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes IOCFR Chapter 1 requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D O Division of Licensing. 82/08/09. Consolidated Edison Co of New York 1p. 14356:332. 24X Fiche: 50-000.82/08/09.
8208090194

8208170102 Forwards addl info re scheduler commitments for items in draft technical evaluation rept on control of heavy loads.
UHRIO, R E. Florida Power & Light Co. 82/08/10. VARQA, S A. Operating Reactors Branch 1. 15pp. 14366:003. 24X
Fiche: 50-250.82/08/10.8208170102.

8208170116 Advises that response to Question 1 of NRC 820316 request for addl info re containment purge & vent valve operability will be submitted by 821001 Util awaiting analysis from valve manufacturer, due in early Sept 1982.
UHRIO, R E. Florida Power & Light Co. 82/08/10. VARQA, S A. Operating Reactors Branch 1. 1p. 14358:187. 24X
Fiche: 50-250.82/08/10.8208170116

8208170123 Proposes mod to turbine runback sys, deleting flux rate input. Sys prone to spurious runbacks due to single failure of electrical component. Encl safety evaluation discusses consequences of single dropped rod control cluster assembly.
UHRIO, R E. Florida Power & Light Co. 82/08/10 EISENHUT, D O.
Division of Licensing. 4pp. 14363:199. 24X Fiche: 50-250.82/08/10.
8208170123.

8208200133 Advises that final heat tracing components necessary for completion of containment hydrogen monitor, per NUREG-0737, Item II.F.1.6, received from manufacturer on 820801 Estimated completion of installation rescheduled until 820930
UHRIO, R E. Florida Power & Light Co. 82/08/12. VARQA, S A. Operating Reactors Branch 1. 1p. 14500:087. 24X
Fiche. 50-250.82/08/12.8208200133

8208200295 Application for amend of Licenses DPR-31 & DPR-41, changing Tech Specs 6.5.2.3, 6.5.2.4, 6.5.2.5, 6.5.2.6 & Figure 6-2-1 to update offsite organization.
UHRIO, R E. Florida Power & Light Co. 82/08/12 EISENHUT, D O.
Division of Licensing 2pp 14394:354 24X Fiche 50-250.82/08/12.
8208200295

--8208200299 Proposed changes to Tech Specs 6.5.2.3, 6.5.2.4, 6.5.2.5, 6.5.2.6 & Figure 6-2-1 to update offsite organization.
* Florida Power & Light Co. 82/08/12 4pp 14394:356 24X
Fiche 50-250.82/08/12.8208200295

8208190152 Advises that NUREG-0737, Item II.D.1.B. "PWR Relief & Safety Valve Testing" is satisfied by submittal of "PORV Block Valve Info Package" & listed info
UHRIO, R E. Florida Power & Light Co. 82/08/13 EISENHUT, D O
Division of Licensing. 2pp. 14382:188 24X Fiche. 50-250.82/08/13.
8208190152

0 Inspection reports, IE Bulletins & correspondence

8208030200 Forwards IE Insp Repts 50-250/82-23 & 50-251/82-23 on 820615-17. No noncompliance noted
DANCE, H C Division of Project & Resident Programs 82/07/06.
UHRIO, R E Florida Power & Light Co. 2pp 14158:270 24X
Fiche. 50-250.82/07/06.8208030200

--8208030224 IE Insp Repts 50-250/82-23 & 50-251/82-23 on 820615-17. No noncompliance noted. Major areas inspected: seismic analysis for as-built safety-related piping (IE Bulletin 79-14) & pipe support baseplate design (IE Bulletin 79-02).
AND, W P., ECONDMQS, N Division of Engineering & Technical Programs 82/07/01 4pp. 14158:280 24X Fiche: 50-250.82/07/06.
8208030200

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/16.
Consolidated Edison Co of New York 87pp. 14356:274 24X
Fiche. 50-000.82/07/16.8204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/19.
Michigan Univ of 112pp. 14358:001. 24X Fiche 50-000.82/07/19.
8204210395.

8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/20.
Consolidated Edison Co. of New York. 112pp. 14381:001. 24X
Fiche: 50-000.82/07/20.8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl
COBB, L I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Consolidated Edison Co of New York. 71pp. 14357:276 24X Fiche: 50-000.82/07/20.8204210397.

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E L. Division of Engineering & Quality Assurance. 82/07/22.
Consolidated Edison Co. of New York. 112pp. 14194:321. 24X
Fiche. 50-000.82/07/22.8204210398.

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York. 122pp. 14380:113. 24X
Fiche: 50-000.82/07/23.8204210401.

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl.
JORDAN, E L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York. 127pp. 14194:120. 24X
Fiche: 50-000.82/07/23.8204210402.

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E L. Division of Engineering & Quality Assurance. 82/07/26.
Consolidated Edison Co. of New York. 121pp. 14194:121. 24X
Fiche: 50-000.82/07/26.8204210403.

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28
Consolidated Edison Co. of New York 122pp. 14397 146 24X
Fiche: 50-000, 82/07/28, 8204210405

8208160317 Forwards IE Insp Repts 50-250/82-25 & 50-251/82-25 on 820713-16 No noncompliance noted
DANCE, H. C. Division of Project & Resident Programs 82/07/28
UHRIG, R. E. Florida Power & Light Co 2pp 14348 146 24X
Fiche: 50-250, 82/07/28, 8208160317

--8208160416 IE Insp Repts 50-250/82-25 & 50-251/82-25 on 820713-16 No noncompliance noted Major areas inspected radiological environ monitoring mgt & administrative controls, QC of analytical measurements & monitoring stations.
CUNNINGHAM, A. L., MONTGOMERY, D. M. Division of Project & Resident Programs 82/07/28 5pp 14348 148 24X Fiche: 50-250, 82/07/28, 8208160317

8208030404 Forwards IE Safeguards Insp Repts 50-250/82-27 & 50-251/82-27 on 820712-16 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 82/07/29
UHRIG, R. E. Florida Power & Light Co 2pp 14154 008 24X
Fiche: 50-250, 82/07/29, 8208030404

--8208030417 IE Safeguards Insp Repts 50-250/82-27 & 50-251/82-27 on 820712-16 No noncompliance noted Major areas inspected, security plan & implementing procedures, security organization & personnel Details withheld (ref IOCFR73 21).
STANBERRY, W. W., MCQUIRE, D. R. Division of Engineering & Technical Programs 82/07/29 1p 14154 010 24X Fiche: 50-250, 82/07/29, 8208030404

8208160267 Forwards info in response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants." Control rod drive flanges have omega seal weld design No injection sealant matl used.
UHRIG, R. E. Florida Power & Light Co 82/08/02 O'REILLY, J. P.
Region 2, Office of Director 3pp 14347 039 24X
Fiche: 50-250, 82/08/02, 8208160267

8208160354 Ack receipt of 820618, 25 & 0715 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/82-21 & 50-251/82-21
DANCE, H. C. Division of Project & Resident Programs 82/08/03
UHRIG, R. E. Florida Power & Light Co 1p 14349 084 24X
Fiche: 50-250, 82/08/03, 8208160354

--8208160365 Forwards addl response to NRC 820314 ltr re violations noted in IE Insp Repts 50-250/82-21 & 50-251/82-21 Corrective actions: proposal for method of tracking plant work order will be incorporated into applicable plant procedures.
UHRIG, R. E. Florida Power & Light Co 82/07/15 O'REILLY, J. P.
Region 2, Office of Director 2pp 14349 085 24X
Fiche: 50-250, 82/08/03, 8208160354

--8208160376 Forwards response to NRC ltr re violations noted in IE Insp Repts 50-250/82-21 & 50-251/82-21 Corrective actions: recorder switches for listed circuits returned to proper positions. Response to Item B expected by 820714
UHRIG, R. E. Florida Power & Light Co 82/06/18 O'REILLY, J. P.
Region 2, Office of Director 3pp 14349 087 24X
Fiche: 50-250, 82/08/03, 8208160354

--8208160382 Forwards IE Insp Repts 50-250/82-21 & 50-251/82-21 on 820403-25 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs 82/05/14
UHRIG, R. E. Florida Power & Light Co 2pp 14349 090 24X
Fiche: 50-250, 82/08/03, 8208160354

--8208160386 Notice of violation from insp on 820403-25
"Division of Project & Resident Programs 82/05/14 2pp.
14349 092 24X Fiche: 50-250, 82/08/03, 8208160354

--8208160394 IE Insp Repts 50-250/82-21 & 50-251/82-21 on 820403-25. Noncompliance noted: failure to follow procedure, failure to meet requirements of GA manual & failure to maintain updated procedures.
VOGT, R. J., HARDIN, A. K. Division of Project & Resident Programs 82/03/12 6pp 14349 094 24X Fiche: 50-250, 82/08/03, 8208160354

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/05
Consolidated Edison Co. of New York 117pp. 14388 201 24X
Fiche: 50-000, 82/08/05, 8204210407

R. Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & affixing said info forwards documents listed in App A
FELTON, J. M. Division of Rules and Records 82/07/13 UDELL, R. A.
Critical Mass Energy Project Bpp 14679 208 24X
Fiche: 50-000, 82/07/13, 8208270010

--8208270066 Forwards "Man Rem Rept, 1981."
UHRIG, R. E. Florida Power & Light Co 82/03/02 O'REILLY, J. P.
Region 2, Office of Director 1p 14680 016 24X
Fiche: 50-000, 82/07/13, 8208270010

--8208270072 "Man Rem Rept, 1981."
"Florida Power & Light Co 82/03/02 1p 14680 017 24X
Fiche: 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
"NRC - No Detailed Affiliation Given 82/07/13 48pp.
14679 216 24X Fiche: 50-000, 82/07/13, 8208270010

--8208270540 Forwards personnel monitoring repts for 1981, per IOCFR20.407 W/o St Lucie rept.
UHRIG, R. E. Florida Power & Light Co 82/03/04 Office of
Management and Program Analysis 1p 14680 028 24X
Fiche: 50-000, 82/07/13, 8208270010

--8208270545 Personnel monitoring repts for 1981
"Florida Power & Light Co 82/03/04 1p 14680 029 24X
Fiche: 50-000, 82/07/13, 8208270010

8208120174 Forwards monthly operating repts for June 1982 & corrected Turkey Point 4 operating rept for May 1982.
WILLIAMS, J. W. Florida Power & Light Co 82/07/15 Office of
Resource Management, Director 1p 14326 001 24X
Fiche: 50-000, 82/07/15, 8208120174

--8208120181 Monthly operating repts for June 1982
PACE, P. Florida Power & Light Co 82/07/15 12pp 14326 002
24X Fiche: 50-000, 82/07/15, 8208120174

--8208120186 Corrected monthly operating rept for May 1982
PACE, P. Florida Power & Light Co 82/07/15 1p 14326 014 24X
Fiche: 50-000, 82/07/15, 8208120174

S. Reportable occurrences, LERs & related correspondence

8208200115 Forwards LER 82-011/03L-0
WILLIAMS, J. W. Florida Power & Light Co 82/08/12 O'REILLY, J. P.
Region 2, Office of Director 1p 14393 318 24X
Fiche: 50-250, 82/08/12, 8208200115

--8208200125 LER 82-011/03L-0 on 820713, quarterly surveillance test of telemograph completed 3 days after last Allowable Tech Spec date. Caused by const equipment blocking access to telemograph. Test successfully completed on 820716
PACE, P. L. Florida Power & Light Co 82/08/12 Region 2, Office
of Director 2pp 14393 319 24X Fiche: 50-250, 82/08/12, 8208200115

00CKET 50-251 TURKEY POINT PLANT, UNIT 4

F. Security, medical, emergency & fire protection plans

8208030404 Forwards IE Safeguards Insp Repts 50-250/82-27 & 50-251/82-27 on 820712-16 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs 82/07/29
UHRIG, R. E. Florida Power & Light Co 2pp 15154 008 24X
Fiche: 50-250, 82/07/29, 8208030404

--8208030417 IE Safeguards Insp Repts 50-250/82-27 & 50-251/82-27 on 820712-16 No noncompliance noted Major areas inspected: security plan & implementing procedures, security organization & personnel Details withheld (ref IOCFR73 21).
STANBERRY, W. W. Division of Engineering & Technical Programs 82/07/29 1p 15154 010 24X Fiche: 50-250, 82/07/29, 8208030404

8208090061 Forwards Revision 5 to security plan & discussion on Section 8.4 (d) referenced in SA Varge 820317 ltr. Encl withheld (ref IOCFR73 21).
UHRIG, R. E. Florida Power & Light Co 82/07/30 EISENHUT, D. G.
Division of Licensing 1p 14270 397 24X Fiche: 50-250, 82/07/30, 8208090061

08110240
08110242 Forwards public version of Emergency Plan Implementing Procedure 20126. "Offsite Dose Calculations," per 820727 telcon
UHR10, R E Florida Power & Light Co 82/07/20 O'REILLY, J P Region 2, Office of Director. 1p 14331.032 24X Fiche 50-250.82/08/05.8208110240

08110244 Public version of Emergency Plan Implementing Procedure 20126, "Offsite Dose Calculations"
HAYS, J C, WILLIAMS, J H. Florida Power & Light Co. 82/09/17. 28pp. 14331.033 24X Fiche 50-250.82/08/05.8208110240

8230007 Forwards corrected discussion of Section 8 4(d) of physical security plan referenced in B Varga 820517 ltr Discussion threshold (ref 10CFR73.21).
UHR10, R E Florida Power & Light Co 82/08/16 EISENHUT, D O Division of Licensing. 1p 14517.273. 24X Fiche 50-250.82/08/16.8208230007

General correspondence

8300503 Responds to 820618 ltr re steam generator tube degradation plant. Encl safety evaluation & Amend 80 provides basis for approval to operate Unit 4 until Oct 1982 Special actions based on Ginna event under consideration w/o encl.
RCKS, W J Office of the Executive Director for Operations. 82/07/09. FASCELL, D B House of Rep. 7pp 14172.001 24X Fiche 50-250.82/07/09.8207300503

82000036 Expresses constituent concern re steam generator tube degradation problem at plant. Basis of NRC decision allowing unit to operate Unit 4 until Oct 1982 & hearing of event at Ginna on plant requested
FASCELL, D B House of Rep 82/06/18 PALLADINO, N Commissioners 2pp 14172.007 24X Fiche 50-250.82/07/09.8207300503

Operating license stage documents & correspondence

82080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for QR Svc list encl.
RCKS, W J Office of the Executive Director for Operations. 82/07/02. Consolidated Edison Co of New York. 92pp 14194.001. 24X Fiche 50-000.82/07/02.8207080064

8300050 Consents to provide FERC w/access to documentation provided w/ util & required by FERC & FBC of FL to retain, as backup w/ util record retention sys Util could establish symbiotic relationship to alleviate recordkeeping burden
AGGS, W P Quality Assurance Branch 82/07/13 UHR10, R E Florida Power & Light Co. 2pp. 14208.330 24X Fiche 50-000.82/07/13.8208030050

82060028 Notification of 820723 meeting w/util in Bethesda, MD to discuss findings & corrective action per License Condition D.1 re steam generator leak
EISENHUT, D O Operating Reactors Branch 1. 82/07/20. VARGA, B A. Operating Reactors Branch 1 2pp. 14244.338 24X Fiche 50-251.82/07/20.8208060028

810213 Forwards evaluation of proposed Tech Specs re organizational changes, per 820216 ltr Proposal to eliminate Figure 6 2-1 & composition of FL Power & Light Nuclear Review Board acceptable
VARGA, B A Operating Reactors Branch 1 82/07/20. UHR10, R E Florida Power & Light Co. 4pp. 14320.360 24X Fiche 50-250.82/07/20.8208110213

8160286 Agrees to changes in dates proposed for Sections 1 & 3 per 81162030 ltr in response to 820408 confirmatory action
Section 2 remains unchanged
O'REILLY, J P Region 2, Office of Director. 82/07/22. HANCOCK, J A Florida Power Corp. 1p. 14346.275. 24X Fiche 50-302.82/07/22.8208160286

8100130 Informs that info requested in 820630 ltr re NURE0-0737, Item II. B.3, "Post-Accident Sampling Sys," will be submitted on or before 821115
UHR10, R E Florida Power & Light Co. 82/08/02. VARGA, B A. Operating Reactors Branch 1 1p. 14298.179. 24X Fiche 50-250.82/08/02.82081100130

8208100075
8208130039 Application for amend to Licenses DPR-31 & DPR-41, revising Tech Spec Tables 3 5-2 re emergency buses, 3 5-4 re undervoltage relay setpoints & 4 1-1 re 4 16-kV & 480-volt load ctr test requirements.
UHR10, R E Florida Power & Light Co. 82/08/06 EISENHUT, D O Division of Licensing. 2pp 14335.075 24X Fiche 50-250.82/08/06.8208130039

--8208130042 Tech Spec Tables 3 5-2 re emergency buses, 3 5-4 re undervoltage relay setpoints & 4 1-1 re 4 16-kV & 480-volt load ctr test requirements.
Florida Power & Light Co 82/08/06 9pp. 14339.077 24X Fiche 50-250.82/08/06.8208130039

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl
EISENHUT, D O Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356.332 24X Fiche 50-000.82/08/09.8208090194

8208170102 Forwards addl info re scheduler commitments for items in draft technical evaluation rept on control of heavy loads.
UHR10, R E Florida Power & Light Co 82/08/10 VARGA, B A Operating Reactors Branch 1 15pp 14366.003 24X Fiche 50-250.82/08/10.8208170102

8208170116 Advises that response to Question 1 of NRC 820316 request for addl info re containment purge & vent valve operability will be submitted by 821001 Util awaiting analysis from valve manufacturer, due in early Sept 1982
UHR10, R E Florida Power & Light Co 82/08/10. VARGA, B A Operating Reactors Branch 1 1p 14358.187 24X Fiche 50-250.82/08/10.8208170116

8208170123 Proposes mod to turbine runback sys, deleting flux rate input Sys prone to spurious runbacks due to single failure of electrical component. Encl safety evaluation discusses consequences of single dropped rod control cluster assembly
UHR10, R E Florida Power & Light Co. 82/08/10 EISENHUT, D O Division of Licensing 4pp. 14363.199. 24X Fiche 50-250.82/08/10.8208170123

8208200133 Advises that final heat tracing components necessary for completion of containment hydrogen monitor, per NURE0-0737, Item II F.1.6, received from manufacturer on 820801. Estimated completion of installation rescheduled until 820930
UHR10, R E Florida Power & Light Co. 82/08/12. VARGA, B A Operating Reactors Branch 1 1p 14500.087 24X Fiche 50-250.82/08/12.8208200133

8208200293 Application for amend of Licenses DPR-31 & DPR-41, changing Tech Specs 6 5.2.3.6 5.2.4.6 5.2.5.2 5.6 5.2.6 & Figure 6 2-1 to update offsite organization.
UHR10, R E Florida Power & Light Co. 82/08/12. EISENHUT, D O Division of Licensing. 2pp. 14394.334 24X Fiche 50-250.82/08/12.8208200293

--8208200299 Proposed changes to Tech Specs 6 5.2.3.6 5.2.4.6 5.2.5.2 5.6 & Figure 6 2-1 to update offsite organization.
Florida Power & Light Co 82/08/12 4pp 14394.366 24X Fiche 50-250.82/08/12.8208200299

8208190152 Advises that NURE0-0737, Item II D.1.B, "PWR Relief & Safety Valve Testing" is satisfied by submittal of "PORV Black Valve Info Package" & listed info
UHR10, R E Florida Power & Light Co. 82/08/13 EISENHUT, D O Division of Licensing. 2pp. 14382.108 24X Fiche 50-250.82/08/13.8208190152

Q. Inspection reports, IE Bulletins & correspondence

8208030200 Forwards IE Insp Repts 50-250/82-23 & 50-251/82-23 on 820615-17. No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 82/07/06. UHR10, R E Florida Power & Light Co. 2pp. 14158.278 24X Fiche 50-250.82/07/06.8208030200

--8208030224 IE Insp Repts 50-250/82-23 & 50-251/82-23 on 820615-17. No noncompliance noted. Major areas inspected seismic analysis for as-built safety-related piping (IE Bulletin 79-14) & pipe support baseplate design (IE Bulletin 79-02).
AND, W P, ECONDMOS, N. Division of Engineering & Technical Programs. 82/07/01. 4pp. 14158.280. 24X Fiche 50-250.82/07/06.8208030200

B204210393 IE Info Notice B2-23. "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16
Consolidated Edison Co. of New York 87pp 14356 274 24X
Fiche: 50-000, 82/07/16, B204210393

B204210395 IE Info Notice B1-26, Part 3, Suppl. 1. "Classification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19
Michigan Univ. of 112pp 14358 001 24X Fiche 50-000, 82/07/19, B204210395

B204210396 IE Info Notice B2-25. "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20
Consolidated Edison Co. of New York 112pp 14381 001 24X
Fiche: 50-000, 82/07/20, B204210396

B204210397 IE Info Notice B2-24. "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20
Consolidated Edison Co. of New York 71pp 14357 276 24X Fiche: 50-000, 82/07/20, B204210397

B204210398 IE Info Notice B2-26. "RCIC & iPC Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22
Consolidated Edison Co. of New York 112pp 14194 321 24X
Fiche: 50-000, 82/07/22, B204210398

B204210401 IE Info Notice B2-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23
Consolidated Edison Co. of New York 122pp 14380 115 24X
Fiche: 50-000, 82/07/23, B204210401

B204210402 IE Info Notice B2-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHRs." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23
Consolidated Edison Co. of New York 127pp 14194 120 24X
Fiche: 50-000, 82/07/23, B204210402

B204210403 IE Info Notice B2-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PHR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26
Consolidated Edison Co. of New York 121pp 14357 013 24X
Fiche: 50-000, 82/07/26, B204210403

B204210405 IE Info Notice B2-31. "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28
Consolidated Edison Co. of New York 122pp 14357 146 24X
Fiche: 50-000, 82/07/28, B204210405

B208160317 Forwards IE Insp Repts 50-250/82-23 & 50-251/82-25 on 820713-16 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 82/07/28
UHRIG, R. E. Florida Power & Light Co. 2pp 14348 146 24X
Fiche: 50-250, 82/07/28, B208160317

--B208160416 IE Insp Repts 50-250/82-25 & 50-251/82-25 on 820713-16. No noncompliance noted. Major areas inspected: radiological environ monitoring mpt & administrative controls, QC of analytical measurements & monitoring stations.
CUNNINGHAM, A. L., MONTGOMERY, D. M. Division of Project & Resident Programs. 82/07/28. 3pp. 14348 148. 24X Fiche: 50-250, 82/07/28, B208160317.

B208030404 Forwards IE Safeguards Insp Repts 50-250/82-27 & 50-251/82-27 on 820712-16. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 82/07/29.
UHRIG, R. E. Florida Power & Light Co. 2pp 14154 008 24X
Fiche: 50-250, 82/07/29, B208030404.

--B208030417 IE Safeguards Insp Repts 50-250/82-27 & 50-251/82-27 on 820712-16. No noncompliance noted. Major areas inspected: security plan & implementing procedures, security organization & personnel. Details withheld (ref 10CFR73.21).
STANBERRY, W. M., MCQUIRE, D. R. Division of Engineering & Technical Programs. 82/07/29. 1p. 14154 010. 24X Fiche: 50-250, 82/07/29, B208030404.

B208160267 Forwards info in response to IE Bulletin B2-02, "Degradation of Threaded Fasteners in RCPs of PHR Plants." Control rod drive flanges have on-site seal weld design. No injection sealant matl used.
UHRIG, R. E. Florida Power & Light Co. 82/08/02. O'REILLY, J. P. Region 2, Office of Director. 3pp 14347 035. 24X
Fiche: 50-250, 82/08/02, B208160267.

B208160354 Ack receipt of B20618.25 & 0715 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts
50-250/82-21 & 50-251/82-21
DANCE, H. C. Division of Project & Resident Programs. 82/08/03
UHRIG, R. E. Florida Power & Light Co. 1p 14349 084 24X
Fiche: 50-250, 82/08/03, B208160354

--B208160365 Forwards addl response to NRC B20814 ltr re violations noted in IE Insp Repts 50-250/82-21 & 50-251/82-21 Corrective actions proposal for method of tracking plant work order will be incorporated into applicable plant procedures.
UHRIG, R. E. Florida Power & Light Co. 82/07/19. O'REILLY, J. P. Region 2, Office of Director. 2pp 14349 085 24X
Fiche: 50-250, 82/08/03, B208160354

--B208160376 Forwards response to NRC ltr re violations noted in IE Insp Repts 50-250/82-21 & 50-251/82-21 Corrective actions: recorder switches for listed circuits returned to proper positions. Response to item B expected by 820714
UHRIG, R. E. Florida Power & Light Co. 82/06/18. O'REILLY, J. P. Region 2, Office of Director. 3pp 14349 087 24X
Fiche: 50-250, 82/08/03, B208160354

--B208160382 Forwards IE Insp Repts 50-250/82-21 & 50-251/82-21 on 820403-25 & notice of violation
LEWIS, R. C. Division of Project & Resident Programs. 82/05/14.
UHRIG, R. E. Florida Power & Light Co. 2pp 14349 090 24X
Fiche: 50-250, 82/08/03, B208160354

--B208160386 Notice of violation from insp on 820403-25.
* Division of Project & Resident Programs. 82/05/14. 2pp 14349 092. 24X Fiche: 50-250, 82/08/03, B208160354.

--B208160394 IE Insp Repts 50-250/82-21 & 50-251/82-21 on 820403-25. Noncompliance noted failure to follow procedure, failure to meet requirements of QA manual & failure to maintain updated procedures.
VOGT, R. J., HARDIN, A. K. Division of Project & Resident Programs. 82/05/12. 6pp. 14349 094. 24X Fiche: 50-250, 82/08/03, B208160354.

B204210407 IE Info Notice B2-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/05
Consolidated Edison Co. of New York 117pp 14308 201 24X
Fiche: 50-000, 82/08/05, B204210407.

B208160296 Forwards "Repts of Steam Generator Insp & Tube Repair - Jul 1982 Outage."
UHRIG, R. E. Florida Power & Light Co. 82/08/09. EISENHUT, D. Q. Division of Licensing. 1p 14345 322 24X Fiche: 50-251, 82/08/09, B208160296.

--B208160303 "Rept of Steam Generator Insp & Tube Repair - Jul 1982 Outage."
* Florida Power & Light Co. 82/07/31. 40pp 14345 323. 24X
Fiche: 50-251, 82/08/09, B208160296.

R Periodic operating reports & related correspondence

B208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A. Critical Mass Energy Project. 8pp. 14679 208. 24X
Fiche: 50-000, 82/07/13, B208270010.

--B208270066 Forwards "Man Rem Rept. 1981."
UHRIG, R. E. Florida Power & Light Co. 82/03/02. O'REILLY, J. P. Region 2, Office of Director. 1p. 14680 016. 24X
Fiche: 50-000, 82/07/13, B208270010

--B208270072 "Man Rem Rept. 1981."
* Florida Power & Light Co. 82/03/02. 1p 14680 017. 24X
Fiche: 50-000, 82/07/13, B208270010

--B208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp. 14679 216. 24X Fiche: 50-000, 82/07/13, B208270010.

--B208270540 Forwards personnel monitoring repts for 1981, per 10CFR20.407. W/o St Lucie rept
UHRIG, R. E. Florida Power & Light Co. 82/03/04. Office of Management and Program Analysis. 1p. 14680 028 24X
Fiche: 50-000, 82/07/13, B208270010.

--B208270545 Personnel monitoring repts for 1981.
* Florida Power & Light Co. 82/03/04. 1p. 14680 029. 24X
Fiche: 50-000, 82/07/13, B208270010.

8208120174 Forwards monthly operating repts for June 1982 & corrected Turkey Point 4 operating rept for May 1982.
WILLIAMS, J.W. Florida Power & Light Co. 82/07/15. Office of Resource Management, Director. 1p 14326 001 24X
Fiche: 50-000, 82/07/15, 8208120174

--8208120181 Monthly operating repts for June 1982.
PACE, P. Florida Power & Light Co. 82/07/15 12pp 14326 002
24X Fiche: 50-000, 82/07/15, 8208120174.

--8208120186 Corrected monthly operating rept for May 1982
PACE, P. Florida Power & Light Co. 82/07/15 1p 14326 014 24X
Fiche: 50-000, 82/07/15, 8208120174

5 Reportable occurrences, LERs & related correspondence

8208020177 Forwards LER 82-009/03L-0
WILLIAMS, J.W. Florida Power & Light Co. 82/07/23 O'REILLY, J.P.
Region 2, Office of Director. 1p 14141 200 24X
Fiche: 50-251, 82/07/23, 8208020177

--8208020180 LER 82-009/03L-0 on 820623, biweekly testing for Tave & Delta T protection channel was completed 2 days after latest date allowable caused by computation using completion date for previous test. Channel test completed 820625
PACE, P.L. Florida Power & Light Co. 82/07/23 Region 2, Office of Director 2pp 14141 201. 24X Fiche: 50-251, 82/07/23, 8208020177

8208200128 Forwards LER 82-010/03L-0
WILLIAMS, J.W. Florida Power & Light Co. 82/08/12 O'REILLY, J.P.
Region 2, Office of Director. 1p. 14393:348. 24X
Fiche: 50-251, 82/08/12, 8208200128

--8208200146 LER 82-010/03L-0 on 820713, camera insp of steam generators revealed foreign objects & minor tube damage. Leak & minor tube damage caused by foreign objects near tube sheet elevations. Metal impact monitoring sys installed
PACE, P.L. Florida Power & Light Co. 82/08/12 Region 2, Office of Director 4pp 14393:349 24X Fiche: 50-251, 82/08/12, 8208200128.

DOCKET 50-252 UNIV. OF NEW MEXICO RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8208170231 Forwards IE Safeguards Insp Rept 50-252/82-02 on 820617-18 & notice of violation. Rept & notice of violation withheld (ref 10CFR2.790).
SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 82/08/13. WOODALL, D. New Mexico, Univ. of. 2pp 14370:070. 24X Fiche: 50-252, 82/08/13, 8208170231.

9 Inspection reports, IE Bulletins & correspondence

8208170231 Forwards IE Safeguards Insp Rept 50-252/82-02 on 820617-18 & notice of violation. Rept & notice of violation withheld (ref 10CFR2.790).
SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 82/08/13. WOODALL, D. New Mexico, Univ. of. 2pp. 14370:070. 24X Fiche: 50-252, 82/08/13, 8208170231.

8208300117 Forwards corrected notice of violation re IE Insp Rept 50-252/82-02 on 820617-18. Notice of violation sent on 820813 did not show security level. Notice of violation withheld (ref 10CFR2.790).
SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 82/08/24. WOODALL, D. New Mexico, Univ. of. 1p. 14678:167. 24X Fiche: 50-252, 82/08/24, 8208300117.

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8208040469 Releases public version of revised emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 82/07/23. Document Management Branch. 1p. 14220:289. 24X Fiche: 50-254, 82/07/23, 8208040469.

--8208040475 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure QEP 530-3, "Offshift Augmentation Drill" & Revision 10 to QEP 530-0, "Exercises & Drills." Receipt form encl.
KOVACK, T.J., GERNER, L. Commonwealth Edison Co. 82/06/21. DENTON, H.R. NRC - No Detailed Affiliation Given. 1p. 14220:290. 24X Fiche: 50-254, 82/07/23, 8208040469.

--8208040481 Public version of Revision 2 to Emergency Plan Implementing Procedure QEP 530-3, "Offshift Augmentation Drill" & Revision 10 to QEP 530-0, "Exercises & Drills." * Commonwealth Edison Co. 82/06/21 3pp. 14220:291. 24X Fiche: 50-254, 82/07/23, 8208040469.

8208200137 Forwards response to 820112 request re exercise objectives, scope of participation & scenario outline for Aug 1982 emergency plan exercise.
RAUSCH, T.J. Commonwealth Edison Co. 82/08/02 KEPPLER, J.Q. Region 3, Office of Director. 7pp. 14393:283 24X Fiche: 50-254, 82/08/02, 8208200137

8208110230 Releases public version of revision to emergency plan implementing procedure
FELTON, J.M. Division of Rules and Records. 82/08/05. Document Management Branch. 1p 14330:309 24X Fiche: 50-254, 82/08/05, 8208110230

--8208110234 Forwards public version of Revision 12 to Emergency Plan Implementing Procedure QEP 530-0, "Assessment Actions." Receipt form encl.
KOVACK, T.J., TIET, O.C. Commonwealth Edison Co. 82/07/17. DENTON, H.R. NRC - No Detailed Affiliation Given. 1p 14330:310. 24X Fiche: 50-254, 82/08/05, 8208110230

--8208110238 Public version of Revision 12 to Emergency Plan Implementing Procedure QEP 530-0, "Assessment Actions." * Commonwealth Edison Co. 82/07/17 2pp. 14330:311. 24X Fiche: 50-254, 82/08/05, 8208110230

8208250559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures."
FELTON, J.M. Division of Rules and Records. 82/08/12. Document Management Branch. 1p. 14559:354. 24X Fiche: 50-000, 82/08/12, 8208250559.

--8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures."
MOORE, R.D. Commonwealth Edison Co. 82/07/19. DENTON, H.R. NRC - No Detailed Affiliation Given. 1p 14559:355. 24X Fiche: 50-000, 82/08/12, 8208250559.

--8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures." * Commonwealth Edison Co. 82/06/30 7pp. 14559:356. 24X Fiche: 50-000, 82/08/12, 8208250559

8208230107 Forwards revised cable discrepancy lists re fire protection safe shutdown analyses. Lists indicate how each discrepancy noted in fire protection associated circuit analysis & mod repts will be resolved.
RAUSCH, T.J. Commonwealth Edison Co. 82/08/13. EISENHUT, D.O. Division of Licensing. 2pp. 14515:001. 24X Fiche: 50-000, 82/08/13, 8208230107.

--8208230122 "Fire Protection Cable Discrepancy List, Quad Cities Unit" * Commonwealth Edison Co. 82/08/06. 250pp. 14515:293. 24X Fiche: 50-000, 82/08/13, 8208230107.

8208270523 Forwards IE Insp Repts 50-254/82-12 & 50-265/82-13 on 820722 & 23. No noncompliance noted.
PAPERIELLO, C.J. Division of Emergency Preparedness & Operational Support. 82/08/13. REED, C. Commonwealth Edison Co. 2pp. 14566:030. 24X Fiche: 50-254, 82/08/13, 8208270523.

--8208270527 IE Insp Repts 50-254/82-12 & 50-265/82-13 on 820722-23. No noncompliance noted. Major areas inspected: prompt public notification/warning sys.
PATTERSON, J.P., AXELSON, W.L. Division of Emergency Preparedness & Operational Support. 82/08/13. 5pp. 14566:032. 24X Fiche: 50-254, 82/08/13, 8208270523

8208230328 Ack receipt of 820806 ltr & 820812 telcon requesting that assembly & accountability portion of 820824 emergency exercise be conducted on 820819. Assembly & accountability should be conducted w/annual exercise.
PAPERIELLO, C.J. Division of Emergency Preparedness & Operational Support. 82/08/18. KALIVIANAKIS, N. Commonwealth Edison Co. 2pp. 14508:260. 24X Fiche: 50-254, 82/08/18, 8208230328.

--8208230335 Requests NRC approval to conduct site assembly portion of 820824 emergency exercise as separate drill on 820819. Separate drill would allow util to more effectively use manpower during exercise.
KALIVIANAKIS, N. Commonwealth Edison Co. 82/08/06. PAPERIELLO, C.J. Division of Emergency Preparedness & Operational Support. 2pp. 14508:262. 24X Fiche: 50-254, 82/08/18, 8208230328.

C Adjudicatory correspondence

8208240267 Response to ASLB 820728 order Requests leave to withdraw application w/o prejudice. Need for transshipment in near-term reduced due to approval of installation of high density spent fuel racks. Certificate of Svc encl STEPTOE, P. Commonwealth Edison Co STEPTOE, P [sham, Lincoln & Beale, 82/08/18 Atomic Safety and Licensing Board Panel. 6pp 14327, 120. 24X Fiche: 50-000.82/08/18.8208240267

8208240265 Response to ASLB 820728 order NRC does not object to proceeding termination since licensee has moved to withdraw license application w/o prejudice due to decision in Dresden high density storage rack case W/Certificate of Svc. WRIGHT, N.A. Hearing Branch 2. 82/08/20 Atomic Safety and Licensing Board Panel. 3pp 14327, 126 24X Fiche: 50-000.82/08/20.8208240265

P Operating license stage documents & correspondence

8208060030 Forwards Amends 78 & 72 to Licenses DPR-29 & DPR-30, respectively, safety evaluation & notice of issuance & availability. Amends change Tech Specs to extend operation to 820701 to allow completion of RHR svc water sys mods. BEVAN, R.B. Operating Reactors Branch 2. 82/05/27. DELOERDGE, L. Commonwealth Edison Co. 2pp. 14282, 102 24X Fiche: 50-254.82/05/27.8208060030

--8208040060 Amends 78 & 72 to Licenses DPR-29 & DPR-30, respectively, changing Tech Specs to extend operation to 820701 to allow completion of mode to PHR svc water sys. VASSALLO, D.B. Operating Reactors Branch 2. 82/05/27 10pp. 14282, 104 24X Fiche: 50-254.82/05/27.8208060030

--8208060053 Safety evaluation supporting Amends 78 & 72 to Licenses DPR-29 & DPR-30, respectively
* Office of Nuclear Reactor Regulation, Director. 82/05/27 2pp. 14282, 114 24X Fiche: 50-254.82/05/27.8208060030

--8208060064 Notice of issuance & availability of Amends 78 & 72 to Licenses DPR-29 & DPR-30, respectively.
VASSALLO, D.B. Operating Reactors Branch 2. 82/05/27 2pp. 14282, 116 24X Fiche: 50-254.82/05/27.8208060030

8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR. Svc list encl. DIRCKS, W.J. Office of the Executive Director for Operations. 82/07/02. Consolidated Edison Co. of New York. 93pp 14194, 001. 24X Fiche: 50-000.82/07/02.8207080064

8208090024 Requests formal notification within 30 days if NRC understanding that until will meet stated positions of NUREG-0737, Item III.D.3.3. "Improved In-Plant Iodine Instrumentation Under Accident Conditions." is correct. VASSALLO, D.B. Operating Reactors Branch 2. 82/07/21. DELOERDGE, L. Commonwealth Edison Co. 2pp. 14283, 358 24X Fiche: 50-254.82/07/21.8208090024

8208050066 Advises that ESF reset controls comply w/NRC criteria, subj to IE confirmation.
NOVAK, I.H. Assistant Director for Operating Reactors. 82/07/28. JORDAN, E.L. Division of Engineering & Quality Assurance. 1p 14242, 069 24X Fiche: 50-254.82/07/28.8208050066

--8208050080 Safety evaluation supporting plant compliance w/ESF reset controls per NRC criteria
* NRC - No Detailed Affiliation Given. 82/07/28 2pp. 14242, 071. 24X Fiche: 50-254.82/07/28.8208050066

8208180266 Forwards revised version of model Tech Specs for reactor protection sys/power monitoring sys design.
VASSALLO, D.B. Operating Reactors Branch 2. 82/07/28. DELOERDGE, L. Commonwealth Edison Co. 3pp. 14389, 318 24X Fiche: 50-000.82/07/28.8208180266

--8208180271 Revised model Tech Specs re electric power monitoring of reactor protection sys design
* Operating Reactors Branch 2. 82/07/28. 1p. 14389, 321 24X Fiche: 50-000.82/07/28.8208180266

8208110041 Forwards response to request to cross-ref info re environ qualification of safety-related equipment & THJ action plan equipment.
SWARTZ, E.D. Commonwealth Edison Co. 82/08/02. EISENHUT, D.O. Division of Licensing. 557pp 14315, 001. 24X Fiche: 50-000.82/08/02.8208110041

8208130046 Requests approval to delay implementation of commitments in response to Generic Ltr 82-09 re NUREG-0737, Item II.F.1.6. "Containment Hydrogen Monitor." Completion postponed until 840101 to accommodate schedule requirements.
SWARTZ, E.D. Commonwealth Edison Co. 82/08/03. EISENHUT, D.O. Division of Licensing. 2pp. 14339, 353. 24X Fiche: 50-000.82/08/03.8208130046

8208240168 Requests addl info verifying satisfaction of encl acceptance criteria re NUREG-0737, Item II.K.3.22. "Automatic Switchover of Reactor Core Isolation Cooling Sys Station." Response requested within 30 days.
VASSALLO, D.B. Operating Reactors Branch 2. 82/08/03. DELOERDGE, L. Commonwealth Edison Co. 4pp. 14340, 181. 24X Fiche: 50-254.82/08/03.8208240168

8208110188 Forwards revised pages to CE-1-A, "Comm Ed QA Program For Nuclear Generating Stations." Revision 21. Revised pages correct typographical & other minor errors.
SWARTZ, E. Commonwealth Edison Co. 82/08/06. HAAHS, W.P. Quality Assurance Branch. 1p. 14314, 079. 24X Fiche: 50-000.82/08/06.8208110188

--8208110204 Revised pages to CE-1-A, Revision 21, "Comm Ed QA Program Nuclear Generating Stations."
* Commonwealth Edison Co. 82/06/06 11pp 14314, 080. 24X Fiche: 50-000.82/08/06.8208110188

8208240040 Forwards Amends 81 & 75 to Licenses DPR-29 & DPR-30, respectively & notice of issuance & availability. Amends authorize replacement of water quality requirements w/enviro protection plan.
VASSALLO, D.B. Operating Reactors Branch 2. 82/08/06. DELOERDGE, L. Commonwealth Edison Co. 3pp. 14329, 316. 24X Fiche: 50-254.82/08/06.8208240040

--8208240046 Amends 81 & 75 to Licenses DPR-29 & DPR-30, respectively, replacing water quality requirements w/enviro protection plan.
VASSALLO, D.B. Operating Reactors Branch 2. 82/08/06 10pp 14329, 319. 24X Fiche: 50-254.82/08/06.8208240040

--8208240050 Notice of issuance & availability of Amends 81 & 75 to Licenses DPR-29 & DPR-30, respectively.
VASSALLO, D.B. Operating Reactors Branch 2. 82/08/06. 2pp. 14329, 337. 24X Fiche: 50-254.82/08/06.8208240040

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summaries 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D.O. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14396, 332. 24X Fiche: 50-000.82/08/09.8208090194

8208170135 Responds to NRC 820721 request to provide notification if util intends to deviate from NUREG-0737, Item III.D.3.3. "Improved In-Plant Iodine Instrumentation Under Accident Conditions." Both facilities comply w/requirement.
SWARTZ, E.D. Commonwealth Edison Co. 82/08/12. EISENHUT, D.O. Division of Licensing. 2pp. 14365, 211. 24X Fiche: 50-000.82/08/12.8208170135

8208250458 Advises of satisfactory response to NUREG-0737, Item II.K.3.24. "Adequacy of Space Cooling for HPCI & Reactor Core Isolation Cooling Sys." Safety evaluation encl.
VASSALLO, D.B. Operating Reactors Branch 2. 82/08/13. DELOERDGE, L. Commonwealth Edison Co. 3pp. 14362, 283. 24X Fiche: 50-254.82/08/13.8208250458

8208270250 Application for amend to License DPR-29, proposing Tech Spec changes to implement 10CFR50.59 reload licensing w/ODYN transient analyses & extended exposure MAPLHOR limits. Significant changes discussed. Class III amend fee encl.
RAUSCH, T.J. Commonwealth Edison Co. 82/08/19. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 14364, 001. 24X Fiche: 50-000.82/08/19.8208270250

--8208270256 Proposed Tech Spec changes to implement 10CFR50.59 reload licensing w/ODYN transient analyses & extended exposure MAPLHOR limits.
* Commonwealth Edison Co. 82/08/19. 20pp. 14364, 006. 24X Fiche: 50-000.82/08/19.8208270250

B2082270296 Errata to a Hoboken and 2, replicating Pages 4-11 & 4-14 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations." * General Electric Co. NEDD-24246A ERR 07 82/07/31 5pp 14564:026 24X Fiche: 50-000, 82/08/19, 8208270295

B208270296 Informs that analysis to determine appropriate equipment qualification temp profiles will be submitted in Sept 1982, not Jul 1982, as previously indicated. RAUSCH, T. J. Commonwealth Edison Co. 82/08/23 VASSALLO, D. B. Division of Licensing. 1p 14564 177 24X Fiche: 50-000, 82/08/23, 8208270296

B208310402 Submits supplemental response to Generic Ltr 82-05 re NUREG-0737, Item II. F. 1.3. "Containment High-Range Radiation Monitor." Requests delay of implementation until 821030 due to delivery problems. SHARTZ, E. D. Commonwealth Edison Co. 82/08/27 EISENHUT, D. G. Division of Licensing. 1p 14694 308 24X Fiche: 50-254, 82/08/27, 8208310402

Q. Inspection reports, IE Bulletins & correspondence

B208050414 Forwards IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-263/81-23, 50-293/81-31 & 50-304/81-29 on B10813-B20503 No noncompliance noted. KEPLER, J. Q. Region 3, Office of Director. 82/07/12. REED, C. Commonwealth Edison Co. 1p 14217.166 24X Fiche: 50-000, 82/07/12, 8208050414

--B208050441 IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-263/81-23, 50-293/81-31 & 50-304/81-29 on B10813-B20503 No noncompliance noted. Major areas inspected allegations re Comm Ed operation of facilities & compliance w/10CFR21. HAYES, D. W., PHILLIP, G. A., HINDS, J. M. Division of Project & Resident Programs. 82/07/09 154pp 14217.169 24X Fiche: 50-000, 82/07/12, 8208050441

B204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16 Consolidated Edison Co. of New York. 87pp. 14356.274 24X Fiche: 50-000, 82/07/16, 8204210393

B204210395 IE Info Notice 81-26, Part 3, Suppl. 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19 Michigan Univ. of 112pp 14398 001 24X Fiche: 50-000, 82/07/19, 8204210395

B208050424 Forwards IE Insp Repts 50-254/82-08 & 50-265/82-09 on B20428-0629 & notice of violation. SPESSARD, R. L. Division of Project & Resident Programs. 82/07/19. REED, C. Commonwealth Edison Co. 2pp. 14214:076 24X Fiche: 50-254, 82/07/19, 8208050424

--B208050426 Notice of violation from insp on B20428-0629 SPESSARD, R. L. Division of Project & Resident Programs. 82/07/19. 8pp. 14214:078 24X Fiche: 50-254, 82/07/19, 8208050426

--B208050435 IE Insp Repts 50-254/82-08 & 50-265/82-09 on B20428-0629. Noncompliance noted: failure to perform required testing after maint on safety-related equipment & failure to provide condensate flood protection. CHRISTIMOS, N., DUPONT, B. Q., WALKER, R. D. Division of Project & Resident Programs. 82/07/11 15pp. 14214:080 24X Fiche: 50-254, 82/07/19, 8208050435

B204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp. 14381:001 24X Fiche: 50-000, 82/07/20, 8204210396

B204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl. COBB, L. I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20. Consolidated Edison Co. of New York. 71pp. 14357:276 24X Fiche: 50-000, 82/07/20, 8204210397

B204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22. Consolidated Edison Co. of New York. 112pp. 14194:321 24X Fiche: 50-000, 82/07/22, 8204210398

B204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB." Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 122pp. 14380:115 24X Fiche: 50-000, 82/07/23, 8204210401

B204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 127pp. 14194:120 24X Fiche: 50-000, 82/07/23, 8204210402

B204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Pipin at Certain Westinghouse PWR Power Plants." Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26. Consolidated Edison Co. of New York. 121pp. 14357:013 24X Fiche: 50-000, 82/07/26, 8204210403

B204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28. Consolidated Edison Co. of New York. 122pp. 14357:146 24X Fiche: 50-000, 82/07/28, 8204210405

B204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/05. Consolidated Edison Co. of New York. 117pp. 14398:201 24X Fiche: 50-000, 82/08/05, 8204210407

B208270523 Forwards IE Insp Repts 50-254/82-12 & 50-265/82-13 on B20722 & 23 No noncompliance noted. PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 82/08/13 REED, C. Commonwealth Edison Co. 2pp. 14566:030 24X Fiche: 50-254, 82/08/13, 8208270523

--B208270527 IE Insp Repts 50-254/82-12 & 50-265/82-13 on B20722-23 No noncompliance noted. Major areas inspected prompt public notification/warning sys. PATTERSON, J. P., AXELSON, W. L. Division of Emergency Preparedness & Operational Support. 82/08/13 5pp. 14566:032 24X Fiche: 50-254, 82/08/13, 8208270527

B208310336 Forwards IE Insp Repts 50-254/82-13 & 50-265/82-13 on B200719-23, 27 & 0806. No noncompliance noted. PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 82/08/17. REED, C. Commonwealth Edison Co. 2pp. 14692:133 24X Fiche: 50-254, 82/08/17, 8208310336

--B208310351 IE Insp Repts 50-254/82-13 & 50-265/82-13 on B20719-23, 27 0806. No noncompliance noted. Major areas inspected conformity program & associated QC procedures. NICHOLSON, N. A., ROZAK, B., SCHUMACHER, M. C. Division of Emergency Preparedness & Operational Support. 82/08/17 8pp. 14692:137 24X Fiche: 50-254, 82/08/17, 8208310351

R. Periodic operating reports & related correspondence

B208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A. FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A. Critical Mass Energy Project. 8pp. 14679:208 24X Fiche: 50-000, 82/07/13, 8208270010

--B208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81." * NRC - No Detailed Affiliation Given. 82/07/13 48pp. 14679:216 24X Fiche: 50-000, 82/07/13, 8208270098

--B208270263 Forwards "1981 Rept of Occupational Personnel Radiation Doses." KALIVIANAKIS, N. Commonwealth Edison Co. 82/02/17. KEPLER, J. Q. Office of Nuclear Reactor Regulation. 1p 14679:300 24X Fiche: 50-000, 82/07/13, 8208270263

--B208270268 "1981 Rept of Occupational Personnel Radiation Doses." * Commonwealth Edison Co. 82/02/17. 3pp. 14679:301 24X Fiche: 50-000, 82/07/13, 8208270268

--B208270559 Forwards "Recorded Annual Whole Body External Exposure for CY81," per 10CFR20.407(b). w/o Quad Cities, Zion, LaSalle, Byron & Braidwood repts. RAUSCH, T. J. Commonwealth Edison Co. 82/03/31. Office of Management and Program Analysis. 1p 14680:075 24X Fiche: 50-000, 82/07/13, 8208270559

B208160116 Forwards changes, tests & experiments completed during Jul 1982. KALIVIANAKIS, N. Commonwealth Edison Co. 82/08/02. CASE, E. Q. Office of Nuclear Reactor Regulation. Director. 4pp. 14348:295 24X Fiche: 50-254, 82/08/02, 8208160116

B208160374 Forwards monthly operating repts for Jul 1982. KALIVIANAKIS, N. Commonwealth Edison Co. 82/08/02. Director's Office, Office of Inspection and Enforcement. 1p. 14348:320 24X Fiche: 50-254, 82/08/02, 8208160374

--B208160381 Monthly operating reports for Jul 1982
WEINFURTER, E. BUSS, R. Commonwealth Edison Co. 82/08/03 27pp.
14348 321. 24X Fiche: 50-254, 82/08/02, 8208160374

9 Reportable occurrences, LERs & related correspondence

B208130210 Forwards LER 82-013/03L-0
KALIVIANAKIS, N. Commonwealth Edison Co. 82/07/14. KEPPLER, J. Region 3, Office of Director. 1p. 14333 003 24X Fiche: 50-254, 82/07/14, 8208130210.

--B208130218 LER 82-013/03L-0 on 820621, while diesel generator cooling water pump was being run in conjunction w/HPCI monthly operability surveillance, QOC 2300-2 pump observed to have no flow by local indications. Caused by pump being air bound
BUSS, R. Commonwealth Edison Co. 82/07/14. Region 3, Office of Director. 2pp. 14333 004 24X Fiche: 50-254, 82/07/14, 8208130210.

B208100049 Forwards LER 82-016/03L-0
KALIVIANAKIS, N. Commonwealth Edison Co. 82/07/21. KEPPLER, J. Region 3, Office of Director. 1p. 14296 230. 24X Fiche: 50-254, 82/07/21, 8208100049.

--B208100056 LER 82-016/03L-0 on 820711, during routine panel checks, HPCI MV found on low speed stop. Setpoint switched to high speed stop, but returned to low speed stop when switch released. Caused by failed amplifier circuit board
MOELLER, J. P. Commonwealth Edison Co. 82/07/21. Region 3, Office of Director. 3pp. 14296 231 24X Fiche: 50-254, 82/07/21, 8208100049.

B208050230 Forwards LER 82-019/03L-0
KALIVIANAKIS, N. Commonwealth Edison Co. 82/07/22. KEPPLER, J. Region 3, Office of Director. 1p. 14209 296 24X Fiche: 50-254, 82/07/22, 8208050230

--B208050232 LER 82-019/03L-0 on 820628, 1/2A diesel fire pump taken out of svc for more than 7 days. Caused by need for overhaul, due to insurance company flow insp test revealing pump capacity marginal. Pump overhauled.
WUNDERLICH, J. Commonwealth Edison Co. 82/07/22. Region 3, Office of Director. 2pp. 14209 297. 24X Fiche: 50-254, 82/07/22, 8208050230

B208100210 Forwards LER 82-017/03L-0
KALIVIANAKIS, N. Commonwealth Edison Co. 82/07/30. KEPPLER, J. Q. Region 3, Office of Director. 1p. 14294 315. 24X Fiche: 50-254, 82/07/30, 8208100210

--B208100219 LER 82-017/03L-0 on 820713, while taking inboard core spray injection valve (I-1402-258) out of svc for insp, valve failed to open from control room. Caused by water from packing leak running into motor operator. Motor repaired.
MENDENHALL, E. Commonwealth Edison Co. 82/07/30. Region 3, Office of Director. 3pp. 14294 316. 24X Fiche: 50-254, 82/07/30, 8208100210.

B208130240 Forwards LER 82-019/03L-0
KALIVIANAKIS, N. Commonwealth Edison Co. 82/08/02. KEPPLER, J. Region 3, Office of Director. 1p. 14333 169. 24X Fiche: 50-254, 82/08/02, 8208130240.

--B208130246 LER 82-019/03L-0 on 820713, during calibr of reactor automatic relief valves, controllers for valves 1-203-38, 3D & 3E found to trip at pressures in excess of Tech Spec limits. Caused by setpoint calibr below limits
PREUSS, M. Commonwealth Edison Co. 82/08/02. Region 3, Office of Director. 3pp. 14333 170. 24X Fiche: 50-254, 82/08/02, 8208130240.

B208160427 Forwards LER 82-018/03L-0
KALIVIANAKIS, N. Commonwealth Edison Co. 82/08/02. KEPPLER, J. Region 3, Office of Director. 1p. 14349 193. 24X Fiche: 50-254, 82/08/02, 8208160427.

--B208160438 LER 82-018/03L-0 on 820719, while performing reactor high pressure scram functional test, pressure switch PS-1-263-55A tripped high. Caused by instrument setpoint drift. Switch recalibr & tested satisfactorily.
MISAK, A. Commonwealth Edison Co. 82/08/02. Region 3, Office of Director. 2pp. 14349 196 24X Fiche: 50-254, 82/08/02, 8208160427.

B208100168 Forwards LER 82-014/03L-0
KALIVIANAKIS, N. Commonwealth Edison Co. 82/08/03. KEPPLER, J. Q. Region 3, Office of Director. 1p. 14296 025. 24X Fiche: 50-254, 82/08/03, 8208100168

--B208100174 LER 82-014/03L-0 on 820708, discharge damper on standby gas treatment train B failed to open when train auto-started. Caused by failure of auxiliary contact on motor starter. Contact replaced.
KAEPPLE, F. Commonwealth Edison Co. 82/08/03. Region 3, Office of Director. 3pp. 14298 026. 24X Fiche: 50-254, 82/08/03, 8208100168

B208200252 Forwards LER 82-011/01T-1
KALIVIANAKIS, N. Commonwealth Edison Co. 82/08/06. KEPPLER, J. Region 3, Office of Director. 1p. 14399 086 24X Fiche: 50-254, 82/08/06, 8208200252

--B208200263 LER 82-011/01T-1 on 820605, control valve 4 failed to fast close so that no reactor protective sys channel B trip received. Caused by personnel error. Amphenol connector may have been damaged by maint personnel
TRETZ, O. Commonwealth Edison Co. 82/08/05. Region 3, Office of Director. 1p. 14399 087 24X Fiche: 50-254, 82/08/06, 8208200252.

DOCKET 50-255 PALISADES NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

B208030195 Provides update to 81106 response to NRC 811007 ltr re NUREG-0737, Item III A 1.2, "Staffing Levels for Emergency Situations." Approval of emergency implementing procedures & training of required personnel expected by 820915
VANDEWALLE, D. J. Consumers Power Co. 82/07/30. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 14160 006. 24X Fiche: 50-255, 82/07/30, 8208030195.

B208200210 IE Insp Rept 50-255/82-14 on 820621-25 No noncompliance noted. Major areas inspected action taken per JO Keppler 811007 confirmation of action ltr to RB DeWitt & 811203 emergency preparedness appraisal.
CRANT, W. B. AXELSON, W. L. Division of Emergency Preparedness & Operational Support. 82/08/05. 7pp. 14399 177. 24X Fiche: 50-255, 82/08/06, 8208200202

B208200202 Forwards IE Insp Rept 50-255/82-14 on 820621-25 No noncompliance noted
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 82/08/06. DEWITT, R. B. Consumers Power Co. 2pp. 14399 175. 24X Fiche: 50-255, 82/08/06, 8208200202.

B208160109 Forwards IE Safeguards Insp Rept 50-255/82-17 on 820511-14 & 0623 No noncompliance noted.
HILLER, J. R. Division of Engineering & Technical Programs. 82/08/10. DEWITT, R. B. Consumers Power Co. 1p. 14345 167 24X Fiche: 50-255, 82/08/10, 8208160109.

--B208160122 IE Safeguards Insp Rept 50-255/82-17 on 820511-14 & 0623. No noncompliance noted. Major areas inspected security organization, physical barriers, access controls, detection aids & alarm stations. Details withheld (ref 10CFR73 21).
BELANGER, J. L., CREED, J. R. Region 3, Office of Director. 82/08/09 1p. 14345 169. 24X Fiche: 50-255, 82/08/10, 8208160109

B208170154 Requests current version of full-size engineering drawings of facility layout & sys to review effectiveness of NRC safeguards regulations & validate vital area designations. Drawing list encl.
CRUTCHFIELD, D. Operating Reactors Branch 5. 82/08/11. VANDEWALLE, D. Consumers Power Co. 4pp. 14364 220. 24X Fiche: 50-255, 82/08/11, 8208170154.

B208270599 Releases public version of site emergency plan & revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 82/08/16. Document Management Branch. 1p. 14681 020. 24X Fiche: 50-255, 82/08/16, 8208270599.

--B208270604 Forwards public version of Revision 0 to site emergency plan & revised emergency plan implementing procedures, including Procedures EI-1 re activation of emergency plan & EI-3 re communications & notification.
VANDEWALLE, D. J. Consumers Power Co. 82/08/04. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14681 023. 24X Fiche: 50-255, 82/08/16, 8208270599.

--B208270609 Public version of Revision 0 to site emergency plan.
* Consumers Power Co. 82/01/13 300pp. 14681 024. 24X Fiche: 50-255, 82/08/16, 8208270599.

--B208270615 Public version of revised emergency plan implementing procedures, including Procedures EI-1 re activation of emergency plan & EI-3 re communications & notification.
* Consumers Power Co. 82/03/25. 200pp. 14681 314. 24X Fiche: 50-255, 82/08/16, 8208270599.

8208310405 Responds to 820628 ltr re proposed changes to four of 22 emergency exercise deficiencies identified in IE Emergency Preparedness Rept 50-225/82-03 & addressed in util 820602 ltr Acceptable items listed
PAPERIELLO, C J Division of Emergency Preparedness & Operational Support. 82/08/25 DEWITT, R B Consumers Power Co. 2pp. 14693 265 24X Fiche 50-255, 82/08/25, 8208310405

--8208310411 Revises schedule commitments on four responses to deficiencies identified in IE Emergency Preparedness Rept 50-255/82-03 Deficiencies re emergency facilities & emergency plan procedures discussed
JOHNSON, B D Consumers Power Co 82/06/28 KEPPLER, J G Region 3, Office of Director 3pp. 14693 267. 24X Fiche: 50-255, 82/08/25, 8208310405.

3 Adjudicatory correspondence

8208030295 Memorandum & Order CLI-82-18, vacating ASLB B10731 order, LBP-81-26 & ASIAD 820331 order, ALAB-670 Appellate review unavailable since proceeding moot NRC & union settled disagreement on allowable overtime
HAYLE, J C Office of the Secretary of the Commission. 82/07/30. 3pp 14158 117 24X Fiche 50-255, 82/07/30, 8208030295.

8208110070 Order scheduling 820921 prehearing conference in St Joseph, MI Conference will be limited to issues re date of steam generator replacement, EIB status, ASLB jurisdiction over application fee forfeiture & discovery schedule.
LAURENSEN, J A Atomic Safety and Licensing Board Panel. 82/08/09. 3pp 14316 353 24X Fiche 50-255, 82/08/09, 8208110070

0 Advisory Committee on Reactor Safeguards reports & correspondence

8207110050 Summary of ACRS Subcommittee on BEP 820415 meeting in Washington, DC
* ACRS - Advisory Committee on Reactor Safeguards. 82/06/03 22pp 14389 001 24X Fiche 50-255, 82/06/03, 8207110050

P. Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CRQR Svc list encl
DIRCKS, W J Office of the Executive Director for Operations. 82/07/02. Consolidated Edison Co. of New York. 93pp. 14194 001. 24X Fiche: 50-000, 82/07/02, 8207080064

8208020282 Forwards application for amend to License DPR-20, requiring power operated relief valves to be in svc when shutdown cooling sys not isolated from RCS
VANDEWALLE, D J Consumers Power Co. 82/07/29 CRUTCHFIELD, D. Operating Reactors Branch 5. 1p 14151 306 24X Fiche: 50-255, 82/07/29, 8208020282

--8208020287 Application for amend to License DPR-20, requiring power operated relief valves to be in svc when shutdown cooling sys not isolated from RCS
REYNOLDS, J W Consumers Power Co. 82/07/29. 2pp. 14151 307. 24X Fiche: 50-255, 82/07/29, 8208020282.

--8208020294 Proposed Tech Spec changes, requiring power operated relief valves to be in svc when shutdown cooling sys not isolated from RCS
* Consumers Power Co. 82/07/29 2pp 14151 309 24X Fiche: 50-255, 82/07/29, 8208020282

8208020299 Forwards application for amend to License DPR-20, requiring check valve closure following use of low pressure safety injection sys for shutdown cooling
VANDEWALLE, D J. Consumers Power Co. 82/07/29. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14152 021. 24X Fiche: 50-255, 82/07/29, 8208020299.

--8208020304 Application for amend to License DPR-20, requiring check valve closure following use of low pressure safety injection sys for shutdown cooling.
REYNOLDS, J W Consumers Power Co. 82/07/29. 2pp. 14152 022. 24X Fiche: 50-255, 82/07/29, 8208020299.

--8208020310 Proposed Tech Specs requiring check valve closure following use of low pressure safety injection sys for shutdown cooling.
* Consumers Power Co. 82/07/29. 3pp. 14152 024. 24X Fiche: 50-255, 82/07/29, 8208020299

8208020356 Forwards application for amend to License DPR-20 requiring addl delamination insp if 5% or more of installed tendons must be retensioned to compensate for excessive loss of prestress.
VANDEWALLE, D J Consumers Power Co. 82/07/29. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p 14150 179 24X Fiche: 50-255, 82/07/29, 8208020356

--8208020360 Application for amend to License DPR-20 requiring addl delamination insp if 5% or more of installed tendons must be restressed to compensate for excessive loss of prestress.
REYNOLDS, J W Consumers Power Co. 82/07/29. 2pp 14150 180. 24X Fiche: 50-255, 82/07/29, 8208020356

--8208020365 Proposed Tech Specs requiring addl delamination insp if 5% or more of installed tendons must be retensioned to compensate for excessive loss of prestress
* Consumers Power Co. 82/07/29. 3pp. 14150 182 24X Fiche: 50-255, 82/07/29, 8208020356

8208050072 Comments on BEP, Phase II & proposals for Phase III Results of BEP do not justify costs.
DEWITT, R B. Consumers Power Co. 82/08/02 DENTON, H R. Office of Nuclear Reactor Regulation, Director 5pp 14213 267 24X Fiche: 50-255, 82/08/02, 8208050072

8208130116 Forwards draft Revision 10 to "Inservice Testing of Plant Valves," per NRC inservice test program review & 820618 conference call. Comments requested complete final draft.
JOHNSON, B D Consumers Power Co. 82/08/06 CRUTCHFIELD, D. Operating Reactors Branch 5. 1p 14333 201. 24X Fiche: 50-255, 82/08/06, 8208130116.

--8208130118 Draft Revision 10 to "Inservice Testing of Plant Valves"
* Consumers Power Co. 82/07/19. 66pp. 14333 202 24X Fiche: 50-255, 82/08/06, 8208130116.

8208190062 Notification of 820819 meeting w/util in Bethesda, MD to present proposed mods to HVAC sys, including mods for response to NUREG-0737, Item III.D.3.4, "Control Room Habitability."
WAMBACH, T V Operating Reactors Branch 5. 82/08/06. CRUTCHFIELD, D. Operating Reactors Branch 5. 4pp. 14307 048 24X Fiche: 50-255, 82/08/06, 8208190062

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl.
EISENHUT, D O Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14356 332. 24X Fiche: 50-000, 82/08/09, 8208090194

8208120317 Forwards revised Pages 14 & 15 to "Inservice Testing of Plant Valves, Table I." Revision 10, submitted on 820806.
JOHNSON, D O. Consumers Power Co. 82/08/10. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p 14324 230. 24X Fiche: 50-255, 82/08/10, 8208120317.

--8208120322 Revised Pages 14 & 15 to "Inservice Testing of Plant Valves, Table I." Revision 10.
* Consumers Power Co. 82/07/15 2pp 14324 231 24X Fiche: 50-255, 82/08/10, 8208120317.

8208180012 Presents addl info re auxiliary feedwater sys mod, per NRC 820325 telcon request.
JOHNSON, B D. Consumers Power Co. 82/08/11. CRUTCHFIELD, D. Operating Reactors Branch 5. 4pp. 14377 202. 24X Fiche: 50-255, 82/08/11, 8208180012.

--8208180016 "Evaluation of Auxiliary Feedwater Flow Requirements For High Pressure Safety Injection Pump Conversion."
* Consumers Power Co. 82/08/11 78pp. 14377 206. 24X Fiche: 50-255, 82/08/11, 8208180012

8208230275 Forwards rept re BEP Topic III-1, "Classification of Structures, Components & Sys (Seismic & Quality)." Plant meets current licensing requirements
VINCENT, R A. Consumers Power Co. 82/08/12. CRUTCHFIELD, D. Operating Reactors Branch 5. 54pp. 14912 264. 24X Fiche: 50-255, 82/08/12, 8208230275.

8208230262 Forwards "BEP High Energy Line Breaks Inside Containment, Palisades Nuclear Station Phase IV Summary of Results." Final rept expected by 821130.
VINCENT, R A. Consumers Power Co. 82/08/16. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14514 001. 24X Fiche: 50-255, 82/08/16, 8208230262.

--B208230266 "SEP High Energy Line Breaks Inside Containment, Palisades Nuclear Station Phase IV Summary of Results." * EDS Nuclear, Inc 02-0540-1108 RB 82/07/31. 120pp. 14514 002 24X Fiche 30-255.82/08/16.8208230262.

B208230334 Submits revised schedule dates for selected action items resulting from SEP.
VANDEWALLE, D J. Consumers Power Co. 82/08/17. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 14508:250. 24X Fiche 30-255.82/08/17.8208230334.

B208250113 Forwards updated rept re SEP Topic III-1, "Classification of Structures, Components & Sys (Seismic & Quality)," originally submitted B20812. Submittal includes pressurizer fracture toughness data inadvertently omitted from B20812 submittal.
VINCENT, R. A. Consumers Power Co. 82/08/19. CRUTCHFIELD, D. Operating Reactors Branch 5. 54pp. 14542:022 24X Fiche: 30-255.82/08/19.8208250113

B208270234 Provides info to meet interim position for containment purge & vent valve operation & submits schedule for addressing long-term issue identified in NRC 781129 ltr for approval of modified purge sys. Safety evaluation encl.
JOHNSON, B D. Consumers Power Co. 82/08/24. CRUTCHFIELD, D. Operating Reactors Branch 5. 4pp. 14560:136 24X Fiche: 30-255.82/08/24.8208270234.

B208310091 Confirms B20817 telcon re scheduling of B20708 mgt meeting at site to discuss progress of regulatory improvement program.
KEPPLER, J. Q. Region 3. Office of Director. 82/08/25. DEWITT, R. B. Consumers Power Co. 1p. 14689:318. 24X Fiche: 30-255.82/08/25.8208310091

B208310414 Provides results of analysis re NRC evaluation of SEP Topic IX-3, "Station Bvc & Cooling Water Sys." Calculations of water drainage capability of intake structure shows drainage capacity adequate to handle largest slot break.
VANDEWALLE, D. J. Consumers Power Co. 82/08/25. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14694:309. 24X Fiche: 30-255.82/08/25.8208310414.

Q. Inspection reports, IE Bulletins & correspondence

B208040040 Ack receipt of B20610 ltr & full payment of civil penalty proposed in NRC B20512 enforcement action violation correctly categorized as Security Level III due to history of containment integrity violations.
LIEBERMAN, J. Enforcement Branch (Pre B20201). 82/06/30. DEWITT, R. B. Consumers Power Co. 2pp. 14235:360 24X Fiche: 30-255.82/06/30.8208040040.

B204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Bvc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16. Consolidated Edison Co. of New York. 87pp. 14356:274. 24X Fiche: 30-000.82/07/16.8204210393.

B204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Bvc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan Univ. of. 112pp. 14358:001. 24X Fiche: 30-000.82/07/19.8204210395

B204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Bvc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp. 14381:001. 24X Fiche: 30-000.82/07/20.8204210396.

B204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Bvc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20. Consolidated Edison Co. of New York. 71pp. 14387:276. 24X Fiche: 30-000.82/07/20.8204210397.

B204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Bvc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22. Consolidated Edison Co. of New York. 112pp. 14194:321. 24X Fiche: 30-000.82/07/22.8204210398.

B208100271 Forwards IE Insp Rept 30-255/82-15 on B20601-30 & notice of violation.
KNOP, R. C. Division of Project & Resident Programs. 82/07/22. DEWITT, R. B. Consumers Power Co. 2pp. 14295:132. 24X Fiche: 30-255.82/07/22.8208100271.

--B208100276 Notice of violation from insp on B20601-30.
KNOP, R. C. Division of Project & Resident Programs. 82/07/22. 1p. 14295:134. 24X Fiche: 30-255.82/07/22.8208100271.

--B208000283 IE Insp Rept 30-255/82-15 on B20601-30. Noncompliance noted: failure to perform required comparison of auxiliary feed pump flow indications for May 1982.
JORDAN, E. L., HELLER, J. K. Region 3. Office of Director. 82/07/21. 10pp. 14295:135. 24X Fiche: 30-255.82/07/22.8208100271.

B204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB." Bvc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 122pp. 14380:115. 24X Fiche: 30-000.82/07/23.8204210401.

B204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Bvc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 127pp. 14194:120. 24X Fiche: 30-000.82/07/23.8204210402.

B204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants." Bvc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26. Consolidated Edison Co. of New York. 121pp. 14357:013. 24X Fiche: 30-000.82/07/26.8204210403.

B204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Bvc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28. Consolidated Edison Co. of New York. 122pp. 14357:146. 24X Fiche: 30-000.82/07/28.8204210405

B208090257 Responds to Action Item 3 of IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants." Carbon steel studs being replaced w/stainless steel.
JOHNSON, B D. Consumers Power Co. 82/08/02. CRUTCHFIELD, D. Operating Reactors Branch 5. 4pp. 14209:333. 24X Fiche: 30-255.82/08/02.8208090257.

B204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Bvc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/05. Consolidated Edison Co. of New York. 117pp. 14388:201. 24X Fiche: 30-000.82/08/05.8204210407.

B208200202 Forwards IE Insp Rept 30-255/82-14 on B20621-25. No noncompliance noted.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 82/08/06. DEWITT, R. B. Consumers Power Co. 2pp. 14399:175. 24X Fiche: 30-255.82/08/06.8208200202.

--B208200210 IE Insp Rept 30-255/82-14 on B20621-25. No noncompliance noted. Major areas inspected: action taken per JO Keppler B1007 confirmation of action ltr to RB DeWitt & B11203 emergency preparedness appraisal.
ORANT, W. B., AXELSON, W. L. Division of Emergency Preparedness & Operational Support. 82/08/05. 7pp. 14399:177. 24X Fiche: 30-255.82/08/06.8208200202

B208160109 Forwards IE Safeguards Insp Rept 30-255/82-17 on B20511-14 & 0623. No noncompliance noted.
MILLER, J. R. Division of Engineering & Technical Programs. 82/08/10. DEWITT, R. B. Consumers Power Co. 1p. 14345:167. 24X Fiche: 30-255.82/08/10.8208160109.

--B208160122 IE Safeguards Insp Rept 30-255/82-17 on B20511-14 & 0623. No noncompliance noted. Major areas inspected: security organization, physical barriers, access controls, detection aids & alarm stations. Details withheld (ref 10CFR73.21).
BELANGER, J. L., CREED, J. L. Region 3. Office of Director. 82/08/09. 1p. 14345:169. 24X Fiche: 30-255.82/08/10.8208160109.

B208160258 Forwards addl provisions re BEP Topic III-7.A, "Inservice Insp Including Prestressed Concrete Containments W/Either Grouted or UngROUTED Tendons."
VINCENT, R. A. Consumers Power Co. 82/08/12. CRUTCHFIELD, D. Operating Reactors Branch 5. 7pp. 14347:056 24X Fiche: 30-255.82/08/12.8208160258.

B208170344 Documents resolution of BEP Topic III-3 C, "Inservice Insp of Water Control Structures." Program discussed in util B20324 ltr will be implemented w/addl annual functionality checks of worm water recirculating pump.
VINCENT, R. A. Consumers Power Co. 82/08/12. CRUTCHFIELD, D. Operating Reactors Branch 5. 1p. 14367:018. 24X Fiche: 30-255.82/08/12.8208170344.

B208200016 Ack receipt of B20723 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-255/82-13.
SPESSARD, R. L. Division of Project & Resident Programs. 82/08/13. DEWITT, R. B. Consumers Power Co. 1p. 14392:201. 24X Fiche: 30-255.82/08/13.8208200016.

Procedures revised & setpoints returned to specific values
DEWITT, R. B. Consumers Power Co. 82/07/23. KEPLER, J. G. Region
3, Office of Director. App. 14392:202. 24X Fiche 50-255,
82/08/13, 820820016.

820820223 Forwards IE Insp Rept 50-255/82-18 on 820728-29 & notice
violation.
MILLER, J. R. Division of Engineering & Technical Programs. 82/08/13.
DEWITT, R. B. Consumers Power Co. 2pp. 14693:141. 24X
Fiche 50-255, 82/08/13, 8208310223

8208310227 Notice of violation from insp on 820728-29
MILLER, J. R. Division of Engineering & Technical Programs.
82/08/13. 1p. 14693:143. 24X Fiche 50-255, 82/08/13, 8208310223.

8208310232 IE Insp Rept 50-255/82-18 on 820728-29 Noncompliance noted.
failure to follow Section 3 to Administrative Procedure 3.6.
"ALARA Committee."
LOVENDALE, P. C., MILLER, D. E., OREGER, L. R. Region 3, Office of
Director. 82/08/12. 4pp. 14693:144. 24X Fiche 50-255, 82/08/13,
8208310223.

8208310405 Responds to 820628 ltr re proposed changes to four of 23
emergency exercise deficiencies identified in IE Emergency
Preparedness Rept 50-255/82-03 & addressed in util 820602
ltr. Acceptable items listed.
APERIELLO, C. J. Division of Emergency Preparedness & Operational
Support. 82/08/25. DEWITT, R. B. Consumers Power Co. 2pp.
14693:265. 24X Fiche 50-255, 82/08/25, 8208310405.

8208310411 Revises schedule commitments on four responses to
deficiencies identified in IE Emergency Preparedness Rept
50-255/82-03. Deficiencies re emergency facilities &
emergency plan procedures discussed.
JOHNSON, B. D. Consumers Power Co. 82/06/28. KEPLER, J. G. Region
3, Office of Director. 3pp. 14693:267. 24X Fiche 50-255,
82/08/25, 8208310405

Periodic operating reports & related correspondence

82070010 Responds to FOIA request for documents detailing collective
dose exposures in 1981 for operating nuclear power plants &
analyzing said info. Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A.
Critical Mass Energy Project. 8pp. 14679:208. 24X
Fiche 50-000, 82/07/13, 8208270010.

8208270098 "Annual Whole Body Dose At Licensed Nuclear Power
Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp.
14679:216. 24X Fiche 50-000, 82/07/13, 8208270010.

8208270639 Forwards "Annual Exposure Range Rept, 1981," per 10CFR20.407.
VANDEWALLE, D. J. Consumers Power Co. 82/03/29. Office of
Management and Program Analysis. 1p. 14680:062. 24X
Fiche 50-000, 82/07/13, 8208270010.

8208270639 "Annual Exposure Range Rept, 1981."
* Consumers Power Co. 82/03/29. 1p. 14680:063. 24X
Fiche 50-000, 82/07/13, 8208270010.

8208130271 Forwards monthly operating rept for Jul 1982 & corrected
monthly operating rept for June 1982.
PETERSON, D. A. Consumers Power Co. 82/08/09. NRC - No Detailed
Affiliation Given. 1p. 14333:055. 24X Fiche 50-255, 82/08/09,
8208130271.

8208130273 Monthly operating rept for Jul 1982.
PETERSON, D. A. Consumers Power Co. 82/08/03. 4pp. 14333:056
24X Fiche 50-255, 82/08/09, 8208130271.

8208130274 Corrected monthly operating rept for June 1982
PETERSON, D. A. Consumers Power Co. 82/07/01. 1p. 14333:060. 24X
Fiche 50-255, 82/08/09, 8208130271.

Reportable occurrences, LERs & related correspondence

8208130028 Forwards repts to State of MI re NPDES nonradiological
permit violations from May 1981 to Apr 1982.
JOHNSON, B. D. Consumers Power Co. 82/05/26. KEPLER, J. G. Region 3,
Office of Director. 44pp. 14335:098. 24X Fiche 50-255, 82/05/26,
8208130028.

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8207060127 Forwards response to Section III C of App R to 10CFR50 re
fire protection plan.
MILLS, L. M. Tennessee Valley Authority. 82/06/30. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 202pp. 13712:142.
24X Fiche 50-259, 82/06/30, 8207060127.

8207120070 Releases public version of revision to State of AL
radiological emergency response plan.
FELTON, J. M. Division of Rules and Records. 82/07/06. Document
Management Branch. 1p. 13829:312. 24X Fiche 50-259, 82/07/06,
8207120070.

--8207120078 Forwards public version of Revision BFN-REF-82-003 to State
of AL radiological emergency response plan, constituting App
F to Browns Ferry radiological emergency response plan.
MILLS, L. M. Tennessee Valley Authority. 82/06/23. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 2pp. 13829:314
24X Fiche 50-259, 82/07/06, 8207120070

--8207120083 Public version of Revision BFN-REF-82-003 to State of AL
radiological emergency response plan, constituting App F to
Browns Ferry radiological emergency response plan.
* Tennessee Valley Authority. 82/06/16. 92pp. 13829:316. 24X
Fiche 50-259, 82/07/06, 8207120070

8208090046 Forwards revisions to physical security plan. Revisions
withheld (ref 10CFR73.21).
MILLS, L. M. Tennessee Valley Authority. 82/07/22. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 1p. 14270:035. 24X
Fiche 50-259, 82/07/22, 8208090046.

8208110219 Releases public version of revised emergency plan
implementing procedures.
FELTON, J. M. Division of Rules and Records. 82/08/04. Document
Management Branch. 1p. 14318:084. 24X Fiche 50-259, 82/08/04,
8208110219.

--8208110221 Forwards public version of revised emergency plan
implementing procedures, including Procedures IP-2 re
notification of unusual event, IP-4 re site emergency &
IP-5 re general emergency.
BLIGER, E. K. Tennessee Valley Authority. 82/07/16. NRC - No
Detailed Affiliation Given. 1p. 14318:087. 24X
Fiche 50-259, 82/08/04, 8208110219

--8208110223 Public version of revised emergency plan implementing
procedures, including Procedures IP-2 re notification of
unusual event, IP-4 re site emergency & IP-5 re general
emergency.
* Tennessee Valley Authority. 82/07/16. 110pp. 14318:088. 24X
Fiche 50-259, 82/08/04, 8208110219.

8208260338 Releases public version of revised radiological emergency
notification directory.
FELTON, J. M. Division of Rules and Records. 82/08/13. Document
Management Branch. 1p. 14575:275. 24X Fiche 50-259, 82/08/13,
8208260338

--8208260343 Forwards public version of Revision 5 to radiological
emergency notification directory. Receipt form encl.
MILLS, L. M., BLIGER, E. K. Tennessee Valley Authority. 82/08/04.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp.
14575:276. 24X Fiche 50-259, 82/08/13, 8208260338.

--8208260346 Public version of Revision 5 to radiological emergency
notification directory.
* Tennessee Valley Authority. 82/08/03. 32pp. 14575:278. 24X
Fiche 50-259, 82/08/13, 8208260338

8208230351 Forwards addl info on implementation of App R, Item III, J re
emergency lighting, per DB Vessaglio 820622 ltr to HQ Parris.
Schedule for item also contained in LM Mills 820715 ltr.
KAMMER, D. S. Tennessee Valley Authority. 82/08/17. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 2pp. 14508:283.
24X Fiche 50-259, 82/08/17, 8208230351.

8208230331 Notifies that addl info re post-accident sampling facility & response schedule requested 820713 will be provided by 821115.
MILLS, L. M. Tennessee Valley Authority 82/08/18 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 1p. 14508 325. 24x
Fiche: 50-259, 82/08/18, 8208230331

D. Adjudicatory correspondence

8208270270 Informs that LBP-82-50 accepted for referral by ASLAB & remanded for reconsideration in ALAB-687.
RAWSON, R. J. Hearing Branch 4. 82/08/25 CHILK, G. J. Office of the Secretary of the Commission 3pp. 14563 088. 24x
Fiche: 50-259, 82/08/25, 8208270270

I. Financial information

8208100002 Forwards "TVA Power Program Summary," Vol 2, for fiscal yr ending 810630 & "1981 Power Program Summary," for fiscal yr ending 810930, per Section 50 71(b) of 10CFR50.
MILLS, L. M. Tennessee Valley Authority 82/08/06 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 116pp. 14294 024.
24x Fiche: 50-000, 82/08/06, 8208100002

8208270457 Forwards financial statements for FY81, power quarterly rept & internal cash flow projection.
MILLS, L. M. Tennessee Valley Authority 82/08/23 SALTZMAN, J.
Assistant Director for State & License Relations 48pp. 14566 135
24x Fiche: 50-000, 82/08/23, 8208270457

J. Insurance & indemnity information

8208310200 Advises that onsite property damage insurance has been purchased in accordance w/10CFR50.54 Coverage status encl
MILLS, L. M. Tennessee Valley Authority 82/08/25 SALTZMAN, J.
Assistant Director for State & License Relations. 2pp. 14693 160
24x Fiche: 50-000, 82/08/25, 8208310200

K. Utility Final Safety Analysis Report (FSAR) & amends

8208170283 Forwards updated FSAR for Browns Ferry Nuclear Plant, Vols 1-7.
MILLS, L. M. Tennessee Valley Authority 82/08/12 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 1p. 14852 001. 24x
Fiche: 50-259, 82/08/12, 8208170283

--8208170293 Updated FSAR for Browns Ferry Nuclear Plant, Vols 1-7.
* Tennessee Valley Authority. 82/08/12. 3430pp. 14852 002. 24x
Fiche: 50-259, 82/08/12, 8208170293

8208170299 Chapter 1 to Browns Ferry updated FSAR, "Introduction & Summary."
* Tennessee Valley Authority. 82/08/12. 150pp. 14852 017. 24x
Fiche: 50-259, 82/08/12, 8208170299

8208170297 Chapter 2 to Browns Ferry updated FSAR, "Site."
* Tennessee Valley Authority. 82/08/12. 450pp. 14852 202. 24x
Fiche: 50-259, 82/08/12, 8208170297

8208170299 Chapter 3 to Browns Ferry updated FSAR, "Reactor."
* Tennessee Valley Authority. 82/08/12. 170pp. 14853 188. 24x
Fiche: 50-259, 82/08/12, 8208170299

8208170301 Chapter 4 to Browns Ferry updated FSAR, "RCS."
* Tennessee Valley Authority. 82/08/12. 170pp. 14854 006. 24x
Fiche: 50-259, 82/08/12, 8208170301

8208170304 Chapter 5 to Browns Ferry updated FSAR, "Containment."
* Tennessee Valley Authority. 82/08/12. 100pp. 14854 150. 24x
Fiche: 50-259, 82/08/12, 8208170304

8208170307 Chapter 6 to Browns Ferry updated FSAR, "Core Standby Coolant Sys."
* Tennessee Valley Authority. 82/08/12. 75pp. 14854 294. 24x
Fiche: 50-259, 82/08/12, 8208170307

8208170308 Chapter 7 to Browns Ferry updated FSAR, "Control & Instrumentation."
* Tennessee Valley Authority. 82/08/12. 300pp. 14855 024. 24x
Fiche: 50-259, 82/08/12, 8208170308

8208170310 Chapter 8 to Browns Ferry updated FSAR, "Electrical Power Sys."
* Tennessee Valley Authority. 82/08/12. 275pp. 14856 133. 24x
Fiche: 50-259, 82/08/12, 8208170310

8208170311 Chapter 9 to Browns Ferry updated FSAR, "Radwaste Control Sys."
* Tennessee Valley Authority. 82/08/12. 120pp. 14857 177. 24x
Fiche: 50-259, 82/08/12, 8208170311

8208170315 Chapter 10 to Browns Ferry updated FSAR, "Auxiliary Sys."
* Tennessee Valley Authority. 82/08/12. 400pp. 14857 177. 24x
Fiche: 50-259, 82/08/12, 8208170315

8208170317 Chapter 11 to Browns Ferry updated FSAR, "Power Conversion Sys."
* Tennessee Valley Authority. 82/08/12. 50pp. 14858 059. 24x
Fiche: 50-259, 82/08/12, 8208170317

8208170319 Chapter 12 to Browns Ferry updated FSAR, "Structures & Shielding."
* Tennessee Valley Authority. 82/08/12. 200pp. 14858 114. 24x
Fiche: 50-259, 82/08/12, 8208170319

8208170322 Chapter 13 to Browns Ferry updated FSAR, "Conduct of Operations."
* Tennessee Valley Authority. 82/08/12. 70pp. 14859 039. 24x
Fiche: 50-259, 82/08/12, 8208170322

8208170328 Chapter 14 to Browns Ferry updated FSAR, "Plant Safety Analysis."
* Tennessee Valley Authority. 82/08/12. 120pp. 14859 224. 24x
Fiche: 50-259, 82/08/12, 8208170328

8208170333 App A to Browns Ferry updated FSAR, "Conformance to AEC Proposed General Design Criteria."
* Tennessee Valley Authority. 82/08/12. 22pp. 14860 029. 24x
Fiche: 50-259, 82/08/12, 8208170333

8208170336 App B to Browns Ferry updated FSAR, "Tech Specs."
* Tennessee Valley Authority. 82/08/12. 1p. 14860 051. 24x
Fiche: 50-259, 82/08/12, 8208170336

8208170339 App C to Browns Ferry updated FSAR, "Structural Loading Criteria."
* Tennessee Valley Authority. 82/08/12. 81pp. 14860 052. 24x
Fiche: 50-259, 82/08/12, 8208170339

8208170340 App D to Browns Ferry updated FSAR, "RA Plan for Browns Ferry Nuclear Plant."
* Tennessee Valley Authority. 82/08/12. 29pp. 14860 136. 24x
Fiche: 50-259, 82/08/12, 8208170340

8208170379 App E to Browns Ferry updated FSAR, "Site Gaseous Release Rate Limit Calculation."
* Tennessee Valley Authority. 82/08/12. 3pp. 14860 163. 24x
Fiche: 50-259, 82/08/12, 8208170379

8208170377 App F to Browns Ferry updated FSAR, "Unit Sharing & Interactions."
* Tennessee Valley Authority. 82/08/12. 30pp. 14860 166. 24x
Fiche: 50-259, 82/08/12, 8208170377

8208170379 App G to Browns Ferry updated FSAR, "Plant Nuclear Safety Operational Analysis."
* Tennessee Valley Authority. 82/08/12. 200pp. 14860 196. 24x
Fiche: 50-259, 82/08/12, 8208170379

8208170380 App H to Browns Ferry updated FSAR, "Core Thermal Design."
* Tennessee Valley Authority. 82/08/12. 6pp. 14860 347. 24x
Fiche: 50-259, 82/08/12, 8208170380

8208170382 App I to Browns Ferry updated FSAR, "Identification-Resolution of CP Concerns."
* Tennessee Valley Authority. 82/08/12. 95pp. 14860 355. 24x
Fiche: 50-259, 82/08/12, 8208170382

8208170384 App J to Browns Ferry updated FSAR, "Reactor Pressure Vessel Design Summary Rept-Unit 1."
* Tennessee Valley Authority. 82/08/12. 1p. 14861 050. 24x
Fiche: 50-259, 82/08/12, 8208170384

8208170386 App K to Browns Ferry updated FSAR, "Reactor Pressure Vessel Design Summary Rept-Unit 2."
* Tennessee Valley Authority. 82/08/12. 1p. 14861 051. 24x
Fiche: 50-259, 82/08/12, 8208170386

8208170387 App L to Browns Ferry updated FSAR, "Reactor Pressure Vessel Design Summary Rept-Unit 3."
* Tennessee Valley Authority. 82/08/12. 1p. 14861 052. 24x
Fiche: 50-259, 82/08/12, 8208170387

Outside Containment in Browns Ferry Nuclear Plant
* Tennessee Valley Authority 82/08/12 50pp 14861 053 24X
Fiche: 50-259, 82/08/12, 8208170389.

8208170392 App N to Browns Ferry updated FBAR, "Browns Ferry Nuclear
Plant Unit 3 Bx Fuel Initial Core Loading."
* Tennessee Valley Authority 82/08/12 100pp. 14861 096. 24X
Fiche: 50-259, 82/08/12, 8208170392

P Operating license stage documents & correspondence

8208030077 Forwards request for addl info re NUREG-0737, Item 11 D 1.
"Testing of Relief & Safety Valves." in order to complete
review of generic test results
VASSALLO, D. B. Operating Reactors Branch 2. 82/06/30. PARRIS, H. Q.
Tennessee Valley Authority. 4pp. 14200:314 24X
Fiche: 50-259, 82/06/30, 8208030077

8208030698 Forwards safety evaluation of proposed method of
implementing NUREG-0737, Item 11 K 3 15, "Isolation of HPCI &
Reactor Core Isolation Cooling " Proposed method
acceptable
VASSALLO, D. B. Operating Reactors Branch 2. 82/06/30 PARRIS, H. Q.
Tennessee Valley Authority. 4pp 14196 321 24X
Fiche: 50-259, 82/06/30, 8208030698

8207080064 Generic ltr to all licensees of operating plants, applicants
for DL & holders of CP re Commission approved charter for
CROR Svc list encl.
DIRKS, W. J. Office of the Executive Director for Operations.
82/07/02 Consolidated Edison Co. of New York 93pp. 66247:231.
24X Fiche: 50-000, 82/07/02, 8207080064.

8208040077 Requests data to support conclusion of adequacy space
cooling for HPCI & reactor core isolation cooling. Response
of B11230 unacceptable since no analysis or test data to
support conclusion submitted.
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/08 PARRIS, H. Q.
Tennessee Valley Authority. 2pp. 14228:291. 24X
Fiche: 50-259, 82/07/08, 8208040077.

8208040064 Notifies that generic issue re possible diesel generator
lockout resolved. Operator training program covers subj
adequately.
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/15. PARRIS, H. Q.
Tennessee Valley Authority. 4pp. 14228:280. 24X
Fiche: 50-259, 82/07/15, 8208040064.

8207270454 Requests extension to 820812 for submittal of updated FBAR
MILLS, L. M. Tennessee Valley Authority. 82/07/20. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 1p 14061:168. 24X
Fiche: 50-259, 82/07/20, 8207270454.

8208040555 Forwards draft technical evaluation rept, "Control of Heavy
Loads " Conference call requested within 30 days to discuss
proposed recommendations in rept
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/22. PARRIS, H. Q.
Tennessee Valley Authority. 2pp 14221:150. 24X
Fiche: 50-259, 82/07/22, 8208040555.

--8208040560 "Control of Heavy Loads." draft technical evaluation rept.
SARGENT, I. Franklin Institute/Franklin Research Center.
TER-C5257-181. 82/07/07. CLEMENSON, F. NRC - No Detailed
Affiliation Given. 38pp. 14221:152. 24X Fiche: 50-259, 82/07/22,
8208040555.

8208110279 Forwards Amends 85, 82 & 56 to Licenses DPR-33, DPR-52 &
DPR-68, respectively, safety evaluation & notice of issuance
& availability. Amends consist of clarification &
administrative changes & additions to reflect plant mode.
CLARK, R. J. Operating Reactors Branch 2. 82/07/22. PARRIS, H. Q.
Tennessee Valley Authority. 2pp. 14332:034. 24X
Fiche: 50-259, 82/07/22, 8208110279.

--8208110283 Amends 85, 82 & 56 to Licenses DPR-33, DPR-52 & DPR-68,
respectively, consisting of clarification & administrative
changes & additions to reflect plant mode & reorganization
of some Tech Spec sections.
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/22. 128pp.
14332:036. 24X Fiche: 50-259, 82/07/22, 8208110279.

--8208110287 Safety evaluation supporting Amends 85, 82 & 56 to Licenses
DPR-33, DPR-52 & DPR-68, respectively.
* Office of Nuclear Reactor Regulation, Director. 82/07/22. 5pp.
14332:165. 24X Fiche: 50-259, 82/07/22, 8208110279.

--8208110290 Notice of issuance & availability of Amends 85, 82 & 56 to
Licenses DPR-33, DPR-52 & DPR-68, respectively.
VASSALLO, D. B. Licensing Branch 2. 82/07/22. 2pp. 14332:170.
24X Fiche: 50-259, 82/07/22, 8208110279.

in BARK plants
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/23. PARRIS, H. Q.
Tennessee Valley Authority. 2pp 14224:360. 24X
Fiche: 50-259, 82/07/23, 8208040663.

8208020221 Responds to NRC 820212 request for addl info re need for
chlorine detectors at facilities, per NUREG-0737,
Item 111 D 3 4. No threat to control room habitability from
chlorine on or off site evident.
MILLS, L. M. Tennessee Valley Authority. 82/07/27. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 2pp. 14151:222.
24X Fiche: 50-259, 82/07/27, 8208020221

8208120363 Forwards revised version of model Tech Specs re electric
power monitoring of reactor protection sys previously
submitted in B11030 ltr
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/28. PARRIS, H. Q.
Tennessee Valley Authority. 3pp. 14340:079 24X
Fiche: 50-259, 82/07/28, 8208120363

8208130444 Forwards safety evaluation & LLL technical evaluation rept
on licensee response to NUREG-0737, Item 11 B 1. "RCB Vents."
Issue resolved.
VASSALLO, D. B. Operating Reactors Branch 2. 82/08/02. PARRIS, H. Q.
Tennessee Valley Authority. 3pp. 14354:343 24X
Fiche: 50-259, 82/08/02, 8208130444.

--8208130448 "RCB Vents." technical evaluation rept
BUTCHER, E., BARNHART, B. Lawrence Livermore Laboratory. FIN
A-0246-2. 82/06/02. Division of Licensing. 4pp. 14354:346.
24X Fiche: 50-259, 82/08/02, 8208130444

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP &
applicants re submittal of documents to NRC Summarizes 10CFR
Chapter I requirements & provides alternatives to
requirements. Svc list encl.
EISENHUT, D. Q. Division of Licensing. 82/08/09. Consolidated
Edison Co. of New York. 1p. 14356:332. 24X Fiche: 50-000, 82/08/09,
8208090194.

8208250376 Forwards mechanical snubber qualification test repts for
Pacific Scientific Co Models PBA 1/4 - PBA 100, as requested
by NRC. Only qualitative-type actuation tests planned at
plants, beginning w/Browns Ferry 2 & Sequoyah 1.
MILLS, L. M. Tennessee Valley Authority. 82/08/18. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 2pp. 14541:002.
24X Fiche: 50-000, 82/08/18, 8208250376.

--8208250383 Revision A to "Qualification Test Rept for Model 1801104-05
PBA 1/4 Shock."
WHITNEY, R. F., GLAUSER, J. E., WRIGHT, W. B. Pacific Scientific. TR
839 RA. 82/03/18. 27pp. 14541:003. 24X Fiche: 50-000, 82/08/18,
8208250376.

--8208250387 Revision R to "Acceptance Test Procedure IT 527 P/N
1801104."
LEVAN, H. C. Pacific Scientific. 79/11/09. 13pp. 14541:032. 24X
Fiche: 50-000, 82/08/18, 8208250376.

--8208250391 "Qualification Test Rept for Model 1801104-07 PBA 1/2 Shock
Arrestor."
WHITNEY, R. F., GLAUSER, J. E., WRIGHT, W. B. Pacific Scientific. TR
840. 79/12/12. 27pp. 14541:043. 24X Fiche: 50-000, 82/08/18,
8208250376.

--8208250402 Revision A to "Qualification Test Rept for Model 1801102-05
PBA 1 Shock Arrestor."
WHITNEY, R. F., GLAUSER, J. E., WRIGHT, W. B. Pacific Scientific. TR
841 RA. 80/03/18. 26pp. 14541:085. 24X Fiche: 50-000, 82/08/18,
8208250376.

--8208250409 Revision I to "Acceptance Test Procedure IT 519 P/N
1801102."
LEVAN, H. C. Pacific Scientific. 79/06/13. 14pp. 14541:111. 24X
Fiche: 50-000, 82/08/18, 8208250376.

--8208250418 "Qualification Test Rept for Model 1801104-05 PBA-3 Shock
Arrestor."
WHITNEY, R. F., GLAUSER, J. E., WRIGHT, W. B. Pacific Scientific. TR
842. 80/01/22. 27pp. 14541:125. 24X Fiche: 50-000, 82/08/18,
8208250376.

--8208250421 Revision R to "Acceptance Test Procedure IT 524 for
1801105."
LEVAN, H. C. Pacific Scientific. 79/02/16. 13pp. 14541:152. 24X
Fiche: 50-000, 82/08/18, 8208250376

--8208250426 "Qualification Test Rept for Model 1801103-07 PSA 10 Shock Arrestor"
WHITNEY, R.F., GLAUSER, J.E., WRIGHT, W.S. Pacific Scientific TR
843 80/01/25 27pp 14541 166 24X Fiche 50-000, 82/08/18,
8208250376

--8208250431 Revision R to "Acceptance Test Procedure IT 523 P/N
1801103"
LEVAN, H.C. Pacific Scientific 79/08/15 14pp 14541:193 24X
Fiche 50-000, 82/08/18, 8208250376

--8208250437 Revision A to "Qualification Test Rept for Model 1801112-11
PSA-33 Shock Arrestor"
WHITNEY, R.F., GLAUSER, J.E., WRIGHT, W.S. Pacific Scientific TR
845 RA 80/02/07 30pp 14541 207 24X Fiche 50-000, 82/08/18,
8208250376

--8208250441 Revision J to "Acceptance Test Procedure IT 534 P/N
1801112"
LEVAN, H.C. Pacific Scientific 77/05/10 12pp 14541:237 24X
Fiche 50-000, 82/08/18, 8208250376

--8208250443 "Qualification Test Rept for Model 1801119-11 PSA-100 Shock
Arrestor"
WHITNEY, R.F., GLAUSER, J.E., WRIGHT, W.S. Pacific Scientific TR
846 80/05/12 31pp 14541 249 24X Fiche 50-000, 82/08/18,
8208250376

--8208250446 Revision H to "Acceptance Test Procedure IT 533 P/N
1801119"
LEVAN, H.C. Pacific Scientific 77/04/07 12pp 14541:280 24X
Fiche 50-000, 82/08/18, 8208250376

G. Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
Leakage" Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/16
Consolidated Edison Co. of New York 87pp 14356:274 24X
Fiche 50-000, 82/07/16, 8204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation" Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19
Michigan, Univ. of 112pp 14358:001 24X Fiche 50-000, 82/07/19,
8204210395

8204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon
Gradual Loss of Air Pressure" Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/20
Consolidated Edison Co. of New York 112pp 14381:001 24X
Fiche 50-000, 82/07/20, 8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From V Hexafluoride
Overpacks" Svc list encl.
COBB, L.I. Division of Fuel Facilities, Materials & Safeguards
82/07/20 Consolidated Edison Co. of New York 71pp 14357:276
24X Fiche 50-000, 82/07/20, 8204210397

8204210398 IE Info Notice 82-26, "RCIC & MPC Turbine Exhaust Check
Valve Failures" Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/22
Consolidated Edison Co. of New York 112pp 14194:321 24X
Fiche 50-000, 82/07/22, 8204210398

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in
Vicinity of Drained & Open RCS" Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co. of New York 122pp 14380:115 24X
Fiche 50-000, 82/07/23, 8204210401

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube
Support Pin Failures at Westinghouse PWRs" Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co. of New York 127pp 14194:120 24X
Fiche 50-000, 82/07/23, 8204210402

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping
at Certain Westinghouse PWR Power Plants" Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/26
Consolidated Edison Co. of New York 121pp 14357:013 24X
Fiche 50-000, 82/07/26, 8204210403

8208030582 Ack receipt of 820716 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-259/82-14,
50-260/82-14 & 50-296/82-14.
LEWIS, R.C. Division of Project & Resident Programs 82/07/26
PARRIS, H.Q. Tennessee Valley Authority 1p 14162:277 24X
Fiche 50-259, 82/07/26, 8208030582

--8208030592 Responds to NRC 820609 ltr re violations noted in IE
Repts 50-259/82-14, 50-260/82-14 & 50-296/82-14 Corrective
actions posted signs identifying shield plugs that require
presence of health physics personnel for removal.
KAMMER, D.S. Tennessee Valley Authority 82/07/16 O'REILLY,
Region 2, Office of Director 4pp 14162:278 24X
Fiche 50-259, 82/07/26, 8208030582

--8208030597 Forwards IE Insp Repts 50-259/82-14, 50-260/82-14 &
50-296/82-14 on 820503-04 & notice of violation.
LEWIS, R.C. Division of Project & Resident Programs 82/06/09
PARRIS, H.Q. Tennessee Valley Authority 2pp 14162:282 24X
Fiche 50-259, 82/07/26, 8208030582

--8208030602 Notice of violation from insp on 820503-04
* Division of Project & Resident Programs 82/06/09 2pp
14162:284 24X Fiche 50-259, 82/07/26, 8208030582

--8208030610 IE Insp Repts 50-259/82-14, 50-260/82-14 & 50-296/82-14
820503-04 Noncompliance noted failure to perform radiation
survey after removal of shield plugs & failure to issue
permit for removal of demineralizer cell shield plugs
PEERY, W.W., BARR, K.P. Division of Engineering & Technical
Programs 82/06/02 4pp 14162:286 24X Fiche 50-259, 82/07/26,
8208030582

8208160395 Forwards IE Insp Repts 50-259/82-18, 50-260/82-18 &
50-296/82-18 on 820626-0725 No noncompliance noted
VERRELLI, D.M. Division of Project & Resident Programs 82/07/26
PARRIS, H.Q. Tennessee Valley Authority 2pp 14348:012 24X
Fiche 50-259, 82/07/26, 8208160395

--8208160408 IE Insp Repts 50-259/82-18, 50-260/82-18 & 50-296/82-18
820626-0725 No noncompliance noted. Major areas inspected:
operational safety, RDM, surveillance testing, maint
observation, TMI action items & independent insp effort.
CHABE, J.W., PAULK, Q.L., CANTRELL, F.S. Division of Project &
Resident Programs 82/07/26 8pp 14348:014 24X
Fiche 50-259, 82/07/26, 8208160395

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work
Fuel Storage Pool." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/28
Consolidated Edison Co. of New York 122pp 14357:146 24X
Fiche 50-000, 82/07/28, 8204210405

8208160294 Forwards IE Insp Repts 50-259/82-21, 50-260/82-21 &
50-296/82-21 on 820628-0702 No noncompliance noted.
VERRELLI, D.M. Division of Project & Resident Programs 82/07/26
PARRIS, H.Q. Tennessee Valley Authority 2pp 14345:255 24X
Fiche 50-259, 82/07/26, 8208160294

--8208160311 IE Insp Repts 50-259/82-21, 50-260/82-21 & 50-296/82-21
820628-0702 No noncompliance noted. Major areas inspected
radioactive matl packaging, shipment & processing, posting of
notices, housekeeping & instrument calibr.
COLLINS, T.R., DEBB, S.T., BARR, K.P. Division of Engineering &
Technical Programs 82/07/22 5pp 14345:257 24X
Fiche 50-259, 82/07/28, 8208160294

8208160484 Ack receipt of 820730 ltr informing NRC of steps taken
correct violations noted in IE Insp Repts 50-259/82-19,
50-260/82-19 & 50-296/82-19
VERRELLI, D. Division of Project & Resident Programs 82/08/03
PARRIS, H.Q. Tennessee Valley Authority 1p 14348:104 24X
Fiche 50-259, 82/08/03, 8208160484

--8208160491 Responds to NRC 820701 ltr re violations noted in IE
Repts 50-259/82-19, 50-260/82-19 & 50-296/82-19. Corrective
actions: torus area high radiation rope barrier reinstalled &
radiological taps placed on floor.
KAMMER, D.S. Tennessee Valley Authority 82/07/30 O'REILLY,
Region 2, Office of Director 3pp 14348:105 24X
Fiche 50-259, 82/08/03, 8208160484

--8208160498 Forwards IE Insp Repts 50-259/82-19, 50-260/82-19 &
50-296/82-19 on 820526-0625 & notice of violation.
LONG, F.J. Division of Project & Resident Programs 82/07/01
PARRIS, H.Q. Tennessee Valley Authority 2pp 14348:108 24X
Fiche 50-259, 82/08/03, 8208160484

--8208160507 Notice of violation from insp on 820526-0625.
* Division of Project & Resident Programs 82/07/01 1p
14348:110 24X Fiche 50-259, 82/08/03, 8208160484

--8208160521 IE Insp Repts 50-259/82-19, 50-260/82-19 & 50-296/82-19
820526-0625 Noncompliance noted: failure to properly
barricade two high radiation areas in torus area.
CHABE, J.W., PAULK, Q.L., CANTRELL, F.S. Division of Project &
Resident Programs 82/06/30 6pp 14348:111 24X
Fiche 50-259, 82/08/03, 8208160484

LEWIS, R. C. Division of Project & Resident Programs. 82/08/04
PARRIS, H. G. Tennessee Valley Authority. 1p 14348:117 24X
Fiche 90-259, 82/08/04, 8208160493

--8208160502 Responds to NRC 820603 ltr re violations noted in IE Insp
Repts 50-259/82-15, 50-260/82-15 & 50-296/82-15. Corrective
actions: daily monitoring & drainage program will be
continued. Violations re items A & B denied.
MILLS, L. M. Tennessee Valley Authority. 82/07/20. O'REILLY, J. P.
Region 2, Office of Director. 7pp 14348:118 24X
Fiche 90-259, 82/08/04, 8208160493

--8208160515 Forwards IE Insp Repts 50-259/82-15, 50-260/82-15 &
50-296/82-15 on 820426-0525 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs. 82/06/03.
PARRIS, H. G. Tennessee Valley Authority. 2pp. 14348:125. 24X
Fiche 50-259, 82/08/04, 8208160493

--8208160520 Notice of violation from Insp on 820426-0525.
* Division of Project & Resident Programs. 82/06/03. 2pp.
14348:127. 24X Fiche. 90-259, 82/08/04, 8208160493.

--8208160528 IE Insp Repts 50-259/82-15, 50-260/82-15 & 50-296/82-15 on
820426-0525. Noncompliance noted: written safety evaluation
re offgas post-treatment sampling station configuration mod
not performed.
CHASE, J. W., PAULK, G. L., CANTRELL, F. S. Division of Project &
Resident Programs. 82/06/02. 10pp 14348:129 24X
Fiche 50-259, 82/08/04, 8208160493

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From
Baffle Water-Jet Impingement" Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/05
Consolidated Edison Co. of New York. 117pp 14368:201. 24X
Fiche 50-000, 82/08/05, 8204210407.

Periodic operating reports & related correspondence

--8208270010 Responds to FOIA request for documents detailing collective
dose exposures in 1981 for operating nuclear power plants &
analyzing said info. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A.
Critical Mass Energy Project. Bpp 14679:208. 24X
Fiche 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power
Facilities For CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp.
14679:216. 24X Fiche. 50-000, 82/07/13, 8208270010.

--8208270601 Forwards "Personnel Whole Body Exposures for CY81," per
10CFR20. 407.
MILLS, L. M. Tennessee Valley Authority. 82/03/23. BROOKS, B. G.
Licensee Operations Evaluation Branch. 1p. 14680:053. 24X
Fiche 50-000, 82/07/13, 8208270010

--8208270605 "Personnel Whole Body Exposures for CY81."
* Tennessee Valley Authority. 82/03/23. 2pp. 14680:054. 24X
Fiche 50-000, 82/07/13, 8208270010

8208120226 Forwards monthly operating repts for June 1982.
JONES, O. T. Tennessee Valley Authority. 82/07/14. Office of
Management and Program Analysis. 1p. 14326:176. 24X
Fiche 50-259, 82/07/14, 8208120226.

--8208120233 Monthly operating repts for June 1982.
JONES, O. T., THOM, T. Tennessee Valley Authority. 82/07/14. 39pp.
14326:177. 24X Fiche 50-259, 82/07/14, 8208120226

Reportable occurrences, LERs & related correspondence

--8208020111 Forwards updated LER 82-020/03X-1.
GREEN, H. J. Tennessee Valley Authority. 82/07/22. O'REILLY, J. P.
Region 2, Office of Director. 1p 14142:108. 24X
Fiche 50-259, 82/07/22, 8208020111.

--8208020113 Updated LER 82-020/03X-1 on 820320, unidentified drywell
leakage increased in excess of Tech Spec limits. Caused by
vibration induced fatigue crack in 3/4-inch reactor water
cleanup sys test connection. Line rerouted.
ROBERTS, W. A. Tennessee Valley Authority. 82/07/22. Region 2,
Office of Director. 3pp 14142:109. 24X Fiche: 50-259, 82/07/22,
8208020111.

Fiche 50-259, 82/07/22, 8208020319.

--8208020331 Updated LER 82-005/03X-1 on 820109, 1 EN reactor motor
operated valve board (LPC1) motor generator set removed from
svc due to loss of lubrication on generator coupling. Caused
by change of consistency & loss of lubricant.
THOMPEN, R. Tennessee Valley Authority. 82/07/22. Region 2,
Office of Director. 2pp. 14151:113. 24X Fiche 50-259, 82/07/22,
8208020319.

8208030160 Forwards LER 82-045/03L-0.
GREEN, H. J. Tennessee Valley Authority. 82/07/27. O'REILLY, J. P.
Region 2, Office of Director. 1p 14160:118. 24X
Fiche 50-259, 82/07/27, 8208030160

--8208030164 LER 82-045/03L-0 on 820701, trouble alarm received for
control bay elevation 593 fire protection panel 1-25-325.
Caused by failed soldered connections as result of
mechanical stresses.
MURPHY, D. Tennessee Valley Authority. 82/07/28. Region 2,
Office of Director. 2pp. 14160:119. 24X Fiche: 50-259, 82/07/27,
8208030160

8208030175 Forwards LER 82-043/03L-0.
GREEN, H. J. Tennessee Valley Authority. 82/07/28. O'REILLY, J. P.
Region 2, Office of Director. 1p 14160:192. 24X
Fiche 50-259, 82/07/28, 8208030175.

--8208030178 LER 82-043/03L-0 on 820630 & 0704, delta air temp recorder
620-737 HBL (TDR-90-103) observed reading discontinuity. Caused
by blown fuses due to lightning striking in vicinity. Caused
environ data station fuses replaced.
IRBY, B. J. Tennessee Valley Authority. 82/07/28. Region 2,
Office of Director. 2pp. 14160:193. 24X Fiche: 50-259, 82/07/28,
8208030175.

8208050208 Forwards updated LER 82-031/03L-1.
GREEN, H. J. Tennessee Valley Authority. 82/07/29. O'REILLY, J. P.
Region 2, Office of Director. 1p. 14212:135. 24X
Fiche 50-259, 82/07/29, 8208050208

--8208050213 Updated LER 82-031/03L-1 on 820518, during normal operation,
hydrogen analyzer B inoperable due to failure of hydrogen
sample inlet pump. Caused by failure to Allen Bradley relay
Model 700-N400A1 contacts. Relay replaced.
CARTER, B. Tennessee Valley Authority. 82/07/29. Region 2,
Office of Director. 2pp. 14212:136. 24X Fiche: 50-259, 82/07/29,
8208050208

8208050229 Forwards updated LER 82-038/03X-1.
GREEN, H. J. Tennessee Valley Authority. 82/07/29. O'REILLY, J. P.
Region 2, Office of Director. 1p. 14209:314. 24X
Fiche 50-259, 82/07/29, 8208050229.

--8208050231 Updated LER 82-038/03X-1 on 820601 & 22 while calibr &
changing out pressure switches, PS-2-74B sw 1 & 2 operated
above Tech Spec limits. Caused by calibr drift. Switches
recalibr, functionally tested & returned to svc.
IRBY, B. J. Tennessee Valley Authority. 82/07/29. Region 2,
Office of Director. 2pp. 14209:315. 24X Fiche: 50-259, 82/07/29,
8208050229.

8208050279 Forwards LER 82-046/03L-0.
GREEN, H. J. Tennessee Valley Authority. 82/07/29. O'REILLY, J. P.
Region 2, Office of Director. 1p 14210:185. 24X
Fiche: 50-259, 82/07/29, 8208050279

--8208050281 LER 82-046/03L-0 on 820701-05, intermittent trouble alarms
received from fire protection panel 1-25-311. Caused by
common control card giving intermittent trouble alarms.
Circuit board replaced.
MURPHY, D. E. Tennessee Valley Authority. 82/07/29. Region 2,
Office of Director. 2pp. 14210:186. 24X Fiche: 50-259, 82/07/29,
8208050279.

8208050450 Forwards LER 82-044/03L-0.
GREEN, H. J. Tennessee Valley Authority. 82/07/29. O'REILLY, J. P.
Region 2, Office of Director. 1p. 14214:158. 24X
Fiche: 50-259, 82/07/29, 8208050450.

--8208050457 LER 82-044/03L-0 on 820625 & 0709, drywell sump pump
discharge valve 1-FCV-77-2A failed to close. Caused by failed
solenoid valve. Valve V80-3521 replaced. All Versa solenoid
valves will be replaced during future outages.
ROBERTS, W. A. Tennessee Valley Authority. 82/07/29. Region 2,
Office of Director. 2pp. 14214:159. 24X Fiche: 50-259, 82/07/29,
8208050450.

8208100037 PNO-11-82-090 on 820730, w/Unit 2 shutdown for scheduled refueling & mods. Units 1 & 3 failed secondary containment integrity tests & were shutdown. Caused by in-leakage between common refueling zone & three individual reactor zones. BUTCHER, R. C., VERRELLI, D. M. Region 2, Office of Director. 82/08/05. 1p. 14296 261. 24X Fiche 50-259, 82/08/05. 8208100037.

8208200062 Forwards updated LER 82-013/01X-1. GREEN, H. J. Tennessee Valley Authority. 82/08/10. O'REILLY, J. P. Region 2, Office of Director. 1p. 14392 181. 24X Fiche 50-259, 82/08/10. 8208200062

--8208200073 Updated LER 82-013/01X-1 on 820202, during calibr of degraded voltage relays on 4 LV shutdown boards, trip setpoint of 12 relays found below Tech Specs. Caused by setpoint drift. Gould-Brown Boveri relays recalibr. SOLLEY, B. W. Tennessee Valley Authority. 82/08/10. Region 2, Office of Director. 2pp. 14392 182. 24X Fiche 50-259, 82/08/10. 8208200062.

8208270492 Forwards LER 82-048/03L-D. GREEN, H. J. Tennessee Valley Authority. 82/08/13. O'REILLY, J. P. Region 2, Office of Director. 1p. 14564 092. 24X Fiche 50-259, 82/08/13. 8208270492

--8208270507 LER 82-048/03L-0 on 820718, coil for relay 16A-A37 failed, resulting in partial primary containment isolation. Caused by burned out OE Type CR 120A Model 50000010002 coil. Relay coil replaced. MURPHY, D. Tennessee Valley Authority. 82/08/13. Region 2, Office of Director. 2pp. 14564 093. 24X Fiche 50-259, 82/08/13. 8208270492

8208270510 Forwards LER 82-049/03L-0. GREEN, H. J. Tennessee Valley Authority. 82/08/13. O'REILLY, J. P. Region 2, Office of Director. 1p. 14564 106. 24X Fiche 50-259, 82/08/13. 8208270510.

--8208270524 LER 82-049/03L-0 on 820721 & 23, SI 4.1-A-11 (MSIV closure functional test) & SI 4.5-E-1.c (HPCI motor operated valve operability test) & SI 4.5-E-1.b & e (HPCI flow rate) not performed. Caused by defective procedure. CAMPBELL, O. Tennessee Valley Authority. 82/08/13. Region 2, Office of Director. 2pp. 14564 107. 24X Fiche 50-259, 82/08/13. 8208270510.

8208270544 Forwards LER 82-047/03L-0. GREEN, H. J. Tennessee Valley Authority. 82/08/13. O'REILLY, J. P. Region 2, Office of Director. 1p. 14566 033. 24X Fiche 50-259, 82/08/13. 8208270544.

--8208270548 LER 82-047/03L-0 on 820721, while performing SI 4.2-A-3 (reactor water level indicating switch) LIS-3-56D, switches 1 & 2 operated at 454.56 inches. Caused by sticking pointer on indicator. Pointer adjusted. IRBY, B. J. Tennessee Valley Authority. 82/08/13. Region 2, Office of Director. 2pp. 14566 034. 24X Fiche 50-259, 82/08/13. 8208270544.

8208270086 Forwards LER 82-053/01T-0. GREEN, H. J. Tennessee Valley Authority. 82/08/19. O'REILLY, J. P. Region 2, Office of Director. 1p. 14563 190. 24X Fiche 50-259, 82/08/19. 8208270086.

--8208270091 LER 82-053/01T-0 on 820730, while performing Safety Insp 4.7.C.1 prior to refueling, secondary containment integrity could not be confirmed. Caused by displaced relief panel in steam tunnel, allowing in-leakage. Relief panel replaced. WILLIAMSON, B. Tennessee Valley Authority. 82/08/19. Region 2, Office of Director. 3pp. 14563 191. 24X Fiche 50-259, 82/08/19. 8208270086.

8208270231 Forwards LER 82-054/01T-0. GREEN, H. J. Tennessee Valley Authority. 82/08/19. O'REILLY, J. P. Region 2, Office of Director. 1p. 14564 153. 24X Fiche 50-259, 82/08/19. 8208270231.

--8208270252 LER 82-054/01T-0 on 820804, during computer analysis of branch lines for suppression chamber attached piping, drywell & torus purge sys found to have branch line anchored to floor. Caused by design deficiency. Anchor design changed. JEWETT, J. R. Tennessee Valley Authority. 82/08/19. Region 2, Office of Director. 2pp. 14564 154. 24X Fiche 50-259, 82/08/19. 8208270231.

8208300290 Forwards LER 82-056/01T-0. GREEN, H. J. Tennessee Valley Authority. 82/08/23. O'REILLY, J. P. Region 2, Office of Director. 1p. 14599 343. 24X Fiche 50-259, 82/08/23. 8208300290.

--8208300304 LER 82-056/01T-0 on 820810, during shutdown, insp in drywell revealed crack in elbow weld of defunct 1-inch pressure differential indicating switch line on jet pump riser. Cause unknown. Elbow replaced. Rept expected within 60 days. GARRIGAN, R. W. Tennessee Valley Authority. 82/08/23. Region 2, Office of Director. 2pp. 14599 344. 24X Fiche 50-259, 82/08/23. 8208300290.

8208310097 PNO-11-82-097 on 820819, truck transporting low specific radioactive matl from facility to Richland, WA found to have liquid dripping from truck bed. On 820821, drum found to have small holes near base. COLLINS, T. R., BARR, K. P. Region 2, Office of Director. 82/08/24. 1p. 14695 084. 24X Fiche 50-259, 82/08/24. 8208310097.

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

P. Security, medical, emergency & fire protection plans

8207060127 Forwards response to Section III. Q of App R to 10CFR50 re fire protection plan. MILLS, L. M. Tennessee Valley Authority. 82/06/30. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 202pp. 13712 142. 24X Fiche 50-259, 82/06/30. 8207060127

8207120070 Releases public version of revision to State of AL radiological emergency response plan. FELTON, J. M. Division of Rules and Records. 82/07/06. Document Management Branch. 1p. 13829 312. 24X Fiche 50-259, 82/07/06. 8207120070

--8207120078 Forwards public version of Revision BFN-REF-82-003 to State of AL radiological emergency response plan, constituting App F to Browns Ferry radiological emergency response plan. MILLS, L. M. Tennessee Valley Authority. 82/06/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 13829 314. 24X Fiche 50-259, 82/07/06. 8207120070

--8207120083 Public version of Revision BFN-REF-82-003 to State of AL radiological emergency response plan, constituting App F to Browns Ferry radiological emergency response plan. * Tennessee Valley Authority. 82/06/16. 92pp. 13829 316. 24X Fiche 50-259, 82/07/06. 8207120070

8208090046 Forwards revisions to physical security plan. Revisions withheld (ref 10CFR73 21). MILLS, L. M. Tennessee Valley Authority. 82/07/22. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 14270 035. 24X Fiche 50-259, 82/07/22. 8208090046.

8208110219 Releases public version of revised emergency plan implementing procedures. FELTON, J. M. Division of Rules and Records. 82/08/04. Document Management Branch. 1p. 14318 084. 24X Fiche 50-259, 82/08/04. 8208110219

--8208110221 Forwards public version of revised emergency plan implementing procedures, including Procedures IP-2 re notification of unusual event, IP-4 re site emergency & IP-5 re general emergency. BLIGER, E. K. Tennessee Valley Authority. 82/07/16. NRC - No Detailed Affiliation Given. 1p. 14318 087. 24X Fiche 50-259, 82/08/04. 8208110219

--8208110223 Public version of revised emergency plan implementing procedures, including Procedures IP-2 re notification of unusual event, IP-4 re site emergency & IP-5 re general emergency. * Tennessee Valley Authority. 82/07/16. 110pp. 14318 088. 24X Fiche 50-259, 82/08/04. 8208110219.

8208260338 Releases public version of revised radiological emergency notification directory. FELTON, J. M. Division of Rules and Records. 82/08/13. Document Management Branch. 1p. 14575 275. 24X Fiche 50-259, 82/08/13. 8208260338

--8208260343 Forwards public version of Revision 3 to radiological emergency notification directory Receipt Form encl. MILLS, L. M., BLIGER, E. K. Tennessee Valley Authority. 82/08/04. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 14575 276. 24X Fiche 50-259, 82/08/13. 8208260338.

--8208260346 Public version of Revision 3 to radiological emergency notification directory. * Tennessee Valley Authority. 82/08/03. 32pp. 14575 278. 24X Fiche 50-259, 82/08/13. 8208260338.

8208230351 Forwards addl info on implementation of App R, Item III J re emergency lighting, per 08 Vassallo 820622 ltr to HQ Parriss. Schedule for item also contained in L.M. Mills 820719 ltr. YAMMER, D. S. Tennessee Valley Authority. 82/08/17. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 14508. 203. 24X Fiche: 50-259, 82/08/17, 8208230351

8208230331 Notifies that addl info re post-accident sampling facility & response schedule requested 820713 will be provided by 821115. MILLS, L. M. Tennessee Valley Authority. 82/08/18. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 14508. 325. 24X Fiche: 50-259, 82/08/18, 8208230331

G Adjudicatory correspondence

8208270270 Informs that LBP-82-50 accepted for referral by ABLAB & remanded for reconsideration in ALAB-687. RAKSON, R. J. Hearing Branch 4. 82/08/25. CHILK, B. J. Office of the Secretary of the Commission. 3pp. 14563. 088. 24X Fiche: 50-259, 82/08/25, 8208270270.

I Financial information

8208100002 Forwards "TVA Power Program Summary," Vol 2, for fiscal yr ending 810630, & "1981 Power Program Summary," for fiscal yr ending 810930, per Section 50 71(b) of 10CFR50. MILLS, L. M. Tennessee Valley Authority. 82/08/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 116pp. 14294. 024. 24X Fiche: 50-000, 82/08/06, 8208100002.

8208270457 Forwards financial statements for FY81, power quarterly rept & internal cash flow projection. MILLS, L. M. Tennessee Valley Authority. 82/08/23. SALTZMAN, J. Assistant Director for State & License Relations. 48pp. 14566. 139. 24X Fiche: 50-000, 82/08/23, 8208270457

J Insurance & indemnity information

8208310200 Advises that onsite property damage insurance has been purchased, in accordance w/10CFR50.54 Coverage status encl. MILLS, L. M. Tennessee Valley Authority. 82/08/25. SALTZMAN, J. Assistant Director for State & License Relations. 2pp. 14693. 160. 24X Fiche: 50-000, 82/08/25, 8208310200.

K Utility Final Safety Analysis Report (FSAR) & amends

8208170283 Forwards updated FSAR for Browns Ferry Nuclear Plant, Vols 1-7. MILLS, L. M. Tennessee Valley Authority. 82/08/12. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 14852. 001. 24X Fiche: 50-259, 82/08/12, 8208170283.

--8208170293 Updated FSAR for Browns Ferry Nuclear Plant, Vols 1-7. Tennessee Valley Authority. 82/08/12. 3430pp. 14852. 002. 24X Fiche: 50-259, 82/08/12, 8208170293

8208170295 Chapter 1 to Browns Ferry updated FSAR, "Introduction & Summary." Tennessee Valley Authority. 82/08/12. 150pp. 14852. 017. 24X Fiche: 50-259, 82/08/12, 8208170295.

8208170297 Chapter 2 to Browns Ferry updated FSAR, "Site." Tennessee Valley Authority. 82/08/12. 450pp. 14852. 202. 24X Fiche: 50-259, 82/08/12, 8208170297.

8208170299 Chapter 3 to Browns Ferry updated FSAR, "Reactor." Tennessee Valley Authority. 82/08/12. 170pp. 14853. 188. 24X Fiche: 50-259, 82/08/12, 8208170299.

8208170301 Chapter 4 to Browns Ferry updated FSAR, "RCS." Tennessee Valley Authority. 82/08/12. 170pp. 14854. 006. 24X Fiche: 50-259, 82/08/12, 8208170301.

8208170304 Chapter 5 to Browns Ferry updated FSAR, "Containment." Tennessee Valley Authority. 82/08/12. 100pp. 14854. 150. 24X Fiche: 50-259, 82/08/12, 8208170304.

8208170307 Chapter 6 to Browns Ferry updated FSAR, "Core Standby Coolant Sys." Tennessee Valley Authority. 82/08/12. 75pp. 14854. 294. 24X Fiche: 50-259, 82/08/12, 8208170307.

8208170308 Chapter 7 to Browns Ferry updated FSAR, "Control & Instrumentation." Tennessee Valley Authority. 82/08/12. 500pp. 14855. 024. 24X Fiche: 50-259, 82/08/12, 8208170308.

8208170310 Chapter 8 to Browns Ferry updated FSAR, "Electrical Power Sys." Tennessee Valley Authority. 82/08/12. 275pp. 14856. 133. 24X Fiche: 50-259, 82/08/12, 8208170310.

8208170311 Chapter 9 to Browns Ferry updated FSAR, "Radioactive Control Sys." Tennessee Valley Authority. 82/08/12. 120pp. 14857. 177. 24X Fiche: 50-259, 82/08/12, 8208170311.

8208170315 Chapter 10 to Browns Ferry updated FSAR, "Auxiliary Sys." Tennessee Valley Authority. 82/08/12. 400pp. 14857. 177. 24X Fiche: 50-259, 82/08/12, 8208170315.

8208170317 Chapter 11 to Browns Ferry updated FSAR, "Power Conversion Sys." Tennessee Valley Authority. 82/08/12. 50pp. 14858. 059. 24X Fiche: 50-259, 82/08/12, 8208170317.

8208170319 Chapter 12 to Browns Ferry updated FSAR, "Structures & Shielding." Tennessee Valley Authority. 82/08/12. 200pp. 14858. 114. 24X Fiche: 50-259, 82/08/12, 8208170319.

8208170322 Chapter 13 to Browns Ferry updated FSAR, "Conduct of Operations." Tennessee Valley Authority. 82/08/12. 70pp. 14859. 039. 24X Fiche: 50-259, 82/08/12, 8208170322.

8208170328 Chapter 14 to Browns Ferry updated FSAR, "Plant Safety Analysis." Tennessee Valley Authority. 82/08/12. 120pp. 14859. 224. 24X Fiche: 50-259, 82/08/12, 8208170328.

8208170333 App A to Browns Ferry updated FSAR, "Conformance to AEC Proposed General Design Criteria." Tennessee Valley Authority. 82/08/12. 22pp. 14860. 029. 24X Fiche: 50-259, 82/08/12, 8208170333.

8208170336 App B to Browns Ferry updated FSAR, "Tech Specs." Tennessee Valley Authority. 82/08/12. 1p. 14860. 031. 24X Fiche: 50-259, 82/08/12, 8208170336.

8208170339 App C to Browns Ferry updated FSAR, "Structural Loading Criteria." Tennessee Valley Authority. 82/08/12. 81pp. 14860. 052. 24X Fiche: 50-259, 82/08/12, 8208170339.

8208170340 App D to Browns Ferry updated FSAR, "QA Plan for Browns Ferry Nuclear Plant." Tennessee Valley Authority. 82/08/12. 29pp. 14860. 136. 24X Fiche: 50-259, 82/08/12, 8208170340.

8208170375 App E to Browns Ferry updated FSAR, "Site Gaseous Release Rate Limit Calculation." Tennessee Valley Authority. 82/08/12. 3pp. 14860. 163. 24X Fiche: 50-259, 82/08/12, 8208170375.

8208170377 App F to Browns Ferry updated FSAR, "Unit Sharing & Interactions." Tennessee Valley Authority. 82/08/12. 30pp. 14860. 166. 24X Fiche: 50-259, 82/08/12, 8208170377.

8208170379 App G to Browns Ferry updated FSAR, "Plant Nuclear Safety Operational Analysis." Tennessee Valley Authority. 82/08/12. 200pp. 14860. 196. 24X Fiche: 50-259, 82/08/12, 8208170379.

8208170380 App H to Browns Ferry updated FSAR, "Core Thermal Design." Tennessee Valley Authority. 82/08/12. 6pp. 14860. 347. 24X Fiche: 50-259, 82/08/12, 8208170380.

8208170382 App I to Browns Ferry updated FSAR, "Identification-Resolution of CP Concerns." Tennessee Valley Authority. 82/08/12. 35pp. 14860. 355. 24X Fiche: 50-259, 82/08/12, 8208170382.

8208170386 App K to Browns Ferry updated FSAR, "Reactor Pressure Vessel Design Summary Rept-Unit 2." Tennessee Valley Authority. 82/08/12. 1p. 14861. 051. 24X Fiche: 50-259, 82/08/12, 8208170386.

8208170389 App M to Browns Ferry updated FSAR, "Rept on Pipe Failure Outside Containment in Browns Ferry Nuclear Plant." Tennessee Valley Authority. 82/08/12. 50pp. 14861. 053. 24X Fiche: 50-259, 82/08/12, 8208170389.

DOCKETED ITEMS

P Operating license stage documents & correspondence

8208030077 Forwards request for addl info re NUREG-0737, Item II D 1. "Testing of Relief & Safety Valves." in order to complete review of generic test results.
VASSALLO, D B Operating Reactors Branch 2 82/06/30 PARRIS, H O
Tennessee Valley Authority App 14200 314 24X
Fiche: 50-259, 82/06/30, 8208030077

8208030698 Forwards safety evaluation of proposed method of implementing NUREG-0737, Item II K 3 15. "Isolation of HPCI & Reactor Core Isolation Cooling." Proposed method acceptable.
VASSALLO, D B Operating Reactors Branch 2 82/06/30 PARRIS, H O
Tennessee Valley Authority App 14196 321 24X
Fiche: 50-259, 82/06/30, 8208030698

8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl
DIRCKB, W J Office of the Executive Director for Operations
82/07/02 Consolidated Edition Co of New York 93pp 14194 001
24X Fiche 50-000, 82/07/02, 8207080064

8208040077 Requests data to support conclusion of adequacy space cooling for HPCI & reactor core isolation cooling. Response of 811230 unacceptable since no analysis or test data to support conclusion submitted.
VASSALLO, D B Operating Reactors Branch 2 82/07/08 PARRIS, H O
Tennessee Valley Authority App 14228 291 24X
Fiche: 50-259, 82/07/08, 8208040077

8208040064 Notifies that generic issue re possible diesel generator lockout resolved. Operator training program covers sub; adequately.
VASSALLO, D B Operating Reactors Branch 2 82/07/15 PARRIS, H O
Tennessee Valley Authority App 14228 280 24X
Fiche: 50-259, 82/07/15, 8208040064

8207270454 Requests extension to 820812 for submittal of updated FSAR.
MILLS, L M Tennessee Valley Authority 82/07/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 1p. 14061 168 24X
Fiche: 50-259, 82/07/20, 8207270454

8208040555 Forwards draft technical evaluation rept. "Control of Heavy Loads." Conference call requested within 30 days to discuss proposed recommendations in rept.
VASSALLO, D B Operating Reactors Branch 2 82/07/22 PARRIS, H O
Tennessee Valley Authority App 14221 150 24X
Fiche: 50-259, 82/07/22, 8208040555

8208110279 Forwards Amends 85, 82 & 56 to Licenses DPR-33, DPR-52 & DPR-68, respectively, safety evaluation & notice of issuance & availability. Amends consist of clarification & administrative changes & additions to reflect plant mods.
CLARK, R J Operating Reactors Branch 2 82/07/22 PARRIS, H O
Tennessee Valley Authority App 14332 034 24X
Fiche: 50-259, 82/07/22, 8208110279

--8208110283 Amends 85, 82 & 56 to Licenses DPR-33, DPR-52 & DPR-68, respectively, consisting of clarification & administrative changes & additions to reflect plant mods & reorganization of some Tech Spec sections.
VASSALLO, D B Operating Reactors Branch 2 82/07/22 128pp.
14332 036 24X Fiche: 50-259, 82/07/22, 8208110279.

--8208110287 Safety evaluation supporting Amends 85, 82 & 56 to Licenses DPR-33, DPR-52 & DPR-68, respectively.
Office of Nuclear Reactor Regulation, Director 82/07/22 5pp.
14332 163 24X Fiche: 50-259, 82/07/22, 8208110279

--8208110290 Notice of issuance & availability of Amends 85, 82 & 56 to Licenses DPR-33, DPR-52 & DPR-68, respectively.
VASSALLO, D B Licensing Branch 2 82/07/22 2pp. 14332 170
24X Fiche: 50-259, 82/07/22, 8208110279

8208040663 Requests 820729 meeting in Chattanooga, TN to discuss MSIVs in BWR plants.
VASSALLO, D B Operating Reactors Branch 2 82/07/23 PARRIS, H O
Tennessee Valley Authority App 14224 360 24X
Fiche: 50-259, 82/07/23, 8208040663

8208020221 Responds to NRC 820212 request for addl info re need for chlorine detectors at facilities, per NUREG-0737, Item III D 3 4 No threat to control room habitability from chlorine on or off site evident.
MILLS, L M Tennessee Valley Authority. 82/07/27. DENTON, H R.
Office of Nuclear Reactor Regulation, Director. 2pp. 14151 222.
24X Fiche: 50-259, 82/07/27, 8208020221.

8208120363 Forwards revised version of model Tech Specs re electric power monitoring of reactor protection sys previously submitted in 811030 ltr.
VASSALLO, D B Operating Reactors Branch 2 82/07/28 PARRIS, H O
Tennessee Valley Authority App 14340 079 24X
Fiche: 50-259, 82/07/28, 8208120363

8208130444 Forwards safety evaluation & LLL technical evaluation rept on licensee response to NUREG-0737, Item II B 1. "RCB Vents." Issue resolved.
VASSALLO, D B Operating Reactors Branch 2 82/08/02 PARRIS, H O
Tennessee Valley Authority App 14354 343 24X
Fiche: 50-259, 82/08/02, 8208130444.

--8208130448 "RCB Vents." technical evaluation rept.
BYTCHER, E., BARNHART, B Lawrence Livermore Laboratory FIN
A-0246-2. 82/06/02 Division of Licensing. App 14354 346
24X Fiche 50-259, 82/08/02, 8208130444.

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl.
FISBENHUT, D O Division of Licensing. 82/08/09 Consolidated
Edison Co. of New York. 1p. 14356 332 24X Fiche: 50-000, 82/08/09, 8208090194

8208250376 Forwards mechanical snubber qualification test repts for Pacific Scientific Co Models PSA 1/4 - PSA 100, as requested by NRC Only qualitative-type actuation tests planned at plants, beginning w/Browns Ferry 2 & Bequyah 1.
MILLS, L M Tennessee Valley Authority 82/08/18 DENTON, H R.
Office of Nuclear Reactor Regulation, Director. 2pp. 14541 002.
24X Fiche: 50-000, 82/08/18, 8208250376

--8208250383 Revision A to "Qualification Test Rept for Model 1801104-05 PSA 1/4 Shock"
WHITNEY, R F., GLAUSER, J E., WRIGHT, W B Pacific Scientific. 1R
839 RA. 82/03/18 27pp. 14541 005 24X Fiche: 50-000, 82/08/18, 8208250376

--8208250387 Revision R to "Acceptance Test Procedure IT 927 P/N 1801104."
LEVAN, H C. Pacific Scientific. 79/11/09. 13pp. 14541 032. 24X
Fiche: 50-000, 82/08/18, 8208250376

--8208250391 "Qualification Test Rept for Model 1801104-07 PSA 1/2 Shock Arrestor."
WHITNEY, R F., GLAUSER, J E., WRIGHT, W B Pacific Scientific. 1R
840 79/12/12 27pp. 14541 045. 24X Fiche: 50-000, 82/08/18, 8208250376.

--8208250402 Revision A to "Qualification Test Rept for Model 1801102-05 PSA 1 Shock Arrestor."
WHITNEY, R F., GLAUSER, J E., WRIGHT, W B. Pacific Scientific. 1R
841 RA. 80/03/18 26pp. 14541 085. 24X Fiche: 50-000, 82/08/18, 8208250376

--8208250409 Revision T to "Acceptance Test Procedure IT 519 P/N 1801102."
LEVAN, H C. Pacific Scientific. 79/06/13. 14pp. 14541 111. 24X
Fiche: 50-000, 82/08/18, 8208250376

--8208250415 "Qualification Test Rept for Model 1801106-05 PSA-3 Shock Arrestor."
WHITNEY, R F., GLAUSER, J E., WRIGHT, W B Pacific Scientific. 1R
842 80/01/22 27pp. 14541 125. 24X Fiche: 50-000, 82/08/18, 8208250376

--8208250421 Revision R to "Acceptance Test Procedure IT 524 for 1801106."
LEVAN, H C. Pacific Scientific. 79/02/16. 13pp. 14541 152. 24X
Fiche: 50-000, 82/08/18, 8208250376.

--8208250426 "Qualification Test Rept for Model 1801103-07 PSA 10 Shock Arrestor."
WHITNEY, R F., GLAUSER, J E., WRIGHT, W B. Pacific Scientific. 1R
843. 80/01/25. 27pp. 14541 166. 24X Fiche: 50-000, 82/08/18, 8208250376

--8208250431 Revision R to "Acceptance Test Procedure IT 523 P/N 1801103."
LEVAN, H C. Pacific Scientific. 79/08/15. 14pp. 14541 193. 24X
Fiche: 50-000, 82/08/18, 8208250376.

--8208250437 Revision A to "Qualification Test Rept for Model 1801112-11 PSA-35 Shock Arrestor."
WHITNEY, R F., GLAUSER, J E., WRIGHT, W B Pacific Scientific. 1R
845 RA. 80/02/07. 30pp. 14541 207. 24X Fiche: 50-000, 82/08/18, 8208250376

8250441 Revision J to "Acceptance Test Procedure IT 534 P/N
8201112 "
EVANS, H. C. Pacific Scientific 77/05/10 12pp. 14541:237 24X
Fiche 50-000, 82/08/18, 8208250376.

8250443 "Qualification Test Rept for Model 1B01119-11 PSA-100 Block
Arrestor "
WHITNEY, R. F., CLAUSER, J. E., WRIGHT, W. S. Pacific Scientific TH
346 80/05/12 31pp. 14541:249 24X Fiche 50-000, 82/08/18,
8208250376

8250446 Revision H to "Acceptance Test Procedure IT 533 P/N
801119 "
EVANS, H. C. Pacific Scientific 77/04/07 12pp. 14541:280. 24X
Fiche 50-000, 82/08/18, 8208250376

Inspection reports. IE Bulletins & correspondence

820393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
Leakage." Svc list encl.

DAN, E. L. Division of Engineering & Quality Assurance. 82/07/16
Consolidated Edison Co. of New York 87pp. 14356:274 24X
Fiche 50-000, 82/07/16, 8204210393.

820395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of
Requirement of Personnel Monitoring Devices for External
Isolation." Svc list encl.

DAN, E. L. Division of Engineering & Quality Assurance. 82/07/19,
Michigan, Univ. of. 112pp. 14398:001. 24X Fiche: 50-000, 82/07/19,
8210395.

820396 IE Info Notice 82-25, "Failures of Miller Actuators Upon
Dual Loss of Air Pressure." Svc list encl.

DAN, E. L. Division of Engineering & Quality Assurance. 82/07/20.
Consolidated Edison Co. of New York 112pp. 14381:001. 24X
Fiche 50-000, 82/07/20, 8204210396.

820397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride
Trucks." Svc list encl.

B. L. I. Division of Fuel Facilities, Materials & Safeguards.
82/07/20 Consolidated Edison Co. of New York 71pp. 14357:276.
Fiche 50-000, 82/07/20, 8204210397

820398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check
Valve Failures." Svc list encl.

DAN, E. L. Division of Engineering & Quality Assurance. 82/07/22
Consolidated Edison Co. of New York 112pp. 14194:321 24X
Fiche 50-000, 82/07/22, 8204210398

820401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in
Unit of Drained & Open RCB." Svc list encl.

DAN, E. L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York. 122pp. 14380:115. 24X
Fiche 50-000, 82/07/23, 8204210401

820402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube
Port Pin Failures at Westinghouse PWRs." Svc list encl.

DAN, E. L. Division of Engineering & Quality Assurance. 82/07/23
Consolidated Edison Co. of New York 127pp. 14194:120 24X
Fiche 50-000, 82/07/23, 8204210402.

820403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping
Certain Westinghouse PWR Power Plants." Svc list encl.

DAN, E. L. Division of Engineering & Quality Assurance. 82/07/26
Consolidated Edison Co. of New York. 121pp. 14357:013 24X
Fiche 50-000, 82/07/26, 8204210403.

820582 Ack receipt of 820716 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-259/82-14,
50-260/82-14 & 50-296/82-14.

CHASE, J. W. Division of Project & Resident Programs. 82/07/26.
PARRIS, H. Q. Tennessee Valley Authority. 1p. 14162:277. 24X
Fiche 50-259, 82/07/26, 8208030582

8203952 Responds to NRC 820609 ltr re violations noted in IE Insp
Repts 50-259/82-14, 50-260/82-14 & 50-296/82-14. Corrective
actions posted signs identifying shield plugs that require
presence of health physics personnel for removal.

KAHER, D. S. Tennessee Valley Authority. 82/07/16. O'REILLY, J. P.
Region 2, Office of Director. App. 14162:278. 24X
Fiche 50-259, 82/07/26, 8208030582.

8203997 Forwards IE Insp Repts 50-259/82-14, 50-260/82-14 &
50-296/82-14 on 820503-04 & notice of violation

WIS, R. C. Division of Project & Resident Programs. 82/06/09.
PARRIS, H. Q. Tennessee Valley Authority. 2pp. 14162:282. 24X
Fiche 50-259, 82/07/26, 8208030582.

820602 Notice of violation from Insp on 820503-04.

Division of Project & Resident Programs. 82/06/09. 2pp.
1462:284. 24X Fiche: 50-259, 82/07/26, 8208030582.

--8208030610 IE Insp Repts 50-259/82-14, 50-260/82-14 & 50-296/82-14 on
820503-04 Noncompliance noted failure to perform radiation
survey after removal of shield plugs & failure to issue
permit for removal of demineralizer cell shield plugs.
PEERY, W. W., BARR, K. P. Division of Engineering & Technical
Programs. 82/06/02 4pp. 14162:286. 24X Fiche 50-259, 82/07/26,
8208030582.

8208160395 Forwards IE Insp Repts 50-259/82-18, 50-260/82-18 &
50-296/82-18 on 820626-0725. No noncompliance noted

VERRELL, I. D. M. Division of Project & Resident Programs. 82/07/26.
PARRIS, H. Q. Tennessee Valley Authority. 2pp. 14348:012 24X
Fiche: 50-259, 82/07/26, 8208160395

--8208160408 IE Insp Repts 50-259/82-18, 50-260/82-18 & 50-296/82-18 on

820626-0725 No noncompliance noted. Major areas inspected:
operational safety, RDS, surveillance testing, maint
observation, IMI action items & independent insp effort.
CHASE, J. W., PAULK, O. L., CANTRELL, F. S. Division of Project &
Resident Programs. 82/07/26. 8pp. 14348:014 24X
Fiche 50-259, 82/07/26, 8208160395

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in

Fuel Storage Pool." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28
Consolidated Edison Co. of New York. 122pp. 14357:146. 24X
Fiche 50-000, 82/07/28, 8204210405.

8208160294 Forwards IE Insp Repts 50-259/82-21, 50-260/82-21 &
50-296/82-21 on 820628-0702. No noncompliance noted

VERRELL, I. D. M. Division of Project & Resident Programs. 82/07/28
PARRIS, H. Q. Tennessee Valley Authority. 2pp. 14345:255 24X
Fiche 50-259, 82/07/28, 8208160294

--8208160311 IE Insp Repts 50-259/82-21, 50-260/82-21 & 50-296/82-21 on

820628-0702 No noncompliance noted. Major areas inspected:
radioactive matl packaging, shipment & processing, posting of
notices, housekeeping & instrument calibr.
COLLINS, T. R., DESS, B. T., BARR, K. P. Division of Engineering &
Technical Programs. 82/07/22. 5pp. 14345:257 24X
Fiche 50-259, 82/07/28, 8208160294

8208160484 Ack receipt of 820730 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-259/82-19,
50-260/82-19 & 50-296/82-19.

VERRELL, I. D. Division of Project & Resident Programs. 82/08/03
PARRIS, H. Q. Tennessee Valley Authority. 1p. 14348:104. 24X
Fiche 50-259, 82/08/03, 8208160484

--8208160491 Responds to NRC 820701 ltr re violations noted in IE Insp

Repts 50-259/82-19, 50-260/82-19 & 50-296/82-19. Corrective
actions torus area high radiation rope barrier reinstalled &
radiological tape placed on floor.
KAHER, D. S. Tennessee Valley Authority. 82/07/30. O'REILLY, J. P.
Region 2, Office of Director. 3pp. 14348:105 24X
Fiche 50-259, 82/08/03, 8208160484

--8208160498 Forwards IE Insp Repts 50-259/82-19, 50-260/82-19 &
50-296/82-19 on 820526-0625 & notice of violation.

LONG, F. J. Division of Project & Resident Programs. 82/07/01.
PARRIS, H. Q. Tennessee Valley Authority. 2pp. 14348:108. 24X
Fiche 50-259, 82/08/03, 8208160484

--8208160507 Notice of violation from Insp on 820526-0625.

* Division of Project & Resident Programs. 82/07/01. 1p.
14348:110 24X Fiche 50-259, 82/08/03, 8208160484.

--8208160521 IE Insp Repts 50-259/82-19, 50-260/82-19 & 50-296/82-19 on

820526-0625. Noncompliance noted: Failure to properly
barricade two high radiation areas in torus area.
CHASE, J. W., PAULK, O. L., CANTRELL, F. S. Division of Project &
Resident Programs. 82/06/30. 6pp. 14348:111 24X
Fiche 50-259, 82/08/03, 8208160484.

8208160493 Ack receipt of 820720 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-259/82-15,
50-260/82-15 & 50-296/82-15.

LEWIS, R. C. Division of Project & Resident Programs. 82/08/04.
PARRIS, H. Q. Tennessee Valley Authority. 1p. 14348:117. 24X
Fiche: 50-259, 82/08/04, 8208160493.

--8208160502 Responds to NRC 820603 ltr re violations noted in IE Insp

Repts 50-259/82-15, 50-260/82-15 & 50-296/82-15. Corrective
actions: daily monitoring & drainage program will be
continued. Violations re Items A & B denied.
MILLS, L. M. Tennessee Valley Authority. 82/07/20. O'REILLY, J. P.
Region 2, Office of Director. 7pp. 14348:118. 24X
Fiche 50-259, 82/08/04, 8208160493.

62080100157 PNO-11-82-091 on 620802, airborne I-131 detected by radiation monitor in occupied space above refueling floor. Caused by leaking flange in spray line connected to reactor vessel head. Clothing of three workers contaminated. BARR, K. Q88BN, A.F. Region 2. Office of Director 02/08/03. 2pp
14298 041. 24X Fiche 30-260, 82/08/03, 62080100157

0208120184 Forwards LER 02-023/011-0
GREEN, H J. Tennessee Valley Authority. 02/08/05 O'REILLY, J H
Region 2, Office of Director 1p. 14325 360 24X
Fiche: 50-260. 02/08/05. 0208120184

--B208120190 LER 02-023/01F-0 on 020723, equalizer valve on differential pressure switch 2-Pdis-73-ID three-valve block manifold would not close, rendering switch inoperable. Caused by improperly seated valve manifold equalizer valve.
 * Tennessee Valley Authority 02/08/03 Region 2, Office of Director 2pp 14323 361 24X Fiche 90-260, 02/08/03, 0208120190

8208270282 Forwards LER 82-021/03L-0
GREEN, H. J. Tennessee Valley Authority. 02/08/12. O'REILLY, J. P.
Region 2, Office of Director In. 14564 196 24X
Fiche: 50-260, 82/08/12. 8208270282.

--B208270291 LER B2-021/03L-0 on B20720, hydrogen analyzer B became inoperable. Caused by Valcor Engineering Corp solenoid operator P/N V52630-529-1 failure. Solenoid replaced but failed again. Valve will be repaired during re-fueling outage CARTER, B. D. Tennessee Valley Authority. 02/08/12. Region 2, Office of Director 2pp 14564 157 24X Fiche 50-260. B2/00/12. B208270292

8208200118 Forwards LER 82-022/03L-0
GREEN, H. J. Tennessee Valley Authority. 82/08/13. O'REILLY, J. P.
Region 2, Office of Director Ip 14393 335. 24x
Fiche: 50-260, 82/08/13, 8208200118

--8208200129 LER 82-022/03L-O on 020721, calculated R Factor less than R
Factor used to set average power range monitor scram & rod
block. Caused by high core exposure & reduced core
reactivity Tech Spec changes issued
NAVE, E.D Tennessee Valley Authority 02/08/13 Region 2,
Office of Director. 2pp 14393 336 24X Fiche 80-260.02/08/13.
8208200118

820827007B Forwards LER 82-025/03L-0.
GREEN, H. J Tennessee Valley Authority 02/08/17 O'REILLY, J P.
Region 2, Office of Director. Ip. 14563 100 24X
Fiche. 50-260. 82/08/17. 820827007B

--B208270082 LER B2-025/03L-0 on B20719, during startup, relay coil failed, resulting in partial primary containment isolation. Caused by burned out coil relay, causing relay to fail in safe direction for primary containment isolation

MURPHY, D. E Tennessee Valley Authority B2/08/17 Region 2,
Office of Director. 2pp. 14563.134. 24X Fiche: 90-260. B2/08/17,
B208270078

B208310097 PNO-11-82-097: on B20819, truck transporting low specific radioactive matl from facility to Richland, WA found to have liquid dripping from truck bed. On B208218, drum found to have small holes near base.

COLLINS, F. R., BARR, K. P. Region 2, Office of Director 82/08/24
 to: 14695.084, 24X Fiche 50-259, 82/08/24, B208310097.

DOCKET 50-261 H B. ROBINSON PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8208100228 Forwards IE Safeguards Insp Rept 80-261/82-16 on 820510-14
Details & notice of violation withheld (ref 10CFR73.21).
LEWIS, R. C. Division of Project & Resident Programs. 82/06/09
JONES, J. A. Caroline Power & Light Co 2pp. 14294.337. 24X
FONE: 80-261. 82/06/09. 8208100228

--8208100233 IE Safeguards Insp Rept 50-261/82-16 on 820510-14.
Noncompliance noted: failure to supply NRC w/ rept describing
change to security plan & to perform audit at required
frequency. Details withheld (ref 10CFR73.21).
PERNY, C.D., MCQUIRE, D.R. Division of Engineering & Technical
Programs. 82/06/02. Ip. 14294:339. 24X Fiche: 50-261.82/06/09.
8208100238

8208050324 Forwarded updated LER 81-054/03X-2.
GREEN, H. J. Tennessee Valley Authority. 82/07/30. O'REILLY, J. P.
Region 2, Office of Director. 1p. 14237-290. 24X
Fiche: 80-260. 82/07/30. 8208050324.

DOCKETED ITEMS

8208040326 Releases public version of revision to Vol 13 of emergency response plan.
FELTON, J.M. Division of Rules and Records. 82/07/23. Document Management Branch. 1p. 14231:183. 24X Fiche: 50-261.82/07/23. 8208040326

--8208040330 Forwards public version of Revision 11 to Vol 13 of emergency response plan, per NRC 820316 ltr re emergency preparedness appraisal.
HOWE, P.W. Carolina Power & Light Co. 82/07/19. O'REILLY, J.P. Region 2, Office of Director. 2pp. 14231:186. 24X Fiche: 50-261.82/07/23. 8208040326

--8208040334 Public version of Revision 11 to Vol 13 of emergency response plan.
* Carolina Power & Light Co. 82/07/02. 78pp. 14231:188. 24X Fiche: 50-261.82/07/23. 8208040326

8208060154 Forwards addl info re reactor coolant pump lubricating oil collection sys exemption request. Existing configuration provides adequate protection. Installation of oil collection sys would pose unnecessary burden.
ZIMMERMAN, B.R. Carolina Power & Light Co. 82/07/30. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 17pp. 14240:019. 24X Fiche: 50-261.82/07/30. 8208060154

8208160106 Forwards IE Safeguards Insp Rept 50-261/82-26 on 820726-30. No noncompliance noted.
VERRELLI, D. Region 2, Office of Director. 82/08/11. JONES, J.A. Carolina Power & Light Co. 2pp. 14345:156. 24X Fiche: 50-261.82/08/11. 8208160106

--8208160110 IE Safeguards Insp Rept 50-261/82-26 on 820726-30. No noncompliance noted. Major areas inspected: security plan & implementing procedures, security organization-mgt, personnel & response. Details withheld (ref 10CFR73.21).
TOBIN, W., STANBERRY, W.W., MCQUIRE, D.R. Division of Engineering & Technical Programs. 82/08/10. 2pp. 14349:158. 24X Fiche: 50-261.82/08/11. 8208160106

8208270563 Releases public version of revised emergency plan procedures.
FELTON, J.M. Division of Rules and Records. 82/08/11. Document Management Branch. 1p. 14682:156. 24X Fiche: 50-261.82/08/11. 8208270563

--8208270571 Forwards public version of revised emergency plan procedures, including Procedures PEP-2.1 re initial emergency actions, PEP-2.2 re emergency control - unusual event & PEP-2.3 re emergency control - alert.
ZIMMERMAN, B.R. Carolina Power & Light Co. 82/07/30. O'REILLY, J.P. Region 2, Office of Director. 3pp. 14682:159. 24X Fiche: 50-261.82/08/11. 8208270563

--8208270578 Public version of revised emergency plan procedures, including Procedures PEP-2.1 re initial emergency actions, PEP-2.2 re emergency control - unusual event & PEP-2.3 re emergency control - alert.
* Carolina Power & Light Co. 82/07/02. 350pp. 14682:164. 24X Fiche: 50-261.82/08/11. 8208270563

8208260470 Requests full-size engineering drawings of plant layout & sys. needed to support programs aimed at reviewing effectiveness of NRC safeguards regulations & at validating vital area designations.
VARQA, B.A. Operating Reactors Branch 1. 82/08/12. JONES, J.A. Carolina Power & Light Co. App. 14599:060. 24X Fiche: 50-261.82/08/12. 8208260470

8208300166 Forwards IE Safeguards Insp Rept 50-261/82-28 on 820816-17. No noncompliance noted.
VERRELLI, D. Division of Project & Resident Programs. 82/08/25. JONES, J.A. Carolina Power & Light Co. 2pp. 14599:190. 24X Fiche: 50-261.82/08/25. 8208300166

--8208300167 IE Safeguards Insp Rept 50-261/82-28 on 820816-17. No noncompliance noted. Major areas inspected: site security operations during investigation of alleged drug usage by security personnel. Details withheld (ref 10CFR73.21).
HALL, B.L., MCQUIRE, D.R. Division of Project & Resident Programs. 82/08/24. 1p. 14599:192. 24X Fiche: 50-261.82/08/25. 8208300166

2. Operating license stage documents & correspondence

8207140517 Informs of forthcoming refunds of fees paid re applications resulting in Amends 67 & 68.
MILLER, W.O. License Fee Management Branch. 82/07/01. JONES, J.A. Carolina Power & Light Co. 1p. 13848:361. 24X Fiche: 50-261.82/07/01. 8207140517

8207080064 Generic ltr to all licensees of operating plants, applicant for OL & holders of CP re Commission approved charter for CROR. Svc list encl.
DIRCKS, W.J. Office of the Executive Director for Operations. 82/07/02. Consolidated Edison Co. of New York. 93pp. 14194:001. 24X Fiche: 50-000.82/07/02. 8207080064

8208020438 Requests util provide rept documenting relief & safety val failures for Apr 1980 to present & commitment to rept all failures promptly & all challenges periodically. Info needed to complete review of TMI Item 11.W.3.3
VARQA, B.A. Operating Reactors Branch 1. 82/07/07. JONES, J.A. Carolina Power & Light Co. 2pp. 14181:039. 24X Fiche: 50-261.82/07/07. 8208020438

8208040058 Forwards request for addl info necessary to complete review of responses to Generic Ltr 81-14 re seismic qualification of auxiliary feedwater sys. Response due by 820806.
VARQA, B.A. Operating Reactors Branch 1. 82/07/21. JONES, J.A. Carolina Power & Light Co. 3pp. 14228:358. 24X Fiche: 50-261.82/07/21. 8208040058

8208110228 Forwards Amend 71 to License DPR-23, safety evaluation & notice of issuance & availability. Amend authorizes Cycle 9 operation at reduced level & revises App A Tech Specs & License Conditions 3 I.a.b.c & d re steam generator insp.
VARQA, B.A. Operating Reactors Branch 1. 82/07/23. JONES, J.A. Carolina Power & Light Co. 2pp. 14330:340. 24X Fiche: 50-261.82/07/23. 8208110228

--8208110231 Amend 71 to License DPR-23, authorizing Cycle 9 operation reduced power level & revising App A Tech Specs & License Conditions 3 I.a.b.c & d to include steam generator insp & tube leakage criteria.
VARQA, B.A. Operating Reactors Branch 1. 82/07/23. 28pp. 14330:342. 24X Fiche: 50-261.82/07/23. 8208110228

--8208110233 Safety evaluation supporting Amend 71 to License DPR-23.
* Office of Nuclear Reactor Regulation, Director. 82/07/23. 20pp. 14331:008. 24X Fiche: 50-261.82/07/23. 8208110228

--8208110237 Notice of issuance & availability of Amend 71 to License DPR-23.
VARQA, B.A. Operating Reactors Branch 1. 82/07/23. 2pp. 14331:028. 24X Fiche: 50-261.82/07/23. 8208110228

8208240137 Forwards safety evaluation of response to TMI Action Item 11.F.1, "Containment High Range Radiation Monitor." Response acceptable.
VARQA, B.A. Operating Reactors Branch 1. 82/07/26. JONES, J.A. Carolina Power & Light Co. 3pp. 14548:168. 24X Fiche: 50-261.82/07/26. 8208240137

8208110151 Requests extension of implementation date for Amend 70 to License DPR-23 until 820913. Request due to delays in plant start up from current refueling outage.
HOWE, P.W. Carolina Power & Light Co. 82/08/06. VARQA, B.A. Operating Reactors Branch 1. 1p. 14314:286. 24X Fiche: 50-261.82/08/06. 8208110151

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP I applicants re submittal of documents to NRC. Summarizes 10CFR Chapter 1 requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D.G. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14356:332. 24X Fiche: 50-000.82/08/09. 8208090194

8208240166 Responds to 820721 ltr requesting clarification of auxiliary feedwater sys boundaries assumed in 811231 response to Generic Ltr 81-14. Analyses conducted for IE Bulletin 79-14 adequate for use in response to generic ltr.
ZIMMERMAN, B.R. Carolina Power & Light Co. 82/08/20. VARQA, B.A. Operating Reactors Branch 1. 2pp. 14519:001. 24X Fiche: 50-261.82/08/20. 8208240166

0. Inspection reports, IE Bulletins & correspondence

8208100228 Forwards IE Safeguards Insp Rept 50-261/82-16 on 820510-14. Details & notice of violation withheld (ref 10CFR73.21).
LEWIS, R.C. Division of Project & Resident Programs. 82/06/09. JONES, J.A. Carolina Power & Light Co. 2pp. 14294:337. 24X Fiche: 50-261.82/06/09. 8208100228

--8208100235 IE Safeguards Insp Rept 50-261/82-16 on 820510-14. Noncompliance noted: failure to supply NRC w/rept describing change to security plan & to perform audit at required frequency. Details withheld (ref 10CFR73.21).
PERNNY, C.D., MCQUIRE, D.R. Division of Engineering & Technical Programs. 82/06/02. 1p. 14294:339. 24X Fiche: 50-261.82/06/09. 8208100228

8204210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV) Leakage" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/16
Consolidated Edison Co. of New York 87pp 14356 274 24X
Fiche 50-000. 82/07/16. 8204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19
Michigan Univ of 112pp 14358 001 24X Fiche 50-000. 82/07/19.
8204210395

8204210396 IE Info Notice 82-25. "Failures of Miller Actuators Upon Gradual Loss of Air Pressure" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20
Consolidated Edison Co. of New York 112pp 14381 001 24X
Fiche 50-000. 82/07/20. 8204210396

8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks" Svc list encl
CCBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/07/20
Consolidated Edison Co. of New York 71pp 14357 276 24X
Fiche 50-000. 82/07/20. 8204210397

8204210398 IE Info Notice 82-26. "RCIC & PC1 Turbine Exhaust Check Valve Failures" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/22
Consolidated Edison Co. of New York 112pp 14194 321 24X
Fiche 50-000. 82/07/22. 8204210398

8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co. of New York 122pp 14380 115 24X
Fiche 50-000. 82/07/23. 8204210401

8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHRs" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co. of New York 127pp 14194 120 24X
Fiche 50-000. 82/07/23. 8204210402

8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PHR Power Plants" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26
Consolidated Edison Co. of New York 121pp 14357 013 24X
Fiche 50-000. 82/07/26. 8204210403

8208160180 Forwards IE Insp Rept 50-261/82-24 on 820628-0702 No noncompliance noted
VERRELLI, D. M. Division of Project & Resident Programs 82/07/26
JONES, J. A. Carolina Power & Light Co. 2pp 14345 103 24X
Fiche 50-261. 82/07/26. 8208160180

--8208160184 IE Insp Rept 50-261/82-24 on 820628-0702 No noncompliance noted. Major areas inspected: previous enforcement matters, organization & administration, housekeeping & cleanliness, test & measurement equipment program & calibr program
BELISLE, G. A., FREDRICKSON, P., UPRIGHT, C. M. Division of Engineering & Technical Programs 82/07/20 11pp 14345 105 24X
Fiche 50-261. 82/07/26. 8208160180

8208160522 Forwards IE Insp Rept 50-261/82-25 on 820706-09 No noncompliance noted
VERRELLI, D. M. Division of Project & Resident Programs 82/07/26
JONES, J. A. Carolina Power & Light Co. 2pp 14348 082 24X
Fiche 50-261. 82/07/26. 8208160522

--8208160526 IE Insp Rept 50-261/82-25 on 820706-09. No noncompliance noted. Major areas inspected: radiation protection & transportation of radioactive materials
ALBRIGHT, R. H., BARR, K. P. Division of Engineering & Technical Programs 82/07/20 4pp 14348 084 24X
Fiche 50-261. 82/07/26. 8208160522

8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28
Consolidated Edison Co. of New York 122pp 14357 146 24X
Fiche 50-000. 82/07/28. 8204210405

8208160344 Ack receipt of 820702 ltr informing NRC of steps taken to correct violations noted in IE Investigation Rept 50-261/82-03 on 820111-0226
VERRELLI, D. M. Division of Project & Resident Programs 82/07/29
JONES, J. A. Carolina Power & Light Co. 1p 14348 001 24X
Fiche 50-261. 82/07/29. 8208160344

--8208160358 Responds to NRC 820624 ltr re violations noted in IE Investigation Rept 50-261/82-03 on 820111-0226. Corrective actions verification made to ensure that curves in reactor vessel would not result in nonconservative operation
STARKEY, R. B. Carolina Power & Light Co. 82/07/24 O'REILLY, J. P. Region 2, Office of Director 3pp 14348 002 24X
Fiche 50-261. 82/07/29. 8208160344

--8208160263 Forwards IE Investigation Rept 50-261/82-03 on 820111-0226 & notice of violation
O'REILLY, J. P. Region 2, Office of Director 82/06/24 JONES, J. A. Carolina Power & Light Co. 2pp 14348 005 24X
Fiche 50-261. 82/07/29. 8208160344

--8208160367 Notice of violation from investigation on 820111-0226
* Region 2, Office of Director 82/06/24 1p 14348 007 24X
Fiche 50-261. 82/07/29. 8208160344

--8208160377 IE Investigation Rept 50-261/82-03 on 820111-0226. Noncompliance noted: failure to process info received from contractor & failure to request amendment to Tech Specs to make heatup & cooldown curves more conservative.
VORBE, J. Y., ALDERSON, C. E. Region 2, Office of Director 82/04/22 4pp 14348 008 24X
Fiche 50-261. 82/07/29. 8208160344

8208160278 Provides info re Action Item 3 in response to IE Bulletin 82-02. "Degradation of Threaded Fasteners in RCP of PHR Plants" Control rod drive flanges & pressurizer heater connections seal welded
FURR, D. J. Carolina Power & Light Co. 82/07/30 O'REILLY, J. P. Region 2, Office of Director 2pp 14346 299 24X
Fiche 50-261. 82/07/30. 8208160278

8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/05
Consolidated Edison Co. of New York 117pp 14380 201 24X
Fiche 50-000. 82/08/05. 8204210407

8208160405 Discusses util actions based on confirmation of action ltr re cracking of reactor coolant pump bolts. Util insps, evaluations & final results of main coolant pump bolt problem comply w/NRC request. Restart may proceed
O'REILLY, J. P. Region 2, Office of Director 82/08/09 JONES, J. A. Carolina Power & Light Co. 1p 14348 319 24X
Fiche 50-261. 82/08/09. 8208160405

8208160106 Forwards IE Safeguards Insp Rept 50-261/82-26 on 820726-30. No noncompliance noted
VERRELLI, D. Region 2, Office of Director 82/08/11 JONES, J. A. Carolina Power & Light Co. 2pp 14345 156 24X
Fiche 50-261. 82/08/11. 8208160106

--8208160110 IE Safeguards Insp Rept 50-261/82-26 on 820726-30. No noncompliance noted. Major areas inspected: security plan & implementing procedures, security organization-mgt, personnel & response details withheld (ref 10CFR73.21)
TODD, W., STANBERRY, W. W., MCQUIRE, D. R. Division of Engineering & Technical Programs 82/08/10 2pp 14345 158 24X
Fiche 50-261. 82/08/11. 8208160106

8208300166 Forwards IE Safeguards Insp Rept 50-261/82-28 on 820816-17. No noncompliance noted
VERRELLI, D. Division of Project & Resident Programs 82/08/25 JONES, J. A. Carolina Power & Light Co. 2pp 14399 190 24X
Fiche 50-261. 82/08/25. 8208300166

--8208300167 IE Safeguards Insp Rept 50-261/82-28 on 820816-17. No noncompliance noted. Major areas inspected: site security operations during investigation of alleged drug usage by security personnel. Details withheld (ref 10CFR73.21)
HALL, B. L., MCQUIRE, D. R. Division of Project & Resident Programs 82/08/24 1p 14399 192 24X
Fiche 50-261. 82/08/25. 8208300166

R. Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records 82/07/13 UDELL, R. A. Critical Mass Energy Project 8pp 14679 208 24X
Fiche 50-000. 82/07/13. 8208270010

--8208270042 Forwards "Statistical Summary Rept for CY81," per 10CFR20.407
STARKEY, R. B. Carolina Power & Light Co. 82/03/01. BARNETT, H. B. Office of Management and Program Analysis 1p 14680 014 24X
Fiche 50-000. 82/07/13. 8208270010

--8208270044 "Statistical Summary Rept for CY81,"
* Carolina Power & Light Co. 82/03/01 1p 14680 015 24X
Fiche 50-000. 82/07/13. 8208270010

--B208060130 Public version of Revision 2 to emergency response plan.
FEY,F.L. Northern States Power Co. 82/07/13. 150pp. 14244:067.
24X Fiche: 50-263,82/08/03,8208060127

0 Forward LER 82-009/03L-0. Caroling Power & Light Co. 82/08/13. O'REILLY, J. P.
R B. Office of Director. 14393.309. 24X
2. Office of Director. 14393.309. 24X
0-261. 82/08/13. 8208200110.

B208190081 Forwards "Final Rept on Monticello Nuclear Power Plant Full-Scale Joint Emergency Exercise. B20302." State of NY & Wright & Sherburne Counties demonstrated adequate level of preparedness to protect public.
KRIEM, R. W. Federal Emergency Management Agency 82/08/05
GRIMES, B. Division of Emergency Preparedness Bpp 14386:182 24X
Fiche: 50-263, 82/08/05, B208190081

--B208190084 "Final Rept on Monticello Nuclear Power Plant Full-Scale Joint Emergency Exercise. B20302"
* Federal Emergency Management Agency 82/04/12 53pp.
14386:190 24X Fiche: 50-263, 82/08/05, B208190081.

B208260089 Releases public version of revised corporate emergency plan.
FELTON, J. M. Division of Rules and Records. 82/08/13 Document
Management Branch. 1p. 14576:196. 24X Fiche: 50-000, 82/08/13.
B208260089.

--B208260315 Forwards public version of Revision 5 to corporate nuclear emergency plan. Updated info on App C items identified in NRC B20304 ltr encl.
LARSON, C. E. Northern States Power Co 82/08/02 Region 3.
Office of Director. App. 14576:199. 24X Fiche: 50-000, 82/08/13.
B208260089.

--B208260319 Public version of Revision 5 to corporate nuclear emergency plan.
HUBSON, O., WARD, E., LARSON, C. E. Northern States Power Co.
82/08/02 140pp. 14576:203. 24X Fiche: 50-000, 82/08/13.
B208260089.

B208260353 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 82/08/13. Document
Management Branch. 1p. 14575:069. 24X Fiche: 50-000, 82/08/13.
B208260353.

--B208260358 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.2 re notifications & EPIP 1.1.5 re startup & operation of emergency operations facility.
WARD, E. C. Northern States Power Co. 82/08/11. Region 3, Office of Director. 1p. 14575:072. 24X Fiche: 50-000, 82/08/13.
B208260353.

--B208260360 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1.2 re notifications & EPIP 1.1.5 re startup & operation of emergency operations facility.
* Northern States Power Co. 82/08/11. 72pp. 14575:073. 24X
Fiche: 50-000, 82/08/13, B208260353

J. Insurance & indemnity information

B208100092 Forwards Endorsements 62 & 63 to NELA Policy NF-174 & Endorsements 51 & 52 to MAELU Policy NF-31.
JOHNSON, R. G. Northern States Power Co. 82/08/05. DINITZ, I.
Antitrust & Economic Analysis Branch (Utility Finance). 5pp
14297:348. 24X Fiche: 50-263, 82/08/05, B208100092

P. Operating license stage documents & correspondence

B207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR. Svc list encl.
DIRCKS, W. J. Office of the Executive Director for Operations.
82/07/02. Consolidated Edison Co. of New York. 93pp. 14194:001.
24X Fiche: 50-000, 82/07/02, B207080064.

B208040029 Advises that shift technical advisor training program is acceptable per NUREG-0660 & NUREG-0737, Item I-A.1.1. Training of candidates w/o bachelor degrees acceptable in interim.
VASSALLO, D. B. Operating Reactors Branch 2 82/07/14. MUSOLF, D. M.
Northern States Power Co. 3pp. 14232:355. 24X
Fiche: 50-263, 82/07/14, B208040029.

B208040084 Grants extension from B20701 to B30201 to implement requirements of NUREG-0634 Table 1-B, "Min Staffing Requirements for Nuclear Power Plant Emergencies." Util making good faith effort to comply as soon as possible.
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/16. MUSOLF, D. M.
Northern States Power Co. 3pp. 14228:319. 24X
Fiche: 50-263, 82/07/16, B208040084.

B208020320 Revision 1 to 790501 application for amend to License DPR-22, changing radioactive effluent Tech Specs & revising offsite dose calculation manual for cement-sodium silicate sys. Implementation of changes on B30101 requested.
MUSOLF, D. Northern States Power Co. 82/07/23. Office of Nuclear Reactor Regulation, Director. 1p. 14150:185. 24X
Fiche: 50-263, 82/07/23, B208020320.

--B208020323 Application for amend to License DPR-22, changing radioactive effluent Tech Specs & revising offsite dose calculation manual.
MUSOLF, D. M. Northern States Power Co 82/07/23. 3pp. 14150:186.
24X Fiche: 50-263, 82/07/23, B208020320

--B208020326 Proposed revised App A radioactive effluent Tech Specs.
* Northern States Power Co. 82/07/23 77pp. 14150:189. 24X
Fiche: 50-263, 82/07/23, B208020320

--B208020330 Revision 2 to offsite dose calculation manual
* Northern States Power Co. 82/07/23 200pp. 14150:263. 24X
Fiche: 50-263, 82/07/23, B208020320.

B208180248 Forwards safety evaluation of util B11231 & B20524 submittals on TMI Action Plan Items II F.1.4.11, F.1.5 & II P.1.8, re containment pressure, water level & hydrogen monitors, respectively NUREG-0737 requirements met.
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/28. MUSOLF, D. M.
Northern States Power Co. 10pp. 14289:327. 24X
Fiche: 50-263, 82/07/28, B208180248

B208190006 Forwards revised version of model Tech Specs for electric power monitoring of reactor protection sys. encl in B1124 ltr.
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/28. MUSOLF, D. M.
Northern States Power Co. 2pp. 14506:314. 24X
Fiche: 50-263, 82/07/28, B208190006.

--B208190008 Revised version of model Tech Specs for electric power monitoring of reactor protection sys.
* Office of Nuclear Reactor Regulation, Director. 82/07/28 1p.
14506:316 24X Fiche: 50-263, 82/07/28, B208190006

B208100067 Provides supplemental info for B20625 amend request to License DPR-22, in response to NRC questions re codes & inputs used in safety analysis for Cycle 10.
MUSOLF, D. Northern States Power Co. 82/08/03. Office of Nuclear Reactor Regulation, Director. 1p. 14296:182. 24X
Fiche: 50-263, 82/08/03, B208100067

B208230111 Requests verification of satisfaction of encl acceptance criteria re NUREG-0737, Item I-A.3.22, "Automatic Switchover of Reactor Core Isolation Cooling Sys Suction." Response due in 30 days.
VASSALLO, D. B. Operating Reactors Branch 2 82/08/05. MUSOLF, D. M.
Northern States Power Co. App. 14517:353. 24X
Fiche: 50-263, 82/08/05, B208230111

B208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D. O. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14356:332. 24X Fiche: 50-000, 82/08/09, B208090194.

B208170247 Provides info re intentions concerning open items & commits to resolutions developed at B20615-16 meeting w/NRC & E&O. Resolutions will be incorporated into Revision 4 to ASME Code inservice testing program.
MUSOLF, D. M. Northern States Power Co. 82/08/12. Office of Nuclear Reactor Regulation, Director. 12pp. 14368:354. 24X
Fiche: 50-263, 82/08/12, B208170247

B208260118 Forwards fee for B00915 license amend request, per NRC B20811 ltr. Util will resubmit request for Tech Spec changes following issuance of proposed changes to 10CFR50, App G.
MUSOLF, D. Northern States Power Co. 82/08/17. DIBBS, R. M. License Fee Management Branch. 2pp. 14556:296. 24X Fiche: 50-263, 82/08/17, B208260118.

B208300232 Provides supplemental info re B20625 license amend request to lower Cycle 10 max critical power ratio from Cycle 9 ratio. OE B20306 & 28 ltrs re extension of ECCS performance limits applicable.
MUSOLF, D. Northern States Power Co. 82/08/24. Office of Nuclear Reactor Regulation, Director. 1p. 14679:141. 24X
Fiche: 50-263, 82/08/24, B208300232.

G. Inspection reports, IE Bulletins & correspondence

B204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16. Consolidated Edison Co. of New York. 87pp. 14356:274. 24X
Fiche: 50-000, 82/07/16, B204210393.

210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices For External Radiation." Svc list encl.
RDAN, E. L. Division of Engineering & Quality Assurance 82/07/19
Michigan, Univ. of 112pp. 1435B 001 24X Fiche 50-000, 82/07/19, 0204210395.

210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Actual Loss of Air Pressure." Svc list encl.
RDAN, E. L. Division of Engineering & Quality Assurance 82/07/20
Consolidated Edison Co. of New York 112pp. 1435B 001 24X
Fiche 50-000, 82/07/20, 8204210396

210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Specta." Svc list encl.
BB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/07/20
Consolidated Edison Co. of New York 71pp. 14357:276
X Fiche 50-000, 82/07/20, 8204210397

210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
RDAN, E. L. Division of Engineering & Quality Assurance 82/07/22
Consolidated Edison Co. of New York 112pp. 14194:321. 24X
Fiche 50-000, 82/07/22, 8204210398

210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in vicinity of Drained & Open RCB." Svc list encl.
RDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co. of New York 122pp. 14380 115. 24X
Fiche 50-000, 82/07/23, 8204210401.

210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl.
RDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co. of New York 127pp. 14194:120. 24X
Fiche 50-000, 82/07/23, 8204210402

210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping Certain Westinghouse PWR Power Plants." Svc list encl.
RDAN, E. L. Division of Engineering & Quality Assurance 82/07/26
Consolidated Edison Co. of New York 121pp. 14357:013. 24X
Fiche 50-000, 82/07/26, 8204210403.

210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Pool Storage Pool." Svc list encl.
RDAN, E. L. Division of Engineering & Quality Assurance 82/07/28
Consolidated Edison Co. of New York 122pp. 14357:146. 24X
Fiche 50-000, 82/07/28, 8204210405.

210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Fuel Water-Jet Impingement." Svc list encl.
RDAN, E. L. Division of Engineering & Quality Assurance 82/08/05
Consolidated Edison Co. of New York 117pp. 14388:201. 24X
Fiche 50-000, 82/08/05, 8204210407

220164 Forwards IE Insp Rept 50-263/82-08 on 820530-0703 No noncompliance noted.
REETER, J. F. Division of Project & Resident Programs 82/08/05
BERTIS, D. E. Northern States Power Co. 2pp. 14514:314. 24X
Fiche 50-263, 82/08/05, 8208230164.

82030176 IE Insp Rept 50-263/82-08 on 820530-0703. No noncompliance noted. Major areas inspected: licensee action on previous insp items, operational safety verification, LER followup, IE info notice followup & onsite review committee.
BROWN, C. H., MADISON, A. L., REVEL, L. A. Division of Project & Resident Programs 82/08/05. 6pp. 14514:316. 24X
Fiche 50-263, 82/08/05, 8208230164.

Periodic operating reports & related correspondence

270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & releasing said info. Forwards documents listed in App A.
TOM, J. M. Division of Rules and Records 82/07/13 UDELL, R. A.
Nuclear Mass Energy Project. 8pp. 14679:208. 24X
Fiche 50-000, 82/07/13, 8208270010.

82070098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given 82/07/13. 48pp.
14679:216. 24X Fiche 50-000, 82/07/13, 8208270010.

82070644 Forwards "Number of Personnel & Man Rem by Work & Job Function for CY81." per NUREG-0737, Item II, K 3.3.
HAYER, L. O. Northern States Power Co. 82/02/26. Region 3.
Office of Director. 1p. 14679:348. 24X Fiche 50-000, 82/07/13, 8208270010.

--8208270648 "Number of Personnel & Man Rem by Work & Job Function, for CY81."
* Northern States Power Co. 82/02/26 1p. 14679:349. 24X
Fiche 50-000, 82/07/13, 8208270010

8208130082 Forwards monthly operating rept for Jul 1982
MUSOLF, D. Northern States Power Co. 82/08/10 Director's Office,
Office of Inspection and Enforcement 1p. 14336:008. 24X
Fiche 50-263, 82/08/10, 8208130082.

--8208130087 Monthly operating rept for Jul 1982
MYRABO, A. L. Northern States Power Co. 82/08/02. 4pp. 14336:009
24X Fiche 50-263, 82/08/10, 8208130082

DOCKET 50-264 DOW CHEMICAL CO.

0. Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices For External Radiation." Svc list encl.
RDAN, E. L. Division of Engineering & Quality Assurance 82/07/19
Michigan, Univ. of 112pp. 1435B 001 24X Fiche 50-000, 82/07/19, 0204210395

DOCKET 50-265 QUAD-CITIES STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8208040469 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 82/07/23 Document
Management Branch. 1p. 14220:289. 24X Fiche 50-254, 82/07/23, 8208040469.

---8208040475 Forwards public version of Revision 2 to Emergency Plan Implementing Procedure QEP 330-3, "Offshift Augmentation Drill" & Revision 10 to QEP 530-0, "Exercises & Drills." Receipt form encl.
KOVACK, T. J., GERNER, L. Commonwealth Edison Co. 82/06/21.
DENTON, H. R. NRC - No Detailed Affiliation Given. 1p. 14220:290. 24X Fiche 50-254, 82/07/23, 8208040469.

--8208040481 Public version of Revision 2 to Emergency Plan Implementing Procedure QEP 330-3, "Offshift Augmentation Drill" & Revision 10 to QEP 530-0, "Exercises & Drills."
* Commonwealth Edison Co. 82/06/21 3pp. 14220:291. 24X
Fiche 50-254, 82/07/23, 8208040469

8208200137 Forwards response to 820112 request re exercise objectives, scope of participation & scenario outline for Aug 1982 emergency plan exercise.
RAUSCH, T. J. Commonwealth Edison Co. 82/08/02 KEPLER, J. O. Region 3, Office of Director. 7pp. 14393:283. 24X Fiche 50-254, 82/08/02, 8208200137.

8208110230 Releases public version of revision to emergency plan implementing procedure.
FELTON, J. M. Division of Rules and Records 82/08/05. Document
Management Branch 1p. 14330:309. 24X Fiche 50-254, 82/08/05, 8208110230.

--8208110234 Forwards public version of Revision 12 to Emergency Plan Implementing Procedure QEP 330-0, "Assessment Actions." Receipt form encl.
KOVACK, T. J., TIET, Q. C. Commonwealth Edison Co. 82/07/17.
DENTON, H. R. NRC - No Detailed Affiliation Given. 1p. 14330:310. 24X Fiche 50-254, 82/08/05, 8208110230.

--8208110238 Public version of Revision 12 to Emergency Plan Implementing Procedure QEP 330-0, "Assessment Actions."
* Commonwealth Edison Co. 82/07/17. 2pp. 14330:311. 24X
Fiche 50-254, 82/08/05, 8208110230

8208300179 Forwards IE Safeguards Insp Rept 50-265/82-14 on 820720-23 No noncompliance noted.
MILLER, J. R. Division of Engineering & Technical Programs 82/08/05.
REED, C. Commonwealth Edison Co. 2pp. 14599:219. 24X
Fiche 50-265, 82/08/05, 8208300179.

--8208300180 IE Safeguards Insp Rept 50-265/82-14 on 820720-23. No noncompliance noted. Major areas inspected: facility organization & operations, inventory & internal controls. Details withheld (ref 10CFR2.790).
FINLEY, A. O., CREED, J. R. Region 3, Office of Director. 82/08/04. 1p. 14599:221. 24X Fiche 50-265, 82/08/05, 8208300179.

DOCKETED ITEMS

8208250559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures".
FELTON, J. M. Division of Rules and Records 82/08/12 Document Management Branch 1p. 14559 354 24X Fiche 50-000.82/08/12. 8208250559.

--8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures".
MOORE, R. D. Commonwealth Edison Co 82/07/19 DENTON, H. R. NRC - No Detailed Affiliation Given 1p. 14559 355 24X Fiche 50-000.82/08/12.8208250559

--8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures".
* Commonwealth Edison Co 82/06/30 7pp. 14559 356. 24X Fiche 50-000.82/08/12.8208250559.

8208230107 Forwards revised cable discrepancy lists re fire protection safe shutdown analyses. Lists indicate how each discrepancy noted in fire protection associated circuit analysis & mod reports will be resolved.
RAUSCH, T. J. Commonwealth Edison Co 82/08/13 EISENHUT, D. G. Division of Licensing 2pp 24X Fiche: 50-000.82/08/13.8208230107.

--8208230130 "Fire Protection Cable Discrepancy List, Quad Cities Unit 2."
* Commonwealth Edison Co 82/08/02 250pp. 14516 216 24X Fiche 50-000.82/08/13.8208230107

8208270523 Forwards IE Insp Repts 50-254/82-12 & 50-265/82-13 on 820722 & 23. No noncompliance noted.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 82/08/13 REED, C. Commonwealth Edison Co. 2pp 14566 030. 24X Fiche: 50-254.82/08/13.8208270523

--8208270527 IE Insp Repts 50-254/82-12 & 50-265/82-13 on 820722-23. No noncompliance noted. Major areas inspected prompt public notification/warning sys.
PATTERSON, J. P. Division of Emergency Preparedness & Operational Support. 82/08/13 5pp. 14566 032. 24X Fiche: 50-254.82/08/13.8208270523

8208230328 Ack receipt of 820806 ltr & 820812 telcon requesting that assembly & accountability portion of 820824 emergency exercise be conducted on 820819. Assembly & accountability should be conducted w/annual exercise.
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 82/08/18 KALLIVANAKIS, N. Commonwealth Edison Co. 2pp 14508 260 24X Fiche: 50-254.82/08/18.8208230328

--8208230335 Requests NRC approval to conduct site assembly portion of 820824 emergency exercise as separate drill on 820819. Separate drill would allow util to more effectively use manpower during exercise.
KALLIVANAKIS, N. Commonwealth Edison Co. 82/08/06 PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support 2pp 14508 262. 24X Fiche: 50-254.82/08/18.8208230328

0. Adjudicatory correspondence

8208240267 Response to ASLB 820728 order. Requests leave to withdraw application w/o prejudice. Need for transshipment in near-term reduced due to approval of installation of high density spent fuel racks. Certificate of Svc encl.
STEPOT, P. Commonwealth Edison Co 82/08/18. Atomic Safety and Licensing Board Panel 6pp. 14527 120. 24X Fiche: 50-000.82/08/18.8208240267.

8208240265 Response to ASLB 820728 order. NRC does not object to proceeding termination since licensee has moved to withdraw license application w/o prejudice. Due to decision in Dresden high density storage rack case. W/Certificate of Svc.
WRIGHT, N. A. Hearing Branch 2. 82/08/20 Atomic Safety and Licensing Board Panel. 3pp. 14527 126. 24X Fiche: 50-000.82/08/20.8208240265.

P. Operating license stage documents & correspondence

8208060050 Forwards Amends 7B & 72 to Licenses DPR-29 & DPR-30, respectively. safety evaluation & notice of issuance & availability. Amends change Tech Specs to extend operation to 820701 to allow completion of RHR svc water sys mods.
BEVAN, R. B. Operating Reactors Branch 2 82/05/27. DELGEOGE, L. Commonwealth Edison Co. 2pp. 14282 102. 24X Fiche: 50-254.82/05/27.8208060050.

--8208060060 Amends 7B & 72 to Licenses DPR-29 & DPR-30, respectively. changing Tech Specs to extend operation to 820701 to allow completion of mods to RHR svc water sys.
VASSALLO, D. B. Operating Reactors Branch 2 82/05/27 10pp. 14282 104 24X Fiche 50-254.82/05/27.8208060050

--8208060063 Safety evaluation supporting Amends 7B & 72 to Licenses DPR-29 & DPR-30, respectively.
* Office of Nuclear Reactor Regulation, Director. 82/05/27. 2pp. 14282 114 24X Fiche 50-254.82/05/27.8208060050

--8208060064 Notice of issuance & availability of Amends 7B & 72 to Licenses DPR-29 & DPR-30, respectively.
VASSALLO, D. B. Operating Reactors Branch 2 82/05/27. 2pp. 14282 116 24X Fiche 50-254.82/05/27.8208060050

8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CRGR Svc list encl.
DIRCKS, W. J. Office of the Executive Director for Operations. 82/07/02 Consolidated Edison Co of New York 93pp. 14194 001. 24X Fiche: 50-000.82/07/02.8207080064

8208090024 Requests formal notification within 30 days if NRC understanding that util will meet stated positions of NUREG-0737, Item III D 3.3. "Improved In-Plant Iodine Instrumentation Under Accident Conditions." is correct.
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/21. DELGEOGE, L. Commonwealth Edison Co 2pp 14283 358 24X Fiche: 50-254.82/07/21.8208090024.

8208050066 Advises that ESF reset controls comply w/NRC criteria, subj to IE confirmation.
NOVAK, T. M. Assistant Director for Operating Reactors. 82/07/28. JORDAN, E. L. Division of Engineering & Quality Assurance. 1p. 14242 069. 24X Fiche 50-254.82/07/28.8208050066.

--8208050080 Safety evaluation supporting plant compliance w/ESF reset controls per NRC criteria.
* NRC - No Detailed Affiliation Given. 82/07/28 2pp. 14242 071. 24X Fiche 50-254.82/07/28.8208050066

--8109210393 "Technical Evaluation of Licensee's Response to IE Bulletin 80-06 re Engineered Safety Feature Reset Controls for Quad Cities Units 1 & 2."
KOUNTANIS, B. obsolete code. FIN A-0250. E00-1183-4212. 81/09/30 8pp 14242 072. 24X Fiche: 50-254.82/07/28.8208050066.

8208180266 Forwards revised version of model Tech Specs for reactor protection sys/power monitoring sys design.
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/28. DELGEOGE, L. Commonwealth Edison Co 3pp 14389 310. 24X Fiche: 50-000.82/07/28.8208180266.

--8208180271 Revised model Tech Specs re electric power monitoring of reactor protection sys design.
* Operating Reactors Branch 2. 82/07/28. 1p. 14389 321 24X Fiche: 50-000.82/07/28.8208180266

8208110041 Forwards response to request to cross-ref info re environ qualification of safety-related equipment & TMI action plan equipment.
SWARTZ, E. D. Commonwealth Edison Co 82/08/02 EISENHUT, D. G. Division of Licensing. 500pp. 14315 001. 24X Fiche: 50-000.82/08/02.8208110041.

8208130046 Requests approval to delay implementation of commitments in response to Generic Ltr 82-03 re NUREG-0737, Item II. F. 1.6. "Containment Hydrogen Monitor." Completion postponed until 840101 to accommodate schedule requirements.
SWARTZ, E. D. Commonwealth Edison Co. 82/08/05. EISENHUT, D. G. Division of Licensing. 2pp. 14335 363. 24X Fiche: 50-000.82/08/05.8208130046.

8208240168 Requests addl info/verifying satisfaction of encl acceptance criteria re NUREG-0737, Item II. K. 3.2. "Automatic Switchover of Reactor Core Isolation Cooling Sys Suction." Response requested within 30 days.
VASSALLO, D. B. Operating Reactors Branch 2. 82/08/05. DELGEOGE, L. Commonwealth Edison Co. 4pp. 14548 181. 24X Fiche: 50-254.82/08/05.8208240168.

8208110188 Forwards revised pages to CE-1-A. "Comm Ed QA Program for Nuclear Generating Stations." Revision 21. Revised pages correct typographical & other minor errors.
SWARTZ, E. Commonwealth Edison Co. 82/08/06. HAAS, W. P. Quality Assurance Branch. 1p. 14314 079. 24X Fiche: 50-000.82/08/06.8208110188.

08240040 Forwards Amends B1 & 75 to Licenses DPR-29 & DPR-30, respectively & notice of issuance & availability. Amends characterize replacement of water quality requirements w/environment protection plan
VASSALLO, D.B. Operating Reactors Branch 2. 02/08/06. DELGEOERGE, L. Commonwealth Edison Co. 3pp. 14529.316. 24X Fiche: 50-254. 82/08/06. 08240040

08240046 Amends B1 & 75 to Licenses DPR-29 & DPR-30, respectively, replacing water quality requirements w/environment protection plan
VASSALLO, D.B. Operating Reactors Branch 2. 02/08/06. 18pp. 14529.319. 24X Fiche: 50-254. 82/08/06. 08240046

08240050 Notice of issuance & availability of Amends B1 & 75 to Licenses DPR-29 & DPR-30, respectively
VASSALLO, D.B. Operating Reactors Branch 2. 02/08/06. 2pp. 14529.337. 24X Fiche: 50-254. 82/08/06. 08240050

090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR after I requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D.O. Division of Licensing. 02/08/09. Consolidated Edison Co. of New York. 1p. 14356.332. 24X Fiche: 50-000. 82/08/09. 08090194

08170135 Responds to NRC 820721 request to provide notification if I intends to deviate from NUREG-0737, Item III D.3.3, Improved In-Plant Iodine Instrumentation Under Accident Conditions. Both facilities comply w/requirement
EISENHUT, D.O. Commonwealth Edison Co. 02/08/12. 2pp. 14365.211. 24X Fiche: 50-000. 82/08/12. 08170135

08250455 Advises of satisfactory response to NUREG-0737, Item K.3.24, "Adequacy of Space Cooling for HPCI & Reactor Isolation Cooling Bys" Safety evaluation encl.
VASSALLO, D.B. Operating Reactors Branch 2. 02/08/13. DELGEOERGE, L. Commonwealth Edison Co. 3pp. 14562.283. 24X Fiche: 50-254. 82/08/13. 08250455

08270250 Application for amend to License DPR-29, proposing Tech Spec changes to implement 10CFR50.59 reload licensing w/DDYN transient analyses & extended exposure MAPLHOR limits. Significant changes discussed. Class III amend fee encl.
JUSCH, T.J. Commonwealth Edison Co. 02/08/19. DENTON, H.R. Office Nuclear Reactor Regulation, Director. 5pp. 14564.001. 24X Fiche: 50-000. 82/08/19. 08280270250

08270273 Errata & Addenda Sheet 7, replacing Pages 4-11 & 4-14 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations."
General Electric Co. NEDD-24246A ERR 07. 02/07/31. 8pp. 14564.026. 24X Fiche: 50-000. 82/08/19. 08280270250

08270296 Informs that analysis to determine appropriate equipment qualification temp profiles will be submitted in Sept 1982, at Jul 1982, as previously indicated
JUSCH, T.J. Commonwealth Edison Co. 02/08/23. VASSALLO, D.B. Division of Licensing. 1p. 14564.177. 24X Fiche: 50-000. 82/08/23. 08270296

08310402 Submits supplemental response to Generic Ltr 82-05 re REG-0737, Item II.F.1.3, "Containment High-Range Radiation Monitor." Requests delay of implementation until 821030 to allow time to delivery problems.
EISENHUT, D.O. Commonwealth Edison Co. 02/08/27. 2pp. 14694.308. 24X Fiche: 50-254. 82/08/27. 08310402

Inspection reports, IE Bulletins & correspondence

08350414 Forwards IE Insp Repts 80-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 on 810813-820503. No noncompliance noted.
REED, C. Region 3, Office of Director. 02/07/12. 2pp. 14599.219. 24X Fiche: 50-000. 82/07/12. 08350414

080800441 IE Insp Repts 80-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 on 810813-820503. No noncompliance noted. Major areas inspected: allegations re Comm Ed operation of facilities & compliance w/10CFR21.
HAYES, D.W., BRAUND, C., TONGUE, T. Division of Project & Resident Programs. 02/07/09. 15pp. 14217.169. 24X Fiche: 50-000. 82/07/12. 080800441

Fiche: 50-000. 82/07/12. 0804210395

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 02/07/19. Michigan, Univ. of. 112pp. 14358.001. 24X Fiche: 50-000. 82/07/19. 8204210395

8208050424 Forwards IE Insp Repts 50-254/82-08 & 50-265/82-09 on 820428-0629 & notice of violation.
BPESSARD, R.L. Division of Project & Resident Programs. 02/07/19. REED, C. Commonwealth Edison Co. 2pp. 14214.076. 24X Fiche: 50-254. 82/07/19. 8208050424

--8208050435 IE Insp Repts 50-254/82-08 & 50-265/82-09 on 820428-0629. Noncompliance noted: failure to perform required testing after maint on safety-related equipment & failure to provide condensate flood protection.
CHRISTENSEN, N., DUPONT, B.G., WALKER, R.D. Division of Project & Resident Programs. 02/07/11. 15pp. 14214.080. 24X Fiche: 50-254. 82/07/19. 8208050435

8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 02/07/20. Consolidated Edison Co. of New York. 112pp. 14381.001. 24X Fiche: 50-000. 82/07/20. 8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L.I. Division of Fuel Facilities, Materials & Safeguards. 02/07/20. Consolidated Edison Co. of New York. 71pp. 14357.276. 24X Fiche: 50-000. 82/07/20. 8204210397

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 02/07/22. Consolidated Edison Co. of New York. 112pp. 14194.321. 24X Fiche: 50-000. 82/07/22. 8204210398

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 02/07/23. Consolidated Edison Co. of New York. 122pp. 14380.118. 24X Fiche: 50-000. 82/07/23. 8204210401

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 02/07/23. Consolidated Edison Co. of New York. 127pp. 14194.120. 24X Fiche: 50-000. 82/07/23. 8204210402

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 02/07/26. Consolidated Edison Co. of New York. 121pp. 14357.013. 24X Fiche: 50-000. 82/07/26. 8204210403

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 02/07/28. Consolidated Edison Co. of New York. 122pp. 14357.146. 24X Fiche: 50-000. 82/07/28. 8204210405

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 02/08/05. Consolidated Edison Co. of New York. 117pp. 14388.201. 24X Fiche: 50-000. 82/08/05. 8204210407

8208300179 Forwards IE Safeguards Insp Rept 80-265/82-14 on 820720-23. No noncompliance noted.
MILLER, J.R. Division of Engineering & Technical Programs. 02/08/09. REED, C. Commonwealth Edison Co. 2pp. 14599.219. 24X Fiche: 50-265. 82/08/09. 8208300179

--8208300180 IE Safeguards Insp Rept 80-265/82-14 on 820720-23. No noncompliance noted. Major areas inspected: facility organization & operations, inventory & internal controls. Details withheld (ref 10CFR2.790).
FINLEY, A.O., CREED, J.R. Region 3, Office of Director. 02/08/04. 1p. 14599.221. 24X Fiche: 50-265. 82/08/05. 8208300179

8208270523 Forwards IE Insp Repts 50-254/82-12 & 50-265/82-13 on 820722 & 23 No noncompliance noted
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 82/08/13 REED, C. Commonwealth Edison Co 2pp
14566 030. 24X Fiche 50-254, 82/08/13, 8208270523

--8208270527 IE Insp Repts 50-254/82-12 & 50-265/82-13 on 820722-23. No noncompliance noted Major areas inspected prompt public notification/warning sys.
PATTERSON, J. P., AXELSON, W. L. Division of Emergency Preparedness & Operational Support. 82/08/13 3pp. 14566 032 24X
Fiche 50-254, 82/08/13, 8208270523

8208310336 Forwards IE Insp Repts 50-254/82-13 & 50-265/82-13 on 820719-23, 27 & 0806 No noncompliance noted
PAPERIELLO, C. J. Division of Emergency Preparedness & Operational Support. 82/08/17 REED, C. Commonwealth Edison Co 2pp
14692 133 24X Fiche 50-254, 82/08/17, 8208310336

--8208310351 IE Insp Repts 50-254/82-13 & 50-265/82-15 on 820719-23, 27 & 0806 No noncompliance noted Major areas inspected confirmatory program & associated QC procedures
NICHOLSON, N. A., ROZAK, S., SCHUMACHER, M. C. Division of Emergency Preparedness & Operational Support. 82/08/17 8pp 14692 137.
24X Fiche 50-254, 82/08/17, 8208310351

R. Periodic operating reports & related correspondence

8208270010 Resgonds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records. 82/07/13 WELLS, R. A. Critical Mass Energy Project 8pp 14679 208 24X
Fiche 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81"
* NRC - No Detailed Affiliation Given. 82/07/13 48pp.
14679 216. 24X Fiche 50-000, 82/07/13, 8208270010

--8208270263 Forwards "1981 Rept of Occupational Personnel Radiation Doses."
KALIVIANAKIS, N. Commonwealth Edison Co. 82/02/17 KEPLER, J. G. Region 3, Office of Director. 1p. 14679 300. 24X
Fiche 50-000, 82/07/13, 8208270010

--8208270268 "1981 Rept of Occupational Personnel Radiation Doses"
* Commonwealth Edison Co. 82/02/17 3pp 14679 301. 24X
Fiche 50-000, 82/07/13, 8208270010

--8208270559 Forwards "Recorded Annual Whole Body External Exposure for CY81." per 10CFR20.407(b). W/o Quad Cities, Zion, LaSalle, Byron & Braidwood repts
RAMSEY, T. J. Commonwealth Edison Co. 82/03/31. Office of Management and Program Analysis. 1p. 14680 075 24X
Fiche 50-000, 82/07/13, 8208270010

8208160116 Forwards changes, tests & experiments completed during Jul 1982.
KALIVIANAKIS, N. Commonwealth Edison Co. 82/08/02. CASE, E. G. Office of Nuclear Reactor Regulation, Director. 4pp 14349:299.
24X Fiche 50-254, 82/08/02, 8208160116

8208160374 Forwards monthly operating repts for Jul 1982
KALIVIANAKIS, N. Commonwealth Edison Co. 82/08/02. Director's Office, Office of Inspection and Enforcement. 1p 14348:320. 24X
Fiche 50-254, 82/08/02, 8208160374

--8208160381 Monthly operating repts for Jul 1982.
WEINFURTER, E., BUSS, R. Commonwealth Edison Co. 82/08/03 27pp.
14348:321. 24X Fiche 50-254, 82/08/02, 8208160374

B. Reportable occurrences, LERs & related correspondence

8208050290 Forwards LER 82-007/03L-0.
KALIVIANAKIS, N. Commonwealth Edison Co. 82/07/19. KEPLER, J. Region 3, Office of Director. 1p. 14210:215 24X
Fiche 50-265, 82/07/19, 8208050290.

--8208050304 LER 82-007/03L-0 on 820622, electromatic relief valve 2-203-3C failed to open on manual open signal. Caused by valve plug compression rings binding in plug sleeve groove. Valve replaced. Specs for sleeves modified.
WEINFURTER, E. Commonwealth Edison Co. 82/07/19. Region 3, Office of Director. 3pp. 14210:216. 24X Fiche 50-265, 82/07/19, 8208050290.

8208090246 Forwards LER 82-011/01T-0
KALIVIANAKIS, N. Commonwealth Edison Co. 82/07/28 KEPLER, J. Region 3, Office of Director. 1p 14271:048 24X
Fiche 50-265, 82/07/28, 8208090246

--8208090255 LER 82-011/01T-0 on 820715, LPCI inboard injection valve MO-2-1001-298 failed to open. Caused by detached electrical lead on torque switch of valve motor operator inboard valve manually opened & torque switch replaced.
BUSS, R. Commonwealth Edison Co. 82/07/28. Region 3, Office of Director. 3pp 14271:049 24X Fiche 50-265, 82/07/28, 8208090246

8208130222 Forwards LER 82-012/03L-0
KALIVIANAKIS, N. Commonwealth Edison Co. 82/08/02. KEPLER, J. Region 3, Office of Director. 1p 14333:184 24X Fiche 50-265, 82/08/02, 8208130222

--8208130229 LER 82-012/03L-0 on 820714, controllers for valves 2-203-3A, 3B, 3C & 3E found to trip at pressures in excess of specified Tech Spec limits. Caused by improper calibr of pressure switches
REED, M. Commonwealth Edison Co. 82/08/02. Region 3, Office of Director. 2pp. 14333:185. 24X Fiche 50-265, 82/08/02, 8208130222

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8208040283 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. 82/07/20. Document Management Branch. 1p 14231:001 24X Fiche 50-266, 82/07/20, 8208040283.

--8208040288 Forwards public version of revised emergency plan implementing procedures, including Procedures EP 1.3 re estimation of source term, EPIP 3.1 re alert - immediate actions & EPIP 4.1 re site emergency - immediate actions.
FAY, C. W. Wisconsin Electric Power Co. 82/07/09. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 4pp 14231:002. 24X
Fiche 50-266, 82/07/20, 8208040283.

--8208040293 Public version of revised emergency plan implementing procedures, including Procedures EP 1.3 re estimation of source term, EPIP 3.1 re alert - immediate actions & EPIP 4.1 re site emergency - immediate actions.
* Wisconsin Electric Power Co. 82/06/25 54pp. 14231:006. 24X
Fiche 50-266, 82/07/20, 8208040283

8208190188 Forwards revisions to security force training & qualification plan as requested in 820715 ltr. Revision withheld (ref 10CFR2.790).
BURSTEIN, S. Wisconsin Electric Power Co. 82/08/06. CLARK, R. A. Operating Reactors Branch 3. 1p. 14387:048 24X
Fiche 50-266, 82/08/06, 8208190188.

8208190224 Advises that scheduling conflicts & reluctance of State of WI to participate in annual emergency exercise during Summer 1983, support until 820630 request for exemption from 10CFR App E Exercise scheduled for 830920.
FAY, C. W. Wisconsin Electric Power Co. 82/08/09. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 3pp. 14387:177. 24X
Fiche 50-266, 82/08/09, 8208190224.

8208260531 Ack receipt of 820715 ltr re emergency operations facility. Deviations from physical proximity guidelines to plant site must be approved by NRC.
COLBURN, T. O. Operating Reactors Branch 3. 82/08/11. FAY, C. W. Wisconsin Electric Power Co. 2pp. 14572:337. 24X
Fiche 50-266, 82/08/11, 8208260531.

8208260054 Releases public version of emergency plan manual.
FELTON, J. M. Division of Rules and Records. 82/08/13. Document Management Branch. 1p. 14574:078. 24X Fiche 50-266, 82/08/13, 8208260054.

--8208260059 Forwards public version of emergency plan manual, including revisions to Procedures EP 2.0 re emergency plan definitions, EP 4.0 re emergency conditions & EP 6.0 re emergency measures.
BURSTEIN, S. Wisconsin Electric Power Co. 82/08/02. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. CLARK, R. A. Operating Reactors Branch 3. 3pp. 14574:079. 24X
Fiche 50-266, 82/08/13, 8208260054.

--8208260067 Public version of emergency plan manual, including revisions to Procedures EP 2.0 re emergency plan definitions, EP 4.0 re emergency conditions & EP 6.0 re emergency measures.
* Wisconsin Electric Power Co. 82/07/30. 290pp. 14574:084. 24X
Fiche 50-266, 82/08/13, 8208260054.

Judiciary correspondence

0180 Responds to ASLB 811013 memorandum & order re removal of
 osive or mechanical plugs from tubes prior to sleeving.
 orting documentation & DK Porter affidavit encl.
 CHILL, B.W., RIDGWAY, D.A. Wisconsin Electric Power Co.
 CHILL, B.W. Shaw, Pittman, Potts & Trowbridge 81/10/16. 30pp.
 4. 141. 24X Fiche: 50-266, 81/10/16, 8208110180.

00031 Advises that NRC will not respond to licensee 820722 motion
 onduct discovery of WI Environ Decade re Decade contacts
 eaving demonstration program workers.
 HANN, R.O. Hearing Branch 1. 82/08/06. BLOCH, P.R., PAXTON, H.C.,
 E, J.R. Atomic Safety and Licensing Board Panel. 1p. 14296:274.
 F Fiche: 50-266, 82/08/06, 8208100031.

00076 Response to interrogatories re safety evaluation on
 -scale sleeving. Certificate of Svc encl.
 HANN, R.O. Hearing Branch 1. 82/08/06. Wisconsin's
 onmental Decade. 17pp. 14296:157. 24X Fiche: 50-266, 82/08/06,
 8100076

00315 Forwards licensee response to WI Environ Decade motion re
 gible issues & WD Fletcher statement. Proprietary
 ions served on NRC & Decade Nonproprietary version
 ved on remainder of svc list.
 CHILL, B.W. Shaw, Pittman, Potts & Trowbridge. CHURCHILL, B.
 onsin Electric Power Co. 82/08/09. BLOCH, P.R., KLINE, J.R.,
 ON, H.C. Atomic Safety and Licensing Board Panel. 2pp.
 3: 207. 24X Fiche: 50-266, 82/08/09, 8208270315.

0270319 Response to WI Environ Decade 820720-21 motion concerning
 itigable issues. Decade stopped from raising number of
 oposed contentions. Decade fails to justify untimeliness.
 me proposed issues irrelevant.
 URCHILL, B.W. Wisconsin Electric Power Co. CHURCHILL, B.W. Shaw,
 itman, Potts & Trowbridge. 82/08/09. Atomic Safety and
 censing Board Panel. 7pp. 14563:209. 24X
 che: 50-266, 82/08/09, 8208270315.

0270323 Testimony of WD Fletcher re issues raised in Contentions
 2-3(a)-(e), 4 & 5 in WI Environ Decade 820721 motion
 concerning litigable issues Prof qualifications &
 Certificate of Svc encl.
 ETCHER, W.D. Wisconsin Electric Power Co. FLETCHER, W.D.
 istinguish Electric Corp. 82/08/04. 30pp. 14563:260. 24X
 che: 50-266, 82/08/09, 8208270315.

02009 Forwards PQ Easley affidavit of preparation of response to
 nviron Decade Interrogatory 2 Affiant not available to
 a affidavit in time to meet 820806 filing deadline.
 HANN, R.O. Hearing Branch 1. 82/08/10. BLOCH, P.R., PAXTON, H.C.,
 E, J.R. Atomic Safety and Licensing Board Panel. 2pp.
 23: 337. 24X Fiche: 50-266, 82/08/10, 8208120009.

020119 Petition for leave to intervene in steam generator
 placement proceeding & petition for hearing. WI Environ
 ade has recognized life, property & financial interests.
 ertificate of Svc encl.
 ERSON, P. Wisconsin's Environmental Decade. 82/08/10.
 iversions. 3pp. 14327:031. 24X Fiche: 50-266, 82/08/10,
 8120119.

0446 Responds to 820706 notice of proposed issuance of amend to
 ility DL re plans to replace two steam generators.
 nsee opposes Commission determination to provide notice
 opportunity for hearing on generator replacement.
 STEIN, B.P. Wisconsin Electric Power Co. 82/08/10. Docketing &
 ices Branch. 2pp. 14348:253. 24X Fiche: 50-266, 82/08/10,
 8160446.

0219 Informs of 820809 telcon w/PR Bloch re Nucleonics Wk 820805
 icle, "Utils Given NRC Laundry List of Steam Generator
 osals." Author informed Bloch on 820810 that NRC will
 provide info on article due to preliminary nature.
 HANN, R.O. Hearing Branch 1. 82/08/12. BLOCH, P.R., KLINE, J.R.,
 ON, H.C. Atomic Safety and Licensing Board Panel. 3pp.
 42: 330. 24X Fiche: 50-266, 82/08/12, 8208160219.

00118 Response to WI Environ Decade 820721 motion concerning
 itigable issues. Contentions 1-5 & alternative contention on
 orrelationship w/thermal shock. Only Contentions 3(a) &
 4 admissible. Notice of appearance encl.
 HANN, R.O., MCCURREN, H.J. Hearing Branch 1. 82/08/16. Atomic
 ty and Licensing Board Panel. 36pp. 14378:203. 24X
 he: 50-266, 82/08/16, 8208180118.

0180123 Statement of matl fact as to which there is no genuine
 issue.
 HANN, R.O. Hearing Branch 1. 82/08/16. Atomic Safety and
 censing Board Panel. 14pp. 14378:239. 24X
 che: 50-266, 82/08/16, 8208180118.

--8208180127 Affidavit of TQ Colburn re WI Environ Decade 820721 motion
 concerning litigable issues. Contentions 1, 2a, 2c, 3b, 3c, 4
 & 5.
 COLBURN, T.Q. Operating Reactors Branch 3. 82/08/16. 10pp.
 14378:253. 24X Fiche: 50-266, 82/08/16, 8208180118

--8208180131 Affidavit of PQ Easley re WI Environ Decade 820721 motion
 concerning litigable issues. Contention 2(a).
 EASLEY, P.Q. Accident Evaluation Branch. 82/08/16. 2pp.
 14378:263. 24X Fiche: 50-266, 82/08/16, 8208180118.

--8208180134 Affidavit of EL Murphy re WI Environ Decade 820721 motion
 concerning litigable issues. Contentions 3(a), 3(d) & 3(e).
 Certificate of Svc encl.
 MURPHY, E.L. Materials Engineering Branch. 82/08/12. 10pp.
 14378:265. 24X Fiche: 50-266, 82/08/16, 8208180118.

8208200087 Notice of ASLB constitution PB Bloch, chairman & HC Paxton &
 JR Kline, members.
 OTTER, B.P. Atomic Safety and Licensing Board Panel. 82/08/18.
 2pp. 14393:251. 24X Fiche: 50-266, 82/08/18, 8208200087.

8208200293 Confirms licensee understanding w/WI Environ Decade re time
 for filing Decade amend to Decade motion concerning
 itigable issues. Licensee provided disputed documents to
 Decade on 820818. Amend to motion due 820820. Svc list encl.
 CHURCHILL, B.W. Shaw, Pittman, Potts & Trowbridge. CHURCHILL, B.W.
 Wisconsin Electric Power Co. 82/08/18. BLOCH, P.R., KLINE, J.R.,
 PAXTON, H.C. Atomic Safety and Licensing Board Panel. 3pp.
 14398:326. 24X Fiche: 50-266, 82/08/18, 8208200293.

8208240409 Memorandum ordering all filings in proceeding about
 replacement of tube bundles to be designated 50-266-OLA2.
 Designation necessary due to two separate OLA proceedings.
 BLOCH, P.B. Atomic Safety and Licensing Board Panel. 82/08/20. 1p.
 14522:330. 24X Fiche: 50-266, 82/08/20, 8208240409.

8208270448 Amend to motion re third litigable issue on increased
 probability of tube failures due to sleeving, per ASLB
 direction during 820601 conference. Change adds Contention F
 on sleeves in corroded tubes. W/Certificate of Svc.
 ANDERSON, P. Wisconsin's Environmental Decade. 82/08/20. Atomic
 Safety and Licensing Board Panel. 3pp. 14565:253. 24X
 Fiche: 50-266, 82/08/20, 8208270448.

8208270411 Answer opposing WI Environ Decade 820810 petition to
 intervene & request for hearing. Standing not demonstrated &
 aspects as to which intervention sought not specified.
 Notices of appearance & Certificate of Svc encl.
 RIDGWAY, D.A. Wisconsin Electric Power Co. RIDGWAY, D.A. Shaw,
 Pittman, Potts & Trowbridge. 82/08/24. Atomic Safety and
 Licensing Board Panel. 25pp. 14565:193. 24X Fiche: 50-266, 82/08/24,
 8208270411.

8208270486 Response to WI Environ Decade 820721 amend to motion re
 itigable issues. Proposed Contention 3(f) fails to satisfy
 requirements for establishing litigable issues Motion should
 be rejected. Certificate of Svc encl.
 RIDGWAY, D.A. Wisconsin Electric Power Co. RIDGWAY, D.A. Shaw,
 Pittman, Potts & Trowbridge. 82/08/24. Atomic Safety and
 Licensing Board Panel. 12pp. 14565:061. 24X Fiche: 50-266, 82/08/24,
 8208270486.

8208270503 Correction to 820824 Certificate of Svc re licensee Answer
 to WI Environ Decade petition to intervene & petition for
 hearing. Copies hand delivered on 820825.
 RIDGWAY, D.A. Wisconsin Electric Power Co. 82/08/25. 2pp.
 14563:361. 24X Fiche: 50-266, 82/08/25, 8208270503.

P. Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants
 for DL & holders of CP re Commission approved charter for
 CROR. Svc list encl.
 DRICKS, W.J. Office of the Executive Director for Operations.
 82/07/02. Consolidated Edison Co. of New York. 93pp. 14194:001.
 24X Fiche: 30-000, 82/07/02, 8207080064.

8208040630 Ack receipt of 820622 ltr stating objections re replacement
 of steam generator major components. Licensee 820527 ltr
 considered application for amend.
 COLBURN, T.Q. Operating Reactors Branch 3. 82/07/22. ANDERSON, P.
 Wisconsin's Environmental Decade. 2pp. 14225:060. 24X
 Fiche: 50-266, 82/07/22, 8208040630.

8208130128 Forwards Amends 62 & 67 to Licenses DPR-24 & DPR-27,
 respectively & notice of issuance & availability. Amend
 changes Tech Specs to modify limiting conditions for
 operation re auxiliary feedwater pump operation.
 COLBURN, T.Q. Operating Reactors Branch 3. 82/07/27. FAY, C.W.
 Wisconsin Electric Power Co. 3pp. 14350:001. 24X
 Fiche: 50-266, 82/07/27, 8208130128.

--8208130132 Amends 62 & 67 to Licenses DPR-24 & DPR-27, respectively, changing Tech Specs to modify limiting conditions for operation re auxiliary feedwater pump operation
CLARK, R A Operating Reactors Branch 3 82/07/27 8pp
14350.005. 24X Fiche 50-266.82/07/27.8208130128

--8208130135 Notice of issuance & availability of Amends 62 & 67 to Licenses DPR-24 & DPR-27, respectively
CLARK, R A Operating Reactors Branch 3 82/07/27 1p
14350.013 24X Fiche 50-266.82/07/27.8208130128.

8208030440 Forwards response to NRC 820519 request for addl info re proposed reactor vessel water level instrumentation sys required by NUREG-0737, Item II F 2
FAY, C W Wisconsin Electric Power Co 82/07/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director. CLARK, R A
Operating Reactors Branch 3 28pp 14154.019 24X
Fiche 50-266.82/07/28.8208030440

8208040140 Forwards proprietary Figure 6 2 7-2, "Alternating Stresses at Location of Max Fatigue Usage" & revised Page 6 86 to WCAP-9960, "Point Beach Nuclear Plant Steam Generator Slewing Rept." Proprietary info withheld (ref 10CFR2.790)
FAY, C W Wisconsin Electric Power Co 82/07/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director. CLARK, R A
Operating Reactors Branch 3 2pp 14189.301. 24X
Fiche 50-266.82/07/28.8208040140

--8208040146 Submits application for withholding supplemental info to WCAP-9960, "Point Beach Nuclear Plant Steam Generator Slewing Rept." Affidavit (AW-80-53) encl.
WIESEMAN, R A Westinghouse Electric Corp 82/07/15 DENTON, H R
Office of Nuclear Reactor Regulation, Director 8pp. 14189.303
24X Fiche 50-266.82/07/28.8208040140

8208100084 Forwards addl info re generation of temp/pressure profiles for typical high energy line breaks outside containment, in response to 820701 request info based on analysis performed by Bechtel Power Corp in 1973
BURSTEIN, S Wisconsin Electric Power Co 82/08/05 DENTON, H R
Office of Nuclear Reactor Regulation, Director. CLARK, R A
Operating Reactors Branch 3 5pp 14296.136 24X
Fiche 50-266.82/08/05.8208100084

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D O Division of Engineering & Quality Assurance 82/08/09 Consolidated
Edison Co of New York 1p 14336.332 24X Fiche 50-000.82/08/09.
8208090194

8208130109 Submits addl response to NUREG-0737, Item II D.1 re block valves Marshall test data indicates that installed valves will function properly over range of operating & accident conditions
FAY, C W Wisconsin Electric Power Co 82/08/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp. 14333.272
24X Fiche 50-266.82/08/09.8208130109

8208130130 Advises that info addressing criteria of NUREG-0737, Item II B.3, "Post-Accident Sampling Syst." will be provided by 820930.
FAY, C W Wisconsin Electric Power Co 82/08/09. DENTON, H R.
Office of Nuclear Reactor Regulation, Director. CLARK, R A
Operating Reactors Branch 3 1p 14336.018 24X
Fiche 50-266.82/08/09.8208130130.

8208160446 Responds to 820705 notice of proposed issuance of amend to Facility OL re plans to replace two steam generators
Licensee opposes Commission determination to provide notice of opportunity for hearing on generator replacement
BURSTEIN, S P Wisconsin Electric Power Co 82/08/10 Docketing &
Services Branch 2pp. 14348.253 24X Fiche 50-266.82/08/10.
8208160446

8208170268 Discusses plans & Tech Spec changes for compliance w/requirements of 10CFR50 App J, per 820625 ltr. Full compliance re plant design mods to containment spray sys will be achieved by Mar 1983
FAY, C W Wisconsin Electric Power Co. 82/08/13 DENTON, H R.
Office of Nuclear Reactor Regulation, Director 4pp 14367.270.
24X Fiche 50-266.82/08/13.8208170268

0 Inspection Reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/16
Consolidated Edison Co of New York 87pp. 14356.274. 24X
Fiche 50-000.82/07/16.8204210393.

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance 82/07/19.
Michigan, Univ of 112pp 14398.001 24X Fiche 50-000.82/07/19.
8204210395

8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance 82/07/20
Consolidated Edison Co. of New York. 112pp 14381.001. 24X
Fiche 50-000.82/07/20.8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L I Division of Fuel Facilities, Materials & Safeguards
82/07/20 Consolidated Edison Co. of New York. 71pp 14357.276
24X Fiche 50-000.82/07/20.8204210397

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance 82/07/22
Consolidated Edison Co. of New York 112pp 14194.321 24X
Fiche 50-000.82/07/22.8204210398

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co of New York 122pp 14380.115 24X
Fiche 50-000.82/07/23.8204210401

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co of New York 127pp 14194.120 24X
Fiche 50-000.82/07/23.8204210402

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance 82/07/26
Consolidated Edison Co. of New York 121pp. 14357.013 24X
Fiche 50-000.82/07/26.8204210403

8208020273 Responds to request for addl info re sleeving process insp Sampling insp of 10% of upper & lower sleeve joints will be made. Insp will be expanded if unacceptable measurements are noted
FAY, C W Wisconsin Electric Power Co 82/07/26 DENTON, H R.
Office of Nuclear Reactor Regulation, Director 2pp. 14152.293.
24X Fiche 50-266.82/07/26.8208020273.

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/28
Consolidated Edison Co of New York. 122pp. 14357.146 24X
Fiche 50-000.82/07/28.8204210405

8208030472 Responds to IE Bulletin 79-14 re as-built, safety-related piping sys. Ninety-eight isometric drawings revised to incorporate mechanical corrections & represent as-built piping. Remaining isometrics will be completed by 821231.
FAY, C W Wisconsin Electric Power Co 82/07/28. KEPPLER, J O
Region 3, Office of Director. 2pp. 14154.090. 24X
Fiche 50-266.82/07/28.8208030472.

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. 82/08/09.
Consolidated Edison Co. of New York 117pp. 14380.201. 24X
Fiche 50-000.82/08/09.8204210407

8208200131 Submits response to IE Bulletin 82-02 re incidents of severe degradation of threaded fasteners in closures of RCPD of PWR plants.
FAY, C W Wisconsin Electric Power Co 82/08/11. KEPPLER, J O.
Region 3, Office of Director. 10pp 14393.269. 24X
Fiche 50-266.82/08/11.8208200131.

8208240365 Ack receipt of 820730 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-01 & 50-301/82-01
SPESSARD, R L Division of Project & Resident Programs. 82/08/16.
BURSTEIN, S Wisconsin Electric Power Co. 1p. 14520.171. 24X
Fiche 50-266.82/08/16.8208240365.

--8208240370 Responds to NRC 820621 ltr re violations noted in IE Insp Repts 50-266/82-01 & 50-301/82-01. Corrective actions:
in-house procedure revised re personnel responsibilities &
in-house chemistry procedure issued.
BURSTEIN, S Wisconsin Electric Power Co. 82/07/30. KEPPLER, J O.
Region 3, Office of Director. 8pp. 14520.172. 24X
Fiche 50-266.82/08/16.8208240365.

8208260240 Requests NRC approval of encl inservice insp relief requests for second 10-yr insp Approval of Tech Spec Change Request 42 necessary for adoption of ASME Section XI as governing document for inservice insp.
FAY, C. W. Wisconsin Electric Power Co. 82/08/20. DENTON, H. R. Office of Nuclear Reactor Regulation. Director CLARK, R. A. Operating Reactors Branch 3. 21pp. 14554. 233. 24X. Fiche: 50-266. 82/08/20. 8208260240.

9208310165 Ack receipt of 820813 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-10 & 50-301/82-09.
SPESARD, R. L. Division of Project & Resident Programs. 82/08/24. BURSTEIN, S. Wisconsin Electric Power Co. 1p. 14693. 195. 24X. Fiche: 50-266. 82/08/24. 8208310165.

--8208310171 Responds to NRC 820716 ltr re violations noted in IE Insp Repts 50-266/82-10 & 50-301/82-09. Corrective actions minor adjustment to door closer made. Fire doors for safe shutdown equipment have been identified & labelled.
FAY, C. W. Wisconsin Electric Power Co. 82/08/13. KEPPLER, J. O. Region 3, Office of Director. 2pp. 14693. 186. 24X. Fiche: 50-266. 82/08/24. 8208310165.

R. Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A. Critical Mass Energy Project. 8pp. 14679. 208. 24X. Fiche: 50-000. 82/07/13. 8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp. 14679. 216. 24X. Fiche: 50-000. 82/07/13. 8208270010.

--8208270577 Forwards "Rept on Personnel Exposure & Monitoring for CY81," per 10CFR20. 407.
FAY, C. W. Wisconsin Electric Power Co. 82/02/22. Office of Management and Program Analysis. 1p. 14679. 318. 24X. Fiche: 50-000. 82/07/13. 8208270010.

--8208270581 "Rept on Personnel Exposure & Monitoring for CY81."
* Wisconsin Electric Power Co. 82/02/22. 1p. 14679. 319. 24X. Fiche: 50-000. 82/07/13. 8208270010.

8208160041 Forwards monthly operating repts for Jul 1982.
FAY, C. W. Wisconsin Electric Power Co. 82/08/10. NRC - No Detailed Affiliation Given. 1p. 14344. 220. 24X. Fiche: 50-266. 82/08/10. 8208160041.

--8208160043 Monthly operating repts for Jul 1982.
FAY, C. W. Wisconsin Electric Power Co. 82/08/06. 8pp. 14344. 221. 24X. Fiche: 50-266. 82/08/10. 8208160041.

S. Reportable occurrences, LERs & related correspondence

8208020109 Forwards LER 82-012/03L-0.
BURSTEIN, S. Wisconsin Electric Power Co. 82/07/21. KEPPLER, J. O. Region 3, Office of Director. 1p. 14142. 112. 24X. Fiche: 50-266. 82/07/21. 8208020109.

--8208020115 LER 82-012/03L-0 on 820621, during annual diesel insp, emergency diesel generator 3D output breaker failed to close. Caused by broken latch check switch. Switch replaced.
FAY, C. W. Wisconsin Electric Power Co. 82/07/21. Region 3, Office of Director. 2pp. 14142. 113. 24X. Fiche: 50-266. 82/07/21. 8208020109.

I. Hearing transcripts on non-antitrust matters

8208270315 Forwards licensee response to WI Environ Decade motion re litigable issues & WD Fletcher statement. Proprietary versions served on NRC & Decade. Nonproprietary version served on remainder of svc list.
CHURCHILL, B. Shaw, Pittman, Potts & Trowbridge. CHURCHILL, B. Wisconsin Electric Power Co. 82/08/09. BLOCH, P. B., KLINE, J. R., PAXTON, H. C. Atomic Safety and Licensing Board Panel. 2pp. 14563. 207. 24X. Fiche: 50-266. 82/08/09. 8208270315.

--8208270323 Testimony of WD Fletcher re issues raised in Contentions 1, 2, 3(a)-(e), 4 & 5 in WI Environ Decade 820721 motion concerning litigable issues. Prof qualifications & Certificate of Svc encl.
FLETCHER, W. D. Wisconsin Electric Power Co. FLETCHER, W. D. Westinghouse Electric Corp. 82/08/04. 30pp. 14563. 280. 24X. Fiche: 50-266. 82/08/09. 8208270315.

DOCKET 50-267 FORT ST. VRAIN NUCLEAR GENERATING STATION

F. Security, medical, emergency & fire protection plans

8208040490 Releases public version of revised radiological emergency response plan.
FELTON, J. M. Division of Rules and Records. 82/07/22. Document Management Branch. 1p. 14220. 322. 24X. Fiche: 50-267. 82/07/22. 8208040490.

--8208040503 Public version of notice that revised radiological emergency response plan is being forwarded under separate cover, per NRC 820315 request.
WAREMBOURG, D. W. Public Service Co. of Colorado. 82/07/12. EISENHUT, D. O. Division of Licensing. 1p. 14220. 323. 24X. Fiche: 50-267. 82/07/22. 8208040490.

8208040512 Releases public version of revised radiological emergency response plan. Field monitoring procedure & Worksheet 1 for in-field sampling data.
FELTON, J. M. Division of Rules and Records. 82/07/22. Document Management Branch. 1p. 14221. 007. 24X. Fiche: 50-267. 82/07/22. 8208040512.

--8208040521 Forwards public version of Issue 1 of radiological emergency response plan. Field monitoring procedure & Worksheet 1 for in-field sampling data.
* Public Service Co. of Colorado. 82/07/09. NRC - No Detailed Affiliation Given. 1p. 14221. 008. 24X. Fiche: 50-267. 82/07/22. 8208040512.

--8208040526 Public version of Issue 1 of radiological emergency response plan. Field monitoring procedure & Worksheet 1 for in-field sampling data.
* Public Service Co. of Colorado. 82/07/09. 32pp. 14221. 009. 24X. Fiche: 50-267. 82/07/22. 8208040512.

8208060165 Ack receipt of 820602 ltr & partial response to confirmatory action ltr. Site visit anticipated.
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs. 82/08/02. LEE, D. R. Public Service Co. of Colorado. 1p. 14239. 238. 24X. Fiche: 50-267. 82/08/02. 8208060165.

--8208060169 Informs of completion of response to confirmatory action items re integration of emergency action levels into emergency procedure, procurement of add'l self-contained breathing apparatus & personnel emergency accountability.
WAREMBOURG, D. Public Service Co. of Colorado. 82/08/02. COLLINS, J. T. Region 4, Office of Director. 2pp. 14239. 239. 24X. Fiche: 50-267. 82/08/02. 8208060165.

8208160390 Ack receipt of 820723 ltr re early warning alert sys. Approach to determining distribution & effectiveness of sys adequate.
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs. 82/08/10. LEE, D. R. Public Service Co. of Colorado. 1p. 14349. 001. 24X. Fiche: 50-267. 82/08/10. 8208160390.

--8208160399 Notifies that survey of residents within 5-mile emergency planning zone to evaluate effectiveness of early warning sys successful. Status of early warning radio problems identified by FEMA encl.
WAREMBOURG, D. W. Public Service Co. of Colorado. 82/07/23. COLLINS, J. T. Region 4, Office of Director. 3pp. 14349. 002. 24X. Fiche: 50-267. 82/08/10. 8208160390.

8208160444 Ack receipt of 820615 ltr re emergency appraisal audit. Requested extension dates for responses to App A & B to 820818 & 820927, respectively, approved.
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs. 82/08/11. LEE, D. R. Public Service Co. of Colorado. 1p. 14348. 250. 24X. Fiche: 50-267. 82/08/11. 8208160444.

--8208160456 Requests extension of response time to App B of emergency preparedness appraisal. Considers response to App A unnecessary.
WAREMBOURG, D. W. Public Service Co. of Colorado. 82/06/15. COLLINS, J. T. Region 4, Office of Director. 2pp. 14348. 251. 24X. Fiche: 50-267. 82/08/11. 8208160444.

P. Operating license stage documents & correspondence

8208040176 Requests submittal addressing encl criteria re NUREG-0737, Item II.B.3. "Post-Accident Sampling Sys." Schedule for responding to encl requested within 20 days of receipt of ltr.
CLARK, R. A. Operating Reactors Branch 3. 82/07/09. WAREMBOURG, D. W. Public Service Co. of Colorado. 11pp. 14229. 348. 24X. Fiche: 50-267. 82/07/09. 8208040176.

208020429 Advises of forthcoming invoice for fee re util 820506 request for approval of route to cover spent fuel shipment.
MILLER, W.O. License Fee Management Branch. 82/07/16. WAREHBOURD. D. Public Service Co. of Colorado. 1p. 14181:053. 24X
Fiche: 50-267, 82/07/16, 8208020429.

208040350 Forwards request for addl info based on util response to IE Bulletin 80-11, "Masonry Wall Design" & "Control of Heavy Loads at Nuclear Power Plants." draft technical evaluation rept based on response to 801222 generic ltr.
CLARK, R.A. Operating Reactors Branch 3. 82/07/21. LEE, O.R. Public Service Co. of Colorado. 4pp. 14223:128. 24X Fiche: 50-267, 82/07/21, 8208040350.

--8208040355 "Control of Heavy Loads at Nuclear Power Plants"
STICKLEY, T.H. EG&G, Inc. 82/06/30. NRC - No Detailed Affiliation Given. 29pp. 14223:132. 24X Fiche: 50-267, 82/07/21, 8208040350.

208020252 Forwards updates to P & Q ltr logs through Pages 95 & 140, respectively, listing correspondence from Util to governmental regulatory agency per telcon.
MCBRIDE, L.M. Public Service Co. of Colorado. 82/07/22. KUZMYCZ, O. NRC - No Detailed Affiliation Given. 14pp. 14152:213. 24X
Fiche: 50-267, 82/07/22, 8208020252.

2080100011 Forwards startup rept "Initial Approach to Power Tests (B-Series), Interim Rept 23 for Period Ending 820522."
WAREHBOURD, D. Public Service Co. of Colorado. 82/07/22. COLLINS, J.T. Region 4, Office of Director. 2pp. 14296:331. 24X
Fiche: 50-267, 82/07/22, 82080100011.

--8208100016 "Initial Approach to Power Tests (B-Series), Interim Rept 23 for Period Ending 820522."
Public Service Co. of Colorado. 82/07/22. 2pp. 14296:333. 24X
Fiche: 50-267, 82/07/22, 82080100011.

208060198 Responds to NRC 820709 request re schedule for responding to 11 criteria of NUREG-0737, Item 11.8 J concerning post-accident sampling eqs. Numerous submittals addressing item already provided. Stand-alone response will be forwarded.
WAREHBOURD, D.W. Public Service Co. of Colorado. 82/07/28. CLARK, R.A. Operating Reactors Branch 3. 1p. 14239:008. 24X
Fiche: 50-267, 82/07/28, 8208060198.

2080170126 Forwards complete submittal list & statement re NUREG-0737 per discussion.
WAREHBOURD, D.W. Public Service Co. of Colorado. 82/07/29. COLLINS, J.T. Region 4, Office of Director. 9pp. 14358:203. 24X
Fiche: 50-267, 82/07/29, 82080170126.

2080909194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D.O. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14356:332. 24X Fiche: 50-000, 82/08/09, 82080909194.

2080190234 Forwards Class III fee for proposed Tech Spec changes re Limiting Conditions for Operation 4.1.7, per 820706 ltr.
WAREHBOURD, D. Public Service Co. of Colorado. 82/08/11. MILLER, W.O. License Fee Management Branch. 2pp. 14388:190. 24X
Fiche: 50-267, 82/08/11, 82080190234.

2080240221 Forwards draft summary of changes incorporated into updated FSAR.
HOLMES, M.H. Public Service Co. of Colorado. 82/08/13. KUZMYCZ, O. Office of Nuclear Reactor Regulation, Director. 200pp. 14522:001. 24X
Fiche: 50-267, 82/08/13, 82080240221.

2080310355 Comments on ORNL 820804 ltr re util 820706 request for release from 70% power. Util will conduct rise-to-power program gathering sufficient data to evaluate core parameters as well as effects of temp redistribution.
WAREHBOURD, D.W. Public Service Co. of Colorado. 82/08/23. KUZMYCZ, O. NRC - No Detailed Affiliation Given. 2pp. 14693:244. 24X
Fiche: 50-267, 82/08/23, 82080310355.

3. Inspection reports, IE Bulletins & correspondence

204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/16. Consolidated Edison Co. of New York. 87pp. 14356:274. 24X
Fiche: 50-000, 82/07/16, 8204210393.

204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp. 14381:001. 24X
Fiche: 50-000, 82/07/20, 8204210396.

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L.I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20. Consolidated Edison Co. of New York. 71pp. 14357:276. 24X
Fiche: 50-000, 82/07/20, 8204210397.

8208040350 Forwards request for addl info based on util response to IE Bulletin 80-11, "Masonry Wall Design" & "Control of Heavy Loads at Nuclear Power Plants." draft technical evaluation rept based on response to 801222 generic ltr.
CLARK, R.A. Operating Reactors Branch 3. 82/07/21. LEE, O.R. Public Service Co. of Colorado. 4pp. 14223:128. 24X Fiche: 50-267, 82/07/21, 8208040350.

--8208040355 "Control of Heavy Loads at Nuclear Power Plants"
STICKLEY, T.H. EG&G, Inc. 82/06/30. NRC - No Detailed Affiliation Given. 29pp. 14223:132. 24X Fiche: 50-267, 82/07/21, 8208040350.

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/22. Consolidated Edison Co. of New York. 112pp. 14194:321. 24X
Fiche: 50-000, 82/07/22, 8204210398.

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 122pp. 14380:113. 24X
Fiche: 50-000, 82/07/23, 8204210401.

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 127pp. 14194:120. 24X
Fiche: 50-000, 82/07/23, 8204210402.

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/24. Consolidated Edison Co. of New York. 121pp. 14357:013. 24X
Fiche: 50-000, 82/07/24, 8204210403.

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/28. Consolidated Edison Co. of New York. 122pp. 14357:146. 24X
Fiche: 50-000, 82/07/28, 8204210405.

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/08/05. Consolidated Edison Co. of New York. 117pp. 14388:201. 24X
Fiche: 50-000, 82/08/05, 8204210407.

8208100267 Ack receipt of 820727 ltr informing NRC of steps taken to correct deviations noted in IE Insp Rept 50-267/82-13. Rept withheld (ref 10CFR2.790).
NORDERHAUG, L.R. Division of Radiological Safety & Safeguards Program. 82/08/06. LEE, O.R. Public Service Co. of Colorado. 1p. 14294:141. 24X
Fiche: 50-267, 82/08/06, 8208100267.

8208160444 Ack receipt of 820615 ltr re emergency appraisal audit. Requested extension dates for responses to App A & B to 820818 & 820727, respectively, approved.
MADSEN, O.L. Division of Resident Reactor Project & Engineering Programs. 82/08/11. LEE, O.R. Public Service Co. of Colorado. 1p. 14348:250. 24X
Fiche: 50-267, 82/08/11, 8208160444.

--8208160436 Requests extension of response time to App B of emergency preparedness appraisal. Considers response to App A unnecessary.
WAREHBOURD, D.W. Public Service Co. of Colorado. 82/06/13. COLLINS, J.T. Region 4, Office of Director. 2pp. 14348:251. 24X
Fiche: 50-267, 82/08/11, 8208160444.

8208300220 Responds to IE Bulletin 80-11, "Masonry Wall Design," per NRC 820721 request. Responses to Questions 2.4 & 14 re stack bonding & modeling techniques encl.
LEE, O.R. Public Service Co. of Colorado. 82/08/24. CLARK, R.A. Operating Reactors Branch 3. 14pp. 14679:029. 24X
Fiche: 50-267, 82/08/24, 8208300220.

R. Periodic operating reports & related correspondence

8208270010 Responds to FDIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J.M. Division of Rules and Records. 82/07/13. UDELL, H.A. Critical Mass Energy Project. 8pp. 14679:208. 24X
Fiche: 50-000, 82/07/13, 8208270010.

--0208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81"
• NRC - No Detailed Affiliation Given 82/07/13 48pp.
14679 216 24X Fiche: 50-000, 82/07/13, 8208270010

--0208270992 Forwards "Personnel Occupational Exposures CY81," per 10CFR20.407
BOST, F. J. Public Service Co. of Colorado. 82/02/23 BRQDKS, N.
Director's Office, Office of Inspection and Enforcement 1p
14679 329 24X Fiche 50-000, 82/07/13, 8208270010

--8208270995 "Personnel Occupational Exposures CY81"
Public Service Co. of Colorado. 82/02/23 3pp 14679 330
24X Fiche 50-000, 82/07/13, 8208270010

8208130201 Forwards monthly operating rept for Jul 1982
WAREMBOURG, D. Public Service Co. of Colorado. 82/08/09
Director's Office, Office of Inspection and Enforcement 1p
14339 098 24X Fiche: 50-267, 82/08/09, 8208130201.

8208130196 Forwards monthly operating rept for Jul 1982.
WAREMBOURG, D. Public Service Co. of Colorado. 82/08/10
OAHMILL, W. P. Assistant Director for Operating Reactors. 2pp.
14339 114 24X Fiche: 50-267, 82/08/10, 8208130196

--8208130199 Monthly operating rept for Jul 1982.
MCBRIDE, L. M. Public Service Co. of Colorado. 82/08/09. 8pp.
14339 116. 24X Fiche 50-267, 82/08/10, 8208130196.

S Reportable occurrences, LERs & related correspondence

8208050349 Forwards LER 82-024/03X-1. Detailed event analysis encl.
WAREMBOURG, D. Public Service Co. of Colorado. 82/07/30.
COLLINS, J. T. Region 4, Office of Director. 8pp. 14219 319 24X
Fiche: 50-267, 82/07/30, 8208050349

--8208050379 LER 82-024/03X-1 on 820605, all three 480-volt essential
buses lost. Caused by Westinghouse type CV-2 volt relay
being improperly calibr. due to inadequacy of relay calibr
procedure. Procedure updated.
FULLER, C. Public Service Co. of Colorado. 82/07/30. Region 4,
Office of Director 1p. 14219: 327. 24X Fiche: 50-267, 82/07/30,
8208050349

8208160025 Forwards LER 82-028/03L-0. Detailed event analysis encl.
WAREMBOURG, D. Public Service Co. of Colorado. 82/08/06.
COLLINS, J. T. Region 4, Office of Director. 5pp. 14345: 038. 24X
Fiche: 50-267, 82/08/06, 8208160025.

--8208160027 LER 82-028/03L-0 on 820707, excessive water leakage through
PV-21244 necessitated isolation of emergency feedwater
supply header. Caused by water cut in valve seat & plug.
Valve ring seat, plug assembly, body & seat gaskets replaced.
FULLER, C. Public Service Co. of Colorado. 82/08/06. Region 4,
Office of Director. 1p. 14345: 043. 24X Fiche: 50-267, 82/08/06,
8208160025.

8208200117 Forwards LER 82-024/03X-2. Detailed event analysis encl.
WAREMBOURG, D. Public Service Co. of Colorado. 82/08/11.
COLLINS, J. T. Region 4, Office of Director. 7pp. 14393: 321. 24X
Fiche: 50-267, 82/08/11, 8208200117

--8208200124 LER 82-024/03X-2 on 820605, 3 480-volt essential buses lost.
Reactor manually scrammed. Caused by improperly calibr
undervoltage relays & inadequate relay calibr procedure.
FULLER, C. Public Service Co. of Colorado. 82/08/11. Region 4,
Office of Director. 2pp. 14393: 328. 24X Fiche: 50-267, 82/08/11,
8208200117.

8208200126 Forwards LER 82-029/03L-0. Detailed event analysis encl.
WAREMBOURG, D. Public Service Co. of Colorado. 82/08/11.
COLLINS, J. T. Region 4, Office of Director. 4pp. 14399: 358. 24X
Fiche: 50-267, 82/08/11, 8208200126.

--8208200141 LER 82-029/03L-0 on 820712, emergency feedwater headers to
helium circulator piston wheel drives were isolated to
perform maint on leaking header safety valves. Caused by
need to reswamp valve seats & discs. Drives returned to svc.
FULLER, C. Public Service Co. of Colorado. 82/08/11. Region 4,
Office of Director. 1p. 14399: 362. 24X Fiche: 50-267, 82/08/11,
8208200126

8208240053 Forwards LER 82-030/03L-0. Detailed event analysis encl.
WAREMBOURG, D. Public Service Co. of Colorado. 82/08/17.
COLLINS, J. T. Region 4, Office of Director. 5pp. 14520: 015. 24X
Fiche: 50-267, 82/08/17, 8208240053.

--8208240056 LER 82-030/03L-0 on 820719, total primary coolant oxidants
exceeded Tech Specs twice. Caused by offgassing of moisture
due to increasing temp during recovery from reactor scram.
FULLER, C. Public Service Co. of Colorado. 82/08/17. Region 4,
Office of Director 1p. 14520 020. 24X Fiche: 50-267, 82/08/17,
8208240053

8208240074 Forwards LER 82-029/03X-1. Detailed event analysis encl.
WAREMBOURG, D. Public Service Co. of Colorado. 82/08/17.
COLLINS, J. T. Region 4, Office of Director. 5pp. 14519 349. 24X
Fiche: 50-267, 82/08/17, 8208240074

--8208240079 LER 82-029/03X-1 on 820712, 20 & 21, emergency feedwater
headers to helium circulator piston wheel drives isolated
to perform maint on leaking header safety valves. Cause of
leakage not stated.
FULLER, C. Public Service Co. of Colorado. 82/08/17. Region 4,
Office of Director 1p. 14519 354. 24X Fiche: 50-267, 82/08/17,
8208240074

DOCKET 50-268 MIDWEST FUEL RECOVERY PLANT

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation" Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19.
Michigan, Univ of 112pp. 14358 001. 24X Fiche: 50-000, 82/07/19,
8204210395

DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8208040450 Forwards request for addl info re standby shutdown facility
to determine acceptability & resolve NRC concerns regarding
fire protection & turbine bldg flooding.
STOLZ, J. F. Operating Reactors Branch 4. 82/07/17. PARKER, W. D.
Duke Power Co. 9pp. 14220 253. 24X Fiche: 50-269, 82/07/17,
8208040450.

8208110182 Informs of planned installation of fire hose cabinets at
entrances to cable rooms & of planned utilization of
existing turbine bldg hose stations for protection of
equipment rooms. Mod affects 771122 commitment.
TUCKER, H. B. Duke Power Co. 82/08/03. DENTON, H. R. Office of
Nuclear Reactor Regulation, Director. 2pp. 14313: 360. 24X
Fiche: 50-269, 82/08/03, 8208110182

8208190405 Releases public version of revised emergency plan
implementing procedures.
FELTON, J. M. Division of Rules and Records. 82/08/10. Document
Management Branch. 1p. 14504: 106. 24X Fiche: 50-269, 82/08/10,
8208190405.

--8208190412 Forwards public version of revised emergency plan
implementing procedures, including Station Directive 2.92 re
emergency response organization & Procedure CP/D/A/2005/20 re
post-accident determination of gamma isotopic activity.
TUCKER, H. B. Duke Power Co. 82/08/03. DENTON, H. R. Office of
Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating
Reactors Branch 4. 2pp. 14504: 187. 24X Fiche: 50-269, 82/08/10,
8208190405.

--8208190422 Public version of revised emergency plan implementing
procedures, including Station Directive 2.92 re emergency
response organization & Procedure CP/D/A/2005/20 re
post-accident determination of gamma isotopic activity.
OWEN, T. B. Duke Power Co. 82/07/23. 94pp. 14504: 189. 24X
Fiche: 50-269, 82/08/10, 8208190405.

8208260418 Releases public version of revised crisis mgt plan.
FELTON, J. M. Division of Rules and Records. 82/08/11. Document
Management Branch. 1p. 14572: 098. 24X Fiche: 50-000, 82/08/11,
8208260418.

--8208260430 Forwards public version of Revision 5 to crisis mgt plan.
Revision involves reorganization of crisis mgt team &
updates of Sections D, K & M.
PARKER, W. D. Duke Power Co. 82/07/19. DENTON, H. R. Office of
Nuclear Reactor Regulation, Director. 1p. 14572: 099. 24X
Fiche: 50-000, 82/08/11, 8208260418.

--8208260437 Public version of Revision 5 to crisis mgt plan.
TUCKER, H. B. Duke Power Co. 82/07/09. 134pp. 14572: 100. 24X
Fiche: 50-000, 82/08/11, 8208260418.

B208260529 Releases public version of emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records 82/08/13 Document
Management Branch. 1p. 14569 001 24X Fiche 50-269.82/08/13.
B208260529

--B208260937 Forwards public version of Emergency Plan Implementing Procedures AP/0/A/1000/10 re emergency evacuation & HP/0/B/1009/15 re sampling & quantifying high level gaseous radiiodine & particulate radioactivity
TUCKER, H. B. Duke Power Co. 82/08/05 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 1p. 14569 003 24X Fiche 50-269.82/08/13.
B208260529

--B208260542 Public version of Emergency Plan Implementing Procedures AP/0/A/1000/10 re emergency evacuation & HP/0/B/1009/15 re sampling & quantifying high level gaseous radiiodine & particulate radioactivity
TUCKER, H. B. Duke Power Co. 82/07/30 4pp. 14569 004 24X Fiche 50-269.82/08/13. B208260529

I. Financial information

B208300328 Forwards util & NC Municipal Power Agency Annual Financial Repts for 1981.
TUCKER, H. B. Duke Power Co. 82/08/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 14599 227 24X Fiche: 50-000, 82/08/24. B208300328

--B208300333 Annual Financial Rept 1981
HORN, C. Duke Power Co. 82/02/15 48pp 14599 006 24X Fiche 50-000, 82/08/24. B208300328

B208300342 Forwards Annual Financial Rept 1981.
TUCKER, H. B. Duke Power Co. 82/08/24. DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4. 1p. 14599:110. 24X Fiche: 50-269.82/08/24. B208300342

P. Operating license stage documents & correspondence

B207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl.
DRAKES, W. J. Office of the Executive Director for Operations. 82/07/02. Consolidated Edison Co. of New York 93pp. 14194:001. 24X Fiche: 50-000, 82/07/02. B207080064.

B208040546 Notification of B20818-19 meetings w/util & consultants in Seneca, SC to discuss radiological effluent Tech Specs.
WAGNER, P. C. Operating Reactors Branch 4 82/07/27. STOLZ, J. F. Operating Reactors Branch 4. 2pp 14220:357 24X Fiche: 50-269.82/07/27. B208040546.

B208030223 Submits changes to completion dates for NUREG-0737, Item II B.3, "Post-Accident Sampling," & II F.1, "Noble Gas Monitors," per B20416 status rept.
PARKER, W. O. Duke Power Co. 82/07/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4. 2pp. 14159:325. 24X Fiche: 50-269.82/07/28. B208030223.

B208030541 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, revising Tech Specs 6 O through 6 J re util reorganization, superintendent of operations qualification requirements & organization chart. Class I & II amend fees encl.
PARKER, W. O. Duke Power Co. 82/07/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4. 3pp. 14162:353. 24X Fiche: 50-000, 82/07/30. B208030541.

--B208030551 Forwards Class I & II amend fees to cover revisions to Tech Specs 6 2 re offsite & station organization & 6 O through 6 J re reorganization.
PARKER, W. O. Duke Power Co. 82/07/30. MILLER, W. E. Office of the Controller. 1p. 14162:356. 24X Fiche 50-000, 82/07/30. B208030541.

--B208030540 Proposed Tech Specs 6 O-6 J re administrative controls, review & audit. Organization chart encl.
* Duke Power Co. 82/07/30 13pp. 14162:357. 24X Fiche: 50-000, 82/07/30. B208030541

B208040311 BIOECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS: OGDNEE CASE STUDY. Docket Nos. 50-269 And 50-270. (Duke Power Company)
FLYNN, J. Social Impact Research, Inc. * Mountain West Research, Inc. FIN 8-6268. NUREG/CR-2749 V07 82/07/31. Division of Health, Biting & Environment. 18pp. Available at NTIS. \$7.00. 14229:001. 24X Fiche: 50-269.82/07/31. B208040311.

B208100193 Responds to NRC B20708 request for schedule for responding to NUREG-0737, Item II B.3, "Post-Accident Sampling Sys." Info will be submitted by B21101
TUCKER, H. B. Duke Power Co. 82/08/05 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4. 1p. 14298:197. 24X Fiche: 50-269.82/08/05. B208100193.

B208120028 Provides addl info re availability of steam generator cooling water in event of tornado strike, per NRC B20408 safety evaluation Configuration, as modified by standby shutdown facility, acceptable
TUCKER, H. B. Duke Power Co. 82/08/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4. 2pp. 14324:038 24X Fiche: 50-269.82/08/06. B208120028

B208120216 Advises that responses to questions re adequacy of station electric distribution sys voltages will be submitted no later than B21008, per B20608 request Delay caused by required addl research & manpower limitations.
TUCKER, H. B. Duke Power Co. 82/08/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 1p. 14326:171. 24X Fiche: 50-269.82/08/06. B208120216

B208090194 Generic ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes IOCFR Chapter 1 requirements & provides alternatives to requirements Svc list encl.
EISENHUT, D. O. Division of Licensing 82/08/09. Consolidated Edison Co. of New York 1p. 14336:332 24X Fiche: 50-000, 82/08/09. B208090194

B208170151 Responds to NRC B20709 ltr reviewing shift technical advisor training programs required by Item I A.1.1 of NUREG-0730 & NUREG-0660 Disagrees w/NRC expectation that all new hires have bachelors degree or equivalent
TUCKER, H. B. Duke Power Co. 82/08/12 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 2pp. 14354:218 24X Fiche: 50-269.82/08/12. B208170151.

B208200025 Advises that util response to NRC B20713 ltr re schedule for submitting supplemental ECCS calculations utilizing cladding models of NUREG-0630 will be submitted by B30301.
TUCKER, H. B. Duke Power Co. 82/08/12. DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 1p. 14392:246 24X Fiche: 50-269.82/08/12. B208200025.

B208240242 Disagrees w/NRC expectations that all new hires have bachelors degree or equivalent pending new guidance per B20709 ltr & NUREG-0737, Item I A.1.1. Shift Technical Advisor" & NUREG-0660
TUCKER, H. B. Duke Power Co. 82/08/12 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 2pp. 14520:070 24X Fiche 50-269.82/08/12. B208240242

B208310236 Forwards summary of licensee efforts to resolve NUREG-0737, Item II K.3.30 re revised small break LOCA methods. Util will support B&W owners group effort to provide integral sys test data, utilizing CERDA test facility.
TUCKER, H. B. Duke Power Co. 82/08/25 DENTON, H. R. Office of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 11pp. 14693:096 24X Fiche: 50-269.82/08/25. B208310236

Q Inspection reports, IE Bulletins & correspondence

B208030999 Forwards IE Insp Repts 50-269/82-21, 50-270/82-21 & 50-287/82-21 on B20614-18. No noncompliance noted
LEWIS, R. C. Division of Project & Resident Programs 82/07/09. PARKER, W. O. Duke Power Co. 2pp 14162:313 24X Fiche 50-269.82/07/09. B208030999.

--B208030613 IE Insp Repts 50-269/82-21, 50-270/82-21 & 50-287/82-21 on B20614-18. No noncompliance noted. Major areas inspected: review of chemistry & radiochemistry procedures & airborne effluent sampling & accountability.
EVANS, C. D., MONTGOMERY, D. M. Division of Emergency Preparedness & Operational Support. 82/07/07. 10pp. 14162:313. 24X Fiche: 50-269.82/07/09. B208030999

B208030548 Forwards IE Insp Repts 50-269/82-26, 50-270/82-26 & 50-287/82-26 on B20706-09. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 82/07/14. PARKER, W. O. Duke Power Co. 2pp. 14162:096. 24X Fiche: 50-269.82/07/14. B208030548.

--B208030557 IE Insp Repts 50-269/82-26, 50-270/82-26 & 50-287/82-26 on B20706-09. No noncompliance noted. Major areas inspected: followup of extraction steam line rupture.
ORDERS, W., PUCKETT, M., KLEINBOROW, W. Division of Project & Resident Programs. 82/07/14. 5pp. 14162:098. 24X Fiche: 50-269.82/07/14. B208030548.

Consolidated Edison Co. of New York 87pp. 14355:274 24X
 Fiche: 50-000, 82/07/16, 8204210393.

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/19.
 Michigan, Univ. of 112pp. 14358:001 24X Fiche: 50-000, 82/07/19, 8204210395.

8204210396 IE Info Notice 82-25. "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20
 Consolidated Edison Co. of New York 112pp. 14381:001 24X
 Fiche: 50-000, 82/07/20, 8204210396.

8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
 COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/07/20. Consolidated Edison Co. of New York. 71pp. 14357:276
 24X Fiche: 50-000, 82/07/20, 8204210397.

8204210398 IE Info Notice 82-26. "RCIC & IFCI Turbine Exhaust Check Valve Failures." Svc list encl.
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/22
 Consolidated Edison Co. of New York 112pp. 14194:321. 24X
 Fiche: 50-000, 82/07/22, 8204210398.

8208160163 Forwards IE Insp Repts 50-269/82-24, 50-270/82-24 & 50-287/82-21 on 820614-25. No noncompliance noted.
 DANCE, H. C. Division of Project & Resident Programs. 82/07/22.
 PARKER, W. D. Duke Power Co. 2pp. 14349:069 24X
 Fiche: 50-269, 82/07/22, 8208160163.

--8208160169 IE Insp Repts 50-269/82-24, 50-270/82-24 & 50-287/82-21 on 820614-25. No noncompliance noted. Major areas inspected: Unit 3 10-yr inservice ultrasonic insp of steam generators, pressurizer reactor vessel & RCPB pipe.
 COLEY, J. L., ECONOMICOS, N. Division of Engineering & Technical Programs 82/07/19 7pp. 14345:071. 24X Fiche: 50-269, 82/07/22, 8208160163.

8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl.
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
 Consolidated Edison Co. of New York 122pp. 14380:115. 24X
 Fiche: 50-000, 82/07/23, 8204210401.

8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl.
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
 Consolidated Edison Co. of New York 127pp. 14194:120. 24X
 Fiche: 50-000, 82/07/23, 8204210402.

8208020303 Responds to NRC 820625 ltr re violations noted during IE Insp. Corrective actions: missing cap for test tee replaced & instrument procedures revised to identify all equipment removed from svc. Util protests civil penalty.
 PARKER, W. D. Duke Power Co. 82/07/23 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 40pp. 14181:345. 24X
 Fiche: 50-269, 82/07/23, 8208020303.

8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl.
 JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26.
 Consolidated Edison Co. of New York 121pp. 14357:013. 24X
 Fiche: 50-000, 82/07/26, 8204210403.

8208160194 Forwards IE Insp Repts 50-269/82-27, 50-270/82-27 & 50-287/82-27 on 820610-0715. No noncompliance noted.
 DANCE, H. C. Division of Project & Resident Programs. 82/07/26.
 PARKER, W. D. Duke Power Co. 2pp. 14344:129. 24X
 Fiche: 50-269, 82/07/26, 8208160194.

--8208160202 IE Insp Repts 50-269/82-27, 50-270/82-27 & 50-287/82-27 on 820610-0715. No noncompliance noted. Major areas inspected: operations safety verification, surveillance testing, station maint activities & plant trips.
 ORDERB, W., FALCONER, D., BRYANT, J. Division of Project & Resident Programs. 82/07/26. 11pp. 14344:131. 24X Fiche: 50-269, 82/07/26, 8208160194.

8208030595 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/82-17, 50-270/82-17 & 50-287/82-17.
 LEWIS, R. C. Division of Project & Resident Programs. 82/07/27.
 PARKER, W. D. Duke Power Co. 1p. 14162:232. 24X
 Fiche: 50-269, 82/07/27, 8208030595.

820715 & prevent198 maint program will be re-evaluated.
 PARKER, W. D. Duke Power Co. 82/07/16 O'REILLY, J. P. Region 2, Office of Director. 2pp. 14162:233 24X Fiche: 50-269, 82/07/27, 8208030595.

--8208030618 Forwards IE Insp Repts 50-269/82-17, 50-270/82-17 & 50-287/82-17 on 820510-14 & notice of violation.
 DANCE, H. C. Division of Project & Resident Programs. 82/06/16
 PARKER, W. D. Duke Power Co. 2pp. 14162:235 24X
 Fiche: 50-269, 82/07/27, 8208030595.

--8208030625 Notice of violation from insp on 820510-14.
 * Division of Project & Resident Programs. 82/06/16 1p
 14162:237. 24X Fiche: 50-269, 82/07/27, 8208030595.

--8208030636 IE Insp Repts 50-269/82-17, 50-270/82-17 & 50-287/82-17 on 820510-14. Noncompliance noted: door providing access to raduate compacting area found unlocked & positive access control not in effect.
 COLLINS, T. R., BARR, K. P. Division of Engineering & Technical Programs. 82/06/10. 8pp. 14162:238 24X Fiche: 50-269, 82/07/27, 8208030595.

8208160364 Forwards IE Insp Repts 50-269/82-29, 50-270/82-29 & 50-287/82-29 on 820712-16. No noncompliance noted.
 DANCE, H. C. Division of Project & Resident Programs. 82/07/27.
 PARKER, W. D. Duke Power Co. 2pp. 14349:041 24X
 Fiche: 50-269, 82/07/27, 8208160364.

--8208160375 IE Insp Repts 50-269/82-29, 50-270/82-29 & 50-287/82-29 on 820712-16. No noncompliance noted. Major areas inspected: radiation protection, shipment of radioactive matl, personnel dosimetry, portable instrument calibr & review of LERs.
 COLLINS, T. R., BARR, K. P. Division of Engineering & Technical Programs. 82/07/23 6pp. 14349:043. 24X Fiche: 50-269, 82/07/27, 8208160364.

--8208160375 IE Insp Repts 50-269/82-29, 50-270/82-29 & 50-287/82-29 on 820712-16. No noncompliance noted. Major areas inspected: radiation protection, shipment of radioactive matl, personnel dosimetry, portable instrument calibr & review of LERs.
 COLLINS, T. R. Region 2, Office of Director. 82/07/23. 6pp. 14349:043 24X Fiche: 50-269, 82/07/27, 8208160364.

--8208160375 IE Insp Repts 50-269/82-29, 50-270/82-29 & 50-287/82-29 on 820712-16. No noncompliance noted. Major areas inspected: radiation protection, shipment of radioactive matl, personnel dosimetry, portable instrument calibr & review of LERs.
 COLLINS, T. R. Division of Engineering & Technical Programs. 82/07/23. 6pp. 14349:043. 24X Fiche: 50-269, 82/07/27, 8208160364.

8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
 JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28
 Consolidated Edison Co. of New York. 122pp. 14357:146. 24X
 Fiche: 50-000, 82/07/28, 8204210405.

8208160291 Forwards response to IE Bulletin 82-02. "Degradation of Threaded Fasteners in RCPB of PWR Plants." Improved design basket is onsite & ready for use to repair reactor coolant pump.
 PARKER, W. D. Duke Power Co. 82/07/29 O'REILLY, J. P. Region 2, Office of Director. 3pp. 14346:265 24X Fiche: 50-269, 82/07/29, 8208160291.

8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
 JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/08.
 Consolidated Edison Co. of New York. 117pp. 14388:201. 24X
 Fiche: 50-000, 82/08/08, 8204210407.

R. Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
 FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A. Critical Mass Energy Project. 8pp. 14679:208 24X
 Fiche: 50-000, 82/07/13, 8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
 * NRC - No Detailed Affiliation Given. 82/07/13. 48pp.
 14679:216. 24X Fiche: 50-000, 82/07/13, 8208270010.

--8208270603 Forwards "Statistical Rpt of Recorded Personnel Whole Body Exposures for CY81," per 10CPR20 407
PARKER, W.D. Duke Power Co 82/02/25 Office of Management and Program Analysis. 1p 14679 340 24X Fiche 50-000, 82/07/13, 8208270010.

--8208270612 "Statistical Rpt of Recorded Personnel Whole Body Exposures for CY81"
LEWIS, L. Duke Power Co 82/02/25 1p 14679 341. 24X
Fiche 50-000, 82/07/13, 8208270010

8208170087 Forwards monthly operating repts for Jul 1982
TUCKER, H.B. Duke Power Co 82/08/13 Director's Office, Office of Inspection and Enforcement. 1p 14358 149 24X
Fiche: 50-269, 82/08/13, 8208170087.

--8208170091 Monthly operating repts for Jul 1982.
REAVIS, J.A. Duke Power Co 82/08/13 16pp 14358 150. 24X
Fiche: 50-269, 82/08/13, 8208170087.

6 Reportable occurrences, LERs & related correspondence

8208020079 RD 269/82-13: on 820706, emergency feedwater pump declared inoperable when required surveillance testing discovered not performed. Investigation & rpt will be completed, reviewed & submitted by 820803
PARKER, W.D. Duke Power Co. 82/07/20. O'REILLY, J.P. Region 2, Office of Director. 1p. 14144 104 24X Fiche: 50-269, 82/07/20, 8208020079

8208020160 Forwards LER 82-012/01T-0 Detailed event analysis encl.
PARKER, W.D. Duke Power Co. 82/07/21. O'REILLY, J.P. Region 2, Office of Director. 2pp. 14141 066. 24X Fiche: 50-269, 82/07/21, 8208020160.

--8208020164 LER 82-012/01T-0 on 820623, both trains of reactor bldg spray inoperable due to train B pump out of svc while train A pump suction valve was shut. Caused by personnel error. Train B pump racked in pump breaker.
KUTZER, J.F. Duke Power Co. 82/07/21. Region 2, Office of Director. 1p. 14141 068. 24X Fiche: 50-269, 82/07/21, 8208020160

8208020168 Advises that RD-269/82-11 providing details of 820622 incident when unit declared inoperable due to main tie breaker to overhead transmission path not closing, will be submitted no later than 820820
PARKER, W.D. Duke Power Co 82/07/22. O'REILLY, J.P. Region 2, Office of Director. 1p 14141 020. 24X Fiche: 50-269, 82/07/22, 8208020168.

8208030460 Forwards updated LER 82-008/01X-1. Detailed event analysis encl.
PARKER, W.D. Duke Power Co. 82/07/23 O'REILLY, J.P. Region 2, Office of Director. 3pp. 14154 060. 24X Fiche: 50-269, 82/07/23, 8208030460.

--8208030465 Updated LER 82-008/01X-1 on 820323, air found leaking into reactor bldg through instrument line test tee in penetration WB-13. Caused by personnel error. Pressure switch not properly returned to svc after last calibr. Cap replaced
MORRIS, J.F. Duke Power Co 82/07/23 Region 2, Office of Director. 1p. 14154 063. 24X Fiche: 50-269, 82/07/23, 8208030460.

8208120172 Forwards LER 82-013/01T-0 Detailed event analysis encl.
TUCKER, H.B. Duke Power Co. 82/08/03. O'REILLY, J.P. Region 2, Office of Director. 2pp. 14324 239. 24X Fiche: 50-269, 82/08/03, 8208120172.

--8208120178 LER 82-013/01T-0 on 820706, emergency feedwater initiation logic pressure switches determined not surveillance tested from 820523-0708, rendering pumps inoperable. Caused by inadequate review of Tech Spec change. Tests performed.
KUTZER, J.F. Duke Power Co 82/08/03. Region 2, Office of Director. 1p. 14324 241. 24X Fiche: 50-269, 82/08/03, 8208120172.

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8208040450 Forwards request for addl info re standby shutdown facility to determine acceptability & resolve NRC concerns regarding fire protection & turbine bldg flooding
STOLZ, J.F. Operating Reactors Branch 4. 82/07/17. PARKER, W.D. Duke Power Co. 9pp. 14220 253. 24X Fiche: 50-269, 82/07/17, 8208040450.

8208110182 Informs of planned installation of fire hose cabinets at entrances to cable rooms & of planned utilization of existing turbine bldg hose stations for protection of equipment rooms. Mod affects 771122 commitment
TUCKER, H.B. Duke Power Co 82/08/03 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp 14313 360 24X Fiche 50-269, 82/08/03, 8208110182

8208190405 Releases public version of revised emergency plan implementing procedures
FELTON, J.M. Division of Rules and Records 82/08/10 Document Management Branch 1p 14504 186 24X Fiche 50-269, 82/08/10, 8208190405

--8208190412 Forwards public version of revised emergency plan implementing procedures, including Station Directive 2.92 re emergency response organization & Procedure CP/O/A/2005/20 re post-accident determination of gamma isotopic activity.
TUCKER, H.B. Duke Power Co 82/08/03 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 2pp 14504 187 24X Fiche 50-269, 82/08/10, 8208190405

--8208190422 Public version of revised emergency plan implementing procedures, including Station Directive 2.92 re emergency response organization & Procedure CP/O/A/2005/20 re post-accident determination of gamma isotopic activity
OWEN, T.B. Duke Power Co 82/07/23 94pp 14504 189. 24X Fiche: 50-269, 82/08/10, 8208190405

8208260418 Releases public version of revised crisis mgt plan
FELTON, J.M. Division of Rules and Records. 82/08/11. Document Management Branch. 1p. 14572 098 24X Fiche 50-000, 82/08/11, 8208260418

--8208260430 Forwards public version of Revision 5 to crisis mgt plan. Revision involves reorganization of crisis mgt team & updates of Sections D.K & M
PARKER, W.D. Duke Power Co. 82/07/19 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 14572 099. 24X Fiche: 50-000, 82/08/11, 8208260418

--8208260437 Public version of Revision 5 to crisis mgt plan
TUCKER, H.B. Duke Power Co 82/07/09 134pp 14572 100. 24X Fiche: 50-000, 82/08/11, 8208260418

8208260529 Releases public version of emergency plan implementing procedures
FELTON, J.M. Division of Rules and Records. 82/08/13 Document Management Branch. 1p. 14569 001 24X Fiche 50-269, 82/08/13, 8208260529.

--8208260537 Forwards public version of Emergency Plan implementing Procedures AP/O/A/1000/10 re emergency evacuation & HP/O/B/1009/15 re sampling & quantifying high level gaseous radioiodine & particulate radioactivity.
TUCKER, H.B. Duke Power Co 82/08/03 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 1p 14569 003 24X Fiche: 50-269, 82/08/13, 8208260529.

--8208260542 Public version of Emergency Plan implementing Procedures AP/O/A/1000/10 re emergency evacuation & HP/O/B/1009/15 re sampling & quantifying high level gaseous radioiodine & particulate radioactivity.
TUCKER, H.B. Duke Power Co. 82/07/30 44pp. 14569 004 24X Fiche: 50-269, 82/08/13, 8208260529.

I. Financial information

8208300328 Forwards util & NC Municipal Power Agency Annual Financial Repts for 1981.
TUCKER, H.B. Duke Power Co. 82/08/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 14599 227. 24X Fiche: 50-000, 82/08/24, 8208300328.

--8208300335 Annual Financial Rept 1981.
HORN, C. Duke Power Co. 82/02/15. 48pp 14599 006. 24X Fiche: 50-000, 82/08/24, 8208300328.

8208300342 Forwards Annual Financial Rept 1981.
TUCKER, H.B. Duke Power Co. 82/08/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 1p. 14599 110. 24X Fiche 50-269, 82/08/24, 8208300342.

DOCKETED ITEMS

P Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRDR, Svc list encl
DIRCAS:W J. Office of the Executive Director for Operations.
82/07/02 Consolidated Edison Co. of New York 93pp 14194-001
24X Fiche: 50-000, 82/07/02, 8207080064

8208040546 Notification of 820818-19 meetings w/utl & consultants in Seneca, BC to discuss radiological effluent Tech Specs.
WAGNER, P C. Operating Reactors Branch 4 82/07/27. STOLZ, J F. Operating Reactors Branch 4 2pp 14220-357 24X Fiche: 50-269, 82/07/27, 8208040546

8208030223 Submits changes to completion dates for NUREQ-0737, Items I I B.3. "Post-Accident Sampling," & I I F.1. "Noble Gas Monitors," per 820416 status rept
PARKER, W O. Duke Power Co. 82/07/28 DENTON, H R. Office of Nuclear Reactor Regulation, Director STOLZ, J F. Operating Reactors Branch 4. 2pp 14159-325. 24X Fiche: 50-269, 82/07/28, 8208030223

8208030541 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, revising Tech Specs & O through & 3 re util reorganization, superintendent of operations qualification requirements & organization chart Class I & II amend fees encl
PARKER, W O. Duke Power Co. 82/07/30. DENTON, H R. Office of Nuclear Reactor Regulation, Director STOLZ, J F. Operating Reactors Branch 4. 3pp 14162-333 24X Fiche: 50-000, 82/07/30, 8208030541

--8208030551 Forwards Class I & II amend fees to cover revisions to Tech Specs & 2 re offsite & station organization & 6 O through & 3 re reorganization
PARKER, W O. Duke Power Co. 82/07/30. MILLER, W E. Office of the Controller. 1p 14162-356. 24X Fiche: 50-000, 82/07/30, 8208030541.

--8208030560 Proposed Tech Specs & O-6.3 re administrative controls, review & audit Organization chart encl.
* Duke Power Co. 82/07/30 13pp. 14162-357. 24X Fiche: 50-000, 82/07/30, 8208030541.

8208040311 SOCIOECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS: OCONEE CASE STUDY. Docket Nos. 50-269 And 50-270. (Duke Power Company)
FLYNN, J. Social Impact Research, Inc. * Mountain West Research, Inc. FIN 8-6268 NUREQ/CR-2749 V07. 82/07/31. Division of Health, Biting & Environment. 185pp. Available at NTIS. \$7.00. 14229-001 24X Fiche: 50-269, 82/07/31, 8208040311.

8208100193 Responds to NRC 820708 request for schedule for responding to NUREQ-0737, Item I I B.3. "Post-Accident Sampling Sys" Info will be submitted by 821101.
TUCKER, H B. Duke Power Co. 82/08/05. DENTON, H R. Office of Nuclear Reactor Regulation, Director. STOLZ, J F. Operating Reactors Branch 4. 1p. 14298-197 24X Fiche: 50-269, 82/08/05, 8208100193

8208120028 Provides addl info re availability of steam generator cooling water in event of tornado strike, per NRC 820408 safety evaluation. Configuration as modified by standby shutdown facility, acceptable.
TUCKER, H B. Duke Power Co. 82/08/06 DENTON, H R. Office of Nuclear Reactor Regulation, Director. STOLZ, J F. Operating Reactors Branch 4. 2pp. 14324-098 24X Fiche: 50-269, 82/08/06, 8208120028

8208120216 Advises that responses to questions re adequacy of station electric distribution sys voltages will be submitted no later than 821008, per 820608 request. Delay caused by required addl research & manpower limitations.
TUCKER, H B. Duke Power Co. 82/08/06. DENTON, H R. Office of Nuclear Reactor Regulation, Director. STOLZ, J F. Operating Reactors Branch 4. 1p 14326-171 24X Fiche: 50-269, 82/08/06, 8208120216.

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes ICFR Chapter I requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D O. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14356-332. 24X Fiche: 50-000, 82/08/09, 8208090194.

8208170151 Responds to NRC 820709 ltr reviewing shift technical advisor training programs required by Item I. A 1.1 of NUREQ-7370 & NUREQ-0660. Disagree w/NRC expectation that all new hires have bachelors degree or equivalent.
TUCKER, H B. Duke Power Co. 82/08/12. DENTON, H R. Office of Nuclear Reactor Regulation, Director. STOLZ, J F. Operating Reactors Branch 4. 2pp. 14364-218. 24X Fiche: 50-269, 82/08/12, 8208170151.

8208200025 Advises that util response to NRC 820713 ltr re schedule submittal supplemental ECCB calculations utilizing cladding models of NUREQ-0630 will be submitted by 830301.
TUCKER, H B. Duke Power Co. 82/08/12. DENTON, H R. Office of Nuclear Reactor Regulation, Director STOLZ, J F. Operating Reactors Branch 4. 1p 14392-246 24X Fiche: 50-269, 82/08/12, 8208200025.

8208240242 Disagrees w/NRC expectations that all new hires have bachelors degree or equivalent pending new guidance per 820709 ltr & NUREQ-0737, Item I. A. 1.1. "Shift Technical Advisor" & NUREQ-0660
TUCKER, H B. Duke Power Co. 82/08/12. DENTON, H R. Office of Nuclear Reactor Regulation, Director STOLZ, J F. Operating Reactors Branch 4. 2pp 14520-070 24X Fiche: 50-269, 82/08/12, 8208240242.

8208310236 Forwards summary of licensee efforts to resolve NUREQ-0737 Item I I K.3 re revised small break LOCA methods Util will support B&W owners group effort to provide integral sys test data, utilizing CERDA test facility
TUCKER, H B. Duke Power Co. 82/08/23 DENTON, H R. Office of Nuclear Reactor Regulation, Director STOLZ, J F. Operating Reactors Branch 4. 11pp. 14695-096 24X Fiche: 50-269, 82/08/23, 8208310236.

Q Inspection reports, IE Bulletins & correspondence

8208030599 Forwards IE Insp Repts 50-269/82-21, 50-270/82-21 & 50-287/82-21 on 820614-18 No noncompliance noted
LEWIS, R C. Division of Project & Resident Programs. 82/07/09
PARKER, W O. Duke Power Co. 2pp. 14162-313 24X Fiche: 50-269, 82/07/09, 8208030599.

--8208030613 IE Insp Repts 50-269/82-21, 50-270/82-21 & 50-287/82-21 on 820614-18 No noncompliance noted Major areas inspected: review of chemistry & radiochemistry procedures & airborne effluent sampling & accountability.
EVANS, C O. MONTGOMERY, D M. Division of Emergency Preparedness Operational Support 82/07/07 10pp 14162-315. 24X Fiche: 50-269, 82/07/09, 8208030599.

8208030548 Forwards IE Insp Repts 50-269/82-26, 50-270/82-26 & 50-287/82-26 on 820706-09 No noncompliance noted.
DANCE, H C. Division of Project & Resident Programs. 82/07/14.
PARKER, W O. Duke Power Co. 2pp. 14162-096. 24X Fiche: 50-269, 82/07/14, 8208030548

--8208030557 IE Insp Repts 50-269/82-26, 50-270/82-26 & 50-287/82-26 on 820706-09 No noncompliance noted Major areas inspected: followup of extraction steam line rupture
ORDERB, W. PUCKETT, M. KLEINSORGE, W. Division of Project & Resident Programs 82/07/14. 5pp. 14162-098. 24X Fiche: 50-269, 82/07/14, 8208030548

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl.
JORDAN, E L. Division of Engineering & Quality Assurance. 82/07/16. Consolidated Edison Co. of New York. 87pp. 14356-274. 24X Fiche: 50-000, 82/07/16, 8204210393.

8204210395 IE Info Notice 81-26, Part 3, Duppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E L. Division of Engineering & Quality Assurance. 82/07/16. Michigan, Univ. of. 112pp. 14358-001. 24X Fiche: 50-000, 82/07/16, 8204210395.

8204210396 IE Info Notice 82-23, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp. 14381-001. 24X Fiche: 50-000, 82/07/20, 8204210396.

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20. Consolidated Edison Co. of New York. 71pp. 14357-27. 24X Fiche: 50-000, 82/07/20, 8204210397.

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp. 14194-321. 24X Fiche: 50-000, 82/07/22, 8204210398

8208160163 Forwards IE Insp Repts 50-269/82-24, 50-270/82-24 & 50-287/82-21 on 820614-23, No noncompliance noted.
DANCE, H C. Division of Project & Resident Programs. 82/07/22.
PARKER, W O. Duke Power Co. 2pp 14345-069. 24X Fiche: 50-269, 82/07/22, 8208160163.

pressurizer reactor vessel & RCPB pipe
CQLEV, J. L. , ECONOMOS, M. Division of Engineering & Technical
Programs 82/07/19 7pp. 14345 071 24X Fiche 50-269, 82/07/22,
8208160163

B204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in
Vicinity of Drained & Open RCB." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York 122pp 14380 115 24X
Fiche 50-000, 82/07/23, 8204210401

B204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube
Support Pin Failures at Westinghouse PWRs." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York 127pp. 14194 120. 24X
Fiche 50-000, 82/07/23, 8204210402

B204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping
at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26
Consolidated Edison Co. of New York. 121pp 14357 013. 24X
Fiche 50-000, 82/07/26, 8204210403

8208160194 Forwards IE Insp Repts 50-269/82-27, 50-270/82-27 &
50-287/82-27 on 820610-0715 No noncompliance noted
DANCE, H. C. Division of Project & Resident Programs. 82/07/26
PARKER, W. D. Duke Power Co. 2pp 14344 129. 24X
Fiche 50-269, 82/07/26, 8208160194.

--8208160202 IE Insp Repts 50-269/82-27, 50-270/82-27 & 50-287/82-27 on
820610-0715. No noncompliance noted. Major areas inspected
operations safety verification, surveillance testing, station
maint activities & plant trips
ORDERB, W., FALCONER, D., BRYANT, J. Division of Project & Resident
Programs. 82/07/26 11pp 14344 131. 24X Fiche 50-269, 82/07/26,
8208160194.

B208030595 Act receipt of 820716 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-269/82-17,
50-270/82-17 & 50-287/82-17
LEWIS, R. C. Division of Project & Resident Programs. 82/07/27.
PARKER, W. D. Duke Power Co. 1p. 14162 232. 24X
Fiche 50-269, 82/07/27, 8208030595.

--8208030609 Response to NRC 820616 ltr re violations noted in IE Insp
Repts 50-269/82-17, 50-270/82-17 & 50-287/82-17. Corrective
actions, stronger door closure devices will be installed by
820915 & preventive maint program will be re-evaluated.
PARKER, W. D. Duke Power Co. 82/07/16. O'REILLY, J. P. Region 2,
Office of Director. 2pp. 14162 233. 24X Fiche 50-269, 82/07/27,
8208030595.

--8208030618 Forwards IE Insp Repts 50-269/82-17, 50-270/82-17 &
50-287/82-17 on 820510-14 & notice of violation
DANCE, H. C. Division of Project & Resident Programs. 82/06/16.
PARKER, W. D. Duke Power Co. 2pp 14162 235. 24X
Fiche 50-269, 82/07/27, 8208030595.

--8208030629 Notice of violation from Insp on 820510-14.
* Division of Project & Resident Programs. 82/06/16. 1p.
14162: 237. 24X Fiche 50-269, 82/07/27, 8208030595

--8208030636 IE Insp Repts 50-269/82-17, 50-270/82-17 & 50-287/82-17 on
820510-14. Noncompliance noted door providing access to
radiation compacting area found unlocked & positive access
control not in effect
COLLINS, T. R., BARR, K. P. Division of Engineering & Technical
Programs. 82/06/10. 8pp. 14162 238. 24X Fiche 50-269, 82/07/27,
8208030595.

8208160364 Forwards IE Insp Repts 50-269/82-29, 50-270/82-29 &
50-287/82-29 on 820712-16 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 82/07/27
PARKER, W. D. Duke Power Co. 2pp. 14349 041. 24X
Fiche 50-269, 82/07/27, 8208160364

--8208160375 IE Insp Repts 50-269/82-29, 50-270/82-29 & 50-287/82-29 on
820712-16. No noncompliance noted. Major areas inspected:
radiation protection, shipment of radioactive matl, personnel
dosimetry, portable instrument calibr & review of LERs.
COLLINS, T. R., BARR, K. P. Division of Engineering & Technical
Programs. 82/07/23. 6pp. 14349 043. 24X Fiche 50-269, 82/07/27,
8208160364

B204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in
Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28.
Consolidated Edison Co. of New York. 122pp. 14357 146. 24X
Fiche 50-000, 82/07/28, 8204210405.

PUMP
PARKER, W. D. Duke Power Co. 82/07/29. O'REILLY, J. P. Region 2,
Office of Director. 3pp 14346 265. 24X Fiche 50-269, 82/07/29,
8208160291

B204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From
Baffle Water-Jet Impingement." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/09
Consolidated Edison Co. of New York 117pp 14388 201. 24X
Fiche 50-000, 82/08/09, 8204210407

R Periodic operating reports & related correspondence

B208270010 Response to FOIA request for documents detailing collective
dose exposures in 1981 for operating nuclear power plants &
analyzing said info Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A.
Critical Mass Energy Project. 8pp 14679 208. 24X
Fiche 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power
Facilities For CY81." per 10CFR20. 407
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp
14679 216. 24X Fiche 50-000, 82/07/13, 8208270010

--8208270603 Forwards "Statistical Rept of Recorded Personnel Whole Body
Exposures for CY81." per 10CFR20. 407
PARKER, W. D. Duke Power Co. 82/02/25. Office of Management and
Program Analysis. 1p. 14679 340. 24X Fiche 50-000, 82/07/13,
8208270010

--8208270612 "Statistical Rept of Recorded Personnel Whole Body Exposures
for CY81." per 10CFR20. 407
LEWIS, L. Duke Power Co. 82/02/25. 1p. 14679 341. 24X
Fiche 50-000, 82/07/13, 8208270010

B208170087 Forwards monthly operating repts for Jul 1982
TUCKER, H. B. Duke Power Co. 82/08/13. Director's Office, Office
of Inspection and Enforcement. 1p. 14398 149. 24X
Fiche 50-269, 82/08/13, 8208170087.

--8208170091 Monthly operating repts for Jul 1982
REAVIS, J. A. Duke Power Co. 82/08/13. 16pp 14398 150. 24X
Fiche 50-269, 82/08/13, 8208170087.

S Reportable occurrences, LERs & related correspondence

8208120271 Forwards LER 82-009/03L-0. Detailed event analysis encl.
PARKER, W. D. Duke Power Co. 82/07/30. O'REILLY, J. P. Region 2,
Office of Director. 2pp 14326 339. 24X Fiche 50-270, 82/07/30,
8208120271.

--8208120275 LER 82-009/03L-0 on 820616. valve 2FDW-316 would not open
fully. Valve declared inoperable, making emergency feedwater
flowpath 2B inoperable. Apparently caused by valve manual
handwheel being partially shut. Handwheels to be locked open.
KUTZER, J. F. Duke Power Co. 82/07/29. Region 2, Office of
Director. 1p. 14326 337. 24X Fiche 50-270, 82/07/30, 8208120271.

8208160284 RO 270/82-10: on 820722, until informed NRC that upper surge
tank indicator read below Tech Spec min required water
level. Investigation & preparation of rept incomplete. Final
review & rept expected by 820819.
TUCKER, H. B. Duke Power Co. 82/08/05. O'REILLY, J. P. Region 2,
Office of Director. 1p. 14346 261. 24X Fiche 50-270, 82/08/05,
8208160284.

8208270403 Forwards LER 82-010/01T-0. Detailed event analysis encl.
TUCKER, H. B. Duke Power Co. 82/08/13. O'REILLY, J. P. Region 2,
Office of Director. 3pp. 14565 118. 24X Fiche 50-270, 82/08/13,
8208270403

--8208270407 LER 82-010/01T-0 on 820722, while investigating erroneous
instrument readings, upper surge tank water level found to be
less than 5 ft. Caused by stuck suction relief valve on main
feedwater pump 2B. Valve reset. Instrumentation repaired.
PETTY, J. C. Duke Power Co. 82/08/13. Region 2, Office of
Director. 1p. 14565 121. 24X Fiche 50-270, 82/08/13, 8208270403.

F Security, medical, emergency & fire protection plans

B208030405 Forwards accident scenario package consisting of emergency plan exercise scenario, simulation list, emergency plan execution list & radiological data package, in response to NRC B11026 ltr Package withheld (ref 10CFR2 790). SMITH, R. L. Vermont Yankee Nuclear Power Corp. 02/01/21. HAYNES, R. C. Region 1, Philadelphia, Office of the Director (B1/03/01) 2pp 14164 065 24X Fiche 50-271, B2/01/21, B208030405.

B208020187 Releases public version of revised emergency plan implementing procedures FELTON, J. M. Division of Rules and Records. 02/07/13. Document Management Branch. 1p. 14179 046 24X Fiche 50-271, B2/07/13, B208020187.

--B208020188 Forwards public version of revised emergency plan implementing procedures, including Procedures O.P. 3501 re alert, O.P. 3502 re site area emergency & O.P. 3503 re general emergency. Receipt form encl. MARKT, D. I. Vermont Yankee Nuclear Power Corp. 02/06/30. Office of Nuclear Reactor Regulation, Director. 1p. 14179:047 24X Fiche 50-271, B2/07/13, B208020187.

--B208020189 Public version of revised emergency plan implementing procedures, including Procedures O.P. 3501 re alert, O.P. 3502 re site area emergency & O.P. 3503 re general emergency. Receipt form encl. MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 02/06/29. 9pp. 14179 048 24X Fiche 50-271, B2/07/13, B208020187.

B208050440 Forwards IE Safeguards Insp Rept 50-271/B2-10 on B20601-04. No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs. 02/07/16. SINCLAIR, J. B. Yankee Atomic Electric Co. 2pp 14218 006 24X Fiche 50-271, B2/07/16, B208050440.

--B208050469 IE Safeguards Insp Rept 50-271/B2-10 on B20601-04 No noncompliance noted. Major areas inspected: security plan & implementing procedures; security organization testing & sys supply. Details withheld (ref 10CFR73.21). SMITH, O. H. DUNLAP, J. M. Region 1, Office of Director. 00DY, A. T. Division of Engineering & Technical Programs. 02/07/09. 1p. 14218 008 24X Fiche 50-271, B2/07/16, B208050440.

B208050264 Forwards IE Emergency Preparedness Appraisal Rept 50-271/B2-05 on B20316-24 & emergency preparedness findings & improvement items. SMITH, O. H. Division of Emergency Preparedness & Operational Support. 02/07/22. JACKSON, E. W. Vermont Yankee Nuclear Power Corp. 32pp. 14210 001 24X Fiche 50-271, B2/07/22, B208050264.

--B208050269 IE Emergency Preparedness Appraisal Rept 50-271/B2-05 on B20316-24 Deficiencies noted: augmentation goals of NUREG-0654 not met & post-accident sampling deficient. MCKENNA, T. J. EP Licensing Branch. MOJTA, M. T. Division of Project & Resident Programs. 02/06/30. 62pp. 14210 033. 24X Fiche: 50-271, B2/07/22, B208050264.

B208090116 Confirmatory Action Ltr B2-13 informing NRC of corrective & preventive actions. Request for extension to B20930 granted to complete incorporation of comments of VT state officials into new procedures. SMITH, O. H. Division of Emergency Preparedness & Operational Support. 02/07/30. SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 1p. 14269:322. 24X Fiche 50-271, B2/07/30, B208090116.

--B208090120 Requests extension to B20930 in order to further revise procedures & retrain operators. Procedures were initially revised on B20602. Necessary operator training initiated. CONWAY, W. F. Vermont Yankee Nuclear Power Corp. 02/07/16. HAYNES, R. C. Region 1, Office of Director. 1p. 14269:323. 24X Fiche: 50-271, B2/07/30, B208090116.

B208300074 Grants extension requested in util B20819 response to NRC B20722 ltr re IE Emergency Preparedness Appraisal Insp Rept 50-271/B2-05, Apps A & B. SMITH, O. H. Division of Emergency Preparedness & Operational Support. 02/08/25. SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 1p. 14598 302. 24X Fiche: 50-271, B2/08/25, B208300074.

--B208300078 Requests extension to respond to B20722 IE Emergency Preparedness Appraisal Insp Rept 50-271/B2-05, Apps A & B. Requested info will be submitted by B20907. SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 02/08/19. SMITH, O. H. Division of Emergency Preparedness & Operational Support. 1p. 14598:303. 24X Fiche: 50-271, B2/08/25, B208300074.

B207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Bvc list encl. DIRCKS, W. J. Office of the Executive Director for Operations. 02/07/02. Consolidated Edison Co. of New York. 93pp. 14194:001. 24X Fiche 50-000, B2/07/02, B207080064.

B208050061 Forwards safety evaluation of util B20103 response to NUREG-0737, Item 11, K.3 24, "Adequacy of Space Cooling for HPCI & Reactor Core Isolation Cooling Sys." Item resolved. VASSALLO, D. B. Operating Reactors Branch 2. 02/07/27. SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 3pp. 14244:052. 24X Fiche: 50-271, B2/07/27, B208050061.

B208240160 Requests addl info, verifying satisfaction of encl acceptance criteria re NUREG-0737, Item 11, K.3 22, "Automatic Switchover of Reactor Core Isolation Cooling Sys Suction." Response requested within 30 days. VASSALLO, D. B. Operating Reactors Branch 2. 02/08/05. SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 4pp. 14548:173. 24X Fiche: 50-271, B2/08/05, B208240160.

B208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter 1 requirements & provides alternatives to requirements Bvc list encl. EISENHUT, D. G. Division of Licensing. 02/08/09. Consolidated Edison Co. of New York. 1p. 14356:332. 24X Fiche: 50-000, B2/08/09, B208090194.

B208160193 Ack receipt of B20630 ltr informing of results of iodine plate-out test, in response to NRC B20428 ltr. Evaluation of amount of sample lost resulting from iodine plate-out will be submitted within 45 days of receipt of ltr. SMITH, O. H. Division of Emergency Preparedness & Operational Support. 02/08/09. SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 2pp. 14342:354. 24X Fiche: 50-271, B2/08/09, B208160193.

B208260514 Forwards request for addl info re util proposal to extend operation w/ presently installed feedwater spargers beyond 1983 refueling outage. VASSALLO, D. B. Operating Reactors Branch 2. 02/08/10. SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 9pp. 14579:281. 24X Fiche: 50-271, B2/08/10, B208260514.

B208240269 Releases reactor noise data tapes from Mar 1981 stability test to NRC & ORNL per agreement reached at B20813 meeting w/ NRC. Affidavit supporting proprietary nature of info encl. PFEFFERLEN, H. C. General Electric Co. 02/08/13. BERLINER, C. H. Core Performance Branch. 5pp. 14526:118. 24X Fiche: 50-271, B2/08/13, B208240269.

B208230165 Application to amend License DPR-28, revising Tech Spec Page 180-01 re max critical power ratio to reflect changes based on methodology per util B20331 ltr. HEIDER, L. H. Vermont Yankee Nuclear Power Corp. 02/08/19. Office of Nuclear Reactor Regulation, Director. 3pp. 14514:322. 24X Fiche: 50-271, B2/08/19, B208230165.

--B208230170 Tech Spec Table 3.11-2 re max critical power ratio operating limits. Update to core performance analysis rept, YAE-1273, encl. Vermont Yankee Nuclear Power Corp. 02/08/19. 9pp. 14514:325. 24X Fiche: 50-271, B2/08/19, B208230165.

B208270393 Advises that plant unique analysis for Mark I containment effort will be submitted by B20917. SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 02/08/23. VASSALLO, D. B. Operating Reactors Branch 2. 1p. 14565:008. 24X Fiche: 50-271, B2/08/23, B208270393.

G Inspection reports, IE Bulletins & correspondence

B204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MSIV) Leakage." Bvc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 02/07/16. Consolidated Edison Co. of New York. 87pp. 14356:274. 24X Fiche: 50-000, B2/07/16, B204210393.

B208050440 Forwards IE Safeguards Insp Rept 50-271/B2-10 on B20601-04. No noncompliance noted. MARTIN, T. T. Division of Engineering & Technical Programs. 02/07/16. SINCLAIR, J. B. Yankee Atomic Electric Co. 2pp. 14218:006. 24X Fiche: 50-271, B2/07/16, B208050440.

--8208030469 IE Safeguards Insp Rept 50-271/82-10 on 820601-04 No noncompliance noted Major areas inspected security plan & implementing procedures, security organization testing & sys supply. Details withheld (ref 10CFR73.21)
SMITH, O. H. DUNLAP, J. M. Region 1, Office of Director 000Y, A T
Division of Engineering & Technical Programs 82/07/09 1p
14218 008 24X Fiche 50-271.82/07/16.8208050440

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/19
Michigan, Univ of 112pp 14358 001 24X Fiche 50-000.82/07/19.
8204210395.

8204210396 IE Info Notice 82-25. "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20
Consolidated Edison Co. of New York 112pp 14381 001 24X
Fiche 50-000.82/07/20.8204210396

8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards.
82/07/20 Consolidated Edison Co. of New York. 71pp. 14357 276
24X Fiche 50-000.82/07/20.8204210397

8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22
Consolidated Edison Co. of New York. 112pp 14194 321. 24X
Fiche 50-000.82/07/22.8204210398

8208050264 Forwards IE Emergency Preparedness Appraisal Rept 50-271/82-05 on 820316-24 & emergency preparedness findings & improvement items
SMITH, O. H. Division of Emergency Preparedness & Operational Support 82/07/22. JACKSON, E. W. Vermont Yankee Nuclear Power Corp. 32pp.
14210 001 24X Fiche 50-271.82/07/22.8208050264.

--8208050269 IE Emergency Preparedness Appraisal Rept 50-271/82-05 on 820316-24. Deficiencies noted augmentation goals of NUREG-0654 not met & post-accident sampling deficient
MCKENNA, T. J. EP Licensing Branch HQJTA, M. T. Division of Project & Resident Programs 82/06/30 62pp 14210 033 24X
Fiche 50-271.82/07/22.8208050264

8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co. of New York 122pp 14380 115 24X
Fiche 50-000.82/07/23.8204210401

8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHRs." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23
Consolidated Edison Co. of New York 127pp 14194 120. 24X
Fiche 50-000.82/07/23.8204210402

8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PHR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26
Consolidated Edison Co. of New York. 121pp. 14357 013 24X
Fiche 50-000.82/07/26.8204210403.

8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28
Consolidated Edison Co. of New York. 122pp 14357 146. 24X
Fiche 50-000.82/07/28.8204210405

8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/05.
Consolidated Edison Co. of New York 117pp. 14388 201 24X
Fiche 50-000.82/08/05.8204210407.

8208030074 Grants extension requested in util 820819 response to NRC 820722 ltr re IE Emergency Preparedness Appraisal Insp Rept 50-271/82-05, Apps A & B
SMITH, O. H. Division of Emergency Preparedness & Operational Support. 82/08/25
SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 1p.
14598 302. 24X Fiche 50-271.82/08/25.8208030074

--8208030078 Requests extension to respond to 820722 IE Emergency Preparedness Appraisal Insp Rept 50-271/82-05, Apps A & B Requested info will be submitted by 820907
SINCLAIR, J. B. Vermont Yankee Nuclear Power Corp. 82/08/19.
SMITH, O. H. Division of Emergency Preparedness & Operational Support. 1p. 14598 303. 24X Fiche 50-271.82/08/25.8208030074.

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records 82/07/13. UDELL, R. A
Critical Mass Energy Project. 8pp 14679 208. 24X
Fiche 50-000.82/07/13.8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81"
NRC - No Detailed Affiliation Given 82/07/13 48pp
14679 216 24X Fiche 50-000.82/07/13.8208270010

--8208270569 Forwards whole body range rept for CY81 per 10CFR20.407.
SMITH, R. L. Vermont Yankee Nuclear Power Corp 82/02/22
HALLER, N. M. Office of Management and Program Analysis. 1p
14679 316 24X Fiche 50-000.82/07/13.8208270010

--8208270573 Whole body range rept for CY81
Vermont Yankee Nuclear Power Corp 82/02/22. 1p. 14679 317
24X Fiche 50-000.82/07/13.8208270010

8208170194 Forwards monthly operating rept for Jul 1982.
JACKSON, E. W. Vermont Yankee Nuclear Power Corp 82/08/13
Division of Data Automation & Management Information 1p
14366 275 24X Fiche 50-271.82/08/13.8208170194

--8208170196 Monthly operating rept for Jul 1982
BURGER, F. J. Vermont Yankee Nuclear Power Corp. 82/08/13 6pp
14366 276. 24X Fiche 50-271.82/08/13.8208170194.

G Reportable occurrences, LERs & related correspondence

8208050259 Forwards LER 82-016/03L-0
MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 82/07/22
HAYNES, R. C. Region 1, Office of Director. 1p 14210 104. 24X
Fiche 50-271.82/07/22.8208050259

--8208050263 LER 82-016/03L-0 on 820622, primary containment isolation valves were cycled on cold shutdown per surveillance procedure contrary to Tech Specs Caused by failure to address proper surveillance requirement
MURPHY, W. P. Vermont Yankee Nuclear Power Corp. 82/07/22
Region 1, Office of Director 2pp 14210 105 24X
Fiche 50-271.82/07/22.8208050259.

U. Congressional/Executive Correspondence

8208100370 Responds to 820621 ltr re alleged conditions near facility. Airborne & waterborne radioactivity monitoring programs discussed. No reason exists to believe that there is any radiological impact on environ from operation of facility.
DIRCKS, W. J. Office of the Executive Director for Operations. 82/07/19. HUMPHREY, O. J. Senate. 5pp 14308 331. 24X
Fiche 50-271.82/07/19.8208100370

--8206200030 Requests response to encl magazine article from constituent re alleged cancer rate increase & agricultural abnormalities in vicinity of plant.
HUMPHREY, O. J. Senate 82/06/21 PALLADINO, N. J. Commissioners. 12pp. 14308 335. 24X Fiche 50-271.82/07/19.8208100370.

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

P. Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CRQR. Svc list encl.
DIRCKS, W. J. Office of the Executive Director for Operations 82/07/02. Consolidated Edison Co. of New York. 92pp. 14194 001. 24X Fiche 50-000.82/07/02.8207080064.

8208030101 Requests submittal documenting compliance w/criteria in NUREG-0737, Item II, B.3, "Post-Accident Sampling Eye"
Criteria & guidelines to conduct NRC review encl.
VARQA, S. A. Operating Reactors Branch 1. 82/07/12. UDERITZ, R. A
Public Service Electric & Gas Co. of New Jersey. 10pp. 14196 354. 24X Fiche 50-272.82/07/12.8208030101

8208060021 Notification of 820726 meeting in Hancocks Bridge, NJ to review component faulting problems associated w/maintenance of American oysters & review status of ETS.
ROSS, W. J. Operating Reactors Branch 1. 82/07/19. VARQA, S. A.
Operating Reactors Branch 1. 2pp. 14244 354. 24X
Fiche 50-272.82/07/19.8208060021.

--B208040458 Amends 45 & 10 to Licenses DPR-70 & DPR-75, respectively, providing undervoltage protection to emergency safety features actuation instrumentation sys
VARQA, S A Operating Reactors Branch 1 82/07/23 12pp
14220 265 24X Fiche 50-272, 82/07/23, B208040453

--B208040461 Safety evaluation supporting Amends 45 & 10 to Licenses DPR-70 & DPR-75, respectively
* Office of Nuclear Reactor Regulation, Director 82/07/23 2pp
14220 277 24X Fiche 50-272, 82/07/23, B208040453

--B208040464 Notice of issuance & availability of Amends 45 & 10 to Licenses DPR-70 & DPR-75, respectively
VARQA, S A Operating Reactors Branch 1 82/07/23 2pp
14220 279 24X Fiche 50-272, 82/07/23, B208040453

B208110096 Advises that shift supervisor - engineer considered to be acceptable equivalent to shift technical advisor, per util
B20616 request Tech Spec should be revised accordingly
VARQA, S A Operating Reactors Branch 1 82/07/29 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 2pp 14329 361
24X Fiche 50-272, 82/07/29, B208110096

B208190189 Forwards "Salem Nuclear Generating Station Unit 1, Cycle 4 Startup Test Rept"
LIDEN, E A Public Service Electric & Gas Co of New Jersey
82/08/03 HAYNES, R C Region I, Office of Director 1p
14387 007 24X Fiche 50-272, 82/08/03, B208190189

--B208190194 "Salem Nuclear Generating Station Unit 1, Cycle 4 Startup Test Rept"
JACKSON, J. CHILLEA, L K, ROSENFELD, E S Public Service Electric & Gas Co of New Jersey 82/08/03 31pp 14387 008 24X
Fiche 50-272, 82/08/03, B208190189

B208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Bureaus 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl
EISENHUT, D O Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14356 332 24X Fiche 50-000, 82/08/09, B208090194

B208250198 Responds to NRC B20712 ltr re post-accident sampling/post-implementation review Post-accident sampling sys for each unit expected to be installed & operational prior to startup following upcoming refueling outage
LIDEN, E A Public Service Electric & Gas Co of New Jersey 82/08/13 VARQA, S A Operating Reactors Branch 1 1p 14341 330 24X Fiche 50-272, 82/08/13, B208250198

B208250097 Forwards summary of responses to NRC B20720 request for addl info re auxiliary feedwater pump endurance test, as discussed in B20818 conference call
LIDEN, E A Public Service Electric & Gas Co of New Jersey 82/08/18 VARQA, S A Operating Reactors Branch 1 2pp 14340 349 24X Fiche 50-272, 82/08/18, B208250097

0 Inspection reports, IE Bulletins & correspondence

B204210293 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/16, Consolidated Edison Co of New York 87pp 14356 274 24X
Fiche 50-000, 82/07/16, B204210293

B204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/19 Michigan, Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, B204210395

B204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co of New York 112pp 14381 001 24X
Fiche 50-000, 82/07/20, B204210396

B204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl
COBB, L I Division of Fuel Facilities, Materials & Safeguards 82/07/20 Consolidated Edison Co of New York 71pp 14357 276 24X Fiche 50-000, 82/07/20, B204210397

B204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/22, Consolidated Edison Co of New York 112pp 14194 321 24X
Fiche 50-000, 82/07/22, B204210398

B204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/23, Consolidated Edison Co of New York 122pp 14380 115 24X
Fiche 50-000, 82/07/23, B204210401

B204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/23, Consolidated Edison Co of New York 127pp 14194 120 24X
Fiche 50-000, 82/07/23, B204210402

B204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/26, Consolidated Edison Co of New York 121pp 14387 013 24X
Fiche 50-000, 82/07/26, B204210403

B208020112 Responds to B20420 request for addl info on postulated main steam line break inside containment (IE Bulletin B0-04). Addl analysis beyond design basis not necessary.
LIDEN, E A Public Service Electric & Gas Co of New Jersey 82/07/26 VARQA, S A Operating Reactors Branch 1 2pp 14142 106 24X Fiche 50-000, 82/07/26, B208020112

B204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/28, Consolidated Edison Co of New York 122pp 14357 146 24X
Fiche 50-000, 82/07/28, B204210405

B208100162 Responds to Action Item 1 of IE Bulletin 82-02 re degradation of threaded fasteners in RCPB of PWR plants. All work performed within confines of RCPB is accomplished per approved written maint procedures & vendor manuals
LIDEN, E A Public Service Electric & Gas Co of New Jersey 82/07/29 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 14298 030 24X Fiche 50-272, 82/07/29, B208100162

B204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Fuel Water-Jet Impingement." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/08/05, Consolidated Edison Co of New York 117pp 14388 201 24X
Fiche 50-000, 82/08/05, B204210407

B208160068 Forwards fourth rept of exams & surveillances re integrity of piping sys containing stagnant boric water, per IE Circular 76-06.
LIDEN, E A Public Service Electric & Gas Co of New Jersey 82/08/09 HAYNES, R C Region I, Office of Director 3pp 14342 036 24X Fiche 50-272, 82/08/09, B208160068

B208300300 Forwards IE Insp Repts 50-272/82-17 & 50-311/82-17 on B20707-0803 & notice of violation.
STAROSTECKI, R Division of Project & Resident Programs 82/08/12 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 14673 201 24X Fiche 50-272, 82/08/12, B208300300

--B208300313 Notice of violation from Insp on B20707-0803.
STAROSTECKI, R Division of Project & Resident Programs 82/08/12 2pp 14673 203 24X Fiche 50-272, 82/08/12, B208300300

--B208300317 IE Insp Repts 50-272/82-17 & 50-311/82-17 on B20707-0803. Noncompliance noted: no incident rept prepared for failure of vital ventilation control ctr feeder breaker IC on B20623.
NORRHL, J. SUMMERB, R., TRIPP, L E Division of Project & Resident Programs 82/08/10 13pp 14673 205 24X Fiche 50-272, 82/08/12, B208300300

B208310358 Ack receipt of B20804 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-272/82-14 & 50-311/82-14.
STAROSTECKI, R Division of Project & Resident Programs 82/08/26 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 1p 14692 123 24X Fiche 50-272, 82/08/26, B208310358

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records 82/07/13 UDELL, R. A. Critical Mass Energy Project Bpp 14679 208 24X
Fiche: 50-000, 82/07/13, 8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13 48pp
14679: 216 24X Fiche: 50-000, 82/07/13, 8208270010.

--8208270176 Forwards, "Annual Wholebody Exposures for CY81." per 10CFR20.407
ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey
82/01/29. Office of Management and Program Analysis. 2pp
14679: 269 24X Fiche: 50-000, 82/07/13, 8208270010

--8208270586 Forwards errata to "Number Personnel & Man Rem by Job Function Rept for CY81." personnel exposures
ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey
82/02/23 HAYNES, R. C. Region 1, Office of Director 2pp
14679: 320 24X Fiche: 50-000, 82/07/13, 8208270010

--8208270589 Errata to "Number Personnel & Man Rem by Job Function Rept for CY81."
* Public Service Electric & Gas Co. of New Jersey 82/02/23
4pp. 14679: 322 24X Fiche: 50-000, 82/07/13, 8208270010

--8208270701 "Annual Whole Body Exposures for CY81."
* Public Service Electric & Gas Co. of New Jersey. 82/01/29. 1p.
14679: 270 24X Fiche: 50-000, 82/07/13, 8208270010.

8208160048 Forwards monthly operating rept for Unit 2 for Jul 1982. Also forwards corrected monthly operating repts for Unit 1 for Mar, Apr, May & June 1982.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
82/08/10 Director's Office, Office of Inspection and Enforcement. 1p. 14344: 233. 24X Fiche: 50-272, 82/08/10, 8208160048.

--8208160049 Monthly operating rept for Jul 1982
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey.
82/08/10. 23pp. 14344: 234. 24X Fiche: 50-272, 82/08/10, 8208160048

--8208160051 Corrected monthly operating rept for Mar 1982
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey.
82/04/18 1p. 14344: 257 24X Fiche: 50-272, 82/08/10, 8208160048.

--8208160053 Corrected monthly operating rept for Apr 1982.
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey.
82/05/10. 1p. 14344: 258. 24X Fiche: 50-272, 82/08/10, 8208160048.

--8208160055 Corrected monthly operating rept for May 1982.
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey.
82/06/10. 1p. 14344: 259. 24X Fiche: 50-272, 82/08/10, 8208160048.

--8208160056 Corrected monthly operating rept for June 1982.
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey.
82/07/10. 1p. 14344: 260 24X Fiche: 50-272, 82/08/10, 8208160048.

8208160085 Forwards monthly operating rept for Jul 1982.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
82/08/10. Director's Office, Office of Inspection and Enforcement. 1p. 14342: 073. 24X Fiche: 50-272, 82/08/10, 8208160085.

--8208160089 Monthly operating rept for Jul 1982.
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey
82/08/10. 25pp. 14342: 074. 24X Fiche: 50-272, 82/08/10, 8208160085.

8208300217 Forwards NPDES discharge monitoring repts for Jul 1982.
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey.
82/08/18. BAKER, R. A. Environmental Protection Agency. 2pp.
14679: 010. 24X Fiche: 50-272, 82/08/18, 8208300217.

--8208300219 NPDES discharge monitoring repts for Jul 1982.
MILLER, L. K. Public Service Electric & Gas Co. of New Jersey.
82/08/18. 17pp. 14679: 012. 24X Fiche: 50-272, 82/08/18, 8208300217.

--8208020141 LER 82-049/03X-1 on 820703, flow control valve 126W127 was not open. Caused by married valve tube bundle. Tube bundle cut back to allow free movement. Design change request implemented. Valve 126W127 replaced w/new design.
HELLER, R. Public Service Electric & Gas Co. of New Jersey.
82/07/21. Region 1, Office of Director. 1p. 14142: 040 24X
Fiche: 50-272, 82/07/21, 8208020137

8208020315 Forwards LER 82-041/03L-0 Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
82/07/21. HAYNES, R. C. Region 1, Office of Director. 4pp
14151: 123 24X Fiche: 50-272, 82/07/21, 8208020315.

--8208020327 LER 82-041/03L-0 on 820626, during routine insp, water discovered in charging pump 12 gear oil reservoir. Caused by leak through gear oil cooler. Cooler & oil replaced.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
82/07/21. Region 1, Office of Director. 1p. 14151: 127. 24X
Fiche: 50-272, 82/07/21, 8208020315

8208050335 Forwards LER 82-005/01X-1 Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
82/07/21. HAYNES, R. C. Region 1, Office of Director. 3pp.
14219: 331. 24X Fiche: 50-272, 82/07/21, 8208050335.

--8208050344 LER 82-005/01X-1 on 820131, degradation of fuel cladding fuel assembly C-04 discovered. Caused by fuel lockup due to wedged fuel pellet. Fuel assembly placed in spent fuel pit. All C assemblies scheduled for reuse in core.
HELLER, R. Public Service Electric & Gas Co. of New Jersey.
82/07/21. Region 1, Office of Director. 1p. 14219: 334 24X
Fiche: 50-272, 82/07/21, 8208050335.

8208050492 Forwards LER 82-042/03L-0 Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
82/07/21. HAYNES, R. C. Region 1, Office of Director. 3pp.
14214: 105. 24X Fiche: 50-272, 82/07/21, 8208050492.

--8208050509 LER 82-042/03L-0 on 820628, valves discovered open & not properly locked. Caused by improperly locked valve upon completion of valve position verifications. Review of incident incorporated into safety tagging training program.
HELLER, R. Public Service Electric & Gas Co. of New Jersey.
82/07/21. Region 1, Office of Director. 1p. 14214: 108. 24X
Fiche: 50-272, 82/07/21, 8208050492

8208100010 Forwards LER 82-046/03L-0 Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
82/07/28. HAYNES, R. C. Region 1, Office of Director. 3pp.
14294: 287. 24X Fiche: 50-272, 82/07/28, 8208100010.

--8208100018 LER 82-046/03L-0 on 820712, two floor penetrations in core room found to be nonfunctional & not included in surveillance. Caused by penetrations being left open at time of installation. Openings sealed.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
82/07/28. Region 1, Office of Director. 1p. 14294: 290. 24X
Fiche: 50-272, 82/07/28, 8208100010

8208100079 Forwards LER 82-045/03L-0 Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
82/07/28. HAYNES, R. C. Region 1, Office of Director. 3pp.
14297: 286. 24X Fiche: 50-272, 82/07/28, 8208100079.

--8208100086 LER 82-045/03L-0 on 820710, sample from waste monitor tank discarded before composite analysis could be performed. Caused by technician error. Sample from similar release doubled composited.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
82/07/28. Region 1, Office of Director. 1p. 14297: 289 24X
Fiche: 50-272, 82/07/28, 8208100079.

8208130113 Forwards LER 81-060/99X-1 Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
82/07/28. HAYNES, R. C. Region 1, Office of Director. 3pp.
14333: 268 24X Fiche: 50-272, 82/07/28, 8208130113.

--8208130117 LER 81-060/99X-1 on 810611, diesel fire suppression pump failed to start in automatic mode. Caused by shearing off of drive shaft counterweight gear. Shaft replaced.
HELLER, R. Public Service Electric & Gas Co. of New Jersey.
82/07/28. Region 1, Office of Director. 1p. 14333: 271. 24X
Fiche: 50-272, 82/07/28, 8208130113.

DOCKETED ITEMS

8208130249 Forwards LER 82-043/03L-0 Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
82/07/28. HAYNES, R. C. Region 1, Office of Director. 3pp.
14333:110. 24X Fiche: 50-272, 82/07/28, 8208130249

--8208130253 LER 82-043/03L-0 on 820704, control room operator received
air particulate detector trouble alarm on Panel 1RPI. Caused
by exhausted filter paper supply roll due to increased use
of paper from clearing filter in fast mode Roll replaced.
HELLER, R. Public Service Electric & Gas Co. of New Jersey
82/07/28. Region 1, Office of Director. 1p. 14333:113. 24X
Fiche: 50-272, 82/07/28, 8208130249

8208060327 Forwards incident reporting sys repts re spill of
contaminated water & contamination of personnel in auxiliary
bldg & failure of control rod guide tube support pins for
transmission to NEA
MICHELSON, C. Director's Office. 82/07/29. LAFLEUR, J. D. Office of
International Programs, Director. 17pp. 14281:234. 24X
Fiche: 50-000, 82/07/29, 8208060327

8208180071 Forwards LER 82-050/03L-0 Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey
82/08/06. HAYNES, R. C. Region 1, Office of Director. 3pp.
14376:351. 24X Fiche: 50-272, 82/08/06, 8208180071

--8208180080 LER 82-050/03L-0 on 820710, Atlantic loggerhead turtle
impinged on circulating water sys intake trash bar. Turtle
dead when collected. Sys circulates large amounts of river
water & dead/damaged turtles can easily be impinged.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
82/08/06. Region 1, Office of Director. 1p. 14376:354. 24X
Fiche: 50-272, 82/08/06, 8208180071

8208260148 Forwards LER 81-053/03X-1 Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
82/08/12. HAYNES, R. C. Region 1, Office of Director. 3pp.
14555:345. 24X Fiche: 50-272, 82/08/12, 8208260148

--8208260153 LER 81-053/03X-1 on 810520, diesel generator 1B 1/4-inch
nipple on water jacket discovered leaking. Caused by
personnel using nipple for support. Nipple replaced &
generator tested.
HELLER, R. Public Service Electric & Gas Co. of New Jersey.
82/08/12. Region 1, Office of Director. 1p. 14555:348. 24X
Fiche: 50-272, 82/08/12, 8208260148

8208260252 Forwards LER 82-047/03L-0 Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
82/08/12. HAYNES, R. C. Region 1, Office of Director. 3pp.
14554:293. 24X Fiche: 50-272, 82/08/12, 8208260252

--8208260261 LER 82-047/03L-0 on 820726, containment plant vent monitor
sample pump found de-energized & failed to start. Supply
breaker found tripped. Cause undetermined. Breaker reset &
closed & pump successfully started from control room.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
82/08/12. Region 1, Office of Director. 1p. 14554:296. 24X
Fiche: 50-272, 82/08/12, 8208260252

8208260320 Forwards LER 82-049/03L-0 Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
82/08/12. HAYNES, R. C. Region 1, Office of Director. 3pp.
14555:352. 24X Fiche: 50-272, 82/08/12, 8208260320

--8208260323 LER 82-049/03L-0 on 820724, hot leg pressure wide range
instrument indication read lower than actual RCB pressure.
Caused by failed printed circuit board in pressure
transmitter. Circuit board replaced & channel recalibr.
FRAHM, R. Public Service Electric & Gas Co. of New Jersey.
82/08/12. Region 1, Office of Director. 1p. 14555:355. 24X
Fiche: 50-272, 82/08/12, 8208260320

8208310285 Forwards LER 82-048/03L-0 Detailed event analysis encl.
MIDURA, H. J. Public Service Electric & Gas Co. of New Jersey.
82/08/12. HAYNES, R. C. Region 1, Office of Director. 3pp.
14688:269. 24X Fiche: 50-272, 82/08/12, 8208310285

--8208310287 LER 82-048/03L-0 on 820724, inner door seal leakage of 100 ft
elevation containment air lock door greater than Tech Spec.
Caused by personnel closing door w/excessive force. Seal
replaced & personnel trained in proper door closing.
HELLER, R. Public Service Electric & Gas Co. of New Jersey.
82/08/12. Region 1, Office of Director. 1p. 14688:272. 24X
Fiche: 50-272, 82/08/12, 8208310285

DOCKET 50-274 U. S. GEOLOGICAL SURVEY RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl. 1, "Clarification
Placement of Personnel Monitoring Devices for External
Radiation" Bvc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 02A
Michigan, Univ. of. 112pp. 1435B:001. 24X Fiche: 50-000, 02A
8204210395

8208130209 Forwards IE Safeguards Insp Rept 50-274/82-02 on U20A
No noncompliance noted. Encl withheld (ref 10CFR790)
HADSEN, O. L. Division of Resident, Reactor Project & Engineering
Programs. 82/08/10. MILLARD, H. Interior, Dept of, Geological
Survey. 2pp. 14333:001. 24X Fiche: 50-274, 82/08/10, 8208130209

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8208310105 Forwards IE Emergency Preparedness Appraisal Repts
50-275/81-33 & 50-323/81-19 on 811207-17.
ENGELKEN, R. H. Region 5, Office of Director. 02/07/08. CRANE,
Pacific Gas & Electric Co. 2pp. 14689:319. 24X
Fiche: 50-275, 82/07/08, 8208310105.

--8208310113 IE Emergency Preparedness Appraisal Repts 50-275/81-
& 50-323/81-19 on 811207-17. Deficiencies noted: equipment,
emergency plan implementing procedures & coordination w/
offsite groups.
FISH, R. F., SCOWEN, K. Region 5, Office of Director. 02/07/07
3pp. 14689:325. 24X Fiche: 50-275, 82/07/08, 8208310105.

8208040527 Approves changes to physical security plan w/exception
items listed in encl. in response to 820527 ltr. Revised pages
to plan requested within 45 days of receipt of ltr.
MIRASOLIA, F. J. Licensing Branch 3. 82/07/30. CRANE, P. Pacific
& Electric Co. 2pp. 14220:344. 24X Fiche: 50-275, 82/07/30,
8208040527.

8208110266 Releases public version of emergency plan implementing
procedures.
FELTON, J. M. Division of Rules and Records. 02/08/05. Docu-
Management Branch. 1p. 14331:151. 24X Fiche: 50-275, 82/08/05,
8208110266.

--8208110269 Forwards public version of Vols 3A & 3B of emergency
implementing procedures, including Procedures EP OP-14 re
high activity in RCB, OP-23 re natural circulation of
reactor coolant & EP R-1 re employee injury (radiological).
GOLESBY, D. A. Pacific Gas & Electric Co. 82/07/29. ENGELKEN,
Region 5, Office of Director. 4pp. 14331:152. 24X
Fiche: 50-275, 82/08/05, 8208110266.

--8208110275 Public version of Vols 3A & 3B of emergency plan
implementing procedures, including Procedures EP OP-14 re
high activity in RCB, OP-23 re natural circulation of reactor
coolant & EP R-1 re employee injury (radiological).
Pacific Gas & Electric Co. 82/04/11. 180pp. 14331:156.
Fiche: 50-275, 82/08/05, 8208110266.

8208230019 Forwards Attachments A & B re changes implemented to
Revision 11 of security plan. Attachment A identifies &
describes changes & B consists of replacement pages. Encls
withheld (ref 10CFR73.21).
CRANE, P. A. Pacific Gas & Electric Co. 82/08/12. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 1p. 14517:22.
Fiche: 50-275, 82/08/12, 8208230019.

0. Adjudicatory correspondence

8204300352 Order CLI-82-7 deciding that definition of "several"
not warrant Commission review in context of proceeding.
Commission will re-evaluate design basis threat generically.
CHILK, B. J. Office of the Secretary of the Commission. 82/04/
Commissioners. 4pp. 14380:111. 24X Fiche: 50-275, 82/04/22,
8204300352.

8208020317 Order directing all copies of Order ALAB-655 be returned
since order contains classified natl security info. NRC will
direct parties to return parts of underlying record which
contains such info.
CHILK, B. J. Office of the Secretary of the Commission. 82/07/
Commissioners. 2pp. 14151:130. 24X Fiche: 50-275, 82/07/29,
8208020317.

8208030275 Order CLF-82-19 releasing public versions of ALAB-453 & Governor Brown 811013 petition for review of ALAB-453
Meaning of "several" as used in design basis threat of 10CFR73.1(a)(1) is safeguards info
HOYLE, J. C. Office of the Secretary of the Commission 82/07/30 2pp. 14199:356 24X Fiche 50-275.82/07/30.8208030275

--8208030280 Public version of petition for review of ALAB-453 Decision is of first impression re meaning of Part 73 in contested proceeding & raises important & critical questions of law, fact & policy w/ Certificate of Svc
BROWN, H. H. California, State of BROWN, H. H. Hill, Christopher & Phillips 81/10/13 Commissioners. 13pp 14196:161. 24X Fiche 50-275.82/07/30.8208030275

8208050338 Comments on Teledyne Engineering Svcs 820618 Phase II Program Mgt Plan per Commission invitation Commission should require listed specific changes to audit program
REYNOLDS, J. R., FLEISCHAKER, D. Center for Law in the Public Interest
REYNOLDS, J. R. Joint Intervenor-Diablo Canyon 82/08/02
PALLADINO, N. J., GILINSKY, V., AHEARNE, J. Commissioners 5pp. 14219:344. 24X Fiche 50-275.82/08/02.8208050338

8208050538 Motion to reopen proceeding to take evidence on QA ASLB does not have info re implementation of QA program
Certificate of Svc encl
BROWN, H. H. California, State of BROWN, H. H. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 82/08/02 Atomic Safety and Licensing Board Panel 13pp. 14213:288 24X Fiche: 50-275.82/08/02.8208050538

8208110148 Order granting extension until 820831 to comment on effect of expunction of classified matl from ALAB-453 & underlying record.
CHILK, B. J. Office of the Secretary of the Commission. 82/08/09 California, State of 1p. 14314:294 24X Fiche: 50-275.82/08/09.8208110148

8208190139 Response opposing Governor Brown 820802 motion to reopen record to take evidence on QA Commission 811119 action leaves ASLB w/o jurisdiction to grant requested relief.
Certificate of Svc encl
NORTON, B. Pacific Gas & Electric Co. NORTON, B. Norton, Burkr, Berry & French 82/08/16 Atomic Safety and Licensing Board Panel 25pp. 14382:190 24X Fiche: 50-275.82/08/16.8208190139

--8208190142 Affidavit of HB Friend re independent design verification program. Prof qualifications encl.
FRIEND, H. B. Pacific Gas & Electric Co. 82/08/13. 8pp. 14382:215 24X Fiche: 50-275.82/08/16.8208190139

8208200250 Request for hearing on util 820803 application for amend to License DPR-76, which could renew low power license granted on 810921 & suspended on 811119 Certificate of Svc encl
REYNOLDS, J. R. Joint Intervenor-Diablo Canyon REYNOLDS, J. R. Center for Law in the Public Interest. 82/08/17. Commissioners 14pp. 14399:316 24X Fiche 50-275.82/08/17.8208200250

8208200262 Response supporting Governor Brown 820802 motion to reopen proceeding to take evidence on QA Outdated & obviously erroneous findings re QA & seismic design should not stand.
Certificate of Svc encl
REYNOLDS, J. R. Joint Intervenor-Diablo Canyon REYNOLDS, J. R. Center for Law in the Public Interest 82/08/17. Atomic Safety and Licensing Board Panel 7pp. 14398:329 24X Fiche: 50-275.82/08/17.8208200262

8208250241 Response opposing Governor Brown 820802 motion to reopen proceeding to take evidence on QA Reopened hearing would serve no useful purpose Certificate of Svc encl.
HASSELL, D. F. Hearing Branch 1. 82/08/23. Atomic Safety and Licensing Board Panel. 17pp. 14542:332 24X Fiche: 50-275.82/08/23.8208250241

8208250356 Order extending time until 820914 for Commission to consider whether to review ALAB-453.
CHILK, B. J. Office of the Secretary of the Commission. 82/08/24. Commissioners. 1p. 14340:209. 24X Fiche: 50-275.82/08/24.8208250356

8208310077 Errata to NRC 820823 response to Governor Brown motion to reopen proceeding to take evidence on QA Certificate of Svc encl
HASSELL, D. F. Hearing Branch 1. 82/08/27. Atomic Safety and Licensing Board Panel 3pp. 14695:146. 24X Fiche: 50-275.82/08/27.8208310077

H. General correspondence

8208030431 Advises that R Wray will serve as project manager during 820802-04 & 12-24.
COOPER, W. E. Teledyne Engineering Services 82/07/29 DENTON, H. H. Office of Nuclear Reactor Regulation, Director ENGELKEN, R. H. Region 5. Office of Director. MANEATIG, O. A. Pacific Gas & Electric Co. 1p. 14154:142. 24X Fiche 50-275.82/07/29.8208030431

M. Antitrust correspondence

8208180018 Discusses PG&E refusal to allow interconnection of Northern CA Power Agency geyser units w/ Diablo Canyon units for testing purposes except under provisions in violation of license conditions
MCDIARMID, R. C. Spiegel, G. MCDIARMID, R. C. Northern California Power Agency, California, State of. 82/08/13 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp. 14377:168 24X Fiche: 50-275.82/08/13.8208180018

P. Operating license stage documents & correspondence

8207070414 Forwards amended Order 82-24, "Waste Discharge Requirements for PG&E, Diablo Canyon Power Plant, Units 1 & 2, San Luis Obispo County" & "Order 82-54 Amending NPDES Permit CA0003751, Waste Discharge Requirements," adopted 820611
JONES, K. R. Dept. of Water Resources, California, State of. 82/06/30. MCKENZIE, J. F. Pacific Gas & Electric Co. 30pp. 13739:088. 24X Fiche 50-275.82/06/30.8207070414

8208020435 Forwards Teledyne Engineering Svcs 820618 independent design verification program-Phase II program mgt plan Comments due in 15 days w/o encl
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 82/07/08 BROWN, E. O. California, State of 5pp. 14181:034 24X Fiche: 50-275.82/07/08.8208020435

8208020444 Forwards Teledyne Engineering Svcs 820618 independent design verification program-Phase II program mgt plan Comments due in 15 days w/o encl
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 82/07/08 REYNOLDS, J. R., PHILLIPS, J. R. Center for Law in the Public Interest 3pp. 14181:048 24X Fiche: 50-275.82/07/08.8208020444

8208040532 Responds to 820615 ltr re concerns over amount of radiation & increase of tritium proposed for release into Pacific Ocean Required design measures taken to protect contaminated liquid effluents to minimize release
DENTON, H. R. Office of Nuclear Reactor Regulation, Director 82/07/21. JONES, K. R. California, State of. 23pp. 14223:241. 24X Fiche: 50-275.82/07/21.8208040532

--8206200027 Forwards CA Regional Water Quality Control Board 820119 & 0218 ltrs voicing concerns re increase in tritium over background levels & amount of radiation to be released to Pacific Ocean
JONES, K. R. California, State of 82/06/15 PALLADINO, N. J., GILINSKY, V., AHEARNE, J. Commissioners 1p. 14223:264 24X Fiche: 50-275.82/07/21.8208040532

8208190336 Informs that Commission will be briefed in late Aug 1982 re recommendations concerning Phase I & II of facility design verification program conducted per Order CLF 81-30
DIRKS, W. J. Office of the Executive Director for Operations 82/07/29. PALLADINO, N. J., GILINSKY, V., AHEARNE, J. Commissioners 4pp. 14506:132. 24X Fiche 50-275.82/07/29.8208190336

8208050338 Comments on Teledyne Engineering Svcs 820618 Phase II Program Mgt Plan per Commission invitation. Commission should require listed specific changes to audit program
REYNOLDS, J. R., FLEISCHAKER, D. Center for Law in the Public Interest
REYNOLDS, J. R. Joint Intervenor-Diablo Canyon 82/08/02
PALLADINO, N. J., GILINSKY, V., AHEARNE, J. Commissioners. 5pp. 14219:344. 24X Fiche 50-275.82/08/02.8208050338

8208190388 Forwards request for addl info re QA program Info should be in form of marked revisions to QA program approved contingent upon submittal of requested revisions w/o encl
EISENHUT, D. O. Division of Licensing. 82/08/02 CRANE, P. A. Pacific Gas & Electric Co. 1p. 14506:097. 24X Fiche 50-275.82/08/02.8208190388

8208260362 Board Notification 82-80, forwarding third interim technical rept, "Diablo Canyon Unit 1 Independent Design Verification Program - Tanks."
EISENHUT, D. O. Division of Licensing 82/08/02. PALLADINO, N. J., GILINSKY, V., AHEARNE, J. Commissioners. 3pp. 14575:143. 24X Fiche: 50-275.82/08/02.8208260362

DOCKETED ITEMS

8208060204 Forwards License Amend Request 82-05 for License DPR-76. Amend changes expiration date of license from 1 yr from date of issuance to 2 yrs from date of issuance. CRANE, P. A. Pacific Gas & Electric Co. 82/08/03. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 14238.354. 24X Fiche: 50-275, 82/08/03, 8208060204.

--8208060207 License Amend Request 82-05 for License DPR-76, changing expiration date of license from 1 yr from date of issuance to 2 yrs from date of issuance. SCHUYLER, J. D. Pacific Gas & Electric Co. 82/08/03. 2pp. 14238.355. 24X Fiche: 50-275, 82/08/03, 8208060204.

8208100218 Forwards "Balen Unit 1 17x17 Fuel Assembly," Jan 1982. Rept adequately resolves question of guide tube wear for both units & satisfies NRC acceptability criteria. CRANE, P. A. Pacific Gas & Electric Co. 82/08/05. MIRAQLIA, F. J. Licensing Branch 3. 1p. 14297.040. 24X Fiche: 50-275, 82/08/05, 8208100218.

8208130069 Forwards Revision 0 to "Independent Design Verification Program Interface Between Independent Design Verification Program Participants & PGE." COOPER, W. E. Teledyne Engineering Services. 82/08/05. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ENGELKEN, R. H. Region 5, Office of Director. MANEATIB, Q. A. Pacific Gas & Electric Co. 1p. 14336.024. 24X Fiche: 50-275, 82/08/05, 8208130069.

--8208130071 "Independent Design Verification Program Interface Between Independent Design Verification Program Participants & PGE," Revision 0. COOPER, W. E. Teledyne Engineering Services. 82/08/02. 11pp. 14336.025. 24X Fiche: 50-275, 82/08/05, 8208130069.

8208270680 Staff requirements memo re 820729 affirmation/discussion session Commission approved orders releasing sanitized version of ALAB-653, reviewing ALAB-670 & denying petition to intervene in proceeding for mod of Pilgrim OL. HOYLE, J. C. Office of the Secretary of the Commission. 82/08/06. BICKWIT, L. Office of the General Counsel. DIRCKS, W. J. Office of the Executive Director for Operations. 4pp. 14683.185. 24X Fiche: 50-000, 82/08/06, 8208270680.

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Bvc list encl. EISENHUT, D. Q. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14336.332. 24X Fiche: 50-000, 82/08/09, 8208090194.

8208130075 Advises that upgrading of Class IE vent radioactive particulates & Gas Monitoring Bys RE-14 A & B & RE-28 A & B will be completed by 821130, per 811125 submittal. CRANE, P. A. Pacific Gas & Electric Co. 82/08/09. MIRAQLIA, F. J. Licensing Branch 3. 1p. 14336.037. 24X Fiche: 50-275, 82/08/09, 8208130075.

8208260613 Forwards request for addl info re analysis of containment annulus structure, as agreed in 820727 meeting at BNL. MIRAQLIA, F. J. Licensing Branch 3. 82/08/11. REICH, M. Brookhaven National Laboratory. 3pp. 14567.357. 24X Fiche: 50-275, 82/08/11, 8208260613.

8208170137 Advises that filing of application for amend to License DPR-76, extending expiration date for 1-yr, was timed to comply w/10CFR2.109. CRANE, P. A. Pacific Gas & Electric Co. 82/08/13. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 14364.209. 24X Fiche: 50-275, 82/08/13, 8208170137.

8208170161 Forwards addl info re QA program in response to NRC 820802 request. Encl consists of statements providing clarifications & revisions to 820618 submittal. Changes to submittal modify scope of QA program. CRANE, P. A. Pacific Gas & Electric Co. 82/08/13. MIRAQLIA, F. J. Licensing Branch 3. 20pp. 14364.294. 24X Fiche: 50-275, 82/08/13, 8208170161.

8208230336 Informs that no fixed implementation date for requirements of Milestone 7 to NUREG-0737, Item III. A. 2.2 re description of Class B model, can be set until NRC clarifies meteorological & modeling sys requirements. CRANE, P. A. Pacific Gas & Electric Co. 82/08/16. MIRAQLIA, F. J. Licensing Branch 3. 2pp. 14508.326. 24X Fiche: 50-275, 82/08/16, 8208230336.

8208230196 Forwards "Reactor Containment Bldg Integrated Leak Rate Test," for 820212-15. CRANE, P. A. Pacific Gas & Electric Co. 82/08/18. MIRAQLIA, F. J. Licensing Branch 3. 1p. 14513.234. 24X Fiche: 50-275, 82/08/18, 8208230196.

--8208230204 "Reactor Containment Bldg Integrated Leak Rate Test," for 820212-15. Pacific Gas & Electric Co. 82/08/18. 34pp. 14513.235. 24X Fiche: 50-275, 82/08/18, 8208230196.

8208270204 Forwards Revision 0 to "Independent Design Verification Program - Design Chain," interim technical rept. DENISON, E. Robert L. Cloud Associates, Inc. 82/08/19. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. MANEATIB, Q. A. Pacific Gas & Electric Co. ENGELKEN, R. H. Region 5, Office of Director. 1p. 14563.144. 24X Fiche: 50-275, 82/08/19, 8208270204.

--8208270212 "Independent Design Verification Program - Design Chain," Revision 0. DENISON, E. Robert L. Cloud Associates, Inc. P 105-4-839-005 ROD. 82/08/19. 43pp. 14563.145. 24X Fiche: 50-275, 82/08/19, 8208270204.

8208310364 Requests info based on Teledyne understanding of util corrective action program in response to independent design verification & internal technical programs. Util should provide addl detailed info on corrective action program. EISENHUT, D. Q. Division of Licensing. 82/08/19. COOPER, W. E. Teledyne Engineering Services. 4pp. 14697.117. 24X Fiche: 50-275, 82/08/19, 8208310364.

8208250202 Forwards preliminary outline developed for final rept Phase I of design verification program. Description of scope, criteria & methodology for certain corrective action program elements will be submitted by 820901. CRANE, P. A. Pacific Gas & Electric Co. 82/08/20. EISENHUT, D. Q. Division of Licensing. 17pp. 14541.340. 24X Fiche: 50-275, 82/08/20, 8208250202.

8208310144 Advises that panel mounted instruments required for safe shutdown were replaced w/instruments qualified to operate submerged, per util 750914 & 1228 evaluations. Design change initiated. Sealant requirements removed. CRANE, P. A. Pacific Gas & Electric Co. 82/08/26. MIRAQLIA, F. J. Licensing Branch 3. 1p. 14693.179. 24X Fiche: 50-275, 82/08/26, 8208310144.

8208310429 Requests concurrence w/util proposal to submit one Tech Sp. change re mods to snubbers at conclusion of independent design verification program prior to fuel loading & plant operation. CRANE, P. A. Pacific Gas & Electric Co. 82/08/27. MIRAQLIA, F. J. Licensing Branch 3. 1p. 14692.066. 24X Fiche: 50-275, 82/08/27, 8208310429.

0 Inspection reports, IE Bulletins & correspondence

8207080424 Forwards IE Insp Rept 50-275/82-19 on 820502-0604. No noncompliance noted. STERNBERG, R. M. Division of Resident, Reactor Project & Engineering Programs. 82/06/18. CRANE, P. A. Pacific Gas & Electric Co. 2pp. 13772.266. 24X Fiche: 50-275, 82/06/18, 8207080424.

--8207080426 IE Insp Rept 50-275/82-19 on 820502-0604. No noncompliance noted. Major areas inspected: plant operations, surveillance testing, physical security, maintenance followup & QA program. CARLBON, J. D., MENDONCA, M. H., YOUNG, T. Division of Resident, Reactor Project & Engineering Programs. 82/06/18. 4pp. 13772.268. 24X Fiche: 50-275, 82/06/18, 8207080424.

8208310105 Forwards IE Emergency Preparedness Appraisal Repts 50-275/81-33 & 50-323/81-19 on 811207-17. ENGELKEN, R. H. Region 5, Office of Director. 82/07/08. CRANE, P. A. Pacific Gas & Electric Co. 2pp. 14689.319. 24X Fiche: 50-275, 82/07/08, 8208310105.

--8208310113 IE Emergency Preparedness Appraisal Repts 50-275/81-33 & 50-323/81-19 on 811207-17. Deficiencies noted: equipment, emergency plan implementing procedures & coordination w/ offsite groups. FISH, R. F., BOWMAN, K. Region 5, Office of Director. 82/07/07. 51pp. 14689.325. 24X Fiche: 50-275, 82/07/08, 8208310105.

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage," Bvc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16. Consolidated Edison Co. of New York. 87pp. 14356.274. 24X Fiche: 50-000, 82/07/16, 8204210393.

8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure," Bvc list encl. JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp. 14381.001. 24X Fiche: 50-000, 82/07/20, 8204210396.

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards.
82/07/20 Consolidated Edison Co. of New York 71pp 14357 276
24X Fiche 50-000, 82/07/20, 8204210397

8208030018 Discusses NRR 820524-28 seismic reevaluation program insp.
Major areas inspected Blume independent internal review of
past Blume structural analyses, until document control manual
& impacts of new project organization
HERRING, K. S. Systematic Evaluation Program Branch 82/07/21
MIRAGLIA, F. J. Licensing Branch 3 7pp 14237 345. 24X
Fiche 50-275, 82/07/21, 8208030018

--8208030020 Revision 2 to "Procedure for PO&E Evaluation of Review
Comments Received From Blume Independent Internal Review."
SCHURMAN, A. B., BEITINGER, R. V., MOORE, G. H. Pacific Gas & Electric
Co. 82/04/17. 6pp 14237 352 24X Fiche 50-275, 82/07/21,
8208030018.

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check
Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/22.
Consolidated Edison Co. of New York 112pp 14194 321 24X
Fiche 50-000, 82/07/22, 8204210398

8208160309 Forwards IE Insp Rept 50-275/82-21 on 820606-0703 No
noncompliance noted.
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering
Programs. 82/07/22. CRANE, P. A. Pacific Gas & Electric Co. App.
14345 293 24X Fiche 50-275, 82/07/22, 8208160309

--8208160314 IE Insp Rept 50-275/82-21 on 820606-0703 No noncompliance
noted Major areas inspected plant operations, surveillance
testing, physical security, maintenance, followup & licensee QA
program
CARLSON, J. D., MENDONCA, M. M., YOUNG, T. Division of Resident,
Reactor Project & Engineering Programs. 82/07/19 4pp
14345 297. 24X Fiche 50-275, 82/07/22, 8208160309

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in
Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23.
Consolidated Edison Co. of New York 122pp 14380 315 24X
Fiche 50-000, 82/07/23, 8204210401

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube
Support Pin Failures at Westinghouse PWRs." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23.
Consolidated Edison Co. of New York 127pp 14194 320 24X
Fiche 50-000, 82/07/23, 8204210402.

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping
at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26
Consolidated Edison Co. of New York 121pp 14357 013 24X
Fiche 50-000, 82/07/26, 8204210403

8208160128 Forwards IE Insp Repts 50-275/82-22 & 50-323/82-11 on
820526-28 & 0628-0702. No noncompliance noted.
BISHOP, T. W. Division of Resident, Reactor Project & Engineering
Programs. 82/07/27. CRANE, P. A. Pacific Gas & Electric Co. App.
14345 185 24X Fiche 50-275, 82/07/27, 8208160128

--8208160129 IE Insp Repts 50-275/82-22 & 50-323/82-11 on 820526-28 &
0628-0702 No noncompliance noted. Major areas inspected:
action on previous items, mods to piping & electrical railway
supports & Unit 2 vessel
BURDIN, J. F., ECKHARDT, J. H. Division of Resident, Reactor Project
& Engineering Programs. 82/07/26 8pp 14345 189. 24X
Fiche 50-275, 82/07/27, 8208160128

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in
Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28.
Consolidated Edison Co. of New York. 122pp. 14357 146 24X
Fiche 50-000, 82/07/28, 8204210405.

8208040305 IE Insp Repts 50-275/82-12 & 50-323/82-07 have been
canceled.
BETTERLE, C. Region 5, Office of Director. 82/07/28. 1p 14183 087.
24X Fiche 50-275, 82/07/28, 8208040305.

8208160466 Forwards IE Insp Repts 50-275/82-23 & 50-323/82-12 on
820721-23. No noncompliance noted.
BOOK, H. E. Division of Radiological Safety & Safeguards Program.
82/07/30. CRANE, P. A. Pacific Gas & Electric Co. App. 14348 220.
24X Fiche 50-275, 82/07/30, 8208160466.

--8208160475 IE Insp Repts 50-275/82-23 & 50-323/82-12 on 820721-23 No
noncompliance noted Major areas inspected followup on IE
circulars, info notices & bulletins, preoperational testing &
monitoring calibr
NORTH, H. S., WENSLAWSKI, F. A., BOCK, H. E. Division of Radiological
Safety & Safeguards Program. 82/07/30 6pp 14348 224 24X
Fiche 50-275, 82/07/30, 8208160466

8208160178 Responds to Action Item 3 of IE Bulletin 82-02, "Degradation
of Threaded Fasteners in RCPB of PWR Plants." No incidents
of leakage in bolted closures evident Maint procedures
specify FEL-PRD-N-500 per Westinghouse ltr
SCHUYLER, J. D. Pacific Gas & Electric Co. 82/08/02 ENGELKEN, R. H.
Region 5, Office of Director. 3pp 14345 091 24X
Fiche 50-275, 82/08/02, 8208160178

8208160523 Forwards IE Insp Rept 50-275/82-24 on 820712-15 No
noncompliance noted.
STERNBERG, D. M. Division of Resident, Reactor Project & Engineering
Programs. 82/08/02. CRANE, P. A. Pacific Gas & Electric Co. 1p
14348 076 24X Fiche 50-275, 82/08/02, 8208160523

--8208160525 IE Insp Rept 50-275/82-24 on 820712-15 No noncompliance
noted Major areas inspected plant operations, onsite review
committee & independent insp
MORRILL, P. J., YOUNG, T. Division of Resident, Reactor Project &
Engineering Programs. 82/08/02 3pp 14348 077 24X
Fiche 50-275, 82/08/02, 8208160523

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From
Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/08/05
Consolidated Edison Co. of New York 117pp 14388 201 24X
Fiche 50-000, 82/08/05, 8204210407

8208200144 Forwards four inservice insp specific repair program plans
to meet requirements of Section XI of ASME boiler &
pressure vessel code
CRANE, P. A. Pacific Gas & Electric Co. 82/08/12 ENGELKEN, R. H.
Region 5, Office of Director. LEBLOW, R. California, State of.
THOMPSON, C. D. Hartford Steam Boiler Inspection & Insurance Co. 2pp.
14393 290. 24X Fiche 50-275, 82/08/12, 8208200144

--8208200148 "Relief Valve for Waste Gas Compressor Seal Water Cooler"
* Pacific Gas & Electric Co. 82/06/25. 1p 14393 292 24X
Fiche 50-275, 82/08/12, 8208200144

--8208200150 "Auxiliary Saltwater Pressure Indicator PB-105A Isolation
Valve"
* Pacific Gas & Electric Co. 82/06/25 2pp 14393 293 24X
Fiche 50-275, 82/08/12, 8208200144

--8208200154 "Chemical & Vol Control Bys Cold Leg Loop Charging Valve
B10B"
* Pacific Gas & Electric Co. 82/06/25. 2pp 14393 295 24X
Fiche 50-275, 82/08/12, 8208200144.

--8208200158 "Drain Stop Valves for RHR Pump 1-2 Loop 4 Cold Leg"
* Pacific Gas & Electric Co. 82/07/21. 1p 14393 297 24X
Fiche 50-275, 82/08/12, 8208200144.

R. Periodic operating reports & related correspondence

8208120072 Forwards monthly operating rept for June 1982.
THORNBERY, R. C. Pacific Gas & Electric Co. 82/07/06. Office of
Resource Management, Director 2pp 14327 172 24X
Fiche 50-275, 82/07/06, 8208120072.

--8208120076 Monthly operating rept for June 1982
SCOTT, W. B. Pacific Gas & Electric Co. 82/07/02 3pp 14327 174.
24X Fiche 50-275, 82/07/06, 8208120072

8208270010 Responds to FOIA request for documents detailing collective
dose exposures in 1981 for operating nuclear power plants &
analyzing said info Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records 82/07/13 UDELL, R. A.
Critical Mass Energy Project. 8pp. 14679 208 24X
Fiche 50-000, 82/07/13, 8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power
Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13 48pp
14679 216. 24X Fiche 50-000, 82/07/13, 8208270010

8208090333 Board Notification 82-76: forwards info re design
verification program, consisting of semi-monthly repts.
EISENHUT, D. G. Division of Licensing. 82/07/22. PALLADINO, N. J.,
OILINSKY, V., AHEARNE, J. Commissioners. 4pp. 14308 001. 24X
Fiche 50-275, 82/07/22, 8208090333.

0200010271 Forwards Revision 1 to "Diable Canyon Nuclear Power Plant Independent Design Verification Program Semi-monthly Rept"
COMPH.H.H. Teledyne Engineering Services 02/07/29 DENTON.H.H
Office of Nuclear Reactor Regulation, Director ENGINEER.H.H
Region 5, Office of Director MAHATHI.H.O A Pacific Gas & Electric Co
1p 1415H 150 24X Fiche 50 275.02/07/29.0200010271

0200010276 Revision 1 to "Diable Canyon Nuclear Power Plant Independent Design Verification Program Semi-monthly Rept"
e Teledyne Engineering Services 02/07/29 53pp 1415H 151
24X Fiche 50 275.02/07/29.0200010276

0200010276 Abstracts Independent design verification program semi-monthly rept for Jul 1982 sent on 02/07/26 Rept not necessary under Phase II program
REIDY.H.H R L Reidy, Inc 02/07/29 DENTON.H.H Office of Nuclear Reactor Regulation, Director ENGINEER.H.H
Office of Director MAHATHI.H.O A Pacific Gas & Electric Co 4pp
1415H 209 24X Fiche 50 275.02/07/29.0200010276

0200100025 Advises that no open item repts issued since Jul semi-monthly rept
GRIEKE.H.H H H GRIEKE Engineering Corp 02/08/12 DENTON.H.H Office of Nuclear Reactor Regulation, Director ENGINEER.H.H
Region 5, Office of Director MAHATHI.H.O A Pacific Gas & Electric Co 1p
1417H 170 24X Fiche 50 275.02/08/12.0200100025

0200102290 Forwards "Diable Canyon Nuclear Power Plant Independent Design Verification Program." semi-monthly rept for Aug 1982
COMPH.H.H Teledyne Engineering Services 02/08/11 DENTON.H.H Office of Nuclear Reactor Regulation, Director ENGINEER.H.H
Region 5, Office of Director MAHATHI.H.O A Pacific Gas & Electric Co 1p
1416H 242 24X Fiche 50 275.02/08/11.0200102290

0200102291 "Diable Canyon Nuclear Power Plant Independent Design Verification Program." semi-monthly rept for Aug 1982
e Teledyne Engineering Services 02/08/11 100pp 1416H 24H
24X Fiche 50 275.02/08/11.0200102291

0200100015 Forwards Open Item Repts 1097, 1098 & 1099, Revision 0, issued during Aug semi-monthly reporting period
GRIEKE.H.H H H GRIEKE Engineering Corp 02/08/11 DENTON.H.H Office of Nuclear Reactor Regulation, Director ENGINEER.H.H
Region 5, Office of Director MAHATHI.H.O A Pacific Gas & Electric Co 4pp
1417H 141 24X Fiche 50 275.02/08/11.0200100015

0200100100 Submits Semi-monthly Rept 18 for 02/07/80 H.H. No open item repts issued Contractor personnel completed statement re potential or apparent conflicts of interest
REIDY.H.H R L Reidy, Inc 02/08/11 DENTON.H.H Office of Nuclear Reactor Regulation, Director ENGINEER.H.H
Region 5, Office of Director MAHATHI.H.O A Pacific Gas & Electric Co 4pp
1417H 146 24X Fiche 50 275.02/08/11.0200100100

0200200267 Forwards nineteenth semi-monthly status rept dtd 02/08/11 re design verification program for 02/07/80 H.H.
CHAM.P.A Pacific Gas & Electric Co 02/08/11 DENTON.H.H Office of Nuclear Reactor Regulation, Director ENGINEER.H.H
Region 5, Office of Director 1p 1417H 18H 24X
Fiche 50 275.02/08/11.0200200267

0200200271 "P&G Semi-monthly Rept 14, Diable Canyon Verification Program"
e Pacific Gas & Electric Co 02/08/11 43pp 1417H 18H 24X
Fiche 50 275.02/08/11.0200200271

B Reportable occurrences, CHN & related correspondence

0200000030 Forwards incident reporting sys repts re effects of fire protection sys activation on safety related equipment & seismic qualification of safety related sys for transmission to NRC
HICHERMAN.C Director's Office 02/07/29 1415H J.D Office of International Programs, Director 4pp 1424 315 24X
Fiche 50 000.02/07/29.0200000030

0200200071 Board Notification 02/08 forwarding Part 21 deficiency rept re error in PIPECO computer program for piping analysis
EIDEMRY.O.O Division of Licensing 02/08/17 PHILADELPHIA.E.O
OLINIKY.V. A.H.A.H.H.J.P Commissioners 4pp 14317 207 24X
Fiche 50 275.02/08/17.0200200071

0200200071 Part 21 rept re potential error in computer software program PIPECO for CYBERNET sys Revised version of program prepared
Bvt list encl
BATCH.O.K Control Data Corp 02/07/07 GTEL.O.V Regional Operations & Generic Requirements 12pp 14317 209 24X
Fiche 50-275.02/08/17.0200200071

DUCKET 50-276 GEORGIA TECH RESEARCH REACTION

B Inspection reports, IE Bulletins & correspondence

0204210395 IE Info Notice 01-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Bvt list encl
JORDAN.E.L Division of Engineering & Quality Assurance 02/07/19
Nichtgan, Univ of 112pp 1419H 001 24X Fiche 50 000.02/07/19
0204210395

DUCKET 50 277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

0200040171 Release public version of revisions to emergency plan implementing procedures
FLETCHER.H.H Division of Rules and Records 02/07/13 Document Management Branch 1p 14224 062 24X Fiche 50 277.02/07/13.
0200040171

0200040174 Forwards public version of revisions to emergency plan implementing procedures, including Procedures LP-C-120 re recovery phase implementation & LP-200A re operation of post accident sampling station
DAITH.H.H Philadelphia Electric Co 02/06/30 DENTON.H.H Office of Nuclear Reactor Regulation, Director 4pp 14224 064
24X Fiche 50 277.02/07/13.0200040174

0200040175 Public version of revision to emergency plan implementing procedures, including Procedures LP-C-120 re recovery phase implementation & LP-200A re operation of post accident sampling station
e Philadelphia Electric Co 02/06/11 110pp 14224 06H 24X
Fiche 50 277.02/07/13.0200040175

0200050218 Forwards IE Insp Repts 50 277/02 12 & 50 278/02 12 on 02/06/16 Noncompliance noted
HALL.H.H Division of Emergency Preparedness & Operational Support 02/07/21 RIVEN.V.H Philadelphia Electric Co 2pp 14209 317
24X Fiche 50 277.02/07/21.0200050218

0200050225 IE Insp Repts 50 277/02 12 & 50 278/02 12 on 02/06/16 Noncompliance noted Major Areas inspected emergency preparedness exercises
TERC.H.H CHICKEN.H.H Division of Emergency Preparedness & Operational Support 02/07/19 10pp 14209 319 24X
Fiche 50 277.02/07/21.0200050225

B Operating licenses stage documents & correspondence

0200000044 Generic ltr to all licensees of operating plants, applicants for DL & holders of LP re Commission approved charter for CROM Bvt list encl
DIRK.H.H Office of the Executive Director for Operations 02/07/02 Consolidated Edison Co of New York 4pp 14194 001
24X Fiche 50 000.02/07/02.0200000044

0200020451 Summarizes status of HRC review of HRCU 02/17, Item 11 & 4 re containment purging & venting H.H encl for guidance in completing item info on purge/vent valve leakage tests also encl
HICK.E.J.P Operating Reactors Branch 4 02/07/07 HAUEN.E.O Philadelphia Electric Co 4pp 14180 17J 24X
Fiche 50 277.02/07/07.0200020451

0200020454 Draft safety evaluation for containment purging & venting during normal operation Addl info required before review of purge/vent sys can be completed
e HRC - No Detailed Affiliation Given 02/07/07 5pp
14180 17H 24X Fiche 50-277.02/07/07.0200020454

0200040378 Forwards revised model Tech Specs re reactor protection sys power monitoring sys design and
BLOD.Z.J.P Operating Reactors Branch 4 02/07/19 HAUEN.E.O Philadelphia Electric Co 2pp 14224 187 24X
Fiche 50 277.02/07/19.0200040378

0200040379 Revised model Tech Specs 3/4 0 4 re electrical power re reactor protection sys electric power monitoring
e HRC - No Detailed Affiliation Given 02/07/19 1p 14224 18H
24X Fiche 50-277.02/07/19.0200040379

0200060357 SOCIOECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS PEACH BOTTOM CASE STUDY Doclet Nos 50 277 And 50 270
(Philadelphia Electric Company)
PIJAMA.K.D Mountain West Research, Inc e Social Impact Research, Inc PIN B-626H HARE/OCH 3749 V08 02/07/31
Division of Health, Biting & Environment 210pp Available at NTIS
97 00 14272 143 24X Fiche 50 277.02/07/31.0200060357

B208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl
EISENHUT, D O Division of Licensing 82/08/09. Consolidated
Edison Co of New York 1p 14336 332. 24X Fiche 50-000, 82/08/09.
8208090194

B208200065 Requests withdrawal of 820806 application for amends to Licensee DPR-44 & DPR-56. Application submitted 790301 will be amended later this yr to reflect guidance contained in Tech Spec for gaseous radiation monitors
DALTROFF, S L Philadelphia Electric Co 82/08/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 2pp 14392: 219
24X Fiche 50-277, 82/08/16, 8208200065

B2082706B9 Informs that review of NUREG-0737, Item 11 K 3 15, "Mod Break Detection Logic HPCI/Reactor Core Isolation Cooling," completed Reactor core isolation cooling sys adequate. Safety evaluation encl
STOLZ, J F. Operating Reactors Branch 4. 82/08/17 BAUER, E O
Philadelphia Electric Co App. 14683 065 24X
Fiche 50-277, 82/08/17, 82082706B9

B208310096 Forwards summary rept of util efforts & findings re TM1 Item 11 E 4 2 on containment purge & vent sys per 820707 request for info.
DALTROFF, S L Philadelphia Electric Co 82/08/26 STOLZ, J F
Operating Reactors Branch 4 15pp 14689: 303. 24X
Fiche 50-277, 82/08/26, 8208310096.

0 Inspection reports, IE Bulletins & correspondence

B206270075 FOIA request for sections of IE Insp Repts 50-277/81-07 & 50-278/81-09 not containing 10CFR2 790 info.
SPECTOR, C. Technical Analysis Corp. 81/06/29 Office of
Administration. 1p. 14328 133. 24X Fiche 50-277, 82/06/29,
8206270075

B204210393 IE Info Notice B2-23. "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/16.
Consolidated Edison Co of New York. 87pp 14356 274. 24X
Fiche 50-000, 82/07/16, 8204210393

B204210395 IE Info Notice B1-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/19
Michigan Univ. of. 112pp. 14358 001. 24X Fiche 50-000, 82/07/19,
8204210395

B208020264 Forwards IE Insp Repts 50-277/82-08 & 50-278/82-08 on 820426-29 & 0513-14 & notice of violation.
MARTIN, T T. Division of Engineering & Technical Programs. 82/07/19.
DALTROFF, S L Philadelphia Electric Co 2pp. 14132 263. 24X
Fiche 50-277, 82/07/19, 8208020264.

--B208020270 Notice of violation from insp on 820426-29 & 0513-14.
MARTIN, T T. Division of Engineering & Technical Programs.
82/07/19. 2pp. 14132: 265 24X Fiche 50-277, 82/07/19, 8208020264.

--B208020278 IE Insp Repts 50-277/82-08 & 50-278/82-08 on 820426-29 & 0513-14. Noncompliance noted: Failure to follow radiation protection procedures, to perform surveys & to instruct workers on radiation conditions.
NIMITZ, R L, ROWE, C A, GREENMAN, E O Division of Engineering & Technical Programs 82/07/16 26pp. 14152: 267. 24X
Fiche 50-277, 82/07/19, 8208020264.

B208230444 Responds to FOIA request for sections of IE Insp Repts 50-277/82-07 & 50-278/82-09 not containing 10CFR2 790 info.
Forwards requested info. Documents also available in PDR.
FELTON, J M. Division of Rules and Records. 82/07/19. ROSENBAUM, O
Technical Analysis Corp. 1p. 14528: 134. 24X Fiche 50-277, 82/07/19,
8208230444

--B208230467 Nonproprietary version of notice of violation from insp on 810301-0407.
BRUNNER, E J. Division of Resident & Project Inspection. 81/07/01.
3pp. 14528: 138. 24X Fiche 50-277, 82/07/19, 8208230444.

--B208230470 Nonproprietary version of notice of violation from insp on 810301-0407.
BRUNNER, E J. Division of Resident & Project Inspection 81/07/01.
1p. 14528: 141. 24X Fiche 50-277, 82/07/19, 8208230444

--B208230473 Nonproprietary version of IE Insp Repts 50-277/81-07 & 50-278/81-09 on 810301-0407 Noncompliance noted. Failure to have adequate radwaste collection procedures & to follow administrative procedures for mods
COWELL, C J, BLOUGH, A R, REYNOLDS, S D Reactor Projects Section
28 81/06/01 31pp. 14528 142 24X Fiche 50-277, 82/07/19,
8208230444

B204210396 IE Info Notice B2-25. "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/20.
Consolidated Edison Co. of New York 112pp 14381 001 24X
Fiche 50-000, 82/07/20, 8204210396

B204210397 IE Info Notice B2-24. "Water Leaking From U Hexafluoride Overpacks." Svc list encl
COWELL, C J Division of Fuel Facilities, Materials & Safeguards.
82/07/20 Consolidated Edison Co of New York 71pp. 14357: 276
24X Fiche 50-000, 82/07/20, 8204210397

B208050218 Forwards IE Insp Repts 50-277/82-12 & 50-278/82-12 on 820616 No noncompliance noted
SMITH, G H Division of Emergency Preparedness & Operational Support.
82/07/21. BOYER, V B Philadelphia Electric Co. 2pp. 14209: 317.
24X Fiche 50-277, 82/07/21, 8208050218

--B208050225 IE Insp Repts 50-277/82-12 & 50-278/82-12 on 820616 No noncompliance noted. Major areas inspected. emergency preparedness exercise.
IERC, N M, CROCKER, H W Division of Emergency Preparedness & Operational Support. 82/07/19 10pp. 14209 319. 24X
Fiche 50-277, 82/07/21, 8208050218

B204210398 IE Info Notice B2-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/22.
Consolidated Edison Co of New York. 112pp. 14194 321 24X
Fiche 50-000, 82/07/22, 8204210398

B204210401 IE Info Notice B2-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co of New York 122pp 14380 115 24X
Fiche 50-000, 82/07/23, 8204210401.

B204210402 IE Info Notice B2-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co of New York 127pp. 14194 120 24X
Fiche 50-000, 82/07/23, 8204210402

B204210403 IE Info Notice B2-30. "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/26.
Consolidated Edison Co of New York 121pp. 14397: 013. 24X
Fiche 50-000, 82/07/26, 8204210403.

B204210405 IE Info Notice B2-31. "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/28
Consolidated Edison Co of New York. 122pp 14397: 146. 24X
Fiche 50-000, 82/07/28, 8204210405.

B204210407 IE Info Notice B2-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. 82/08/05.
Consolidated Edison Co. of New York 117pp. 14388: 201. 24X
Fiche 50-000, 82/08/05, 8204210407.

B208300049 Forwards IE Enforcement Conference Repts 50-277/82-17 & 50-278/82-15 on 820722
STAROSTECKI, R. Division of Project & Resident Programs. 82/08/10.
DALTROFF, S L Philadelphia Electric Co. 2pp. 14598 297. 24X
Fiche 50-277, 82/08/10, 8208300049.

--B208300051 IE Enforcement Conference Repts 50-277/82-17 & 50-278/82-15 on 820722 No noncompliance noted. Major areas discussed: findings of previous insp re health physics program & primary containment integrity.
BLOUGH, A R, MCCABE, E C. Division of Project & Resident Programs.
82/08/04. 3pp. 14598: 299. 24X Fiche 50-277, 82/08/10, 8208300049.

R. Periodic operating reports & related correspondence

B208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J M. Division of Rules and Records. 82/07/13. UDELL, R A.
Critical Mass Energy Project. Bpp. 14679: 208. 24X
Fiche 50-000, 82/07/13, 8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power
Facilities for CY81"
* NRC - No Detailed Affiliation Given 82/07/13 48pp
14679:216 24X Fiche: 50-000,82/07/13,8208270010

8208190098 Forwards monthly operating repts for Jul 1982.
CODNEY, M J Philadelphia Electric Co 82/08/13 Director's
Office, Office of Inspection and Enforcement 1p. 14383:164 24X
Fiche: 50-277,82/08/13,8208190098

--8208190102 Monthly operating repts for Jul 1982.
ALDEN, W M Philadelphia Electric Co 82/08/11 9pp 14383:165.
24X Fiche: 50-277,82/08/13,8208190098

G Reportable occurrences, LERs & related correspondence

8208050317 Forwards LERs 82-015/01T-0 & 82-016/01T-0. Detailed event
analysis submitted
CODNEY, M J Philadelphia Electric Co 82/07/16. HAYNES, R. C.
Region 1, Office of Director 3pp 14237:315 24X
Fiche: 50-277,82/07/16,8208050317

--8208050321 LER 82-015/01T-0 on 820703, operator observed no steam flow
indication on D main steam line. Caused by equalizing valve
being left open as result of instrument work done during
outage. Instrument checked to verify proper valving.
CODNEY, M J Philadelphia Electric Co. 82/07/16 Region 1,
Office of Director 1p 14237:318 24X Fiche: 50-277,82/07/16,
8208050317

--8208050329 LER 82-016/01T-0 on 820709, operator observed discrepancy
between indication of 1 of 4 A main steam line high flow
trip transmitters & other 3. Caused by equalizing valve
left open following instrument work during outage.
CODNEY, M J Philadelphia Electric Co 82/07/16 Region 1,
Office of Director 1p 14237:319 24X Fiche: 50-277,82/07/16,
8208050317.

8208100147 LER 82-014/03L-0 on 820701, after installation of modified
printed circuit board on drywell pressure transmitter
PT 2508B, transmitter PT 2508A lost signal. Caused by blown
fuses due to new board. Original board reinstalled.
CODNEY, M J Philadelphia Electric Co 82/07/31. HAYNES, R. C.
Region 1, Office of Director 1p. 14297:217. 24X
Fiche: 50-277,82/07/31,8208100147.

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8208040371 Releases public version of revisions to emergency plan
implementing procedures
FELTON, J M Division of Rules and Records 82/07/13. Document
Management Branch. 1p. 14224:062 24X Fiche: 50-277,82/07/13,
8208040371.

--8208040374 Forwards public version of revisions to emergency plan
implementing procedures, including Procedures EP-C-320 re
recovery phase implementation & EP-205A.1 re operation of
post-accident sampling station.
DALTROFF, B L Philadelphia Electric Co. 82/06/30. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 4pp 14224:064.
24X Fiche: 50-277,82/07/13,8208040371.

--8208040375 Public version of revision to emergency plan implementing
procedures, including Procedures EP-C-320 re recovery phase
implementation & EP-205A.1 re operation of post-accident
sampling station.
* Philadelphia Electric Co. 82/06/11. 110pp. 14224:068. 24X
Fiche: 50-277,82/07/13,8208040371.

8208050218 Forwards IE Insp Repts 50-277/82-12 & 50-278/82-12 on
820616. No noncompliance noted.
SMITH, G H Division of Emergency Preparedness & Operational Support.
82/07/21. BOYER, V S Philadelphia Electric Co 2pp. 14209:317.
24X Fiche: 50-277,82/07/21,8208050218

--8208050225 IE Insp Repts 50-277/82-12 & 50-278/82-12 on 820616. No
noncompliance noted. Major areas inspected: emergency
preparedness exercise.
TERC, N M Division of Emergency Preparedness & Operational
Support. 82/07/19. 10pp. 14209:319. 24X Fiche: 50-277,82/07/21,
8208050218.

P Operating license stage documents & correspondence

8207080064 Generic Ltr to all licensees of operating plants, applicants
for OL & holders of CP re Commission approved charter for
CROR. Svc list encl.
DIRKSB, W J. Office of the Executive Director for Operations.
82/07/02 Consolidated Edison Co. of New York. 93pp. 14194:001.
24X Fiche: 50-000,82/07/02,8207080064.

8208020451 Summarizes status of NRC review of NUREG-0737, item II.E.4.2
re containment purging & venting. SIB encl for guidance in
completing item. Info on purge/vent valve leakage tests also
encl.
STOLZ, J F Operating Reactors Branch 4. 82/07/07. BAUER, E. O.
Philadelphia Electric Co. 6pp 14180:172. 24X
Fiche: 50-277,82/07/07,8208020451.

--8208020454 Draft safety evaluation for containment purging & venting
during normal operation. Addl info required before review of
purge/vent sys can be completed.
* NRC - No Detailed Affiliation Given 82/07/07 5pp.
14180:178. 24X Fiche: 50-277,82/07/07,8208020451.

8208040378 Forwards revised model Tech Specs re reactor protection sys
power monitoring sys design mod.
STOLZ, J. F. Operating Reactors Branch 4 82/07/19. BAUER, E. O.
Philadelphia Electric Co. 2pp. 14224:187. 24X
Fiche: 50-277,82/07/19,8208040378.

--8208040379 Revised model Tech Specs 3/4.B.4.4 re electrical power sys
reactor protection sys electric power monitoring.
* NRC - No Detailed Affiliation Given 82/07/19. 1p. 14224:189.
24X Fiche: 50-277,82/07/19,8208040378

8208130041 Forwards Amend B5 to License DPR-56, safety evaluation &
notice of issuance & availability. Amend changes Tech Spec
to amend min critical power ratios during mid-cycle 5
operation.
FAIRFILL, M D Operating Reactors Branch 4. 82/07/29. BAUER, E. O.
Philadelphia Electric Co. 2pp. 14340:299. 24X
Fiche: 50-278,82/07/29,8208130041.

--8208130043 Amend B5 to License DPR-56, changing Tech Spec to amend min
critical power ratios during mid-cycle 5 operation.
STOLZ, J. F. Operating Reactors Branch 4. 82/07/29. 7pp.
14340:297. 24X Fiche: 50-278,82/07/29,8208130041.

--8208130047 Safety evaluation supporting Amend B5 to License DPR-56.
* Office of Nuclear Reactor Regulation, Director. 82/07/29. 4pp.
14340:304. 24X Fiche: 50-278,82/07/29,8208130041.

--8208130067 Notice of issuance & availability of Amend B5 to License
DPR-56.
MINER, B. Operating Reactors Branch 4. 82/07/29. 2pp. 14340:308.
24X Fiche: 50-278,82/07/29,8208130041.

8208060357 SOCIOECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS: PEACH
BOTTOM CASE STUDY. Docket Nos. 50-277 And 50-278
(Philadelphia Electric Company)
PIJAWKA, K. D. Mountain West Research, Inc. * Social Impact
Research, Inc. FIN B-6268. NUREG/CR-2749 V08. 82/07/31.
Division of Health, Siting & Environment. 215pp. Available at NTIS.
\$7.00. 14272:143. 24X Fiche: 50-277,82/07/31,8208060357.

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP &
applicants re submittal of documents to NRC. Summarizes 10CFR
Chapter I requirements & provides alternatives to
requirements. Svc list encl.
EISENHUT, D. O. Division of Licensing. 82/08/09. Consolidated
Edison Co. of New York. 1p. 14356:332. 24X Fiche: 50-000,82/08/09,
8208090194.

8208200065 Requests withdrawal of 820806 application for amends to
Licenses DPR-44 & DPR-56. Application submitted 790301 will
be amended later this yr to reflect guidance contained in
Tech Spec for gaseous radiation monitors.
DALTROFF, S. L. Philadelphia Electric Co. 82/08/16. DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 2pp. 14392:219.
24X Fiche: 50-277,82/08/16,8208200065.

8208270689 Informs that review of NUREG-0737, item II.K.3.15, "Mod Break
Detection Logic HPCI/Reactor Core Isolation Cooling,"
completed. Reactor core isolation cooling sys adequate. Safety
evaluation encl.
STOLZ, J. F. Operating Reactors Branch 4. 82/08/17. BAUER, E. O.
Philadelphia Electric Co. 4pp. 14683:069. 24X
Fiche: 50-277,82/08/17,8208270689.

Iter 1E 4.2 on containment purge & vent sys. per 820707
request for info
DALTROFF, S. L. Philadelphia Electric Co. 82/08/26 STOLZ, J. F.
Operating Reactors Branch 4 19pp 14669 303 24X
Fiche 50-277, 82/08/26, 8208310096

noncompliance noted. Major areas inspected: Emergency
preparedness exercise
TERC, N. H., CROCKER, H. W. Division of Emergency Preparedness &
Operational Support 82/07/19 10pp 14209 319 24X
Fiche 50-277, 82/07/21, 8208050218

Q. Inspection reports, IE Bulletins & correspondence

8206270075 FOIA request for sections of IE Insp Repts 50-277/81-07 &
50-278/81-09 not containing 10CFR2 790 info.
SPECTOR, C. Technical Analysis Corp. 81/06/29 Office of
Administration 1p 14528 133 24X Fiche 50-277, 82/06/29,
8206270075

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
Leakage." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16.
Consolidated Edison Co. of New York 87pp. 14356 274 24X
Fiche 50-000, 82/07/16, 8204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19,
Michigan, Univ. of 112pp. 14398 001 24X Fiche 50-000, 82/07/19,
8204210395

8208020264 Forwards IE Insp Repts 50-277/82-08 & 50-278/82-08 on
820426-29 & 0513-14 & notice of violation
MARTIN, T. Y. Division of Engineering & Technical Programs. 82/07/19.
DALTROFF, S. L. Philadelphia Electric Co. 2pp. 14152 263 24X
Fiche 50-277, 82/07/19, 8208020264.

--8208020270 Notice of violation from insp on 820426-29 & 0513-14.
MARTIN, T. Y. Division of Engineering & Technical Programs
82/07/19 2pp. 14152 263 24X Fiche 50-277, 82/07/19, 8208020264.

--8208020278 IE Insp Repts 50-277/82-08 & 50-278/82-08 on 820426-29 &
0513-14 Noncompliance noted: failure to follow radiation
protection procedures, to perform surveys & to instruct
workers on radiation conditions
NIMITZ, R. L., ROWE, C. A., GREENMAN, E. O. Division of Engineering &
Technical Programs. 82/07/16 26pp 14152 267 24X
Fiche 50-277, 82/07/19, 8208020264.

8208230444 Responds to FOIA request for sections of IE Insp Repts
50-277/82-07 & 50-278/82-09 not containing 10CFR2 790 info.
Forwards requested info. Documents also available in PDR.
FELTON, J. M. Division of Rules and Records. 82/07/19 ROSENBAUM, D.
Technical Analysis Corp. 1p. 14528 134 24X Fiche 50-277, 82/07/19,
8208230444

--8208230467 Nonproprietary version of notice of violation from insp on
810301-0407.
BRUNNER, E. J. Division of Resident & Project Inspection. 81/07/01.
3pp. 14528 138 24X Fiche 50-277, 82/07/19, 8208230444.

--8208230470 Nonproprietary version of notice of violation from insp on
810301-0407.
BRUNNER, E. J. Division of Resident & Project Inspection. 81/07/01.
1p. 14528 141 24X Fiche 50-277, 82/07/19, 8208230444.

--8208230473 Nonproprietary version of IE Insp Repts 50-277/81-07 &
50-278/81-09 on 810301-0407. Noncompliance noted: failure to
have adequate radwaste collection procedures & to follow
administrative procedures for rods.
COWGILL, C. J., BLOUGH, A. R., REYNOLDS, S. D. Reactor Projects Section
28 81/06/01 31pp. 14528 142 24X Fiche 50-277, 82/07/19,
8208230444.

8204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon
Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20.
Consolidated Edison Co. of New York. 112pp. 14381 001 24X
Fiche 50-000, 82/07/20, 8204210396.

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride
Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards.
82/07/20. Consolidated Edison Co. of New York. 71pp. 14387 276
24X Fiche 50-000, 82/07/20, 8204210397

8208050218 Forwards IE Insp Repts 50-277/82-12 & 50-278/82-12 on
820616 No noncompliance noted
SMITH, O. H. Division of Emergency Preparedness & Operational Support
82/07/21. BOYER, V. S. Philadelphia Electric Co. 2pp. 14209 317
24X Fiche 50-277, 82/07/21, 8208050218

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check
Valve Failures." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22
Consolidated Edison Co. of New York. 112pp. 14194 321 24X
Fiche 50-000, 82/07/22, 8204210398

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in
Vicinity of Drained & Open RCS." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23
Consolidated Edison Co. of New York. 122pp. 14380 115 24X
Fiche 50-000, 82/07/23, 8204210401.

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube
Support Pin Failures at Westinghouse PWRs." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23
Consolidated Edison Co. of New York. 127pp. 14194 120 24X
Fiche 50-000, 82/07/23, 8204210402

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping
at Certain Westinghouse PWR Power Plants." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26
Consolidated Edison Co. of New York. 121pp. 14357 013 24X
Fiche 50-000, 82/07/26, 8204210403.

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in
Fuel Storage Pool." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28
Consolidated Edison Co. of New York. 122pp. 14357 146 24X
Fiche 50-000, 82/07/28, 8204210405.

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From
Baffle Water-Jet Impingement." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/05.
Consolidated Edison Co. of New York. 117pp. 14388 201 24X
Fiche 50-000, 82/08/05, 8204210407

8208030049 Forwards IE Enforcement Conference Repts 50-277/82-17 &
50-278/82-15 on 820722
STAROBETSKY, R. Division of Project & Resident Programs. 82/08/10
DALTROFF, S. L. Philadelphia Electric Co. 2pp. 14590 297 24X
Fiche 50-277, 82/08/10, 8208030049

--8208030051 IE Enforcement Conference Repts 50-277/82-17 & 50-278/82-15
on 820722 No noncompliance noted. Major areas discussed:
findings of previous insps re health physics program &
primary containment integrity.
BLOUGH, A. R., MCCABE, E. C. Division of Project & Resident Programs
82/08/04 3pp. 14598 299 24X Fiche 50-277, 82/08/10, 8208030049

R. Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective
dose exposures in 1981 for operating nuclear power plants &
analyzing said info. Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A.
Critical Mass Energy Project. Bpp. 14679 208 24X
Fiche 50-000, 82/07/13, 8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power
Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp.
14679 216 24X Fiche 50-000, 82/07/13, 8208270010.

8208190098 Forwards monthly operating reports for Jul 1982
CDONEY, M. J. Philadelphia Electric Co. 82/08/13. Director's
Office, Office of Inspection and Enforcement. 1p. 14383 164 24X
Fiche 50-277, 82/08/13, 8208190098

--8208190102 Monthly operating reports for Jul 1982.
ALDEN, W. M. Philadelphia Electric Co. 82/08/11. 9pp. 14383 165
24X Fiche 50-277, 82/08/13, 8208190098.

DOCKET 50-280 BARRY POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8208030218 Forwards IE Insp Repts 50-280/82-13 & 50-281/82-13 on
820601-02. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 82/07/07.
LEASBURG, R. H. Virginia Electric & Power Co. 2pp. 14159 331 24X
Fiche 50-280, 82/07/07, 8208030218.

--B208030201 IE Insp Repts 50-280/B2-13 & 50-281/B2-13 on B20601-02 No noncompliance noted. Major areas inspected: emergency planning, specifically interface between licensee & Region 3 at emergency response facility.
TAYLOR, P. A. Division of Project & Resident Programs JENKINS, O. R.
Division of Emergency Preparedness & Operational Support.
B2/07/07. 4pp. 14159. 333. 24X Fiche: 50-280, B2/07/07, B208030218

B208030521 Ack receipt of B20624 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-280/B2-05 & 50-281/B2-05.
LEWIS, R. C. Division of Project & Resident Programs. B2/07/27.
LEASBURG, R. H. Virginia Electric & Power Co. 1p. 14163. 130. 24X
Fiche: 50-280, B2/07/27, B208030521

--B208030534 Responds to NRC B20525 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-280/B2-05 & 50-281/B2-05. Corrective actions task force formed in Mar 1982 to perform complete revision of emergency plan.
LEASBURG, R. H. Virginia Electric & Power Co. B2/06/24.
O'REILLY, J. P. Region 2, Office of Director. 13pp. 14163. 131. 24X
Fiche: 50-280, B2/07/27, B208030534

--B208030561 Forwards list of items that should be improved re emergency preparedness program. Some corrective actions in progress prior to B20315-26 site visit.
O'REILLY, J. P. Region 2, Office of Director. B2/04/06.
LEASBURG, R. H. Virginia Electric & Power Co. 13pp. 14163. 147. 24X
Fiche: 50-280, B2/07/27, B208030561

--B208030574 IE Emergency Preparedness Appraisal Repts 50-280/B2-05 & 50-281/B2-05 on B20315-26 Noncompliance noted: deficiencies in emergency plan re training, procedures & initial dose assessment.
HUFFMAN, G. N., MCFARLAND, C. R., MARSTON, R. R. Division of Emergency Preparedness & Operational Support. B2/05/21. 48pp. 14163. 160. 24X
Fiche: 50-280, B2/07/27, B208030574

B208190097 Provides status of eight items identified in NRC B10213 ltr as unresolved fire protection issues.
LEASBURG, R. H. Virginia Electric & Power Co. B2/08/13. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARQA, B. A. Operating Reactors Branch 1. 2pp. 14383. 136. 24X
Fiche: 50-280, B2/08/13, B208190097

B208240315 Forwards changes to security plans. Changes withheld (ref 10CFR2.790).
LEASBURG, R. H. Virginia Electric & Power Co. B2/08/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARQA, B. A. Operating Reactors Branch 1. 1p. 14520. 350. 24X
Fiche: 50-000, B2/08/23, B208240315.

P. Operating license stage documents & correspondence

B207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR. Bvc list encl.
DIRCKE, W. J. Office of the Executive Director for Operations. B2/07/02. Consolidated Edison Co. of New York. 93pp. 14194. 001. 24X
Fiche: 50-000, B2/07/02, B207080064.

B208250483 Approves B20713 request for routes to be used for transporting spent fuel.
SHERR, T. B. Material Transfer Safeguards Licensing Branch. B2/07/28.
LEASBURG, R. H. Virginia Electric & Power Co. 1p. 14562. 260. 24X
Fiche: 50-280, B2/07/28, B208250483

B208030444 Suppl 1 to B01028 application for amend to Licenses DPR-32 & DPR-37 modifying auxiliary bldg ventilation sys & expanding control room air filtration sys. Requests 30 days to implement Tech Specs.
LEASBURG, R. H. Virginia Electric & Power Co. B2/07/29. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARQA, B. A. Operating Reactors Branch 1. 3pp. 14153. 320. 24X
Fiche: 50-280, B2/07/29, B208030444

--B208030448 Proposed Tech Spec changes re auxiliary bldg ventilation sys & control room air filtration sys.
* Virginia Electric & Power Co. B2/07/29. 19pp. 14195. 323. 24X
Fiche: 50-280, B2/07/29, B208030448

B208040245 SOCIOECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS: BARRY CASE STUDY. Docket Nos. 50-280 And 50-281. (Virginia Electric Power And Light Company)
FLYNN, J. Social Impact Research, Inc. * Mountain West Research, Inc. FIN 8-6268. NUREG/CR-2749 V11. B2/07/31. Division of Health, Siting & Environment. 182pp. Available at NTIS. \$6.50. 14233. 001. 24X
Fiche: 50-280, B2/07/31, B208040245.

B208090101 Suppl 1 to B20316 & Q628 applications for amend to Licenses DPR-32 & DPR-37, correcting inadvertent administrative error on Tech Spec 6.4-4 to reflect revised list of procedures & persons designated for approval in Section 6.4.E.
LEASBURG, R. H. Virginia Electric & Power Co. B2/08/03. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARQA, B. A. Operating Reactors Branch 1. 2pp. 14269. 247. 24X
Fiche: 50-280, B2/08/03, B208090101

--B208090103 Proposed Tech Spec Pages 6.4-4 & 6.4-5, reflecting revised list of procedures & persons designated for approval in Sections 6.4.E & 6.4.F.
* Virginia Electric & Power Co. B2/08/03. 2pp. 14269. 249. 24X
Fiche: 50-280, B2/08/03, B208090101.

B208100110 Forwards calculations indicating that relative humidity in lab testing used charcoal samples from auxiliary ventilation sys does not exceed 76.25% upon entering Category I filter train.
LEASBURG, R. H. Virginia Electric & Power Co. B2/08/05. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARQA, B. A. Operating Reactors Branch 1. 25pp. 14298. 106. 24X
Fiche: 50-280, B2/08/05, B208100110.

B208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements Bvc list encl.
EISENHUT, D. Q. Division of Licensing. B2/08/09. Consolidated Edison Co. of New York. 1p. 14356. 332. 24X
Fiche: 50-000, B2/08/09, B208090194.

B208120283 Application for amend to Licenses DPR-32 & DPR-37, changing Tech Spec 6.4.E.4 & correcting administrative error in B20803 amend application re assistant health physics supervisor or health physicist.
LEASBURG, R. H. Virginia Electric & Power Co. B2/08/09. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARQA, B. A. Operating Reactors Branch 1. 2pp. 14324. 311. 24X
Fiche: 50-280, B2/08/09, B208120283.

--B208120289 Proposed Tech Spec 6.4.E.4 re assistant health physics supervisor or health physicist.
* Virginia Electric & Power Co. B2/08/09. 1p. 14324. 313. 24X
Fiche: 50-280, B2/08/09, B208120289

B208190195 Responds to NRC request for addl info re Generic Ltr B1-14 concerning seismic qualification of auxiliary feedwater sys. Revised Sketch 12846.01-MKB-3 will be forwarded when available.
LEASBURG, R. H. Virginia Electric & Power Co. B2/08/13. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARQA, B. A. Operating Reactors Branch 1. 3pp. 14499. 070. 24X
Fiche: 50-280, B2/08/13, B208190195.

B208230280 Application for amend to Licenses DPR-32 & DPR-37 changing Tech Spec to reflect degraded voltage protection sys mod.
LEASBURG, R. H. Virginia Electric & Power Co. B2/08/17. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARQA, B. A. Operating Reactors Branch 1. 4pp. 14512. 250. 24X
Fiche: 50-280, B2/08/17, B208230280

--B208230284 Proposed Tech Specs 4.6-2 & Tables 3.7-2, 3.7-4 & 4.1-1 re degraded voltage protection sys.
* Virginia Electric & Power Co. B2/08/17. 4pp. 14512. 254. 24X
Fiche: 50-280, B2/08/17, B208230280.

B208250346 Forwards oversize Sketch 12846.01-MKB-3 re seismic qualification of auxiliary feedwater sys ref in B20813 ltr. Aperture card is available in PDR.
LEASBURG, R. H. Virginia Electric & Power Co. B2/08/20. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARQA, B. A. Operating Reactors Branch 1. 1p. 14541. 001. 24X
Fiche: 50-280, B2/08/20, B208250346

B208270076 Advises of revised commitment date to B30101 re completion of reactor coolant sampling sys, per Generic Ltr B2-05 & NUREG-0737, Item II. B.3. Delay due to need for const of environmentally controlled encl around monitoring panels.
LEASBURG, R. H. Virginia Electric & Power Co. B2/08/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. EISENHUT, D. Q. Division of Licensing. 3pp. 14563. 130. 24X
Fiche: 50-280, B2/08/23, B208270076.

Q. Inspection reports, IE Bulletins & correspondence

B208030218 Forwards IE Insp Repts 50-280/B2-13 & 50-281/B2-13 on B20601-02. No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. B2/07/07.
LEASBURG, R. H. Virginia Electric & Power Co. 2pp. 14159. 331. 24X
Fiche: 50-280, B2/07/07, B208030218.

noncompliance noted Major areas inspected: emergency planning, specifically interface between licensee & Region 3 at emergency response facility
TAYLOR, P. A. Division of Project & Resident Programs JENKINS, O. R. Division of Emergency Preparedness & Operational Support
82/07/07. 4pp. 14159. 333 24X Fiche. 50-280. 82/07/07. 82080305218.

50-281/82-03 on 820315-25 Noncompliance noted deficiencies in emergency plan re training, procedures & initial dose assessment
HUFFMAN, G. N., MCFARLAND, C. R., MARSTON, R. R. Division of Emergency Preparedness & Operational Support 82/05/21 48pp. 14163 160 24X Fiche. 50-280. 82/07/27. 8208030521

8204210393 IE Info Notice B2-23. "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co. of New York 87pp. 14356 274. 24X Fiche. 50-000. 82/07/16. 8204210393

8204210395 IE Info Notice B1-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19 Michigan Univ. of. 112pp 14358 001 24X Fiche 50-000. 82/07/19. 8204210395.

8204210396 IE Info Notice B2-25. "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20. Consolidated Edison Co. of New York. 112pp 14381:001. 24X Fiche 50-000. 82/07/20. 8204210396

8204210397 IE Info Notice B2-24. "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Consolidated Edison Co. of New York 71pp. 14357 276 24X Fiche. 50-000. 82/07/20. 8204210397

8204210398 IE Info Notice B2-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co. of New York 112pp. 14194:321. 24X Fiche. 50-000. 82/07/22. 8204210398

8204210401 IE Info Notice B2-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York. 122pp. 14380:119. 24X Fiche. 50-000. 82/07/23. 8204210401.

8204210402 IE Info Notice B2-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co. of New York. 127pp. 14194. 120. 24X Fiche. 50-000. 82/07/23. 8204210402.

8204210403 IE Info Notice B2-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26 Consolidated Edison Co. of New York. 121pp. 14357 013. 24X Fiche. 50-000. 82/07/26. 8204210403.

8208030521 Ack receipt of 820624 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-280/82-03 & 50-281/82-03
LEWIS, R. C. Division of Project & Resident Programs. 82/07/27. LEASBURG, R. H. Virginia Electric & Power Co. 1p. 14163:130. 24X Fiche. 50-280. 82/07/27. 8208030521.

--8208030534 Responds to NRC 820525 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-280/82-03 & 50-281/82-03 Corrective actions: task force formed in Mar 1982 to perform complete revision of emergency plan.
LEASBURG, R. H. Virginia Electric & Power Co. 82/06/24 O'REILLY, J. P. Region 2, Office of Director 13pp 14163:131. 24X Fiche: 50-280. 82/07/27. 8208030521.

--8208030546 Forwards IE Emergency Preparedness Appraisal Repts 50-280/82-03 & 50-281/82-03 on 820315-26. Planned changes for correcting each deficiency due within 120 days of receipt of ltr.
O'REILLY, J. P. Region 2, Office of Director. 82/05/25. LEASBURG, R. H. Virginia Electric & Power Co. 3pp. 14163:144. 24X Fiche: 50-280. 82/07/27. 8208030521.

--8208030561 Forwards list of items that should be improved re emergency preparedness program. Some corrective actions in progress prior to 820315-26 site visit.
O'REILLY, J. P. Region 2, Office of Director. 82/04/06 LEASBURG, R. H. Virginia Electric & Power Co. 13pp. 14163. 147. 24X Fiche: 50-280. 82/07/27. 8208030521.

8204210405 IE Info Notice B2-31. "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York. 122pp. 14357 146 24X Fiche. 50-000. 82/07/28. 8204210405.

8208030615 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/82-09 & 50-281/82-09
O'REILLY, J. P. Region 2, Office of Director 82/07/28 LEASBURG, R. H. Virginia Electric & Power Co. 1p 14161:138. 24X Fiche. 50-280. 82/07/28. 8208030615

--8208030622 Responds to NRC 820616 ltr re violations noted in IE Insp Repts 50-280/82-09 & 50-281/82-09 Corrective actions repaired relief valve & revised health physics & radioactive release notification procedures.
LEASBURG, R. H. Virginia Electric & Power Co. 82/07/16 O'REILLY, J. P. Region 2, Office of Director 3pp 14161:139. 24X Fiche. 50-280. 82/07/28. 8208030615

--8208030626 Forwards IE Insp Repts 50-280/82-09 & 50-281/82-09 on 820419-23 & notice of violation
O'REILLY, J. P. Region 2, Office of Director. 82/06/16 LEASBURG, R. H. Virginia Electric & Power Co. 2pp 14161:144. 24X Fiche. 50-280. 82/07/28. 8208030615

--8208030630 Notice of violation from insp on 820419-23
* Region 2, Office of Director 82/06/16 2pp 14161 146 24X Fiche. 50-280. 82/07/28. 8208030615

--8208030635 IE Insp Repts 50-280/82-09 & 50-281/82-09 on 820419-23. Noncompliance noted: exceeded instantaneous Tech Spec limit for gaseous waste; failure to perform adequate evaluation of unplanned release & failure to promptly notify NRC.
HOSEY, C. M., BARR, K. P. Division of Engineering & Technical Programs 82/05/28. 7pp. 14161:148 24X Fiche 50-280. 82/07/28. 8208030615.

8208260424 Ack receipt of util 820609 ltr & payment of civil penalty. Based on review of incidents, no basis for remission or mitigation of penalty identified.
LIEBERMAN, J. Enforcement Staff 82/07/29. LEASBURG, R. H. Virginia Electric & Power Co. 3pp. 15574:313. 24X Fiche. 50-280. 82/07/29. 8208260424.

8208160402 Responds to IE Bulletin 82-02. "Degradation of Threaded Fasteners in RCPB of PWR Plants." Info provided re use of lubricants & injection sealants & leakage bolted connections.
LEASBURG, R. H. Virginia Electric & Power Co. 82/07/30. O'REILLY, J. P. Region 2, Office of Director. 3pp. 14347:359. 24X Fiche: 50-000. 82/07/30. 8208160402.

8204210407 IE Info Notice B2-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/03. Consolidated Edison Co. of New York. 117pp. 14388 201. 24X Fiche: 50-000. 82/08/03. 8204210407.

8208300195 Responds to NRC 820714 ltr requesting written documentation on installation of flow restricting orifices in auxiliary feedwater sys in ref to IE Bulletin 80-04. Orifices installed under Design Change Package 80-575 & completed 810708.
LEASBURG, R. H. Virginia Electric & Power Co. 82/08/23. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARQA, S. A. Operating Reactors Branch 1. 1p. 14595:357. 24X Fiche: 50-280. 82/08/23. 8208300195

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A. Critical Mass Energy Project. 8pp. 14679 208. 24X Fiche: 50-000. 82/07/13. 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp. 14679:216. 24X Fiche: 50-000. 82/07/13. 8208270010

--0200270103 Forwards "Recorded Annual Whole Body Exposures CY81," per 10CFR20.402 (FASB) (R) H Virginia Electric & Power Co 02/02/79 HALLIR,N H Office of Management and Program Analysis 1p 14679 312 24X Fiche 50 000, 02/02/79, 0200270103

--0200270112 "Recorded Annual Whole Body Exposures CY81" Virginia Electric & Power Co 02/02/79 1p 14679 313 24X Fiche 50 000, 02/02/79, 0200270112

0200120203 Forwards monthly operating rept for June 1982 (FASB) (R) H Virginia Electric & Power Co 02/02/79 HALLIR,N H Office of Resource Management, Director 1p 14334 222 24X Fiche 50 200, 02/02/79, 0200120203

--0200120204 Monthly operating rept for June 1982 (FASB) (R) H Virginia Electric & Power Co 02/02/79 1p 14326 221 24X Fiche 50 200, 02/02/79, 0200120204

B Reportable occurrences, IIRs & related correspondence

0200270660 Forwards IIRs H1 005703H-0 & H1 006703H-0 WILSON, J L Virginia Electric & Power Co 02/02/80 O'REILLY, J P Region 2, Office of the Director 1p 14603 109 24X Fiche 50 200, 02/02/80, 0200270660

0200270674 IIR H1 005703H-0 on 010301, radiation monitor recorder RR 173 found printing erratically Caused by dirty slide wire resistor in circuit that controls positioning of printing device Resistor cleaned & recorder returned to svc WILSON, J L Virginia Electric & Power Co 02/02/80 Region 2, Office of the Director (02/02/80) 2pp 14603 190 24X Fiche 50 200, 02/02/80, 0200270660

0200270677 IIR H1 006703H-0 on 010306, alarm output for component cooling water radiation monitor RR 173 10A found to be greater than twice background Caused by instrument drift Monitor reset in proper output & returned to svc WILSON, J L Virginia Electric & Power Co 02/02/80 Region 2, Office of the Director (02/02/80) 2pp 14603 192 24X Fiche 50 200, 02/02/80, 0200270660

0200030283 Forwards IIRs H2 027703H-0 & H2 027703H-0 WILSON, J L Virginia Electric & Power Co 02/02/76 O'REILLY, J P Region 2, Office of the Director 1p 14336 261 24X Fiche 50 200, 02/02/76, 0200030283

--0200030289 IIR H2 027703H-0 on 020629, during 75% power, signal from loop A steam pressure transmitter PT 1 A23 failed low Cause not determined Feedwater diaphragm placed in trip Transmitters replaced & tested WILSON, J L Virginia Electric & Power Co 02/02/76 Region 2, Office of the Director 2pp 14336 264 24X Fiche 50 200, 02/02/76, 0200030289

--0200030294 IIR H2 027703H-0 on 020711, during periodic test A control rods from cabinet JAC did not respond to demand signal Caused by faulty phase control card Card replaced & periodic test completed WILSON, J L Virginia Electric & Power Co 02/02/76 Region 2, Office of the Director 2pp 14336 267 24X Fiche 50 200, 02/02/76, 0200030294

0200060200 Forwards IIRs H4 028703H-0 & H2 028703H-0 WILSON, J L Virginia Electric & Power Co 02/02/76 O'REILLY, J P Region 2, Office of the Director 1p 14336 001 24X Fiche 50 200, 02/02/76, 0200060200

--0200060208 IIR H2 028703H-0 on 020701, w/unit at full power, B curve cooling monitor displayed erratic indications Caused by failed relay on plug in module on circuit board A failed component replaced Module returned to circuit board WILSON, J L Virginia Electric & Power Co 02/02/76 Region 2, Office of the Director 2pp 14336 002 24X Fiche 50 200, 02/02/76, 0200060208

--0200060218 IIR H2 028703H-0 on 020703, alarm chest revealed that amp reading for heat tracing panel 9 circuit 208 was below acceptance criteria Caused by excessive heat Defective heat tracing replaced & tested WILSON, J L Virginia Electric & Power Co 02/02/76 Region 2, Office of the Director 2pp 14336 004 24X Fiche 50 200, 02/02/76, 0200060200

0200060030 Forwards incident reporting sys rept re effects of fire protection sys activation on safety-related equipment & seismic qualification of safety-related sys for transmission to NRC

NICHOLSON, C Director's Office 02/07/79 LAFLEUR, J D Office of International Programs, Director 2pp 14244 313 24X Fiche 50 000, 02/07/79, 0200060030

0200120166 Forwards IIRs H2-069703H-0 & 02-042703H-0 WILSON, J L Virginia Electric & Power Co 02/08/02 O'REILLY, J P Region 2, Office of the Director 1p 14319 180 24X Fiche 50 200, 02/08/02, 0200120166

0200120170 IIR H2-069703H-0 on 020706, charging pump A found leaking oil Water found in tube oil Caused by leak in tube in charging pump tube oil cooler A & B pump coolers interchanged & A pump returned to svc WILSON, J L Virginia Electric & Power Co 02/08/02 Region 2, Office of the Director 2pp 14319 181 24X Fiche 50 200, 02/08/02, 0200120166

0200120175 IIR H2 042703H-0 on 020706, main steam line snubber found w oil in reservoir Caused by leaking rod seal due to improper installation Spare snubber tested & installed WILSON, J L Virginia Electric & Power Co 02/08/02 Region 2, Office of the Director 2pp 14319 183 24X Fiche 50 200, 02/08/02, 0200120166

0200120110 Forwards updated IIRs H1-047703H-1 & H2 047703H-1 WILSON, J L Virginia Electric & Power Co 02/08/02 O'REILLY, J P Region 2, Office of the Director 1p 14327 017 24X Fiche 50 200, 02/08/02, 0200120110

0200120112 Updated IIR H1-047703H-1 on 010910, following reactor trip while returning to power, specific activity of RCR indicated dose equivalent 1-131 level greater than Tech Spec limit Caused by fuel element defect in reactor core WILSON, J L Virginia Electric & Power Co 02/08/02 Region 2, Office of the Director 2pp 14327 018 24X Fiche 50 200, 02/08/02, 0200120110

0200120116 Updated IIR H2 047703H-1 on 020419, at 100% power, charging pump svc water pump 1 RR P 10B found w/zero discharge pressure Caused by loss of suction to pumps due to increased use of svc water by chillers Pump operation restored WILSON, J L Virginia Electric & Power Co 02/08/02 Region 2, Office of the Director 2pp 14327 021 24X Fiche 50 200, 02/08/02, 0200120110

0200100071 RI on 020721, rate of exchange of condenser cooling water outlet temp reached max of 12 F/hour exceeding max rate of change of 3 F/hour per Tech Spec 4.14 A.3 Caused by loss of electrical power to four of eight circulating water pumps (FASB) (R) H Virginia Electric & Power Co 02/08/02 DENTON, H H Office of Nuclear Reactor Regulation, Director VANDER, B A Operating Reactors Branch 1 1p 14296 101 24X Fiche 50 200, 02/08/02, 0200100071

02-0160268 Forwards IIRs H2 042703H-0 & H2 042703H-0 WILSON, J L Virginia Electric & Power Co 02/08/06 O'REILLY, J P Region 2, Office of the Director 1p 14336 107 24X Fiche 50 200, 02/08/06, 0200160268

0200160278 IIR H2 042703H-0 on 020713, post reactor trip specific activity sample of RCR indicated dose equivalent 1-131 level greater than Tech Spec Caused by fuel defects in reactor core Accelerated sampling frequency implemented WILSON, J L Virginia Electric & Power Co 02/08/06 Region 2, Office of the Director 2pp 14336 108 24X Fiche 50 200, 02/08/06, 0200160268

0200160285 IIR H2 047703H-0 on 020713, w/unit at 100% power, performance of PT-27 revealed amperage reading for heat tracing panel 10, circuit 6A below acceptance criteria Caused by defective heat tracing due to excessive heat Heat tracing replaced WILSON, J L Virginia Electric & Power Co 02/08/06 Region 2, Office of the Director 2pp 14336 194 24X Fiche 50 200, 02/08/06, 0200160268

0200160529 FNO-11-02 092 on 020808, Xe-133 gaseous radioactivity from ventilation sys exhaust exceeded controlled release rate No particulate or iodine activity released No personnel contamination occurred MOSEY, C H, BARR, M P Region 2, Office of the Director 02/08/09 2pp 14336 146 24X Fiche 50 200, 02/08/09, 0200160529

0200030032 Forwards IIRs H2-044703H-0 & H2 064703H-0 WILSON, J L Virginia Electric & Power Co 02/08/20 O'REILLY, J P Region 2, Office of the Director 1p 14399 103 24X Fiche 50 200, 02/08/20, 0200030032

--0200030037 IIR H2 044703H-0 on 020720, operators noted RMBT temp indicators reading 44 F & 46 F Caliber of channels revealed 46 F correct & above limit Caused by one inoperable refrigeration unit WILSON, J L Virginia Electric & Power Co 02/08/20 Region 2, Office of the Director 2pp 14399 104 24X Fiche 50 200, 02/08/20, 0200030032

DOCKETED ITEMS

--8208300340 LER 82-084/01T-0 on 820808, during venting of charging pump A via charcoal filter to ventilation sys. venting evolution resulted in max instantaneous release rate being exceeded
WILSON, J. L. Virginia Electric & Power Co 82/08/20 Region 2.
Office of Director 3pp 14599 107 24x Fiche 50-280. 82/08/20.
8208300332

8208310118 PNJ-11-82-099 on 820826, controlled radioactive gaseous release rate exceeded Tech Specs during sampling of waste gas stripper surge drum at primary sample tank Cause not stated Estimated 3 2 Ci Xe-133 released
HOSEY, C. M., BARR, K. P. Region 2, Office of Director. 82/08/27 2pp
14695 082 24x Fiche 50-280. 82/08/27. 8208310118

DOCKET 50-281 SLARRY POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8208030218 Forwards IE Insp Repts 50-280/82-13 & 50-281/82-13 on 820601-02 No noncompliance noted
DANCE, H. C. Division of Project & Resident Programs 82/07/07
LEASBURG, R. H. Virginia Electric & Power Co 2pp 14159 331 24x
Fiche 50-280. 82/07/07. 8208030218

--8208030221 IE Insp Repts 50-280/82-13 & 50-281/82-13 on 820601-02 No noncompliance noted Major areas inspected emergency planning, specifically interface between licensee & Region 3 & emergency response facility
TAYLOR, P. A. Division of Project & Resident Programs. 82/07/07
4pp. 14159 333 24x Fiche 50-280. 82/07/07. 8208030218

8208030521 Ack receipt of 820624 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Repts 50-280/82-05 & 50-281/82-05
LEWIS, R. C. Division of Project & Resident Programs 82/07/27
LEASBURG, R. H. Virginia Electric & Power Co 1p 14163 130. 24x
Fiche 50-280. 82/07/27. 8208030521

--8208030534 Responds to NRC 820525 ltr re violations noted in IE Emergency Preparedness Appraisal Repts 50-280/82-05 & 50-281/82-05 Corrective actions test force formed in Mar 1982 to perform complete revision of emergency plan
LEASBURG, R. H. Virginia Electric & Power Co. 82/06/24.
O'REILLY, J. P. Region 2, Office of Director 13pp 14163 131
24x Fiche 50-280. 82/07/27. 8208030521

--8208030546 Forwards IE Emergency Preparedness Appraisal Repts 50-280/82-05 & 50-281/82-05 on 820315-26 Planned changes for correcting each deficiency due within 120 days of receipt of ltr.
O'REILLY, J. P. Region 2, Office of Director. 82/05/25.
LEASBURG, R. H. Virginia Electric & Power Co 3pp. 14163 144 24x
Fiche 50-280. 82/07/27. 8208030521

--8208030561 Forwards list of items that should be improved re emergency preparedness program Some corrective actions in progress prior to 820315-26 site visit
O'REILLY, J. P. Region 2, Office of Director. 82/04/06
LEASBURG, R. H. Virginia Electric & Power Co 13pp. 14163 147
24x Fiche 50-280. 82/07/27. 8208030521

--8208030574 IE Emergency Preparedness Appraisal Repts 50-280/82-05 & 50-281/82-05 on 820315-26 Noncompliance noted deficiencies in emergency plan re training, procedure & initial dose assessment
HUFFMAN, Q. N., JENKINS, Q. R. Division of Emergency Preparedness & Operational Support. 82/05/21 48pp. 14163 160. 24x
Fiche 50-280. 82/07/27. 8208030521

8208190097 Provides status of eight items identified in NRC 810213 ltr as unresolved fire protection issues.
LEASBURG, R. H. Virginia Electric & Power Co 82/08/13 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director VARQA, S. A.
Operating Reactors Branch 1 2pp. 14383 136 24x
Fiche 50-280. 82/08/13. 8208190097.

8208240315 Forwards changes to security plans. Changes withheld (ref 10CFR 2.790).
LEASBURG, R. H. Virginia Electric & Power Co. 82/08/23 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. VARQA, S. A.
Operating Reactors Branch 1 1p 14520 350. 24x
Fiche 50-000. 82/08/23. 8208240315

P Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR Svc list encl.
DIRCKS, W. J. Office of the Executive Director for Operations.

8208030444 Suppl to 801028 application for amend to Licensee DPR-32 & DPR-37 modifying auxiliary bldg ventilation sys & expanding control room air filtration sys Requests 30 days to implement Tech Specs
LEASBURG, R. H. Virginia Electric & Power Co 82/07/29 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director VARQA, S. A.
Operating Reactors Branch 1 3pp 14155 320 24x
Fiche 50-280. 82/07/29. 8208030444

--8208030448 Proposed Tech Spec changes re auxiliary bldg ventilation sys & control room air filtration sys
* Virginia Electric & Power Co 82/07/29 19pp 14155 323 24x
Fiche 50-280. 82/07/29. 8208030444

8208040245 SOCIOECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS SURRY CASE STUDY Docket Nos 50-280 And 50-281 (Virginia Electric Power And Light Company)
FLYNN, J. Social Impact Research, Inc * Mountain West Research, Inc FIN 8-626B NUREG/CR-2749 VII 82/07/31. Division of Health, Siting & Environment 182pp Available at NTIS \$6 50 14233 001. 24x Fiche 50-280. 82/07/31. 8208040245.

8208090101 Suppl to 820316 & 0628 applications for amend to Licensee DPR-32 & DPR-37, correcting inadvertent administrative error on Tech Spec 6 4-4 to reflect revised list of procedures & persons designated for approval in Section 6 4 E
LEASBURG, R. H. Virginia Electric & Power Co 82/08/03 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director VARQA, S. A.
Operating Reactors Branch 1 2pp 14269 247 24x
Fiche 50-280. 82/08/03. 8208090101

--8208090105 Proposed Tech Spec Pages 6 4-4 & 6 4-5, reflecting revised list of procedures & persons designated for approval in Sections 6 4 E & 6 4 F.
* Virginia Electric & Power Co 82/08/03 2pp. 14269 247 24x
Fiche 50-280. 82/08/03. 8208090101

8208100110 Forwards calculations indicating that relative humidity in lab testing used charcoal samples from auxiliary ventilation sys does not exceed 76 25% upon entering Category 1 filter train
LEASBURG, R. H. Virginia Electric & Power Co 82/08/05 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director VARQA, S. A.
Operating Reactors Branch 1 25pp 14298 106. 24x
Fiche 50-280. 82/08/05. 8208100110

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summaries 10CFR Chapter 1 requirements & provides alternatives to requirements Svc list encl.
EISENHUT, D. Q. Division of Licensing 82/08/09 Consolidated
Edison Co. of New York. 1p 14396 332 24x Fiche 50-000. 82/08/09. 8208090194

8208120283 Application for amend to Licensee DPR-32 & DPR-37, changing Tech Spec 6 4 E 4 & correcting administrative error in 820803 amend application re assistant health physics supervisor or health physicist
LEASBURG, R. H. Virginia Electric & Power Co 82/08/09 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. VARQA, S. A.
Operating Reactors Branch 1 2pp 14324 311 24x
Fiche 50-280. 82/08/09. 8208120283

--8208120289 Proposed Tech Spec 6 4 E 4 re assistant health physics supervisor or health physicist.
* Virginia Electric & Power Co 82/08/09 1p. 14324 313. 24x
Fiche 50-280. 82/08/09. 8208120283

8208190195 Responds to NRC request for addl info re Generic Ltr 81-14 concerning seismic qualification of auxiliary feedwater sys. Revised Sketch 12046 01-MKB-3 will be forwarded when available.
LEASBURG, R. H. Virginia Electric & Power Co 82/08/13 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director VARQA, S. A.
Operating Reactors Branch 1 3pp. 14499 070 24x
Fiche 50-280. 82/08/13. 8208190195.

8208230280 Application for amend to Licensee DPR-32 & DPR-37 changing Tech Specs to reflect degraded voltage protection sys mod
LEASBURG, R. H. Virginia Electric & Power Co 82/08/17 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director VARQA, S. A.
Operating Reactors Branch 1 4pp 14512 250. 24x
Fiche 50-280. 82/08/17. 8208230280

--8208230284 Proposed Tech Specs 4 6-2 & Tables 3 7-2.3 7-4 & 4 1-1 re degraded voltage protection sys
* Virginia Electric & Power Co 82/08/17 4pp. 14512 254. 24x
Fiche 50-280. 82/08/17. 8208230280

0200250146 Forwards oversize Hatch 12044 01 PMU 3 re seismic qualification of auxiliary feedwater eye ref in 020013 1tr
 Apparure card is available in PMU
 LEASBURG, R H Virginia Electric & Power Co 02/00/20 DENTON, H H
 Office of Nuclear Reactor Regulation, Director VARQA, H A
 Operating Reactors Branch 1 1p 14541 001 24X
 Fiche 50 200.02/00/20.0200250146

0200270076 Advice of revised commitment date to 020101 re completion of reactor coolant sampling system Generic 1tr 02 05 &
 NUREG-0717 Item 11 H 1 Delay due to need for cost of environmentally controlled unit around monitoring panels
 LEASBURG, R H Virginia Electric & Power Co 02/00/20 DENTON, H H
 Office of Nuclear Reactor Regulation, Director 1100007, D Q
 Division of Licensing 1pp 14561 130 24X Fiche 50 200.02/00/20.0200270076

0 Inspection Reports, 0 Bulletins & correspondence

0200030210 Forwards 02 Insp Repts 50 200/02 11 & 50 201/02 17 on 020601-02 No noncompliance noted
 DANCE, H C Division of Project & Resident Programs 02/07/07
 LEASBURG, R H Virginia Electric & Power Co 3pp 14159 111 24X
 Fiche 50 200.02/07/07.0200030210

0200030221 02 Insp Repts 50 200/02 11 & 50 201/02 17 on 020601 02 No noncompliance noted Major Areas inspected emergency planning, specifically interface between licensees & Region 1 at emergency response facility
 TAYLOR, P A Division of Project & Resident Programs 020000, Q H
 Division of Emergency Preparedness & Operational Support
 02/07/07 4pp 14159 111 24X Fiche 50 200.02/07/07.0200030221

0204210193 02 Info Notice 02 23. "Main Steam Isolation Valve (MSIV) Leakage" - Nrc list encl
 JORDAN, E I Division of Engineering & Quality Assurance 02/07/16
 Consolidated Edison Co of New York 12pp 14156 274 24X
 Fiche 50 000.02/07/16.0204210193

0204210195 02 Info Notice 02 24, Part 1, 00pp 1. "Clarification of Placement of Personnel Monitoring Device for Internal Radiation" - Nrc list encl
 JORDAN, E I Division of Engineering & Quality Assurance 02/07/19
 Michigan Univ of 11pp 14158 001 24X Fiche 50 000.02/07/19.0204210195

0204210196 02 Info Notice 02 25. "Failures of Miller Actuators Upon Gradual Loss of Air Pressure" - Nrc list encl
 JORDAN, E I Division of Engineering & Quality Assurance 02/07/20
 Consolidated Edison Co of New York 11pp 14161 001 24X
 Fiche 50 000.02/07/20.0204210196

0204210197 02 Info Notice 02 24. "Water Leaking from 02 Heatsouride Overpacks" - Nrc list encl
 JORDAN, E I Division of Engineering & Quality Assurance 02/07/20
 Consolidated Edison Co of New York 2pp 14157 274 24X
 Fiche 50 000.02/07/20.0204210197

0204210198 02 Info Notice 02 26. "Helic & 0001 Forging Exhaust Chert Valve Failures" - Nrc list encl
 JORDAN, E I Division of Engineering & Quality Assurance 02/07/22
 Consolidated Edison Co of New York 11pp 14194 121 24X
 Fiche 50 000.02/07/22.0204210198

0204210401 02 Info Notice 02 20. "Hydrogen Explosion While Grinding in Vicinity of Unrated & Open RCH" - Nrc list encl
 JORDAN, E I Division of Engineering & Quality Assurance 02/07/21
 Consolidated Edison Co of New York 12pp 14380 115 24X
 Fiche 50 000.02/07/21.0204210401

0204210402 02 Info Notice 02 27. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Neelinghouse PMHs" - Nrc list encl
 JORDAN, E I Division of Engineering & Quality Assurance 02/07/21
 Consolidated Edison Co of New York 12pp 14194 120 24X
 Fiche 50 000.02/07/21.0204210402

0204210403 02 Info Notice 02 20. "Loss of Thermal Sleeves in RCH Piping at Certain Neelinghouse PMH Power Plants" - Nrc list encl
 JORDAN, E I Division of Engineering & Quality Assurance 02/07/26
 Consolidated Edison Co of New York 12pp 14357 013 24X
 Fiche 50 000.02/07/26.0204210403

0200030521 Act receipt of 020624 1tr informing NRC of steps taken to correct violations noted in 02 Emergency Preparedness Appraisal Repts 50 200/02 05 & 50 201/02 05
 LEWIS, H C Division of Project & Resident Programs 02/07/27
 LEASBURG, R H Virginia Electric & Power Co 1p 14163 130 24X
 Fiche 50 200.02/07/27.0200030521

0200030524 Responds to NRC 020524 1tr re violations noted in 02 Emergency Preparedness Appraisal Repts 50 200/02 05 & 50 201/02 05 Corrective actions task force formed in Mar 1902 to perform complete revision of emergency plan
 LEASBURG, R H Virginia Electric & Power Co 02/06/24
 O'REILLY, J P Region 2, Office of Director 13pp 14161 131 24X
 Fiche 50 200.02/07/27.0200030524

0200030526 Forwards 02 Emergency Preparedness Appraisal Repts 50 200/02 05 & 50 201/02 05 on 020115 26 Planned changes for correcting each deficiency due within 120 days of receipt of 1tr
 O'REILLY, J P Region 2, Office of Director 02/05/25
 LEASBURG, R H Virginia Electric & Power Co 3pp 14161 144 24X
 Fiche 50 200.02/07/27.0200030526

0200030528 Forwards list of items that should be improved re emergency preparedness program Some corrective actions in progress prior to 020115 26 site visit
 O'REILLY, J P Region 2, Office of Director 02/04/04
 LEASBURG, R H Virginia Electric & Power Co 13pp 14161 147 24X
 Fiche 50 200.02/07/27.0200030528

0200030529 02 Emergency Preparedness Appraisal Repts 50 200/02 05 & 50 201/02 05 on 020115 26 Noncompliance noted deficiencies in emergency plan re training, procedures & initial dose assessment
 JORDAN, E I, MEAHAN, E R, MAHFFER, R Division of Emergency Preparedness & Operational Support 02/05/21 40pp 14161 160 24X
 Fiche 50 200.02/07/27.0200030529

0204210405 02 Info Notice 02 21. "Overexposure of Diver During Work in Fuel Storage Pool" - Nrc list encl
 JORDAN, E I Division of Engineering & Quality Assurance 02/07/20
 Consolidated Edison Co of New York 12pp 14157 146 24X
 Fiche 50 000.02/07/20.0204210405

0204210415 Act receipt of 020716 1tr informing NRC of steps taken to correct violations noted in 02 Insp Repts 50 200/02 09 & 50 201/02 09
 O'REILLY, J P Region 2, Office of Director 02/07/20
 LEASBURG, R H Virginia Electric & Power Co 1p 14161 130 24X
 Fiche 50 200.02/07/20.0204210415

0200030622 Responds to NRC 020616 1tr re violations noted in 02 Insp Repts 50 200/02 09 & 50 201/02 09 Corrective actions repaired relief valve & revised health physics & radioactive release notification procedures
 LEASBURG, R H Virginia Electric & Power Co 02/07/16
 O'REILLY, J P Region 2, Office of Director 8pp 14161 139 24X
 Fiche 50 200.02/07/20.0200030622

0200030626 Forwards 02 Insp Repts 50 200/02 09 & 50 201/02 09 on 020419 23 020419 23 notice of violation
 O'REILLY, J P Region 2, Office of Director 02/06/14
 LEASBURG, R H Virginia Electric & Power Co 2pp 14161 144 24X
 Fiche 50 200.02/07/20.0200030626

0200030628 Notice of violation from Insp on 020419 23
 * Region 2, Office of Director 02/06/14 3pp 14161 146 24X
 Fiche 50 200.02/07/20.0200030628

0200030635 02 Insp Repts 50 200/02 09 & 50 201/02 09 on 020419 23 Noncompliance noted exceeded instantaneous tech spec limit for gaseous waste failure to perform adequate evaluation of unplanned release & failure to promptly notify NRC
 JORDAN, E I, HARRIS, P Division of Engineering & Technical Programs 02/05/20 3pp 14161 148 24X
 Fiche 50 200.02/07/20.0200030635

020160402 Responds to 02 Bulletin 02 02. "Degradation of Threaded Fasteners in NCRB of PMH Plants" Info provided re use of lubricants & injection sealants & leakage bolted connections
 LEASBURG, R H Virginia Electric & Power Co 02/07/30
 O'REILLY, J P Region 2, Office of Director 3pp 14347 359 24X
 Fiche 50 000.02/07/30.020160402

0204210407 02 Info Notice 02 27. "Fuel Rod Degradation Resulting from Baffle Water Jet Impingement" - Nrc list encl
 JORDAN, E I Division of Engineering & Quality Assurance 02/09/03
 Consolidated Edison Co of New York 11pp 14380 201 24X
 Fiche 50 000.02/08/03.0204210407

0200030095 Responds to NRC 020714 1tr requesting written documentation on installation of flow restricting orifices in auxiliary feedwater eye in ref to 02 Bulletin 02 04 Orifices installed under Design Change Package 02 575 & completed 010700
 LEASBURG, R H Virginia Electric & Power Co 02/08/23
 DENTON, H H Office of Nuclear Reactor Regulation, Director VARQA, H A
 Operating Reactors Branch 1 1p 14395 357 24X
 Fiche 50 200.02/08/23.0200030095

DOCKETED ITEMS

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A
FELTON, J.M. Division of Rules and Records. 82/07/13 UDELL, R.A.
Critical Mass Energy Project Bpp. 14679 20B 24X
Fiche: 50-000. 82/07/13. 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities For CY81."
* NRC - No Detailed Affiliation Given 82/07/13 4Bpp
14679-216. 24X Fiche: 50-000. 82/07/13. 8208270010

--8208270303 Forwards "Recorded Annual Whole Body Exposures CY81," per 10CFR20.407.
LEASBURG, R.H. Virginia Electric & Power Co. 82/02/19.
HALLER, N.M. Office of Management and Program Analysis. 1p.
14679-312 24X Fiche: 50-000. 82/07/13. 8208270010.

--8208270312 "Recorded Annual Whole Body Exposures CY81."
* Virginia Electric & Power Co. 82/02/19 1p 14679-313. 24X
Fiche: 50-000. 82/07/13. 8208270010

8208120203 Forwards monthly operating reports for June 1982.
LEASBURG, R.H. Virginia Electric & Power Co. 82/07/15 HALLER, N.M.
Office of Resource Management, Director 1p 14326 222. 24X
Fiche: 50-280. 82/07/15. 8208120203

--8208120204 Monthly operating reports for June 1982
JONES, V.H. Virginia Electric & Power Co. 82/07/08 39pp
14326-223 24X Fiche: 50-280. 82/07/15. 8208120203.

B Reportable occurrences, LERs & related correspondence

8208030463 Forwards LERs 82-040/03L-0 & 82-041/03L-0.
WILSON, J.L. Virginia Electric & Power Co. 82/07/26. O'REILLY, J.P.
Region 2, Office of Director. 1p 14199-285. 24X
Fiche: 50-281. 82/07/26. 8208030463.

--8208030470 LER 82-040/03L-0 on 820703, containment spray chemical addition tank level found to be 5% below Tech Spec requirement. Cause resulted from minor leaks through one or both isolation valves. Tank level restored.
WILSON, J.L. Virginia Electric & Power Co. 82/07/26. Region 2,
Office of Director. 2pp. 14199-286 24X Fiche: 50-281. 82/07/26. 8208030463.

--8208030477 LER 82-041/03L-0 on 820626, steam generator B level indication LI-2-486 drifted high. Caused by wire broken at splice. Splice replaced & channel returned to svc.
WILSON, J.L. Virginia Electric & Power Co. 82/07/26. Region 2,
Office of Director. 3pp. 14199-288 24X Fiche: 50-281. 82/07/26. 8208030463.

8208060200 Forwards LERs 82-078/03L-0 & 82-038/03L-0.
WILSON, J.L. Virginia Electric & Power Co. 82/07/26 O'REILLY, J.P.
Region 2, Office of Director. 1p. 14239-001. 24X
Fiche: 50-280. 82/07/26. 8208060200.

--8208060218 LER 82-038/03L-0 on 820703, alarm check revealed that amp reading for heat tracing panel 9 circuit 20B was below acceptance criteria. Caused by excessive heat. Defective heat tracing replaced & tested.
WILSON, J.L. Virginia Electric & Power Co. 82/07/26. Region 2,
Office of Director. 2pp. 14239-004 24X Fiche: 50-280. 82/07/26. 8208060200.

8208060030 Forwards incident reporting sys repts re effects of fire protection sys actuation on safety-related equipment & seismic qualification of safety-related sys for transmission to NEA.
MICHELSON, C. Director's Office. 82/07/29 LAFLEUR, J.D. Office of International Programs, Director. 21pp. 14244-318. 24X
Fiche: 50-000. 82/07/29. 8208060030.

8208060327 Forwards incident reporting sys repts re spill of contaminated water & contamination of personnel in auxiliary bldg & failure of control rod guide tube support pins for transmittal to NEA.
MICHELSON, C. Director's Office. 82/07/29. LAFLEUR, J.D. Office of International Programs, Director. 17pp. 14281-234. 24X
Fiche: 50-000. 82/07/29. 8208060327.

8208120166 Forwards LERs 82-069/03L-0 & 82-042/03L-0.
WILSON, J.L. Virginia Electric & Power Co. 82/08/02 O'REILLY, J.P.
Region 2, Office of Director. 1p. 14319-150. 24X

--8208120175 LER 82-042/03L-0 on 820706, main steam line snubber found oil in reservoir. Caused by leaking rod seal due to improper installation. Spare snubber tested & installed.
WILSON, J.L. Virginia Electric & Power Co. 82/08/02. Region 2,
Office of Director. 2pp. 14319-153 24X Fiche: 50-280. 82/08/02. 8208120166.

8208100071 RO on 820721, rate of exchange of condenser cooling water outlet temp reached max of 12 F/hour exceeding max rate of change of 3 F/hour per Tech Spec 4.14 A.3. Caused by loss of electrical power to four of eight circulating water pumps.
LEASBURG, R.H. Virginia Electric & Power Co. 82/08/05. DENTON, H.R.
Office of Nuclear Reactor Regulation, Director. VAROA, S.A.
Operating Reactors Branch 1. 1p. 14296-181 24X
Fiche: 50-280. 82/08/05. 8208100071.

8208160268 Forwards LERs 82-082/03L-0 & 82-043/03L-0.
WILSON, J.L. Virginia Electric & Power Co. 82/08/06 O'REILLY, J.P.
Region 2, Office of Director. 1p. 14346-187. 24X
Fiche: 50-280. 82/08/06. 8208160268

--8208160265 LER 82-043/03L-0 on 820713, w/unit at 100% power, performance of PT-27 revealed amperage reading for heat tracing panel 10, circuit 6A below acceptance criteria. Caused by defective heat tracing due to excessive heat. Heat tracing replaced.
WILSON, J.L. Virginia Electric & Power Co. 82/08/06. Region 2,
Office of Director. 2pp. 14346-194. 24X Fiche: 50-280. 82/08/06. 8208160268.

8208200142 Forwards LER 82-046/03L-0 & updated LER 80-010/01X-1.
WILSON, J.L. Virginia Electric & Power Co. 82/08/13. O'REILLY, J.P.
Region 2, Office of Director. 1p. 14394-349. 24X
Fiche: 50-281. 82/08/13. 8208200142

--8208200153 LER 82-046/03L-0 on 820713, periodic test 2.9 revealed high steam flow trip setpoint for steam generator B comparator FC-2-485 was high & could not be adjusted. Caused by malfunctioning comparator. Comparator replaced.
WILSON, J.L. Virginia Electric & Power Co. 82/08/13. Region 2,
Office of Director. 2pp. 14394-350. 24X Fiche: 50-281. 82/08/13. 8208200142

--8208200169 Updated LER 80-010/01X-1 on 800721, containment gaseous & particulate radiation monitor found to have one automatic function incapable of operating during fuel movement. Caused by bypass of containment exhaust fan relay in design change.
WILSON, J.L. Virginia Electric & Power Co. 82/08/13. Region 2,
Office of Director. 2pp. 14394-352. 24X Fiche: 50-281. 82/08/13. 8208200142

8208300332 Forwards LERs 82-044/03L-0 & 82-084/01T-0.
WILSON, J.L. Virginia Electric & Power Co. 82/08/20. O'REILLY, J.P.
Region 2, Office of Director. 1p. 14399-103 24X
Fiche: 50-280. 82/08/20. 8208300332.

--8208300337 LER 82-044/03L-0 on 820720, operators noted RHWT temp indicators reading 44 F & 46 F. Calibr of channels revealed 46 F correct & above limit. Caused by one inoperable refrigeration unit.
WILSON, J.L. Virginia Electric & Power Co. 82/08/20. Region 2,
Office of Director. 3pp. 14399-104 24X Fiche: 50-280. 82/08/20. 8208300332.

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8208030038 Releases public version of revised emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 82/07/19. Document Management Branch. 1p. 14182-219. 24X Fiche: 50-282. 82/07/19. 8208030038.

--8208030090 Forwards public version of revised emergency plan implementing procedures, including Procedures F3-14.2 re operations emergency surveys & F3-B re recommendations for offsite protective actions.
MUSOLF, D.M. Northern States Power Co. 82/07/07. Region 2,
Office of Director. 1p. 14182-220. 24X Fiche: 50-282. 82/07/19. 8208030038.

--8208030091 Public version of revised emergency plan implementing procedures, including Procedures F3-14.2 re operations emergency surveys & F3-B re recommendations for offsite protective actions.
SCHUELKE, D.A. Northern States Power Co. 82/07/01. 175pp.
14182-221. 24X Fiche: 50-282. 82/07/19. 8208030038.

8208170399 Advises that exemption from fire protection scheduler requirements of 10CFR50 40(c) re emergency lighting cannot be granted based on 820920 request alone Complete chronology of Section III J implementation efforts requested
CLARK, R. A. Operating Reactors Branch 3 82/07/29 MUSBOLF, D. M.
Northern States Power Co 4pp. 14372 349 24X
Fiche 50-282, 82/07/29, 8208170399

8208260089 Releases public version of revised corporate emergency plan
FELTON, J. M. Division of Rules and Records 82/08/13 Document
Management Branch. 1p 14576 196 24X Fiche: 50-000, 82/08/13.
8208260089

--8208260315 Forwards public version of Revision 5 to corporate nuclear emergency plan Updated info on App C items identified in NRC
820504 ltr encl
LARSON, C. E. Northern States Power Co 82/08/02. Region 3.
Office of Director 4pp 14576 199 24X Fiche: 50-000, 82/08/13.
8208260089.

--8208260319 Public version of Revision 5 to corporate nuclear emergency plan
HUDSON, O. WARD, E. LARSON, C. E. Northern States Power Co.
82/08/02. 140pp 14576 203. 24X Fiche: 50-000, 82/08/13.
8208260089.

8208260353 Releases public version of revised emergency plan implementing procedures
FELTON, J. M. Division of Rules and Records. 82/08/13. Document
Management Branch. 1p. 14575 069 24X Fiche 50-000, 82/08/13.
8208260353

--8208260358 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1 2 re notifications & EPIP 1.1 5 re startup & operation of emergency operations facility
WARD, E. C. Northern States Power Co 82/08/11. Region 3. Office of Director. 1p. 14575 072. 24X Fiche: 50-000, 82/08/13.
8208260353

--8208260360 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1 2 re notifications & EPIP 1.1 5 re startup & operation of emergency operations facility.
* Northern States Power Co. 82/08/11. 72pp. 14575 073 24X
Fiche: 50-000, 82/08/13, 8208260353

8208300326 Provides addl info in support of util 820520 request for relief from schedule for completion of 10CFR50, App R, Section III J re emergency lighting nodes. Nodes will be implemented by 830101.
MUSBOLF, D. Northern States Power Co 82/08/23 Office of Nuclear Reactor Regulation, Director. BPP. 14599 086. 24X
Fiche: 50-282, 82/08/23, 8208300326

P Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CRQR. Bvc list encl.
DIRCKS, W. J. Office of the Executive Director for Operations.
82/07/02. Consolidated Edison Co. of New York. 93pp 14194 001.
24X Fiche: 50-000, 82/07/02, 8207080064.

8208020446 Provides results of post-implementation review of shift technical advisor training program. Program meets intent of NUREG-0737, Item II.A.1.1. In future, all new hires into program should have bachelor degree or equivalent.
CLARK, R. A. Operating Reactors Branch 3. 82/07/06. MUSBOLF, D. M.
Northern States Power Co 3pp. 14181 045 24X
Fiche: 50-282, 82/07/06, 8208020446.

8208020051 Forwards Amends 56 & 50 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability. Amend increases peak burnup limit.
GIANNI, D. C. Operating Reactors Branch 3. 82/07/16. MUSBOLF, D. M.
Northern States Power Co. 3pp. 14181 007. 24X
Fiche: 50-282, 82/07/16, 8208020051.

--8208020054 Amends 56 & 50 to Licenses DPR-42 & DPR-60, respectively, revising App A Tech Spec peak burnup limit from 41,830 to 47,000 MWD/MTU.
CLARK, R. A. Operating Reactors Branch 3. 82/07/16. 6pp.
14181 010. 24X Fiche: 50-282, 82/07/16, 8208020051.

--8208020056 Safety evaluation supporting Amends 56 & 50 to Licenses DPR-42 & DPR-60, respectively.
* Office of Nuclear Reactor Regulation, Director. 82/07/16. 5pp.
14181 016. 24X Fiche: 50-282, 82/07/16, 8208020051.

--8208020062 Notice of issuance & availability of Amends 56 & 50 to Licenses DPR-42 & DPR-60, respectively.
CLARK, R. A. Operating Reactors Branch 3 82/07/16. 2pp.
14181 021 24X Fiche 50-282, 82/07/16, 8208020051.

8208040642 Advises that plant operation in Cycle 7 acceptable w/thermal margins for core loadings containing mixture of TOPROD & Exxon std fuel assemblies.
CLARK, R. A. Operating Reactors Branch 3 82/07/22. MUSBOLF, D. M.
Northern States Power Co 2pp 14224 023 24X
Fiche 50-282, 82/07/22, 8208040642

--8208040646 Safety evaluation supporting thermal hydraulic margins for Exxon TOPROD for Cycle 7.
* Office of Nuclear Reactor Regulation, Director. 81/10/20. 2pp.
14224 025 24X Fiche 50-282, 82/07/22, 8208040642

--8208040651 Safety evaluation supporting thermal hydraulic margins for Exxon TOPROD for Cycle 7.
* Office of Nuclear Reactor Regulation, Director. 82/07/09. 3pp.
14224 027 24X Fiche 50-282, 82/07/22, 8208040642.

8208030228 Advises that Tech Spec change request re NUREG-0737, Items II.E.1.1 & II.E.1.2 concerning auxiliary feedwater sys will be submitted by 820919 Delay due to organizational changes, worked & Unit 2 outage
MUSBOLF, D. Northern States Power Co. 82/07/28 Office of Nuclear Reactor Regulation, Director. 1p. 14158 285 24X
Fiche 50-282, 82/07/28, 8208030228

8208110088 Forwards request for addl info re pressure & temp profiles outside containment as part of equipment environ qualification review to perform calculations for pipe breaks outside containment info requested within 30 days.
CLARK, R. A. Operating Reactors Branch 3. 82/07/29. MUSBOLF, D. M.
Northern States Power Co 4pp. 14329 357 24X
Fiche 50-282, 82/07/29, 8208110088.

8208100194 Advises that Exxon 820708 ltr transmitting XN-NF-82-49 (P) should be considered until response to TMI Item II.K.3.30. Method/model changes have been made where necessary
MUSBOLF, D. M. Northern States Power Co 82/08/03 Office of Nuclear Reactor Regulation, Director. 1p 14298 196 24X
Fiche: 50-282, 82/08/03, 8208100194.

8208100055 Forwards application for amend to Licenses DPR-42 & DPR-60, changing Tech Spec Table 4.1-2A for waiver of end-of-cycle monthly turbine valve test. Approval requested 2 months prior to Unit 1 refueling outage scheduled for 821113
MUSBOLF, D. Northern States Power Co. 82/08/06 Office of Nuclear Reactor Regulation, Director. 1p. 14296 224. 24X
Fiche: 50-282, 82/08/06, 8208100055.

--8208100062 Application for amend to Licenses DPR-42 & DPR-60, changing Tech Spec Table 4.1-2A for waiver of end-of-cycle turbine valve test. Description of proposed changes & reasons encl.
MUSBOLF, D. M. Northern States Power Co. 82/08/06. 3pp. 14296 224. 24X
Fiche: 50-282, 82/08/06, 8208100055

--8208100074 Revised Tech Spec Table 4.1-2A re min frequencies for equipment tests. Licensing fee determination encl.
* Northern States Power Co. 82/08/06 2pp. 14296 228 24X
Fiche: 50-282, 82/08/06, 8208100055.

8208090194 Generic ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Bvc list encl
EISENHUT, D. Q. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14356 332. 24X Fiche: 50-000, 82/08/09
8208090194.

8208120151 Forwards proprietary version, "Computer Program Control Procedure." NAP 5.01P. Procedure contains supplemental info to util reload methodology topical repts submitted 820212. Procedure withheld (ref 10CFR2.790). Affidavit encl.
MUSBOLF, D. Northern States Power Co. 82/08/09. Office of Nuclear Reactor Regulation, Director. 5pp. 14326 030 24X
Fiche: 50-282, 82/08/09, 8208120151.

8208200294 Forwards Revision 1 to application to amend OL & proposed Tech Spec changes re radiological effluent Tech Specs & environ monitoring.
MUSBOLF, D. Northern States Power Co. 82/08/13 Office of Nuclear Reactor Regulation, Director. 2pp. 14394 146. 24X
Fiche: 50-282, 82/08/13, 8208200294.

--8208200297 Revision 1 to application to amend OL, changing Tech Spec enhance radiological effluent & environ monitoring.
* Northern States Power Co 82/08/13. 3pp. 14394 148. 24X
Fiche: 50-282, 82/08/13, 8208200294.

--8208200298 Revisions 1 to proposed Tech Spec changes, enhancing radiological effluent & environ monitoring.
* Northern States Power Co 82/08/13 63pp 14394: 191. 24X
Fiche: 50-282, 82/08/13, 8208200294.

--8208200300 Revision 1 to "Offsite Dose Calculation Manual"
MUSOLF, D Northern States Power Co 82/08/13. 125pp 14394 214
24X Fiche: 50-282, 82/08/13, 8208200294.

8208230338 Forwards "Process Control Program for Solidification of
Residue from Liquid Sys." & proprietary pages to "Radwaste
Solidification Sys." Encls withheld (ref 10CFR2 790)
MUSOLF, D M Northern States Power Co. 82/08/13. Office of
Nuclear Reactor Regulation, Director 3pp 14513 196. 24X
Fiche 50-282, 82/08/13, 8208230338

8208200084 Forwards responses to 820603 questions re station electric
distribution sys voltage study Installation of second
startup transformer will provide flexible & reliable
distribution sys.
MUSOLF, D Northern States Power Co 82/08/17 Office of Nuclear
Reactor Regulation, Director 20pp 14393: 221. 24X
Fiche: 50-282, 82/08/17, 8208200084

8208240136 Advises that Tech Spec Section 3.3.A.1 (g) applies to safety
injection pump discharge cross-connect valves & other ECCS
valves. In response to NRC B11201 ltr Section work
instruction requires monthly surveillance of subv valves
MUSOLF, D M Northern States Power Co. 82/08/19. Office of
Nuclear Reactor Regulation, Director 1p 14519: 333 24X
Fiche 50-282, 82/08/19, 8208240136.

8208270294 Provides confirmation of info discussed in earlier telcons
re containment purging & venting during normal operation.
MUSOLF, D Northern States Power Co. 82/08/23 Office of Nuclear
Reactor Regulation, Director 4pp 14564: 178. 24X
Fiche: 50-282, 82/08/23, 8208270294

Q Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
Leakage." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/16
Consolidated Edison Co. of New York. 87pp 14355: 274. 24X
Fiche: 50-000, 82/07/16, 8204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/14.
Michigan Univ. of 112pp 14358 001. 24X Fiche: 50-000, 82/07/19,
8204210395

8208050508 Forwards IE Insp Repts 50-282/82-09 & 50-306/82-09 on
820601-30. No noncompliance noted
STREETER, J F Region 3, Office of Director 82/07/19 LARSON, C E
Northern States Power Co. 2pp 14214 061. 24X
Fiche: 50-282, 82/07/19, 8208050508

--8208050521 IE Insp Repts 50-282/82-09 & 50-306/82-09 on 820601-30.
No noncompliance noted Major areas inspected: plant
operation, maint, organization, surveillance, security, radiation
protection, LER followup & refueling activities
FEIERABEND, C D., BURGESS, B L., REYES, L. Region 3, Office of
Director. 82/07/15 9pp 14214 063. 24X Fiche 50-282, 82/07/19,
8208050508

8204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon
Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/20
Consolidated Edison Co. of New York. 112pp. 14381. 001. 24X
Fiche: 50-000, 82/07/20, 8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride
Overpacks." Svc list encl.
COBB, L I. Division of Fuel Facilities, Materials & Safeguards.
82/07/20 Consolidated Edison Co. of New York. 71pp. 14357: 276.
24X Fiche: 50-000, 82/07/20, 8204210397.

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check
Valve Failures." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/22
Consolidated Edison Co. of New York. 112pp. 14194: 321. 24X
Fiche 50-000, 82/07/22, 8204210398

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in
Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. 82/07/23
Consolidated Edison Co. of New York. 122pp. 14380: 115. 24X
Fiche: 50-000, 82/07/23, 8204210401

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD)
Support Pin Failures at Westinghouse PWRs." Svc list
JORDAN, E L Division of Engineering & Quality Assurance.
Consolidated Edison Co. of New York 127pp 14194
Fiche: 50-000, 82/07/23, 8204210402

8204210403 IE Info Notice 82-30, "Loss of Thermal Shield
at Certain Westinghouse PWR Power Plants." Svc list
JORDAN, E L Division of Engineering & Quality Assurance.
Consolidated Edison Co. of New York 121pp 14357
Fiche 50-000, 82/07/26, 8204210403

8204210405 IE Info Notice 82-31, "Overexposure of Diver
Fuel Storage Pool." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance.
Consolidated Edison Co. of New York 122pp 14357
Fiche 50-000, 82/07/28, 8204210405

8208100080 Responds to IE Bulletin 82-02, "Degradation
Fasteners in RCPB of PWR Plants." RCPB insps performed
regular intervals Few leakage problems experienced at
facility.
LARSON, C E Northern States Power Co 82/08/02. KE
Region 3, Office of Director 4pp 14296: 145 24X
Fiche 50-282, 82/08/02, 8208100080

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation
Baffle Water-Jet Impingement." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance.
Consolidated Edison Co. of New York 117pp. 14386
Fiche: 50-000, 82/08/03, 8204210407.

8208240037 Forwards Franklin Research Ctr request for
B11130 response to IE Bulletin 80-11, "Masonry Walls
Requested within 30 days
CLARK, R A Operating Reactors Branch 3 82/08/12
Northern States Power Co 5pp 14548 183 24X
Fiche: 50-282, 82/08/12, 8208240037

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detail
dose exposures in 1981 for operating nuclear power pl
analyzing said info. Forwards documents listed in App
FELTON, J M Division of Rules and Records 82/07/13
Critical Mass Energy Project. 8pp 14679: 208 24X
Fiche: 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear
Facilities for CY81"
* NRC - No Detailed Affiliation Given 82/07/13
14679 216. 24X Fiche 50-000, 82/07/13, 8208270010

--8208270209 Forwards annual rept of occupational radiation
CY81, per 10CFR20 407
SCHUELKE, D A Northern States Power Co 82/02/02
Management and Program Analysis 1p. 14679: 282
Fiche 50-000, 82/07/13, 8208270010

--8208270215 Annual occupational radiation exposure rep
* Northern States Power Co. 82/02/02 1p. 14679
Fiche 50-000, 82/07/13, 8208270010

8208270619 Forwards rept on number of personnel & man r
& job function for 1981, per NUREG-0737, Item 11, K. 3. 3.
MAYER, L O Northern States Power Co. 82/02/26. KEP
Region 3, Office of Director 1p. 14679: 342. 24X
Fiche: 50-000, 82/07/13, 8208270619.

--8208270626 Rept on number of personnel & man rem by u
for 1981
* Northern States Power Co 82/02/26 2pp 14679
Fiche 50-000, 82/07/13, 8208270619

8208130198 Forwards monthly operating repts for Jul 1982
MUSOLF, D Northern States Power Co 82/08/10. DI
Office of Inspection and Enforcement 1p. 14339: 105
Fiche: 50-282, 82/08/10, 8208130198.

--8208130202 Monthly operating repts for Jul 1982.
DUOSTAD, D Northern States Power Co. 82/08/04. S
24X Fiche: 50-282, 82/08/10, 8208130198.

S Reportable occurrences, LERs & related correspondence

8208020119 Forwards LER 82-011/03L-0.
MUSOLF, D Northern States Power Co. 82/07/20. Re
of Director 1p. 14142: 104. 24X Fiche: 50-282, 82/07/20

--8208020123 LER 82-011/03L-0 on 820622, motor-driven auxiliary feedwater pump 12 failed to start during surveillance test. Caused by installing self-cleaning oil filter backwards, allowing build up of sludge. Filter reversed.
HUNSTAD, A.A. Northern States Power Co. 82/07/20. Region 3, Office of Director. 1p. 14142 105. 24X Fiche: 50-285, 82/07/20, 8208020119.

DOCKET 50-284 IDAHO STATE UNIV. RESEARCH REACTOR

0 Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Enc 1 list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of. 112pp. 14358 001. 24X Fiche: 50-000, 82/07/19, 8204210395.

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8208030475 Forwards IE Safeguards Insp Rept 50-285/82-08 on 820813-14. No noncompliance noted. Rept withheld (ref 10CFR2 790).
BEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 82/07/19. JONES, W.C. Omaha Public Power District. 2pp. 14164 067. 24X Fiche: 50-285, 82/07/19, 8208030475.

8208060032 Releases public version of revision to emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 82/08/02. Document Management Branch. 1p. 14244 286. 24X Fiche: 50-285, 82/08/02, 8208060032.

--8208060034 Forwards public version of Revision 5 to Emergency Plan Implementing Procedure EPIP-08C-2, "Emergency Plan Activation" & Revision 2 to EPIP-EDF-18-1, "Offsite Radiological Surveys."
JONES, W.C. Omaha Public Power District. 82/07/22. BEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 1p. 14244 287. 24X Fiche: 50-285, 82/08/02, 8208060032.

--8208060036 Public version of Revision 5 to Emergency Plan Implementing Procedure EPIP-08C-2, "Emergency Plan Activation" & Revision 2 to EPIP-EDF-18-1, "Offsite Radiological Surveys." Revised table of contents encl.
* Omaha Public Power District. 82/07/15. 20pp. 14244 288. 24X Fiche: 50-285, 82/08/02, 8208060032.

8208120165 Approves 1982 emergency exercise scope scenario description transmitted w/820701 ltr. Item B of exercise objectives assumed not to include simulation of evacuation for nonessential personnel from vital & protected areas.
BEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 82/08/09. JONES, W.C. Omaha Public Power District. 1p. 14319 279. 24X Fiche: 50-285, 82/08/09, 8208120165.

--8208120168 Forwards 1982 emergency exercise scope scenario description in response to 820114 request.
JONES, W.C. Omaha Public Power District. 82/07/01. COLLINS, J.T. Region 4, Office of Director. 5pp. 14319 280. 24X Fiche: 50-285, 82/08/09, 8208120165.

8208160452 Forwards IE Safeguards Insp Rept 50-285/82-10 on 820504-05. No noncompliance noted. Rept withheld (ref 10CFR2 790).
BEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 82/08/10. JONES, W.C. Omaha Public Power District. 2pp. 14349 289. 24X Fiche: 50-285, 82/08/10, 8208160452.

8208310376 Advises that util design meets requirements of 10CFR30. App R, Items III.O.3 & III.L w/respect to safe shutdown in event of fire in control room or cable spreading room. BER revision encl.
CLARK, R.A. Operating Reactors Branch 3. 82/08/12. JONES, W.C. Omaha Public Power District. 5pp. 14697 123. 24X Fiche: 50-285, 82/08/12, 8208310376.

8208190170 Ack receipt of util 820722 ltr re changes to emergency plan implementing procedures. Confirmation of transmittal encl per request.
BEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 82/08/16. JONES, W.C. Omaha Public Power District. 1p. 14386 314. 24X Fiche: 50-285, 82/08/16, 8208190170.

--8208190172 Requests completion of encl transmittal sheets confirming receipt of util emergency plan implementing procedures.
JONES, W.C. Omaha Public Power District. 82/07/22. BEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 4pp. 14386 315. 24X Fiche: 50-285, 82/08/16, 8208190170.

8208240153 Requests clarification of 820601 ltr re exact location of emergency plan implementing procedure changes concerning deficiencies noted in IE emergency preparedness appraisal on 811207-16.
BEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 82/08/18. JONES, W.C. Omaha Public Power District. 1p. 14520 129. 24X Fiche: 50-285, 82/08/18, 8208240153.

8208270354 Confirms 820818 telcon re license. 820804 request for installation of health physics network & emergency notification sys telephones in permanent technical support ctr. Installation will take at least 60 days.
BEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 82/08/20. JONES, W.C. Omaha Public Power District. 2pp. 14565 078. 24X Fiche: 50-285, 82/08/20, 8208270354.

--8208270362 Requests installation of health physics network & emergency notification sys telephones in permanent technical support ctr by 820707.
JONES, W.C. Omaha Public Power District. 82/08/04. BEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 2pp. 14565 080. 24X Fiche: 50-285, 82/08/20, 8208270362.

J Insurance & indemnity information

8208310193 Forwards Endorsements 44 & 47 to MAELU Policy MF-63 & Endorsements 51-55 to NELLIA Policy MF-207.
PETERSEN, H.E. Omaha Public Power District. 82/08/26. DINI, T.J. Antitrust & Economic Analysis Branch (Utility Finance). 12pp. 14693 163. 24X Fiche: 50-285, 82/08/26, 8208310193.

K Utility Final Safety Analysis Report (FSAR) & amends

8208030549 Forwards Fort Calhoun 1 updated FSAR, incorporating plant mods & reflecting info & analyses submitted to NRC since previous submittal of FSAR. Affidavit & list of plant changes made under 10CFR50.59, but not previously reported, encl.
JONES, W.C. Omaha Public Power District. 82/07/22. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 14846 001. 24X Fiche: 50-285, 82/07/22, 8208030549.

--8208030554 Fort Calhoun 1 updated FSAR, Vols 1-7.
* Omaha Public Power District. 82/07/22. 2, 115pp. 14846 006. 24X Fiche: 50-285, 82/07/22, 8208030549.

8208030558 Chapter 1 to Fort Calhoun 1 updated FSAR, "Introduction & Summary."
* Omaha Public Power District. 82/07/22. 200pp. 14846 011. 24X Fiche: 50-285, 82/07/22, 8208030558.

8208030563 Chapter 2 to Fort Calhoun 1 updated FSAR, "Site & Environs."
* Omaha Public Power District. 82/07/22. 100pp. 14846 147. 24X Fiche: 50-285, 82/07/22, 8208030563.

8208030566 Chapter 3 to Fort Calhoun 1 updated FSAR, "Reactor."
* Omaha Public Power District. 82/07/22. 100pp. 14846 265. 24X Fiche: 50-285, 82/07/22, 8208030566.

8208030571 Chapter 4 to Fort Calhoun 1 updated FSAR, "RCB."
* Omaha Public Power District. 82/07/22. 100pp. 14847 011. 24X Fiche: 50-285, 82/07/22, 8208030571.

8208030575 Chapter 5 to Fort Calhoun 1 updated FSAR, "Structures."
* Omaha Public Power District. 82/07/22. 250pp. 14847 127. 24X Fiche: 50-285, 82/07/22, 8208030575.

8208030580 Chapter 6 to Fort Calhoun 1 updated FSAR, "Engineered Safeguards."
* Omaha Public Power District. 82/07/22. 78pp. 14847 354. 24X Fiche: 50-285, 82/07/22, 8208030580.

8208030584 Chapter 7 to Fort Calhoun 1 updated FSAR, "Instrumentation Control."
* Omaha Public Power District. 82/07/22. 100pp. 14848 064. 24X Fiche: 50-285, 82/07/22, 8208030584.

8208030590 Chapter 8 to Fort Calhoun 1 updated FSAR, "Electrical Sys."
* Omaha Public Power District. 82/07/22. 73pp. 14848 179. 24X Fiche: 50-285, 82/07/22, 8208030590.

8208030593 Chapter 9 to Fort Calhoun 1 updated FSAR, "Auxiliary Sys."
* Omaha Public Power District. 82/07/22. 190pp. 14848 247. 24X Fiche: 50-285, 82/07/22, 8208030593.

8208030601 Chapter 10 to Fort Calhoun 1 updated FSAR, "Steam & Power Conversion Sys."
* Omaha Public Power District. 82/07/22. 23pp. 14849 030. 24X Fiche: 50-285, 82/07/22, 8208030601.

B208030606 Chapter 11 to Fort Calhoun 1 updated FSAR, "Redwaste & Radiation Protection & Monitoring"
* Omaha Public Power District 82/07/22 100pp 14849 093. 24X
Fiche 50-285, 82/07/22, B208030606

B208030612 Chapter 12 to Fort Calhoun 1 updated FSAR, "Conduct of Operations"
* Omaha Public Power District 82/07/22 29pp 14849 154 24X
Fiche 50-285, 82/07/22, B208030612

B208030614 Chapter 13 to Fort Calhoun 1 updated FSAR, "Initial Tests & Operation"
* Omaha Public Power District 82/07/22 7pp 14849 183. 24X
Fiche 50-285, 82/07/22, B208030614

B208030619 Chapter 14 to Fort Calhoun 1 updated FSAR, "Safety Analysis"
* Omaha Public Power District 82/07/22 225pp 14849 190. 24X
Fiche 50-285, 82/07/22, B208030619

B208030623 Chapter 15 to Fort Calhoun 1 updated FSAR, "Tech Specs."
* Omaha Public Power District 82/07/22 1p 14850 076 24X
Fiche 50-285, 82/07/22, B208030623

B208030628 App A to Fort Calhoun 1 updated FSAR, "QA Program"
* Omaha Public Power District 82/07/22 38pp 14850 077 24X
Fiche 50-285, 82/07/22, B208030628

B208030632 App B to Fort Calhoun 1 updated FSAR, "Site Environ Studies"
* Omaha Public Power District 82/07/22 3pp 14850 115. 24X
Fiche 50-285, 82/07/22, B208030632

B208030634 App C to Fort Calhoun 1 updated FSAR, "Foundation Studies"
* Omaha Public Power District * Dames & Moore 82/07/22 101pp 14850 118 24X Fiche 50-285, 82/07/22, B208030634

B208030637 App D to Fort Calhoun 1 updated FSAR, "Pile Load Test Programs"
* Omaha Public Power District * Dames & Moore 82/07/22 100pp 14850 218 24X Fiche 50-285, 82/07/22, B208030637

B208030642 App E to Fort Calhoun 1 updated FSAR, "Qualifications & Resumes of Station Operating & Technical Personnel"
* Omaha Public Power District 82/07/22 12pp 14850 334. 24X
Fiche 50-285, 82/07/22, B208030642

B208030647 App F to Fort Calhoun 1 updated FSAR, "Classification of Structures & Equipment & Seismic Criteria"
* Omaha Public Power District 82/07/22 60pp 14850 346 24X
Fiche 50-285, 82/07/22, B208030647

B208030652 App G to Fort Calhoun 1 updated FSAR, "Responses to 70 Criteria"
* Omaha Public Power District 82/07/22 80pp 14851 044. 24X
Fiche 50-285, 82/07/22, B208030652

B208030657 App H to Fort Calhoun 1 updated FSAR, "Training Summaries of Fort Calhoun Station Unit 1 Related Personnel"
* Omaha Public Power District 82/07/22 75pp 14851 128 24X
Fiche 50-285, 82/07/22, B208030657

B208030661 App I to Fort Calhoun 1 updated FSAR, "Startup Manual"
* Omaha Public Power District 82/07/22 50pp 14851 209. 24X
Fiche 50-285, 82/07/22, B208030661

B208030664 App J to Fort Calhoun 1 updated FSAR, "Supplementary Meteorological Correlations"
* Omaha Public Power District 82/07/22 1p 14851 271. 24X
Fiche 50-285, 82/07/22, B208030664

B208030668 App K to Fort Calhoun 1 updated FSAR, "Revised Analysis of Fort Calhoun ECCS Performance"
* Omaha Public Power District 82/07/22 1p 14851 272. 24X
Fiche 50-285, 82/07/22, B208030668

B208030673 App L to Fort Calhoun 1 updated FSAR, "Predicted Creep Collapse Behavior for Fort Calhoun Fuel Cladding"
* Omaha Public Power District 82/07/22 2pp 14851 273. 24X
Fiche 50-285, 82/07/22, B208030673

B208030675 App M to Fort Calhoun 1 updated FSAR, "Postulated High Energy Line Rupture Outside Containment"
* Omaha Public Power District 82/07/22 30pp 14851 275. 24X
Fiche 50-285, 82/07/22, B208030675

B208030679 App N to Fort Calhoun 1 updated FSAR, "Risk Sys"
* Omaha Public Power District 82/07/22 4pp 14851 212. 24X Fiche 50-285, 82/07/22, B208030679

B208240177 Requests act of receipt of Copies B5 & B6 forwarded under separate cover Transmittal sheets completed & returned Other responsible person should designated on transmittal sheets
JONES, W C Omaha Public Power District 82/08/12
Division of Resident, Reactor Project & Engineering
14521 212 24X Fiche 50-285, 82/08/12, B208240177

P. Operating license stage documents & correspondence

B207080064 Generic Ltr to all licensees of operating for OL & holders of CP re Commission approved changes CROR Svc list encl.
DIRCKS, W J Office of the Executive Director P.O. Box 14521
82/07/02 Consolidated Edison Co. of New York
24X Fiche 50-000, 82/07/02, B207080064

B208040083 Requests schedule for responding to evaluation guidelines re NUREG-0737, Item II B.3, "Post-Accident Sampling Sys." within 20 days.
CLARK, R A Operating Reactors Branch 3 82/07/14
Omaha Public Power District 10pp 14228 309 24X
Fiche 50-285, 82/07/14, B208040083

B208050012 Forwards safety evaluation identifying the App J containment leak testing review NRC review pending receipt of licensee info. Response due in 30 days. Supplemental SER will be issued upon review completion.
CLARK, R A Operating Reactors Branch 3 82/07/23
Omaha Public Power District 3pp 14243 073 24X
Fiche 50-285, 82/07/23, B208050012

--B208050013 Safety evaluation re App J review. Three identified
* Operating Reactors Branch 3 82/07/23 3pp 14243 073 24X
Fiche 50-285, 82/07/23, B208050013

B208090038 Forwards request for addl info needed to request re spent fuel storage mod to increase storage capacity.
CLARK, R A Operating Reactors Branch 3 82/07/26
Omaha Public Power District 3pp 14301 109. 24X
Fiche 50-285, 82/07/26, B208090038

B208130038 Advises that procedure for natural circulation implemented effective 820630. Procedure will be modified to incorporate use of reactor gas vent sys. Sys could significantly reduce time to achieve cold shutdown.
JONES, W C Omaha Public Power District 82/08/05
Operating Reactors Branch 3 1p 14335 074 24X
Fiche 50-285, 82/08/05, B208130038

B208090194 Generic Ltr B2-14 to all reactor licensees applicants re submittal of documents to NRC. Summary Chapter 1 requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D Q Division of Licensing 82/08/09
Edison Co. of New York 1p 14356 332 24X
Fiche 50-000, 82/08/09, B208090194

B208130248 Responds to B20714 request for schedule post-accident sampling sys info per TMI Action Item 1. Requested info substantially deviates from NUREG-0737 criteria. Info will be provided by 821130.
JONES, W C Omaha Public Power District 82/08/09
Operating Reactors Branch 3 2pp 14333 108. 24X
Fiche 50-285, 82/08/09, B208130248

B208240165 Forwards rept on cleanup following introduction of Tesco Type 46 hydraulic fluid into spool due to failure of fuel insp stand hydraulic.
JONES, W C Omaha Public Power District 82/08/18
Operating Reactors Branch 4 22pp 14520 107. 24X
Fiche 50-285, 82/08/18, B208240165

B208240178 Responds to B20714 ltr requesting addl info re Item II K.3.17, "Rept on Outages of ECCS." LERs re outages encl.
JONES, W C Omaha Public Power District 82/08/19
Operating Reactors Branch 3 36pp 14521 215. 24X
Fiche 50-285, 82/08/19, B208240178

8208310159 Forwards addl info re 820312 application for increased spent fuel storage capacity at facility, in response to NRC 820726 ltr Summary of 820623 telcon & four oversize drawings encl. Aperture cards are available in PDR JONES, W.C. Omaha Public Power District 82/08/27 CLARK, R.A. Operating Reactors Branch 3 5pp 14687 257. 24X Fiche: 30-285, 82/08/27, 8208310159.

0 Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/16 Consolidated Edison Co. of New York 87pp 14356 274. 24X Fiche: 30-000, 82/07/16, 8204210393.

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19 Michigan Univ. of. 112pp. 14388 001. 24X Fiche: 30-000, 82/07/19, 8204210395.

8208030475 Forwards IE Safeguards Insp Rept 50-285/82-08 on 820513-14. No noncompliance noted. Rept withheld (ref 10CFR2.790). SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs 82/07/19 JONES, W.C. Omaha Public Power District. 2pp 14164 067 24X Fiche: 30-285, 82/07/19, 8208030475

8204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/20 Consolidated Edison Co. of New York. 112pp. 14381 001. 24X Fiche: 30-000, 82/07/20, 8204210396.

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl. COBB, L.I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Consolidated Edison Co. of New York. 71pp. 14357 276. 24X Fiche: 30-000, 82/07/20, 8204210397

8204210398 IE Info Notice 82-26, "RCIC & IPCI Turbine Exhaust Check Valve Failures." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/22 Consolidated Edison Co. of New York. 112pp. 14194 321 24X Fiche: 30-000, 82/07/22, 8204210398

8208090040 Forwards safety evaluation of util analysis of main steam line break w/continued feedwater addition, submitted per IE Bulletin 80-04, Analysis acceptable CLARK, R.A. Operating Reactors Branch 3 82/07/22 JONES, W.C. Omaha Public Power District. 2pp. 14283 327. 24X Fiche: 30-285, 82/07/22, 8208090040.

--8208090042 Safety evaluation supporting util analysis submitted per IE Bulletin 80-04 of main steam line break w/continued feedwater addition, submitted per IE Bulletin 80-04. * NRC - No Detailed Affiliation Given. 82/07/22 7pp. 14283 329. 24X Fiche: 30-285, 82/07/22, 8208090040.

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York. 122pp. 14380 115. 24X Fiche: 30-000, 82/07/23, 8204210401.

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23 Consolidated Edison Co. of New York. 127pp. 14194 120. 24X Fiche: 30-000, 82/07/23, 8204210402.

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/26 Consolidated Edison Co. of New York. 121pp. 14357 013. 24X Fiche: 30-000, 82/07/26, 8204210403.

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/28 Consolidated Edison Co. of New York. 122pp. 14387 146. 24X Fiche: 30-000, 82/07/28, 8204210405.

8208180070 Forwards IE Insp Rept 50-285/82-12 on 820601-30 & notice of violation. SEIDLE, W.C. Region 4, Office of Director. 82/07/28 JONES, W.C. Omaha Public Power District. 4pp. 14377 042. 24X Fiche: 30-285, 82/07/28, 8208180070.

--8208180074 Notice of violation from insp on 820601-30. * Region 4, Office of Director. 82/07/28. 1p 14377 046. 24X Fiche: 30-285, 82/07/28, 8208180070

--8208180081 IE Insp Rept 50-285/82-12 on 820601-30. Noncompliance noted: Failure to follow radiation protection manual procedures. YANDELL, L.A., HALL, R.E. Region 4, Office of Director. 82/07/28 6pp 14377 047. 24X Fiche: 30-285, 82/07/28, 8208180070.

8208060213 Act receipt of 820421, 0503 & 0718 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/82-02. SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs 82/08/02 JONES, W.C. Omaha Public Power District. 1p 14241 086. 24X Fiche: 30-285, 82/08/02, 8208060213

--8208060216 Responds to NRC 820322 & 0702 ltrs re violations noted in IE Insp Rept 50-285/82-02. Corrective actions, requalification exams will commence in Fall 1992 using randomly selected questions from training dept bank JONES, W.C. Omaha Public Power District. 82/07/19. SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 1p 14241 087. 24X Fiche: 30-285, 82/08/02, 8208060213.

8208180089 Forwards response to IE Bulletin 82-02, "Degradation of Threaded Fasteners in PCPB of PWR Plants." JONES, W.C. Omaha Public Power District. 82/08/02 COLLINS, J.T. Region 4, Office of Director. 6pp. 14376 319. 24X Fiche: 30-285, 82/08/02, 8208180089.

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance 82/08/02 Consolidated Edison Co. of New York. 117pp. 14388 201. 24X Fiche: 30-000, 82/08/02, 8204210407.

8208160452 Forwards IE Safeguards Insp Rept 50-285/82-10 on 820504-05. No noncompliance noted. Rept withheld (ref 10CFR2.790). SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 82/08/10. JONES, W.C. Omaha Public Power District. 2pp 14349 289. 24X Fiche: 30-285, 82/08/10, 8208160452.

8208190236 Act receipt of 820210, 0512 & 0601 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/81-30. SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 82/08/13. JONES, W.C. Omaha Public Power District. 1p 14388 192. 24X Fiche: 30-285, 82/08/13, 8208190236.

--8208190247 Responds to NRC 820111 ltr re violations noted in IE Insp Rept 50-285/81-30. Corrective actions: Standing Order Q-26 revised & review of all surveillance test procedures completed. JONES, W.C. Omaha Public Power District. 82/05/12. SEIDLE, W.C. Region 4, Office of Director. 2pp. 14388 193. 24X Fiche: 30-285, 82/08/13, 8208190236.

--8208190264 Responds to NRC 820111 ltr re violations noted in IE Insp Rept 50-285/81-30. Corrective actions: Standing Order Q-22, "Storage of Critical Quality Elements." revised to incorporate tagging program. JONES, W.C. Omaha Public Power District. 82/06/01. SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 1p 14388 194. 24X Fiche: 30-285, 82/08/13, 8208190236.

--8208190276 Responds to NRC 820111 ltr re violations noted in IE Insp Rept 50-285/81-30. Corrective actions: Standing Order Q-28, "Stolen Fire Protection Plan." will be revised to include responsibilities of assistant general manager. JONES, W.C. Omaha Public Power District. 82/02/10. COLLINS, J.T. Region 4, Office of Director. 6pp. 14388 195. 24X Fiche: 30-285, 82/08/13, 8208190236.

8208270318 Forwards IE Insp Rept 50-285/82-14 on 820701-31. No noncompliance noted. SEIDLE, W.C. Division of Resident, Reactor Project & Engineering Programs. 82/08/13. JONES, W.C. Omaha Public Power District. 2p 14565 031. 24X Fiche: 30-285, 82/08/13, 8208270318.

--8208270320 IE Insp Rept 50-285/82-14 on 820701-31. No noncompliance noted. Major areas inspected: operational safety verification, surveillance testing, maint & LER followup. YANDELL, L.A., JAUDON, J.P. Division of Resident, Reactor Project Engineering Programs. 82/08/12. 5pp. 14565 033. 24X Fiche: 30-285, 82/08/13, 8208270318.

8208240153 Requests clarification of 820601 ltr re exact location of emergency plan implementing procedure changes concerning deficiencies noted in IE emergency preparedness appraisal on 811207-16
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/08/18 JONES, W C Omaha Public Power District 1p 14520 129 24X Fiche 50-285, 82/08/18, 8208240153

8208240294 Act receipt of 820625 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/82-06
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/08/18 JONES, W C Omaha Public Power District 1p 14528 093 24X Fiche 50-285, 82/08/18, 8208240294

--8208240290 Responds to NRC 820527 ltr re violations noted in IE Insp Rept 50-285/82-06 Corrective actions contractor personnel involved in handling & insp of irradiated fuel rods re-instructed. Further control of future work to be provided.
JONES, W C Omaha Public Power District 82/06/25 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 3pp 14528 094 24X Fiche 50-285, 82/08/18, 8208240294

8208270367 Forwards Systematic Assessment of Licensee Performance Rept 50-285/81-37 for Jul 1980-June 1981 Major area discussed mgt involvement in QA Rept being issued as NRC rept w/o encl
COLLINS, J T Region 4, Office of Director 82/08/20 JONES, W C Omaha Public Power District 2pp 14564 239 24X Fiche 50-285, 82/08/20, 8208270367

--8208270371 Forwards Systematic Assessment of Licensee Performance Rept 50-285/81-37 for June 1980-Jul 1981 Major area discussed mgt involvement in QA Comments requested within 20 days
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/06/25 JONES, W C Omaha Public Power District 19pp 14564 241 24X Fiche 50-285, 82/08/20, 8208270371

8208310278 Act receipt of util 820729 ltr re insps, analyses & mods completed in response to IE Bulletins 79-02 & 79-14
SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 82/08/23 JONES, W C Omaha Public Power District 2pp 14688 273 24X Fiche 50-285, 82/08/23, 8208310278

--8208310282 Submits final rept re IE Bulletins 79-02 & 79-14 re piping sys insps, analyses & mods completed prior to June 1980 startup Consultant verified that safety-related piping is seismically qualified
JONES, W C Omaha Public Power District 82/07/29 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 3pp 14688 275 24X Fiche 50-285, 82/08/23, 8208310278

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A
FELTON, J M Division of Rules and Records 82/07/13 UDELL, R A Critical Mass Energy Project 8pp 14679 208 24X Fiche 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81"
* NRC - No Detailed Affiliation Given 82/07/13 48pp 14679 216 24X Fiche 50-000, 82/07/13, 8208270010

8208190089 Forwards monthly operating rept for Jul 1982
JONES, W C Omaha Public Power District 82/08/10 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 14383 174 24X Fiche 50-285, 82/08/10, 8208190089

--8208190093 Monthly operating rept for Jul 1982
SHORT, R W Omaha Public Power District 82/08/10 12pp 14383 173 24X Fiche 50-285, 82/08/10, 8208190089

S Reportable occurrences, LERs & related correspondence

8208100003 RO on 820521, no flow condition observed on blowdown sample flow from RC-28. Caused by closure of HCV-2507A (containment isolation blowdown sample valve) Valve immediately opened Investigation continuing.
JONES, W C Omaha Public Power District 82/05/21 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 2pp 14296 361 24X Fiche 50-285, 82/05/21, 8208100003

8208200135 Forwards LER 82-016/03L-0
JONES, W C Omaha Public Power District 82/08/10 SEIDLE, W C Division of Resident, Reactor Project & Engineering Programs 1p 14393 342 24X Fiche 50-285, 82/08/10, 8208200135

--8208200149 LER 82-016/03L-0 on 820714, Channel B of reactor auxiliary power distribution unit had negative axial shape index setpoint out of tolerance Caused by setpoint drift to dirty contact in flow dependent setpoint selector switch
MUELLER, R Omaha Public Power District 82/07/26 Re Office of Director App 14393 343 24X Fiche 50-285, 8208200135

8208240178 Responds to 820714 ltr requesting addl info re NUR Item II K 3 17. "Rept on Outages of ECCS" LERs re maintenance encl
JONES, W C Omaha Public Power District 82/08/19 CLARK, Operating Reactors Branch 3 36pp 14521 215 24X Fiche 50-285, 82/08/19, 8208240178

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8208030080 Responds to Rockland County Legislature Resolution prohibiting use of county employees funds for federally mandated radiological response plans for facilities FEMA will provide Findings on adequacy of offsite preparedness
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/07/06 GRANT, J T Rockland County, NY 14200 289 24X Fiche 50-247, 82/07/06, 8208030080

--8208030085 Requests FEMA Findings on adequacy of offsite preparedness facilities to determine whether to invoke provisions of NRC regulations requiring licensee to demonstrate removal of identified significant deficiencies
ORINES, B K Division of Emergency Preparedness 82/06/14 KRIMM, R M Federal Emergency Management Agency 4pp 14244 289 24X Fiche 50-247, 82/07/06, 8208030080

8207300508 Responds to 820602 ltr concerning emergency response for facilities & requesting initiation of 120-day regulatory clock against facilities. FEMA will provide findings on adequacy of plant offsite preparedness.
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/07/07 DEL BELLO, A B Westchester County 14172 063 24X Fiche 50-247, 82/07/07, 8207300508

--8206060006 Expresses concerns re facility emergency response requests initiation of 120-day regulatory clock against facilities Critiques on emergency drill encl.
DEL BELLO, A B Westchester County, NY 82/06/02 PALLADINO, Commissioners 37pp 14172 066 24X Fiche 50-247, 82/07/07, 8207300508

8208050295 Forwards IE Emergency Preparedness Appraisal Rept 50-286/82-02 on 820208-11 No noncompliance noted
SMITH, Q H Division of Emergency Preparedness & Operation 82/07/22 BRUNS, J C Power Authority of the State of New York 2pp 14210 188 24X Fiche 50-286, 82/07/22, 8208050295

--8208050306 IE Emergency Preparedness Appraisal Rept 50-286/82-02 on 820208-11 No noncompliance noted Major areas inspected followup of emergency preparedness items from prior appraisal on 810311-20
TERC, N H, CROCKER, H W Division of Emergency Preparedness & Operation Support 82/07/22 13pp 14210 190 24X Fiche 50-286, 82/07/22, 8208050295

8208050050 Forwards FEMA 820802 ltr & interim findings rept of radiological emergency response preparedness of state & local govts near plant
HABSELL, D F Hearing Branch 1 82/08/02 CARTER, L J A Safety and Licensing Board Panel 36pp 14213 231 24X Fiche 50-247, 82/08/02, 8208050050

8208100143 Notifies that NRC will determine whether reactor shutdown if significant deficiencies identified in FEMA 820802 ltr are not corrected within 120 days. Written statement describing plans requested within 30 days.
HAYNES, R C Region 1, Office of Director 82/08/03 BAY, Power Authority of the State of New York 2pp 14298 052 24X Fiche 50-286, 82/08/03, 8208100143

--8208100151 Forwards FEMA interim findings rept on adequacy of radiological emergency response preparedness of state & local govts at Indian Point Power Station. Plans & preparedness inadequate.
THOMAS, L M Federal Emergency Management Agency 82/08/03 DRICKS, W Office of the Executive Director for Operations 14298 055 24X Fiche 50-286, 82/08/03, 8208100143

--8208100155 Interim findings on adequacy of radiological emergency response preparedness of state & local govts at Indian Point Nuclear Power Station.
PETRONE, F P Federal Emergency Management Agency 82/08/03 33pp 14298 057 24X Fiche 50-286, 82/08/03, 8208100143

8208190196 Forwards Revision 3 to security force training & qualification program. Rept withheld (ref 10CFR2.790)
BAYNE, J. P. Power Authority of the State of New York. 82/08/09.
VARQA, S. A. Operating Reactors Branch 1 2pp 14387 046 24X
Fiche 50-286, 82/08/09, 8208190196.

8208270155 Forwards Revision 7 to security plan. Revision withheld (ref 10CFR2.790 & 10CFR73.211).
BAYNE, J. P. Power Authority of the State of New York. 82/08/09.
VARQA, S. A. Operating Reactors Branch 1 1p 14363.318 24X
Fiche 50-286, 82/08/09, 8208270155

8208170407 Ack receipt of 820429 & 0515 ltr transmitting changes to security plan. Changes consistent w/provisions of 10CFR50.54(p).
VARQA, S. A. Operating Reactors Branch 1 82/08/10 SINCLAIR, L. W.
Power Authority of the State of New York 2pp 14372.345 24X
Fiche 50-286, 82/08/10, 8208170407

8208310499 Releases public version of licensee advice re revisions to emergency plan procedures
FELTON, J. M. Division of Rules and Records 82/08/13 Document
Management Branch 1p 14697.284 24X Fiche 50-286, 82/08/13,
8208310499

--8208310503 Submits public version of advice that most recent revisions to emergency plan procedures were distributed to NRR.
Region 1 Emergency Preparedness Section & NRC facility
resident inspector
BARNS, J. C. Power Authority of the State of New York 82/07/30.
HAYNES, R. C. Region 1, Office of Director. 1p. 14697.285 24X
Fiche 50-286, 82/08/13, 8208310499

Q Adjudicatory correspondence

8208110236 Response to UCS/NY PIR0 820521 request for admissions Affidavits & Certificate of Bvc encl
MCURREN, H. J. Hearing Branch 1. 82/06/11 Union of Concerned
Scientists 25pp. 14330.319. 24X Fiche 50-247, 82/06/11, 8208110236.

8208270458 Expresses appreciation for opportunity to address ASLB.
DIAMANT, L. Affiliation Unknown 82/07/07 CARTER, L. Atomic Safety
& Licensing Board Panel. 1p. 14365.272. 24X
Fiche 50-247, 82/07/07, 8208270458.

8208030348 Response to final set of interrogatories & document requests re Commission Question 1. Certificate of Bvc encl Related correspondence.
POBNER, P. Parents Concerned About Indian Point. 82/07/23
Consolidated Edison Co. of New York 8pp. 14157.214. 24X
Fiche 50-247, 82/07/23, 8208030348

8208030335 Attempts to clear confusion of ASLB 820714 & 16 telcons to Comm Ed Conversation on 820714 was substantive. Discussions re merits of motions or issues should be entertained only w/all parties participating w/Certificate of Bvc.
BOHNAI, S. M. Consolidated Edison Co. of New York. 82/07/27.
CARTER, L. J. Atomic Safety and Licensing Board Panel. 7pp
14156.351. 24X Fiche 50-247, 82/07/27, 8208030335

8208160223 Memorandum & Order CLI-82-15 denying PAGNY request for directed certification of charges that ASLB exceeded or misapplied jurisdiction in admitting UCS & other intervenor contentions Addl Commissioner views encl.
CHILK, B. J. Office of the Secretary of the Commission 82/07/27.
30pp. 14346.290. 24X Fiche 50-247, 82/07/27, 8208160223.

8208020275 Urges Order CLI-82-15 be rescinded. Interests of nearby residents must be considered.
HEBBINGER, R. L., FRIEDLANDER, M., GREITZER, C. New York, NY 82/07/28.
PALLADINO, N. J., AHEARNE, J., GILINSKY, V. Commissioners. 1p.
14152.262. 24X Fiche 50-247, 82/07/28, 8208020275.

8208020281 Expresses outrage on behalf of Alliance to Close Indian Point at order CLI-82-15 narrowing scope of hearing.
POBNER, P. Affiliation Unknown 82/07/28. PALLADINO, N. J.,
AHEARNE, J. F., ROBERTS, T. M. Commissioners. 1p. 14151.311. 24X
Fiche 50-247, 82/07/28, 8208020281.

8208050050 Forwards FEMA 820802 ltr & interim findings re: adequacy of radiological emergency response preparedness of state & local govts near plant.
HABSELL, D. F. Hearing Branch 1. 82/08/02. CARTER, L. J., SHON, F. J.,
PARIS, D. H. Atomic Safety and Licensing Board Panel. 36pp.
14213.231. 24X Fiche 50-247, 82/08/02, 8208050050.

8208060100 Requests immediate suspension of plant OLS until determination made that adequate emergency plans exist that are capable of protecting public
WEISS, E. R., SHOLLY, S. C. Union of Concerned Scientists WEISS, E. R.
Hannon & Weiss 82/08/04 PALLADINO, N. J., GILINSKY, V., AHEARNE, J.
Commissioners. 3pp 14238.173. 24X Fiche 50-247, 82/08/04,
8208060100

8208100053 Forwards Region 1 820803 ltr to licensees re emergency preparedness
HABSELL, D. F. Hearing Branch 1. 82/08/05 CARTER, L. J., SHON, F. J.,
PARIS, D. H. Atomic Safety and Licensing Board Panel. 5pp.
14296.234 24X Fiche 50-247, 82/08/05, 8208100053.

8208110079 Memorandum & certification seeking further Commission guidance on witness testimony on consequences & probabilities & evidence on status & degree of conformance w/NRC/FEMA guidelines
CARTER, L. J., PARIS, D. H., SHON, F. J. Atomic Safety and Licensing Board
Panel 82/08/09 6pp. 14316.344 24X Fiche 50-247, 82/08/09,
8208110079.

8208110085 Errata to 820809 memorandum & certification, correcting typographical errors.
CARTER, L. J. Atomic Safety and Licensing Board Panel 82/08/09. 1p.
14316.343 24X Fiche 50-247, 82/08/09, 8208110085

8208170274 Solicits support for encl Croton-Harmon Board of Ed 820706 resolution demanding NRC institute 120-day clock to develop acceptable evacuation plan.
GERADI, K. A. Affiliation Unknown 82/08/10 PARIS, D. H. Atomic
Safety and Licensing Board Panel. 2pp 14369.226 24X
Fiche 50-247, 82/08/10, 8208170274.

8208160440 Supports UCS/NY PIR0 motion for order to show cause requesting shutdown. Cancellation of testimony & tardiness of objections to 820423 order unsupported.
FLEISHER, Z. B. West Branch Conservation Association. 82/08/11.
PALLADINO, N. Commissioners 1p 14348.255 24X
Fiche 50-247, 82/08/11, 8208160440

8208170120 Forwards Town of Cortlandt 820810 Resolutions 250-82 & 251-82 committing to cooperate in formulating evacuation plans & to demand documents re evacuation plans from utility.
BOYLE, H. L. Cortlandt, Town of, NY. 82/08/12. Docketing &
Services Branch 3pp. 14365.206. 24X Fiche 50-247, 82/08/12,
8208170120

8208170284 Opposes congressional investigation re conduct of ongoing adjudicatory proceeding. Investigation could irreparably impair legal validity of subsequent agency decisions. Memo detailing concerns encl.
DUFFY, J. F. Power Authority of the State of New York. 82/08/13.
DITTINGER, R. L. House of Rep., Energy & Commerce. 7pp 14369.195.
24X Fiche: 50-247, 82/08/13, 8208170284

8208170285 Response supporting ASLB 820809 memorandum & order on two questions to Commission re probabilities & consequences. Certificate of Bvc encl.
BRANDENBURG, B. Consolidated Edison Co. of New York MORAN, C.
Power Authority of the State of New York MORAN, C. Morgan
Associates. 82/08/13. Commissioners. 12pp. 14369.183 24X
Fiche: 50-247, 82/08/13, 8208170285

8208190119 Lists corrections to licensee 820813 response to ASLB 820809 memorandum & certification.
COLARULLI, P. F. Morgan Associates. COLARULLI, P. F. Consolidated
Edison Co. of New York COLARULLI, P. F. Power Authority of the State
of New York. 82/08/17. STUCKY, B. H. Docketing & Services Branch.
1p. 14381.294 24X Fiche: 50-247, 82/08/17, 8208190119.

--8208190123 Corrected copy of response to ASLB 820809 memorandum & certification. Commission should reaffirm 820727 decision w/o further opinion.
BRANDENBURG, B. Consolidated Edison Co. of New York MORAN, C.
Power Authority of the State of New York MORAN, C. Morgan
Associates. 82/08/17. 8pp. 14381.295. 24X Fiche: 50-247,
82/08/17, 8208190119.

8208200120 Forwards documents in response to Interrogatory 7 filed on 820719. W/o encl.
MOORE, J. E. Hearing Branch 1. 82/08/19. WEISS, E. R. Hannon & Weiss.
WEISS, E. R. Union of Concerned Scientists WEISS, E. R. Public
Interest Research Group, New York. 1p. 14300.086 24X
Fiche: 50-247, 82/08/19, 8208200120.

8208240367 Submits informal Commission response to ASLB 820809 memorandum & certification of questions re intent to issue 820727 memorandum & order, CLI-82-15. Formal response expected during wk of 820830
CHILK, B. J. Office of the Secretary of the Commission. 82/08/23.
CARTER, L. J., SHON, F. J., PARIS, D. H. Atomic Safety and Licensing Board

H General correspondence

8208020290 Ack receipt of NRC ltr in response to Westchester County, NY request for 120-day regulatory clock against facilities. County appreciates NRC efforts to meet concerns by requesting interim findings from FEMA
DELBELLO, A. B. Westchester County, NY 82/07/13 PALLADINO, N. Commissioners 1p 14151. 301 24x Fiche: 50-003. 82/07/13. 8208020290

8208180044 Informs of concerns & objections to proposed NRC plans for evacuation of residents from areas surrounding facilities in event of accident
ELSDON, G. Gray Panthers 82/07/22 Commissioners 2pp. 14376. 300. 24x Fiche: 50-247. 82/07/22. 8208180044.

P Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR Svc list encl
DIRCKS, W. J. Office of the Executive Director for Operations 82/07/02. Consolidated Edison Co. of New York 93pp. 14194. 001. 24x Fiche: 50-000. 82/07/02. 8207080064

8208200291 Forwards advance notification of shipment of nuclear waste from facilities to Barnwell, SC
O'TOOLE, J. D. Consolidated Edison Co. of New York. 82/07/14. HAYNES, R. C. Region I. Office of Director 3pp 14398. 323 24x Fiche: 50-247. 82/07/14. 8208200291

8208030263 Notifies of changes in mgt organization structure to be incorporated in proposed Tech Specs
HILVERDINO, G. M. Power Authority of the State of New York. 82/07/21. VARQA, S. A. Operating Reactors Branch 1. VABSAALLO, S. A. Operating Reactors Branch 2. 2pp 14158. 142 24x Fiche: 50-000. 82/07/21. 8208030263.

8208040518 Notification of 820728 meeting w/utill in Bethesda, MD to discuss scheduling of open items
THOMA, J. Q. Operating Reactors Branch 1 82/07/21. VARQA, S. A. Operating Reactors Branch 1 2pp. 14220. 340 24x Fiche: 50-286. 82/07/21. 8208040518.

8208110050 Requests info re NY City water supply sys to aid R Codell testimony for hearing on risk re water contamination by release of radioactivity in event of severe accident, per 820709 discussion
HAAVER, S. H. Division of Safety Technology 82/07/22 CONWAY, J. New York, State of. 4pp 14330. 218 24x Fiche: 50-003. 82/07/22. 8208110050.

8208020426 Notification of 820727 meeting w/Sandia Natl Lab & Pickard Lowe & Garrick in Albuquerque, NM to obtain info re open technical issues raised during meeting in June 1982
HANNON, J. Operating Reactors Branch 1 82/07/26. VARQA, S. A. Operating Reactors Branch 1 2pp. 14181. 023. 24x Fiche: 50-247. 82/07/26. 8208020426

8208050449 Advises that addl info in response to TMI Action Plan Item 11 K. 3.17 re outages of ECSS will be provided by end of Oct 1982, per 820625 request.
BAYNE, J. P. Power Authority of the State of New York. 82/08/02. VARQA, S. A. Operating Reactors Branch 1. 1p. 14216. 347. 24x Fiche: 50-286. 82/08/02. 8208050449.

8208100390 Forwards addl info re masonry wall design, in response to NRC 820428 ltr w/32 oversize drawings. Aperture cards are available in PDR
BAYNE, J. P. Power Authority of the State of New York. 82/08/05. VARQA, S. A. Operating Reactors Branch 1 39pp 14294. 146. 24x Fiche: 50-286. 82/08/05. 8208100390.

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D. O. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14356. 332. 24x Fiche: 50-000. 82/08/09. 8208090194.

8208200119 Responds to NRC 820630 ltr re NUREG-0737, Item 11. B. 3. "Post-Accident Sampling Sys." Util will provide requested criteria in two parts within 60 days & 180 days.
BAYNE, J. P. Power Authority of the State of New York. 82/08/13. VARQA, S. A. Operating Reactors Branch 1. 2pp. 14393. 263. 24x Fiche: 50-286. 82/08/13. 8208200119.

8208260290 Forwards description of conceptual design of auxiliary feedwater sys made to resolve concerns re environ qualification of safety-related equipment within pump room & simultaneous blowdown of two steam generators
BAYNE, J. P. Power Authority of the State of New York 82/08/23. VARQA, S. A. Operating Reactors Branch 1 6pp. 14554. 275 24x Fiche: 50-286. 82/08/23. 8208260290.

O Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/16. Consolidated Edison Co. of New York 87pp 14356. 274 24x Fiche: 50-000. 82/07/16. 8204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ of 112pp 14398. 001 24x Fiche: 50-000. 82/07/19. 8204210395.

8204210396 IE Info Notice 82-25. "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp 14381. 001. 24x Fiche: 50-000. 82/07/20. 8204210396

8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20. Consolidated Edison Co. of New York. 71pp. 14357. 276 24x Fiche: 50-000. 82/07/20. 8204210397

8204210398 IE Info Notice 82-26. "RCIC & IPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/22. Consolidated Edison Co. of New York. 112pp. 14194. 321 24x Fiche: 50-000. 82/07/22. 8204210398.

8208090295 Forwards IE Emergency Preparedness Appraisal Rept 50-286/82-02 on 820808-11 No noncompliance noted.
SMITH, G. H. Division of Emergency Preparedness & Operational Support 82/07/22. BRONS, J. C. Power Authority of the State of New York 2pp 14210. 188. 24x Fiche: 50-286. 82/07/22. 8208090295

--8208050306 IE Emergency Preparedness Appraisal Rept 50-286/82-02 on 820208-11 No noncompliance noted. Major areas inspected: Followup of emergency preparedness items from prior appraisal on 810311-20.
TERC, N. M., CROCKER, H. W. Division of Emergency Preparedness & Operational Support. 82/07/22 13pp. 14210. 190. 24x Fiche: 50-286. 82/07/22. 8208050306.

8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 122pp. 14380. 115 24x Fiche: 50-000. 82/07/23. 8204210401

8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York 127pp. 14194. 120. 24x Fiche: 50-000. 82/07/23. 8204210402.

8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26. Consolidated Edison Co. of New York. 121pp. 14397. 013 24x Fiche: 50-000. 82/07/26. 8204210403.

8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/28. Consolidated Edison Co. of New York. 122pp. 14357. 146. 24x Fiche: 50-000. 82/07/28. 8204210405.

8208160009 Forwards IE Insp Rept 50-286/82-10 on 820616-0715 No noncompliance noted.
STARDBECKI, R. Division of Project & Resident Programs 82/07/30. BRONS, J. C. Power Authority of the State of New York. 2pp. 14344. 319. 24x Fiche: 50-286. 82/07/30. 8208160009.

--8208160010 IE Insp Rept 50-286/82-10 on 820616-0715 No noncompliance noted. Major areas inspected: shift logs & records, action on previous findings, audits, loss of offsite power & followup on IE bulletins.
FOLEY, T., KENNY, T. J., KISTER, H. Division of Project & Resident Programs. 82/07/29 10pp. 14344. 321. 24x Fiche: 50-286. 82/07/30. 8208160009.

8208130234 Forwards response to IE Bulletin B2-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants." Approx 70 manhours expended in bulletin preparation
BRONBS, J.C. Power Authority of the State of New York 82/08/03
HAYNES, R.C. Region 1, Office of Director. 2pp. 14333 144. 24X
Fiche 50-286, 82/08/03, 8208130234

8204210407 IE Info Notice B2-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." 5vc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/08/05.
Consolidated Edison Co. of New York 117pp. 14388:201. 24X
Fiche 50-090, 82/08/05, 8204210407.

8208180091 Ack receipt of 820723 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-286/82-08
STAROSTECKI, R. Division of Project & Resident Programs 82/08/12.
BRONBS, J.C. Power Authority of the State of New York. 1p.
14378 186 24X Fiche: 50-286, 82/08/12, 8208180091.

--8208180098 Responds to NRC 820629 ltr re violations noted in IE Insp Rept 50-286/82-08 Corrective actions: instructed personnel in proper method of baling machine operation & developed more appropriate procedure for baling operations.
BRONBS, J.C. Power Authority of the State of New York. 82/07/23.
STAROSTECKI, R. Division of Project & Resident Programs 2pp.
14378 187 24X Fiche: 50-286, 82/08/12, 8208180091.

R. Periodic operating reports & related correspondence

8208110049 "Core Melt Melt Interactions Evaluations," annual progress rept for Apr 1980-Mar 1981
SWANBDN, D.G., CATTON, I. Applied Science Associates, Inc.
NRC-03-80-104 ASAI-B1-001 81/03/31 Division of Systems
Integration (post B11005) 219pp 14330:001. 24X
Fiche 50-247, 81/03/31, 8208110049

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J.M. Division of Rules and Records. 82/07/13 UDELL, R.A.
Critical Mass Energy Project 8pp 14679:208. 24X
Fiche: 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13 48pp.
14679 216 24X Fiche: 50-000, 82/07/13, 8208270010.

--8208270632 Forwards "Personnel Whole Body Exposures For CY81," per 10CFR20.407
BRONBS, J.C. Power Authority of the State of New York. 82/02/26.
Office of Management and Program Analysis. 1p. 14679:345. 24X
Fiche 50-000, 82/07/13, 8208270010.

--8208270640 "Personnel Whole Body Exposures for CY81."
* Power Authority of the State of New York. 82/02/26. 1p.
14679:347 24X Fiche: 50-000, 82/07/13, 8208270010

8208120215 Forwards monthly operating rept for June 1982.
BRONBS, J.C. Power Authority of the State of New York 82/08/06.
Office of Management and Program Analysis. 1p. 14326:164. 24X
Fiche: 50-286, 82/08/06, 8208120215.

--8208120217 Monthly operating rept for June 1982.
AUTERINO, L. Power Authority of the State of New York. 82/07/01.
6pp. 14326:165. 24X Fiche: 50-286, 82/08/06, 8208120215.

S Reportable occurrences, LERs & related correspondence

8208020381 Forwards LER 82-004/01T-0.
BRONBS, J.C. Power Authority of the State of New York. 82/07/26.
HAYNES, R.C. Region 1, Office of Director. 1p. 14148:224. 24X
Fiche: 50-286, 82/07/26, 8208020381.

--8208020385 LER 82-004/01T-0: on 820713, setpoints for Crosby Model MB pressurizer safety relief valves PCV-466 & PCV-468 discovered below Tech Spec limit during cold testing. Caused by mechanical valve drift. Valves reset.
QUIMBLE, F.W. Power Authority of the State of New York. 82/07/26.
Region 1, Office of Director. 2pp. 14148:225. 24X
Fiche: 50-286, 82/07/26, 8208020381.

T Hearing transcripts on non-antitrust matters

8208040357 Transcript of Commission 820722 public meeting/affirmation session in Washington, DC re BECY-82-270A on alternative Commission decision in Indian Point special proceeding.
* Commissioners. 82/07/22 10pp. 14223:170. 24X
Fiche: 50-247, 82/07/22, 8208040357

U Congressional/Executive Correspondence

8208100350 Responds to 820608 ltr to Chairman Palladino requesting that facilities be shut down pending NRC review of results of hearings. Protective measures imposed by NRC cited. Results of current hearings to be reported to Commissioners Sept 1982.
DIRCKS, W.J. Office of the Executive Director for Operations. 82/07/09. OILMAN, B.A. House of Rep. 5pp. 14308:347. 24X
Fiche: 50-247, 82/07/09, 8208100350

--8206060022 Urges shutdown of facilities until adequate emergency plan can be formulated & ASLB findings studied. Constituent concern re plant safety & inadequate evacuation plan cited.
OILMAN, B.A. House of Rep. 82/06/08. PALLADINO, N. Commissioners 4pp. 14308:351. 24X Fiche: 50-247, 82/07/09, 8208100350.

DOCKET 50-287 OGDNEE NUCLEAR STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8208040450 Forwards request for addl info re standby shutdown facility to determine acceptability & resolve NRC concerns regarding fire protection & turbine bldg flooding.
STOLZ, J.F. Operating Reactors Branch 4. 82/07/17. PARKER, W.O.
Duke Power Co. 9pp. 14220:253. 24X Fiche: 50-269, 82/07/17, 8208040450.

8208110182 Informs of planned installation of fire hose cabinets at entrances to cable rooms & of planned utilization of existing turbine bldg hose stations for protection of equipment rooms. Had effects 771122 commitment.
TUCKER, H.B. Duke Power Co. 82/08/03. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp. 14313:360. 24X
Fiche: 50-269, 82/08/03, 8208110182.

8208190403 Releases public version of revised emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 82/08/10. Document Management Branch. 1p. 14504:186. 24X Fiche: 50-269, 82/08/10, 8208190403.

--8208190412 Forwards public version of revised emergency plan implementing procedures, including Station Directive 2.92 re emergency response organization & Procedure CP/O/A/2005/20 re post-accident determination of gamma isotopic activity.
TUCKER, H.B. Duke Power Co. 82/08/03. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 2pp. 14504:187. 24X Fiche: 50-269, 82/08/10, 8208190403.

--8208190422 Public version of revised emergency plan implementing procedures, including Station Directive 2.92 re emergency response organization & Procedure CP/O/A/2005/20 re post-accident determination of gamma isotopic activity.
DHEM, T.B. Duke Power Co. 82/07/23. 94pp. 14504:189. 24X
Fiche: 50-269, 82/08/10, 8208190403

8208260418 Releases public version of revised crisis mgt plan.
FELTON, J.M. Division of Rules and Records. 82/08/11. Document Management Branch. 1p. 14572:098. 24X Fiche: 50-000, 82/08/11, 8208260418.

--8208260430 Forwards public version of Revision 5 to crisis mgt plan. Revision involves reorganization of crisis mgt team & updates of Sections D, K & M.
PARKER, W.O. Duke Power Co. 82/07/19. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 14572:099. 24X
Fiche: 50-000, 82/08/11, 8208260418.

--8208260437 Public version of Revision 5 to crisis mgt plan.
TUCKER, H.B. Duke Power Co. 82/07/09. 134pp. 14572:100. 24X
Fiche: 50-000, 82/08/11, 8208260418.

8208260529 Releases public version of emergency plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 82/08/13. Document Management Branch. 1p. 14569:001. 24X Fiche: 50-269, 82/08/13, 8208260529.

--8208260537 Forwards public version of Emergency Plan implementing Procedures AP/O/A/1000/10 re emergency evacuation & HP/O/B/1009/13 re sampling & quantifying high level gaseous radioiodine & particulate radioactivity.
TUCKER, H.B. Duke Power Co. 82/08/05. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. STOLZ, J.F. Operating Reactors Branch 4. 1p. 14569:003. 24X Fiche: 50-269, 82/08/13, 8208260529.

--B208260542 Public version of Emergency Plan Implementing Procedures AP/0/A/1000/10 re emergency evaluation & HP/0/B/1009/15 re sampling & quantifying high level gaseous radioiodine & particulate radioactivity
TUCKER, H. B. Duke Power Co. 82/07/30 44pp 14569.004 24X
Fiche: 50-269.82/08/13.8208260529

I. Financial information

B208300328 Forwards util & NC Municipal Power Agency Annual Financial Repts for 1981
TUCKER, H. B. Duke Power Co. 82/08/24 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp 14599.227 24X
Fiche: 50-000.82/08/24.8208300328

--B208300335 Annual Financial Rept 1981
HORN, C. Duke Power Co. 82/02/15 48pp 14599.006 24X
Fiche: 50-000.82/08/24.8208300328

B208300342 Forwards Annual Financial Rept 1981
TUCKER, H. B. Duke Power Co. 82/08/24 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Reactors Branch 4 1p. 14599.110 24X Fiche: 50-269.82/08/24.8208300342.

P. Operating license stage documents & correspondence

B207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CQR Svc list encl
DIRKMS, W. J. Office of the Executive Director for Operations. 82/07/02 Consolidated Edison Co of New York 93pp 14174.001 24X Fiche: 50-000.82/07/02.8207080064

B208040546 Notification of B20818-19 meetings w/util & consultants in Seneca, SC to discuss radiological effluent Tech Specs
WAGNER, P. C. Operating Reactors Branch 4 82/07/27 STOLZ, J. F. Operating Reactors Branch 4 2pp 14220.357 24X
Fiche: 50-269.82/07/27.8208040546.

B208030223 Submits changes to completion dates for NUREG-0737, Items II B 3. "Post-Accident Sampling," & II F. 1. "Noble Gas Monitors," per B20416 status rept.
PARKER, W. D. Duke Power Co. 82/07/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Reactors Branch 4 2pp 14199.325 24X Fiche: 50-269.82/07/28.8208030223

B208030541 Application for amend to Licenses DPR-38, DPR-47 & DPR-55, revising Tech Specs 6.0 through 6.3 re util reorganization, superintendent of operations qualification requirements & organization chart Class I & II amend fees encl.
PARKER, W. D. Duke Power Co. 82/07/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Reactors Branch 4 3pp 14162.353 24X Fiche: 50-000.82/07/30.8208030541.

--B208030551 Forwards Class I & II amend fees to cover revisions to Tech Specs 6.2 re offsite & station organization & 6.0 through 6.3 re reorganization.
PARKER, W. D. Duke Power Co. 82/07/30 MILLER, W. E. Office of the Controller 1p 14162.356 24X Fiche: 50-000.82/07/30.8208030551.

--B208030560 Proposed Tech Specs 6.0-6.3 re administrative controls, review & audit organization chart encl
* Duke Power Co. 82/07/30. 13pp 14162.357 24X
Fiche: 50-000.82/07/30.8208030561.

B208060163 Forwards BAW-1732, "Evaluation, Repair & Replacement of Damaged Internal Auxiliary Feedwater Header at Davis Besse 1, Onconee 3 & Rancho Seco," per B20624 meeting w/NRC in Bethesda, MD & NRC B20523 request Response summary submitted.
WALBRIDGE, W. C. Sacramento Municipal Utility District. 82/08/03. STOLZ, J. F. Operating Reactors Branch 4. 8pp. 14238.087 24X
Fiche: 50-000.82/08/03.8208060163

--B208060168 "Evaluation, Repair & Replacement of Damaged Internal Auxiliary Feedwater Header at Davis Besse 1, Onconee 3 & Rancho Seco."
* Babcock & Wilcox Co. BAW-1732. 82/07/01 32pp. 14238.097. 24X Fiche: 50-000.82/08/03.8208060163

B208100193 Responds to NRC B20708 request for schedule for responding to NUREG-0737, Item II B 3. "Post-Accident Sampling Sys." Info will be submitted by 821101.
TUCKER, H. B. Duke Power Co. 82/08/05. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Reactors Branch 4. 1p. 14298.197 24X Fiche: 50-269.82/08/05.8208100193

B208120028 Provides addl info re availability of steam generator cooling water in event of tornado strike, per NRC B20408 safety evaluation Configuration, as modified by standby shutdown facility, acceptable
TUCKER, H. B. Duke Power Co. 82/08/06 DENTON, H. R. Office Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Branch 4 2pp 14324.058 24X Fiche: 50-269.82/08/06.8208120028

B208120216 Advises that responses to questions re adequacy of electric distribution sys voltages will be submitted no later than 821008, per B20608 request Delay caused by required addl research & manpower limitations
TUCKER, H. B. Duke Power Co. 82/08/06 DENTON, H. R. Office Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Branch 4 1p 14326.171 24X Fiche: 50-269.82/08/06.8208120216

B208090194 Generic Ltr 82-14 to all reactor licensees, holders applicants re submittal of documents to NRC summarizes 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl
EISENHUT, D. G. Division of Licensing. 82/08/07 Consolidated Edison Co of New York. 1p 14356.332 24X Fiche: 50-000.8208090194

B208240234 Application for amend to license DPR-47, changing Tech re reload design calculations for Cycle 7
TUCKER, H. B. Duke Power Co. 82/08/11 DENTON, H. R. Office Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Branch 4 3pp 14521.268 24X Fiche: 50-287.82/08/11.8208240234

--B208240237 Proposed Tech Spec revisions re reload design cal for Cycle 7
* Duke Power Co. 82/08/11. 29pp 14521.271 24X
Fiche: 50-287.82/08/11.8208240234

--B208240239 "Onconee Unit 3, Cycle 7 Reload Rept." Revision 1
* Duke Power Co. DPC-RD-2001 R01 82/07/31. 39pp 14521.271 24X Fiche: 50-287.82/08/11.8208240234.

B208170151 Responds to NRC B20709 ltr reviewing shift technical advisor training programs required by Item I A 1.1 of NUREG-7370 & NUREG-0660. Disagrees w/NRC expectation that all new hires have bachelors degree or equivalent
TUCKER, H. B. Duke Power Co. 82/08/12 DENTON, H. R. Office Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Branch 4 2pp 14364.218 24X Fiche: 50-269.82/08/12.8208170151

B208200025 Advises that util response to NRC B20713 ltr re sch submitting supplemental ECCS calculations utilizing cladding models of NUREG-0630 will be submitted by 830301
TUCKER, H. B. Duke Power Co. 82/08/12 DENTON, H. R. Office Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Branch 4 1p. 14392.246 24X Fiche: 50-269.82/08/12.8208200025

B208240242 Disagrees w/NRC expectations that all new hires have bachelors degree or equivalent pending new guidance per B20709 ltr & NUREG-0737, Item I A 1.1 "Shift Technical Advisor" & NUREG-0660
TUCKER, H. B. Duke Power Co. 82/08/12 DENTON, H. R. Office Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Branch 4 2pp. 14520.070 24X Fiche: 50-269.82/08/12.8208240242

B208240440 Forwards internal pin pressure calculation results Onconee 3 Cycle 7, per B20812 telcon re Cycle 7 reload rept & Tech Spec changes submitted B20503, revised B20811 Info re peak burnup also provided.
TUCKER, H. B. Duke Power Co. 82/08/16 DENTON, H. R. Office Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Branch 4 2pp. 14926.359 24X Fiche: 50-287.82/08/16.8208240440

B208310236 Forwards summary of licensee efforts to resolve NUREG-0737, Item II K 3 30 re revised small break LOCA methods. Util will support B&W owners group effort to provide integral sys test data, utilizing QERDA test facility.
TUCKER, H. B. Duke Power Co. 82/08/25 DENTON, H. R. Office Nuclear Reactor Regulation, Director. STOLZ, J. F. Operating Branch 4 11pp. 14695.096 24X Fiche: 50-269.82/08/25.8208310236

Q Inspection reports, IE Bulletins & correspondence

B208030599 Forwards IE Insp Repts 50-269/82-21, 50-270/82-21 & 50-287/82-21 on B20614-18. No noncompliance noted.
LEWIS, R. C. Division of Project & Resident Programs. 82/07/09. PARKER, W. D. Duke Power Co. 2pp 14162.313 24X
Fiche: 50-269.82/07/09.8208030599

--B208030613 IE Insp Repts 50-269/82-21, 50-270/82-21 & 50-287/82-21. No noncompliance noted. Major areas inspected: review of chemistry & radiochemistry procedures & airborne effluent sampling & accountability
EVANS, C. D., MONTGOMERY, D. M. Division of Emergency Preparedness & Operational Support. 82/07/07. 10pp. 14162.313. 24X
Fiche: 50-269.82/07/09.8208030599

8205030548 Forwards IE Insp Repts 50-269/82-26, 50-270/82-26 & 50-287/82-26 on 820706-09 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 82/07/14.
PARKER, W. O. Duke Power Co. 2pp 14162:096 24X
Fiche: 50-269, 82/07/14, 8208030548.

--8208030557 IE Insp Repts 50-269/82-26, 50-270/82-26 & 50-287/82-26 on 820706-09 No noncompliance noted Major areas inspected followup of extraction steam line rupture.
ORDERS, W., PUCKETT, M., KLEIN, SORCE, W. Division of Project & Resident Programs. 82/07/14 5pp 14162:098 24X
Fiche: 50-269, 82/07/14, 8208030548

8204210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/14
Consolidated Edison Co. of New York. 87pp 14356:274 24X
Fiche: 50-000, 82/07/16, 8204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/19.
Michigan, Univ. of 112pp. 14358:001. 24X Fiche: 50-000, 82/07/19, 8204210395

8204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure" Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/20
Consolidated Edison Co. of New York 112pp. 14381:001. 24X
Fiche: 50-000, 82/07/20, 8204210396

8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks." Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/07/20. Consolidated Edison Co. of New York 71pp. 14337:276 24X Fiche: 50-000, 82/07/20, 8204210397.

8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures" Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22.
Consolidated Edison Co. of New York. 112pp 14194:321 24X
Fiche: 50-000, 82/07/22, 8204210398

8208160163 Forwards IE Insp Repts 50-269/82-24, 50-270/82-24 & 50-287/82-21 on 820614-25 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 82/07/22.
PARKER, W. O. Duke Power Co. 2pp. 14345:069. 24X
Fiche: 50-269, 82/07/22, 8208160163.

--8208160169 IE Insp Repts 50-269/82-24, 50-270/82-24 & 50-287/82-21 on 820614-25 No noncompliance noted Major areas inspected.
Unit 3 10-yr inservice ultrasonic insp of steam generators, pressurizer reactor vessel & RCPB pipe.
COLEY, J. L., ECONOMOS, N. Division of Engineering & Technical Programs. 82/07/19. 7pp. 14348:071. 24X Fiche: 50-269, 82/07/22, 8208160163.

8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS" Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23
Consolidated Edison Co. of New York. 122pp. 14380:115. 24X
Fiche: 50-000, 82/07/23, 8204210401.

8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York. 127pp. 14194:120. 24X
Fiche: 50-000, 82/07/23, 8204210402.

8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance 82/07/26.
Consolidated Edison Co. of New York. 121pp. 14357:013. 24X
Fiche: 50-000, 82/07/26, 8204210403.

8208160194 Forwards IE Insp Repts 50-269/82-27, 50-270/82-27 & 50-287/82-27 on 820610-0715 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 82/07/26.
PARKER, W. O. Duke Power Co. 2pp. 14344:129. 24X
Fiche: 50-269, 82/07/26, 8208160194.

--8208160202 IE Insp Repts 50-269/82-27, 50-270/82-27 & 50-287/82-27 on 820610-0715 No noncompliance noted Major areas inspected: operations safety verification, surveillance testing, station maint activities & plant trips.
ORDERS, W., FALCONER, O., BRYANT, J. Division of Project & Resident Programs. 82/07/26. 11pp 14344:131. 24X Fiche: 50-269, 82/07/26, 8208160194.

8208030395 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/82-17, 50-270/82-17 & 50-287/82-17
LEWIS, R. C. Division of Project & Resident Programs. 82/07/27.
PARKER, W. O. Duke Power Co. 1p. 14162:232. 24X
Fiche: 50-269, 82/07/27, 8208030395

--8205030609 Responds to NRC 820616 ltr re violations noted in IE Insp Repts 50-269/82-17, 50-270/82-17 & 50-287/82-17 Corrective actions stronger door closure devices will be installed by 820715 & preventive maint program will be re-evaluated.
PARKER, W. O. Duke Power Co. 82/07/16. O'REILLY, J. P. Region 2, Office of Director 2pp 14162:233 24X Fiche: 50-269, 82/07/27, 8208030595

--8208030618 Forwards IE Insp Repts 50-269/82-17, 50-270/82-17 & 50-287/82-17 on 820510-14 & notice of violation.
DANCE, H. C. Division of Project & Resident Programs. 82/06/16
PARKER, W. O. Duke Power Co. 2pp 14162:235. 24X
Fiche: 50-269, 82/07/27, 8208030595

--8208030625 Notice of violation from insp on 820510-14.
* Division of Project & Resident Programs 82/06/16. 1p. 14162:237. 24X Fiche: 50-269, 82/07/27, 8208030595.

--8208030636 IE Insp Repts 50-269/82-17, 50-270/82-17 & 50-287/82-17 on 820510-14 Noncompliance noted: door providing access to radiowave compacting area found unlocked & positive access control not in effect
COLLINS, T. R., BARR, K. P. Division of Engineering & Technical Programs 82/06/10 6pp 14162:238 24X Fiche: 50-269, 82/07/27, 8208030595.

8208160364 Forwards IE Insp Repts 50-269/82-29, 50-270/82-29 & 50-287/82-29 on 820712-16 No noncompliance noted
DANCE, H. C. Division of Project & Resident Programs 82/07/27.
PARKER, W. O. Duke Power Co. 2pp 14349:041. 24X
Fiche: 50-269, 82/07/27, 8208160364

--8208160375 IE Insp Repts 50-269/82-29, 50-270/82-29 & 50-287/82-29 on 820712-16 No noncompliance noted Major areas inspected: radiation protection, shipment of radioactive matl, personnel dosimetry, portable instrument calibr & review of LERs.
COLLINS, T. R., BARR, K. P. Division of Engineering & Technical Programs 82/07/23 6pp. 14349:043. 24X Fiche: 50-269, 82/07/27, 8208160364.

8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28
Consolidated Edison Co. of New York 122pp. 14357:146 24X
Fiche: 50-000, 82/07/28, 8204210405.

8208160291 Forwards response to IE Bulletin 82-02. "Degradation of Threaded Fasteners in RCPB of PWR Plants." Improved design gasket is onsite & ready for use to repair reactor coolant pump.
PARKER, W. O. Duke Power Co. 82/07/29. O'REILLY, J. P. Region 2, Office of Director. 3pp 14346:265 24X Fiche: 50-269, 82/07/29, 8208160291.

8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water Jet Impingement." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/03.
Consolidated Edison Co. of New York 117pp 14388:201. 24X
Fiche: 50-000, 82/08/03, 8204210407

R. Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A. Critical Mass Energy Project. 8pp. 14679:208 24X
Fiche: 50-000, 82/07/13, 8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81." per IOCFR20 407.
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp. 14679:216 24X Fiche: 50-000, 82/07/13, 8208270010.

--8208270603 Forwards "Statistical Rept of Recorded Personnel Whole Body Exposures for CY81." per IOCFR20 407.
PARKER, W. O. Duke Power Co. 82/02/25. Office of Management and Program Analysis. 1p. 14679:340. 24X Fiche: 50-000, 82/07/13, 8208270010.

--8208270612 "Statistical Rept of Recorded Personnel Whole Body Exposures for CY81."
LEWIS, L. Duke Power Co. 82/02/25. 1p 14679:341. 24X
Fiche: 50-000, 82/07/13, 8208270010.

B208170087 Forwards monthly operating repts for Jul 1982
TUCKER, H B Duke Power Co 82/08/13 Director's Office, Office
of Inspection and Enforcement 1p 14358 149 24X
Fiche: 50-269, 82/08/13, B208170087

--B208170091 Monthly operating repts for Jul 1982
REAVIS, J A Duke Power Co 82/08/13 16pp 14358 150 24X
Fiche: 50-269, 82/08/13, B208170087

S Reportable occurrences, LERs & related correspondence

B208310076 Forwards LER B1-005/03L-0 Detailed event analysis encl
PARKER, W O Duke Power Co 81/04/22 O'REILLY, J P Region 2,
Atlanta, Office of the Director (81/03/01) 3pp 14697 246 24X
Fiche: 50-287, 81/04/22, B208310076

--B208310079 LER B1-005/03L-0 on B10323, engineering safeguard valve
JCB-S failed to operate caused by operator failure since
valve could be operated manually Valve operator will be
inspected during next outage
JONES, J L Duke Power Co 81/04/22 Region 2, Atlanta, Office
of the Director (81/03/01) 1p 14697 249 24X
Fiche: 50-287, 81/04/22, B208310076

B208030297 Forwards LER B2-007/01T-0 Detailed event analysis encl
PARKER, W O Duke Power Co 82/07/23 O'REILLY, J P Region 2,
Office of Director 3pp 14156 239 24X Fiche: 50-287, 82/07/23,
B208030297

--B208030303 LER B2-007/01T-0 on B20521, during video insp of fuel
assemblies, broken hold-down springs found on fuel assemblies
NJ001MH & NJ001M9 Caused by fatigue induced cracking at
existing surface flow springs will be replaced.
KUTZER, J F Duke Power Co 82/07/23 Region 2, Office of
Director, 1p 14156 242 24X Fiche: 50-287, 82/07/23, B208030297.

B208270125 Interim deficiency rept re degraded reactor coolant pump
closure studs initially reported on B20804 Investigation of
incident & preparation of rept incomplete due to difficulty
in removing affected studs Next rept expected by B20901.
TUCKER, H B Duke Power Co 82/08/12 O'REILLY, J P Region 2,
Office of Director 3pp 14563 310 24X Fiche: 50-287, 82/08/12,
B208270125

DOCKET 50-288 REED COLLEGE RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

B204210395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation," Svc list encl.
JORDAN, E L Division of Engineering & Quality Assurance, 82/07/19,
Michigan, Univ of 112pp 14358 001 24X Fiche: 50-000, 82/07/19,
B204210395.

DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

B208190124 Forwards objectives & proposed table of events for 1982
annual emergency plan exercise scheduled for B20811 Util
supports PA Emergency Mgt Agency concept of limited risk
county participation. Scenario to be submitted by B20706.
HUKILL, H D General Public Utilities - GPU Service Corp, 82/06/23,
QUIMES, B K Division of Emergency Preparedness, 3pp 14381 138,
24X Fiche: 50-289, 82/06/23, B208190124

B208190186 Forwards objectives for annual exercise to be held B20811,
per Encl 1 to FEMA Radiological Emergency Plan Guidance
Memorandum 17.
HUKILL, H D General Public Utilities - GPU Service Corp, 82/07/02,
HAYNES, R C Region 1, Office of Director, 9pp 14386 089 24X
Fiche: 50-289, 82/07/02, B208190186.

B208040265 Releases public version of revised emergency plan
implementing procedures.
FELTON, J M Division of Rules and Records, 82/07/20, Document
Management Branch 1p 14230 220 24X Fiche: 50-289, 82/07/20,
B208040265.

--B208040274 Forwards public version of revised emergency plan
implementing procedures, including Procedures 1004.1 re
unusual event, 1004.2 re alert & 1004.3 re site emergency.
Receipt form encl.
NASH, B General Public Utilities - GPU Service Corp, 82/07/07,
DENTON, H R Office of Nuclear Reactor Regulation, Director, 1p
14230: 221 24X Fiche: 50-289, 82/07/20, B208040265.

--B208040278 Public version of revised emergency plan implement
procedures, including Procedures 1004.1 re unusual event,
1004.2 re alert & 1004.3 re site emergency
NELSON, M A, TOOLE, R J General Public Utilities - GPU S
Corp 82/07/02 150pp 14230 222 24X Fiche: 50-289, 82
B208040265

B208270267 Forwards Revision 3 to guard training & qualificat
Revision withheld (ref 10CFR73 71)
HUKILL, H D General Public Utilities - GPU Service Corp
STOLZ, J F Operating Reactors Branch 4 1p 14563 091
Fiche: 50-289, 82/07/23, B208270267

B208050121 Releases public version of temporary change notice
emergency procedure
FELTON, J M Division of Rules and Records, 82/08/02, D
Management Branch 1p 14243 007 24X Fiche: 50-289, 82/08
B208050121

--B208050125 Forwards public version of Temporary Change Not
1-B2-0107 to Revision 4 of Emergency Procedure 1004.6.
"Add Assistance & Notification" Receipt form encl
NASH, B General Public Utilities - GPU Service Corp, 82
DENTON, H R Office of Nuclear Reactor Regulation, Director
14243: 008 24X Fiche: 50-289, 82/08/02, B208050121

--B208050130 Public version of Temporary Change Notice 1-B2-0
Revision 4 of Emergency Procedure 1004.6. "Add Assistance
Notification"
NELSON, M A, TOOLE, R J General Public Utilities - GPU S
Corp 82/07/16 2pp 14243 009 24X Fiche: 50-289, 82/0
B208050121.

B208270262 Forwards Revision 4 to guard training & qualificat
Revision withheld (ref 10CFR73 71)
HUKILL, H D General Public Utilities - GPU Service Corp
STOLZ, J F Operating Reactors Branch 4 1p 14563 356
Fiche: 50-289, 82/08/03, B208270262

B208160292 Forwards annual exercise requirements exemption fr
10CFR170 22
HUKILL, H D General Public Utilities - GPU Service Corp
CHILK, S J Office of the Secretary of the Commission 2pp
14346 263 24X Fiche: 50-289, 82/08/07, B208160292

B208170354 Releases public version of revision to emergency
procedure
FELTON, J M Division of Rules and Records, 82/08/10
Management Branch 1p 14373 166 24X Fiche: 50-289, 82/0
B208170354.

--B208170357 Forwards public version of Revision 4 to Emerge
Procedure 1004.7, "Offsite/Onsite Dose Projections"
Receipt form encl.
General Public Utilities - GPU Service Corp 82/08/0
DENTON, H R Office of Nuclear Reactor Regulation, Direc
14373: 167 24X Fiche: 50-289, 82/08/10, B208170354.

--B208170359 Public version of Revision 4 to Emergency Plan
1004.7, "Offsite/Onsite Dose Projections."
NELSON, M A, TOOLE, R J General Public Utilities - GPU
Corp, 82/07/30 24pp 14373: 168 24X Fiche: 50-289, 82
B208170354

B208310177 Forwards, "TMI-1 Once-Through Steam Generator Rep
Analysis," supplementing B1120B & B20216 responses
Affidavit requesting withholding encl. Evaluation withheld
(ref 10CFR2.790).
HUKILL, H D General Public Utilities - GPU Service Corp
EIBENHUT, D O Division of Licensing 6pp 14689 005 2
Fiche: 50-289, 82/08/20, B208310177

G Adjudicatory correspondence

B208160467 Ack suggestion to be eliminated from TMI restart
Mailings from ASLB & NRC staff sufficient
LEWIS, M I, Lewis, M 82/05/08 SMITH, I W Atomic Safe
Licensing Board Panel, 1p 14349 202 24X Fiche: 50-289,
B208160467.

B208160034 Order CLI-82-13 denying licensee B20524 request
Commission decide expeditiously whether NRC intended to
prepare supplemental EIS on psychological health effects.
NRC does not yet have enough info to decide.
CHILK, S J Office of the Secretary of the Commission, B
Metropolitan Edison Co, 5pp 14344: 273 24X Fiche: 50-2
B208160034.

separation for 820701 Hearing in Bethesda, MD. Subsequent to
obligation to answer ASLB 820714 Question III.E
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 82/08/02
7pp. 14158 135. 24X Fiche: 50-289, 82/08/02, 8208030261

8208040259 Addendum to 820727 partial initial decision, supplementing
Paragraph 2411 which imposed monetary penalty of \$100,000
upon licensee for failure to safeguard integrity of exam
process & adding condition to Paragraph 2421.
SMITH, I. W. Atomic Safety and Licensing Board Panel. 82/08/03. 2pp.
14183 085. 24X Fiche: 50-289, 82/08/03, 8208040259.

8208050058 Forwards completed procedures SP-A, 2, SP-A 4, SP-A 5, SP-A 6 &
SP-A B as part of Region 1 incident response suppl W/o encl.
ORAY, J. R. Hearing Branch 4. 82/08/03. Atomic Safety and
Licensing Board Panel. 1p. 14213 229. 24X Fiche: 50-289, 82/08/03,
8208050058.

8208090238 Motion for extension of time until 820820 & 27 to file
comments & reply comments re ASLB 820727 decision re
restart. Delay due to conflicting commitments.
AAMODT, M. M. Aamodts, The. 82/08/03. Commissioners. 3pp
14271 091. 24X Fiche: 50-289, 82/08/03, 8208090238

--8208090240 Motion for extension of time until 820820 & 0920 to file
exceptions & supporting brief in response to ASLB 820727
decision re restart. Delay due to conflicting commitments.
AAMODT, M. M. Aamodts, The. 82/08/03. Atomic Safety and
Licensing Appeal Panel. 2pp. 14271 094. 24X
Fiche: 50-289, 82/08/03, 8208090238.

8208090258 Notifies that oral argument for UCS will be presented by
ER Weiss w/technical assistance by RD Pollard.
WEISS, E. R. Harmon & Weiss. WEISS, E. R. Union of Concerned
Scientists. 82/08/03. SHOEMAKER, C. J. Atomic Safety and Licensing
Appeal Panel. 1p. 14270 347. 24X Fiche: 50-289, 82/08/03, 8208090258.

8208050387 Memorandum correcting ASLB 820727 Partial Initial Decision
LBP-82-56.
SMITH, I. W. Atomic Safety and Licensing Board Panel. 82/08/04. 2pp.
14209 176. 24X Fiche: 50-289, 82/08/04, 8208050387.

8208090155 Notification of action re ASLB 820727 partial initial
decision Ltr-designated individuals Q & H except 2-wk
suspension w/o pay in lieu of proceedings to consider
suspension/mod of operator licenses. Certificate of Bvc encl.
TROWBRIDGE, G. F. Metropolitan Edison Co. TROWBRIDGE, G. F. Shaw,
Pittman, Potts & Trowbridge. 82/08/06. 6pp. 14271 340. 24X
Fiche: 50-289, 82/08/06, 8208090155.

8208110089 Memorandum & order releasing cross-examination plans of
restart proceeding documents available at PDR.
SMITH, I. W. Atomic Safety and Licensing Board Panel. 82/08/06. 2pp.
14316 337. 24X Fiche: 50-289, 82/08/06, 8208110089.

8208110091 Order granting Aamodt request for 8-day extension to file
exceptions to ASLB 820728 partial initial decision.
Exceptions due by 820820. Time for filing brief to be
calculated on basis of last-filed appellant brief.
SHOEMAKER, C. J. Atomic Safety and Licensing Board Panel. 82/08/06.
Aamodts, The. 3pp. 14316 334. 24X Fiche: 50-289, 82/08/06,
8208110091.

8208110192 Comments re new info provided by licensee & NRC in response
to ASLAB 820829 memorandum & order. NRC & licensee integrity
remains principle issue & should be considered in review of
appeal. Certificate of Bvc encl.
AAMODT, N. D. Aamodts, The. 82/08/06. 7pp. 14313 340. 24X
Fiche: 50-289, 82/08/06, 8208110192

8208240119 Forwards 820806 memorandum & order & cross-examination plans
used during TMI-1 restart adjudicative proceeding Requests
documents be treated as single document & made available for
insp in PDR.
SMITH, I. W. Atomic Safety and Licensing Board Panel. 82/08/06.
COLLINS, M. Documents Management Branch. 700pp. 14344 180. 24X
Fiche: 50-289, 82/08/06, 8208240119.

8208110147 Response opposing Aamodt 820803 motion for extension until
820820 to file comments on ASLB 820727 decision favoring
restart. Aamodt on notice throughout proceeding that
Commission would decide within 35 days. W/Certificate of Bvc
TROWBRIDGE, G. F. Metropolitan Edison Co. TROWBRIDGE, G. F. Shaw,
Pittman, Potts & Trowbridge. 82/08/09. Commissioners. 7pp.
14314 295. 24X Fiche: 50-289, 82/08/09, 8208110147.

separation issues. Affidavits & Certificates of Bvc encl.
CUTCHIN, J. M. Hearing Branch 3. 82/08/09. Atomic Safety and
Licensing Appeal Panel. 2pp. 14313 061. 24X Fiche: 50-289, 82/08/09,
8208110198

--8208110200 Affidavit of RH Jacobs re questions raised in ASLAB 820714
short-term order Items 1 & 2.
JACOBS, R. H. Operating Reactors Branch 4. 82/08/06. 6pp.
14313 063. 24X Fiche: 50-289, 82/08/09, 8208110198

--8208110203 Affidavit of WL Jensen re status of licensee compliance
w/long-term item 2 of CLI-78-B & ASLAB 820714 order.
Questions I, D, III L, IV, A, IV, C, IV, E & IV, G
JENSEN, W. L. Reactor Systems Branch. 82/08/06. 16pp. 14313 069
24X Fiche: 50-289, 82/08/09, 8208110198.

--8208110206 Affidavit of JH Conran re ASLAB 820714 order, item III J re
status of generic reviews of sys interactions
CONRAN, J. H. Reliability & Risk Assessment Branch. 82/08/06. 6pp.
14313 085. 24X Fiche: 50-289, 82/08/09, 8208110198

--8208110207 Affidavit of ZR Roostock re ASLAB 820714 order, item III, Q
ROSTOCK, Z. R. Equipment Qualification Branch. 82/08/05. 3pp.
14313 091. 24X Fiche: 50-289, 82/08/09, 8208110198

--8208110209 Affidavit of LE Phillips re ASLAB 820714 order, Question
IV, H
PHILLIPS, L. E. Core Performance Branch. 82/08/06. 7pp.
14313 094. 24X Fiche: 50-289, 82/08/09, 8208110198

--8208110210 Affidavit of OP Chopra re ASLAB 820714 order, item IV, B(4).
Prof. Qualifications, Certificate of Bvc & documents cited in
RH Jacobs 820806 affidavit encl.
CHOPRA, O. P. Division of Systems Integration (post 811005).
82/08/05. 106pp. 14313 101. 24X Fiche: 50-289, 82/08/09,
8208110198.

8208130153 Provides info re changes on mgt issues, since close of
record, per 811001 commitment. RD Hurd prof qualifications &
svc list encl.
BAUSER, D. B. Shaw, Pittman, Potts & Trowbridge. BAUSER, D. B.
Metropolitan Edison Co. 82/08/10. EDLER, G. J., BUCK, J. H., KOHL, C. N.
Atomic Safety and Licensing Board Panel. 7pp. 14338 085. 24X
Fiche: 50-289, 82/08/10, 8208130153

8208120139 Order granting MM Aamodt 820806 request for extension until
820820 to comment on ASLB 820727 decision.
CHILK, S. J. Office of the Secretary of the Commission. 82/08/11.
Aamodts, The. 1p. 14327 108. 24X Fiche: 50-289, 82/08/11, 8208120139.

8208160139 Response to ASLAB 820714 order, consisting of status rept on
restart mode & description of short & long-term emergency
feedwater mods, per NUREG-0737, item II.E i. i. Affidavit &
Certificate of Bvc encl.
BAKTER, T. A. Metropolitan Edison Co. BAKTER, T. A. Shaw, Pittman,
Potts & Trowbridge. 82/08/12. 35pp. 14344 179. 24X
Fiche: 50-289, 82/08/12, 8208160139.

8208160433 Order directing Commonwealth of PA & util to advise whether
communications drill conducted per Partial Initial Decision
LBP-81-59 & when next scheduled drill or annual exercise
anticipated. Response due by 820820.
SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 82/08/13.
Pennsylvania, State of. 1p. 14349 263. 24X Fiche: 50-289,
82/08/13, 8208160433.

8208240414 Notice of Anti-Nuclear Group Representing York change of
address.
PHILIPS, G. B. Anti-Nuclear Group Representing York. 82/08/17. 1p.
14522 357. 24X Fiche: 50-289, 82/08/17, 8208240414.

8208190153 Response to ASLAB 820813 order requesting addl info re
communications drill & annual exercise. Drill required by
ASLB partial initial decision completed on 811014. Annual
exercise for 1982 conducted on 820811. W/Certificate of Bvc.
ZAHLER, R. E. Metropolitan Edison Co. ZAHLER, R. E. Shaw, Pittman,
Potts & Trowbridge. 82/08/18. 5pp. 14381 121. 24X
Fiche: 50-289, 82/08/18, 8208190153.

8208230059 Advises that author will represent NRC at 820901 oral
argument.
CUTCHIN, J. M. Hearing Branch 4. 82/08/18. SHOEMAKER, C. J. Atomic
Safety and Licensing Appeal Panel. 1p. 14517 226. 24X
Fiche: 50-289, 82/08/18, 8208230059.

8208230083 Response supporting licensee 820726 objection to answering Question III E of ASLB 820714 order Answer would provide info beyond info included in evidentiary record Rulemaking on environ qualification controls. Certificate of Svc encl. CUTCHIN, J. M. Hearing Branch 4 82/08/20. Atomic Safety and Licensing Appeal Panel. 12pp. 14517:128 24X Fiche: 50-289, 82/08/20, 8208230083

8208240245 Exceptions to ASLB 820727 partial initial decision re restart. BRADFORD, L. Three Mile Island Alert. 82/08/20. Atomic Safety and Licensing Board Panel. 20pp. 14520:072 24X Fiche: 50-289, 82/08/20, 8208240245

8208240260 Comments on immediate effectiveness of ASLB 820727 partial initial decision on cheating issues. per Commission 820310 order Decisions remove all bases for immediately effective shutdown order Order should be lifted. W/Certificate of Svc encl. GOLDBERG, J. R. Hearing Branch 2 82/08/20. Commissioners 20pp. 14527:014 24X Fiche: 50-289, 82/08/20, 8208240260

8208240272 Informs that NRC will not file any exceptions to ASLB 820727 partial initial decision. GOLDBERG, J. R. Hearing Branch 2. 82/08/20. EDLES, G. J., BUCK, J. H., KOHL, C. N. Atomic Safety and Licensing Appeal Panel. 1p. 14527:182 24X Fiche: 50-289, 82/08/20, 8208240272

8208240338 Advises that licensee will remove prohibition contained in emergency procedures against connecting pressurizer heaters when only one diesel generator available. Change has bearing on issue presently before ASLB. TROWBRIDGE, O. F. Shaw, Pittman, Potts & Trowbridge. TROWBRIDGE, O. F. Metropolitan Edison Co. 82/08/20. EDLES, G. J., BUCK, J. H., GOITCHY, R. L. Atomic Safety and Licensing Appeal Panel. 3pp. 14520:293. 24X Fiche: 50-289, 82/08/20, 8208240338

8208240342 Forwards comments on immediate effectiveness of ASLB 820727 partial initial decision on cheating. Licensee will file no exceptions to decision W/o encl. TROWBRIDGE, O. F. Shaw, Pittman, Potts & Trowbridge. TROWBRIDGE, O. F. Metropolitan Edison Co. 82/08/20. EDLES, G. J., BUCK, J. H., KOHL, C. N. Atomic Safety and Licensing Appeal Panel. 2pp. 14520:304 24X Fiche: 50-289, 82/08/20, 8208240342

8208240417 Comments opposing immediate effectiveness of ASLB 820727 partial initial decision on cheating. Reaffirms request for stay of 810827 partial initial decision & requests stay of 820727 decision. BRADFORD, L. Three Mile Island Alert. 82/08/20. 21pp. 14524:001. 24X Fiche: 50-289, 82/08/20, 8208240417.

8208240432 Comments supporting immediate effectiveness of ASLB 810817, 1214, & 820727 partial initial decisions. Immediate effectiveness of NRC 790702 & 0809 orders suspending operating authority should be lifted W/Certificate of Svc encl. TROWBRIDGE, O. F. Metropolitan Edison Co. TROWBRIDGE, O. F. Shaw, Pittman, Potts & Trowbridge. 82/08/20. 17pp. 14526:233 24X Fiche: 50-289, 82/08/20, 8208240432.

8208240449 Comments opposing immediate effectiveness of ASLB 820727 partial initial decision on cheating. Decision failed to resolve issues re ability of licensee personnel to operate plant safely W/notice of appearance & Certificates of Svc. BLAZEY, D. R. Pennsylvania, State of. 82/08/20. 12pp. 14526:316. 24X Fiche: 50-289, 82/08/20, 8208240449.

8208240454 Comments opposing immediate effectiveness of ASLB partial initial decisions authorizing restart. No reason for Commission to act before ASLB reviews decisions, since plant not ready to restart. WEISS, E. R. Union of Concerned Scientists. WEISS, E. R. Harmon & Weiss 82/08/20. 3pp. 14526:328 24X Fiche: 50-289, 82/08/20, 8208240454

--8208240457 Exceptions to ASLB 820727 partial initial decision on cheating issues. Certificate of Svc encl. WEISS, E. R. Union of Concerned Scientists. WEISS, E. R. Harmon & Weiss 82/08/20. Atomic Safety and Licensing Appeal Panel. 6pp. 14526:331. 24X Fiche: 50-289, 82/08/20, 8208240454.

8208250270 Exceptions to ASLB 820727 partial initial decision on cheating. Certificate of Svc encl. AMMOTT, T. M. M. Amnotts, The. 82/08/20. Atomic Safety and Licensing Appeal Panel. 19pp. 14543:010. 24X Fiche: 50-289, 82/08/20, 8208250270

8208250281 Comments on ASLB 820727 partial initial decision on cheating issues. Certificate of Svc encl. AMMOTT, T. M. M. Amnotts, The. 82/08/20 48pp. 14542:136. 24X Fiche: 50-289, 82/08/20, 8208250281

8208270470 Response to ASLB 820813 order re scheduled drill Initial notification drill conducted on 11/11/82. C482 annual exercise held on 820811 Next regular W/C communications drill in Sept 1982 W/Certificate of Svc encl. ADLER, R. W. Metropolitan Edison Co. 82/08/20 4pp. Fiche: 50-289, 82/08/20, 8208270470

8208250280 Advises that two separate mailings of 11/11/82 together. WEISS, E. R. Harmon & Weiss 82/08/23 EDLES, G. J., GOITCHY, R. L. Atomic Safety and Licensing Appeal Panel. 14543:063 24X Fiche: 50-289, 82/08/23, 8208250280

8208270532 Motion for ltr-designated individuals O & V Certificate of Svc encl. VOIOT, H. H. Affiliation Unknown. VOIOT, H. H. 14564:131 24X Fiche: 50-289, 82/08/23, 8208270532

8208270487 Reply to NRC 820809 response to ADLER, R. W. disallows w/CL Jensen summary & current status of actions taken per NUREG-0737, Item II, K 3 30. BAXTER, T. A. Metropolitan Edison Co. BAXTER, T. A. Potts & Trowbridge 82/08/23. 2pp. 14560:040 24X Fiche: 50-289, 82/08/25, 8208270487

--8208270495 Affidavit of RW Keaton re NRC & licensee response to NUREG-0737, Item II, K 3 30. Licensee agree w/NRC summary of actions Certificate of Svc encl. KEATON, R. W. Metropolitan Edison Co. KEATON, R. W. Utilities - GPU Service Corp. 82/08/25 16pp. Fiche: 50-289, 82/08/25, 8208270487

8208270477 Supplemental memorandum of ltr-designated individuals, clarifying intended involvement on appeal if possible. Intervene. Certificate of Svc encl. VOIOT, H. H. Affiliation Unknown. VOIOT, H. H. 14563:343 24X Fiche: 50-289, 82/08/26, 8208270477

8208300099 Order directing parties objecting to ltr designating individuals O & V 820823 motion to intervene to submit ASLB of objection by 820901. SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel. 2pp. 14596:132 24X Fiche: 50-289, 82/08/27, 8208300099

General correspondence

8208040061 Responds to 820607 ltr expressing concern re delays. Due to steam generator tube degradation, plant may be unable to restart until end of yr at earliest. NOVAK, T. M. Assistant Director for Operating Reactors. PETERS, E. Friends & Family of TMI. 2pp. 14216:114. Fiche: 50-289, 82/07/13, 8208040061.

--8208040067 Expresses concern over delays in restarting. PETERS, E. Friends & Family of TMI. 82/06/07. PETERS, E. Commissioners. 2pp. 14236:308 24X Fiche: 50-289, 82/08/04, 8208040061.

8208100364 Informs that NRC made arrangements w/Pittman & Univ to receive publicly available hearing transcripts & TMI-1, per 820616 request. SQUER, J. L. Division of Rules and Records 82/07/13. State College, PA 1p. 14308:358 24X Fiche: 50-289, 82/08/04, 8208100364

8208120351 Responds to 820712 ltr reiterating concerns of MD residents re possible disposal of waste water from TMI into Susquehanna River & Chesapeake Bay. Two studies are to evaluate impacts of 27 disposition alternatives. DIRCKS, W. J. Office of the Executive Director for Up & 82/08/04. DYSON, R. P. House of Rep. 3pp. 14339:289. Fiche: 50-289, 82/08/04, 8208120351.

--8208120356 Responds to 820517 ltr re future disposition from TMI. Two studies underway to evaluate potential of 27 possible disposition alternatives. SNYDER, B. J. TMI Program Office. 82/06/07. SNYDER, B. J. State of 10pp. 14339:289 24X Fiche: 50-289, 82/08/04, 8208120351

--8207050016 Expresses concern re possibility that waste may be discharged into Susquehanna River & Chesapeake Bay. DYSON, R. P. House of Rep. 82/07/12. MARTIN, J. B. Waste Management. 2pp. 14339:299. 24X Fiche: 50-289, 82/08/04, 8207050016

8208120130 Informs that restart proceeding contains duplicate addressee. Correspondence need not be sent to director, Ofc of Radiological Health
GERUSKY, T M Pennsylvania, State of 82/08/06 Office of the Secretary of the Commission 1p 14323 283 24X
Fiche 50-289, 82/08/06, 8208120130

82CB250042 Responds to concerns re steam generator corrosion problem. NRC shares some valid concerns particularly w/respect to performance of repaired tubes in event of transients &/or accidents during operation
EISENHUT, D O. Division of Licensing 82/08/09. LEWIS, M J. Lewis, M 2pp. 14559 178 24X Fiche 50-289, 82/08/09, 8208250042

K Utility Final Safety Analysis Report (FSAR) & amends

8208030299 Forwards Update 1 to TMI-1 updated FSAR, consisting of Figures 12 1-1, 12 1-2, 7 1-5, 7 1-6 & 7 1-7.
MATIS, J. B. Gibbs & Hill, Inc. (subs. of Dravo Corp.) 82/07/28.
DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 14157 183 24X Fiche 50-289, 82/07/28, 8208030299.

--8208030307 Update 1 to TMI-1 updated FSAR, consisting of Figures 12 1-1, 12 1-2, 7 1-5, 7 1-6 & 7 1-7 re station organization & logic diagram for MB-V-130 & EF-P28 activation.
* General Public Utilities - GPU Service Corp. 82/07/28 10pp
14137 184 24X Fiche 50-289, 82/07/28, 8208030299.

P Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CRGR Bvc list encl
DIRCKS, W. J. Office of the Executive Director for Operations. 82/07/02 Consolidated Edison Co. of New York 93pp. 14194 001. 24X Fiche 50-000, 82/07/02, 8207080064

8208030088 Draft Commission paper informing of present status of GPU program for recovery from steam generator tube corrosion problem & describing NRC intended response to GPU 820430 ltr re need for hearings.
DIRCKS, W. J. Office of the Executive Director for Operations. 82/07/19 9pp 14193 343 24X Fiche 50-289, 82/07/19, 8208030088.

8208040633 Forwards preliminary "Short Form Spec for Once-Through Steam Generator Tube Repair" & "Explosive Expansion Qualification Requirements for Mechanical Testing for Explosive Expansion Repair of TMI-1 Once-Through Steam Generators."
MCCRACKEN, C. Chemical Engineering Branch. 82/07/19. JACOB, R. Operating Reactors Branch 4. 37pp. 14228 162. 24X
Fiche 50-289, 82/07/19, 8208040633

8208040030 Confirms 820720 telcon re decision to start sending all publicly available hearing transcripts for TMI-1 to Pattee Library at PA State Univ.
SOUDEK, J. L. Division of Rules and Records. 82/07/20. SMITH, D. Pennsylvania State Univ. 1p. 14235 354 24X Fiche 50-289, 82/07/20, 8208040030.

8208190076 Board Notification 82-75 forwarding summary info re issues on probability of accidents for nuclear power reactors.
NOVAK, T. M. Assistant Director for Operating Reactors. 82/07/21. Atomic Safety and Licensing Appeal Panel. 18pp. 14506 102. 24X
Fiche 50-289, 82/07/21, 8208190076

8208260580 Notification of contract execution: "Reanalysis of Existing Data from Telephone Surveys Concerning TMI," awarded to Natl Inst of Mental Health.
FLENDOR, C. M. Technical Assistance Contracts Branch. FIN B-8621. 82/07/21. VOLLMER, R. H., REGAN, W. H. Division of Engineering. 1p. 14368 045. 24X Fiche 50-289, 82/07/21, 8208260580.

--8208260585 Memorandum of Agreement between NRC & Natl Inst of Mental Health expanding Grant MH35425 to encompass "Reanalysis of Existing Data from Telephone Surveys Concerning TMI."
MATIAS, M. Division of Contracts. PARDES, H. Health & Human Services, Dept. of. FIN B-8621. 82/07/14. 3pp. 14568 046. 24X
Fiche 50-289, 82/07/21, 8208260580.

8208130031 Forwards request for addl info re containment flood level calculations. Response requested within 30 days.
STOLZ, J. F. Operating Reactors Branch 4. 82/07/26. HUKILL, H. D. General Public Utilities - GPU Service Corp. 7pp. 14340 335. 24X
Fiche 50-289, 82/07/26, 8208130031.

8208060369 Board Notification 82-71: informs that NRC did not rely on feed & bleed cooling to protect core & forwards info supporting info.
CAINAB, O. C. Assistant Director for Operating Reactors 82/07/27. Atomic Safety and Licensing Appeal Panel. 20pp. 14281 359. 24X
Fiche 50-289, 82/07/27, 8208060369.

8208110036 Informs of util finalized steam generator repair plans. Dates of scheduled future meetings & areas of concern listed.
MCCRACKEN, C. Chemical Engineering Branch. 82/07/29. BENARDYA, V. Chemical Engineering Branch. 3pp. 14330 296. 24X
Fiche 50-289, 82/07/29, 8208110036

8208090010 SOCIOECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS: THREE MILE ISLAND CASE STUDY, Oct 1, 1978-January 4, 1982 Docket Nos. 50-289 and 50-320 (Metropolitan Edison et al.)
FLYNN, C. Social Impact Research, Inc. * Mountain West Research, Inc. FIN B-6268. NUREG/CR-2749 V12. 82/07/31. Division of Health, Siting & Environment. 242pp. Available at NTIS. \$7.50. 14302 168. 24X Fiche 50-289, 82/07/31, 8208090010.

8208050123 Forwards description & evaluation of main steam line rupture detection sys design changes. Approval requested.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 82/08/02. STOLZ, J. F. Operating Reactors Branch 4. 3pp. 14213 119. 24X
Fiche 50-289, 82/08/02, 8208050123.

8208170358 Forwards supplemental safety evaluation re util response to NUREG-0737, Item 11.K.2.9 concerning failure mode effects analysis on integrated control sys. Design meets all current regulatory requirements.
STOLZ, J. F. Operating Reactors Branch 4. 82/08/02. HUKILL, H. D. General Public Utilities - GPU Service Corp. 6pp 14373 229. 24X
Fiche 50-289, 82/08/02, 8208170358.

8208240035 Responds to approval request for info collection re psychological stress of TMI-1 restart on residents of surrounding communities. Request not approved (withdrawn at agency request).
SCURRY, N. Office of Management & Budget. 82/08/02. SCOTT, B. Document Management Branch. 2pp. 14529 256. 24X
Fiche 50-289, 82/08/02, 8208240035.

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Bvc list encl.
EISENHUT, D O. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14356 332 24X Fiche 50-000, 82/08/09, 8208090194.

8208170207 Forwards addl info on reactor bldg spray sys mode in support of Tech Spec Change Request 107. Braidout test of borated waste storage tank & sodium hydroxide tank not warranted.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 82/08/11. STOLZ, J. F. Operating Reactors Branch 4. 24pp. 14362 061. 24X
Fiche 50-289, 82/08/11, 8208170207.

8208190200 Forwards Tech Spec Change Request 116 supporting amend to License DPR-50, App A Change implements Branch Technical Position C8B 6-4 Item B. 4, providing for leak rate testing of purge/vent sys isolation valves.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 82/08/13. STOLZ, J. F. Operating Reactors Branch 4. 1p. 14386 331. 24X
Fiche 50-289, 82/08/13, 8208190200

--8208190204 Tech Spec Change Request 116 supporting amend to License DPR-50, App A Change implements Branch Technical Position C8B 6-4, providing for leak rate testing of purge/vent sys isolation valves. Certificate of Bvc encl.
HUKILL, H. D. General Public Utilities - GPU Service Corp. 82/08/13. 5pp. 14386 332 24X Fiche 50-289, 82/08/13, 8208190200.

--8208190210 Proposed Tech Specs supporting amend to License DPR-50, App A, implementing Branch Technical Position C8B 6-4 Item B. 4, providing for leak rate testing of purge/vent sys isolation valves.
* General Public Utilities - GPU Service Corp. 82/08/13. 12pp. 14386 337. 24X Fiche 50-289, 82/08/13, 8208190200.

8208190086 Formalizes proposals made at 820720 meeting w/NRC for resolution of NUREG-0737, Item 11.K.3.30, "Revised Small Break LOCA Methods." Followup ltr w/addl details & milestones will be provided within next several wks.
WILSON, R. F. General Public Utilities - GPU Service Corp. 82/08/16. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 10pp. 14383 187. 24X Fiche 50-289, 82/08/16, 8208190086.

8208310393 Forwards for comment. 8&W rept, "Evaluation of Tube Samples From TMI-1 Steam Generators." Addl results from later tube pulls including BMI exam results to be available in near future. W/o encl.
MCCRACKEN, C. Chemical Engineering Branch. 82/08/19. BENARDYA, V. Chemical Engineering Branch. 1p. 14697 128. 24X
Fiche 50-289, 82/08/19, 8208310393.

8208260201 Forwards supplemental response to NRC 820316 request for addl info re NUREG-0737, Item 11 B. 1. "RCB Vents" One oversize drawing encl Aperture card is available in PDR. HUKILL, H.D. General Public Utilities - GPU Service Corp. 82/08/23 STOLZ, J.F. Operating Reactors Branch A. 18pp. 14552:329 24X Fiche: 50-289, 82/08/23, 8208260201

0 Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/16 Consolidated Edison Co. of New York. 87pp. 14336:274. 24X Fiche: 50-000, 82/07/16, 8204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/19, Michigan, Univ. of. 112pp. 14358:001 24X Fiche: 50-000, 82/07/19, 8204210395

8204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/20, Consolidated Edison Co. of New York. 112pp. 14381:001. 24X Fiche: 50-000, 82/07/20, 8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl. COBB, L. Division of Fuel Facilities, Materials & Safeguards. 82/07/20 Consolidated Edison Co. of New York. 71pp. 14357:276. 24X Fiche: 50-000, 82/07/20, 8204210397

8208020372 Forwards IE Insp Rept 50-289/82-09 on 820609-0705 No noncompliance noted. STAROSTECKI, R. Division of Project & Resident Programs. 82/07/20 HUKILL, H.D. General Public Utilities - GPU Service Corp. 2pp. 14150:119. 24X Fiche: 50-289, 82/07/20, 8208020372

--8208020377 IE Insp Rept 50-289/82-09 on 820609-0705 No noncompliance noted Major areas inspected selective exam of procedures & representative records, interviews w/personnel & inspector observations. CONTE, R., NAPUDA, G., MEYER, G. Division of Project & Resident Programs. 82/07/10 10pp. 14150:121. 24X Fiche: 50-289, 82/07/20, 8208020372

8208040652 Forwards safety evaluation of util 800509 & 20 responses to IE Bulletin 80-04, "Analysis of PHR Main Steam Line Break w/Continued Feedwater Addition." Analysis acceptable STOLZ, J.F. Operating Reactors Branch A. 82/07/21. HUKILL, H.D. General Public Utilities - GPU Service Corp. 4pp. 14225:194. 24X Fiche: 50-289, 82/07/21, 8208040652

--8208040657 Safety evaluation re main steam line break w/continued feedwater addition No further action required by licensee re IE Bulletin 80-04 * NRC - No Detailed Affiliation Given. 82/07/21. 6pp. 14225:198. 24X Fiche: 50-289, 82/07/21, 8208040652

--8208280525 "PHR Main Steam Line Break w/Continued Feedwater Addition (B-691, Mod Ed, TH-1." technical evaluation rept. VOSSBURY, F.W. Franklin Institute/Franklin Research Center. NRC-03-B1-130. TER-03505-141 82/06/23 HEARN, P. NRC - No Detailed Affiliation Given. 21pp. 14225:205. 24X Fiche: 50-289, 82/07/21, 8208280525

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/22, Consolidated Edison Co. of New York. 112pp. 14194:321. 24X Fiche: 50-000, 82/07/22, 8204210398

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23 Consolidated Edison Co. of New York. 122pp. 14380:115. 24X Fiche: 50-000, 82/07/23, 8204210401

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHRs." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23, Consolidated Edison Co. of New York. 127pp. 14194:120 24X Fiche: 50-000, 82/07/23, 8204210402

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCB Piping at Certain Westinghouse PHR Power Plants." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/26 Consolidated Edison Co. of New York. 121pp. 14397:013 24X Fiche: 50-000, 82/07/26, 8204210403

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/28 Consolidated Edison Co. of New York. 122pp. 14357:146 24X Fiche: 50-000, 82/07/28, 8204210405

8208130013 Forwards response to Items 3 & 5 of IE Bulletin 82-02 re RCPB closures. Encls identify bolted closures that leaked, corrective actions & closures using fastener lubricants or injection sealant matl. HUKILL, H.D. General Public Utilities - GPU Service Corp. 82/08/03, HAYNES, R.C. Region 1, Office of Director. 3pp. 14335:051. 24X Fiche: 50-289, 82/08/03, 8208130013

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl. JORDAN, E.L. Division of Engineering & Quality Assurance. 82/08/05, Consolidated Edison Co. of New York. 117pp. 14388:201 24X Fiche: 50-000, 82/08/05, 8204210407

8208190227 Ack receipt of 820729 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/82-07. STAROSTECKI, R. Division of Project & Resident Programs. 82/08/12, HUKILL, H.D. General Public Utilities - GPU Service Corp. 2pp. 14387:141. 24X Fiche: 50-289, 82/08/12, 8208190227

--8208190237 Response to NRC 820701 ltr re violations noted in IE Insp Rept 50-289/82-07 Corrective actions damaged tubing supports repaired & Drawing B-308-854 changed to reflect new slope criteria for transmitter sensing lines. HUKILL, H.D. General Public Utilities - GPU Service Corp. 82/07/29 HAYNES, R.C. Region 1, Office of Director. 3pp. 14387:143 24X Fiche: 50-289, 82/08/12, 8208190227

8208300002 Board Notification 82-83 forwarding IE Insp Rept 50-320/82-04 identifying inadequate corrective maint actions on TH-1 ventilation sys important to safety. Region 1 will inspect TH-1 maint sys to determine if problems exist LAINEB, G.C. Assistant Director for Operating Reactors. 82/08/13 Atomic Safety and Licensing Appeal Panel 3pp. 14683:326. 24X Fiche: 50-289, 82/08/13, 8208300002

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A. FELDM, J.H. Division of Rules and Records. 82/07/13 UDELL, K.A. Critical Mass Energy Project. 8pp. 14679:208 24X Fiche: 50-000, 82/07/13, 8208270010

--8208270019 Forwards "Statistical Summary Rept of Personnel Monitoring Info for CY81." per 10CFR20 407 HUKILL, H.D. General Public Utilities - GPU Service Corp. 82/03/01 HAYNES, R.C. Region 1, Office of Director. 1p. 14680:001. 24X Fiche: 50-000, 82/07/13, 8208270010

--8208270023 "Statistical Summary Rept of Personnel Monitoring Info for CY81." * General Public Utilities - GPU Service Corp. 82/03/01. 2pp. 14680:002. 24X Fiche: 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81." * NRC - No Detailed Affiliation Given. 82/07/13. 48pp. 14679:216. 24X Fiche: 50-000, 82/07/13, 8208270010

--8208270649 Forwards "Number of Personnel & Man Rems By Work & Job Function for CY81." HUKILL, H.D. General Public Utilities - GPU Service Corp. 82/03/01. HAYNES, R.C. Region 1, Office of Director. 1p. 14679:382 24X Fiche: 50-000, 82/07/13, 8208270010

--8208270656 "Number of Personnel & Man Rems By Work & Job Function for CY81." * General Public Utilities - GPU Service Corp. 82/03/01. 5pp. 14679:353 24X Fiche: 50-000, 82/07/13, 8208270010

8208100275 Forwards "THI Aquatic Study." monthly rept for June 1982. TEIT, T.R. General Public Utilities - GPU Service Corp. 82/08/05, HICKEY, C. NRC - No Detailed Affiliation Given. 1p. 14295:145 24X Fiche: 50-289, 82/08/05, 8208100275

--8208100278 "THI Aquatic Study." monthly rept for June 1982. NARDACCI, O.A., RANEY, E.C. Ichthyological Associates, Inc. 82/08/05. 32pp. 14295:146. 24X Fiche: 50-289, 82/08/05, 8208100275

8208190074 Forwards monthly operating rept for Jul 1982. HUKILL, H.D. General Public Utilities - GPU Service Corp. 82/08/13, McDONALD, W.C. Office of Resource Management, Director. 1p. 14383:197. 24X Fiche: 50-289, 82/08/13, 8208190074

--8208190077 Monthly operating rept for Jul 1982
SMITH, C. W. General Public Utilities - OPU Service Corp. 82/08/13
12pp. 14383 198 24X Fiche 50-293, 82/08/13, 8208190074

T. Hearing transcripts on non-antitrust matters

8208260551 Addl response to FOIA request for documents made available
by NRC to CM McMurray (FOIA Request 82-176) Documents listed
in Appx A & B provided on 820709 & 0713, respectively
Forwards App B documents.
FELTON, J. M. Division of Rules and Records 82/07/13. ELLIS, T. S.
Huntton & Williams. 3pp 14569 045. 24X Fiche 50-293, 82/07/13.
8208260551

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8208170140 Forwards IE Emergency Preparedness Appraisal Rept
50-293/81-15 on 810713-24 No noncompliance noted.
SMITH, G. H. Division of Emergency Preparedness & Operational Support.
82/06/22. HARRINGTON, W. D. Boston Edison Co. 30pp. 14366 149.
24X Fiche: 50-293, 82/06/22, 8208170140

--8208170141 IE Emergency Preparedness Appraisal Rept 50-293/81-15 on
810713-24 No noncompliance noted. Major areas inspected
emergency facilities & equipment, emergency implementing
procedures & emergency organization
MCKENNA, T. J., CROCKER, H. W. Division of Emergency Preparedness &
Operational Support 82/06/16. 59pp 14366:175. 24X
Fiche 50-293, 82/06/22, 8208170140.

8208120058 Ack receipt of 820709 ltr informing NRC of steps taken to
correct violations noted in IE Emergency Preparedness
Appraisal Rept 50-293/81-15.
SMITH, G. H. Division of Emergency Preparedness & Operational Support.
82/08/04. HARRINGTON, W. D. Boston Edison Co. 2pp. 14323 347 24X
Fiche 50-293, 82/08/04, 8208120058.

--8208120060 Responds to NRC 820622 ltr re violations noted in IE
Emergency Preparedness Appraisal Rept 50-293/81-15.
Corrective actions will be submitted by 820801. Many App A
items should be placed in App B
HARRINGTON, W. D. Philadelphia Electric Co 82/07/09. SMITH, G. H.
Division of Emergency Preparedness & Operational Support. 2pp.
14323:349 24X Fiche 50-293, 82/08/04, 8208120058

8208230277 Forwards summary of 820805 mgt meeting w/util in King of
Prussia, PA re emergency preparedness program
SMITH, G. H. Division of Emergency Preparedness 82/08/17.
HARRINGTON, W. D. Boston Edison Co 2pp. 14512:260 24X
Fiche 50-293, 82/08/17, 8208230277.

--8208230281 Summary of 820805 mgt meeting w/util in King of Prussia, PA
re emergency liason function, 820728 emergency preparedness
implementation appraisal response, App C response & status of
siren sys coverage.
KDJFA, M. T. Region 1, Office of Director. 82/08/17. Region 1,
Office of Director 2pp. 14512:262. 24X Fiche: 50-293, 82/08/17,
8208230277.

8208300213 Ack receipt of 820728 ltr informing NRC of steps taken to
improve items identified in Appx A & B of NRC 820622 ltr
transmitting IE Emergency Preparedness Appraisal Rept
50-293/81-15.
SMITH, G. H. Division of Emergency Preparedness & Operational Support.
82/08/24 HARRINGTON, W. D. Boston Edison Co. 2pp. 14679:072. 24X
Fiche: 50-293, 82/08/24, 8208300213.

--8208300215 Forwards responses to items identified in Appx A & B of NRC
820622 ltr transmitting IE Emergency Preparedness Appraisal
Rept 50-293/81-15. Meeting will be scheduled in early Aug to
discuss sub.
HOWARD, J. E. Boston Edison Co. 82/07/28. SMITH, G. H. Division of
Emergency Preparedness & Operational Support. 62pp. 14679:074.
24X Fiche 50-293, 82/08/24, 8208300213

Q Adjudicatory correspondence

8208020312 Order extending time until 820806 for Commission to decide
whether to review IE Director denial of Commonwealth of MA
Executive Ofc of Energy Resources 820318 request for action
per 10CFR2.204.
HOYLE, J. C. Office of the Secretary of the Commission. 82/07/29.
Commissioners. 1p. 14151:130. 24X Fiche: 50-293, 82/07/29.
8208020312

8208030302 Order CLI-B2-16, denying Commonwealth of MA 820217 petition
to intervene & request for hearing re IE 820118 order. Stated
concerns beyond scope of proceeding. State of MA not
entitled as of right to any formal hearing.
HOYLE, J. C. Office of the Secretary of the Commission. 82/07/30.
Massachusetts, State of. App. 14157:156 24X Fiche: 50-293,
82/07/30, 8208030302.

8208090142 Order extending time for Commission to decide whether to
review IE denial of State of MA Executive Ofc of Energy
Resources 820318 request for action under 10CFR2.206 until
820811.
HOYLE, J. C. Office of the Secretary of the Commission. 82/08/06.
Commissioners. 1p. 14271:307. 24X Fiche: 50-293, 82/08/06,
8208090142.

8208160083 Forwards request of MA Atty General for submission of
documents re mgt & safety of facility since 820118
QOMES, J. R. Massachusetts, State of. 82/08/10. NRC - No Detailed
Affiliation Given. 1p. 14342:066 24X Fiche: 50-293, 82/08/10,
8208160083.

--8208160087 Request of MA Atty General for submission of documents re
mgt & safety of facility since 820118 Petition for review
of Commission 820730 decision denying petition to intervene
filed w/Court of Appeals. Certificate of Svc encl.
QOMES, J. R. Massachusetts, State of. 82/08/10. Commissioners.
3pp. 14342:067. 24X Fiche: 50-293, 82/08/10, 8208160083

8208170321 Informs that Commission declined to review Director's
Decision DD-B2-4. Decision designated final agency action on
820811.
CHILK, S. J. Office of the Secretary of the Commission 82/08/16.
KENNY, P. J. Massachusetts, State of. 1p. 14366:338 24X
Fiche: 50-293, 82/08/16, 8208170321.

F Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants
for DL & holders of CP re Commission approved charter for
CROR. Svc list encl.
DIRCKB, W. J. Office of the Executive Director for Operations.
82/07/02 Consolidated Edison Co. of New York 93pp. 14194:001.
24X Fiche: 50-000, 82/07/02, 8207080064.

8208030040 Forwards safety evaluation & LLL technical evaluation rept
supporting reactor protection sys power monitoring sys mod
IF NRC understanding re mod implementation incorrect, NRC
must be notified within 30 days.
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/28 MORISI, A. V.
Boston Edison Co. 2pp. 14243:189. 24X Fiche: 50-293, 82/07/28,
8208030040.

--8208030042 Safety evaluation supporting reactor protection sys power
monitoring sys mod.
AHMED, J. NRC - No Detailed Affiliation Given 82/07/28 2pp.
14243:191 24X Fiche 50-293, 82/07/28, 8208030040.

--8208030044 "Monitoring of Electric Power to Reactor Protection Sys of
Pilgrim Nuclear Power Station," technical evaluation rept
SELAN, J. C. Lawrence Livermore Laboratory. FIN A-0250. 82/04/29.
NRC - No Detailed Affiliation Given. 7pp. 14243:193. 24X
Fiche: 50-293, 82/07/28, 8208030040.

8208100104 Advises that Tech Specs re iodine concentration limit will
not be modified until final disposition of BWR owners group
study is completed by NRC.
MORISI, A. V. Boston Edison Co. 82/07/28 VASSALLO, D. B. Operating
Reactors Branch 2. 1p. 14297:303 24X Fiche: 50-293, 82/07/28,
8208100104.

8208120299 Forwards revised version of model Tech Specs re reactor
protection sys power monitoring sys design mod. Tech Specs
less restrictive.
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/28 MORISI, A. V.
Boston Edison Co. 3pp. 14332:252. 24X Fiche: 50-293, 82/07/28,
8208120299.

8208180265 Advises that IMI item 11.K.3.15 re isolation of HPCI/reactor
core isolation cooling sys (RCIC) resolved for facility.
Proposed method for preventing spurious isolation of HPCI/
RCIC approved. Implementation may require revised Tech Spec.
VASSALLO, D. B. Operating Reactors Branch 2. 82/07/28. MORISI, A. V.
Boston Edison Co. 3pp. 14389:319. 24X Fiche: 50-293, 82/07/28,
8208180265.

8208230038 Forwards Amend 62 to License DPR-35, safety evaluation &
notice of issuance & availability. Amend clarifies
alternate rod insertion sys operation & core spray, LPCI &
diesel generator testing requirements.
ECCLESTON, K. Y. Operating Reactors Branch 2. 82/08/05. MORISI, A. V.
Boston Edison Co. 2pp. 14507:292 24X Fiche: 50-293, 82/08/05,
8208230038.

--B208230040 Amend 62 to License DPR-35, clarifying alternate rod insertion sys operation & core spray, LPCI & diesel generator testing requirements
ROONEY, V. L. Operating Reactors Branch 2 82/08/05. 11pp
14307 294 24X Fiche 50-293.82/08/05.8208230038

--B208230043 Safety evaluation supporting Amend 62 to License DPR-35
* Office of Nuclear Reactor Regulation, Director 82/08/05 3pp
14507 303. 24X Fiche 50-293.82/08/05.8208230038

--B208230046 Notice of issuance & availability of Amend 62 to License DPR-35
ROONEY, V. L. Operating Reactors Branch 2 82/08/05. 2pp
14507 308 24X Fiche 50-293.82/08/05.8208230038

B208270680 Staff requirements memo re B20729 affirmation/discussion session. Commission approved orders releasing sanitized version of ALAB-653, reviewing ALAB-670 & denying petition to intervene in proceeding for mod of Pilgrim CL
MOYLE, J. C. Office of the Secretary of the Commission 82/08/06
BICKWIT, L. Office of the General Counsel App. 14683 185 24X
Fiche 50-000.82/08/06.8208270680

B208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter 1 requirements & provides alternatives to requirements Svc list encl
EISENHUT, D. 9 Division of Licensing 82/08/09 Consolidated
Edison Co. of New York 1p 14356 332 24X Fiche 50-000.82/08/09.
8208090194

B208190391 Requests documentation indicating completion of NUREG-0737, ITEM 11 B J re post-accident sampling Schedule requested within 20 days of receipt of ltr
VASSALLO, D. 8 Operating Reactors Branch 2 82/08/09. MORISI, A. V.
Boston Edison Co 10pp. 14504 166 24X Fiche 50-293.82/08/09.
8208190391

B208230234 Forwards proposed agenda for B20824 joint util/NRC performance improvement update meeting at Region 1 ofcs
Agenda Item 3 re Unreviewed Safety Question 50 59 will be discussed per onsite inspector request
HARRINGTON, W. D. Boston Edison Co 82/08/16. HAYNES, R. C. Region 1,
Office of Director. 2pp 14508 339 24X Fiche 50-293.82/08/16.
8208230234

0 Inspection reports, IE Bulletins & correspondence

B208170140 Forwards IE Emergency Preparedness Appraisal Rept 50-293/81-15 on 810713-24 No noncompliance noted.
SMITH, Q. H. Division of Emergency Preparedness & Operational Support.
82/06/22 HARRINGTON, W. D. Boston Edison Co. 30pp 14366 145.
24X Fiche 50-293.82/06/22.8208170140.

--B208170141 IE Emergency Preparedness Appraisal Rept 50-293/81-15 on 810713-24 No noncompliance noted Major areas inspected: emergency facilities & equipment, emergency implementing procedures & emergency organization
MCKENNA, T. J., CRICKER, H. W. Division of Emergency Preparedness & Operational Support 82/06/16 59pp. 14366 175 24X
Fiche 50-293.82/06/22.8208170140

B204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16
Consolidated Edison Co. of New York. 87pp. 14356 274. 24X
Fiche 50-000.82/07/16.8204210393

B204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19
Michigan, Univ. of 112pp. 14358 001. 24X Fiche 50-000.82/07/19.
8204210395

B208050162 Forwards results of insp & re-evaluation of as-built configuration of safety-related piping sys. per requirements of IE Bulletins 79-02 & 79-14. Mods should be completed in late 1982
MORISI, A. V. Boston Edison Co 82/07/19 HAYNES, R. C. Region 1,
Office of Director 32pp. 14212 085. 24X Fiche 50-293.82/07/19.
8208050162

B204210396 IE Info Notice 82-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20.
Consolidated Edison Co. of New York 112pp 14381 001. 24X
Fiche 50-000.82/07/20.8204210396

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexaplug Overpacks." Svc list encl.
CDB, L. I. Division of Fuel Facilities, Materials & Safeguards.
82/07/20 Consolidated Edison Co. of New York. 71pp 14147 097. 24X
Fiche 50-000.82/07/20.8204210397

B208050239 Forwards IE Insp Rept 50-293/82-14 on B20517-21 No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs
HARRINGTON, W. D. Boston Edison Co 2pp. 14209 269 24X
Fiche 50-293.82/07/21.8208050239

--B208050243 IE Insp Rept 50-293/82-14 on B20517-21 No noncompliance noted Major areas inspected: radiation protection program, including transportation & radwaste mgt
COLLINS, D. J., WRAY, J. R., GREENMAN, E. O. Region 1, Office of Director 82/07/09 8pp 14209 271 24X Fiche 50-293.82/07/09.8208050239.

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Valve Failures." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16
Consolidated Edison Co. of New York 112pp. 14194 321
Fiche 50-000.82/07/22.8204210398

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While On Vicinity of Drained & Open RCS." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16
Consolidated Edison Co. of New York 122pp. 14380 115
Fiche 50-000.82/07/23.8204210401.

B204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guid Support Pin Failures at Westinghouse PWRs." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16
Consolidated Edison Co. of New York. 127pp. 14194 120
Fiche 50-000.82/07/23.8204210402.

B204210403 IE Info Notice 82-30, "Loss of Thermal Bleeders in at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16
Consolidated Edison Co. of New York. 121pp 14397 013
Fiche 50-000.82/07/26.8204210403

B204210405 IE Info Notice 82-31, "Overexposure of Diver During Fuel Storage Pool." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16
Consolidated Edison Co. of New York. 122pp. 14357 146
Fiche 50-000.82/07/28.8204210405.

B208020338 Ack receipt of 820607 ltr informing NRC of steps to correct violations noted in IE Insp Rept 50-293/82-13
MARTIN, T. T. Division of Engineering & Technical Programs.
HARRINGTON, W. D. Boston Edison Co 1p. 14147 097. 24X
Fiche 50-293.82/07/28.8208020338.

--B208020342 Responds to NRC B20511 ltr re violations noted in Rept 50-293/82-13 Corrective actions nuclear organization policy issued on 820513, requiring complete identification design criteria & deviations before design change approval
HARRINGTON, W. D. Boston Edison Co 82/06/07. MARTIN, T. T. Division of Engineering & Technical Programs. 4pp 14147 097. 24X
Fiche 50-293.82/07/28.8208020338.

B208050531 Ack receipt of 820719 ltr informing NRC of steps to correct violations noted in IE Insp Rept 50-293/82-06
MARTIN, T. T. Division of Engineering & Technical Programs
HARRINGTON, W. D. Boston Edison Co. 1p 14214 088. 24X
Fiche 50-293.82/07/30.8208050531.

--B208050539 Responds to NRC B20621 ltr re violations noted in Rept 50-293/82-06. Corrective actions: revised training manual requalification of nuclear auxiliary operations & developed training schedule. Completion expected by 830101
HARRINGTON, W. D. Boston Edison Co. 82/07/19. MARTIN, T. T. Division of Engineering & Technical Programs. 2pp 14214 088. 24X
Fiche 50-293.82/07/30.8208050531.

B208120058 Ack receipt of 820709 ltr informing NRC of steps to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-293/81-15.
SMITH, Q. H. Division of Emergency Preparedness & Operational Support 82/08/04. HARRINGTON, W. D. Boston Edison Co. 2pp. 14323 349. 24X
Fiche 50-293.82/08/04.8208120058

--B208120060 Responds to NRC B20622 ltr re violations noted in Emergency Preparedness Appraisal Rept 50-293/81-15
Corrective actions will be submitted by B20801. Many App A items should be placed in App B.
HARRINGTON, W. D. Philadelphia Electric Co. 82/07/09 8H
Division of Emergency Preparedness & Operational Support 14323 349. 24X
Fiche 50-293.82/08/04.8208120058.

8208300245 Forwards IE Insp Rept 50-293/82-20 on 820611-13. No noncompliance noted.
MARTIN, T. T. Division of Engineering & Technical Programs. 82/08/13
HARRINGTON, W. D. Boston Edison Co. 2pp. 14679:155. 24X
Fiche 50-293, 82/08/13, 8208300245.

--8208300248 IE Insp Rept 50-293/82-20 on 820611-13. No noncompliance noted. Major areas inspected: initial contamination identification, contamination surveys, posting & barricading & main source determination.
MITZ, R. L., MCBRIDE, M. H., KOTTAN, J. J. Division of Engineering & Technical Programs. 82/08/03. 8pp. 14679:157. 24X
Fiche 50-293, 82/08/13, 8208300245.

8208300184 Forwards IE Insp Rept 50-293/82-19 on 820614-0801 & notices of violation & deviation.
STAROSTECKI, R. Division of Project & Resident Programs. 82/08/16.
HARRINGTON, W. D. Boston Edison Co. 2pp. 14596:015. 24X
Fiche 50-293, 82/08/16, 8208300184.

--8208300185 Notice of violation from insp on 820614-0801
* Region 1, Office of Director. 82/08/16. 3pp. 14596:017. 24X
Fiche 50-293, 82/08/16, 8208300184.

--8208300186 Notice of deviation from insp on 820614-0801.
* Region 1, Office of Director. 82/08/16. 1p. 14596:020. 24X
Fiche 50-293, 82/08/16, 8208300184.

--8208300188 IE Insp Rept 50-293/82-19 on 820614-0801. Noncompliance noted. Fire door blocked open w/o proper controls, failure to evaluate fire loading prior to moving combustibles & failure to translate design info into drawings.
JOHNSON, J., EICHENHOLZ, H., BRIGGS, L. Region 1, Office of Director. 82/08/12. 20pp. 14596:021. 24X Fiche 50-293, 82/08/16, 8208300184.

8208300213 Act receipt of 820728 ltr informing NRC of steps taken to improve items identified in Apps A & B of NRC 820622 ltr transmitting IE Emergency Preparedness Appraisal Rept 50-293/81-15.
SMITH, O. H. Division of Emergency Preparedness & Operational Support. 82/08/24. HARRINGTON, W. D. Boston Edison Co. 2pp. 14679:072. 24X
Fiche 50-293, 82/08/24, 8208300213.

--8208300215 Forwards responses to items identified in Apps A & B of NRC 820622 ltr transmitting IE Emergency Preparedness Appraisal Rept 50-293/81-15. Meeting will be scheduled in early Aug to discuss sub J.
HOWARD, J. E. Boston Edison Co. 82/07/28. SMITH, O. H. Division of Emergency Preparedness & Operational Support. 62pp. 14679:074. 24X Fiche 50-293, 82/08/24, 8208300213.

R. Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A. Critical Mass Energy Project. 8pp. 14679:208. 24X
Fiche 50-000, 82/07/13, 8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp. 14679:216. 24X Fiche 50-000, 82/07/13, 8208270010.

--8208270620 Forwards "Personnel Whole Body Exposures for CY81." per 10CFR20.407(a) & (b).
MACHON, R. D. Boston Edison Co. 82/03/26. Office of Management and Program Analysis. 1p. 14680:038. 24X Fiche 50-000, 82/07/13, 8208270010.

--8208270623 "Personnel Whole Body Exposures for CY81."
* Boston Edison Co. 82/03/26. 1p. 14680:039. 24X
Fiche 50-000, 82/07/13, 8208270010.

8208120141 Forwards monthly operating rept for June 1982.
MACHON, R. D. Boston Edison Co. 82/07/14. Management Information Branch. 1p. 14319:169. 24X Fiche 50-293, 82/07/14, 8208120141.

--8208120143 Monthly operating rept for June 1982.
WHITNEY, O. G. Boston Edison Co. 82/07/14. 6pp. 14319:170. 24X
Fiche 50-293, 82/07/14, 8208120141.

Office of Director. 1p. 14210:120. 24X Fiche 50-293, 82/07/21, 8208050266.

--8208050271 LER 82-021/03L-0 on 820624, fire door 153 on 37 ft elevator of turbine bldg annex found blocked opened. Caused by door being blocked to remove mat. Faulty lock replaced.
MCLAUGHLIN, M. T. Boston Edison Co. 82/07/21. Region 1, Office of Director. 1p. 14210:121. 24X Fiche 50-293, 82/07/21, 8208050266.

8208130186 LER 82-022/01X-0 on 820801, during power ascension following scheduled power reduction, speed of A recirculation pump went above 15% allowable Tech Spec limit. Caused by broken timing belt on pump scoop tube positioner.
WHITNEY, O. G. Boston Edison Co. 82/08/03. Region 1, Office of Director. 1p. 14338:262. 24X Fiche 50-293, 82/08/03, 8208130186.

8208260316 Telecopy message of LER 82-023/01X-0 on 820813, reactor scram occurred due to main steam line high flow trip signal. Caused by damage to main steam flow instruments on panel 2256 due to moving pipe staging instruments retallibr.
WHITNEY, O. G. Boston Edison Co. 82/08/13. Region 1, Office of Director. 1p. 14595:351. 24X Fiche 50-293, 82/08/13, 8208260316.

8208300210 Telecopy LER 82-025/01X-0 on 820815, hydrogen sample valves failed to meet containment isolation single failure criteria. Probably caused by design errors. Appropriate wiring changes made to provide redundant isolation signals.
GIARDIELLO, P. F. Boston Edison Co. 82/08/16. Region 1, Office of Director. 1p. 14678:231. 24X Fiche 50-293, 82/08/16, 8208300210.

8208300214 Telecopy LER 82-026/01X-0 on 820817, determined that Tech Spec 4.9.8.1.6 inadequate to demonstrate standby svc water sys capability. Caused by apparent incorrect translation of FSAR design basis into Tech Spec surveillance requirements.
GIARDIELLO, P. F. Boston Edison Co. 82/08/17. Region 1, Office of Director. 1p. 14678:230. 24X Fiche 50-293, 82/08/17, 8208300214.

8208300289 Forwards LER 82-027/03L-0.
MACHON, R. D. Boston Edison Co. 82/08/19. HAYNES, R. C. Region 1, Office of Director. 1p. 14599:331. 24X Fiche 50-293, 82/08/19, 8208300289.

--8208300296 LER 82-027/03L-0 on 820720, review of data from performance of Procedure 8.M.2-2.1.3 indicated changes to input data for calibr were made prior to mgt approval. Caused by personnel error. Revised procedure approved.
GIARDIELLO, P. F. Boston Edison Co. 82/08/19. Region 1, Office of Director. 1p. 14599:332. 24X Fiche 50-293, 82/08/19, 8208300289.

DOCKET 50-294 MICHIGAN STATE UNIV. RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of. 112pp. 14338:001. 24X Fiche 50-000, 82/07/19, 8204210393.

DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8208090231 Forwards IE Insp Repts 50-295/82-11 & 50-304/82-09 on 820310-0625 & notice of violation.
HIND, J. A. Division of Emergency Preparedness & Operational Support. 82/07/22. REED, C. Commonwealth Edison Co. 2pp. 14271:105. 24X
Fiche 50-295, 82/07/22, 8208090231.

--8208090236 Notice of violation from insp on 820310-0625.
HIND, J. A. Division of Emergency Preparedness & Operational Support. 82/07/19. 1p. 14271:107. 24X Fiche 50-295, 82/07/22, 8208090231.

--8208090241 IE Insp Repts 50-295/82-11 & 50-304/82-09 on 820310-0625. Noncompliance noted: failure to follow & maintain emergency response plan, to meet stds of 10CFR50.47(b) & to implement plan by 810401.
JANUSKA, A. G., AXELSON, W. L. Division of Emergency Preparedness & Operational Support. 82/07/19. 3pp. 14271:108. 24X
Fiche 50-295, 82/07/22, 8208090231.

8208030186 Application to amend Licenses DPR-39 & DPR-48, clarifying responsibilities of licensee during emergencies to take actions necessary to protect health & safety of public
LENTINE, F. G. Commonwealth Edison Co 82/07/23 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 14160, 157 24X
Fiche 50-295, 82/07/23, 8208030186

8208030603 Forwards final revised "Fire Protection Associated Cable Rept Zion 1 & 2"
LENTINE, F. G. Commonwealth Edison Co 82/07/30 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 10pp 14195 031 24X
Fiche 50-295, 82/07/30, 8208030603

--8208030621 Final revised "Fire Protection Associated Cable Rept Zion 1 & 2" W/77 oversize drawings Aperture cards are available in PDR
* Commonwealth Edison Co 82/07/31 135pp 14195 033 24X
Fiche 50-295, 82/07/30, 8208030603

8208110254 Releases public version of revised emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records 82/08/05, Document Management Branch 1p 14331 141 24X Fiche 50-295, 82/08/05, 8208110254

--8208110256 Forwards public version of Revision 3 to Emergency Plan Implementing Procedure EPIP 110-1, "Station Director"
Receipt form encl
PLIML, G. Commonwealth Edison Co 82/07/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 14331 142 24X
Fiche 50-295, 82/08/05, 8208110254

--8208110261 Public version of Revision 3 to Emergency Plan Implementing Procedure EPIP 110-1, "Station Director."
* Commonwealth Edison Co 82/07/22 8pp, 14331 143 24X
Fiche 50-295, 82/08/05, 8208110254

8208110259 Releases public version of revised page to emergency plan implementing procedure
FELTON, J. M. Division of Rules and Records, 82/08/05, Document Management Branch 1p 14332 172 24X Fiche 50-295, 82/08/05, 8208110259

--8208110263 Forwards public version of revised Page B to Revision 3 to Emergency Plan Implementing Procedure EPIP 700-1, "Corporate Command Ctr Group Directory" Receipt form encl.
PLIML, G. Commonwealth Edison Co 82/07/22 DENTON, H. R. NRC - No Detailed Affiliation Given 1p 14332 173 24X
Fiche 50-295, 82/08/05, 8208110259

--8208110265 Public version of revised Page B to Revision 3 to Emergency Plan Implementing Procedure EPIP 700-1, "Corporate Command Ctr Group Directory."
* Commonwealth Edison Co 82/07/22 2pp 14332 174 24X
Fiche 50-295, 82/08/05, 8208110259

8208180090 Forwards exemption requests from sections of post-fire shutdown capability rept to assist in fire protection review
LENTINE, F. G. Commonwealth Edison Co. 82/08/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 14pp 14370 189 24X
Fiche 50-295, 82/08/10, 8208180090

8208230559 Releases public version of revision to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"
FELTON, J. M. Division of Rules and Records 82/08/12, Document Management Branch 1p 14559 354 24X Fiche 50-000, 82/08/12, 8208230559

--8208260024 Forwards public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures."
MODRE, R. D. Commonwealth Edison Co 82/07/19 DENTON, H. R. NRC - No Detailed Affiliation Given 1p 14559 355 24X
Fiche 50-000, 82/08/12, 8208230559

--8208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures."
* Commonwealth Edison Co. 82/06/30, 7pp 14559 356 24X
Fiche 50-000, 82/08/12, 8208230559.

P Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for OL & holders of CP re Commission approved charter for CROR Svc list encl
DIRCKS, W. J. Office of the Executive Director for Operations, 82/07/02 Consolidated Edison Co. of New York, 93pp, 14194 001 24X Fiche 50-000, 82/07/02, 8207080064

8208040980 Forwards revised criteria to be used to review submittal or TMI Action Item I B 3, "Post-Accident Sampling Sys"
Schedule for responding to info requested in 20 days of ltr receipt
NEIGHBOR, J. D. Operating Reactors Branch 1 82/07/22
DELOEGRCE, L. O. Commonwealth Edison Co 10pp 14228 225 24X
Fiche 50-295, 82/07/22, 8208040980

8208030186 Application to amend Licenses DPR-39 & DPR-48, clarifying responsibilities of licensee during emergencies to take actions necessary to protect health & safety of public
LENTINE, F. G. Commonwealth Edison Co 82/07/23 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 14160 157 24X
Fiche 50-295, 82/07/23, 8208030186

8208090103 Provides actions to be taken re startup of units w/equipment required by out of svc Tech Specs & interpretation of phrase "recovery from inadvertent trip," discussed during 820721 meeting
LENTINE, F. G. Commonwealth Edison Co 82/07/23 KEPPNER, J. O. Region 3, Office of Director 2pp 14269 273 24X
Fiche 50-295, 82/07/23, 8208090103

8208030239 Application to amend Licenses DPR-39 & DPR-48, adding Tech Spec on sealed source contamination
LENTINE, F. G. Commonwealth Edison Co 82/07/29 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1p 14150 219 24X
Fiche 50-295, 82/07/29, 8208030239

--8208030245 Proposed Tech Spec Pages 295AD, 295AE & 295AF re sealed source contamination
* Commonwealth Edison Co 82/07/29 4pp 14150 220 24X
Fiche 50-295, 82/07/29, 8208030239

8208130072 Forwards Amend 75 to License DPR-39, safety evaluation & notice of issuance & availability Amend changes Tech Specs to allow one safety injection pump to be inoperable when power does not exceed 3%
WIGGINTON, D. Operating Reactors Branch 1 82/07/30 DELOEGHGL, L. () Commonwealth Edison Co 2pp 14340 330 24X Fiche 50-295, 82/07/30, 8208130072

--8208130077 Amend 75 to License DPR-39, providing one-time Tech Spec change to allow inoperability of one safety injection pump while power levels do not exceed approx 5% of rated power
VAROA, B. A. Operating Reactors Branch 1 82/07/30 4pp 14340 340 24X Fiche 50-295, 82/07/30, 8208130072

--8208130079 Safety evaluation supporting Amend 75 to License DPR-39, * Office of Nuclear Reactor Regulation, Director 82/07/30 3pp 14340 344 24X Fiche 50-295, 82/07/30, 8208130072

--8208130083 Notice of issuance & availability of Amend 75 to License DPR-39
VAROA, B. A. Operating Reactors Branch 1 82/07/30 2pp 14340 346 24X Fiche 50-295, 82/07/30, 8208130072.

8208130018 Application to amend Licenses DPR-39 & DPR-48, changing frequency at which reactor protection & engineered safeguard instrumentation must be functionally tested
LENTINE, F. G. Commonwealth Edison Co 82/08/05 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp 14335 082 24X
Fiche 50-295, 82/08/05, 8208130018

--8208130023 Proposed Tech Spec Tables 3.1.2.4.1-1 & 3.4.2 re functional testing of reactor protection & engineered safety instrumentation
* Commonwealth Edison Co. 82/08/05 7pp, 14335 086 24X
Fiche 50-295, 82/08/05, 8208130018

8208130166 Application for amend to Licenses DPR-39 & DPR-48, changing Tech Spec 3.2.3 re control rod sys operability.
LENTINE, F. G. Commonwealth Edison Co 82/08/05 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp 14339 015 24X
Fiche 50-295, 82/08/05, 8208130166

--8208130172 Proposed changes to Tech Spec 3.2.3 re control rod sys operability.
* Commonwealth Edison Co 82/08/05 4pp 14339 017 24X
Fiche 50-295, 82/08/05, 8208130166

8208110188 Forwards revised pages to CE-1-A, "Comm Ed QA Program for Nuclear Generating Stations," Revision 21 Revised pages correct typographical & other minor errors
SHARTZ, E. Commonwealth Edison Co. 82/08/06, HAABBS, W. P. Quality Assurance Branch 1p 14314 079 24X Fiche 50-000, 82/08/06, 8208110188

--8208110204 Revised pages to CE-1-A, Revision 21, "Comm Ed QA Program for Nuclear Generating Stations."
* Commonwealth Edison Co 82/06/06 11pp, 14314 080 24X
Fiche 50-000, 82/08/06, 8208110188.

B208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter I requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D.G. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p. 14356:332. 24X Fiche 50-000.82/08/09. B208090194

B208230137 Forwards addl info re diesel generator outages for 1976-B1, per Franklin Research Ctr B20628 request & NUREG-0737. Item 11 H 3 17. "ECCB Outage Rept."
LENTINE, F.O. Commonwealth Edison Co. 82/08/16. EISENHUT, D.G. Division of Licensing. 21pp. 14341:309. 24X Fiche 50-295.82/08/16. B208230137

B208240308 Submits updated schedule for submittal of addl info re containment purge valve operability Program scheduled for Fall 1982 completion. Summary of stress values calculated by hand encl.
LENTINE, F.O. Commonwealth Edison Co. 82/08/19. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp. 14527:197. 24X Fiche 50-295.82/08/19. B208240308

0 Inspection reports, IE Bulletins & correspondence

B208050414 Forwards IE Insp Repts 50-237/B1-39, 50-249/B1-32, 50-254/B1-23, 50-265/B1-23, 50-295/B1-31 & 50-304/B1-29 on B10813-B20503. No noncompliance noted.
KEPPLER, J.O. Region 3, Office of Director. 82/07/12. REED, C. Commonwealth Edison Co. 1p. 14217:166. 24X Fiche 50-000.82/07/12. B208050414

--B208050441 IE Insp Repts 50-237/B1-39, 50-249/B1-32, 50-254/B1-23, 50-265/B1-23, 50-295/B1-31 & 50-304/B1-29 on B10813-B20503. No noncompliance noted. Major areas inspected: allegations re Comm Ed operation of facilities & compliance w/10CFR21.
HAYES, D.W., BRAUND, C., TONGUE, T. Division of Project & Resident Programs. 82/07/09. 195pp. 14217:169. 24X Fiche 50-000.82/07/12. B208050441

B204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/16. Consolidated Edison Co. of New York. 87pp. 14356:274. 24X Fiche 50-000.82/07/16. B204210393

B204210395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices For External Radiation." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/19. Michigan, Univ. of. 112pp. 14358:001. 24X Fiche 50-000.82/07/19. B204210395

B204210396 IE Info Notice B2-25, "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp. 14381:001. 24X Fiche 50-000.82/07/20. B204210396

B204210397 IE Info Notice B2-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L.I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20. Consolidated Edison Co. of New York. 71pp. 14357:276. 24X Fiche 50-000.82/07/20. B204210397

B204210398 IE Info Notice B2-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/22. Consolidated Edison Co. of New York. 112pp. 14194:321. 24X Fiche 50-000.82/07/22. B204210398

B208090231 Forwards IE Insp Repts 50-295/82-11 & 50-304/82-09 on B20510-0625 & notice of violation.
HIND, J.A. Division of Emergency Preparedness & Operational Support. 82/07/22. REED, C. Commonwealth Edison Co. 2pp. 14271:105. 24X Fiche 50-295.82/07/22. B208090231

--B208090236 Notice of violation from Insp on B20510-0625.
HIND, J.A. Division of Emergency Preparedness & Operational Support. 82/07/18. 1p. 14271:107. 24X Fiche 50-295.82/07/22. B208090236

--B208090241 IE Insp Repts 50-295/82-11 & 50-304/82-09 on B20510-0625. Noncompliance noted: failure to follow & maintain emergency response plan to meet stds of 10CFR50.47(b) & to implement plan by B10401.
JANUSKA, A.G., AXELSON, W.L. Division of Emergency Preparedness & Operational Support. 82/07/15. 3pp. 14271:108. 24X Fiche 50-295.82/07/22. B208090231

B204210401 IE Info Notice B2-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 122pp. 14380:115. 24X Fiche 50-000.82/07/23. B204210401

B204210402 IE Info Notice B2-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PHRs." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 127pp. 14194:120. 24X Fiche 50-000.82/07/23. B204210402

B204210403 IE Info Notice B2-30, "Loss of Thermal Sleeves in RCB Pipes at Certain Westinghouse PHR Power Plants." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/26. Consolidated Edison Co. of New York. 121pp. 14357:013. 24X Fiche 50-000.82/07/26. B204210403

B204210405 IE Info Notice B2-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/28. Consolidated Edison Co. of New York. 122pp. 14357:146. 24X Fiche 50-000.82/07/28. B204210405

B208050490 Forwards response to IE Bulletin B2-02 re bolted connections. Visual or surface exams not typically performed on bolting in RCB unless requested. No trend of leakage recurrence detected.
SMART, E.D. Commonwealth Edison Co. 82/07/29. KEPPLER, J.O. Region 3, Office of Director. 14pp. 14214:109. 24X Fiche 50-295.82/07/29. B208050490

B208090130 Ack receipt of B20716 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Rept 50-295/82-08.
NORELIV, C.E. Division of Project & Resident Programs. 82/08/04. REED, C. Commonwealth Edison Co. 1p. 14269:342. 24X Fiche 50-295.82/08/04. B208090130

--B208090132 Responds to NRC B20618 ltr re noncompliance noted in IE Insp Rept 50-295/82-08. Corrective actions: station procedure will be written to govern control of personnel, tools & equipment entering RCB & steam generating channel heads.
DELGORGIE, L.O. Commonwealth Edison Co. 82/07/16. KEPPLER, J.O. Region 3, Office of Director. 4pp. 14269:343. 24X Fiche 50-295.82/08/04. B208090130

B204210407 IE Info Notice B2-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/08/05. Consolidated Edison Co. of New York. 117pp. 14388:201. 24X Fiche 50-000.82/08/05. B204210407

B208130163 Forwards remittance of civil penalties imposed in connection w/IE Insp Rept 50-295/82-09 re B20325 personnel overexposure.
LEE, B. Commonwealth Edison Co. 82/08/09. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 1p. 14333:148. 24X Fiche 50-295.82/08/09. B208130163

--B208130262 Responds to NRC B20709 ltr re violations noted in IE Insp Rept 50-295/82-09 concerning circumstances surrounding overexposure received by worker during entry beneath reactor vessel on B20325.
LEE, B. Commonwealth Edison Co. 82/08/09. DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement. 8pp. 14333:149. 24X Fiche 50-295.82/08/09. B208130163

R. Periodic operating reports & related correspondence

B208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J.M. Division of Rules and Records. 82/07/13. UDELL, R.A. Critical Mass Energy Project. 8pp. 14679:208. 24X Fiche 50-000.82/07/13. B208270010

--B208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp. 14679:216. 24X Fiche 50-000.82/07/13. B208270010

--B208270559 Forwards "Recorded Annual Whole Body External Exposure for CY81," per 10CFR20.407(b) w/o Quad Cities, Zion, LaSalle, Byron & Braidwood repts.
RAUSCH, T.J. Commonwealth Edison Co. 82/03/31. Office of Management and Program Analysis. 1p. 14680:075. 24X Fiche 50-000.82/07/13. B208270010

B208130103 Forwards monthly operating repts for Jul 1982.
ORABER, H.L. Commonwealth Edison Co. 82/08/06. Director's Office, Office of Inspection and Enforcement. 1p. 14333:340. 24X Fiche 50-295.82/08/06. B208130103

--8208130106 Monthly operating repts for Jul 1982
COOK, J Commonwealth Edison Co 82/08/06 11pp 14335 341. 24X
Fiche 50-295, 82/08/06, 8208130103

S Reportable occurrences, LERs & related correspondence

8208050233 Forwards LER 82-022/03L-0
GRAEBER, K L Commonwealth Edison Co 82/07/28 KEPLER, J G
Region 3, Office of Director Ip 14209 294. 24X
Fiche: 50-295, 82/07/28, 8208050233

--8208050236 LER 82-022/03L-0 on 820709, low pressure & high flow alarms
received on Zone 1 of penetration pressure sys, due to leak
in rupture disc on Zone 1. Caused of failure unknown Rupture
disc replaced
GLOVER, J Commonwealth Edison Co 82/07/28, Region 3, Office
of Director, Ip. 14209 295 24X Fiche 50-295, 82/07/28,
8208050233

8208050310 Forwards LER 82-023/03L-0
GRAEBER, K L Commonwealth Edison Co 82/07/28, KEPLER, J G
Region 3, Office of Director Ip 14237 323 24X
Fiche 50-295, 82/07/28, 8208050310.

--8208050322 LER 82-023/03L-0 on 820713, during normal operation, component
cooling supply valve to pump oil cooler & seal plate
isolated Cause unknown. Component cooling alignment procedure
changed to require complete lineup check.
BINODELL, B L Commonwealth Edison Co 82/07/28 Region 3,
Office of Director, Ip. 14237 324. 24X Fiche 50-295, 82/07/28,
8208050310

DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8207060127 Forwards response to Section III G of App A to 10CFR50 re
fire protection plan
MILLS, L M Tennessee Valley Authority 82/06/30, DENTON, H R
Office of Nuclear Reactor Regulation, Director. 202pp. 13712:142
24X Fiche: 50-259, 82/06/30, 8207060127

8207120070 Releases public version of revision to State of AL
radiological emergency response plan
FELTON, J M Division of Rules and Records 82/07/06 Document
Management Branch, Ip 13829 312. 24X Fiche 50-259, 82/07/06,
8207120070.

--8207120078 Forwards public version of Revision BFN-REP-82-003 to State
of AL radiological emergency response plan, constituting App
F to Browns Ferry radiological emergency response plan.
MILLS, L M Tennessee Valley Authority. 82/06/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp. 13829 314
24X Fiche: 50-259, 82/07/06, 8207120070

--8207120083 Public version of Revision BFN-REF-82-003 to State of AL
radiological emergency response plan, constituting App F to
Browns Ferry radiological emergency response plan.
* Tennessee Valley Authority. 82/06/16. 92pp. 13829:316. 24X
Fiche: 50-259, 82/07/06, 8207120070

8208090046 Forwards revisions to physical security plan. Revisions
withheld (ref 10CFR73.21)
MILLS, L M Tennessee Valley Authority 82/07/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director. Ip 14270 035 24X
Fiche: 50-259, 82/07/22, 8208090046.

8208110219 Releases public version of revised emergency plan
implementing procedures.
FELTON, J M Division of Rules and Records. 82/08/04. Document
Management Branch. Ip. 14318 084. 24X Fiche: 50-259, 82/08/04,
8208110219.

--8208110221 Forwards public version of revised emergency plan
implementing procedures, including Procedures IP-2 re
notification of unusual event, IP-4 re site emergency &
IP-5 re general emergency
SLIOER, E K Tennessee Valley Authority. 82/07/16. NRC - No
Detailed Affiliation Given. Ip. 14318:087. 24X
Fiche 50-259, 82/08/04, 8208110219.

--8208110223 Public version of revised emergency plan implementing
procedures, including Procedures IP-2 re notification of
unusual event, IP-4 re site emergency & IP-5 re general
emergency.
* Tennessee Valley Authority. 82/07/16. 110pp. 14318:088. 24X
Fiche: 50-259, 82/08/04, 8208110219.

8208260338 Releases public version of revised radiological emergency
notification directory.
FELTON, J M Division of Rules and Records 82/08/13 Document
Management Branch Ip. 14575 275 24X Fiche 50-259, 82/08/13,
8208260338

--8208260343 Forwards public version of Revision 5 to radiological
emergency notification directory Receipt form encl
MILLS, L M, SLIOER, E K Tennessee Valley Authority. 82/08/04
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
14575 276 24X Fiche 50-259, 82/08/13, 8208260338.

--8208260346 Public version of Revision 5 to radiological emergency
notification directory
* Tennessee Valley Authority 82/08/03 32pp. 14575 278. 24X
Fiche 50-259, 82/08/13, 8208260338

8208230351 Forwards addl info on implementation of App R, Item III J re
emergency lighting, per DB Vassallo 820622 ltr to HQ Parris.
Schedule for item also contained in LM Mills 820715 ltr
HAMMER, D B Tennessee Valley Authority 82/08/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 14508 2113
24X Fiche 50-259, 82/08/17, 8208230351

8208230331 Notifies that addl info re post-accident sampling facility &
response schedule requested 820713 will be provided by
821115
MILLS, L M Tennessee Valley Authority. 82/08/18 DENTON, H R
Office of Nuclear Reactor Regulation, Director. Ip. 14508 325 24X
Fiche 50-259, 82/08/18, 8208230331

Q Adjudicatory correspondence

8208270270 Informs that LBP-82-90 accepted for referral by ASLAB &
remanded for reconsideration in ALAB-687
RAMSON, R J Hearing Branch 4. 82/08/25 CHILK, B J Office of the
Secretary of the Commission. 3pp 14563 088 24X
Fiche: 50-259, 82/08/25, 8208270270.

1 Financial information

8208100002 Forwards "TVA Power Program Summary," Vol 2, for fiscal yr
ending 810630 & "1981 Power Program Summary," for fiscal yr
ending 810930, per Section 50 71(b) of 10CFR50
MILLS, L M Tennessee Valley Authority. 82/08/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 116pp. 14244 024
24X Fiche: 50-000, 82/08/06, 8208100002.

8208270457 Forwards financial statements for FY81, power quarterly rept &
internal cash flow projection.
MILLS, L M Tennessee Valley Authority 82/08/23 SALTZMAN, J
Assistant Director for State & Licensee Relations. 48pp 14566 135
24X Fiche: 50-000, 82/08/23, 8208270457.

J Insurance & indemnity information

8208310200 Advises that onsite property damage insurance has been
purchased, in accordance w/10CFR50 34 Coverage status encl.
MILLS, L M Tennessee Valley Authority. 82/08/23. SALTZMAN, J
Assistant Director for State & Licensee Relations. 2pp 14693 160
24X Fiche: 50-000, 82/08/25, 8208310200

K Utility Final Safety Analysis Report (FSAR) & amends

8208170283 Forwards updated FSAR for Browns Ferry Nuclear Plant, Vols
1-7.
MILLS, L M Tennessee Valley Authority 82/08/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director Ip. 14852:001. 24X
Fiche: 50-259, 82/08/12, 8208170283.

--8208170293 Updated FSAR for Browns Ferry Nuclear Plant, Vols 1-7.
* Tennessee Valley Authority. 82/08/12 3430pp. 14852:002 24X
Fiche: 50-259, 82/08/12, 8208170283

8208170295 Chapter 1 to Browns Ferry updated FSAR, "Introduction &
Summary."
* Tennessee Valley Authority. 82/08/12 150pp 14852:017. 24X
Fiche: 50-259, 82/08/12, 8208170295.

8208170297 Chapter 2 to Browns Ferry updated FSAR, "Site."
* Tennessee Valley Authority. 82/08/12. 450pp. 14852 202 24X
Fiche: 50-259, 82/08/12, 8208170297

8208170299 Chapter 3 to Browns Ferry updated FSAR, "Reactor"
* Tennessee Valley Authority 82/08/12. 170pp. 14853 188. 24X
Fiche: 50-259, 82/08/12, 8208170299.

Chapter 4 to Browns Ferry updated FSAR. "RCB "
see Valley Authority. 82/08/12. 170pp. 14854.006. 24X
-259. 82/08/12. 8208170303.

Chapter 5 to Browns Ferry updated FSAR. "Containment "
see Valley Authority. 82/08/12. 100pp. 14854.150. 24X
-259. 82/08/12. 8208170304.

Chapter 6 to Browns Ferry updated FSAR. "Core Standby
Sys "
see Valley Authority. 82/08/12. 75pp. 14854.294. 24X
-259. 82/08/12. 8208170307.

Chapter 7 to Browns Ferry updated FSAR. "Control &
ntation. "
see Valley Authority. 82/08/12. 500pp. 14855.024. 24X
-259. 82/08/12. 8208170308.

Chapter 8 to Browns Ferry updated FSAR. "Electrical
s. "
see Valley Authority. 82/08/12. 275pp. 14856.133. 24X
-259. 82/08/12. 8208170310.

Chapter 9 to Browns Ferry updated FSAR. "Redwaste Control
see Valley Authority. 82/08/12. 120pp. 14857.177. 24X
-259. 82/08/12. 8208170311.

Chapter 10 to Browns Ferry updated FSAR. "Auxiliary Sys "
see Valley Authority. 82/08/12. 400pp. 14857.177. 24X
-259. 82/08/12. 8208170315.

Chapter 11 to Browns Ferry updated FSAR. "Power
on Sys. "
see Valley Authority. 82/08/12. 50pp. 14858.039. 24X
-259. 82/08/12. 8208170317.

Chapter 12 to Browns Ferry updated FSAR. "Structures &
g. "
see Valley Authority. 82/08/12. 200pp. 14858.114. 24X
-259. 82/08/12. 8208170319.

Chapter 13 to Browns Ferry updated FSAR. "Conduct of
ne. "
see Valley Authority. 82/08/12. 70pp. 14859.039. 24X
-259. 82/08/12. 8208170322.

Chapter 14 to Browns Ferry updated FSAR. "Plant Safety
see Valley Authority. 82/08/12. 120pp. 14859.224. 24X
-259. 82/08/12. 8208170328.

App A to Browns Ferry updated FSAR. "Conformance to
osed General Design Criteria. "
see Valley Authority. 82/08/12. 22pp. 14860.029. 24X
-259. 82/08/12. 8208170333.

App B to Browns Ferry updated FSAR. "Tech Specs. "
see Valley Authority. 82/08/12. 1p. 14860.031. 24X
-259. 82/08/12. 8208170336.

App C to Browns Ferry updated FSAR. "Structural Loading
see Valley Authority. 82/08/12. 81pp. 14860.032. 24X
-259. 82/08/12. 8208170339.

App D to Browns Ferry updated FSAR. "QA Plan for Browns
Clear Plant. "
see Valley Authority. 82/08/12. 29pp. 14860.136. 24X
-259. 82/08/12. 8208170340.

App E to Browns Ferry updated FSAR. "Site Gaseous Release
it Calculation. "
see Valley Authority. 82/08/12. 3pp. 14860.163. 24X
-259. 82/08/12. 8208170375.

App F to Browns Ferry updated FSAR. "Unit Sharing &
ions. "
see Valley Authority. 82/08/12. 30pp. 14860.166. 24X
-259. 82/08/12. 8208170377.

App G to Browns Ferry updated FSAR. "Plant Nuclear
Operational Analysis. "
see Valley Authority. 82/08/12. 200pp. 14860.196. 24X
-259. 82/08/12. 8208170379.

8208170380 App H to Browns Ferry updated FSAR. "Core Thermal Design. "
see Tennessee Valley Authority. 82/08/12. 6pp. 14860.347. 24X
Fiche: 50-259. 82/08/12. 8208170380.

8208170382 App I to Browns Ferry updated FSAR. "Identification-
Resolution of CP Concerns. "
see Tennessee Valley Authority. 82/08/12. 55pp. 14860.355. 24X
Fiche: 50-259. 82/08/12. 8208170382.

8208170387 App L to Browns Ferry updated FSAR. "Reactor Pressure
Vessel Design Summary Rept-Unit 3. "
see Tennessee Valley Authority. 82/08/12. 1p. 14861.032. 24X
Fiche: 50-259. 82/08/12. 8208170387.

8208170389 App M to Browns Ferry updated FSAR. "Rept on Pipe Failure
Outside Containment in Browns Ferry Nuclear Plant. "
see Tennessee Valley Authority. 82/08/12. 50pp. 14861.033. 24X
Fiche: 50-259. 82/08/12. 8208170389.

8208170392 App N to Browns Ferry updated FSAR. "Browns Ferry Nuclear
Plant Unit 3 Bx8 Fuel Initial Core Loading. "
see Tennessee Valley Authority. 82/08/12. 100pp. 14861.096. 24X
Fiche: 50-259. 82/08/12. 8208170392.

P. Operating license stage documents & correspondence

8208030077 Forwards request for addl info re NUREG-0737, Item II.D.1,
"Testing of Relief & Safety Valves," in order to complete
review of generic test results.
VABALLD.D.B. Operating Reactors Branch 2. 82/06/30. PARRIS.H.O.
Tennessee Valley Authority. App. 14200.314. 24X
Fiche: 50-259. 82/06/30. 8208030077.

8208030698 Forwards safety evaluation of proposed method of
implementing NUREG-0737, Item II.K.3.15, "Isolation of HPCI &
Reactor Core Isolation Cooling. " Proposed method
acceptable.
VABALLD.D.B. Operating Reactors Branch 2. 82/06/30. PARRIS.H.O.
Tennessee Valley Authority. App. 14196.321. 24X
Fiche: 50-259. 82/06/30. 8208030698.

8207080064 Generic ltr to all licensees of operating plants, applicants
for DL & holders of CP re Commission approved charter for
CRGR. Bv list encl.
DIRCKB.W.J. Office of the Executive Director for Operations.
82/07/02. Consolidated Edison Co. of New York. 93pp. 14194.001.
24X Fiche: 50-000. 82/07/02. 8207080064.

8208040077 Requests data to support conclusion of adequacy space
cooling for HCPI & reactor core isolation cooling. Response
of B11230 unacceptable since no analysis or test data to
support conclusion submitted.
VABALLD.D.B. Operating Reactors Branch 2. 82/07/08. PARRIS.H.O.
Tennessee Valley Authority. App. 14228.291. 24X
Fiche: 50-259. 82/07/08. 8208040077.

8208040064 Notifies that generic issue re possible diesel generator
lockout resolved. Operator training program covers sub
adequately.
VABALLD.D.B. Operating Reactors Branch 2. 82/07/15. PARRIS.H.O.
Tennessee Valley Authority. App. 14228.280. 24X
Fiche: 50-259. 82/07/15. 8208040064.

8207270454 Requests extension to 820812 for submittal of updated FSAR.
MILLB.L.M. Tennessee Valley Authority. 82/07/20. DENTON.H.R.
Office of Nuclear Reactor Regulation. Director. 1p. 14061.168. 24X
Fiche: 50-259. 82/07/20. 8207270454.

8208040355 Forwards draft technical evaluation rept. "Control of Heavy
Load. " Conference call requested within 30 days to discuss
proposed recommendations in rept.
VABALLD.D.B. Operating Reactors Branch 2. 82/07/22. PARRIS.H.O.
Tennessee Valley Authority. App. 14221.150. 24X
Fiche: 50-259. 82/07/22. 8208040355.

8208110279 Forwards Amends 85, 82 & 56 to Licenses DPR-33, DPR-52 &
DPR-68, respectively, safety evaluation & notice of issuance
& availability. Amends consist of clarification &
administrative changes & additions to reflect plant mods.
CLARK.R.J. Operating Reactors Branch 2. 82/07/22. PARRIS.H.O.
Tennessee Valley Authority. App. 14332.034. 24X
Fiche: 50-259. 82/07/22. 8208110279.

--8208110283 Amends 85, 82 & 56 to Licenses DPR-33, DPR-52 & DPR-68,
respectively, consisting of clarification & administrative
changes & additions to reflect plant mods & reorganization
of some Tech Spec sections.
VABALLD.D.B. Operating Reactors Branch 2. 82/07/22. 128pp.
14332.036. 24X Fiche: 50-259. 82/07/22. 8208110279.

--B208110287 Safety evaluation supporting Amends B5,B2 & 56 to Licensee
DPR-33, DPR-52 & DPR-68, respectively
+ Office of Nuclear Reactor Regulation, Director B2/07/22 5pp.
14332 165 24X Fiche 50-000, B2/07/22, B208110279

--B208110290 Notice of issuance & availability of Amends B5,B2 & 56 to
Licensees DPR-33, DPR-52 & DPR-68, respectively
VASSALLO, D B Licensing Branch 2 B2/07/22 2pp 14332 170.
24X Fiche 50-000, B2/07/22, B208110279.

B208040663 Requests B20729 meeting in Chattanooga, TN to discuss MSIVs
in BWR plants
VASSALLO, D B Operating Reactors Branch 2 B2/07/23 PARRIS, H G
Tennessee Valley Authority, 2pp 14224, 360 24X
Fiche: 50-000, B2/07/23, B208040663

B208020221 Responds to NRC B20212 request for addl info re need for
chlorine detectors at facilities per NUREG-0737.
Item III D 3.4. No threat to control room habitability from
chlorine on or off site evident
MILLS, L M Tennessee Valley Authority B2/07/27 DENTON, H R.
Office of Nuclear Reactor Regulation, Director 2pp. 14131 222
24X Fiche 50-000, B2/07/27, B208020221.

B208120363 Forwards revised version of model Tech Specs re electric
power monitoring of reactor protection sys previously
submitted in B11030 ltr.
VASSALLO, D B Operating Reactors Branch 2 B2/07/28 PARRIS, H G.
Tennessee Valley Authority, 3pp. 14340, 079 24X
Fiche: 50-000, B2/07/28, B208120363.

B208130444 Forwards safety evaluation & LLL technical evaluation rept
on licensee response to NUREG-0737, Item II B 1, "RCB Vents"
Issue resolved.
VASSALLO, D B Operating Reactors Branch 2 B2/08/02 PARRIS, H G
Tennessee Valley Authority, 3pp 14354, 343. 24X
Fiche: 50-000, B2/08/02, B208130444.

--B208130448 "RCB Vents," technical evaluation rept
BUTCHER, E., BARNHART, B. Lawrence Livermore Laboratory, FIN
A-0246-2. B2/06/02 Division of Licensing, 4pp. 14354, 346.
24X Fiche: 50-000, B2/08/02, B208130444

B208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP &
applicants re submittal of documents to NRC. Summarizes 10CFR
Chapter I requirements & provides alternatives to
requirements Bvc list encl.
EISENHUT, D O. Division of Licensing, B2/08/09. Consolidated
Edison Co. of New York 1p. 14356-332 24X Fiche: 50-000, B2/08/09,
B208090194.

B208250376 Forwards mechanical snubber qualification test repts for
Pacific Scientific Co Models PSA 1/4 - PSA 100, as requested
by NRC. Only qualitative-type actuation tests planned at
plants, beginning w/Brouns Ferry 2 & Sequoyah 1.
MILLS, L M Tennessee Valley Authority B2/08/18, DENTON, H R.
Office of Nuclear Reactor Regulation, Director 2pp. 14541 002
24X Fiche: 50-000, B2/08/18, B208250376.

--B208250383 Revision A to "Qualification Test Rept for Model 1801104-05
PSA 1/4 Shock."
WHITNEY, R F., GLAUSER, J E., WRIGHT, W B Pacific Scientific TR
B39 RA B2/03/18 27pp. 14541:005. 24X Fiche: 50-000, B2/08/18,
B208250376.

--B208250387 Revision R to "Acceptance Test Procedure IT 527 P/N
1801104."
LEVAN, H C. Pacific Scientific, 79/11/09. 13pp. 14541:032. 24X
Fiche: 50-000, B2/08/18, B208250376

--B208250391 "Qualification Test Rept for Model 1801104-07 PSA 1/2 Shock
Arrestor."
WHITNEY, R F., GLAUSER, J E., WRIGHT, W B Pacific Scientific. TR
B40. 79/12/12. 27pp. 14541:045 24X Fiche: 50-000, B2/08/18,
B208250376.

--B208250402 Revision A to "Qualification Test Rept for Model 1801102-05
PSA 1 Shock Arrestor"
WHITNEY, R F., GLAUSER, J E., WRIGHT, W B Pacific Scientific. TR
B41 RA. 80/03/18 26pp. 14541:083. 24X Fiche: 50-000, B2/08/18,
B208250376

--B208250409 Revision T to "Acceptance Test Procedure IT 519 P/N
1801102."
LEVAN, H C. Pacific Scientific, 79/06/13. 14pp. 14541:111. 24X
Fiche: 50-000, B2/08/18, B208250376.

--B208250415 "Qualification Test Rept for Model 1801106-05 PSA-3 Shock
Arrestor."
WHITNEY, R F., GLAUSER, J E., WRIGHT, W B Pacific Scientific TR
B42. 80/01/22. 27pp 14541:125. 24X Fiche 50-000, B2/08/18,
B208250376.

--B208250421 Revision R to "Acceptance Test Procedure IT 524 for
1801106 "
LEVAN, H C Pacific Scientific, 79/02/15 13pp 14541 152 24X
Fiche: 50-000, B2/08/18, B208250376

--B208250426 "Qualification Test Rept for Model 1801103-07 PSA 10 Shock
Arrestor "
WHITNEY, R F., GLAUSER, J E., WRIGHT, W B Pacific Scientific TR
B43. 80/01/25 27pp 14541 166. 24X Fiche 50-000, B2/08/18,
B208250376

--B208250431 Revision R to "Acceptance Test Procedure IT 523 P/N
1801103 "
LEVAN, H C. Pacific Scientific, 79/08/15. 14pp. 14541 193. 24X
Fiche: 50-000, B2/08/18, B208250376

--B208250437 Revision A to "Qualification Test Rept for Model 1801102-11
PSA-35 Shock Arrestor."
WHITNEY, R F., GLAUSER, J E., WRIGHT, W B Pacific Scientific. TR
B45 RA. 80/02/07. 30pp. 14541:207 24X Fiche: 50-000, B2/08/18,
B208250376.

--B208250441 Revision J to "Acceptance Test Procedure IT 534 P/N
1801112 "
LEVAN, H C Pacific Scientific, 77/05/10 12pp 14541:237 24X
Fiche: 50-000, B2/08/18, B208250376

--B208250443 "Qualification Test Rept for Model 1801119-11 PSA-100 Shock
Arrestor."
WHITNEY, R F., GLAUSER, J E., WRIGHT, W B Pacific Scientific TR
B45. 80/05/12. 31pp 14541:249. 24X Fiche: 50-000, B2/08/18,
B208250376

--B208250446 Revision H to "Acceptance Test Procedure IT 533 P/N
1801119."
LEVAN, H C Pacific Scientific, 77/04/07 12pp. 14541:280. 24X
Fiche: 50-000, B2/08/18, B208250376.

G Inspection reports, IE Bulletins & correspondence

B204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MSIV)
Leakage." Bvc list encl.
JORDAN, E L Division of Engineering & Quality Assurance B2/07/16
Consolidated Edison Co. of New York. 87pp 14356, 274. 24X
Fiche: 50-000, B2/07/16, B204210393.

B204210395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of
Placement of Personnel Monitoring Devices for External
Radiation." Bvc list encl.
JORDAN, E L Division of Engineering & Quality Assurance B2/07/19
Michigan, Univ of. 112pp. 14358:001 24X Fiche: 50-000, B2/07/19,
B204210395

B204210396 IE Info Notice B2-25, "Failures of Miller Actuators Upon
Gradual Loss of Air Pressure." Bvc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. B2/07/20
Consolidated Edison Co. of New York. 112pp. 14381:001. 24X
Fiche: 50-000, B2/07/20, B204210396

B204210397 IE Info Notice B2-24, "Water Leaking From U Hexafluoride
Overpacks." Bvc list encl.
COBB, L I. Division of Fuel Facilities, Materials & Safeguards.
B2/07/20. Consolidated Edison Co. of New York. 71pp. 14357, 2/6
24X Fiche: 50-000, B2/07/20, B204210397.

B204210398 IE Info Notice B2-26, "RCIC & HPCI Turbine Exhaust Check
Valve Failures." Bvc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. B2/07/22.
Consolidated Edison Co. of New York. 112pp. 14194:321. 24X
Fiche: 50-000, B2/07/22, B204210398.

B204210401 IE Info Notice B2-28, "Hydrogen Explosion While Grinding in
Vicinity of Drained & Open RCB." Bvc list encl.
JORDAN, E L Division of Engineering & Quality Assurance B2/07/23
Consolidated Edison Co. of New York. 122pp. 14380:115. 24X
Fiche 50-000, B2/07/23, B204210401.

B204210402 IE Info Notice B2-29, "Control Rod Drive (CRD) Guide Tube
Support Pin Failures at Westinghouse PWRs." Bvc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. B2/07/23
Consolidated Edison Co. of New York. 127pp 14194:120. 24X
Fiche: 50-000, B2/07/23, B204210402.

B204210403 IE Info Notice B2-30, "Loss of Thermal Sleeves in RCB Piping
at Certain Westinghouse PWR Power Plants." Bvc list encl.
JORDAN, E L Division of Engineering & Quality Assurance. B2/07/26
Consolidated Edison Co. of New York. 121pp. 14397:013. 24X
Fiche: 50-000, B2/07/26, B204210403

8208030582 Ack receipt of 820716 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-14, 50-260/82-14 & 50-296/82-14
LEWIS, R.C. Division of Project & Resident Programs. 82/07/26
PARRIS, H.G. Tennessee Valley Authority. 1p. 14162:277. 24X
Fiche 50-259, 82/07/26, 8208030582

--8208030592 Responds to NRC 820609 ltr re violations noted in IE Insp Repts 50-259/82-14, 50-260/82-14 & 50-296/82-14. Corrective actions posted signs identifying shield plugs that require presence of health physics personnel for removal
KAMMER, D.B. Tennessee Valley Authority. 82/07/16. O'REILLY, J.P. Region 2, Office of Director. 4pp. 14162:278. 24X
Fiche 50-259, 82/07/26, 8208030592

--8208030597 Forwards IE Insp Repts 50-259/82-14, 50-260/82-14 & 50-296/82-14 on 820503-04 & notice of violation
LEWIS, R.C. Division of Project & Resident Programs. 82/06/09
PARRIS, H.G. Tennessee Valley Authority. 2pp. 14162:282. 24X
Fiche 50-259, 82/07/26, 8208030597

--8208030602 Notice of violation from Insp on 820503-04
* Division of Project & Resident Programs. 82/06/09. 2pp.
14162:284. 24X Fiche 50-259, 82/07/26, 8208030602

--8208030610 IE Insp Repts 50-259/82-14, 50-260/82-14 & 50-296/82-14 on 820503-04 Noncompliance noted. Failure to perform radiation survey after removal of shield plugs & failure to issue permit for removal of demineralizer cell shield plugs
PEERY, W.W., BARR, K.P. Division of Engineering & Technical Programs. 82/06/02. 4pp. 14162:285. 24X Fiche 50-259, 82/07/26, 8208030610

8208160395 Forwards IE Insp Repts 50-259/82-18, 50-260/82-18 & 50-296/82-18 on 820626-0725 No noncompliance noted.
VERRELLI, D.M. Division of Project & Resident Programs. 82/07/26.
PARRIS, H.G. Tennessee Valley Authority. 2pp. 14348:012. 24X
Fiche 50-259, 82/07/26, 8208160395

--8208160408 IE Insp Repts 50-259/82-18, 50-260/82-18 & 50-296/82-18 on 820626-0725 No noncompliance noted. Major areas inspected: operational safety, RDs, surveillance testing, maint. observation, TMI action items & independent insp effort
CHASE, J.W., PAULK, G.L., CANTRELL, F.B. Division of Project & Resident Programs. 82/07/26. 8pp. 14348:014. 24X
Fiche 50-259, 82/07/26, 8208160395

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/28
Consolidated Edison Co. of New York. 122pp. 14357:146. 24X
Fiche 50-000, 82/07/28, 8204210405

8208160294 Forwards IE Insp Repts 50-259/82-21, 50-260/82-21 & 50-296/82-21 on 820628-0702 No noncompliance noted.
VERRELLI, D.M. Division of Project & Resident Programs. 82/07/28.
PARRIS, H.G. Tennessee Valley Authority. 2pp. 14345:255. 24X
Fiche 50-259, 82/07/28, 8208160294

--8208160311 IE Insp Repts 50-259/82-21, 50-260/82-21 & 50-296/82-21 on 820628-0702 No noncompliance noted. Major areas inspected: radioactive matl packaging, shipment & processing, posting of notices, housekeeping & instrument calibr.
COLLINS, T.R., DEBS, B.T., BARR, K.P. Division of Engineering & Technical Programs. 82/07/22. 9pp. 14345:257. 24X
Fiche 50-259, 82/07/20, 8208160294

8208160484 Ack receipt of 820730 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-19, 50-260/82-19 & 50-296/82-19
VERRELLI, D. Division of Project & Resident Programs. 82/08/03.
PARRIS, H.G. Tennessee Valley Authority. 1p. 14348:104. 24X
Fiche 50-259, 82/08/03, 8208160484

--8208160491 Responds to NRC 820701 ltr re violations noted in IE Insp Repts 50-259/82-19, 50-260/82-19 & 50-296/82-19 Corrective actions: torus area high radiation rope barrier reinstalled & radiological tape placed on floor.
KAMER, D.B. Tennessee Valley Authority. 82/07/30. O'REILLY, J.P. Region 2, Office of Director. 3pp. 14348:105. 24X
Fiche 50-259, 82/08/03, 8208160484

--8208160498 Forwards IE Insp Repts 50-259/82-19, 50-260/82-19 & 50-296/82-19 on 820926-0625 & notice of violation.
LONG, F.J. Division of Project & Resident Programs. 82/07/01.
PARRIS, H.G. Tennessee Valley Authority. 2pp. 14348:108. 24X
Fiche 50-259, 82/08/03, 8208160484

--8208160531 IE Insp Repts 50-259/82-19, 50-260/82-19 & 50-296/82-19 on 820926-0625 Noncompliance noted: failure to properly barricade two high radiation areas in torus area.
CHASE, J.W., PAULK, G.L., CANTRELL, F.B. Division of Project & Resident Programs. 82/06/30. 6pp. 14348:111. 24X
Fiche 50-259, 82/08/03, 8208160484

8208160493 Ack receipt of 820720 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-15, 50-260/82-15 & 50-296/82-15.
LEWIS, R.C. Division of Project & Resident Programs. 82/08/04.
PARRIS, H.G. Tennessee Valley Authority. 1p. 14348:117. 24X
Fiche 50-259, 82/08/04, 8208160493

--8208160502 Responds to NRC 820603 ltr re violations noted in IE Insp Repts 50-259/82-15, 50-260/82-15 & 50-296/82-15. Corrective actions: daily monitoring & drainage program will be continued. Violations re items A & B denied.
MILLS, L.M. Tennessee Valley Authority. 82/07/20. O'REILLY, J.P. Region 2, Office of Director. 7pp. 14348:118. 24X
Fiche 50-259, 82/08/04, 8208160493

--8208160515 Forwards IE Insp Repts 50-259/82-15, 50-260/82-15 & 50-296/82-15 on 820426-0525 & notice of violation.
LEWIS, R.C. Division of Project & Resident Programs. 82/06/03.
PARRIS, H.G. Tennessee Valley Authority. 2pp. 14348:125. 24X
Fiche 50-259, 82/08/04, 8208160493

--8208160520 Notice of violation from Insp on 820426-0525.
* Division of Project & Resident Programs. 82/06/03. 2pp.
14348:127. 24X Fiche 50-259, 82/08/04, 8208160493

--8208160528 IE Insp Repts 50-259/82-15, 50-260/82-15 & 50-296/82-15 on 820426-0525. Noncompliance noted: written safety evaluation re offgas post-treatment sampling station configuration mod not performed.
CHASE, J.W., PAULK, G.L., CANTRELL, F.B. Division of Project & Resident Programs. 82/06/02. 10pp. 14348:129. 24X
Fiche 50-259, 82/08/04, 8208160493

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/08/05.
Consolidated Edison Co. of New York. 117pp. 14388:201. 24X
Fiche 50-000, 82/08/05, 8204210407

R Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J.M. Division of Rules and Records. 82/07/13. UDELL, R.A. Critical Mass Energy Project. 8pp. 14679:208. 24X
Fiche 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp.
14679:216. 24X Fiche 50-000, 82/07/13, 8208270010

--8208270601 Forwards "Personnel Whole Body Exposures for CY81," per 10CFR20.407.
MILLS, L.M. Tennessee Valley Authority. 82/03/23. BROOKS, B.O. License Operations Evaluation Branch. 1p. 14680:053. 24X
Fiche 50-000, 82/07/13, 8208270010

--8208270605 "Personnel Whole Body Exposures for CY81."
* Tennessee Valley Authority. 82/03/23. 2pp. 14680:054. 24X
Fiche 50-000, 82/07/13, 8208270010

8208120226 Forwards monthly operating repts for June 1982.
JONES, G.T. Tennessee Valley Authority. 82/07/14. Office of Management and Program Analysis. 1p. 14326:176. 24X
Fiche 50-259, 82/07/14, 8208120226

--8208120233 Monthly operating repts for June 1982.
JONES, G.T., THOM, T. Tennessee Valley Authority. 82/07/14. 39pp.
14326:177. 24X Fiche 50-259, 82/07/14, 8208120226

S. Reportable occurrences, LERs & related correspondence

8208030164 Forwards LER 82-030/03L-0.
GREEN, H.J. Tennessee Valley Authority. 82/07/29. O'REILLY, J.P. Region 2, Office of Director. 1p. 14212:075. 24X
Fiche 50-259, 82/07/29, 8208030164

--8208050170 LER 82-030/05L-0 on 820713, flow bias compactor trip initiated flow bias A drifted from accurate value of 94% to 100% causing high-flow trip points. Caused by proportional amplifier FG-6B-5 drifting upscale Amplifier replaced.
0050WHL D C Tennessee Valley Authority 82/07/29 Region 2,
Office of Director 2pp 14212 076 24X Fiche 50-296, 82/07/29,
8208050164

8208050394 Forwards updated LER 81-034/03X-1
GREEN, H J Tennessee Valley Authority 82/07/29 O'REILLY, J P
Region 2, Office of Director 1p 14209 204 24X
Fiche 50-296, 82/07/29, 8208050394.

--8208050401 Updated LER 81-034/03X-1 on 810709, RHR pump 3C tripped on ground overcurrent. Caused by turn-to-turn failure of motor coil in nonconnection and in buckle Motor replaced.
SOLLEY, S W Tennessee Valley Authority 82/07/29 Region 2,
Office of Director 3pp 14209 205 24X Fiche 50-296, 82/07/29,
8208050394

8208100037 PNO-11-82-090 on 820730, w/Unit 2 shutdown for scheduled refueling & mods, Units 1 & 2 failed secondary containment integrity tests & were shutdown. Caused by in-leakage between common refueling zone & three individual reactor zones
BUTCHER, R C VERRELLI, D M Region 2, Office of Director 82/08/05
1p 14296 261 24X Fiche 50-296, 82/08/05, 8208100037

8208200030 Forwards LER 82-032/03L-0
GREEN, H J Tennessee Valley Authority 82/08/12 O'REILLY, J P
Region 2, Office of Director 1p 14392 211 24X
Fiche 50-296, 82/08/12, 8208200030

--8208200041 LER 82-032/03L-0 on 820722, two degraded voltage relays on 4-kV shutdown boards 3EB & 3ED found to operate above max allowable setpoint. Setpoints apparently drifted up due to increased room temp since last calibr. Relays recalibr.
CHRISTOPHER, W Tennessee Valley Authority 82/08/12 Region 2,
Office of Director 2pp 14392 212 24X Fiche 50-296, 82/08/12,
8208200030

8208270474 Forwards LER 82-031/03L-0
GREEN, H J Tennessee Valley Authority 82/08/12 O'REILLY, J P
Region 2, Office of Director 1p 14565 337 24X
Fiche 50-296, 82/08/12, 8208270474

--8208270488 LER 82-031/03L-0 on 820716, two degraded voltage relay timers on 4-kV 608 3EC & 3ED found set at 0.26-s. Caused by timer setpoints change in 820329 Tech Spec revision, but not incorporated into 81 4 9 A 4 c. Timers recalibr.
CHRISTOPHER, W Tennessee Valley Authority 82/08/12 Region 2,
Office of Director 2pp 14565 338 24X Fiche 50-296, 82/08/12,
8208270474

8208310097 PNO-11-82-077 on 820819, truck transporting low specific radioactive matl from facility to Richland, WA found to have liquid dripping from truck bed. On 820821, drum found to have small holes near base
COLLINS, T R Region 2, Office of Director 82/08/24 1p
14695:084 24X Fiche 50-296, 82/08/24, 8208310097

DOCKET 50-297 NORTH CAROLINA STATE UNIV FULSTAR REACTOR

Q Inspection reports, IE Bulletins & correspondence

8204210395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Bvc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/19
Michigan Univ of 112pp 14358:001 24X Fiche 50-000, 82/07/19,
8204210395

DOCKET 50-298 COOPER NUCLEAR STATION

F Security, medical, emergency & fire protection plans

8208240176 Forwards IE Insp Rept 50-298/02-11 & IE Investigation Rept 50-298/02-09 on 820311 & 22-23 & 0315-30, respectively. No noncompliance noted
COLLINS, J T Region 4, Office of Director 82/08/09 HILL, D W
Nebraska Public Power District 2pp 14519 260 24X
Fiche 50-298, 82/08/09, 8208240176.

--8208240179 IE Insp Rept 50-298/02-11 on 820311 & 22-23. No noncompliance noted. Major areas inspected: capability of emergency warning sys to notify population promptly.
JOHNSON, E H, WILBORN, L, MURRAY, B Region 4, Office of Director
82/04/08 8pp 14519 270 24X Fiche 50-298, 82/08/09, 8208240176

--8208240184 IE Investigation Rept 50-298/02-09 on 820315-30. No noncompliance noted. Major areas investigated: apparent ratl false statement in util 820208 ltr to NRC re status of facility compliance w/10CFR App E
MATAKAB, R A, HACKETT, C A, MADSEN, O L Region 4, Office of Director 82/03/17 19pp 14519 278 24X Fiche 50-298, 82/04/09,
8208240176

8208310441 Discusses IE Insp on 820311 & 22 & forwards notice of violation & notice of proposed imposition of civil penalty
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/08/09 WASHMAN, H B Nebraska Public Power District
5pp 14697 327 24X Fiche 50-298, 82/08/09, 8208310441

--8208310446 Notice of violation & notice of proposed imposition of civil penalty in amount of \$300,000. Noncompliance noted: licensee had not demonstrated that administrative & physical means had been established for alerting public during emergency
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/08/09 3pp 14697 332 24X
Fiche 50-298, 82/08/09, 8208310441

--8208310452 Order modifying license effective immediately. Licensee submit to Region 4 for review & approval, comprehensive plan of action including independent appraisal of site & corporate mgt organizations & functions within 30 days
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 82/08/09 Nebraska Public Power District 19pp
14697 335 24X Fiche 50-298, 82/08/09, 8208310441

8208240437 Ack receipt of 820726 ltr w/encl Emergency Plan Implementing Procedure 5 7 27, "Early Warning Sys." Procedure under review
MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/08/13 PILANT, J M Nebraska Public Power District
1p 14526 361 24X Fiche 50-298, 82/08/13, 8208240437

--8208240438 Forwards Emergency Plan Implementing Procedure 5 7 27, Revision 1, "Early Warning Sys." w/encl
PILANT, J M Nebraska Public Power District 82/07/26
COLLINS, J T Region 4, Office of Director 1p 14526 362 24X
Fiche 50-298, 82/08/13, 8208240437

8208310130 Forwards IE Safeguards Insp Rept 50-298/02-19 on 820628-0702. No noncompliance noted. Rept withheld (ref 10CFR 2.790)
MADSEN, O L Division of Resident, Reactor Project & Engineering Programs 82/08/27 PILANT, J M Nebraska Public Power District
2pp 14695:128 24X Fiche 50-298, 82/08/27, 8208310130

O Adjudicatory correspondence

8208110155 Statement of Commission directing NRC to issue notice of violation & order imposing civil penalties on licensee for failure to complete prompt public notification sys by 820201 & for three matl false statements re on-line status.
CHILKIS, J J Office of the Secretary of the Commission 82/08/09
9pp 14314 274 24X Fiche 50-298, 82/08/09, 8208110155

I Financial information

8208020106 Forwards info demonstrating ability to obtain funds of \$10 million for payment of deferred premiums
PILANT, J M Nebraska Public Power District 82/07/28 Office of Nuclear Reactor Regulation, Director 87pp 14142 117 24X
Fiche 50-298, 82/07/28, 8208020106

P Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applic for PL & holders of CP re Commission approved charter for CROR Bvc list encl.
DIRKSB, W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14196 403
24X Fiche 50-000, 82/07/02, 8207080064

8208020442 Forwards safety evaluation finding util 810630 response NUREG-0737, Item 11 K 3 24 re adequacy of space cooling for HPCI & reactor core isolation cooling sys acceptable
VASSALLO, D B Operating Reactors Branch 2 82/07/08 PILANT, J M Nebraska Public Power District 3pp 14181 041 24X
Fiche 50-298, 82/07/08, 8208020442

8208160297 Forwards revisions to 820224 P&ID list
PILANT, J M Nebraska Public Power District 82/07/27 COLLINS, J T
Region 4, Office of Director 3pp 14346 276 24X
Fiche 50-298, 82/07/27, 8208160297

26 Forwards revised Tech Specs updating 800805 submittal re
loop operation.
J.M. Nebraska Public Power District. 82/07/28
L.D.B. Operating Reactors Branch 2. 2pp. 14142 076. 24X
90-298. 82/07/28. 8208020126.

Q124 Revised Tech Specs re single loop operation
Nebraska Public Power District. 82/07/28. 26pp. 14142.078.
Fiche: 90-298. 82/07/28. 8208020126

35 Forwards safety evaluation supporting conclusion that
method for implementing guidance of NUREG-0737,
T.K. 3.15, "Isolation of HPCI & RCIC," acceptable item
erred resolved.
L.D.B. Licensing Branch 2. 82/08/03. PILANT, J.M. Nebraska
Public Power District. 3pp. 14544.177. 24X Fiche: 90-298. 82/08/03.
0435.

94 Generic Ltr 82-14 to all reactor licensees, holders of CP &
ents re submittal of documents to NRC Bureaus; 10CFR
r I requirements & provides alternatives to
essents. Svc list encl.
UT.D. Division of Licensing. 82/08/09. Consolidated
Co. of New York. 1p. 14356.332. 24X Fiche: 90-000. 82/08/09.
0194

80 Informs that due to terminations of 6 senior licensed
ers, overtime being used to regularly fill 3 positions
ular reactor operator crews. Crew shifting necessary
er to properly train license candidates
J.M. Nebraska Public Power District. 82/08/13
L.D.B. Operating Reactors Branch 2. 2pp. 14393.245. 24X
90-298. 82/08/13. 8208200088.

40 Responds to 820708 request for info re Cycles 7 & 8
ing limit min critical power ratio. Util has been
ed by GE that decrease is result of normal cycle-to-
differences & not correction in ODYN code
J.M. Nebraska Public Power District. 82/08/20
L.D.B. Operating Reactors Branch 3. 1p. 14565.105. 24X
90-298. 82/08/20. 8208270340

86 Requests that 820930 order date for completion of Mark I
ment program mode be changed to Spring 1983 refueling
to complete remaining work on torus temp monitoring

J.M. Nebraska Public Power District. 82/08/23.
L.D.B. Operating Reactors Branch 2. 2pp. 14692.111. 24X
90-298. 82/08/23. 8208310306.

ction reports, IE Bulletins & correspondence

93 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
e." Svc list encl.
J.E.L. Division of Engineering & Quality Assurance. 82/07/16.
olidated Edison Co. of New York. 87pp. 14356.274. 24X
90-000. 82/07/16. 8204210393

95 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of
ent of Personnel Monitoring Devices for External
ion." Svc list encl.
J.E.L. Division of Engineering & Quality Assurance. 82/07/19.
igan, Univ. of. 112pp. 14358.001. 24X Fiche: 90-000. 82/07/19.
0395

96 IE Info Notice 82-25, "Failures of Hiller Actuators Upon
Loss of Air Pressure." Svc list encl.
J.E.L. Division of Engineering & Quality Assurance. 82/07/20.
olidated Edison Co. of New York. 112pp. 14381.001. 24X
90-000. 82/07/20. 8204210396.

97 IE Info Notice 82-24, "Water Leaking From U Hexafluoride
cks." Svc list encl.
J.E.L. Division of Fuel Facilities, Materials & Safeguards.
20. Consolidated Edison Co. of New York. 71pp. 14387.276.
Fiche: 90-000. 82/07/20. 8204210397.

98 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check
Failures." Svc list encl.
J.E.L. Division of Engineering & Quality Assurance. 82/07/22.
olidated Edison Co. of New York. 112pp. 14194.321. 24X
90-000. 82/07/22. 8204210398.

01 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in
ty of Drained & Open RCS." Svc list encl.
J.E.L. Division of Engineering & Quality Assurance. 82/07/23.
olidated Edison Co. of New York. 122pp. 14380.115. 24X
90-000. 82/07/23. 8204210401.

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube
Support Pin Failures at Westinghouse PHRs." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York. 127pp. 14194.120. 24X
Fiche: 90-000. 82/07/23. 8204210402.

8208160465 Forwards IE Insp Rept 90-298/82-17 on 820621. No
noncompliance noted.
MADSEN, O.L. Division of Resident, Reactor Project & Engineering
Programs. 82/07/23. PILANT, J.M. Nebraska Public Power District
2pp. 14349.263. 24X Fiche: 90-298. 82/07/23. 8208160465.

--8208160470 IE Insp Rept 90-298/82-17 on 820621. No noncompliance noted.
Major areas inspected followup insp of C-E reactor vessel
stud evaluation.
TAPIA, J.L., WESTERMAN, T.F., HUNNICUTT, D.M. Division of Resident,
Reactor Project & Engineering Programs. 82/07/22. 3pp.
14349.283. 24X Fiche: 90-298. 82/07/23. 8208160465.

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping
at Certain Westinghouse PHR Power Plants." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/26.
Consolidated Edison Co. of New York. 121pp. 14357.013. 24X
Fiche: 90-000. 82/07/26. 8204210403.

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in
Fuel Storage Pool." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/28.
Consolidated Edison Co. of New York. 122pp. 14357.146. 24X
Fiche: 90-000. 82/07/28. 8204210405

8208190292 Forwards IE Insp Rept 90-298/82-18 on 820622-24. No
noncompliance noted.
MADSEN, O.L. Division of Resident, Reactor Project & Engineering
Programs. 82/08/02. PILANT, J.M. Nebraska Public Power District.
2pp. 14387.109. 24X Fiche: 90-298. 82/08/02. 8208190292

--8208190293 IE Insp Rept 90-298/82-18 on 820622-24. No noncompliance
noted. Major areas inspected. license action on previously
identified items & review of insp & repair activities re
replacement of degraded pipe in reactor water cleanup sys.
GILBERT, L.D., WESTERMAN, T.F., HUNNICUTT, D.M. Division of Resident,
Reactor Project & Engineering Programs. 82/07/28. 5pp.
14387.111. 24X Fiche: 90-298. 82/08/02. 8208190292.

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From
Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/08/05.
Consolidated Edison Co. of New York. 117pp. 14388.201. 24X
Fiche: 90-000. 82/08/05. 8204210407.

8208100033 EN-82-028 on 820809, notices of violation & proposed
imposition of civil penalty & order modifying license
effective immediately issued to licensee.
LEBERMAN, J., DEYOUNG, R. Director's Office, Office of Inspection and
Enforcement. 82/08/09. 1p. 14296.273. 24X Fiche: 90-298. 82/08/09.
8208100033

8208240176 Forwards IE Insp Rept 90-298/82-11 & IE Investigation Rept
90-298/82-09 on 820311 & 22-23 & 0315-30, respectively. No
noncompliance noted.
COLLINS, J.T. Region 4, Office of Director. 82/08/09. HILL, D.W.
Nebraska Public Power District. 2pp. 14519.268. 24X
Fiche: 90-298. 82/08/09. 8208240176.

--8208240179 IE Insp Rept 90-298/82-11 on 820311 & 22-23. No noncompliance
noted. Major areas inspected: capability of emergency warning
sys to notify population promptly.
JOHNSON, E.H., WILBORN, L., MURRAY, B. Region 4, Office of Director.
82/04/08. 5pp. 14519.270. 24X Fiche: 90-298. 82/08/09. 8208240176.

--8208240184 IE Investigation Rept 90-298/82-09 on 820315-30. No
noncompliance noted. Major areas investigated: apparent matl
false statement in util 820208 ltr to NRC re status of
facility compliance w/10CFR App E
MATAKAB, R.A., HACKNEY, C.A., MADSEN, O.L. Region 4, Office of
Director. 82/05/17. 19pp. 14519.278. 24X Fiche: 90-298. 82/08/09.
8208240176.

8208310441 Discusses IE insp on 820311 & 22 & forwards notice of
violation & notice of proposed imposition of civil penalty.
DEYOUNG, R.C. Director's Office, Office of Inspection and
Enforcement. 82/08/09. KASHAN, H.B. Nebraska Public Power District.
5pp. 14697.327. 24X Fiche: 90-298. 82/08/09. 8208310441.

--8208310446 Notice of violation & notice of proposed imposition of civil
penalty in amount of \$300,000. Noncompliance noted: licensee
had not demonstrated that administrative & physical means
had been established for alerting public during emergency.
DEYOUNG, R.C. Director's Office, Office of Inspection and
Enforcement. 82/08/09. 3pp. 14697.332. 24X
Fiche: 90-298. 82/08/09. 8208310441.

--B208310452 Order modifying license effective immediately Licensee shall submit to Region 4 for review & approval, comprehensive plan of action including independent appraisal of site & corporate mgt organizations & functions within 30 days
DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. B2/08/09 Nebraska Public Power District Bpp. 14697 335. 24X Fiche 50-298, B2/08/09, B208310441

B208270471 Forwards IE Insp Rept 50-298/B2-15 on B20706-09 No noncompliance noted
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs B2/08/10 PILANT, J. M. Nebraska Public Power District. 2pp 14564: 047 24X Fiche 50-298, B2/08/10, B208270471

--B208270478 IE Insp Rept 50-298/B2-15 on B20706-09 No noncompliance noted Major areas inspected, organization & administration, calibr & fire prevention
JAUDON, J. P., MURPHY, M. E., WESTERMAN, T. F. Division of Resident, Reactor Project & Engineering Programs. B2/08/06 Bpp 14564: 049. 24X Fiche 50-298, B2/08/10, B208270471

B208240216 Forwards errata to IE Insp Rept 50-298/B2-09, containing Exhibits 1-21
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs B2/08/19 PILANT, J. M. Nebraska Public Power District 1p 14521: 111 24X Fiche 50-298, B2/08/19, B208240216

--B208240223 Errata to IE Insp Rept 50-298/B2-09, containing Exhibits 1-21
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs. B2/08/19 53pp 14521: 112. 24X Fiche 50-298, B2/08/19, B208240216

B208310130 Forwards IE Safeguards Insp Rept 50-298/B2-19 on B20628-0702 No noncompliance noted, Rept withheld (ref 10CFR2.790).
MADSEN, G. L. Division of Resident, Reactor Project & Engineering Programs. B2/08/27 PILANT, J. M. Nebraska Public Power District 2pp. 14695: 128. 24X Fiche 50-298, B2/08/27, B208310130

R. Periodic operating reports & related correspondence

B208120040 Forwards monthly operating rept for June 1982
LEBBOR, L. C. Nebraska Public Power District. B2/06/29 Management Information Branch. 1p. 14323: 351 24X Fiche 50-298, B2/06/29, B208120040

--B208120042 Monthly operating rept for June 1982
BALLINGER, B. L. Nebraska Public Power District. B2/06/29. 4pp. 14323: 352 24X Fiche 50-298, B2/06/29, B208120040.

B208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A
FELTON, J. M. Division of Rules and Records. B2/07/13 UDELL, R. A. Critical Mass Energy Project. Bpp 14679: 208 24X Fiche 50-000, B2/07/13, B208270010.

--B208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. B2/07/13 4Bpp. 14679: 216. 24X Fiche 50-000, B2/07/13, B208270010.

--B208270182 Forwards "Personnel Whole Body Exposures for CY81," per 10CFR20.407(a) & (b).
LEBBOR, L. C. Nebraska Public Power District. B2/01/29. Office of Management and Program Analysis. 1p. 14679: 271. 24X Fiche 50-000, B2/07/13, B208270010.

--B208270185 "Personnel Whole Body Exposures for CY81."
* Nebraska Public Power District. B2/01/29 1p. 14679: 272. 24X Fiche 50-000, B2/07/13, B208270010.

B. Reportable occurrences, LERs & related correspondence

B208100277 Forwards noncompliance rept submitted on B20803 to NE Dept of Environ Control. Max temp of 103.5 F experienced on B20725 while circulating water pump A was removed from svc.
COOPER, L. J. Nebraska Public Power District. B2/08/03 IPPOLITO, T. A. Operating Reactors Branch 2 2pp. 14297: 068 24X Fiche 50-298, B2/08/03, B208100277

B208160173 Forwards LER B2-015/03L-0 Detailed event analysis submitted.
LESSOR, L. C. Nebraska Public Power District. B2/08/05 COLLINS, J. T. Region 4, Office of Director. 4pp. 14345: 116. 24X Fiche 50-298, B2/08/05, B208160173

--B208160176 LER B2-015/03L-0 on B20706, eleven penetrations, 1 excessively during leak rate test Cause not stated Valve repairs performed on anchor gates, globes & checks Anchor gate valve replaced Final leakage within limit
HOLKEN, M. A. Nebraska Public Power District. B2/08/05 4. Office of Director 1p. 14345: 120 24X Fiche 50-298, B208160173.

B208200103 Forwards LER B2-016/03L-0 Detailed event analysis
LESSOR, L. C. Nebraska Public Power District. B2/08/10 CO Region 4, Office of Director 2pp 14399: 153 24X Fiche 50-298, B2/08/10, B208200103

--B208200109 LER B2-016/03L-0 on B20712, diesel generator trip alarms or indications Redundant sys operable. Caused by dn in holding mechanism of safety trip valve overspeed device Valve & section of control air line replaced.
FLAHERTY, J. R. Nebraska Public Power District. B2/08/10 4. Office of Director 1p. 14399: 155 24X Fiche 50-298, B208200103

B208200166 Forwards LER B2-017/03L-0 Detailed event analysis
LESSOR, L. C. Nebraska Public Power District. B2/08/10 CO Region 4, Office of Director 2pp 14394: 022. 24X Fiche 50-298, B2/08/10, B208200166

--B208200176 LER B2-017/03L-0 on B20713, at completion of over on diesel generator 2, diesel tripped before loading. Cause by low lube oil pressure switch Switch replaced
FLAHERTY, J. R. Nebraska Public Power District. B2/08/10. 4. Office of Director 1p. 14394: 024 24X Fiche 50-298, B208200166

B208240369 Forwards LER B2-019/03L-0 Detailed event analysis
LESSOR, L. C. Nebraska Public Power District. B2/08/13 CO Region 4, Office of Director 2pp. 14522: 347 24X Fiche 50-298, B2/08/13, B208240369

--B208240380 LER B2-019/03L-0 on B20726, drywell equipment su level alarm w/ subsequent automatic pump operation observ. Caused by blown fuse in power supply 20-545A for flow recorder & flow integrator Fuse replaced.
KRAUSE, R. W. Nebraska Public Power District. B2/08/13 4. Office of Director. 1p. 14522: 349. 24X Fiche 50-298, B208240369.

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

B208040283 Releases public version of revised emergency plan implementing procedures.
FELTON, J. M. Division of Rules and Records. B2/07/20 Management Branch. 1p. 14231: 001 24X Fiche 50-266, B2/07/20, B208040283

--B208040288 Forwards public version of revised emergency plan implementing procedures, including Procedures EP 1.3 re estimation of source term, EPIP 3.1 re alert - immediate actions & EPIP 4.1 re site emergency - immediate actions
FAY, C. W. Wisconsin Electric Power Co. B2/07/09. DENTON, Office of Nuclear Reactor Regulation, Director. CLARK, R. Operating Reactors Branch 3. 4pp. 14231: 002. 24X Fiche 50-266, B2/07/20, B208040283.

--B208040293 Public version of revised emergency plan implementing procedures, including Procedures EP 1.3 re estimation of source term, EPIP 3.1 re alert - immediate actions & EPIP 4.1 re site emergency - immediate actions.
* Wisconsin Electric Power Co. B2/06/25. 54pp. 14231: 003. 24X Fiche 50-266, B2/07/20, B208040283.

B208190188 Forwards revisions to security force training & qualification plan as requested in B20715 ltr. Revision withheld (ref 10CFR2.790).
BURGATEIN, S. Wisconsin Electric Power Co. B2/08/06 CLARK, Operating Reactors Branch 3. 1p. 14387: 048. 24X Fiche 50-266, B2/08/06, B208190188.

B208190224 Advises that scheduling conflicts & reluctance of WI to participate in annual emergency exercise during Bump 1983, support until B20630 request for exemption from 10CFR App E Exercise scheduled for B20920.
FAY, C. W. Wisconsin Electric Power Co. B2/08/09. DENTON, Office of Nuclear Reactor Regulation, Director. CLARK, R. Operating Reactors Branch 3. 3pp. 14387: 177. 24X Fiche 50-266, B2/08/09, B208190224.

8208260531 Ack receipt of 820715 ltr re emergency operations facility
Deviations from physical proximity guidelines to plant site
must be approved by NRC.
COLBURN, T.O. Operating Reactors Branch 3. 82/08/11. FAY, C.W.
Wisconsin Electric Power Co. 2pp. 14372 337. 24X
Fiche: 50-266, 82/08/11, 8208260531

8208260054 Releases public version of emergency plan manual.
FELTON, J.H. Division of Rules and Records. 82/08/13. Document
Management Branch. 1p. 14374 078. 24X Fiche: 50-266, 82/08/13.
8208260054

--8208260059 Forwards public version of emergency plan manual, including
revisions to Procedures EP 2.0 re emergency plan
definitions, EP 4.0 re emergency conditions & EP 6.0 re
emergency measures.
BURSTEIN, S. Wisconsin Electric Power Co. 82/08/02. DENTON, H.R.
Office of Nuclear Reactor Regulation, Director. CLARK, R.A.
Operating Reactors Branch 3. 5pp. 14374 079. 24X
Fiche: 50-266, 82/08/13, 8208260054

--8208260067 Public version of emergency plan manual, including revisions
to Procedures EP 2.0 re emergency plan definitions, EP 4.0 re
emergency conditions & EP 6.0 re emergency measures
* Wisconsin Electric Power Co. 82/07/30. 250pp. 14374 084. 24X
Fiche: 50-266, 82/08/13, 8208260054.

Q Adjudicatory correspondence

8208110180 Responds to ASLB B11013 memorandum & order re removal of
explosive or mechanical plugs from tubes prior to sleeving.
Supporting documentation & DW Porter affidavit encl.
CHURCHILL, B.W., RIDGWAY, D.A. Wisconsin Electric Power Co.
CHURCHILL, B.W., Shaw, Pittman, Potts & Trowbridge. 81/10/16. 30pp.
14314: 141. 24X Fiche: 50-266, 81/10/16, 8208110180.

8208100031 Advises that NRC will not respond to licensee 820722 motion
to conduct discovery of WI Environ Decade re Decade contacts
w/sleeving demonstration program workers
BACHMANN, R.Q. Hearing Branch 1. 82/08/06. BLOCH, P.R., PAXTON, H.C.,
KLINE, J.R. Atomic Safety and Licensing Board Panel. 1p. 14296 274.
24X Fiche: 50-266, 82/08/06, 8208100031

8208100076 Response to interrogatories re safety evaluation on
Full-scale sleeving Certificate of Svc encl.
BACHMANN, R.Q. Hearing Branch 1. 82/08/06. Wisconsin's
Environmental Decade. 17pp. 14296 137. 24X Fiche: 50-266, 82/08/06,
8208100076

8208270315 Forwards licensee response to WI Environ Decade motion re
litigable issues & WD Fletcher statement Proprietary
versions served on NRC & Decade. Nonproprietary version
served on remainder of svc list
CHURCHILL, B.W., Shaw, Pittman, Potts & Trowbridge. CHURCHILL, B.W.
Wisconsin Electric Power Co. 82/08/09. BLOCH, P.R., KLINE, J.R.,
PAXTON, H.C. Atomic Safety and Licensing Board Panel. 2pp.
14363: 207. 24X Fiche: 50-266, 82/08/09, 8208270315.

--8208270319 Response to WI Environ Decade 820720-21 motion concerning
litigable issues. Decade stopped from raising number of
proposed contentions. Decade fails to justify untimeliness.
Some proposed issues irrelevant.
CHURCHILL, B.W. Wisconsin Electric Power Co. CHURCHILL, B.W., Shaw,
Pittman, Potts & Trowbridge. 82/08/09. Atomic Safety and
Licensing Board Panel. 7pp. 14363: 209. 24X
Fiche: 50-266, 82/08/09, 8208270315.

8208120009 Forwards PQ Easley affidavit of preparation of response to
WI Environ Decade Interrogatory 2. Affiant not available to
sign affidavit in time to meet 820806 filing deadline.
BACHMANN, R.Q. Hearing Branch 1. 82/08/10. BLOCH, P.R., PAXTON, H.C.,
KLINE, J.R. Atomic Safety and Licensing Board Panel. 2pp.
14323 337. 24X Fiche: 50-266, 82/08/10, 8208120009.

8208160219 Informs of 820809 telcon w/PR Bloch re Nucleonics WI 820809
article. "Utils Given NRC Laundry List of Steam Generator
Proposals." Author informed Bloch on 820810 that NRC will
not provide info on article due to preliminary nature.
BACHMANN, R.Q. Hearing Branch 1. 82/08/12. BLOCH, P.R., KLINE, J.R.,
PAXTON, H.C. Atomic Safety and Licensing Board Panel. 5pp.
14342 330. 24X Fiche: 50-266, 82/08/12, 8208160219.

8208180118 Response to WI Environ Decade 820721 motion concerning
litigable issues. Contentions 1-3 & alternative contention on
interrelationship w/thermal shock. Only Contentions 3(a) &
3(b) admissible. Notice of appearance encl.
BACHMANN, R.Q., MCCURREN, H.J. Hearing Branch 1. 82/08/16. Atomic
Safety and Licensing Board Panel. 36pp. 14378 203. 24X
Fiche: 50-266, 82/08/16, 8208180118

--8208180123 Statement of matl fact as to which there is no genuine
issue.
BACHMANN, R.Q. Hearing Branch 1. 82/08/16. Atomic Safety and
Licensing Board Panel. 14pp. 14378 239. 24X
Fiche: 50-266, 82/08/16, 8208180118.

--8208180127 Affidavit of TO Colburn re WI Environ Decade 820721 motion
concerning litigable issues. Contentions 1, 2a, 2c, 3b, 3c, 4
& 5.
COLBURN, T.O. Operating Reactors Branch 3. 82/08/16. 10pp.
14378 253. 24X Fiche: 50-266, 82/08/16, 8208180118.

--8208180131 Affidavit of PQ Easley re WI Environ Decade 820721 motion
concerning litigable issues. Contention 2(a).
EASLEY, P.Q. Accident Evaluation Branch. 82/08/16. 2pp.
14378 263. 24X Fiche: 50-266, 82/08/16, 8208180118.

--8208180134 Affidavit of EL Murphy re WI Environ Decade 820721 motion
concerning litigable issues. Contentions 3(a), 3(d) & 3(e).
Certificate of Svc encl.
MURPHY, E.L. Materials Engineering Branch. 82/08/12. 10pp.
14378 265. 24X Fiche: 50-266, 82/08/16, 8208180118

8208200293 Confirms licensee understanding w/WI Environ Decade re time
for filing Decade amend to Decade motion concerning
litigable issues. Licensee provided disputed documents to
Decade on 820818. Amend to motion due 820820. Svc list encl.
CHURCHILL, B.W., Shaw, Pittman, Potts & Trowbridge. CHURCHILL, B.W.
Wisconsin Electric Power Co. 82/08/18. BLOCH, P.R., KLINE, J.R.,
PAXTON, H.C. Atomic Safety and Licensing Board Panel. 3pp.
14398: 326. 24X Fiche: 50-266, 82/08/18, 8208200293.

8208270448 Amend to motion re third litigable issue on increased
probability of tube failures due to sleeving, per ASLB
direction during 820601 conference. Change adds Contention F
on sleeves in corroded tubes. W/Certificate of Svc.
ANDERSON, P. Wisconsin's Environmental Decade. 82/08/20. Atomic
Safety and Licensing Board Panel. 3pp. 14365: 253. 24X
Fiche: 50-266, 82/08/20, 8208270448.

8208270486 Response to WI Environ Decade 820721 amend to motion re
litigable issues. Proposed Contention 3(f) fails to satisfy
requirements for establishing litigable issues. Motion should
be rejected. Certificate of Svc encl.
RIDGWAY, D.A. Wisconsin Electric Power Co. RIDGWAY, D.A., Shaw,
Pittman, Potts & Trowbridge. 82/08/24. Atomic Safety and
Licensing Board Panel. 12pp. 14365: 061. 24X Fiche: 50-266, 82/08/24,
8208270486.

P. Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants
for OL & holders of CP re Commission approved charter for
CRGR. Svc list encl.
DIRCKE, W.J. Office of the Executive Director for Operations.
82/07/02. Consolidated Edison Co. of New York. 9pp. 14194: 001.
24X Fiche: 50-000, 82/07/02, 8207080064.

8208130128 Forwards Amends 62 & 67 to Licensees DPR-24 & DPR-27,
respectively & notice of issuance & availability. Amend
changes Tech Specs to modify limiting conditions for
operation re auxiliary feedwater pump operation.
COLBURN, T.O. Operating Reactors Branch 3. 82/07/27. FAY, C.W.
Wisconsin Electric Power Co. 5pp. 14350: 001. 24X
Fiche: 50-266, 82/07/27, 8208130128.

--8208130132 Amends 62 & 67 to Licensees DPR-24 & DPR-27, respectively,
changing Tech Specs to modify limiting conditions for
operation re auxiliary feedwater pump operation.
CLARK, R.A. Operating Reactors Branch 3. 82/07/27. 8pp.
14350: 005. 24X Fiche: 50-266, 82/07/27, 8208130128.

--8208130135 Notice of issuance & availability of Amends 62 & 67 to
Licensees DPR-24 & DPR-27, respectively.
CLARK, R.A. Operating Reactors Branch 3. 82/07/27. 1p.
14350: 013. 24X Fiche: 50-266, 82/07/27, 8208130128.

8208030440 Forwards response to NRC 820619 request for addl info re
proposed reactor vessel water level instrumentation sys
required by NUREG-0737, Item II, P.2.
FAY, C.W. Wisconsin Electric Power Co. 82/07/28. DENTON, H.R.
Office of Nuclear Reactor Regulation, Director. CLARK, R.A.
Operating Reactors Branch 3. 28pp. 14154: 019. 24X
Fiche: 50-266, 82/07/28, 8208030440.

8208040140 Forwards proprietary Figure 6.2.7-2, "Alternating Stresses
at Location of Max Fatigue Usage" & revised Page 6.86 to
WCAP-9960, "Point Beach Nuclear Plant Steam Generator
Sleeving Rept." Proprietary info withheld (ref 10CFR 2.790).
FAY, C.W. Wisconsin Electric Power Co. 82/07/28. DENTON, H.R.
Office of Nuclear Reactor Regulation, Director. CLARK, R.A.
Operating Reactors Branch 3. 2pp. 14189: 301. 24X
Fiche: 50-266, 82/07/28, 8208040140.

--B208040146 Submits application for withholding supplemental info to WCAP-9760. "Point Beach Nuclear Plant Steam Generator Sleeve Rept " Affidavit (AW-80-93) encl
WIESEMAN, R A Westinghouse Electric Corp 82/07/15 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 8pp 14189 303
24X Fiche 50-266, 82/07/28, B208040140

8208103084 Forwards addl info re generation of temp/pressure profiles for typical high energy line breaks outside containment, in response to B20701 request info based on analysis performed by Bechtel Power Corp in 1973.
BURSTEIN, S Wisconsin Electric Power Co 82/08/05 DENTON, H. R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 8pp 14246, 136 24X
Fiche 50-266, 82/08/05, B208100084

8208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter 1 requirements & provides alternatives to requirements Svc list encl
EISENHUT, D O Division of Licensing 82/08/09 Consolidated
Edison Co. of New York 1p 14356, 332 24X Fiche 50-000, 82/08/09, B208090194

8208130109 Submits addl response to NUREG-0737, Item II D 1 re black valves Marshall test data indicates that installed valves will function properly over range of operating & accident conditions
FAY, C W Wisconsin Electric Power Co 82/08/09 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 2pp 14333 272
24X Fiche 50-266, 82/08/09, B208130109

8208130130 Advises that info addressing criteria of NUREG-0737, Item II, B 3, "Post-Accident Sampling Sys." will be provided by B20930
FAY, C W Wisconsin Electric Power Co 82/08/09 DENTON, H. R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 1p 14336 018 24X
Fiche 50-266, 82/08/09, B208130130

8208170066 Forwards "Rept of Reactor Containment Bldg Integrated Leakage Rate Test for Point Beach Unit 2"
FAY, C W Wisconsin Electric Power Co 82/08/11 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 2pp 14362 102
24X Fiche 50-301, 82/08/11, B208170066

--8208170068 "Rept of Reactor Containment Bldg Integrated Leakage Rate Test for Point Beach Unit 2"
* Wisconsin Electric Power Co 82/07/31 18pp, 14362 104 24X
Fiche 50-301, 82/08/11, B208170066

8208170268 Discusses plans & Tech Spec changes for compliance w/requirements of 10CFR50 App J, per B20625 ltr Full compliance re plant design mods to containment spray sys will be achieved by Mar 1983
FAY, C W Wisconsin Electric Power Co 82/08/13 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 4pp 14367, 270
24X Fiche 50-266, 82/08/13, B208170268

0 Inspection reports, IE Bulletins & correspondence

8204210393 IE Info Notice B2-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/16
Consolidated Edison Co. of New York, 87pp, 14356 274 24X
Fiche 50-000, 82/07/16, B204210393

8204210395 IE Info Notice B1-26, Part 3, Suppl 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/19
Michigan Univ of 112pp 14358 001 24X Fiche 50-000, 82/07/19, B204210395

8204210396 IE Info Notice B2-23, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/20
Consolidated Edison Co. of New York 112pp 14381 001 24X
Fiche 50-000, 82/07/20, B204210396

8204210397 IE Info Notice B2-24, "Water Leaking From U Hexafluoride Overpacks " Svc list encl
COBB, L F Division of Fuel Facilities, Materials & Safeguards 82/07/20
Consolidated Edison Co. of New York 71pp, 14357, 276
24X Fiche 50-000, 82/07/20, B204210397

8204210398 IE Info Notice B2-26, "RPI & HPI Turbine Exhaust Check Valve Failures " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/22
Consolidated Edison Co. of New York, 112pp, 14194 321 24X
Fiche 50-000, 82/07/22, B204210398

B204210401 IE Info Notice B2-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co. of New York 122pp, 14380 115 24X
Fiche 50-000, 82/07/23, B204210401

B204210402 IE Info Notice B2-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/23
Consolidated Edison Co. of New York 127pp 14194 120 24X
Fiche 50-000, 82/07/23, B204210402

B204210403 IE Info Notice B2-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/26
Consolidated Edison Co. of New York 121pp 14357 013 24X
Fiche 50-000, 82/07/26, B204210403

8208020273 Responds to request for addl info re sleeving process Insp Sampling Insp of 10% of upper & lower sleeve joints will be made. Insp will be expanded if unacceptable measurements are noted
FAY, C W Wisconsin Electric Power Co 82/07/26 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 2pp 14152 293
24X Fiche 50-266, 82/07/26, B208020273

B204210405 IE Info Notice B2-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/07/28
Consolidated Edison Co. of New York 122pp 14357 146 24X
Fiche 50-000, 82/07/28, B204210405

B208030472 Responds to IE Bulletin 79-14 re as-built, safety-related piping sys Ninety-eight isometric drawings revised to incorporate mechanical corrections & represent as-built piping Remaining isometrics will be completed by B21231
FAY, C W Wisconsin Electric Power Co 82/07/28 KEPPLER, J O
Region 3, Office of Director 2pp 14154 090 24X
Fiche 50-266, 82/07/28, B208030472

B204210407 IE Info Notice B2-27, "Fuel Rod Degradation Resulting From Duffle Water-Jet Impingement " Svc list encl
JORDAN, E L Division of Engineering & Quality Assurance 82/08/05
Consolidated Edison Co. of New York 117pp 14388 201 24X
Fiche 50-000, 82/08/05, B204210407

B208200151 Submits response to IE Bulletin B2-02 re incidents of severe degradation of threaded fasteners in closures of RCPB of PWR plants
FAY, C W Wisconsin Electric Power Co 82/08/11 KEPPLER, J O
Region 3, Office of Director 10pp 14393 269 24X
Fiche 50-266, 82/08/11, B208200151

B208240365 Ack receipt of B20730 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/B2-01 & 50-301/B2-01.
SPESSARD, R L Division of Project & Resident Programs 82/08/16
BURSTEIN, S Wisconsin Electric Power Co 1p, 14920 171 24X
Fiche 50-266, 82/08/16, B208240365

--8208240370 Responds to NRC B20621 ltr re violations noted in IE Insp Repts 50-266/B2-01 & 50-301/B2-01 Corrective actions in-house procedure revised re personnel responsibilities & in-house chemistry procedure issued
BURSTEIN, S Wisconsin Electric Power Co 82/07/30 KEPPLER, J O
Region 3, Office of Director 9pp 14520 172 24X
Fiche 50-266, 82/08/16, B208240365

B208310165 Ack receipt of B20813 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/B2-10 & 50-301/B2-09.
SPESSARD, R L Division of Project & Resident Programs 82/08/24
BURSTEIN, S Wisconsin Electric Power Co 1p, 14693 185 24X
Fiche 50-266, 82/08/24, B208310165

--8208310171 Responds to NRC B20716 ltr re violations noted in IE Insp Repts 50-266/B2-10 & 50-301/B2-09. Corrective actions minor adjustment to door closer made Fire doors for safe shutdown equipment have been identified & labelled
FAY, C W Wisconsin Electric Power Co 82/08/13 KEPPLER, J O
Region 3, Office of Director 2pp 14693 186 24X
Fiche 50-266, 82/08/24, B208310165

R. Periodic operating reports & related correspondence

B208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info Forwards documents listed in App A.
FELYON, J M Division of Rules and Records 82/07/13 UOELL, R A
Critical Mass Energy Project 8pp 14679 208 24X
Fiche 50-000, 82/07/13, B208270010

--2208270577 Forwards "Rept on Personnel Exposure & Monitoring for CY81."

per 10CFR20.407
FAY, C. W. Wisconsin Electric Power Co. 82/02/22 Office of
Management and Program Analysis 1p 14679 318. 24X
Fiche: 50-000.82/07/13.8208270010.

--2208270581 "Rept on Personnel Exposure & Monitoring for CY81"
* Wisconsin Electric Power Co. 82/02/22. 1p 14679 319. 24X
Fiche: 50-000.82/07/13.8208270010

8208160041 Forwards monthly operating repts for Jul 1982
FAY, C. W. Wisconsin Electric Power Co. 82/08/10. NRC - No
Established Affiliation Given. 1p. 14344:220 24X
Fiche: 50-266.82/08/10.8208160041

--2208160043 Monthly operating repts for Jul 1982.
FAY, C. W. Wisconsin Electric Power Co. 82/08/06 8pp 14344:221.
24X Fiche 50-266.82/08/10.8208160041

5 Reportable occurrences, LERs & related correspondence

8208160510 Forwards LER 82-009/01T-0
FAY, C. W. Wisconsin Electric Power Co. 82/08/10. KEPLER, J. G.
Region 3, Office of Director 1p 14348 139 24X
Fiche: 50-301.82/08/10.8208160510

--2208160518 LER 82-009/01T-0 on 820727, discovered two of three level
instruments on boric acid storage tank C powered from
common source. Cause unknown due to lack of maint
documentation. Wiring will be changed to correct problem.
FAY, C. W. Wisconsin Electric Power Co. 82/08/10. Region 3,
Office of Director 3pp 14348 140. 24X Fiche: 50-301.82/08/10.
8208160510.

8208310264 Forwards LER 82-006/03L-0.
FAY, C. W. Wisconsin Electric Power Co. 82/08/20. KEPLER, J. G.
Region 3, Office of Director 1p 14688:160 24X
Fiche: 50-301.82/08/20.8208310264

--2208310269 LER 82-006/03L-0 on 820728, during pipe restraint welding to
section of chemical & vol control sys divert line piping,
pinhole leak developed in pipe adjacent to weld. Caused by
welding process. Hole repaired & hydrostatically tested.
FAY, C. W. Wisconsin Electric Power Co. 82/08/20. Region 3,
Office of Director 2pp. 14688:161. 24X Fiche 50-301.82/08/20.
8208310264.

7 Hearing transcripts on non-antitrust matters

8208270315 Forwards licensee response to WI Environ Decade motion re
litigable issues & WD Fletcher statement. Proprietary v
versions served on NRC & Decade. Nonproprietary version
served on remainder of svc list
CHURCHILL, B. Shaw, Pittman, Potts & Trowbridge. 82/08/09.
BLOCH, P. B. Atomic Safety and Licensing Board Panel. 2pp
14563:207 24X Fiche: 50-266.82/08/09.8208270315.

--2208270323 Testimony of WD Fletcher re issues raised in Contentions
1, 2, 3(a)-(e), 4 & 5 in WI Environ Decade 820721 motion
concerning litigable issues. Prof qualifications &
Certificate of Svc encl
FLETCHER, W. D. Wisconsin Electric Power Co. FLETCHER, W. D.
Westinghouse Electric Corp. 82/08/04. 30pp. 14563:280 24X
Fiche: 50-266.82/08/09.8208270315

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

8208090013 Responds to util 820608 ltr re guard training &
qualification plan. Commitments for guard force during 2-yr
implementation period acceptable.
STOLZ, J. Operating Reactors Branch 4. 82/07/23. HANCOCK, J. A.
Florida Power Corp. 1p. 14283:336. 24X Fiche: 50-302.82/07/23.
8208090013

8208160505 Forwards IE Insp Rept 50-302/82-13 on 820628-0702 No
noncompliance noted.
CANCE, H. C. Division of Project & Resident Programs. 82/07/26.
HANCOCK, J. A. Florida Power Corp. 2pp. 14348:088. 24X
Fiche: 50-302.82/07/26.8208160505.

Fiche: 50-302.82/07/26.8208160505

8208240148 Advises that changes re modified amended security plan.
Revision 2 are consistent w/provisions of 10CFR50.34(p), in
response to 820628 ltr. Safeguards info will be withheld
(ref 10CFR73.21)
STOLZ, J. Operating Reactors Branch 4. 82/08/03. HANCOCK, J. A.
Florida Power Corp. 2pp. 14529:361. 24X Fiche: 50-302.82/08/03.
8208240148

8208270700 Forwards request for addl info in response to 820506
submittal re Revision 4 to facility security plan. Response
requested within 30 days Encl withheld (ref 10CFR73.21).
STOLZ, J. Operating Reactors Branch 4. 82/08/18. HANCOCK, J. A.
Florida Power Corp. 2pp. 14683:043. 24X Fiche: 50-302.82/08/18.
8208270700.

P. Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants
for DL & holders of CP re Commission approved charter for
CROR Svc list encl
DIRCKE, W. J. Office of the Executive Director for Operations.
82/07/02. Consolidated Edison Co. of New York. 93pp. 14194:001.
24X Fiche: 50-000.82/07/02.8207080064.

8208040360 Forwards criteria contained in NUREG-0737, Item II D.3,
"Post-Accident Sampling Sys." for use in post-implementation
review. Submittal showing compliance w/criteria requested
within 20 days of receipt
STOLZ, J. F. Operating Reactors Branch 4. 82/07/12. HANCOCK, J. A.
Florida Power Corp. 10pp. 14221:348. 24X Fiche: 50-302.82/07/12.
8208040360.

8208040032 Requests schedule be provided for submittal of supplemental
ECCB calculations, which may be generic to other B&W plants &
which may employ offsetting margins.
NOVAK, T. M. Assistant Director for Operating Reactors. 82/07/13.
HANCOCK, J. A. Florida Power Corp. 4pp 14229:344. 24X
Fiche: 50-302.82/07/13.8208040032.

8208160286 Agrees to changes in dates proposed for Sections 1 & 3 per
util 820630 ltr. in response to 820408 confirmatory action
ltr. Section 2 remains unchanged.
O'REILLY, J. P. Region 2, Office of Director. 82/07/22. HANCOCK, J. A.
Florida Power Corp. 1p 14346:275. 24X Fiche: 50-302.82/07/22.
8208160286

8208040563 Requests submittal of Class III Fee for review of 820409
amend application to operate at 75% power w/four reactor
coolant pumps operating & power monitors bypassed.
MILLER, W. D. License Fee Management Branch. 82/07/29. HANCOCK, J. A.
Florida Power Corp. 1p. 14221:142. 24X Fiche: 50-302.82/07/29.
8208040563

8208030272 Informs that util will provide response to NRC 820712
request for schedule to document satisfaction of NUREG-0737,
Item II. B.3, "Post-Accident Sampling Sys." within 90 days of
Mar 1983 outage during which sys scheduled to be installed
HARDIE, D. O. Florida Power Corp. 82/07/30. STOLZ, J. F. Operating
Reactors Branch 4. 1p. 14156:178. 24X Fiche: 50-302.82/07/30.
8208030272

8208040215 BDCI ECONOMIC IMPACTS OF NUCLEAR GENERATING STATIONS: CRYSTAL
RIVER UNIT 3 CASE STUDY. Docket No. 50-302. (Florida Power
Corporation)
BERGMAN, P. A. Mountain West Research, Inc. * Social Impact
Research, Inc. FIN 8-6268. NUREG/CR-2749 V03. 82/07/31.
Division of Health, Biting & Environment. 239pp. Available at NTIS.
#7. 50. 14234:225. 24X Fiche: 50-302.82/07/31.8208040215

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP &
applicants re submittal of documents to NRC. Summarizes 10CFR
Chapter I requirements & provides alternatives to
requirements. Svc list encl.
EISENHUT, D. G. Division of Licensing. 82/08/09. Consolidated
Edison Co. of New York. 1p. 14356:332. 24X Fiche: 50-000.82/08/09.
8208090194.

8208180021 Formalizes proposals made at B&W owners group 820720 meeting
re scope of program to resolve NUREG-0737, Item II. K. 3.30,
"Revised Small Break LCCA Methods to Show Compliance W/
10CFR50, App K."
BAYNARD, P. Y. Florida Power Corp. 82/08/13. DENTON, H. R. Office of
Nuclear Reactor Regulation, Director. 12pp. 14377:175. 24X
Fiche: 50-302.82/08/13.8208180021.

DOCKETED ITEMS

8208180046 Submits addl info re NUREG-0737, Item II K.3.17 re rept on outages of ECCS. In response to NRC 820331 ltr Total outage time minimal Cumulative outage limitation for ECCS unwarranted.
HARDIS, D. O. Consumers Power Co. 82/08/13. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 1437a. 210. 24X Fiche: 50-302.82/08/13. 8208180046

8208200093 Ack receipt of 820713 ltr requesting schedule for submitting supplemental ECCS calculations similar to those discussed in Midland SEA Calculations will be submitted on or before 830214.
HARDIS, D. O. Florida Power Corp. 82/08/13. LAINAS, O. C. Assistant Director for Operating Reactors. 1p. 14393. 215. 24X Fiche: 50-302.82/08/13.8208200093

Q. Inspection reports, IE Bulletins & correspondence

8208160213 Documents 820407 verbal request for 20-day extension to allow addl time to prepare formal response to IE Insp Rept 50-302/81-15, Items A.2.A.3 & B.
HARDIS, D. O. Florida Power Corp. 82/04/14. O'REILLY, J. P. Region 2, Office of Director. 2pp. 14344. 165. 24X Fiche: 50-302.82/04/14. 8208160213

8208160468 Responds to NRC 820309 ltr re Items A.2.A.3 & B of IE Insp Rept 50-302/81-15 Emergency procedures include all reliable operator aides & safety-related monitors. Monitors do not serve mitigation function.
LUTKEHAUS, T. C. HARDIS, D. O. Florida Power Corp. 82/05/11. O'REILLY, J. P. Region 2, Office of Director. 2pp. 14348. 214. 24X Fiche: 50-302.82/05/11.8208160468

8208030531 Forwards IE Insp Rept 50-302/82-12 on 820616-18 No noncompliance noted.
LEWIS, R. C. Division of Project & Resident Programs. 82/07/14. HANCOCK, J. A. Florida Power Corp. 2pp. 14163. 013. 24X Fiche: 50-302.82/07/14.8208030531

--8208030539 IE Insp Rept 50-302/82-12 on 820616-18 No noncompliance noted. Major areas inspected action on previous insps. Followup on IE Bulletin 80-11, quality records for reactor bldg tendon & bldg dome surveillance programs.
LENAHAN, J. J., CONLON, T. E. Division of Engineering & Technical Programs. 82/07/07. 8pp. 14163. 015. 24X Fiche: 50-302.82/07/14. 8208030531.

8204210393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16. Consolidated Edison Co. of New York. 87pp. 14356. 274. 24X Fiche: 50-000.82/07/16.8204210393

8204210393 IE Info Notice 81-26, Part 3, Suppl. 1, "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19. Michigan Univ. of 112pp. 14358. 001. 24X Fiche: 50-000.82/07/19. 8204210393.

8204210396 IE Info Notice 82-25, "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20. Consolidated Edison Co. of New York. 112pp. 14381. 001. 24X Fiche: 50-000.82/07/20.8204210396.

8204210397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20. Consolidated Edison Co. of New York. 71pp. 14357. 276. 24X Fiche: 50-000.82/07/20.8204210397.

8204210398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22. Consolidated Edison Co. of New York. 112pp. 14194. 321. 24X Fiche: 50-000.82/07/22.8204210398

8204210401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 122pp. 14380. 115. 24X Fiche: 50-000.82/07/23.8204210401.

8204210402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23. Consolidated Edison Co. of New York. 127pp. 14194. 120. 24X Fiche: 50-000.82/07/23.8204210402.

8204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26. Consolidated Edison Co. of New York. 121pp. 14357. 013. 24X Fiche: 50-000.82/07/26.8204210403

8208160505 Forwards IE Insp Rept 50-302/82-13 on 820628-0702 No noncompliance noted.
DANCE, H. C. Division of Project & Resident Programs. 82/07/26. HANCOCK, J. A. Florida Power Corp. 2pp. 14348. 088. 24X Fiche: 50-302.82/07/26.8208160505

--8208160513 IE Insp Rept 50-302/82-13 on 820628-0702 No noncompliance noted. Major areas inspected. Followup on previous emergency preparedness findings.
HUFFMAN, G. N., JENKINS, G. R. Division of Emergency Preparedness & Operational Support. 82/07/23. 14pp. 14348. 090. 24X Fiche: 50-302.82/07/26.8208160505

8204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28. Consolidated Edison Co. of New York. 122pp. 14357. 146. 24X Fiche: 50-000.82/07/28.8204210405

8208160310 Ack receipt of 820625 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/82-09.
DANCE, H. C. Division of Project & Resident Programs. 82/07/30. HANCOCK, J. A. Florida Power Corp. 1p. 14345. 303. 24X Fiche: 50-302.82/07/30.8208160310

--8208160316 Responds to NRC 820528 ltr re violations noted in IE Insp Rept 50-302/82-09. Corrective actions future license amendments will be circulated among personnel. Withdrawal of violation re calibr procedure requested.
HARDIS, D. O. Florida Power Corp. 82/06/25. O'REILLY, J. P. Region 2, Office of Director. 2pp. 14345. 304. 24X Fiche: 50-302.82/07/30.8208160310

--8208160324 Forwards IE Insp Rept 50-302/82-09 on 820327-0426 & notice of violation.
LEWIS, R. C. Division of Project & Resident Programs. 82/05/28. HANCOCK, J. A. Florida Power Corp. 2pp. 14345. 306. 24X Fiche: 50-302.82/07/30.8208160310

--8208160327 Notice of violation from insp on 820327-0426
* Division of Project & Resident Programs. 82/05/28. 1p. 14345. 308. 24X Fiche: 50-302.82/07/30.8208160310.

--8208160333 IE Insp Rept 50-302/82-09 on 820327-0426. Noncompliance noted: Failure to receive prior NRC approval for Tech Spec change & failure to review & approve seismic monitoring calibr procedure prior to implementation.
BETKA, T. F., SMITH, B. W., BROWNLEE, V. L. Division of Project & Resident Programs. 82/05/17. 10pp. 14345. 309. 24X Fiche: 50-302.82/07/30.8208160310.

8208160360 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB in PWR Plants." Control rod drive mechanism found w/excessive leakage on flanges. No injection sealant matl used.
HARDIS, D. O. Florida Power Corp. 82/08/02. O'REILLY, J. P. Region 2, Office of Director. 5pp. 14349. 107. 24X Fiche: 50-302.82/08/02.8208160360.

8204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/08/05. Consolidated Edison Co. of New York. 117pp. 14388. 201. 24X Fiche: 50-000.82/08/05.8204210407.

R. Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A.
FELTON, J. M. Division of Rules and Records. 82/07/13. UDELL, R. A. Critical Mass Energy Project. 8pp. 14679. 208. 24X Fiche: 50-000.82/07/13.8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp. 14679. 216. 24X Fiche: 50-000.82/07/13.8208270010.

8208160086 Forwards monthly operating rept for Jul 1982.
HARDIS, D. O. Florida Power Corp. 82/08/09. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 1p. 14342. 021. 24X Fiche: 50-302.82/08/09.8208160086.

--8208160093 Monthly operating rept for Jul 1982
BODART, D. CULVER, M. W. Florida Power Corp 82/08/03 5pp
14342:022. 24X Fiche: 50-302, 82/08/09, 8208160086

5 Reportable occurrences, LERs & related correspondence

8208310507 Forwards LER 81-013/03L-0
MACOCK, J. A. Florida Power Corp 81/03/31 O'REILLY, J. P. Region
2, Atlanta, Office of the Director (81/03/01) 1p 14697:278 24X
Fiche: 50-302, 81/03/31, 8208310507

--8208310511 LER 81-013/03L-0 on 810302, during routine testing in Mode 5
operation, RCS discovered w/chloride concentration of
0.1B ppm Caused by release of chlorides from makeup
Procedures will be revised by 810430
KCMARRA, B. P. Florida Power Corp 81/03/31 Region 2, Atlanta,
Office of the Director (81/03/01) 2pp. 14697:279. 24X
Fiche: 50-302, 81/03/31, 8208310507

8208090133 Forwards LER 82-047/04T-0
HARDIS, D. O. Florida Power Corp 82/08/02 O'REILLY, J. P. Region 2,
Office of Director. 1p 14271:304 24X Fiche: 50-302, 82/08/02,
8208090133

--8208090136 LER 82-047/04T-0 on 820720, waste disposal tank 11B
discharged w/flow rate meter WD-101-FR inoperable. Caused by
operator error Rate meter power supply reset Procedures to
be revised
BROWN, C. O. Florida Power Corp 82/08/02 Region 2, Office of
Director. 2pp. 14271:305 24X Fiche: 50-302, 82/08/02, 8208090133

8208200095 Forwards LER 82-046/03L-0
HARDIS, D. O. Florida Power Corp 82/08/11 O'REILLY, J. P. Region 2,
Office of Director. 1p 14393:211 24X Fiche: 50-302, 82/08/11,
8208200095

--8208200100 LER 82-046/03L-0 on 820712, emergency diesel generator B
failed to start in required time Cause attributed to manual
timing techniques used for determining elapsed start time
Generator restarted
BROWN, C. O. Florida Power Corp 82/08/11 Region 2, Office of
Director. 2pp 14393:212 24X Fiche: 50-302, 82/08/11, 8208200095

8208200156 Forwards LER 82-050/01T-0 Detailed event analysis encl.
HARDIS, D. O. Florida Power Corp 82/08/13 O'REILLY, J. P. Region 2,
Office of Director. 2pp 14394:019. 24X Fiche: 50-302, 82/08/13,
8208200156

--8208200172 LER 82-050/01T-0 on 820730, util & AE determined that two
motor control ctrs for four emergency feedwater valves could
not withstand seismic event & were located in nonseismic
bldg. Caused by design inadequacy Problem under review
BROWN, C. O. Florida Power Corp 82/08/13 Region 2, Office of
Director. 1p. 14394:021. 24X Fiche: 50-302, 82/08/13, 8208200156

8208200219 Forwards LER 82-048/03L-0 Detailed event analysis encl.
HARDIS, D. O. Florida Power Corp 82/08/13 O'REILLY, J. P. Region 2,
Office of Director. 2pp 14399:342. 24X Fiche: 50-302, 82/08/13,
8208200219

--8208200229 LER 82-048/03L-0 on 820715, windspeed & temp channels for 33
& 173-Ft meteorological tower elevations failed to function
properly. Caused by lightning strike. Damaged equipment
removed, repaired & calibr.
BROWN, C. O. Florida Power Corp. 82/08/13 Region 2, Office of
Director. 1p. 14399:344 24X Fiche: 50-302, 82/08/13, 8208200219

8208270355 Forwards LER 82-049/03L-0
HARDIS, D. O. Florida Power Corp 82/08/16 O'REILLY, J. P. Region 2,
Office of Director. 1p. 14365:012 24X Fiche: 50-302, 82/08/16,
8208270355

--8208270358 LER 82-049/03L-0 on 820717, during normal plant operation,
control complex ventilation monitor, RM-A5, discovered
inoperable. Caused by failure of vacuum pump carbon impeller
vanes. Pump replaced
BROWN, C. O. Florida Power Corp 82/08/16 Region 2, Office of
Director. 2pp. 14365:013. 24X Fiche: 50-302, 82/08/16, 8208270355

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8208390231 Forwards IE Insp Repts 50-295/82-11 & 50-304/82-09 on
820310-0625 & notice of violation.
HEND, J. A. Division of Emergency Preparedness & Operational Support
82/07/22 REED, C. Commonwealth Edison Co. 2pp. 14271:105. 24X
Fiche: 50-295, 82/07/22, 8208090231

--8208090236 Notice of violation from insp on 820510-0625.
HEND, J. A. Division of Emergency Preparedness & Operational
Support 82/07/19 1p 14271:107 24X Fiche: 50-295, 82/07/22,
8208090231

--8208090241 IE Insp Repts 50-295/82-11 & 50-304/82-09 on 820510-0625.
Noncompliance noted, failure to follow & maintain emergency
response plan, to meet side of 10CFR50.47(b) & to implement
plan by 810401
JANUSKA, A. O. Division of Emergency Preparedness & Operational
Support 82/07/15 5pp. 14271:108. 24X Fiche: 50-295, 82/07/22,
8208090231

8208030186 Application to amend Licenses LPR-39 & DPR-4B, clarifying
responsibilities of licensee during emergencies to take
actions necessary to protect health & safety of public.
LENTINE, F. O. Commonwealth Edison Co. 82/07/23 DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 2pp 14160:157. 24X
Fiche: 50-295, 82/07/23, 8208030186

8208030603 Forwards final revised "Fire Protection Associated Cable
Rept Zion 1 & 2"
LENTINE, F. O. Commonwealth Edison Co 82/07/30 DENTON, H. R. Office
of Nuclear Reactor Regulation, Director 10pp 14195:031 24X
Fiche: 50-295, 82/07/30, 8208030603

--8208030621 Final revised "Fire Protection Associated Cable Rept Zion
1 & 2." W/77 oversize drawings Aperture cards are available
in PDR
* Commonwealth Edison Co. 82/07/31. 135pp. 14195:033 24X
Fiche: 50-295, 82/07/30, 8208030603

8208110254 Releases public version of revised emergency plan
implementing procedure.
FELTON, J. M. Division of Rules and Records. 82/08/05. Document
Management Branch. 1p. 14331:141 24X Fiche: 50-295, 82/08/05,
8208110254

--8208110256 Forwards public version of Revision 5 to Emergency Plan
Implementing Procedure EPIP 110-1, "Station Director."
Receipt form encl.
PLIML, G. Commonwealth Edison Co. 82/07/22. DENTON, H. R. Office
of Nuclear Reactor Regulation, Director. 1p. 14331:142. 24X
Fiche: 50-295, 82/08/05, 8208110254

--8208110261 Public version of Revision 5 to Emergency Plan Implementing
Procedure EPIP 110-1, "Station Director."
* Commonwealth Edison Co. 82/07/22 8pp. 14331:143. 24X
Fiche: 50-295, 82/08/05, 8208110254

8208110259 Releases public version of revised page to emergency plan
implementing procedure.
FELTON, J. M. Division of Rules and Records. 82/08/05. Document
Management Branch. 1p. 14332:172. 24X Fiche: 50-295, 82/08/05,
8208110259

--8208110263 Forwards public version of revised Page 8 to Revision 3 to
Emergency Plan Implementing Procedure EPIP 700-1,
"Corporate Command Ctr Group Directory." Receipt form encl.
PLIML, G. Commonwealth Edison Co. 82/07/22. DENTON, H. R. NRC - M
Detailed Affiliation Given. 1p. 14332:173 24X
Fiche: 50-295, 82/08/05, 8208110259

--8208110265 Public version of revised Page 8 to Revision 3 to Emergency
Plan Implementing Procedure EPIP 700-1, "Corporate Command
Ctr Group Directory."
* Commonwealth Edison Co. 82/07/22. 2pp. 14332:174. 24X
Fiche: 50-295, 82/08/05, 8208110259

8208180090 Forwards exemption requests from sections of post-fire
shutdown capability rept to assist in fire protection
review.
LENTINE, F. O. Commonwealth Edison Co. 82/08/10. DENTON, H. R. Office
of Nuclear Reactor Regulation, Director. 14pp. 14378:189. 24X
Fiche: 50-295, 82/08/10, 8208180090

8208250359 Releases public version of revision to "Environ Assistance
Directory for Environ Director Emergency Plan Implementing
Procedures."
FELTON, J. M. Division of Rules and Records. 82/08/12. Document
Management Branch. 1p. 14339:354. 24X Fiche: 50-000, 82/08/12,
8208250359

--8208260024 Forwards public version of Revision 2 to "Environ Assist
Directory for Environ Director Emergency Plan Implementing
Procedures."
MOORE, R. D. Commonwealth Edison Co. 82/07/19. DENTON, H. R. NRC
No Detailed Affiliation Given. 1p. 14359:355. 24X
Fiche: 50-000, 82/08/12, 8208250359

--B208260047 Public version of Revision 2 to "Environ Assistance Directory for Environ Director Emergency Plan Implementing Procedures"
* Commonwealth Edison Co 82/06/30. 7pp 14599 356 24X
Fiche: 50-000, 82/08/12, 8208260059

P. Operating license stage documents & correspondence

8208110098 "Simulation of Zion Unit 2 Cycle-1 Operation." Interim rept KOHUT, P., CDKINDS, D., CAREW, J. Brookhaven National Laboratory FIN A-3374 8208110098 82/04/30 DUNFELD, M. Division of Systems Integration (post B11005) 80pp 14339 198 24X
Fiche: 50-304, 82/04/30, 8208110098

8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CRGR, Svc list encl.
DIRCKB, W. J. Office of the Executive Director for Operations. 82/07/02. Consolidated Edison Co of New York 93pp, 14194.001 24X Fiche: 50-000, 82/07/02, 8207080064

8208040580 Forwards revised criteria to be used to review submittal on TMI Action Item II.B.3. "Post-Accident Sampling Sys." Schedule for responding to info requested in 20 days of ltr receipt.
NEIGHBOR, J. D. Operating Reactors Branch 1 82/07/22.
DELGEORGE, L. O. Commonwealth Edison Co. 10pp 14228.225 24X
Fiche: 50-295, 82/07/22, 8208040580

8208030186 Application to amend Licenses DPR-39 & DPR-48, clarifying responsibilities of licensee during emergencies to take actions necessary to protect health & safety of public.
LENTINE, F. O. Commonwealth Edison Co 82/07/23 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp 14160.197. 24X
Fiche: 50-295, 82/07/23, 8208030186

8208090103 Provides actions to be taken re startup of units w/equipment required by out of svc Tech Specs & interpretation of phrase "recovery from inadvertent trip." discussed during 820721 meeting.
LENTINE, F. O. Commonwealth Edison Co 82/07/23. KEPPLER, J. O. Region 3, Office of Director. 2pp 14249.273. 24X
Fiche: 50-295, 82/07/23, 8208090103

8208030239 Application to amend Licenses DPR-39 & DPR-48, adding Tech Spec on sealed source contamination
LENTINE, F. O. Commonwealth Edison Co 82/07/29 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p 14158.219. 24X
Fiche: 50-295, 82/07/29, 8208030239

--8208030245 Proposed Tech Spec Pages 295AD, 295AE & 295AF re sealed source contamination
* Commonwealth Edison Co 82/07/29 4pp 14158.220 24X
Fiche: 50-295, 82/07/29, 8208030239

8208130018 Application to amend Licenses DPR-39 & DPR-48, changing frequency at which reactor protection & engineered safeguard instrumentation must be functionally tested.
LENTINE, F. O. Commonwealth Edison Co 82/08/05. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp. 14335.082 24X
Fiche: 50-295, 82/08/05, 8208130018

--8208130023 Proposed Tech Spec Tables 3.1 2.4.1-1 & 3.4-2 re functional testing of reactor protection & engineered safety instrumentation
* Commonwealth Edison Co 82/08/05 7pp 14335.086. 24X
Fiche: 50-295, 82/08/05, 8208130018

8208130186 Application to amend to Licenses DPR-39 & DPR-48, changing Tech Spec 3.2.3 re control rod sys operability.
LENTINE, F. O. Commonwealth Edison Co. 82/08/05. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 14339.015. 24X
Fiche: 50-295, 82/08/05, 8208130186

--8208130172 Proposed changes to Tech Spec 3.2.3 re control rod sys operability.
* Commonwealth Edison Co 82/08/05 4pp. 14339.017. 24X
Fiche: 50-295, 82/08/05, 8208130186

8208110188 Forwards revised pages to CE-1-A. "Comm Ed QA Program for Nuclear Generating Stations." Revision 21. Revised pages correct typographical & other minor errors.
SWARTZ, E. Commonwealth Edison Co. 82/08/06 HAASE, W. P. Quality Assurance Branch. 1p 14314.079. 24X Fiche: 50-000, 82/08/06, 8208110188

--8208110204 Revised pages to CE-1-A, Revision 21. "Comm Ed QA Program for Nuclear Generating Stations."
* Commonwealth Edison Co. 82/08/06. 11pp. 14314.080 24X
Fiche: 50-000, 82/08/06, 8208110188

8208090194 Generic ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summaries 10CFR Chapter I requirements & provides alternatives to requirements Svc list encl
EISENHUT, D. O. Division of Licensing 82/08/09. Consolidated Edison Co of New York 1p 14356.332 24X Fiche: 50-000, 82/08/09, 8208090194

8208230137 Forwards addl info re diesel generator outages for 1976-81, per Franklin Research Ctr 820628 request & NUREO-0737, Item II K 3 17, "ECCB Outage Rept"
LENTINE, F. O. Commonwealth Edison Co 82/08/16 EISENHUT, D. O. Division of Licensing 21pp. 14541.309 24X Fiche: 50-295, 82/08/16, 8208230137

8208240305 Submits updated schedule for submittal of addl info re containment purge valve operability. Program scheduled for Fall 1982 completion Summary of stress values calculated by hand encl
LENTINE, F. O. Commonwealth Edison Co 82/08/19 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp 14527.197. 24X
Fiche: 50-295, 82/08/19, 8208240305

Q. Inspection reports, IE Bulletins & correspondence

8208050414 Forwards IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 on 810813-820503. No noncompliance noted.
KEPPLER, J. O. Region 3, Office of Director 82/07/12 REED, C. Commonwealth Edison Co 1p 14217.166. 24X Fiche: 50-000, 82/07/12, 8208050414

--8208050441 IE Insp Repts 50-237/81-39, 50-249/81-32, 50-254/81-23, 50-265/81-23, 50-295/81-31 & 50-304/81-29 on 810813-820503. No noncompliance noted Major areas inspected allegations re Comm Ed operation of facilities & compliance w/10CFR21
HAYEB, D. W., CHRIBSOTIMOS, N., KOHLER, J. Division of Project & Resident Programs 82/07/09 155pp 14217.169 24X
Fiche: 50-000, 82/07/12, 8208050414

8204210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16 Consolidated Edison Co. of New York 87pp 14356.274 24X
Fiche: 50-000, 82/07/16, 8204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation" Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19 Michigan Univ. of 112pp 14358.001 24X Fiche: 50-000, 82/07/19, 8204210395

8204210396 IE Info Notice 82-25. "Failures of Hiller Actuators Upon Gradual Loss of Air Pressure." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20 Consolidated Edison Co. of New York. 112pp. 14381.001. 24X
Fiche: 50-000, 82/07/20, 8204210396

8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks." Svc list encl
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards 82/07/20. Consolidated Edison Co. of New York. 71pp 14337.276 24X Fiche: 50-000, 82/07/20, 8204210397

8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22 Consolidated Edison Co. of New York. 112pp 14194.321. 24X
Fiche: 50-000, 82/07/22, 8204210398

8208090231 Forwards IE Insp Repts 50-295/82-11 & 50-304/82-09 on 820510-0625 & notice of violation.
HIND, J. A. Division of Emergency Preparedness & Operational Support. 82/07/22. REED, C. Commonwealth Edison Co. 2pp. 14271.103. 24X
Fiche: 50-295, 82/07/22, 8208090231

--8208090236 Notice of violation from insp on 820510-0625.
HIND, J. A. Division of Emergency Preparedness & Operational Support. 82/07/19. 1p. 14271.107. 24X Fiche: 50-295, 82/07/22, 8208090231

--8208090241 IE Insp Repts 50-295/82-11 & 50-304/82-09 on 820510-0625 Noncompliance noted: failure to follow & maintain emergency response plan to meet stds of 10CFR50.47(b) & to implement plan by 810401
JANUSKA, A. G., AXELSON, W. L. Division of Emergency Preparedness & Operational Support. 82/07/19. 5pp. 14271.108. 24X
Fiche: 50-295, 82/07/22, 8208090231

DOCKETED ITEMS

8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Drilling in Vicinity of Drained & Open RCS." Svc list encl
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York 122pp 14380-119. 24X
Fiche: 50-000, 82/07/23, 8204210401

8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23
Consolidated Edison Co. of New York 127pp. 14194-120. 24X
Fiche: 50-000, 82/07/23, 8204210402

8204210403 IE Info Notice 82-30. "Loss of Thermal Bleeders in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/26.
Consolidated Edison Co. of New York 121pp. 14357-013. 24X
Fiche: 50-000, 82/07/26, 8204210403

8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/28
Consolidated Edison Co. of New York. 122pp. 14357-146. 24X
Fiche: 50-000, 82/07/28, 8204210405

8208060490 Forwards response to IE Bulletin 82-02 re bolted connections. Visual or surface exams not typically performed on bolting in RCS unless requested. No trend of leakage recurrence detected.
SWARTZ, E.D. Commonwealth Edison Co. 82/07/29. KEPPLER, J.Q. Region 3, Office of Director 14pp 14214-109. 24X Fiche: 50-295, 82/07/29, 8208060490

8204210407 IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Baffle Water-Jet Impingement." Svc list encl
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/08/05.
Consolidated Edison Co. of New York. 117pp 14388-201. 24X
Fiche: 50-000, 82/08/05, 8204210407

R. Periodic operating reports & related correspondence

8208270010 Responds to FOIA request for documents detailing collective dose exposures in 1981 for operating nuclear power plants & analyzing said info. Forwards documents listed in App A
FELTON, J.M. Division of Rules and Records. 82/07/13. UDELL, R.A. Critical Mass Energy Project. 8pp. 14679-208. 24X
Fiche: 50-000, 82/07/13, 8208270010

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power Facilities for CY81."
* NRC - No Detailed Affiliation Given. 82/07/13. 48pp.
14679-216. 24X Fiche: 50-000, 82/07/13, 8208270010

--8208270359 Forwards "Recorded Annual Whole Body External Exposure for CY81." per 10CFR20 407(b). W/o Quad Cities, Zion, LaSalle, Byron & Braidwood repts.
RAUSCH, T.J. Commonwealth Edison Co. 82/03/31. Office of Management and Program Analysis. 1p. 14680-075. 24X
Fiche: 50-000, 82/07/13, 8208270010

8208130103 Forwards monthly operating repts for Jul 1982
GRAEBER, K.L. Commonwealth Edison Co. 82/08/06. Director's Office, Office of Inspection and Enforcement. 1p. 14333-340. 24X
Fiche: 50-295, 82/08/06, 8208130103

--8208130106 Monthly operating repts for Jul 1982
COOK, J.C. Commonwealth Edison Co. 82/08/06. 11pp. 14333-341. 24X
Fiche: 50-295, 82/08/06, 8208130103

S. Reportable occurrences, LERs & related correspondence

8208130225 Forwards LER 82-017/03L-0
GRAEBER, K.L. Commonwealth Edison Co. 82/08/06. KEPPLER, J.Q. Region 3, Office of Director. 1p. 14333-180. 24X
Fiche: 50-304, 82/08/06, 8208130225

--8208130231 LER 82-017/03L-0 on 820708, during hot shutdown & after taking MSIV 28 out of sequence, MSIV drifted open & was rendered inoperable. Caused by failure to open drain valve. Signs reminding operators to verify drain position posted.
MARSH, R.L. Commonwealth Edison Co. 82/08/06. Region 3, Office of Director. 1p. 14333-181. 24X Fiche: 50-304, 82/08/06, 8208130225

DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

F. Security, medical, emergency & fire protection plans

8208020190 Releases public version of revised radiological emergency response plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 82/07/13. Document Management Branch. 1p. 14179-057. 24X Fiche: 50-305, 82/07/13, 8208020190

--8208020191 Forwards public version of revised radiological emergency response plan implementing procedures, including Procedures EP-AD-17 re communications & EP-RET-3C re post-accident operation of high radiation sample room.
QIESLER, C.W. Wisconsin Public Service Corp. 82/06/30.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 14179-058. 24X Fiche: 50-305, 82/07/13, 8208020190

--8208020192 Public version of revised radiological emergency response plan implementing procedures, including Procedures EP-AD-17 re communications & EP-RET-3C re post-accident operation of high radiation sample room.
QIESLER, C.W. Wisconsin Public Service Corp. 82/06/18. 100pp. 14179-060. 24X Fiche: 50-305, 82/07/13, 8208020190

8208060322 Releases public version of revised radiological emergency response plan implementing procedures.
FELTON, J.M. Division of Rules and Records. 82/08/02. Document Management Branch. 1p. 14281-131. 24X Fiche: 50-305, 82/08/02, 8208060322

--8208060324 Forwards public version of revised radiological emergency response plan implementing procedures, including Revision E to Procedure EP-ENV-3A, "Environ Protection Director Actions & Directives."
QIESLER, C.W. Wisconsin Public Service Corp. 82/07/26.
DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 1p. 14281-152. 24X Fiche: 50-305, 82/08/02, 8208060322

--8208060328 Public version of revised radiological emergency response plan implementing procedures, including Revision E to Procedure EP-ENV-3A, "Environ Protection Director Actions & Directives." Revised index encl.
LANGE, R.H. Wisconsin Public Service Corp. 82/07/02. 59pp. 14281-153. 24X Fiche: 50-305, 82/08/02, 8208060322

8208090253 Summarizes info presented at 820423 meeting re request that shutdown sys be considered dedicated rather than alternate.
Schedule & scope of work encl.
QIESLER, C.W. Wisconsin Public Service Corp. 82/08/04. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 29pp. 14272-020. 24X Fiche: 50-305, 82/08/04, 8208090253

8208310422 Forwards IE Safeguards Insp Rept 50-305/82-15 on 820810-13 & notice of violation.
MILLER, J.R. Division of Engineering & Technical Programs. 82/08/24.
QIESLER, C.W. Wisconsin Public Service Corp. 2pp. 14692-062. 24X Fiche: 50-305, 82/08/24, 8208310422

--8208310424 Notice of violation from insp on 820813-15.
MILLER, J.R. Division of Engineering & Technical Programs. 82/08/24. 1p. 14692-064. 24X Fiche: 50-305, 82/08/24, 8208310422

--8208310431 IE Safeguards Insp Rept 50-305/82-15 on 820813-15. Noncompliance noted: failure to comply w/reporting requirements for receipt & shipment of BNH reported on Forms NRC-741. Details withheld (ref 10CFR2.790).
FINLEY, A.O., CREED, J.R. Region 3, Office of Director. 82/08/24. 1p. 14692-066. 24X Fiche: 50-305, 82/08/24, 8208310422

8208310305 Responds to NRC 820729 request for info on diesel generator outages per TMI Action Plan Item II.K.3.17, "Rept on Outages of ECCB." Info previously submitted in 811125 response to Unresolved Safety Issue A-44, "Station Blackout."
QIESLER, C.W. Wisconsin Public Service Corp. 82/08/27. VAROA, B.A. Operating Reactors Branch 1. 1p. 14687-355. 24X
Fiche: 50-305, 82/08/27, 8208310305

K. Utility Final Safety Analysis Report (FSAR) & amends

8208240181 Forwards Figure 10-2-2 entitled "Flow Diagram-Condensate & Gland Seal Sys." inadvertently omitted from updated FSAR.
QIESLER, C.W. Wisconsin Public Service Corp. 82/08/20. VAROA, B.A. Operating Reactors Branch 1. 3pp. 14527-079. 24X
Fiche: 50-305, 82/08/20, 8208240181

P. Operating license stage documents & correspondence

8207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR Svc list encl
DIRCKS, W. J. Office of the Executive Director for Operations
82/07/02 Consolidated Edison Co. of New York 93pp 14194 001
24X Fiche: 50-000, 82/07/02, 8207080064.

8208030513 Forwards Revision 2 to "Reactor Test Program, Kewaunee Nuclear Power Plant."
QIESLER, C. W. Wisconsin Public Service Corp. 82/07/22 VARQA, B. A.
Operating Reactors Branch 1 2pp 14163 253 24X
Fiche: 50-305, 82/07/22, 8208030513

--8208030517 Revision 2 to "Reactor Test Program, Kewaunee Nuclear Power Plant."
* Wisconsin Public Service Corp. 82/07/22 30pp 14163 255
24X Fiche: 50-305, 82/07/22, 8208030513.

8208110095 Forwards Franklin Research Ctr request for addl info re TMI Action Plan Item 11 K 3 17. "Rept on Outages of ECCB" Responses requested within 30 days of ltr receipt.
VARQA, B. A. Operating Reactors Branch 1. 82/07/29. QIESLER, C. W.
Wisconsin Public Service Corp. 3pp. 14331.062 24X
Fiche: 50-305, 82/07/27, 8208110095

8208030396 Revises commitment date to develop procedures utilizing containment high-range radiation monitors for emergency class determination per TMI Action Item 11. F. 1. Emergency plan implementing procedures to be revised 821031
QIESLER, C. W. Wisconsin Public Service Corp. 82/07/30.
EISENHUT, D. Q. Division of Licensing. 1p 14154 007. 24X
Fiche: 50-305, 82/07/30, 8208030396

8208050276 Forwards response to request for addl info re environ qualification of safety-related electrical equipment Listing of design change requests in response to NUREG-0737.
"Clarification of TMI Action Plan Items" encl
QIESLER, C. W. Wisconsin Public Service Corp. 82/08/02. VARQA, B. A.
Operating Reactors Branch 1 50pp 14209 212 24X
Fiche: 50-305, 82/08/02, 8208050276

8208100178 Forwards revised Table 1, "Acceptance & Review Criteria for Reactor Tests," to "Reactor Test Program, Kewaunee Nuclear Power Plant," Revision 2, submitted on 820722.
QIESLER, C. W. Wisconsin Public Service Corp. 82/08/06 VARQA, B. A.
Operating Reactors Branch 1 1p 14298 221 24X
Fiche: 50-305, 82/08/06, 8208100178

--8208100181 Revised Table 1, "Acceptance & Review Criteria for Reactor Tests," to "Reactor Test Program, Kewaunee Nuclear Power Plant," Revision 2, submitted on 820722
* Wisconsin Public Service Corp. 82/08/06 1p. 14298 222 24X
Fiche: 50-305, 82/08/06, 8208100178

8208090194 Generic Ltr 82-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC. Summarizes 10CFR Chapter 1 requirements & provides alternatives to requirements. Svc list encl.
EISENHUT, D. Q. Division of Licensing. 82/08/09. Consolidated Edison Co. of New York. 1p 14356 332 24X Fiche: 50-000, 82/08/09, 8208090194

8208130137 Requests extension to 820115 for submittal of proposed amends to radiological effluent Tech Spec. per NRC 820713 request.
QIESLER, C. W. Wisconsin Public Service Corp. 82/08/09 VARQA, B. A.
Operating Reactors Branch 1. 1p 14335.328 24X
Fiche: 50-305, 82/08/09, 8208130137

8208240250 Application for Amend 49 to License DPR-43, proposing Tech Spec changes including rearrangement of table of contents, correction of typographical errors & other administrative changes. Class II amend fee encl.
QIESLER, C. W. Wisconsin Public Service Corp. 82/08/18
EISENHUT, D. Q. Division of Licensing. 6pp 14521.063 24X
Fiche: 50-305, 82/08/18, 8208240250

--8208240253 Proposed Tech Specs, rearranging table of contents & correcting typographical errors & other administrative changes.
* Wisconsin Public Service Corp. 82/08/18 33pp. 14521.071.
24X Fiche: 50-305, 82/08/18, 8208240250.

8208310205 Requests until 770104 proposed Amend 23 be disregarded. New amend request on App J will be submitted by 821101. New amend proposal preferable to updating proposed Amend 23.
QIESLER, C. W. Wisconsin Public Service Corp. 82/08/27. VARQA, B. A.
Operating Reactors Branch 1 1p 14693.126 24X
Fiche: 50-305, 82/08/27, 8208310205.

8208310305 Responds to ARC 820729 request for info on diesel generator outages per TMI Action Plan Item 11 K 3 17. "Rept on Outages of ECCB" Info previously submitted in 811125 response to Unresolved Safety Issue A-44. "Station Blackout"
QIESLER, C. W. Wisconsin Public Service Corp. 82/08/27 VARQA, B. A.
Operating Reactors Branch 1 1p 14687 359 24X
Fiche: 50-305, 82/08/27, 8208310305

Q. Inspection reports, IE Bulletins & correspondence

8208040026 Forwards request for addl info to complete review of 820507 ltr re IE Bulletin 80-04. "Analysis of PWR Main Steam Line Break 4/Continued Feedwater Addition"
VARQA, B. A. Operating Reactors Branch 1 82/07/15 QIESLER, C. W.
Wisconsin Public Service Corp. 4pp 14233 357. 24X
Fiche: 50-305, 82/07/15, 8208040026

8204210393 IE Info Notice 82-23. "Main Steam Isolation Valve (MSIV) Leakage." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/16
Consolidated Edison Co. of New York 87pp. 14356 274 24X
Fiche: 50-000, 82/07/16, 8204210393

8204210395 IE Info Notice 81-26, Part 3, Suppl 1. "Clarification of Placement of Personnel Monitoring Devices for External Radiation." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/19.
Michigan, Univ. of 112pp 14358 001. 24X Fiche: 50-000, 82/07/19, 8204210395

8204210396 IE Info Notice 82-25. "Failures of Miller Actuators Upon Gradual Loss of Air Pressure." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/20
Consolidated Edison Co. of New York 112pp. 14381 001 24X
Fiche: 50-000, 82/07/20, 8204210396

8204210397 IE Info Notice 82-24. "Water Leaking From U Hexafluoride Overpacks." Svc list encl.
COBB, L. I. Division of Fuel Facilities, Materials & Safeguards. 82/07/20
Consolidated Edison Co. of New York 71pp. 14357 276
24X Fiche: 50-000, 82/07/20, 8204210397

8204210398 IE Info Notice 82-26. "RCIC & HPCI Turbine Exhaust Check Valve Failures." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/22
Consolidated Edison Co. of New York 112pp 14194 321 24X
Fiche: 50-000, 82/07/22, 8204210398

8204210401 IE Info Notice 82-28. "Hydrogen Explosion While Grinding in Vicinity of Drained & Open RCB." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23
Consolidated Edison Co. of New York 122pp 14380 115 24X
Fiche: 50-000, 82/07/23, 8204210401

8204210402 IE Info Notice 82-29. "Control Rod Drive (CRD) Guide Tube Support Pin Failures at Westinghouse PWRs." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/23
Consolidated Edison Co. of New York 127pp 14194 120 24X
Fiche: 50-000, 82/07/23, 8204210402

8204210403 IE Info Notice 82-30. "Loss of Thermal Sleeves in RCS Piping at Certain Westinghouse PWR Power Plants." Svc list encl.
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/26
Consolidated Edison Co. of New York 121pp. 14357 013 24X
Fiche: 50-000, 82/07/26, 8204210403

8204210405 IE Info Notice 82-31. "Overexposure of Diver During Work in Fuel Storage Pool." Svc list encl
JORDAN, E. L. Division of Engineering & Quality Assurance. 82/07/28.
Consolidated Edison Co. of New York 122pp. 14357 146 24X
Fiche: 50-000, 82/07/28, 8204210405

8208100159 Submits response to Item 5 of IE Bulletin 82-02. "Degradation of Threaded Fasteners in RCPB of PWR Plants." Boric acid leakage found on bonnet studs of RCPB valves.
QIESLER, C. W. Wisconsin Public Service Corp. 82/08/02 KEPLER, J. O.
Region 3, Office of Director 3pp 14298 036 24X
Fiche: 50-305, 82/08/02, 8208100159

8208230088 Forwards IE Insp Rept 50-305/82-10 on 820601-30 & notice of violation.
SPESBARD, R. L. Division of Project & Resident Programs. 82/08/02
QIESLER, C. W. Wisconsin Public Service Corp. 2pp. 14317 322 24X
Fiche: 50-305, 82/08/02, 8208230088

--8208230092 Notice of violation from insp on 820601-30
SPESBARD, R. L. Division of Project & Resident Programs. 82/08/02.
1p. 14317 324. 24X Fiche: 50-305, 82/08/02, 8208230088.

00 IE Insp Rept 90-309/82-10 on 820601-30. Noncompliance noted re to conduct maint activities of safety-related studies & components per approved procedures. 82/08/05. L. KONKLIN, J. E. Division of Project & Resident Programs 14317-325 24X Fiche: 50-305.82/08/02.8208230088

IE Info Notice 82-27. "Fuel Rod Degradation Resulting From Water-Jet Impingement" Svc list encl. Division of Engineering & Quality Assurance 82/08/05. 14317-325 24X Fiche: 50-305.82/08/02.8208230088

Forwards IE Safeguards Insp Rept 90-305/82-15 on 820810-13 of violation Division of Engineering & Technical Programs 82/08/24. C.W. Wisconsin Public Service Corp. 2pp. 14692-062. 24X Fiche: 50-305.82/08/24.8208310422

Notice of violation from Insp on 820813-15. Division of Engineering & Technical Programs. 1p. 14692-064 24X Fiche: 50-305.82/08/24.8208310422

IE Safeguards Insp Rept 90-305/82-15 on 820813-15. Compliance noted: Failure to comply w/reporting events for receipt & shipment of BNM reported on Forms (Details withheld (ref 10CFR2.790)). A.O. CREED, J.R. Region 3, Office of Director. 82/08/24. 14692-063. 24X Fiche: 50-305.82/08/24.8208310422

Operating reports & related correspondence

Forwards monthly operating rept for June 1982 C.W. Wisconsin Public Service Corp. 82/07/12. Office of Engineering and Program Analysis 1p. 14326-139. 24X Fiche: 50-305.82/07/12.8208120213

Monthly operating rept for June 1982. C.W. Wisconsin Public Service Corp. 82/07/01. 4pp. 14326-139. 24X Fiche: 50-305.82/07/12.8208120213

Responds to FOIA request for documents detailing collective doses in 1981 for operating nuclear power plants & related info. Forwards documents listed in App A. M. Division of Rules and Records. 82/07/13. UDELL, R.A. Mass Energy Project. 8pp. 14677-208. 24X Fiche: 50-305.82/07/13.8208270010

"Annual Whole Body Dose At Licensed Nuclear Power Plants for CY81." No Detailed Affiliation Given 82/07/13. 48pp. 14677-208. 24X Fiche: 50-305.82/07/13.8208270010

Occurrences, LERs & related correspondence

Forwards LER 82-019/03L-0. C.W. Wisconsin Public Service Corp. 82/07/28. KEPPNER, J.O. Office of Director. 1p. 14213-278. 24X Fiche: 50-305.82/07/28.8208050486

LER 82-019/03L-0 on 820628, 1B shield bldg ventilation fan found out of svc. Caused by shutdown due to neck because of repeated trips of circuit breaker extended fan runs. Loose contactor block replaced. T.B.L. Wisconsin Public Service Corp. 82/07/28. Region 3, Office of Director. 1p. 14213-279. 24X Fiche: 50-305.82/07/28.8208050486

Forwards LER 82-020/03L-0. C.W. Wisconsin Public Service Corp. 82/07/30. KEPPNER, J.O. Office of Director. 1p. 14270-360. 24X Fiche: 50-305.82/07/30.8208090209

LER 82-020/03L-0 on 820702, while performing control rod deviation monitor failed to operate. Caused by positions not updated on process computer following computer failure. Procedure updated. T.B.L. Wisconsin Public Service Corp. 82/07/30. Region 3, Office of Director. 1p. 14270-361. 24X Fiche: 50-305.82/07/30.8208090209

Forwards updated LER 82-009/03X-1. C.W. Wisconsin Public Service Corp. 82/08/05. KEPPNER, J.O. Office of Director. 1p. 14337-149. 24X Fiche: 50-305.82/08/05.8208130223

8208130243 Updated LER 82-009/03X-1 on 820410, while in hot shutdown prior to scheduled refueling outage, both source range nuclear instruments determined inoperable. Caused by water accumulation in instrument canisters. HOLZAHN, D.J. Wisconsin Public Service Corp. 82/08/05. Region 3, Office of Director. 1p. 14337-150. 24X Fiche: 50-305.82/08/05.8208130223

8208130093 Forwards LERs 82-021/01T-0 & 82-022/01T-0. OIESLER, C.W. Wisconsin Public Service Corp. 82/08/06. KEPPNER, J.O. Region 3, Office of Director. 1p. 14336-013. 24X Fiche: 50-305.82/08/06.8208130093

8208130098 LER 82-021/01T-0 on 820723, while performing test on containment fan coil units & associated duct work, measured flows found low. Caused by fan interactions between two fans feeding common containment ring - header duct work. HOLZAHN, D.J., SCHROCK, C.A. Wisconsin Public Service Corp. 82/08/06. Region 3, Office of Director. 2pp. 14336-014. 24X Fiche: 50-305.82/08/06.8208130093

8208130102 LER 82-022/01T-0 on 820727, containment fan coil unit 1A failed to restart during test of sys heat removal & flow capabilities. Caused by high instantaneous current due to fan having to overcome back pressure from sys breaker reset. BERNHOFT, B.L., SHOKER, C.S. Wisconsin Public Service Corp. 82/08/10. Region 3, Office of Director. 1p. 14336-016. 24X Fiche: 50-305.82/08/06.8208130093

8208170078 Forwards LER 82-023/03L-0. OIESLER, C.W. Wisconsin Public Service Corp. 82/08/10. KEPPNER, J.O. Region 3, Office of Director. 1p. 14338-133. 24X Fiche: 50-305.82/08/10.8208170078

8208170081 LER 82-023/03L-0 on 820711, 1A diesel generator declared out of svc due to generator startup air compressor not maintaining proper pressure. Caused by suction valve on secondary stage having cracked leaf valves replaced. BERNHOFT, B.L. Wisconsin Public Service Corp. 82/08/10. Region 3, Office of Director. 1p. 14338-134. 24X Fiche: 50-305.82/08/10.8208170078

8208230142 Forwards updated LER 82-002/03X-1 & LERs 82-024/03L-0 & 82-025/03L-0. OIESLER, C.W. Wisconsin Public Service Corp. 82/08/13. KEPPNER, J.O. Region 3, Office of Director. 1p. 14314-304. 24X Fiche: 50-305.82/08/13.8208230142

8208230153 Updated LER 82-002/03X-1 on 820114, during normal operation, pressurizer level transmitter LT427 found out of spec. Caused by instrument drift. Transmitter recalibrated. Barton transmitters will be changed as part of long-term upgrade. SHOKER, C.B. Wisconsin Public Service Corp. 82/08/13. Region 3, Office of Director. 1p. 14314-305. 24X Fiche: 50-305.82/08/13.8208230142

8208230161 LER 82-024/03L-0 on 820716, while at full power, overpower delta T channel 3 rod stop alarm observed cycling in & out. Caused by malfunction of TAVO signal conditioner causing channel to drift. Spare signal box installed & calibrated. BERNHOFT, B.L. Wisconsin Public Service Corp. 82/08/13. Region 3, Office of Director. 1p. 14314-306. 24X Fiche: 50-305.82/08/13.8208230142

8208230172 LER 82-025/03L-0 on 820716, during document review, waste disposal liquid effluent monitor found indicating low. Caused by weak detection tube on monitor. Tube replaced & detector recalibrated. BERNHOFT, B.L. Wisconsin Public Service Corp. 82/08/13. Region 3, Office of Director. 1p. 14314-307. 24X Fiche: 50-305.82/08/13.8208230142

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

F. Security, medical, emergency & fire protection plans

8208030038 Releases public version of revised emergency plan implementing procedures. FELTON, J.H. Division of Rules and Records. 82/07/19. Document Management Branch. 1p. 14182-219. 24X Fiche: 50-282.82/07/19.8208030038

8208030090 Forwards public version of revised emergency plan implementing procedures, including Procedures F3-14.2 re operations emergency surveys & F3-8 re recommendations for offsite protective actions. HUBBARD, D.M. Northern States Power Co. 82/07/07. Region 3, Office of Director. 1p. 14182-220. 24X Fiche: 50-282.82/07/19.8208030038

--B208030091 Public version of revised emergency plan implementing procedures, including Procedures F3-14 2 re operations emergency surveys & F3-B re recommendations for offsite protective actions
SCHULKE, D A Northern States Power Co 82/07/01 175pp
14182 221 24X Fiche 50-282, 82/07/19, B208030038

B208170399 Advises that exemption from fire protection scheduler requirements of 10CFR50.48(c) re emergency lighting cannot be granted based on B20520 request alone. Complete chronology of Section III J implementation efforts requested
CLARK, R A Operating Reactors Branch 3 82/07/29 MUSOLF, D M Northern States Power Co 4pp 14372 349 24X
Fiche: 50-282, 82/07/29, B208170399

B208260089 Releases public version of revised corporate emergency plan
FELTON, J M Division of Rules and Records 82/08/13 Document Management Branch 1p 14576 196 24X Fiche 50-000, 82/08/13, B208260089

--B208260315 Forwards public version of Revision 5 to corporate nuclear emergency plan. Updated info on App C items identified in NRC B20504 ltr encl
LARSON, C E Northern States Power Co 82/08/02 Region 3, Office of Director 4pp 14576 199 24X Fiche 50-000, 82/08/13, B208260089

--B208260319 Public version of Revision 5 to corporate nuclear emergency plan
HUDSON, O WARD, E LARSON, C E Northern States Power Co 82/08/02 140pp 14576 203 24X Fiche 50-000, 82/08/13, B208260089

B208260353 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 82/08/13 Document Management Branch 1p 14576 069 24X Fiche 50-000, 82/08/13, B208260353

--B208260358 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1 2 re notifications & EPIP 1.1 5 re startup & operation of emergency operations facility.
WARD, E C Northern States Power Co 82/08/11 Region 3, Office of Director 1p 14575 072 24X Fiche 50-000, 82/08/13, B208260353

--B208260360 Public version of revised emergency plan implementing procedures, including Procedures EPIP 1.1 2 re notifications & EPIP 1.1 5 re startup & operation of emergency operations facility
Northern States Power Co 82/08/11 72pp 14575 073 24X Fiche 50-000, 82/08/13, B208260353

B208300326 Provides addl info in support of util B20520 request for relief from schedule for completion of 10CFR50, App R, Section III J re emergency lighting mods. Mods will be implemented by B20101
MUSOLF, D Northern States Power Co 82/08/23 Office of Nuclear Reactor Regulation, Director, EPP 14599 086 24X
Fiche 50-282, 82/08/23, B208300326

P. Operating license stage documents & correspondence

B207080064 Generic ltr to all licensees of operating plants, applicants for DL & holders of CP re Commission approved charter for CROR Svc list encl
DIRCKS, W J Office of the Executive Director for Operations 82/07/02 Consolidated Edison Co of New York 93pp 14194 001 24X Fiche 50-000, 82/07/02, B207080064

B208020446 Provides results of post-implementation review of shift technical advisor training program. Program meets intent of NUREG-0737, Item II A 1.1 In future, all new hires into program should have bachelor degree or equivalent
CLARK, R A Operating Reactors Branch 3 82/07/06 MUSOLF, D M Northern States Power Co 3pp 14181 045 24X
Fiche: 50-282, 82/07/06, B208020446

B208020051 Forwards Amends 56 & 50 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability. Amend increases peak burnup limit
DIIANNI, D C Operating Reactors Branch 3 82/07/16 MUSOLF, D M Northern States Power Co 3pp 14181 007 24X
Fiche: 50-282, 82/07/16, B208020051

--B208020054 Amends 56 & 50 to Licenses DPR-42 & DPR-60, respectively, revising App A Tech Spec peak burnup limit from 41,850 to 47,000 MWD/MTU
CLARK, R A Operating Reactors Branch 3 82/07/16 6pp 14181 010 24X Fiche 50-282, 82/07/16, B208020051

--B208020056 Safety evaluation supporting Amends 56 & 50 to Licenses DPR-42 & DPR-60, respectively
Office of Nuclear Reactor Regulation, Director 82/07/16 3pp 14181 016 24X Fiche 50-282, 82/07/16, B208020051

--B208020062 Notice of issuance & availability of Amends 56 & 50 to Licenses DPR-42 & DPR-60, respectively
CLARK, R A Operating Reactors Branch 3 82/07/16 2pp 14181 021 24X Fiche 50-282, 82/07/16, B208020051

B208040642 Advises that plant operation in Cycle 7 acceptable w/thermal margins for core loadings containing mixture of TOPROD & Exxon std fuel assemblies
CLARK, R A Operating Reactors Branch 3 82/07/22 MUSOLF, D M Northern States Power Co 2pp 14224 023 24X
Fiche 50-282, 82/07/22, B208040642

B208030228 Advises that Tech Spec change request re NUREG-0737, Items II E 1.1 & II E 1.2 concerning auxiliary feedwater sys will be submitted by B20915 Delay due to organizational changes, workload & Unit 2 outage
MUSOLF, D Northern States Power Co 82/07/28 Office of Nuclear Reactor Regulation, Director 1p 14158 203 24X
Fiche 50-282, 82/07/28, B208030228

B208110088 Forwards request for addl info re pressure & temp profiles outside containment as part of equipment environ qualification review to perform calculations for pipe breaks outside containment info requested within 30 days
CLARK, R A Operating Reactors Branch 3 82/07/29 MUSOLF, D M Northern States Power Co 4pp 14324 337 24X
Fiche 50-282, 82/07/29, B208110088

B208100194 Advises that Exxon B20708 ltr transmitting XN-NF-B2-49 (p) should be considered util response to TMI Item II K 3.30. Method/model changes have been made where necessary
MUSOLF, D M Northern States Power Co 02/08/03 Office of Nuclear Reactor Regulation, Director 1p 14299 196 24X
Fiche 50-282, 82/08/03, B208100194

B208100055 Forwards application for amend to Licenses DPR-42 & DPR-60, changing Tech Spec Table 4.1-2A for waiver of end-of-cycle monthly turbine valve test Approval requested 2 months prior to Unit 1 refueling outage scheduled for B21113
MUSOLF, D Northern States Power Co 82/08/06 Office of Nuclear Reactor Regulation, Director 1p 14296 224 24X
Fiche 50-282, 82/08/06, B208100055

--B208100062 Application for amend to Licenses DPR-42 & DPR-60, changing Tech Spec Table 4.1-2A for waiver of end-of-cycle turbine valve test Description of proposed changes & reasons encl
MUSOLF, D M Northern States Power Co 82/08/06 3pp 14296 225 24X Fiche 50-282, 82/08/06, B208100055

--B208100074 Revised Tech Spec Table 4.1-2A re min frequencies for equipment tests, Licensing fee determination encl
Northern States Power Co 82/08/06 2pp 14276 228 24X
Fiche 50-282, 82/08/06, B208100055

B208090194 Generic Ltr B2-14 to all reactor licensees, holders of CP & applicants re submittal of documents to NRC Summarizes 10CFR Chapter I requirements & provides alternatives to requirements, Bvc list encl
EISENHUT, D O Division of Licensing 82/08/09 Consolidated Edison Co of New York 1p 14336 332 24X Fiche 50-000, 82/08/09, B208090194

B208120131 Forwards proprietary version, "Computer Program Control Procedure," NAF 5 OIP Procedure contains supplemental info to util reload methodology topical repts submitted B20212 Procedure withheld (ref 10CFR2.790) Affidavit encl
MUSOLF, D Northern States Power Co 82/08/09 Office of Nuclear Reactor Regulation, Director 5pp 14326 030 24X
Fiche 50-282, 82/08/09, B208120131

B208200294 Forwards Revision 1 to application to amend OL & proposed Tech Spec changes re radiological effluent Tech Specs & environ monitoring
MUSOLF, D Northern States Power Co 82/08/13 Office of Nuclear Reactor Regulation, Director 2pp 14394 146 24X
Fiche 50-282, 82/08/13, B208200294

--B208200297 Revision 1 to application to amend OL, changing Tech Specs to enhance radiological effluent & environ monitoring
Northern States Power Co 82/08/13 3pp 14394 148 24X
Fiche 50-282, 82/08/13, B208200294

--B208200298 Revisions 1 to proposed Tech Spec changes, enhancing radiological effluent & environ monitoring
Northern States Power Co 82/08/13 63pp 14394 151 24X
Fiche 50-282, 82/08/13, B208200294

0200300 Revision 1 to 'Offsite Dose Calculation Manual.'
MUSOLF, D. Northern States Power Co 82/08/13. 125pp. 14394.214.
24X Fiche: 50-282.82/08/13.8208200294

020338 Forwards "Process Control Program for Solidification of
Waste from Liquid Sys." & proprietary pages to "Radwaste
Solidification Sys." Encls withheld (ref 10CFR2 790).
MUSOLF, D.M. Northern States Power Co 82/08/13. Office of
Nuclear Reactor Regulation, Director 3pp. 14513.196. 24X
Fiche: 50-282.82/08/13.8208230338

020084 Forwards responses to 820603 questions re station electric
distribution sys voltage study. Installation of second
step-up transformer will provide flexible & reliable
distribution sys.
MUSOLF, D. Northern States Power Co 82/08/17. Office of Nuclear
Reactor Regulation, Director 20pp. 14393.221. 24X
Fiche: 50-282.82/08/17.8208200084

020136 Advises that Tech Spec Section 3.3.A.1 (g) applies to safety
injection pump discharge cross-connect valves & other ECCB
valves. In response to NRC B11201 ltr Section work
injection requires monthly surveillance of subv valves.
MUSOLF, D.M. Northern States Power Co 82/08/19. Office of
Nuclear Reactor Regulation, Director 1p. 14519.333. 24X
Fiche: 50-282.82/08/19.8208240136

020294 Provides confirmation of info discussed in earlier telcons
concerning purging & venting during normal operation.
MUSOLF, D. Northern States Power Co 82/08/23. Office of Nuclear
Reactor Regulation, Director 4pp. 14564.178. 24X
Fiche: 50-282.82/08/23.8208270294

Inspection reports, IE Bulletins & correspondence

020393 IE Info Notice 82-23, "Main Steam Isolation Valve (MSIV)
Leakage." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/16.
Consolidated Edison Co. of New York. 87pp. 14356.274. 24X
Fiche: 50-000.82/07/16.8204210393.

020395 IE Info Notice 81-26, Part 3, Suppl 1, "Clarification of
Movement of Personnel Monitoring Devices for External
Radiation." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/19.
Michigan Univ. of 112pp. 14358.001. 24X Fiche: 50-000.82/07/19.
8208210395

020508 Forwards IE Insp Repts 50-282/82-09 & 50-306/82-09 on
820501-30 No noncompliance noted.
REETER, J.F. Region 3, Office of Director. 82/07/19. LARSON, C.E.
Northern States Power Co. 2pp. 14214.061. 24X
Fiche: 50-282.82/07/19.8208050508

02050521 IE Insp Repts 50-282/82-09 & 50-306/82-09 on 820601-30.
No noncompliance noted. Major areas inspected: plant
operation, maint, organization, surveillance, security, radiation
protection, LER followup & refueling activities.
REETER, J.F. Region 3, Office of Director. 82/07/19. 9pp. 14214.063. 24X Fiche: 50-282.82/07/19.
8208050508.

020396 IE Info Notice 82-25, "Failures of Miller Actuators Upon
Annual Loss of Air Pressure." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/20.
Consolidated Edison Co. of New York 112pp. 14381.001. 24X
Fiche: 50-000.82/07/20.8204210396

020397 IE Info Notice 82-24, "Water Leaking From U Hexafluoride
Exhausts." Svc list encl.
JORDAN, E.L. Division of Fuel Facilities, Materials & Safeguards
82/07/20. Consolidated Edison Co. of New York. 71pp. 14357.276.
Fiche: 50-000.82/07/20.8204210397.

020398 IE Info Notice 82-26, "RCIC & HPCI Turbine Exhaust Check
Valve Failures." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/22.
Consolidated Edison Co. of New York 112pp. 14194.321. 24X
Fiche: 50-000.82/07/22.8204210398

020401 IE Info Notice 82-28, "Hydrogen Explosion While Grinding in
 vicinity of Drained & Open RCS." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance 82/07/23.
Consolidated Edison Co. of New York 122pp. 14387.115. 24X
Fiche: 50-000.82/07/23.8204210401.

020402 IE Info Notice 82-29, "Control Rod Drive (CRD) Guide Tube
Support Pin Failures at Westinghouse PHRs." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/23.
Consolidated Edison Co. of New York. 127pp. 14194.120. 24X
Fiche: 50-000.82/07/23.8204210402.

0204210403 IE Info Notice 82-30, "Loss of Thermal Sleeves in RCS Piping
at Certain Westinghouse PHR Power Plants." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/26.
Consolidated Edison Co. of New York 121pp. 14357.013. 24X
Fiche: 50-000.82/07/26.8204210403.

0204210405 IE Info Notice 82-31, "Overexposure of Diver During Work in
Fuel Storage Pool." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/07/28.
Consolidated Edison Co. of New York 122pp. 14357.146. 24X
Fiche: 50-000.82/07/28.8204210405

0208100080 Responds to IE Bulletin 82-02, "Degradation of Threaded
Fasteners in RCPB of PHR Plants." RCPB insps performed at
regular intervals. Few leakage problems experienced at
facility.
LARSON, C.E. Northern States Power Co. 82/08/02. KEPLER, J.O.
Region 3, Office of Director 4pp. 14296.145. 24X
Fiche: 50-282.82/08/02.8208100080

0204210407 IE Info Notice 82-27, "Fuel Rod Degradation Resulting From
Baffle Water-Jet Impingement." Svc list encl.
JORDAN, E.L. Division of Engineering & Quality Assurance. 82/08/03.
Consolidated Edison Co. of New York. 117pp. 14388.201. 24X
Fiche: 50-000.82/08/03.8204210407

0208240037 Forwards Franklin Research Ctr request for addl info re
B11130 response to IE Bulletin 80-11, "Masonry Walls." Info
requested within 30 days.
CLARK, R.A. Operating Reactors Branch 3 82/08/12. MUSOLF, D.M.
Northern States Power Co. 3pp. 14548.193. 24X
Fiche: 50-282.82/08/12.8208240037

R Periodic operating reports & related correspondence

0208270010 Responds to FOIA request for documents detailing collective
dose exposures in 1981 for operating nuclear power plants &
analyzing said info. Forwards documents listed in App A.
FELTON, J.M. Division of Rules and Records 82/07/13. UDELL, R.A.
Critical Mass Energy Project. 8pp. 14679.208. 24X
Fiche: 50-000.82/07/13.8208270010.

--8208270098 "Annual Whole Body Dose At Licensed Nuclear Power
Facilities For CY81."
* NRC - No Detailed Affiliation Given 82/07/13. 48pp.
14679.216. 24X Fiche: 50-000.82/07/13.8208270010.

--8208270209 Forwards annual rept of occupational radiation exposures for
CY81, per 10CFR20.407.
SCHUELKER, D.A. Northern States Power Co. 82/02/02. Office of
Management and Program Analysis. 1p. 14679.282. 24X
Fiche: 50-000.82/07/13.8208270010.

--8208270215 Annual occupational radiation exposure rept for CY81.
* Northern States Power Co. 82/02/02. 1p. 14679.283. 24X
Fiche: 50-000.82/07/13.8208270010.

0208270619 Forwards rept on number of personnel & man rem by work
& job function for 1981, per NUREG-0737, Item 11.K.3.3.
MAYER, L.O. Northern States Power Co. 82/02/26. KEPLER, J.O.
Region 3, Office of Director. 1p. 14679.342. 24X
Fiche: 50-000.82/07/13.8208270619.

--8208270626 Rept on number of personnel & man rem by work & job function
for 1981.
* Northern States Power Co. 82/02/26. 2pp. 14679.343. 24X
Fiche: 50-000.82/07/13.8208270619.

0208130198 Forwards monthly operating repts for Jul 1982.
MUSOLF, D. Northern States Power Co. 82/08/10. Director's Office,
Office of Inspection and Enforcement 1p. 14339.109. 24X
Fiche: 50-282.82/08/10.8208130198.

--8208130202 Monthly operating repts for Jul 1982.
MUSOLF, D. Northern States Power Co. 82/08/04. 8pp. 14339.106.
24X Fiche: 50-282.82/08/10.8208130198.

B. Reportable occurrences, LERs & related correspondence

0208090259 Forwards LER 82-012/03L-0
MUSOLF, D. Northern States Power Co. 82/07/30. Region 3, Office
of Director. 1p. 14270.345. 24X Fiche: 50-306.82/07/30.8208090259.

--8208090267 LER 82-012/03L-0: on 820702, radiation monitor sample return
isolation valve gave dual (open/closed) indication. Cause
not determined. Valves will be cycled periodically.
MUNSTAD, A.A. Northern States Power Co. 82/07/30. Region 3,
Office of Director. 1p. 14270.346. 24X Fiche: 50-306.82/07/30.
8208090259.